

Available from
National Technical Information Service
Springfield, Virginia 22161

**TITLE LIST
of
DOCUMENTS MADE PUBLICLY AVAILABLE**

May 1 - 31, 1979

**Division of Technical Information and Document Control
Office of Administration
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555**

CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Arrangement of Docket 50 Items by Facility Name	xviii
Docketed Items	I
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	1
Domestic Licensing of Production and Utilization Facilities - Docket 50	6
Domestic Licensing of Special Nuclear Material - Docket 70	272
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71	279
Nondocketed Items	289
Personal Author Index	321
Corporate Source Index - By Corporate Types	357
Citizen Group/Individual/Media	357
Engineering/Construction/Consultants/Services	357
Educational Institutions	357
Foreign Governments and Agencies	358
Legal/Law Firms/Insurance Companies	358
Local Government and Agencies	359
Medical Institutions and Laboratories	359
Manufacturers/Equipment and Supplies	360
Professional/Industrial Institutions, Societies	362
State Governments and Agencies	362
U.S. Federal Government and Agencies	362
Utilities, Holding Companies, Investor Associations	363
Research Institutions and Laboratories	373
U.S. Nuclear Regulatory Commission Organizational Source Index	375
Report Number Index	395
Appendix A - Definitions of Docket 50 Categories	397

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information includes the information formerly issued through the Department of Energy's Technical Information Center under the title *Power Reactor Docket Information* (PRDI) and, in addition, information received or generated on other uses of radioactive materials. The last issue of PRDI, published in January 1979, was an annual cumulation of the information for 1978. The *Title List* series initiated by this document replaces PRDI, which will no longer be prepared. Plans for providing microfiche of the docketed material will be announced in a future issue of the *Title List* and in other mailings and announcements.

We are making the monthly issues produced in 1979 available free to all who subscribed to PRDI in Calendar Year 1978. We are doing this to encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material. Near the end of 1979, subscriptions will be solicited for Calendar Year 1980 at a fee yet to be established.


DOCKETED ITEMS

Beginning with Vol. 1, No. 4, the listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:




1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number
3. Description of information contained in the document
4. Personal author. An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source
6. Date of document described
7. Pages in document
8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The principal elements of the nondocketed items are:



1. NRC Accession Number
2. NRC Report Number
3. Title and description of information contained in the document
4. Personal author(s). An asterisk in this position indicates that there is no personal author
5. Corporate, agency or other nonindividual source
6. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
7. Date of document described
8. Pages in document
9. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or Available at GPO."

The Nondocketed Items list is arranged sequentially by Accession Number. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NTIS is:
National Technical Information Service
Springfield, Virginia 22161
2. The address for GPO is:
Superintendent of Documents
Government Printing Office
Washington, D.C. 20402

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
27-039	Sheffield, IL., Nuclear Engineering Co., Inc.	1	40-8698	Flatiron Resources, Ltd.	5
27-047	Barwell, SC., Chem-Nuclear Systems, Inc.	1	40-8714	Cleveland Cliffs Iron Co.	6
40-0299	Union Carbide Corp.	1	40-8721	Rocky Mountain Energy Co.	6
40-1162	Western Nuclear	2	40-8722	Brush-Wellman, Inc.	6
40-2061	Kerr-McGee Corp., West Chicago Facility	2	50-2	Univ. of Michigan Research Reactor	6
40-2259	Pathfinder Mines Corp.	2	50-3	Indian Point Station, Unit 1	6
40-2407	Fellows Medical Manufacturing Co., Inc.	2	50-5	Pennsylvania State Univ. Research Reactor	7
40-3392	Allied Chemical Corp.	3	50-6	Battelle Memorial Inst. Research Reactor	7
40-3453	Atlas Minerals	4	50-8	North Carolina State Univ. Research Reactor	7
40-4492	Federal American Partners	4	50-10	Dresden Nuclear Power Station, Unit 1	7
40-4602	Morton Ranch Uranium Mill	4	50-12	Lynchburg Pool Reactor	9
40-6659	Petrolomics Co.	4	50-13	Babcock & Wilcox Co. Critical Facility	9
40-7086	Army, Dept. of	4	50-14	Battelle Memorial Inst. Critical Facility	9
40-8027	Kerr-McGee Corp.	4	50-16	Enrico Fermi Atomic Power Plant, Unit 1	9
40-8035	Cottor Corp.	4	50-18	Vallecitos Boiling Water Reactor	9
40-8064	Exxon Minerals Co., USA	4	50-20	Massachusetts Institute of Technology Research Reactor	9
40-8102	Exxon Minerals Co., USA, Exxon Corp.	4	50-22	Westinghouse Test Reactor	9
40-8158	Army, Dept. of, Communications & Electronics Material	4	50-24	General Electric Co. Critical Environment	9
40-8452	Bear Creek Mining Co.	4	50-27		
40-8502	Wyoming Mining Corp., Irigaray Mine	5	50-29		
40-8584	Union 76 Exploration Co.	5	50-30		
40-8602	United Nuclear Corp.	5	50-32		
40-8663	Nuclear Dynamics	5	50-37		
40-8681	Energy Fuels Nuclear	5	50-47		
40-8693	Ogle Petroleum, Inc.	5			
40-8697	Rocky Mountain Energy Co.	5			

Docket	Name	Page	Docket	Name	Page
50-53	Aeropot General Nucleonics	11	50-142	UCLA Training Reactor	16
50-54	Pawling Research Reactor	11	50-146	Saxton Nuclear Experimental Facility	16
50-59	Texas A & M Univ. Research Reactor	11	50-147	Rockwell International Corp. Critical Facility	16
50-62	Univ. of Virginia Research Reactor	11	50-148	Univ. of Kansas Research Reactor	16
50-70	General Electric Test Reactor	12	50-150	Ohio State Univ. Research Reactor	16
50-72	Univ. of Utah Research Reactor	12	50-151	Univ. of Illinois Research Reactor	16
50-73	General Electric Nuclear Test Reactor	12	50-155	Big Rock Point Nuclear Power Plant	16
50-77	Catholic Univ. of America Research Reactor	12	50-156	Univ. of Wisconsin Research Reactor	17
50-83	Univ. of Florida Training Reactor	12	50-157	Cornell Univ. Research Reactor	18
50-84	Univ. of California Research Reactor	12	50-160	Georgia Institute of Technology Research Reactor	18
50-87	Westinghouse Critical Experiment	12	50-166	Univ. of Maryland Research Reactor	18
50-89	General Atomic Co.	12	50-170	National Naval Medical Center	18
50-94	Rockwell International Research Reactor	12	50-171	Powder Bottom Atomic Power Station, Unit 1	18
50-97	Cornell Univ. Zero Power Reactor	12	50-182	Purdue Univ. Research Reactor	18
50-99	Babcock & Wilcox Test Reactor	13	50-183	Vallecitos Experimental Superheat Reactor	18
50-103	Aeropot General Nucleonics	13	50-184	National Bureau of Standards Reactor	18
50-106	Oregon State Univ.	13	50-186	Univ. of Missouri Research Reactor	18
50-111	North Carolina State Univ. Research Reactor	13	50-187	Space Radiation Research Reactor	18
50-112	Univ. of Oklahoma Research Reactor	13	50-188	Kansas State Univ. Research Reactor	18
50-113	Univ. of Arizona Research Reactor	13	50-191	Babcock & Wilcox Co. Critical Facility	19
50-116	Iowa State Univ. Research Reactor	13	50-192	Univ. of Texas Research Reactor	19
50-123	Univ. of Missouri Research Reactor	13	50-193	Rhode Island & Providence Plantations AEC	19
50-124	Virginia Polytech Inst. Training Reactor	14	50-199	Manhattan College Research Reactor	19
	Texas A & M Univ. Research Reactor	14	50-200	Babcock & Wilcox Test Reactor	19
	Texas A & M Univ. Research Reactor	14	50-201	West Valley Reprocessing Plant	19
	Omaha Veterans Administration Hospital Research Reactor	14	50-206	San Onofre Nuclear Station, Unit 1	19
	Humboldt Bay Power Plant, Unit 3	14	50-208	Columbia Univ. Research Reactor	21
	Worcester Polytech Inst. Research Reactor	16	50-213	Haddam Neck Plant	21
	Univ. of Washington Research Reactor	16	50-219	Oyster Creek Nuclear Power Plant	22
	Stanford Univ. Research Reactor	16	50-220	Nine Mile Point Nuclear Station, Unit 1	24

Docket	Name	Page	Docket	Name	Page
50-223	Univ. of Lowell Research Reactor	25	50-267	Fort St. Vrain Nuclear Generating Station	50
50-224	Univ. of California Research Reactor	25	50-269	Oconee Nuclear Station, Unit 1	52
50-225	RPI Critical Experiment	25	50-270	Oconee Nuclear Station, Unit 2	55
50-227	TRIGA Thermionic Prototype Reactor	26	50-271	Vermont Yankee Nuclear Power Station	57
50-228	Aerostat Radiography & Research Reactor	26	50-272	Salem Nuclear Generating Station, Unit 1	58
50-233	Mexico Research Reactor	26	50-273	Bernau Nuclear Station, Unit 1	61
50-234	Tungsten Nuclear Rocket Critical Facility	26	50-274	U.S. Geological Survey Research Reactor	61
50-235	Accelerator Pulsed Fast Assembly	26	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	61
50-237	Dresden Nuclear Power Station, Unit 2	26	50-276	Georgia Tech Research Reactor	64
50-240	High Temp. Gas Cooled Critical Experiment	28	50-277	Peach Bottom Atomic Power Station, Unit 2	64
50-241	Mississippi State Univ. Research Reactor	28	50-278	Peach Bottom Atomic Power Station, Unit 3	66
50-243	Oregon State Univ. Research Reactor	28	50-280	Savoy Power Station, Unit 1	67
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	28	50-281	Savoy Power Station, Unit 2	70
50-245	Millstone Nuclear Power Station, Unit 1	29	50-282	Pacific Island Nuclear Station, Unit 1	72
50-247	Indian Point Station, Unit 2	31	50-284	Idaho State Univ. Research Reactor	74
50-249	Dresden Nuclear Power Station, Unit 3	32	50-285	Fort Calhoun Station, Unit 1	74
50-250	Turkey Point Plant, Unit 3	34	50-286	Indian Point Station, Unit 3	76
50-251	Turkey Point Plant, Unit 4	36	50-287	Oconee Nuclear Station, Unit 3	77
50-252	Univ. of New Mexico Research Reactor	38	50-288	Rensselaer College Research Reactor	80
50-254	Quad-Cities Station, Unit 1	38	50-289	Three Mile Island Nuclear Station, Unit 1	80
50-255	Palisades Nuclear Plant	39	50-293	Higgins Nuclear Power Station, Unit 1	81
50-259	Browns Ferry Nuclear Power Station, Unit 1	41	50-294	Michigan State Univ. Research Reactor	82
50-260	Browns Ferry Nuclear Power Station, Unit 2	42	50-295	Zion Nuclear Power Station, Unit 1	82
50-261	H.B. Robinson Plant, Unit 2	44	50-296	Browns Ferry Nuclear Power Station, Unit 3	84
50-262	Brigham Young Univ. Research Reactor	46	50-297	North Carolina State Univ. PULSTAR Reactor	85
50-263	Monticello Nuclear Generating Plant	46	50-298	Cooper Nuclear Station	86
50-264	Dow Chemical Co.	47	50-301	Point Beach Nuclear Plant, Unit 2	87
50-265	Quad-Cities Station, Unit 2	48	50-302	Crystal River Nuclear Plant, Unit 3	88
50-266	Point Beach Nuclear Plant, Unit 1	49			

Page	Name	Page	Docket	Name	Page
91	Crystal River Nuclear Plant, Unit 4	91	50-338	North Anna Power Station, Unit 1	154
91	Egin Nuclear Power Station, Unit 2	91	50-339	North Anna Power Station, Unit 2	158
93	Kewaunee Nuclear Power Plant	93	50-341	Enrico Fermi Atomic Power Plant, Unit 2	160
94	Pratt Island Nuclear Station, Unit 2	94	50-344	Trojan Nuclear Plant, Unit 1	161
95	Marble Valley Atomic Power Plant	95	50-346	Darwin-Besse Nuclear Power Station, Unit 1	164
97	Salem Nuclear Generating Station, Unit 2	97	50-348	Joseph M. Farley Nuclear Plant, Unit 1	166
99	Rancho Seco Nuclear Generating Station	99	50-352	Limerick Generating Station, Unit 1	168
100	Arkansas Nuclear One, Unit 1	100	50-353	Limerick Generating Station, Unit 2	168
103	Donald C. Cook Nuclear Power Plant, Unit 1	103	50-354	Hope Creek Nuclear Station, Unit 1	169
105	Donald C. Cook Nuclear Power Plant, Unit 2	105	50-355	Hope Creek Nuclear Station, Unit 2	169
106	Calvert Cliffs Nuclear Power Plant, Unit 1	106	50-358	William H. Zimmer Nuclear Station, Unit 1	170
107	Calvert Cliffs Nuclear Power Plant, Unit 2	107	50-360	Battelle Memorial Inst. Critical Facility	173
108	Three Mile Island Nuclear Station, Unit 2	108	50-361	San Onofre Nuclear Station, Unit 2	173
108	Three Mile Island Nuclear Station, Unit 2	108	50-362	San Onofre Nuclear Station, Unit 3	174
130	Edwin I. Hatch Nuclear Plant, Unit 1	130	50-363	Forked River Nuclear Station, Unit 1	175
131	Shoshone Nuclear Power Station	131	50-364	Joseph M. Farley Nuclear Plant, Unit 2	176
133	Duablo Canyon Nuclear Power Plant, Unit 2	133	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	176
135	Brunswick Steam Electric Plant, Unit 2	135	50-367	Bally Generating Station	178
137	Brunswick Steam Electric Plant, Unit 1	137	50-368	Arkansas Nuclear One, Unit 2	178
139	Univ. of California at Irvine Res. Reactor	139	50-369	William B. MacGulre Nuclear Station, Unit 1	180
139	Sequoyah Nuclear Plant, Unit 1	139	50-370	William B. MacGulre Nuclear Station, Unit 2	182
141	Seminole Nuclear Station, Unit 2	141	50-373	LaSalle County Station, Unit 1	182
142		142	50-374	LaSalle County Station, Unit 2	184
			50-375	Nuclear Examination Reactor	185
			50-376	North Coast Nuclear Plant (Puerto Rico)	185
			50-382	Waterford Generating Station, Unit 3	185
			50-387	Susquehanna Steam Electric Station, Unit 1	186
			50-388	Susquehanna Steam Electric Station, Unit 2	187
			50-389	St. Lucie Plant, Unit 2	188

Docket	Name	Page	Docket	Name	Page
50-390	Watts Bar Nuclear Plant, Unit 1	189	50-440	Perry Nuclear Power Plant, Unit 1	210
50-391	Watts Bar Nuclear Plant, Unit 2	191	50-441	Perry Nuclear Power Plant, Unit 2	211
50-394	California State Polytech College Research Reactor	192	50-443	Seabrook Nuclear Station, Unit 1	211
50-395	Virgil C. Summer Nuclear Station, Unit 1	192	50-444	Seabrook Nuclear Station, Unit 2	212
50-396	Univ. of Virginia Cavalier Reactor	193	50-445	Comanche Peak Steam Electric Station, Unit 1	213
50-397	WPPSS Nuclear Project, Unit 2	193	50-446	Comanche Peak Steam Electric Station, Unit 2	216
50-400	Shearon Harris Nuclear Power Plant, Unit 1	194	STN-50-447	GESSAR-238	218
50-401	Shearon Harris Nuclear Power Plant, Unit 2	196	50-448	Douglas Point Nuclear Station, Unit 1	218
50-402	Shearon Harris Nuclear Power Plant, Unit 3	197	50-449	Douglas Point Nuclear Station, Unit 2	219
50-403	Shearon Harris Nuclear Power Plant, Unit 4	198	50-450	Summit Nuclear Power Station, Unit 1	219
50-404	North Anna Power Station, Unit 3	199	50-451	Summit Nuclear Power Station, Unit 2	219
50-405	North Anna Power Station, Unit 4	200	50-452	Greenwood Energy Center, Unit 2	219
50-406	Tuskegee Inst. Research Reactor	201	50-453	Greenwood Energy Center, Unit 3	219
50-407	Univ. of Utah Research Reactor	201	50-454	Byron Station, Unit 1	219
50-409	La Crosse Boiling Water Reactor	201	50-455	Byron Station, Unit 2	220
50-410	Nine Mile Point Nuclear Station, Unit 2	202	50-456	Braidwood Station, Unit 1	221
50-412	Beaver Valley Power Station, Unit 2	203	50-457	Braidwood Station, Unit 2	222
50-413	Catawba Nuclear Station, Unit 1	203	50-458	River Bend Station, Unit 1	223
50-414	Catawba Nuclear Station, Unit 2	204	50-459	River Bend Station, Unit 2	224
50-416	Grand Gulf Nuclear Station, Unit 1	204	50-460	WPPSS Nuclear Project, Unit 1	224
50-417	Grand Gulf Nuclear Station, Unit 2	205	50-461	Clinton Power Station, Unit 1	225
50-423	Millstone Nuclear Power Station, Unit 3	206	50-462	Clinton Power Station, Unit 2	226
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	206	50-463	Fulton Generating Station, Unit 1	226
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	207	50-464	Fulton Generating Station, Unit 2	226
50-426	Alvin W. Vogtle Nuclear Plant, Unit 3	208	50-466	Allens Creek Nuclear Station, Unit 1	227
50-427	Alvin W. Vogtle Nuclear Plant, Unit 4	208	50-467	Allens Creek Nuclear Station, Unit 2	229
50-430	ASCO, Unit 1	208	50-471	Pilgrim Nuclear Power Station, Unit 2	229
50-433	UC-Santa Barbara Research Reactor	208	50-472	Pilgrim Nuclear Power Station, Unit 3	230
STN-50-437	Floating Nuclear Plant	208	STN-50-477	Atlantic Generating Station, Unit 1	230
50-438	Bellefonte Nuclear Plant, Unit 1	209	STN-50-478	Atlantic Generating Station, Unit 2	230
50-439	Bellefonte Nuclear Plant, Unit 2	210	STN-50-482	Wolf Creek Generating Station	230
			STN-50-483	Calloway Plant, Unit 1	232
			STN-50-484	Tyrone Energy Park, Unit 1	232

Docket	Name	Page	Docket	Name	Page
STN-50-485	Sterling Power Project, Nuclear, Unit 1	233	STN-50-530	Palo Verde Nuclear Station, Unit 3	258
STN-50-486	Calloway Plant, Unit 2	234	STN-50-531	GESSAR-251	258
STN-50-488	Perkins Nuclear Station, Unit 1	234	STN-50-532	BOP SAR	259
STN-50-489	Perkins Nuclear Station, Unit 2	235	50-537	Clinch River Breeder Reactor	259
STN-50-490	Perkins Nuclear Station, Unit 3	236	50-538	Memphis State Univ. Research Reactor	259
STN-50-491	Cheesokee Nuclear Station, Unit 1	236	STN-50-546	Marble Hill Nuclear Station, Unit 1	259
STN-50-492	Cheesokee Nuclear Station, Unit 2	237	STN-50-547	Marble Hill Nuclear Station, Unit 2	260
STN-50-493	Cheesokee Nuclear Station, Unit 3	238	50-548	Fort Calhoun Station, Unit 2	261
STN-50-495	SWESSAR-P1	239	50-549	Greene County Nuclear Power Plant	261
STN-50-498	South Texas Project, Unit 1	239	STN-50-550	GESSAR-238-BOP Interface	262
STN-50-499	South Texas Project, Unit 2	241	STN-50-553	Phipps Bend Nuclear Plant, Unit 1	262
50-500	Davis-Besse Nuclear Power Station, Unit 2	244	STN-50-554	Phipps Bend Nuclear Plant, Unit 2	263
50-501	Davis-Besse Nuclear Power Station, Unit 3	245	STN-50-556	Black Fox Station, Unit 1	263
STN-50-502	Haven Nuclear Plant, Unit 1	245	STN-50-557	Black Fox Station, Unit 2	264
STN-50-503	Haven Nuclear Plant, Unit 2	246	50-564	Nuclear Fuels Recovery and Recycle Center	266
STN-50-508	WPPSS Nuclear Project, Unit 3	246	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	266
STN-50-509	WPPSS Nuclear Project, Unit 5	247	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	266
50-510	Blue Hills Station, Unit 1	247	STN-50-568	NEP Nuclear, Unit 1	267
50-511	Blue Hills Station, Unit 2	248	STN-50-569	NEP Nuclear, Unit 2	267
50-513	WPPSS Nuclear Project, Unit 4	248	STN-50-574	Bugmao Nuclear Power Project	267
50-514	Pebble Springs Nuclear Plant, Unit 1	249	STN-50-580	Erie Nuclear Plant, Unit 1	267
50-515	Pebble Springs Nuclear Plant, Unit 2	249	STN-50-581	Erie Nuclear Plant, Unit 2	267
STN-50-516	Jamestown Nuclear Station, Unit 1	250	STN-50-584	GIBBSAR	268
STN-50-517	Jamestown Nuclear Station, Unit 2	250	STN-50-592	Palo Verde Nuclear Station, Unit 4	268
		251	STN-50-593	Palo Verde Nuclear Station, Unit 5	268
		251	50-596	New Haven, Unit 1	269
		252	50-597	New Haven, Unit 2	270
		253	50-598	Northwestern Univ.	271
		254	50-599	Carroll Facility I	271
		255	50-600	Carroll Facility II	271
		256	70-0008	Battelle Columbus Laboratories	272
		256	70-0025	Rockwell International Corp.	272
		256	70-0027	Babcock & Wilcox Co.	272
		256	70-0033	Texas Instruments, Inc.	272
		257	70-0102	Amherst College	272

Docket	Name	Page	Docket	Name	Page
70-0135	Babcock & Wilcox Co.	272	70-2838	Cincinnati Gas & Electric Co.	279
70-0143	Nuclear Fuel Services, Inc.	273	71-0001	ANEFEO, Inc.	279
70-0150	Purdue University	273	71-0002	Chem-Nuclear Systems, Inc.	279
70-0364	Packs Township Site, Babcock & Wilcox Co.	273	71-0006	United Nuclear Corp.	279
70-0371	United Nuclear Corp.	274	71-0008	Commonwealth Edison Co.	279
70-0734	General Atomic Co.	274	71-0024	Hittman Nuclear & Development Corp.	279
70-0754	Vallecitos Nuclear Center, General Electric Co.	274	71-0031	Maryland Shipbuilding & Dry Dock Co.	279
70-0820	United Nuclear Corp.	274	71-0033	Industrial Testing Laboratory Servists Co.	279
70-0824	Babcock & Wilcox Co.	275	71-0034	Babcock & Wilcox Co.	279
70-0984	Pacific Northwest Laboratory	275	71-0036	ITT Gennell Corp.	279
70-1007	General Electric Co.	275	71-0038	Crane Co.	279
70-1086	Westinghouse Electric Corp.	275	71-0039	Walworth Co.	279
70-1100	Combustion Engineering, Inc.	275	71-0047	Capital International Airways, Inc.	280
70-1113	General Electric Co.	275	71-0048	Intermountain Pipe and Welding	280
70-1143	Westinghouse Electric Corp.	275	71-0050	Midland-Ross Corp.	280
70-1151	Westinghouse Electric Corp.	276	71-0055	H.R. Inspection Service	280
70-1173	Mercyhurst College	276	71-0056	Philadelphia Electric Co.	280
70-1193	Chnaron Facility, Kerr-McGee Corp.	276	71-0057	Exxon Co. U.S.A., Exxon Corp.	280
70-1201	UPG Conversion Facility, Babcock & Wilcox Co.	276	71-0063	Ozark Airlines, Inc.	280
70-1257	Mixed Oxide Fabrication Plant, Exxon Nuclear Co., Inc.	277	71-0065	H.P. & Associates, Inc.	280
70-1308	Morris Operations, General Electric Co.	277	71-0066	Certified Testing Laboratories, Inc.	280
70-1309	Morris Operations, Sources & Standards, General	277	71-0068	Yankee Atomic Electric	280
70-1318	NL Nuclear/NL Industries, Inc.	277	71-0070	General Motors Corp.	280
70-1319	U.S. Nuclear, Inc.	277	71-0072	Babcock & Wilcox Co.	280
70-1355	Army, Dept. of	278	71-0074	Nuclear Welding, Inc.	280
70-1379	Parkwell Laboratories, Inc.	278	71-0077	Midstate Testing Laboratory	280
70-1821	Plutonium Production Facility, Allied General Nuclear Service Corp.	278	71-0087	Navy, Dept. of	280
70-2428	St. Francis General Hospital, Pittsburgh, PA	278	71-0088	Babcock & Wilcox Co.	280
70-2623	McGuire Spent Fuel Pool, Duke Power Co.	278	71-0089	Navy, Dept. of	280
70-2753	Holyoke Hospital, Holyoke, MA	279	71-0090	Combustion Engineering Co., Inc.	280
70-2760	United Nuclear Corp.	279	71-0099	Foster Wheeler Energy Corp.	281
			71-0103	Twins City Testing & Engineering Laboratory	281
			71-0104	Chicago Bridge & Iron Co.	281
			71-0109	Union Carbide Corp.	281

Docket	Name	Page	Docket	Name	Page
71-0110	Buckeye Steel Castings	281	71-0209	Jacksonville Shipyards, Inc.	282
71-0111	Material Testing Laboratory of Virginia, Inc.	281	71-0213	Intermountain Testing Co.	283
71-0116	Navy, Dept. of	281	71-0214	Gas Rentals, Inc.	283
71-0119	Ingersoll-Rand Co.	282	71-0215	Space Science Services	283
71-0120	Daniel International Corp.	281	71-0216	Nuclear Energy Services, Inc.	283
71-0121	Nutron Products, Inc.	281	71-0217	Pallman Kellogg, Inc.	283
71-0126	Stanwick Corp.	281	71-0220	General Dynamics Corp.	283
71-0127	National Anstalling Box Co.	281	71-0222	St. Louis Testing Laboratories, Inc.	283
71-0128	Amoco Oil Co.	281	71-0223	B.F. Shew, Inc.	283
71-0130	Chicago Bridge & Iron Co.	281	71-0225	Navy, Dept. of	283
71-0131	Welding Institute of Alaska	281	71-0226	New York, State Univ. of	283
71-0137	Metals Testing Co., Inc.	281	71-0234	X-Ray, Inc.	283
71-0141	Rockwell International	281	71-0235	Army, Dept. of	283
71-0143	Ranchers Exploration and Development Co.	281	71-0238	Agriculture, Dept. of	283
71-0151	Hess Oil Virgin Islands Corp.	282	71-0239	Navy, Dept. of	283
71-0154	General Dynamics	282	71-0241	United Nuclear Corp.	283
71-0156	Industrial Fabricating Co.	282	71-0251	Westinghouse Electric Corp.	283
71-0158	X-Ray Industries, Inc.	282	71-0255	Walworth Co.	283
71-0161	Curtis-Wright Corp.	282	71-0257	Industrial Laboratories, Inc.	283
71-0162	Ebasco Services, Inc.	282	71-0260	Astrotech, Inc.	283
71-0166	New York Testing Laboratories, Inc.	282	71-0261	Navy, Dept. of	283
71-0167	Finlay Testing Laboratories	282	71-0266	Duke Power Co.	284
71-0168	Quality Assurance Laboratories	282	71-0268	Navy, Dept. of	284
71-0169	Florida Power & Light Co.	282	71-0273	Navy, Dept. of	284
71-0174	Southern California Edison Co.	282	71-0277	Allied Chemical Corp.	284
71-0175	QC Services, Inc.	282	71-0280	ABCO Perforators, Inc.	284
71-0178	Energy Products Group	282	71-0282	WKM Wellhead Systems, Inc.	284
71-0180	Hartford Steam Boiler Co.	282	71-0286	EPB Instruments, Inc.	284
71-0181	Consolidated X-Ray Service Co.	282	71-0287	Carson Non-Destructive Testing	284
71-0188	Maynard Steel Casting Co.	282	71-0288	North Dakota State Water Commission	284
71-0189	Todd Shipyards Corp.	282	71-0290	United Testing Services, Inc.	284
71-0202	Pacific Gas & Electric Co.	282	71-0296	Iowa Electric Light & Phone Co.	284
71-0205	Quality Testing, Inc.	282	71-0297	E. Lewis Cook & Associates	284
71-0207	Connecticut Yankee Atomic Power Co.	282	71-0299	Quality Control Services, Inc.	284
			71-0300	Independent Testing Laboratories	284

Docket	Name	Page	Docket	Name	Page
71-0304	Teledyne Brown Engineering Co.	284	71-6697	Model: 8500 PKG, General Electric Co.	286
71-0305	American X-Ray & Inspection, Inc.	284	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	286
71-0307	Texas Pipe Bending Co. of Puerto Rico	284	71-6744	Model: Poly Tiger, Nuclear Engineering Co.	287
71-0309	Worthington Pump Corp. (U.S.A.)	284	71-6771	Model: SN-1, Nuclear Engineering Co.	287
71-0311	Logwell, Inc.	285	71-9009	Model: FL-10-1, General Electric Co.	287
71-0312	Metalfoms, Inc.	285	71-9010	Model: NLI-1/2, NL Industries, Inc.	287
71-0317	Hudson Products Corp.	285	71-9023	Model: NLI-10/24, NL Industries, Inc.	287
71-0322	Control Components International	285	71-9033	Model: 660 & 660E, Technical Operations, Inc.	287
71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	285	71-9044	Model: GE-1600, General Electric Co.	287
71-5026	Model: BC-48-220, Atcor, Inc.	285	71-9070	Model: N-55, Energy, Dept. of	287
71-5450	Model: RCC-1, -2, -3, Westinghouse Electric Corp.	285	71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	287
71-5790	Model: A1-M3, Energy, Dept. of	285	71-9080	Model: HN-600, Hittman Nuclear & Development Corp.	287
71-5791	Model: A1-M6, Energy, Dept. of	285	71-9086	Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	287
71-5795	Model: None, Energy, Dept. of	285	71-9089	Model: NH-100 S, Hittman Nuclear & Development Corp.	287
71-5805	Model: Atcor VNDB Cask, Atcor, Inc.	285	71-9090	Model: 480M, Allied Chemical Corp.	287
71-5908	Model: DOT-GM Type B, Babcock & Wilcox Co.	285	71-9091	Model: 30A, General Electric Co.	287
71-5926	Model: 100, General Electric Co.	285	71-9092	Model: HN-300, Hittman Nuclear & Development Corp.	288
71-5957	Model: BML-1, Energy, Dept. of	285	71-9093	Model: HN-400 Hittman Nuclear & Development Corp.	288
71-6058	Model: B3-1, Nuclear Engineering Co.	285	71-9116	Model: CN6-80B, Nuclear Packaging, Inc.	288
71-6144	Model: 6144, Nuclear Engineering Co.	286	71-9120	Model: TN-12, Transnuclear Corp.	288
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	286	71-9132	Model: T-3, Nuclear Packaging, Inc.	288
71-6272	Model: Poly Panther, Nuclear Engineering Co.	286	71-9506	Model: MS27684-2, Energy, Dept. of	288
71-6273	Model: 48X, F, A, Y, Allied-General Nuclear Services	286	71-9785	Model: SZW/SZWA, Energy, Dept. of	288
71-6346	Model: FSV-1, General Atomic Co.	286	71-9852	Model: IOT-14, Energy, Dept. of	288
71-6386	Model: 235R001, Energy, Dept. of	286			
71-6387	Model: 60, Battelle Memorial Institute	286			
71-6400	Model: Super Tiger, Westinghouse Electric Corp.	286			
71-6583	Model: Paducah Tiger, Energy, Dept. of	286			
71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	286			

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Accelerator Pulsed Fast Assembly	50-235	26	Battelle Memorial Inst. Critical Facility	50-360	173
Aerojet General Nuclears	50-32	11	Battelle Memorial Inst. Research Reactor	50-6	7
Aerojet General Nuclears	50-33	11	Beaver Valley Power Station, Unit 1	50-334	149
Aerojet General Nuclears	50-103	13	Beaver Valley Power Station, Unit 2	50-412	203
Aerotest Radiography & Research Reactor	50-328	26	Bellefonte Nuclear Plant, Unit 1	50-438	209
Allons Creek Nuclear Station, Unit 1	50-466	227	Bellefonte Nuclear Plant, Unit 2	50-439	210
Allons Creek Nuclear Station, Unit 2	50-467	229	Bemas Nuclear Station, Unit 1	50-273	61
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	266	Big Rock Point Nuclear Power Plant	50-155	16
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	207	Black Fox Station, Unit 1	STN-50-556	263
Alvin W. Vogtle Nuclear Plant, Unit 3	50-426	208	Black Fox Station, Unit 2	STN-50-557	264
Alvin W. Vogtle Nuclear Plant, Unit 4	50-427	208	Blue Hills Station, Unit 1	50-510	247
Arkansas Nuclear One, Unit 1	50-313	100	Blue Hills Station, Unit 2	50-511	248
Arkansas Nuclear One, Unit 2	50-368	178	BOF SAR, C.F. Braun	STN-50-532	259
Army Materials Research Reactor	50-47	11	Braidwood Station, Unit 1	50-456	221
ASCO, Unit 1	50-430	208	Braidwood Station, Unit 2	50-457	222
Atlantic Generating Station, Unit 1	STN-50-477	230	Brigham Young Univ. Research Reactor	50-262	46
Atlantic Generating Station, Unit 2	STN-50-478	230	Browns Ferry Nuclear Power Station, Unit 1	50-259	41
Babcock & Wilcox Co. Critical Facility	50-13	9	Browns Ferry Nuclear Power Station, Unit 2	50-260	42
Babcock & Wilcox Co. Critical Facility	50-191	19	Browns Ferry Nuclear Power Station, Unit 3	50-296	84
Babcock & Wilcox Test Reactor	50-99	13	Brunswick Steam Electric Plant, Unit 2	50-324	135
Babcock & Wilcox Test Reactor	50-200	19	Brunswick Steam Electric Plant, Unit 1	50-325	137
Bagnasco Nuclear Power Project	STN-50-574	267	Byron Station, Unit 1	50-454	219
Bally Generating Station	50-367	178	Byron Station, Unit 2	50-455	220
essing Plant	50-332	148	California State Polytech College Research Reactor	50-394	192
	50-524	256	Calloway Plant, Unit 1	STN-50-483	232
	50-525	256			
	50-14	9			

Name	Docket	Page	Name	Docket	Page
Calloway Plant, Unit 2	STN-50-486	234	Douglas Point Nuclear Station, Unit 2	50-449	219
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	106	Dow Chemical Co.	50-264	47
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	107	Dresden Nuclear Power Station, Unit 1	50-10	7
Carroll Facility I	50-599	271	Dresden Nuclear Power Station, Unit 2	50-237	26
Carroll Facility II	50-600	271	Dresden Nuclear Power Station, Unit 3	50-249	32
Catawba Nuclear Station, Unit 1	50-413	203	Duane Arnold Energy Center	50-331	146
Catawba Nuclear Station, Unit 2	50-414	204	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	130
Catholic Univ. of America Research Reactor	50-77	12	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	176
Cherokee Nuclear Station, Unit 1	STN-50-491	236	Enrico Fermi Atomic Power Plant, Unit 1	50-16	9
Cherokee Nuclear Station, Unit 2	STN-50-492	237	Enrico Fermi Atomic Power Plant, Unit 2	50-341	160
Cherokee Nuclear Station, Unit 3	STN-50-493	238	Erie Nuclear Plant, Unit 1	STN-50-580	267
Clinch River Breeder Reactor	50-537	259	Erie Nuclear Plant, Unit 2	STN-50-581	267
Clinton Power Station, Unit 1	50-461	225	Floating Nuclear Plant	STN-50-437	208
Clinton Power Station, Unit 2	50-462	226	Forked River Nuclear Station, Unit 1	50-363	175
Columbia Univ. Research Reactor	50-208	21	Fort Calhoun Station, Unit 1	50-285	74
Comanche Peak Steam Electric Station, Unit 1	50-445	213	Fort Calhoun Station, Unit 2	50-548	261
Comanche Peak Steam Electric Station, Unit 2	50-446	216	Fort St. Vrain Nuclear Generating Station	50-267	50
Cooper Nuclear Station	50-298	86	Fulton Generating Station, Unit 1	50-463	226
Cornell Univ. Research Reactor	50-157	18	Fulton Generating Station, Unit 2	50-464	226
Cornell Univ. Zero Power Reactor	50-97	12	General Atomic Co.	50-89	12
Crystal River Nuclear Plant, Unit 3	50-302	88	General Electric Co. Critical Experiment	50-24	9
Crystal River Nuclear Plant, Unit 4	50-303	91	General Electric Test Reactor	50-70	12
Davis-Besse Nuclear Power Station, Unit 1	50-346	164	General Electric Nuclear Test Reactor	50-77	--
Davis-Besse Nuclear Power Station, Unit 2	50-500	244	Georgia Institute of Technology Research Reactor		
Davis-Besse Nuclear Power Station, Unit 3	50-501	245	Georgia Institute of Technology Research Reactor		
Dinabio Canyon Nuclear Power Plant, Unit 1	50-275	61	GESSAR-238	STN	
Dinabio Canyon Nuclear Power Plant, Unit 2	50-323	133	GESSAR-238-BOP Interface	STN	
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	103	GESSAR-251		
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	105	GIBBSAR	STN	
Douglas Point Nuclear Station, Unit 1	50-448	218	Grand Gulf Nuclear Station, Unit 1		
			Grand Gulf Nuclear Station, Unit 2		
			Greene County Nuclear Power Plant		

Name	Docket	Page	Name	Docket	Page
Lawrence Livermore Energy Center, Unit 2	50-452	219	Marble Hill Nuclear Station, Unit 2	STN-50-547	260
Lawrence Livermore Energy Center, Unit 3	50-453	219	Massachusetts Institute of Technology Research Reactor	50-20	9
Libby-Robinson Plant, Unit 2	50-261	44	Memphis State Univ. Research Reactor	50-538	259
Midwest Nuclear Plant	50-213	21	Mexico Research Reactor	50-223	26
Hotelsville Nuclear Plant, Unit 1	STN-50-518	251	Michigan State Univ. Research Reactor	50-294	82
Hotelsville Nuclear Plant, Unit 2	STN-50-519	251	Midland Plant, Unit 1	50-329	142
Hotelsville Nuclear Plant, Unit 3	STN-50-520	252	Midland Plant, Unit 2	50-330	144
Hotelsville Nuclear Plant, Unit 4	STN-50-521	253	Millstone Nuclear Power Station, Unit 1	50-245	29
Haven Nuclear Plant, Unit 1	STN-50-502	245	Millstone Nuclear Power Station, Unit 2	50-336	153
Haven Nuclear Plant, Unit 2	STN-50-503	246	Millstone Nuclear Power Station, Unit 3	50-423	206
High Temp. Gas Cooled Critical Experiment	50-240	28	Mississippi State Univ. Research Reactor	50-241	28
Hipe Creek Nuclear Station, Unit 1	50-354	169	Mondulbo Nuclear Generating Plant	50-263	46
Hipe Creek Nuclear Station, Unit 2	50-355	169	National Bureau of Standards Reactor	50-184	18
Humboldt Bay Power Plant, Unit 3	50-133	14	National Naval Medical Center	50-170	18
Idaho State Univ. Research Reactor	50-284	74	NEP Nuclear, Unit 1	STN-50-568	267
Indian Point Station, Unit 1	50-3	6	NEP Nuclear, Unit 2	STN-50-569	267
Indian Point Station, Unit 2	50-247	31	New Haven, Unit 1	50-596	269
Indian Point Station, Unit 3	50-286	76	New Haven, Unit 2	50-597	270
Iowa State Univ. Research Reactor	50-116	13	Nine Mile Point Nuclear Station, Unit 1	50-220	24
Jarvis A. Fitzpatrick Nuclear Power Plant	50-333	148	Nine Mile Point Nuclear Station, Unit 2	50-410	202
Jamestown Nuclear Station, Unit 1	STN-50-516	250	North Anna Power Station, Unit 1	50-338	154
Jamestown Nuclear Station, Unit 2	STN-50-517	250	North Anna Power Station, Unit 2	50-339	158
Joseph M. Farley Nuclear Plant, Unit 1	50-348	166	North Anna Power Station, Unit 3	50-404	199
Joseph M. Farley Nuclear Plant, Unit 2	50-364	176	North Anna Power Station, Unit 4	50-405	200
			North Carolina State Univ. PULSTAR Reactor	50-297	85
			North Carolina State Univ. Research Reactor	50-8	7
			North Carolina State Univ. Research Reactor	50-111	13
			North Carolina State Univ. Research Reactor	50-376	185
			North Carolina State Univ. Research Reactor	50-398	271
			North Carolina State Univ. Research Reactor	50-375	185
			North Carolina State Univ. Research Reactor	50-364	266

Name	Docket	Page	Name	Docket	Page
Oconee Nuclear Station, Unit 1	50-269	52	Point Beach Nuclear Plant, Unit 2	50-301	87
Oconee Nuclear Station, Unit 2	50-270	55	Prairie Island Nuclear Station, Unit 1	50-282	72
Oconee Nuclear Station, Unit 3	50-287	77	Prairie Island Nuclear Station, Unit 2	50-306	94
Ohio State Univ. Research Reactor	50-150	16	Purdue Univ. Research Reactor	50-182	18
Omaha Veterans Administration Hospital Research Reactor	50-131	14	Quad-Cities Station, Unit 1	50-254	38
Oregon State Univ.	50-106	13	Quad-Cities Station, Unit 2	50-265	48
Oregon State Univ. Research Reactor	50-243	28	Rancho Seco Nuclear Generating Station	50-312	99
Oyster Creek Nuclear Power Plant	50-219	22	Reed College Research Reactor	50-288	80
Palladas Nuclear Plant	50-255	39	Rhode Island & Providence Plants AEC	50-193	19
Palo Verde Nuclear Station, Unit 1	STN-50-528	256	River Bend Station, Unit 1	50-458	223
Palo Verde Nuclear Station, Unit 2	STN-50-529	257	River Bend Station, Unit 2	50-459	224
Palo Verde Nuclear Station, Unit 3	STN-50-530	258	Rockwell International Corp. Critical Facility	50-147	16
Palo Verde Nuclear Station, Unit 4	STN-50-592	268	Rockwell International Research Reactor	50-94	12
Palo Verde Nuclear Station, Unit 5	STN-50-593	268	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	28
Pawling Research Reactor	50-54	11	RPI Critical Experiment	50-225	25
Peach Bottom Atomic Power Station, Unit 1	50-171	18	Salem Nuclear Generating Station, Unit 1	50-272	58
Peach Bottom Atomic Power Station, Unit 2	50-277	64	Salem Nuclear Generating Station, Unit 2	50-311	97
Peach Bottom Atomic Power Station, Unit 3	50-278	66	San Onofre Nuclear Station, Unit 1	50-206	19
Pebble Springs Nuclear Plant, Unit 1	50-514	249	San Onofre Nuclear Station, Unit 2	50-361	173
Pebble Springs Nuclear Plant, Unit 2	50-515	249	San Onofre Nuclear Station, Unit 3	50-362	174
Pennsylvania State Univ. Research Reactor	50-5	7	Saxton Nuclear Experimental Facility	50-146	16
Perkins Nuclear Station, Unit 1	STN-50-488	234	Seabrook Nuclear Station, Unit 1	50-443	211
Perkins Nuclear Station, Unit 2	STN-50-489	235	Seabrook Nuclear Station, Unit 2	50-444	212
Perkins Nuclear Station, Unit 3	STN-50-490	236	Sequoyah Nuclear Plant, Unit 1	50-327	139
Perry Nuclear Power Plant, Unit 1	50-440	210	Sequoyah Nuclear Plant, Unit 2	50-328	141
Perry Nuclear Power Plant, Unit 2	50-441	211	Shearon Harris Nuclear Power Plant, Unit 1	50-400	194
Philips Bond Nuclear Plant, Unit 1	50-553	262	Shearon Harris Nuclear Power Plant, Unit 2	50-401	196
Philips Bond Nuclear Plant, Unit 2	50-554	263	Shearon Harris Nuclear Power Plant, Unit 3	50-402	197
Pilgrim Nuclear Power Station, Unit 1	50-293	81	Shearon Harris Nuclear Power Plant, Unit 4	50-403	198
Pilgrim Nuclear Power Station, Unit 2	50-471	229	Shoreham Nuclear Power Station	50-322	131
Pilgrim Nuclear Power Station, Unit 3	50-472	230			
Plum Brook Research Reactor Facility	50-30	11			
Point Beach Nuclear Plant, Unit 1	50-266	49			

Name	Docket	Page	Name	Docket	Page
South Texas Nuclear Power Project, Unit 1	STN-50-522	254	UCLA Training Reactor	50-142	16
South Texas Nuclear Power Project, Unit 2	STN-50-523	255	UC-Santa Barbara Research Reactor	50-433	208
South Texas Project, Unit 1	STN-50-498	239	Univ. of Arizona Research Reactor	50-113	13
South Texas Project, Unit 2	STN-50-499	241	Univ. of California Research Reactor	50-84	12
Space Radiation Research Reactor	50-187	18	Univ. of California Research Reactor	50-224	25
Stanford Univ. Research Reactor	50-141	16	Univ. of Florida Training Reactor	50-83	17
Stirling Power Project, Nuclear, Unit 1	STN-50-485	233	Univ. of Illinois Research Reactor	50-151	16
St. Louis Plant, Unit 1	50-335	151	Univ. of Kansas Research Reactor	50-148	16
St. Louis Plant, Unit 2	50-389	188	Univ. of Lowell Research Reactor	50-223	25
Swampscott Nuclear Power Station, Unit 1	50-450	219	Univ. of Maryland Research Reactor	50-166	18
Swampscott Nuclear Power Station, Unit 2	50-451	219	Univ. of Michigan Research Reactor	50-2	6
Swire Power Station, Unit 1	50-280	67	Univ. of Missouri Research Reactor	50-123	13
Swire Power Station, Unit 2	50-281	70	Univ. of Missouri Research Reactor	50-186	18
Savannah Steam Electric Station, Unit 1	50-387	186	Univ. of New Mexico Research Reactor	50-252	38
Savannah Steam Electric Station, Unit 2	50-388	187	Univ. of Oklahoma Research Reactor	50-112	13
SWISSAR-P1	STN-50-495	239	Univ. of Texas Research Reactor	50-192	19
Texas A & M Univ. Research Reactor	50-59	13	Univ. of Utah Research Reactor	50-72	12
Texas A & M Univ. Research Reactor	50-128	14	Univ. of Utah Research Reactor	50-407	201
Texas A & M Univ. Research Reactor	50-129	14	Univ. of Virginia Cavender Reactor	50-396	193
Three Mile Island Nuclear Station, Unit 1	50-289	80	Univ. of Virginia Research Reactor	50-62	11
Three Mile Island Nuclear Station, Unit 2	50-320	108	Univ. of Washington Research Reactor	50-139	16
			Univ. of Wisconsin Research Reactor	50-156	17
			U.S. Geological Survey Research Reactor	50-274	61
			Vallecitos Boiling Water Reactor	50-18	9
			Vallecitos Experimental Superheat Reactor	50-183	18
			Vermont Yankee Nuclear Power Station	50-271	57
			Virgil C. Summer Nuclear Station, Unit 1	50-395	192
			Virginia Polytech Inst. Training Reactor	50-124	14
			Washington State Univ. Research Reactor	50-27	10
			Watford Generating Station, Unit 3	50-382	185
			Watts Bar Nuclear Plant, Unit 1	50-390	189

Name	Docket	Page	Name	Docket	Page
Watts Bar Nuclear Plant, Unit 2	50-391	191	WPPSS Nuclear Project, Unit 1	50-460	224
Westinghouse Critical Experiment	50-87	12	WPPSS Nuclear Project, Unit 2	50-397	193
Westinghouse Test Reactor	50-22	9	WPPSS Nuclear Project, Unit 3	STN-50-508	246
West Valley Reprocessing Plant	50-201	19	WPPSS Nuclear Project, Unit 4	50-513	248
William B. MacGuire Nuclear Station, Unit 1	50-369	180	WPPSS Nuclear Project, Unit 5	STN-50-509	247
William B. MacGuire Nuclear Station, Unit 2	50-370	182	Yankee-Rowe Nuclear Power Station	50-29	10
William H. Zimmer Nuclear Station, Unit 1	50-358	170	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	266
Wolf Creek Generating Station	STN-50-482	230	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	266
Worcester Polytech Inst. Research Reactor	50-134	16	Zion Nuclear Power Station, Unit 1	50-295	82
			Zion Nuclear Power Station, Unit 2	50-304	91

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-036 SHEFFIELD, IL. NUCLEAR ENGINEERING CO

7905100223 Motion by licensee for emergency action to reach NRC 790320 order to show cause. Sent to refer matter to ASL. Affidavit of 10 Best encl
COMBET, T. B. Counsel, Moore & Corber 79/02/22 1pp

7905100110 Response to 790320 order to show cause. Order should be found voidable any violation of license Certificate of Rev encl
COMBET, T. B. Counsel, Moore & Corber 79/03/23 7pp

7905100372 Response to ASL 790313 directive. Censure w/NRC 790320 motion that license applications may only be withdrawn per NRC. Censure & conditions request to file instanter. Affidavit of ASL. Certificate of Rev encl
MCDOTT, M. J. NUCLEAR, S. M. Illinois, State of 79/03/26 10pp

7905100248 NRC response to licensee's motion for emergency action. Urges denial of request to rescind 790320 order to show cause why licensee should not resume obligations under its supporting documentation & Certificate of Rev encl
NEIS, E. J. Branch 3 79/04/02 26pp

7905030168 Forward Bureau County Circuit Court. Licensee granting preliminary injunctive relief re operation of facility
NEIS, E. J. Branch 3 79/04/03 5p

--7905030171 Order granting preliminary injunctive relief & ordering licensee to take certain action re facility
NEIS, E. J. Illinois, State of 79/03/27 7pp

7905100237 Post-hearing brief submitted by licensee re issues arising from 790327 oral argument before ASL. Responds to positions of NRC & State of IL. Certificate of Rev encl
COMBET, T. B. Counsel, Moore & Corber 79/04/03 25pp

7905100138 Proposed corrections to transcript of 790327 oral argument in Peoria, IL. Certificate of Rev encl
COMBET, T. B. Counsel, Moore & Corber 79/04/03 4pp

7905100153 FDA request for all records, studies, correspondence & notes re decommissioning of reactor & shipping of decommissioned waste to Sheffield IL low level nuclear waste site
HAMELL, G. Illinois, State of 79/04/05 4pp

7905100151 Replies to applicant's motion for emergency action & to applicant's answer to show cause. Supporting documentation & Certificate of Rev encl
HAMELL, G. Illinois, State of 79/04/05 9pp

7905100172 Response to 790313 letter re Nuclear Engineering Co illegal abandonment of Sheffield, IL low level nuclear waste burial ground. Forward 790320 order to show cause why company should not resume responsibilities & obligations
DISCHER, M. J. Office of Nuclear Material Safety & Safeguards 79/04/09 2pp

--7905100181 Expresses concern w/illegal abandonment by Nuclear Engineering Co of its Sheffield, IL nuclear waste site. Requests NRC intervene to secure site until matter of responsibility is adjudicated
SCHWED, V. Illinois, State of, 79/03/13, 3p.

7905240299 Lists conditions by which proceeding may be dismissed relevant to site decommissioning & protection of public health & safety
NEIS, E. J. Branch 3, 79/04/10, 3pp.

7905100192 Response by Intervenor Bureau County, IL to ASL 790327 hearing. State of IL licensee is jointly responsible for maintenance of waste disposal site. Certificate of Rev encl
HARDEN, B. Illinois, State of 79/04/10, 7pp.

7905070354 Forward 790320 letter discussing inop of License 12-10042-01 on 790320, 16-21-23 & 29 letter referenced in reply to applicant's motion for emergency action & applicant's order to show cause
HAMELL, G. Illinois, State of, 79/04/11, 1p.

7905050187 Response to 790327 letter re plans to prepare NRC for low level radioactive waste burial ground. EIL has been delayed because applicant has withdrawn its application & has not complied w/requirements for add info
COMBET, T. B. Office of the Executive Director for Operations 79/04/12 3pp

7905100372 Forward signed affidavit by M. Bell of Low Level Waste Branch to be included in NRC response to licensee's motion for emergency action to replace earlier assigned version
NEIS, E. J. Branch 3 79/04/12 4pp

7905100372 Dismisses conditions precedent to Nuclear Engineering Co withdrawal of application & termination of activities. Licensee should fulfill obligations supporting documentation & Certificate of Rev encl
HAMELL, G. M. Illinois, State of 79/04/12 43pp

7905100304 Sites objections to draft interim bench position re low level waste burial ground site closure & stabilization. Most of position is reasonable
NEIS, E. J. & Chem-Nuclear Systems, Inc 79/04/12 3pp

7905100379 Grants NRC & intervenor's motion to dismiss license amendment for site expansion. Denies licensee's motion for withdrawal of application for license renewal & motion to dismiss proceedings
LITTLE, M. W. NRC, J. C. SCHWED, A. C. Atomic Safety and Licensing Board Panel 79/05/03 4pp

7905100153 Partial response to FDA request for records re decommissioning of reactor & shipping of decommissioned waste. Lists forwarded from IL Dept of Public Health & 790301, 790304, 790314, 790320 & 790327 encl
POLLACK, M. Division of Rules and Records 79/05/07 4pp

DOCKET 27-047 SHEFFIELD, IL. CHEM-NUCLEAR SYSTEMS

7905240354 Request that Condition 12 contained in Amend 12 to License 12-13536-10 be retained in future license amendments re U-235 waste burial
COMBET, T. B. Chem-Nuclear Systems, Inc 79/01/10 1p

7905240326 Dismisses request for amend to License 12-13536-10 which would permit local pump range monitors containing plutonium. Prior to amend licensee written permission from EC for plutonium burial must be obtained
BRACKETT, K. S. Low Level Waste Branch (Re 790301) 79/04/04 5p

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 45-0079 UNION CARBIDE CORP

7905050551 Requests amend to License 504-648 to permit receiving & processing of carbonate activation shipments to be begin
790510
DISCHER, P. C. Union Carbide Corp 79/03/29 1p

7905240280 Comments on SEC corrects factual errors in meeting. Planned monitoring program should be adequate
DISCHER, P. C. Hearing, State of 79/03/30 1p

7905240132 Forward 790325 "Environ Assessment of Below Grade U Tailing Disposal in A-9 Open Pit East Oak Hills U Mine & Mill." for Union Carbide Corp
MURDOCK, L. T. Dames & Moore 79/04/10, 1p

--7905240136 "Environ Assessment of Below Grade U Tailing Disposal in A-9 Open Pit East Oak Hills U Mine & Mill." for Union Carbide Corp
MURDOCK, L. T. Dames & Moore 79/04/11 11pp

7905100465 Summary of 790501 meeting w/Union Carbide Corp in Silver Spring, MD re comments on SEC
DISCHER, P. C. Assistant Director for Waste Management (Re 790501) 79/04/16, 4pp.

DOCKETED ITEMS

- 7905200032 Provides supplemental info requested in 790016 telcon re East Coast Hills Area 2400
RICHARDSON, P. C. Union Carbide Corp. 79/04/17 App
- 7905200113 Forwards supplemental info re Morris Hill license/drawings of proposed area (each & description of reclamation plans & costs overlaid drawings and
RICHARDSON, P. C. Union Carbide Corp. 79/04/19 App
- DOCKET 40-1162 WESTERN NUCLEAR, INC.
DOCKETED BY: 79/04/19
- 7905200209 Forwards info requested by 790016 telcon re radionuclide samples from Deep Mountain TX Marsh
BERLIN, D. Western Nuclear, Inc. (subs. of Philip Dodge Corp.) 79/05/09 App
- 7905200147 Requests determination of need for new draft prior to approval of Tellings map app
RICHARDSON, P. C. Western Nuclear, Inc. (subs. of Philip Dodge Corp.) 79/04/06 App
- 7905200402 Forwards add'l copies of map showing location of wells & well water monitoring results for 1977-78
RICHARDSON, P. C. Western Nuclear, Inc. (subs. of Philip Dodge Corp.) 79/04/16 App
- 7905200407 Forwards map & chart showing location of wells & well water monitoring results for 1977-78
RICHARDSON, P. C. Western Nuclear, Inc. (subs. of Philip Dodge Corp.) 79/04/09 App
- DOCKET 40-2041 WEST CHICAGO FACILITY, KERR-McOEE CORP.
DOCKETED BY: 79/04/12
- 7905200564 Confirms 790404 discussion re encl. comments on decommissioning plan submitted is not acceptable due to lack of detail for preparation of EIR outlines major deficiencies suggested format for plan
CARROLL, T. Fuel Process & Fuel Branch 79/04/12 App
- 7905200571 Forwards Region III comments on Kerr-McOee decommissioning plan thickness of "slag structure" should be stated.
which criteria for radiologically should be specified & "air structure" should be stated.
RICHARDSON, P. C. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/05/08 App
- 7905200572 Forwards comments on Kerr-McOee decommissioning plan M/s encl.
CARROLL, T. West Chicago, IL 79/05/14 App
- 7905200589 Summary of activities of IL State Geological Survey & data collected in attempts to locate suitable site for disposal of thorium-bearing solid wastes from Kerr-McOee facility.
CARROLL, T. Illinois, State of 79/05/13 App
- 7905200594 Forwards "Lines on Boundary Landfills & Chemical & Petroleum Waste Disposal Sites." 790409-790505, Reg. 107D, in response to 790016 meeting re decommissioning at Kerr-McOee Facility M/s encl.
RICHARDSON, P. C. Environmental Protection Agency 79/05/16 App
- 7905200614 Requests amend to 790038 request re thorium radionuclides in West Chicago decommissioning plan for West Chicago facility should be resolved within six months of date of Rtr.
RICHARDSON, P. C. West Chicago, IL 79/05/16 App
- DOCKET 40-2209 PATHFINDER MEDICAL CORP.
DOCKETED BY: 79/05/07
- 7905200609 Amends License RM-072 to change name of licensee, modify radionuclide drug & packaging div. collection type & handling area
RICHARDSON, P. C. Radiotopes Licensing Branch (P/O 790503) 79/05/22 App
- 7905200611 Recommends approval of Pathfinder Medical Corp's request for Amend. to License RM-072 authorizing made to most collection type, handling radionuclide drug & packaging area.
RICHARDSON, P. C., RICHARDSON, L. M. Radiotopes Licensing Branch (P/O 790501) 79/05/22 App
- 7905200609 Forwards ABC positions & second round request for add'l info re geology & geotechnical engineering of tellings radonion
RICHARDSON, P. C. Radiotopes Licensing Branch (P/O 790501) 79/05/23 App
- 7905200176 Review of 790016 responses to requests for info have been completed & determined to be inadequate. Forwards request for add'l info re probable max. rad. rainfall value & area draining into pond associated w/ponded Tellings Dam Addition 2
RICHARDSON, P. C. Fuel Process & Fuel Branch 79/04/09 App
- 7905200408 Forwards request for add'l info to complete radiological assessment for amend request. Requests responses by 790016
RICHARDSON, P. C. Division of Fuel Cycle & Materials Safety 79/04/10 App
- 7905200609 Responds to 790038 ltr. Provides clarification & add'l info re Tellings dam plan, including area radiological inventory.
RICHARDSON, P. C. Pathfinder Medical Corp. 79/04/03 App
- DOCKET 40-2407 PATHFINDER MEDICAL CORP. CO. INC.
DOCKETED BY: 79/05/09
- 7905200113 Responds to PDS request for info re Thorotrast, its license imp. manufacturing & licensees. Forwards radonion contained in Docket 40-2307
RICHARDSON, P. C. Division of Rules and Records 79/05/09 App
- 7905200132 Notifies Source. Mail License RM-070 for Follow Medical M/s encl. is terminated. Forwards 491110 ltr. radiation survey & evaluation result re radonion preparation
RICHARDSON, P. C. Atomic Energy Commission (P/O 1975) 49/12/01 App
- 7905200197 Notifies of issuance of License C-0150 for Tellings & Co. authorizing use of thorium sulfate in mfg. of Thorotrast & Unbraker
RICHARDSON, P. C. Atomic Energy Commission (P/O 1975) 49/12/10 App
- 7905200204 Notifies of issuance of License R-152 for Tellings & Co. authorizing use of thorium sulfate in mfg. of Thorotrast & Unbraker
RICHARDSON, P. C. Atomic Energy Commission (P/O 1975) 49/12/03 App
- 7905200204 Notifies of issuance of License R-152 for Tellings & Co. in authorizing thoron sulfate for use in mfg. of Thorotrast & Unbraker
RICHARDSON, P. C. Atomic Energy Commission (P/O 1975) 49/12/07 App
- 7905200214 Requests termination of License RM-078. Pigs at 1336 M. LaSalle, Southwestern Bell, MI. should be released from license for destruction
CARROLL, T. M. Follow Medical Mfg. Co., Inc. Follow-Tellings Div. 49/12/03 App
- 7905200219 Requests report indicating that radiological limits of 4000 ltr have been met. Application for license amend to be filed re proposed activities at new locations. Encl. radiological limits set.
RICHARDSON, P. C. Atomic Energy Commission (P/O 1975) 49/12/04 App
- 7905200230 Requests add'l info on procedures for evaluating personal exposure to airborne radionuclides in response to 49001 application for renewal of License RM-078
LAFFERTY, R. L. Atomic Energy Commission (P/O 1975) 49/12/02 App
- 7905200256 Requests renewal of License RM-078
CARROLL, T. M. Follow Medical Mfg. Co., Inc. Follow-Tellings Div. 49/12/11 App
- 7905200219 Requests max quantity of waste shall be change from 100 to 300 lb to maintain production levels
CARROLL, T. M. Follow Medical Mfg. Co., Inc. Follow-Tellings Div. 49/12/07 App
- 7905200320 Advises that licensee dissolved. 490021 merger approved w/ Follow Medical Mfg. Co. Inc. New name as of 4/30/82 is Follow-Tellings Co. Officers remain same, except for secretary & treasurer positions. Mfg. to be done in Detroit.
CARROLL, T. M. Follow Medical Mfg. Co., Inc. Follow-Tellings Div. 49/12/03 App
- 7905200342 Requests 490021 request for info re license renewal. Is determine if source info meets 490021 criteria
CARROLL, T. M. Atomic Energy Commission (P/O 1975) 49/05/23 App
- 7905200345 Clarifies that request is for renewal of license as 490011 as application for new license
CARROLL, T. M. Follow Medical Mfg. Co., Inc. Follow-Tellings Div. 49/05/03 App

DOCKETED ITEMS

3

- 7905200378 Requests info necessary for application for renewal of License R-152 Application must include max quantity of matl to be processed, safeguard procedure, list of survey instruments & methods of radioactive waste disposal
MUSSEBAUMER, D. A. Atomic Energy Commission (Pre 1975) 61/09/02 1p
- 7905200351 Requests renewal of License R-152
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/03/28 1p
- 7905200353 Requests renewal of License R-152
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/06/02 1p
- 7905200357 Requests renewal of License R-152
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 59/08/18 1p
- 7905200370 Responds to 590314 request for info re License R-152 Thorium suitable to be used for medical profession personnel handling matl user gown, protective mask & work in isolated room
Matl measured solely by badge
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 59/04/10 2pp
- 7905200374 Responds to licensee 590320 1st Requester submital of info requested in AEC 500314 1st before renewal of source matl license can be considered
DELAUNEY, J. C. Atomic Energy Commission (Pre 1975) 59/04/01 1p
- 7905200390 Application for renewal of License R-152 authorizing use of thorium suitable in mag media
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 56/11/26 2pp
- 79052003139 Forwards renewed Source Matl License STD-478
MUSSEBAUMER, D. A. Atomic Energy Commission (Pre 1975) 61/03/05 1p
- 79052003145 Source Matl License STD-478 For Feltous Medical Mfg Co. Inc authorizing use of thorium as described in 400324 application
MUSSEBAUMER, D. A. Radiotopes Licensing Branch (Pre 790501) 61/03/24 1p
- 79052003150 Forwards renewed Source Matl License STD-478
MUSSEBAUMER, D. A. Atomic Energy Commission (Pre 1975) 61/04/12 1p
- 79052003160 Source Matl License STD-478 For Feltous-Testtager Co authorizing use of thorium as described in 610607 & 610618 applications
Radiotopes Licensing Branch (Pre 790501) 61/04/12 2pp
- 79052003164 Forwards Source Matl License STD-478
MUSSEBAUMER, D. A. Atomic Energy Commission (Pre 1975) 61/01/23 1p
- 79052003177 Source Matl License STD-478 For Feltous-Testtager Co authorizing use of U & thorium as described in 610607, 610725, & 610818 applications
MUSSEBAUMER, D. A. Radiotopes Licensing Branch (Pre 790501) 61/01/23 1p
- 79052003183 Forwards Source Matl License STD-478
MUSSEBAUMER, D. A. Atomic Energy Commission (Pre 1975) 61/02/25 1p
- 79052003193 License STD-478 For Testtager & Co, Inc authorizing use of thorium as described in 610607, 610727, & 610818 application
MUSSEBAUMER, D. A. Radiotopes Licensing Branch (Pre 790501) 61/02/25 1p
- 79052003202a Notifies of equipment for mfg of Thorotrast to be eliminated, stored, or disposed within next two months
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/03/07 1p
- 79052003203 Application for renewal of License STD-478 authorizing use of thorium in mfg of sterile mag contrast medium
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/03/14 2pp
- 79052003205 Approves extension of time for submission of info requested in 610328 1st
LAWFILL, R. L. Atomic Energy Commission (Pre 1975) 61/11/12 1p
- 79052003204 Ack receipt of AEC 640818 1st Evaluation of personnel radiation exposure accomplished by readings of personnel badges & urine analyses Lab used once periodically Survey met
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/09/11 2pp
- 79052003270 Requests addl info on procedures for evaluating personnel exposure to airborne radioactivity & airborne activity in exhaust fan effluents in response to 640712 application for renewal of License STD-478
LAWFILL, R. L. Atomic Energy Commission (Pre 1975) 61/08/10 2pp
- 79052003276 Application for renewal of License STD-478 authorizing use of thorium suitable in mfg of sterile mag contrast
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/07/15 2pp
- 79052003291 Requests replies to AEC 620312 questions Amend to License STD-478 to be filled on Form AEC-2
MUSSEBAUMER, D. A. Atomic Energy Commission (Pre 1975) 61/07/24 1p
- 79052003297 Inquires whether current source matl license needs to be amended to recognize handling of mag media
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/07/09 1p
- 79052003306 Discusses AEC 620312 1st requesting addl info re application for amend of License STD-478 Detrital Health Dept called to assist in evaluation
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/04/15 1p
- 79052003312 Requests addl info re amend of License STD-478 authorizing use of addl 250 lb of thorium Requires description of procedures for evaluating personnel exposure to airborne activity & decontamination control within lab
MUSSEBAUMER, D. A. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/06/12 1p
- 79052003320 Submits info as amend to Parts 6.2 & D of 610607 application for License R-152 Max quantity of source matl to be processed is 100 lb Detrital Health Dept contains CE 72292 Conf
Respirator dust filter
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/06/18 2pp
- 79052003322 Informs licensee not yet received Requester assurance of license or reasons for not receiving license
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/07/27 1p
- 79052003328 Applies for renewal of License R-152
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/06/07 2pp
- 79052003330 Ack receipt of AEC 590318 1st re renewal of License R-152 Data indicates controls & safety precautions in order Inquires whether written part of imp desired
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 61/03/20 2pp
- 79052003383 Requests addl info on activities, safeguard procedures, survey instrument description & method of waste disposal in response to 500304 application for renewal of License R-152
DELAUNEY, J. C. Atomic Energy Commission (Pre 1975) 50/03/14 1p
- 79052003388 Requests renewal of License R-152
CARRISMAN, R. H. Feltous Medical Mfg Co., Inc. Follow-up-Testtager Div 59/03/04 1p

DOCKET 40-3392 ALLIED CHEMICAL CORP

- 7905200109 Forwards info requested by AEC 790115 1st & 790326 memo re compliance of Metropolitan, IL waste w/requirements of 40CFR170 Benth emission & Long fluid solubility data sent.
NEWMAN, R. I. Allied Chemical Corp. 79/03/22 20pp
- 7905200630 Ack receipt of 790415 1st Informing AEC of steps taken to correct violations noted in CE Inspect 60-3292/29-01
SMITH, A. E. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/24 1p

DOCKETED ITEMS

5

7905000232 Forwards requested drawing showing tailing reservoir after reclamation per 790404 request. Drainage from tailing cover reversed in flow south to diversion cut. Drainage can reduced in flow from D 1 to D 2. Overlaid drawings attached. AMERGEN, R. Rocky Mountain Energy Co. 79/04/05. 3pp

7905000233 Forwards requested flow sheet for mill process changes relate to process amplification improvements or necessary addition to handle tailing area. Overlaid drawing attached. AMERGEN, R. Rocky Mountain Energy Co. 79/04/07. 1p

DOCKET 40-0502 TREASURY MINE, JENNINGS MINING CORP.

7905000234 Recommends Amend 1 to License SUA-1384 be approved to authorize in situ U solution extraction & recovery of natural U using calcium-magnesium-carbonate/bicarbonate & sodium ion within licensed solution extraction area. OGDENSTEIN, R. Radiological Licensing Branch (PFA 7905001) 79/04/10. 3pp

7905000237 Forwards 790405 ltr to DOE requesting med of NY State Mine Permit. GINSBERG, R. Mining Mineral Corp. 79/04/26. 3pp

DOCKET 40-0504 UNION & MINERALS EXPLORATION CO.

7905000238 Summary of 790306 meeting w/Minerals Exploration Co. in Silver Spring, MD re minor amend to License SUA-1390 & geophysical monitoring program. LINDMAN, J. Assistant Director for Waste Management (PFA 7905001) 79/04/16. 2pp

7905000239 Inform that geosurvey expenditure required for review of Amend 1 to License SUA-1350 calls for smaller amend for then fee which was sent. Refund will be made. MILLER, D. License Fee Management Branch 79/04/24. 1p

DOCKET 40-0602 UNITED NUCLEAR CORP.

7905000241 Response to NRC 790409 request. Submit comments of United Nuclear Corporation. Exploration Drilling Co/UNR report re planned U milling facility at Hutton Beach property. MELP, C. E. United Nuclear Corp. 79/04/12. 2pp

7905000242 Response to 790310 request. Forwards revisions & additions to application for U mill license w/over converted drawings. MELP, C. E. United Nuclear Corp. 79/04/20. 7pp

7905000243 Forwards revised application in response to 790422 request. Some note were made to U milling application in line of addition in source mill license. MELP, C. E. United Nuclear Corp. 79/04/22. 7pp

DOCKET 40-0603 NUCLEAR SYNTHESIS, INC.

7905000249 Amends License SUA-1391 to authorize use of alternate ammonium carbonate/bicarbonate (invariant) sys in in situ U solution extraction program. OGDEN, W. T. Fuel Process. & Fab Branch 79/03/30. 1p

7905000250 Evaluates license request to authorize in situ U solution extraction field tests w/ammonium carbonate/bicarbonate & evident sys. OGDENSTEIN, R. Radiological Licensing Branch (PFA 7905001) 79/03/30. 7pp

DOCKET 40-0605 ENERGY FUELS NUCLEAR, INC.

7905000251 Requests clarification of EIR re air pollution. W/790125 & 790220. Internal correspondence. KOSKINEN, C. Utah, State of. 79/01/23. 4pp.

7905000252 Comments on preliminary case report for Energy Fuels White Mesa U Mill. OOI memo re professional considerations surrounding inconspicuous burial of archeological site and. NEWALL, R. Interior, Dept. of. 79/04/06. 2pp

7905000253 Forwards "Research Design for White Mesa Archaeological Project". GARDNER, L. Utah, State of. 79/04/05. 22pp.

7905000254 Comments on DOE classification of containers as Type A in case of shipper, not DOT. RICHIE, M. R. Coast Guard, Transportation, Dept. of. 79/04/12. 1p.

7905000255 Forwards supplemental archeological report re stockpile area re west of wellings area. BARNER, C. E. Energy Fuels Nuclear, Inc. 79/04/16. 14pp

7905000256 Forwards report re findings of recent archeological survey of eastern half of northeast quarter of Section 30. Re further archeological work required. BARNER, C. E. Energy Fuels Nuclear, Inc. 79/04/25. 4pp

7905000257 Summary of 790409-11 trip to DNL to review DOE reflecting finalized NRC comments. TRAGER, E. A. Radiological Licensing Branch (PFA 7905001) 79/04/26. 1p

7905000258 Forwards requested eligibility determination for earth dam in San Juan County, UT to be included in Nats Register of Historic Places info should be integrated into NEPA analysis. MORTIS, U. J. Interior, Dept. of. 79/05/01. 14pp

7905000259 Requests determination of area eligibility re archeological district. For Natl Register. Forwards State of UT 790304 ltr describing eligibility. OGDEN, R. A. Fuel Process. & Fab Branch 79/04/20. 3pp

7905000260 Approves proposed name of agreement w/White Mesa, San Juan County, UT, except items re obligations of developer. KOSKINEN, J. P. Utah, State of. 79/05/02. 1p

DOCKET 40-0603 OGLE PETROLEUM, INC.

7905000261 Forwards quarterly report for License SUA-1336. GATCHEL, G. J. Ogle Petroleum, Inc. 79/04/10. 23pp

DOCKET 40-0605 PLATEAU RESOURCES, LTD.

7905000262 Inform of completion of EIR review. No comments at this time. BARNER, C. E. Agriculture, Dept. of. 79/03/12. 1p

7905000263 Offers no specific comments on DOE INURE-09241. MCNULTY, D. Agriculture, Dept. of. 79/03/30. 1p

7905000264 Suggests granting source mill license project will help solve problems of economically depressed area. OGDEN, P. D. Utah, State of. 79/03/30. 1p

7905000265 Comments on DOE boundaries of San Juan Natl Recreational Area are incorrectly shown. BERNHARD, M. B. Woodward-Clyde Consultants. 79/04/04. 11pp

7905000266 Forwards UT state agency comments on DOE EIR-0924. Utah, State of. 79/04/04. 11pp

7905000267 Forwards "Analysis of Shoshone Canyon U Project". LECHITT, W. A. Affiliation Unknown. 79/04/08. 11pp

7905000268 Comments re DOE recommends NRC contact Regional Director of Fish & Wildlife, DE, Denver, CO for guidance re endangered American peregrine falcon. MERRITT, T. E. Interior, Dept. of. 79/04/09. 8pp

7905000269 Forwards documents containing comments & questions re DOE INURE-09241. W/00003. BOSTWELL, J. E. Division of Fuel Cycle & Material Safety. 79/04/10. 2pp

7905000270 Requests approval of application for source mill license for Shoshone Canyon U Project. Project would be beneficial to economically depressed area. MERRITT, T. E. House of Rep. 79/04/11. 2pp

7905000271 Supports conclusions of DOE INURE-09241. GARDNER, L. Senate. 79/04/12. 1p

7905000272 Forwards DOE 790419 comments on DOE. Requests appropriate reply. BOSTWELL, J. E. Uranium Recovery Licensing Branch. 79/04/13. 1p.

7905000273 Forwards 790310 ltr describing county economic conditions & significance of mine-mill complex & tourist. Wager to see project underway. KOSKINEN, J. P. San Juan County, UT. 79/04/19. 4pp.

DOCKETED ITEMS

790310200 Forwards response to comments on OER Requests revised language for PCB
 SHELL M R. Fluke Resources, Ltd 79/04/26 3pp

DOCKET NO-8714 CLEVELAND CLIFFS BROW CO

790500010 Summary of 790410 meeting w/Cleveland-Cliffs Iron Co in Silver Spring, MD re source metal license for Cellulos Brown, NY site applicant's draft radiation monitoring plan; permit application & guidelines for U extraction. RSD
 COOPERSTEIN, R. Radiological Licensing Branch (FPA 790501) 79/04/13 2pp

DOCKET NO-8723 ROCKY MOUNTAIN ENERGY CO

790510004 Summary of 790320 meeting w/Rocky Mountain Energy Co in Silver Spring, MD re commercial waste U solution extraction proposal & uranium rep.
 COOPERSTEIN, R. Fuel Process & Fab. Branch 79/05/08 2pp

DOCKET NO-8722 DUGH-WELLMAN, INC

790300000 Responds to 790412 letter Violation of health rules has never been documented at plant
 ANDERSON, L. P. Utah, State of 79/04/13 1p

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET NO-2 UNIV OF MICHIGAN RESEARCH REACTOR

1 Insurance & indemnity information

790510001 Forwards Amend 10 to Indemnity Agreement E-26 per 10CFR140 changes re increase from \$140 million to \$160 million effective 790501 Supporting documentation and
 BALTFRANK, J. Antitrust & Indemnity Group 79/05/01 3pp

F Operating license stage documents & correspondence

790500008 Requests exemption of small quantities of SNM from proposed upgrade rules for research reactors
 BURNS, R. Michigan, Univ of 79/05/04 1p

790500007 Requests exemption for small quantities of SNM from proposed upgrade rule for research reactors
 BURNS, R. Michigan, Univ of 79/05/04 1p

790501000 Forwards GA program & procedures for handling SNM-1 shipping package 9937
 FARR, M. Michigan, Univ of 79/05/14 1p

--790500006 GA program for Ford Nuclear Reactor
 Michigan, Univ of 79/05/14 1pp

DOCKET NO-3 INDIAN POINT STATION, UNIT 1

0 Adjudicatory correspondence

790510002 Forwards compilation of Board notifications re licensee regulatory performance evaluation for distribution to all appropriate licensing boards
 PATCHEL, M. Branch A 79/05/28 23pp

J Insurance & indemnity information

790500007 Confirms increased liability limits re \$126,000,000 for policies AP-120, 83, 76, 85, 100, 111, 140, 146, 181, 181, 184, 175, 175, 174, 170, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215 & others
 BALTFRANK, J. American Nuclear Insurers 79/05/01 1p

790500002 Confirms increase in liability limits re \$100,000,000 for policies AP-22, 24, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

790510007 Forwards Amend 21 to Indemnity Agreement B-19 per 10CFR140 changes re increase in liability insurance from \$100 million to \$160 million effective 790501 Supporting documentation and
 BALTFRANK, J. Antitrust & Indemnity Group 79/05/01 4pp

F Operating license stage documents & correspondence

790500004 Ack receipt of NRC 790410 ltr willing to cooperate in planned analysis scheduled for week of 790504
 CHALL, M J. Consolidated Edison Co of New York 79/04/20 1p

0 Inspection reports, EE Bulletins & correspondence

790500005 Forwards IE Info Notice 79-07, "Status of Radiactive Tanks"
 GRIDER, S H. Region 1, Philadelphia, Office of the Director 79/05/26 1p

790500006 Response to IE Bulletin 79-02 re longitudinal weld defects in certain pipe joints w/2 by Thompson Welding & Engineering Co piping not used in Unit 3 info re Unit 3 will be provided when returned to svc
 CHALL, M J. Consolidated Edison Co of New York 79/04/13 3pp

790500007 Forwards IE Bulletin 79-07, "Status of Radiactive Tanks of Safety-Related Piping" Licensee action required
 GRIDER, S H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

790500008 Forwards IE Bulletin 79-08, "Review of Operational Errors & Re Misalignments Identified During TMI Incident"
 GRIDER, S H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

790500009 Forwards IE Bulletin 79-08, "Status of Radiative Tanks of Safety-Related Piping" Licensee action required
 GRIDER, S H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

790500010 Forwards IE Bulletin 79-09, "Failures of OE Type AW-2 Circuit Breaker in Safety-Related Bays" Licensee action required
 GRIDER, S H. Region 1, Philadelphia, Office of the Director 79/04/17 1p

--790500011 IE Bulletin 79-09, "Failures of OE Type AW-2 Circuit Breaker in Safety-Related Bays" Extract of OE Bsc Ltr 79/04/17 3 pcc
 Office of Inspection & Enforcement 79/04/17 10pp

790500012 Forwards IE Bulletin 79-09A/Revision 1, "Review of Operational Errors & Re Misalignments Identified During TMI Incident"
 GRIDER, S H. Region 1, Philadelphia, Office of the Director 79/04/18 1p

790500013 Ack receipt of 790521 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 79-003/79-13 & 79-007/79-28
 SMITH, S H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/04 2pp

--790500014 Responds to NRC 790521 ltr re violation noted in IE Insp Repts 79-003/79-13 & 79-007/79-28 corrective actions
 CHALL, M J. Consolidated Edison Co. of New York 79/05/21 3pp

--790500015 Forwards IE Insp Repts 79-003/79-13 & 79-007/79-28 re 790521-29 & 790517-10 & notice of violation
 SMITH, S H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/28 2pp

--790500016 Notice of violation from Insps 790521-29 & 790517-10
 Region 1, Philadelphia, Office of the Director 79/05/28 1p

--790500017 IE Insp Repts 79-003/79-13 & 79-007/79-28 re 790521-29 & 790517-10 Nonconformities noted failure to maintain personnel exposure limits in accordance w/10CFR20.101
 KELLY, D. R. Region 1, Philadelphia, Office of the Director, SECCS, H. M. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/27 10pp

H Periodic operating reports & related correspondence

790500018 Forwards effluent monitoring & impingement data specified in Section 401 of Clean Water Act for monitoring data specified
 CHALL, M J. Consolidated Edison Co. of New York 79/05/10 3pp

790500019 Forwards daily record of fish collections for Apr 1979
 Monthly species breakdown & total weight for Units 2 & 3
 GRIDER, S H. Region 1, Philadelphia, Office of the Director 79/05/14 3pp

DOCKETED ITEMS

7

7905230368 Forwards monthly operating rept for Apr 1979
CAHILL, M J Consolidated Edison Co. of New York 79/05/15 1p

--7905230367 Monthly operating rept for Apr 1979
KAMA, A L Consolidated Edison Co. of New York 79/05/04 7pp

B Reportable occurrences, LORA & related correspondence

7905230362 LER 79-001 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905230364 LER 79-003 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905230365 LER 79-004 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905230391 LER 79-005 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905230394 LER 79-006 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905230399 LER 79-007 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905230366 LER 79-008 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905230363 LER 79-009 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905230312 LER 79-010 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905230313 LER 79-011 has been voided
* Consolidated Edison Co. of New York 79/04/01 1p

7905110515 Forwards LER 79-012/043-5
CAHILL, M J Consolidated Edison Co. of New York 79/05/10 1p

--7905110510 LER 79-012/043-5 on 790515 activity of precipitation sample
exceeded 35 times control station level. Caused by tritium
release from source external to facility. Manufacturer in
area has modified installation to prevent recurrence
HMS1UAL, J Consolidated Edison Co. of New York 79/05/10 3pp

7905110521 Forwards LER 79-015/047-0
CAHILL, M J Consolidated Edison Co. of New York 79/05/10 1p

--7905110520 LER 79-015/047-0 on 790505 activity of precipitation sample
exceeded 35 times control station level. Caused by tritium
release from source external to facility. Manufacturer in
area has modified installation to prevent recurrence
HMS1UAL, J Consolidated Edison Co. of New York 79/05/10 3pp

DOCKET NO-8 PENNSYLVANIA STATE UNIV, RESEARCH REACTOR

J Insurance & indemnity information

7905140328 Forwards Amend 14 to Indemnity Agreement E-10 per 10CFR140
changes re increase from \$140 million to \$160 million.
effective 790501 Supporting documentation encl
GALTMAN, J Antitrust & Indemnity Group 79/05/01 3pp

DOCKET NO-8 BATTELLE MEMORIAL INST RESEARCH REACTOR

J Insurance & indemnity information

7905230365 Forwards Amend 14 to Indemnity Agreement E-6 reflecting
change in 10CFR140 reflecting increase in primary layer of
liability from \$140 million to \$160 million effective
790501 Supporting documentation encl
GALTMAN, J Antitrust & Indemnity Group 79/05/01 3pp

7905240391 Forwards executed Amend 14 to Indemnity Agreement E-6,
effective 790501,
STALL, S H Battelle Memorial Institute, Columbus Laboratories
79/05/14 2pp.

DOCKET NO-8 NORTH CAROLINA STATE UNIV, RESEARCH REACTOR

J Insurance & indemnity information

7905050349 Forwards Amend 15 to Indemnity Agreement E-7 reflecting
change in 10CFR140 increasing primary layer of liability
from \$140 million to \$160 million effective 790501.
Supporting documentation encl
GALTMAN, J Antitrust & Indemnity Group 79/05/01 3pp.

7905230482 Forwards Amend 15 to Indemnity Agreement E-7. Requests change
in addresses for correspondence
BOHANNON, J R North Carolina State Univ 79/05/01 3pp

DOCKET NO-10 BREIDENBACH NUCLEAR POWER STATION, UNIT 1

D HRC Draft/Final Environmental Statements, supply & correspondence

7905230334 Requests preparation of HRC for proposed chemical
decontamination experiment. Forwards pertinent questions re
radioactive corrective products, waste burial &
radioactive decontamination agents
DREY, A Affiliation Unknown 79/05/01 3pp

F Security: medical, emergency & fire protection plans

7905240412 Memoranda 790520-22 fire protection review trip Areas
inspected physical separation of redundant safe shutdown
equipment, fire hazards & facility protection features.
Forwards unanswered questions & petitions
DEBERIAN, L Plant Systems Branch 79/04/17 11pp

7905230397 Notification of 790508 meeting w/et al in Bethesda, MD to
discuss fire protection program
D'ONOFIO, F W Operating Reactors Branch 2 79/04/23 1p

7905050346 Forwards modified physical security plan, Revision 5 Plan
withheld (ref 10CFR140 7901)
LEE, P Consolidated Edison Co 79/04/26 1p

G Adjudicatory correspondence

7905050323 Forwards petition requesting E16 be prepared on proposed
decontamination experiments designed to flush radioactive
corrosion from reactor piping. WPP Reville
GENTON, H R Office of Nuclear Reactor Regulation 79/04/09 2pp

--7905230333 Plan for preparation of E16 on proposed decontamination
experiments designed to dissolve & flush out radioactive
corrosion products from reactor piping
DREY, A Affiliation Unknown 79/05/14 3pp

H General correspondence

7905195673 Forwards R Drey 790519 ltr requesting that E16 be required
before authorization is granted to flush piping at facility.
D'ONOFIO, F W House of Rep 79/04/04 3pp

J Insurance & indemnity information

7905105163 Endorsement 99 to HANU Policy NP-22
SOMER, T Nuclear Energy Liability Insurance Association 79/05/07 1p

7905200497 Confirms increased liability limit to \$124,000,000 for
policy NP-1, 23, 42, 74, 93, 103, 111, 140, 144, 151, 163, 164, 170,
173, 174, 176, 179, 180, 183, 185, 187, 188, 189, 192, 194, 195,
197, 198, 200, 201, 204, 205, 206, 214, 215, & others.
QUARTZHEIM, J American Nuclear Insurers 79/05/01 1p

7905070382 Confirms increase in liability limit to \$34,000,000 for
policy NP-23, 24, 29, 38, 39, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 81, 82,
83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96
HSEKSTED, M Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905140404 Forwards Amend 21 to Indemnity Agreement E-10 per 10CFR140
changes re increase in liability insurance from \$140 million
to \$160 million effective 790501 Supporting documentation
encl
GALTMAN, J Antitrust & Indemnity Group 79/05/01 3pp.

DOCKETED ITEMS

F Operating license stage documents & correspondence

7903030947 Forwards notes on 790303-15 & 30 conference balloons between NRC consultants & staff on Bulletin "Potential Explosive Gas Mixtures Accumulations Associated w/AR Offgas Gas Operations"
 RECD:J.D. A Operating Reactors Branch 3 79/04/16 App

7903030397 Forwards topics deleted from systematic evaluation program review of Facilities Requester review & identification of errors within 30 days from receipt of list
 ZEDHANA D L Operating Reactors Branch 3 79/04/16 App

7904270346 Summary of 790403 meeting of 22 stills operating 27 reactor plants, re planned use of ECTAN AGS simulation program Requester meeting w/NRC to assure AGS functionality w/309948
 RECD: C Commonwealth Edison Co 79/04/18 App

7905260304 Notifies them date for completion of solid waste handling site has been delayed until 790530 due to lack of manpower
 For electrical work
 JANECEK R F Commonwealth Edison Co 79/04/20 App

7905040103 Notifies of intention to develop safety analysis using existing computer code Requester add info
 SOLARIO D M Commonwealth Edison Co 79/04/24 App

7905040370 Review systematic evaluation program for shared engineered safety features: engine emergency power & aux sep duplicate unit stations
 JANECEK R F Commonwealth Edison Co 79/05/02 App

7905040273 Summarize status of completion of BFC and Bld structure complete & most equipment in use after all defective found for north electric dock run, except for Hanalei
 JANECEK R F Commonwealth Edison Co 79/05/01 App

7905050391 Forwards current licensing open items status list
 RECD: C Commonwealth Edison Co 79/05/10 App

G Inspection reports: IE Bulletin and correspondence

7903030401 Forwards responses to IE Bulletin 79-12 & 79-13A "Atypical Wind Heat in Reactor Pressure Vessel Heads"
 RECD: C Commonwealth Edison Co 79/03/22 App

7903010336 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/03/23 App

7903030370 Forwards IE Info Notice 79-07, "Regulation of Reducible Tanks"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/03/26 App

7903010135 Forwards IE Info Notice 79-08, "Indisconnection of Contaminated Gas w/Hot Air Gas Used as Source of Breathing Air"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/03/23 App

7903010304 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Salt"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/03/30 App

7903030301 Forwards IE Bulletin 79-04A, "Review of Operational Errors & Site Missalignments Identified During TH Incident"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/04/18 App

7903240448 Forwards IE Insp Repts 30-010/79-07, 30-237/79-06 & 30-241/79-07 on 790306-07, 0312 & 0303. No nonconformance noted.
 DAVIS, R. A Region 3, Chicago, Fuel Facility & Materials Safety Branch, 79/04/15 App.

--7903040454 IE Insp Repts 30-010/79-07, 30-237/79-06 & 30-241/79-07 on 790306-07, 0312 & 0303. No nonconformance noted. Major areas inspected: internal access, offsite support agency coordination, emergency facilities, welding & drills
 GRANT, W. B. RECD: J.D. A Region 3, Chicago, Office of the Director, 79/04/03 App

7903030380 Responds to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools. Plants inspecting for pipe found.
 RECD: C Commonwealth Edison Co. 79/04/12, App.

7903030349 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Site Missalignments Identified During TH Incident"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/04/18 App

7903040304 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Site Missalignments Identified During TH Incident"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/04/18 App

7903040329 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Reactor Operations Identified During TH Incident"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/04/18 App

7903030356 Forwards IE Bulletin 79-09, "Failures of SE Type AW-2 Circuit Breaker in Safety-Related Sys" License action required
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/04/17 App

7903040142 Forwards IE Bulletin 79-02B, "Nuclear Incident at TH-0001"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/04/21 App

--7903040108 IE Bulletin 79-03B, "Nuclear Incident at TH-0001"
 Supporting documentation not
 Region 3, Chicago, Office of the Director 79/04/21 App

--7903040170 AGS recommendations re 790308 incident at TH suggests AGS priority be placed on development of safety research on behavior of LMR during abnormal transients
 AGS - Advisory Committee on Reactor Safeguards 79/04/17 App

--7903040201 Forwards AGS recommendations re TH incident, presented at 790417
 FOLEY, R F AGS - Advisory Committee on Reactor Safeguards 79/04/18 App

--7903040201 In response to NRC 790418 letter, 790417 AGS recommendations apply to all PWRs but were not intended to require immediate changes. Plans should be made after study of effects on control safety. AGS enclosed
 CARROLL, H X AGS - Advisory Committee on Reactor Safeguards 79/04/20 App

7903030363 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping. Reanalysis indicates method of internal combination has little effect on pipe stresses & equipment support loads
 RECD: C Commonwealth Edison Co 79/03/26 App

7903030363 Ack receipt of 790416 letter informing NRC of steps taken to correct violations noted in IE Insp Repts 30-010/79-04
 30-237/79-06 & 30-241/79-07
 RECD: J.D. A Region 3, Chicago, Safeguards Branch, 79/04/26 App

--7903030318 Responds to NRC 790320 letter re violations noted in IE Insp Repts 30-010/79-04, 30-237/79-06 & 30-241/79-07. Corrective actions with AGS (790320 7901)
 RECD: C Commonwealth Edison Co. 79/04/16 App

7903030148 Forwards responses to IE Bulletin 79-06A, "Review of Operational Errors & Site Missalignments Identified During TH Incident"
 AGS events identified during TH-05. AGS will be formed task force to review AGS events & recommend corrective actions as required
 RECD: C Commonwealth Edison Co 79/04/27 App

7903030363 Responds to IE Bulletin 79-04 on 3.4 or 6-inch valves being checked valves are in use at Dresden or Grand-Guilles. Review of valves has identified use of valves in some piping systems but review is incomplete. Will report later
 RECD: C Commonwealth Edison Co 79/04/21 App

7903040448 Forwards IE Circular 79-07, "Unspecified Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase"
 RECD: J.D. A Region 3, Chicago, Office of the Director 79/04/21 App

--7903040448 IE Circular 79-07, "Unspecified Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase"
 Region 3, Chicago, Office of the Director, 79/05/02 App

DOCKETED ITEMS

9

R Periodic operating reports & related correspondence

7905160354 Forwards monthly operating rep for Apr 1979
RTSPH8002.9 Commonwealth Edison Co 79/05/08 1p

7905160259 Monthly operating rep for Apr 1979
CIS80PH002.9 Commonwealth Edison Co 79/05/08 20pp

DOCKET 50-12 LYNCHBURG P2SL REACTOR

J Insurance & indemnity information

7905070477 Confirms increased liability limit to \$124,000,000 for
policies #P-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 176, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 211, 214, 215, & others
QUATERS0001.9 American Nuclear Insurers 79/05/01 1p

DOCKET 50-12 BADCOSK & HELOSK 00 CRITICAL FACILITY

J Insurance & indemnity information

7905070477 Confirms increased liability limit to \$124,000,000 for
policies #P-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170,
173, 174, 176, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 211, 214, 215, & others
QUATERS0001.9 American Nuclear Insurers 79/05/01 1p

7905030714 Forwards Amend 14 to Indemnity Agreement 0-0, per 100PRI40
change, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
SALT29M4.9 Antitrust & Indemnity Group 79/05/01 5pp

7905050427 Forwards executed Amend 1 to Indemnity Agreement 0-2 & Amend
10 to Indemnity Agreement 0-0
GLENK.A.F Gabcock & Wilcox Co 79/05/23 3pp

0 Inspection reports, SC Bulletin & correspondence

7905070139 Forwards IE Bulletin 79-05, 79-06A & 79-06 re nuclear
incident at TMI
O'REILLY.J.P Region 2, Atlanta, Office of the Director
79/06/13 1p

DOCKET 50-14 BATTILLE MEMORIAL INST CRITICAL FACILITY

J Insurance & indemnity information

7905030605 Forwards Amend 14 to Indemnity Agreement 0-0 reflecting
change in 100PRI40 reflecting increase in primary layer of
liability from \$140 million to \$160 million, effective
790501 Supporting documentation encl
SALT29M4.9 Antitrust & Indemnity Group 79/05/01 5pp

7905020291 Forwards executed Amend 14 to Indemnity Agreement 0-0,
effective 790501
BETL.D.H Battelle Memorial Institute, Columbus Laboratories
79/05/14 2pp

DOCKET 50-16 EMBROOD FERRI ATOMIC POWER PLANT, UNIT 1

P Security, medical, emergency & fire protection plans

7905050140 Responds to 790429 Telcon & 790408 mailgram re fire
protection at facility Forwards most recent insp. conducted
on 790124 h/a encl
MEPFLER.J.G Region 3, Chicago, Office of the Director
79/04/13 2pp

J Insurance & indemnity information

7905030385 Forwards Amend 22 to Indemnity Agreement 0-0, per 100PRI40
change, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
SALT29M4.9 Antitrust & Indemnity Group 79/05/01 5pp

7905160451 Forwards Amend 22 to Indemnity Agreement 0-0, per 100
request
HWSKART.P.A Detroit Edison Co 79/05/20 2pp

DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

J Insurance & indemnity information

7905030190 Forwards Amend 22 to Indemnity Agreement 0-1, reflecting
change in 100PRI40 increasing primary layer of liability
from \$140 million to \$160 million, effective 790501
Supporting documentation encl
SALT29M4.9 Antitrust & Indemnity Group 79/05/01 5pp

7905160388 Amend 22 to Indemnity Agreement 0-1
SALT29M4.9 Antitrust & Indemnity Group 79/05/08 1p

F Operating license stage documents & correspondence

7905040244 Forwards questions of clarification re geologic
investigations around test reactor
SEVIRE.J.F Interior/Dept. of Geological Survey 79/05/04 2pp

DOCKET 50-18 WASSACHUSETTS INST OF TECH RES REACTOR

J Insurance & indemnity information

7905040322 Forwards Amend 10 to Indemnity Agreement 0-0, per 100PRI40
change, re increase from \$140 million to \$160 million,
effective 790501 Supporting documentation encl
SALT29M4.9 Antitrust & Indemnity Group 79/05/01 5pp

F Operating license stage documents & correspondence

7905050323 Raises questions as to whether increase in mail science
activities are legal Requests advice re required changes to
license of Tech Report before proceeding w/research
activities
PSCYCH.H Massachusetts Institute of Technology 79/05/04 2pp

0 Reportable occurrences, LERs & related correspondence

7905040480 RD 79-02 on 790410 during completion of startup checklist
for less than 100 hp operation, core tank level alarm
discovered inoperable Caused by shorting between probe
conductor lead & casing
GLARR.L Massachusetts Institute of Technology 79/04/19 2pp

DOCKET 50-03 MORTINSHOUSE TEST REACTOR

J Insurance & indemnity information

7905070497 Confirms re
policies #P-1, 25, 43,
173, 174, 176, 179, 180,
197, 198, 200, 201, 204
QUATERS0001.9 Amc

DICHLT 25-27 WASHINGTON STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

790501920 Forwards Amend 12 to Indemnity Agreement E-38, per 10CFR140 change, re increase from \$145 million to \$148 million, effective 7/20/80 (Supporting documentation not)
BALTDMA-J Antitrust & Industry Group 7/19/80 5pp

790501972 Forwards accepted Amend 12 to Indemnity Agreement E-38
GABE-E Washington State Univ 7/19/80 2pp

P Operating license stage documents & correspondence

790501022 Forwards application for renewal of License R-76, revised proposed Tech Spec. 2.1A, emergency plan & unit financial part for FY 1980-81
MILSON M E, MORAN C J, RADNER R D Washington State Univ 7/15/80 1p

790501023 Application for renewal of license R-76
Washington State Univ 7/15/80 4pp

790501029 Proposed Tech Spec for WA State Univ modified SR10A reactor
Washington State Univ 7/15/80 70pp

790501042 KIA for continued operation of WA State Univ modified SR10A reactor
Washington State Univ 7/15/80 10pp

790501045 WA State Univ Nuclear Radiation Chr emergency plan
Washington State Univ 7/15/80 10pp

DICHLT 53-59 BANNER-PINE NUCLEAR POWER STATION

J Insurance & indemnity information

790501070 Advances of plan to file annual cash flow statements guaranteeing payment of reinsurance premiums on 790501
OF rates 5 of Banner will also file statements by 790501
DOUGLAS H Banner Atomic Electric Co 7/15/80 1p

J Insurance & indemnity information

790501049 Confirms increased liability limit to \$104,000,000 for policies WP-1, 25, 42, 74, 85, 100, 111, 140, 146, 151, 161, 164, 170, 173, 176, 179, 184, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215 & others
AMERICAN NUCLEAR INSURANCE 7/15/80 1p

790501052 Confirms increase in liability limit to \$104,000,000 for policies WP-23, 24, 25, 26, 27, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 69, 70, 71, 72, 74, 75, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS E H Mutual Atomic Energy Liability Underwriters 7/15/80 1p

790501053 Forwards Amend 12 to Indemnity Agreement E-17, per 10CFR140 change, re increase from \$145 million to \$148 million, effective 7/20/80 (Supporting documentation not)
BALTDMA-J Antitrust & Industry Group 7/15/80 5pp

790501058 Forwards executed Amend 12 to Indemnity Agreement E-17
BERRY, B H Yankee Atomic Electric Co 7/15/80 3pp

790510037 Submits response to NRC 790504 questions re auxiliary
Pawnee

790501007 Forwards IE Info Notice 79-06, "Epilic 4F Radioactive Contaminated Basin"
BERRY, B H Region 1, Philadelphia, Office of the Director 7/15/80 1p

790501002 Responds to IE Bulletin 79-03 re longitudinal weld defects
No action required; welds met shop requirement in ASME Section III. Only plants designed under these rules are affected
ROBERTS E H Yankee Atomic Electric Co 7/15/80 1p

790501016 Forwards IE Bulletin 79-06, "Review of Operational Errors & Site Missions Identified During THE Incident" - Licensee action required
BERRY, B H Region 1, Philadelphia, Office of the Director 7/15/80 1p

P Operating license stage documents & correspondence

790501024 Finds 790401-A "Operational QA Program" acceptable, based on review of Revision 6 including Amend 1
HARRIS W F Division of Project Management 7/15/80 2pp

790501022 Responds to issues raised from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of list
HARRIS W F Operating Reactors Branch 2 7/15/80 1p

790501023 Forwards draft evaluation of systematic evaluation program
Topic 3-1-A, "Operation Unless than All Loops in Use"
Requests review & response within 30 days
HARRIS W F Operating Reactors Branch 2 7/15/80 1p

790501023 Discusses loss of fast reactor transient analysis reported on 790417
Analysis error was found in inverted GENSI code & incorrect assumption in analysis of reactor coolant pump operation following trip
ROBERTS E H Yankee Atomic Electric Co 7/15/80 3pp

790501024 Summary of 790301 meeting w/with & Newton Geophysical re ongoing review of systematic evaluation program topics
hydrologic seismic design & pipe breaks inside containment
BERRY, B H Operating Reactors Branch 2 7/15/80 4pp

790501026 Responds to 790410 request re QA program suggests revision number of VQMR-1 is not be designated
HARRIS W F Yankee Atomic Electric Co 7/15/80 1p

790501048 Forwards Revision 6 & Amend 1 to Revision 6 of operational QA program as requested in 790410
BERRY, B H Yankee Atomic Electric Co 7/15/80 4pp

790501053 Informs that revisions to QA program are acceptable
HARRIS W F Quality Assurance Branch 7/15/80 1pp

790501051 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" - Licensee action required
BERRY, B H Region 1, Philadelphia, Office of the Director 7/15/80 1p

790501013 Forwards IE Bulletin 79-06, "Review of Operational Errors & Site Missions Identified During THE Incident"
BERRY, B H Region 1, Philadelphia, Office of the Director 7/15/80 1p

790501020 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Reactors Identified During THE Incident"
BERRY, B H Region 1, Philadelphia, Office of the Director 7/15/80 1p

790501012 Forwards IE Bulletin 79-06, "Failures of OR Type AK 2 Circuit Breaker in Safety-Related Bay" - Licensee action required
BERRY, B H Region 1, Philadelphia, Office of the Director 7/15/80 1p

790501021 Forwards IE Bulletin 79-06, Revision 1, "Review of Operational Errors & Site Missions Identified During THE Incident"
BERRY, B H Region 1, Philadelphia, Office of the Director 7/15/80 1p

790501048 Responds to IE Bulletin 79-03, "Seismic Stress Analysis of Safety-Related Piping" - Unit was designed using nonseismic loads of analysis
ROBERTS E H Yankee Atomic Electric Co 7/15/80 1p

DOCKETED ITEMS

11

7903250302 Responds to IE Bulletin 79-04, 79-06A & 79-06B-Revision 1 re
TNI errors. Outlines changes in operating procedures.
proventative measures taken Supporting personnel briefing &
documentation encl
HOSSEY, D E Yankee Atomic Electric Co 79/04/26 5pp

B. Periodic operating reports & related correspondence

7903130324 Forwards monthly operating rept for Apr 1979
HOSSEY, D E Yankee Atomic Electric Co 79/05/12 1p

--7903130327 Monthly operating rept for Apr 1979
GUSSEN, R H Yankee Atomic Electric Co 79/05/12 5pp

C. Reportable occurrences, LERs & related correspondence

7903130422 Forwards LER 79-012/036-1
AUGER, R A Yankee Atomic Electric Co 79/05/11 1p

--7903130426 LER 79-012/036-1 on 790419 level of primary seal leak found
to be decreasing at faster rate than normal. Caused by crack
in carbon ring of mechanical seal. Seal replaced
HAY, E L Yankee Atomic Electric Co 79/05/11 1p

7903130433 Forwards LER 79-014/038-0
AUGER, R A Yankee Atomic Electric Co 79/05/11 1p

--7903130437 LER 79-014/038-0 on 790412 GA-U-608 valve failed containment
isolation. Valve closed by crew on valve testing. Surface Valve
isolated. Closed, released & returned to use
HAY, E L Yankee Atomic Electric Co 79/05/11 1p

7903130526 Forwards LER 79-010/044-0
AUGER, R A Yankee Atomic Electric Co 79/05/14 1p

--7903130528 LER 79-010/044-0 on 790323 while performing loop on air
sample pump station A-3, air sample pump found inoperative.
Caused by bearing failure on motor shaft. Bearing replaced
HAY, E L Yankee Atomic Electric Co 79/05/14 1p

DOCKET 30-30 PLUMB BROOK RESEARCH REACTOR FACILITY

J. Insurance & indemnity information

7903140380 Forwards Amend 14 to Indemnity Agreement B-3, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501. Supporting documentation encl
BALTIMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903190171 Amend 14 to Indemnity Agreement D-3 between OMGA & ABE
BALTIMAN, J Antitrust & Indemnity Group 79/05/07 1p

DOCKET 30-32 ARGENT GENERAL HUGHESON

J. Insurance & indemnity information

7903030305 Forwards Amend 17 to Indemnity Agreement B-2, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790501.
Supporting documentation encl
BALTIMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903240327 Forwards executed Amend 17 to Indemnity Agreement B-2
NEWMARKER, R L. Aereset Operations 79/05/15 2pp

DOCKET 30-37 TRIUMPH-REAR 1 PROTOTYPE REACTOR

J. Insurance & indemnity information

7903030302 Forwards Amendment 31 to Indemnity Agreement B-3, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790501.
Supporting documentation encl
BALTIMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 30-47 ARMY MATERIALS RESEARCH REACTOR

J. Insurance & indemnity information

7903160320 Forwards Amend 11 to Indemnity Agreement B-3, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501. Supporting documentation encl
BALTIMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903140421 Forwards Amend 17 to Indemnity Agreement D-7
NEWMARKER, R L. Army, Dept of, Halls & Mechanics Research Center
79/05/09 5pp

DOCKET 30-50 ARGENT GENERAL HUGHESON

J. Insurance & indemnity information

7903030305 Forwards Amend 17 to Indemnity Agreement B-2, reflecting
change in 10CFR140, increasing primary layer of liability
from \$140 million to \$160 million, effective 790501.
Supporting documentation encl
BALTIMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903240327 Forwards executed Amend 17 to Indemnity Agreement B-2
NEWMARKER, R L. Aereset Operations 79/05/15 2pp

DOCKET 30-54 UNION CARBIDE RESEARCH REACTOR

J. Insurance & indemnity information

7903160305 Forwards Amend 11 to Indemnity Agreement B-3, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501. Supporting documentation encl
BALTIMAN, J Antitrust & Indemnity Group 79/05/01 5pp

F. Operating license stage documents & correspondence

7903010330 Provides responses to proposed Tech Spec items re potential
reactivity, organization chart & definition of "unplanned
transients"
GOSSEL, R D Union Carbide Corp 79/04/10 5pp

7903010449 Art 790412 Union re Tech Spec note. Details requested
changes re liquid effluent releases
GOSSEL, R D Union Carbide Corp 79/04/16 5pp

DOCKET 30-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

J. Insurance & indemnity information

7903140380 Forwards Amend 12 to Indemnity Agreement B-3, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501. Supporting documentation encl
BALTIMAN, J Antitrust & Indemnity Group 79/05/01 5pp

F. Operating license stage documents & correspondence

7903190019 Requests change to Tech Spec re present period reversal &
screen
GOSSEL, R D New York State Univ of Buffalo 79/01/09 5pp

DOCKET 30-59 TRIUMPH-REAR 1 PROTOTYPE REACTOR

J. Insurance & indemnity information

7903160320 Forwards Amend 14 to Indemnity Agreement B-2, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501. Supporting documentation encl
BALTIMAN, J Antitrust & Indemnity Group 79/05/01 5pp

DOCKET 30-62 UNIV OF VIRGINIA RESEARCH REACTOR

J. Insurance & indemnity information

7903230345 Forwards Amend 12 to Indemnity Agreement B-2, per 10CFR140
changes, re increase from \$140 million to \$160 million,
effective 790501. Supporting documentation encl
BALTIMAN, J Antitrust & Indemnity Group 79/05/01 5pp

7903240422 Forwards accepted Amend 12 to Indemnity Agreement B-2,
effective 790501.
GOSSEL, R D Virginia Univ of 79/05/17 5pp

G. Inspection reports, IE Bulletins & correspondence

7903070148 Forwards IE Bulletin 79-05, 79-06A & 79-06 re nuclear
incident at TRS
GOSSEL, R D Region 2, Atlanta, Office of the Director
79/04/12 1p

DOCKETED ITEMS

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

8. NRC Safety Evaluation Report (SER), supply & correspondence
 7/9/05/04

7905010428 Requests review of geologic rep & probability analysis be expedited so SER can be issued
 7/9/05/04

J Insurance & indemnity information

7905030497 Confirms increased liability limit to \$184,000,000 for policies HP-1,28,42,76,82,100,171,180,186,191,194,195,197,170,179,180,180,185,186,187,188,189,190,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,225 & others
 7/9/05/04

7905030502 Confirms increase in liability limit to \$20,000,000 for policies HP-22,26,29,30,39,44,46,47,49,50,51,52,33,34,35,36,37,50,50,61,64,66,67,68,69,70,71,72,74,75,77,78,79,80,81,82,83,84,85,86,90,91,92,93,94,95 & 96
 7/9/05/04

7905030503 Forwards Amend 20 to Indemnity Agreement 8-1, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

7905030508 Amend 20 to Indemnity Agreement 8-1
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 1p

DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR

J Insurance & indemnity information

7905030504 Forwards Amend 10 to Indemnity Agreement 8-3, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

7905030505 Amend 10 to Indemnity Agreement 8-3
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 1p

G Inspection reports, EE Bulletins & correspondence

7905010655 Act receipt of 790302 ltr informing NRC of steps taken to correct violations noted in IC Insp Rep 50-072/79-01
 7/9/05/01

7905030644 Responds to NRC 790303 ltr re violations noted in IC Insp Rep 50-072/79-01
 7/9/05/01

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

J Insurance & indemnity information

7905030510 Forwards Amend 20 to Indemnity Agreement 8-1, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

F. Operating license stage documents & correspondence

7905010518 Notifies that GE will have resources necessary to decommission reactor
 7/9/05/14, 1p

DOCKET 50-77 CATHOLIC UNIV OF AMERICA RESEARCH REACTOR

J Insurance & indemnity information

7905010512 Forwards Amend 9 to Indemnity Agreement 8-3, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

7905030479 Forwards Amend 9 to Indemnity Agreement 8-3
 7/9/05/10, 1p

P Operating license stage documents & correspondence

7905030527 Forwards correction to page 10-1 in Amend 7 for License 8-21
 7/9/05/09 3pp

R Periodic operating reports & related correspondence

7905010530 Announces plan to restart AGR-201 reactor on 7/9/05 NRC representative invited to attend Forwards Annual Operating Rep 1978
 7/9/05/04 11pp

7905010547 Annual Operating Rep 1978
 7/9/05/04 11pp

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

J Insurance & indemnity information

7905010547 Forwards Amend 9 to Indemnity Agreement 8-3, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

B Inspection reports, EE Bulletins & correspondence

7905010542 Forwards EE Bulletin 79-25, 79-26 & 79-27 re nuclear incidents at TRS
 7/9/05/10 1p

DOCKET 50-84 UNIV OF CALIFORNIA RESEARCH REACTOR

J Insurance & indemnity information

7905030520 Forwards Amend 10 to Indemnity Agreement 8-3, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

J Insurance & indemnity information

7905010544 Forwards Amend 8 to Indemnity Agreement 8-3, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

DOCKET 50-89 GENERAL ATOMIC CO

J Insurance & indemnity information

7905030502 Forwards Amendment 30 to Indemnity Agreement 8-3, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

DOCKET 50-94 ROCKWELL INTERNATIONAL RESEARCH REACTOR

J Insurance & indemnity information

7905010520 Forwards Amend 18 to Indemnity Agreement 8-3, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

J Insurance & indemnity information

7905030508 Forwards Amend 11 to Indemnity Agreement 8-3, reflecting change in IOCFR140, increasing primary layer of liability from \$140 million to \$160 million, effective 7/9/05
 Supporting documentation encl.
 BALTIMAR-J Antitrust & Indemnity Group 7/9/05/01 5pp

DOCKETED ITEMS

13

DOCKET 50-84 WAGOON & HILSON TEST REACTOR

J Insurance & indemnity information

7905260714 Forwards Amend 19 to Indemnity Agreement E-0, per 10CFR140 changes, re increase from \$140 million to \$140 million effective 790501 Supporting documentation encl
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 Spp

7905260427 Forwards executed Amend 1 to Indemnity Agreement E-0 & Amend 19 to Indemnity Agreement E-0
GLSEN, A P Babcock & Wilcox Co 79/05/01 Spp

F Operating license stage documents & correspondence

7905140441 Submits annual operations report for 1978
GLSEN, A P Babcock & Wilcox Co 79/05/01 Spp

7905140414 Submits annual operations report for 1978
GLSEN, A P Babcock & Wilcox Co 79/05/01 Spp

7905140408 Submits annual operations report for 1977
GLSEN, A P Babcock & Wilcox Co 79/05/01 Spp

7905140309 Forwards additions to License E-47, renewal application & proposed Test Reactor for power limits
GLSEN, A P Babcock & Wilcox Co 79/05/01 Spp

G Inspection reports, IE Bulletins & correspondence

7905270519 Forwards IE Bulletins 79-08, 79-09A & 79-08 re nuclear incident at TH
O'BRIEN, J P Region 2, Atlanta, Office of the Director 79/05/13 Ip

R Periodic operating reports & related correspondence

7905140382 Forwards "Annual Report 1978"
GLSEN, A P Babcock & Wilcox Co 79/05/01 Spp

--7905140384 "Annual Report 1978"
GLSEN, A P Babcock & Wilcox Co 79/05/01 Spp

DOCKET 50-160 AEROJET GENERAL NUCLEAR

J Insurance & indemnity information

7905260501 Forwards Amend 17 to Indemnity Agreement E-2, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$140 million effective 790501 Supporting documentation encl
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 Spp

7905260503 Forwards executed Amend 17 to Indemnity Agreement E-2, AEROJET, R. L. Aerojet Operations 79/05/01 Spp

DOCKET 50-105 OREGON STATE UNIV

J Insurance & indemnity information

7905140328 Forwards Amend 12 to Indemnity Agreement E-1, per 10CFR140 changes, re increase from \$140 million to \$140 million effective 790501 Supporting documentation encl
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 Spp

DOCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905260504 Forwards Amend 18 to Indemnity Agreement E-7, reflecting change in 10CFR140, increasing primary layer of liability from \$140 million to \$140 million effective 790501 Supporting documentation encl
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 Spp

7905260502 Forwards Amend 18 to Indemnity Agreement E-7, Requests change in addresses for correspondence
BONHAM, J R North Carolina State Univ 79/05/01 Spp

G Inspection reports, IE Bulletins & correspondence

7905270146 Forwards IE Bulletin 79-05, 79-08A & 79-08 re nuclear incident at TH
O'BRIEN, J P Region 2, Atlanta, Office of the Director 79/05/13 Ip

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

J Insurance & indemnity information

7905140324 Forwards Amend 9 to Indemnity Agreement E-0, per 10CFR140 changes, re increase from \$140 million to \$140 million effective 790501 Supporting documentation encl
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 Spp

G Inspection reports, IE Bulletins & correspondence

7905150570 Forwards IE Insp Rpt 50-112/79-01 on 790412-13 No noncompliance noted
HEMER, G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/01 Spp

--7905150584 IE Insp Rpt 50-112/79-01 on 790412-13 No noncompliance noted Major areas inspected security organization, physical barriers, access control, detection aids & testing of security equipment Details withheld (ref 10CFR 2003)
KAMMELER, A Region 4, Dallas, Office of the Director, 790501, G L, Dallas, Reactor Operations Nuclear Support Branch 79/05/01 Spp

DOCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR

J Insurance & indemnity information

7905140323 Forwards Amend 9 to Indemnity Agreement E-1, per 10CFR140 changes, re liability insurance increase from \$140 million to \$140 million effective 790501 Supporting documentation encl
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 Spp

7905140507 Forwards executed Amend 9 to Indemnity Agreement E-14
CARBON, R Arizona Univ 79/05/01 Spp

DOCKET 50-116 IOWA STATE UNIV RESEARCH REACTOR

J Insurance & indemnity information

7905140104 Forwards Amend 9 to Indemnity Agreement E-2, per 10CFR140 changes, re liability insurance increase from \$140 million to \$140 million effective 790501 Supporting documentation encl
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 Spp

7905140104 Forwards signed Amend 9 to Indemnity Agreement E-2, increasing liability insurance from \$140 to \$140 million
RUSSELL, R Iowa State Univ 79/05/01 Spp

G Inspection reports, IE Bulletins & correspondence

7905140400 Act receipt of 790404 for informing NRC of steps taken to correct violations noted in IE Insp on 790322-23
MILLS, J A Region 2, Chicago, Safeguards Branch, 79/05/01 Spp

--7905140400 Responds to NRC 790310 for re violations noted in IE Insp on 790322-23 Corrective actions withheld (ref 10CFR 2003)
MILLS, J Iowa State Univ 79/05/01 Spp

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

J Insurance & indemnity information

7905140324 Forwards Amend 10 to Indemnity Agreement E-0, per 10CFR140 changes, re increase from \$140 million to \$140 million effective 790501 Supporting documentation encl
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 Spp

7905140401 Forwards executed Amends 10 & 11 to Indemnity Agreements E-23 & E-25, respectively
BLANNEY, V Missouri Univ 79/05/01 Spp

A Periodic operating reports & related correspondence

7903200609 Forwards progress rept for Apr 1978-Mar 1979 for Bella nuclear reactor facility
EDWARDS, B W Missouri: Univ of 79/04/30 1p

7903200609 Progress rept for Apr 1978-Mar 1979 for Bella nuclear reactor facility
ELLIS, A C Missouri: Univ of 79/04/30 10pp

DOCKET 30-126 VERONICA POLYTECH INST TRAINING REACTOR

J Insurance & indemnity information

7903160308 Forwards Amend 12 to Indemnity Agreement 8-25 per 100% rate change, re increase from \$100 million to \$100 million.
effective 790301 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 5pp

7903160308 Amend 12 to Indemnity Agreement 8-25, increasing liability coverage from \$100 million to \$100 million
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 1p

G Inspection reports: IE Bulletins & correspondence

7903060193 Forwards IE Insp Rept 30-124/79-31 on 790310-31 No noncompliance noted
SUTHERLAND, J T Region 2, Atlanta: Fuel Facility & Materials Safety Branch 79/03/14 3pp

7903060207 IE Insp Rept 30-124/79-31 on 790310-31 No noncompliance noted Major areas inspected radiation protection re procedures, posting, labeling, dosimetry, training, surveys & instrument calibration
EDWARDS, C C OREGON: A F Region 2, Atlanta: Fuel Facility & Materials Safety Branch 79/03/09 7pp

7903240474 Forwards IE Insp Rept 30-124/79-31 on 790320-0202 No noncompliance noted
LEWIS, R C Region 2, Atlanta: Reactor Operations National Support Branch 79/04/04 2pp

7903240482 IE Insp Rept 30-124/79-31 on 790320-0301 No noncompliance noted Major areas inspected refueling operations & associated radiological controls
JULIANO, C A Region 2, Atlanta: Office of the Director INTNHLR 2 Region 2, Atlanta: Reactor Operations National Support Branch 79/04/02 3pp

7903270438 Forwards IE Bulletins 79-03-79-85 & 79-04-16 nuclear incident at THE
O'REILLY, J P Region 2, Atlanta: Office of the Director 79/04/13 1p

DOCKET 50-126 TEXAS A&M UNIV RESEARCH REACTOR

F Operating license stage documents & correspondence

7903150779 Requests addl info to complete review of proposed amend, including effects of blanket beam strength & transportation of radioactive matl
REID, R W Operating Reactors Branch 4 79/03/30 2pp

7903200836 Notices of pending license expiration Forwards license renewal notice (same Application for renewal matl to file at least 30 days prior to expiration
REID, R W Operating Reactors Branch 4 79/04/28 10pp

G Inspection reports: IE Bulletins & correspondence

7903200106 Forwards IE Bulletins 79-03-79-08A & 79-03-79 nuclear incident at THE
O'REILLY, J P Region 2, Atlanta: Office of the Director 79/04/13 1p

DOCKET 50-126 TEXAS A&M UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

7903140308 Forwards physical security plan Plan withhold (redacted)
BLITCH, J V Vet Admin Hosp NE/OM 79/03/10 1p

J Insurance & indemnity information

7903160308 Forwards Amend 8 to Indemnity Agreement 8-25 per 100% rate change, re increase from \$100 million to \$100 million.
effective 790301 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 5pp

7903160307 Amend 8 to Indemnity Agreement 8-25, increasing liability coverage from \$100 million to \$100 million
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 1p

F Operating license stage documents & correspondence

7903140190 Forwards application for renewal of License E-17
BLITCH, J V Vet Admin Hosp NE/OM 79/03/10 1p

7903140201 Applies for renewal of License E-37 Forwards application supporting documentation
BLITCH, J V Vet Admin Hosp NE/OM 79/03/10 1p

7903140204 Application for renewal of License E-37
Vet Admin Hosp NE/OM 79/03/10 70pp

DOCKET 50-130 BUREAU OF BAY POWER PLANT, UNIT 3

G Regulatory correspondence

7903031008 Forwards Lewis Committee rept (MURDER/CR-0400) re safety statement on reactor safety study (NRC-1400), its review by Lewis Committee & survey of NRC area of 1000-1400
MURDER, R C Branch 2 79/03/09 3pp

7903070207 Notification of resignation of DE Passmore as counsel for interviewers interview will continue to be represented by L. Braun & Sierra Corp Legal Defense Fund
PERKINS, D E Gulf: Drayton, McFarlan, Drabsky, Harnden & Passmore Inc 79/04/04 1p

I Financial information

7903200148 Forwards "Annual Financial Rept 1978"
CRANE, P A Pacific Gas & Electric Co 79/03/23 1p

7903200174 "Annual Financial Rept 1978"
Pacific Gas & Electric Co 79/12/31 40pp

7903200310 Forwards "Established Internal Fund Generation for C&P"
CRANE, P A Pacific Gas & Electric Co 79/03/24 3pp

7903200520 "Annual Financial Rept 1978"
Pacific Gas & Electric Co 79/03/23 36pp

J Insurance & indemnity information

7903160298 Forwards Amend 21 to Indemnity Agreement 8-25 per 100% rate change, re increase from \$100 million to \$100 million.
effective 790301 Supporting documentation encl
SALTZMAN, J Antitrust & Indemnity Group 79/03/01 5pp

7903140406 Forwards Amends executed Amends 21 & 4 to Indemnity Agreement 8-25 & 8-25, respectively
CRANE, P A Pacific Gas & Electric Co 79/03/08 3pp

DOCKETED ITEMS

10

Operating License stage documents & correspondence

7905090011 Response to 790313 1st letter references to specific docketed info describing operational SA program
CRANE, P A Pacific Gas & Electric Co 79/04/20 1p

7905030256 Forward summary of EBE Nuclear, Inc resolution/documentation of above flexibility error which existed in version of FIDUC piping analysis computer program from Jan-Oct 1969
Review & analysis included all work through Dec 1975
PORTER, P L EBE Nuclear, Inc 79/05/21 5pp

--7905030263 Forward EBE Nuclear, Inc list of S&Ts & piping sgs which could have been impacted by deficient computer program
Co has no record of reanalysis for Cooper program
OTTER, M G General Electric Co, Nuclear Energy Products Div 79/05/24 15pp

0 Inspection reports, IE Bulletins & correspondence

7905100267 Forward IE Info Notice 79-26, "Stress Analysis of Safety-Related Piping"
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/03/23 1p

7905040561 Forward IE Info Notice 79-27, "Baptism of Radiactive Tanks"
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/03/24 1p

7905100216 Forward IE Info Notice 79-28, "Interconnection of Customized Sgs w/DC Air Sgs Used as Source of Breathing Air"
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/03/28 1p

7905010423 Forward IE Info Notice 79-29, "Spill of Radioactively Contaminated Resin"
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/03/30 1p

7905010023 Forward IE Bulletin 79-26A, "Review of Operational Errors & Sgs Misalignments Identified During TMI Incidents"
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

7905010526 Forward IE Bulletin 79-26B, "Review of Operational Errors & Sgs Misalignments Identified During TMI Incident"
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

0 Inspection reports, IE Bulletins & correspondence

7905070099 Forward IE Bulletin 79-27, "Stress Analysis of Safety-Related Piping" License action required
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

7905000266 Forward IE Bulletin 79-26, "Failures of SE Type AM-2 Circuit Breaker in Safety-Related Sgs" License action required
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/17 1p

7905100969 Response to IE Bulletin 79-26, "Environ Qualification of Class 2E Equipment" NRC provide schedule for submission of info after seismic issues have been resolved
CRANE, P A Pacific Gas & Electric Co 79/04/20 1p

7905060366 Forward IE Bulletin 79-26B, "Nuclear Incident at TMI-2"
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/21 1p

8 Periodic operating reports & related correspondence

7905050218 Forward "Quarterly Status Rep of Investigations & Meds" Jan-Mar 1979, Sept 21
CRANE, P A Pacific Gas & Electric Co 79/05/03 1p

7905100130 Forward monthly operating rep for Apr 1979
MOORE, R D Pacific Gas & Electric Co 79/05/11 1p

--7905100132 Monthly operating rep for Apr 1979.
Pacific Gas & Electric Co 79/05/22 4pp

Reportable occurrences, LERs & related correspondence

7905100600 Forward PNO-79-47L
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/25 1p

7905030233 Forward LER 78-004/03L-1
CRANE, P A Pacific Gas & Electric Co 79/04/09 1p

--7905040304 LER 78-004/03L-1 on 781203 redundant gas treatment sgs de fan operated below required design flow & pressure dropped across gas scrubber column caused by apparent packing blockage in scrubber column Packing replaced
SETTY, D C Pacific Gas & Electric Co 79/04/09 1p

7905100107 Forward PNO-79-47R
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/11 1p

7905040123 Forward PNO-79-47R
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/12 1p

7905100141 Forward PNO-79-47T
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/13 1p

7905030045 Forward PNO-79-47U
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/14 1p

7905030317 Forward PNO-79-47AA
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/20 1p

7905100428 Forward PNO-79-47AB
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/21 1p

7905100444 Forward PNO-79-47AC & AD
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/23 1p

7905030484 Forward PNO-79-47AE
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/24 1p

7905030227 Forward PNO-79-47AF
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/25 1p

--7905030233 PNO-79-47AF summary of info re nuclear incident at of 790420, Describes plant status & environ status. Highest thermocouple reading, 302 F.
Office of Inspection & Enforcement, 79/04/25 8pp.

7905030234 Forward PNO-79-47AG
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/26 1p

--7905030236 PNO-79-47AG summary of info re nuclear incident at of 790420 Describes plant status & environ status. Highest sacra temp reading is 311 F
ENCL:ENR, R H Region 3, San Francisco, Office of Inspection & Enforcement, 79/04/26 8pp.

7905030238 Forward PNO-79-47AH
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/27 1p

7905040239 Forward PNO-79-47AJ, AJ & AK per NRC 790401 1st transmitting IE Bulletin 79-28
ENCL:ENR, R H Region 3, San Francisco, Office of the Director 79/04/30 1p

--7905040363 PNO-79-47AJ summary of info re nuclear incident at of 790420 Describes plant & environ status
Office of Inspection & Enforcement, 79/04/28 8pp

--7905040365 PNO-79-47AK summary of info re nuclear incident at of 790420 Describes plant & environ status
Office of Inspection & Enforcement, 79/04/28 8pp.

DOCKETED ITEMS

7700070007 Forwards RUS-77-47AL per SEC 770001 for transmitting to
Bulletin 77-03
ENGLISH, R. H. Region 3, San Francisco, Office of the Director
7/4/05/01 3p

7705170012 Forwards RUS-77-47AM
ENGLISH, R. H. Region 3, San Francisco, Office of the Director
7/4/05/07 3p

DOCKET 30-134 WINCHESTER POLYTECH INST RESEARCH REACTOR

J Insurance & indemnity information

7705160205 Forwards Amend 9 to Indemnity Agreement E-36, per 10CFR140
changes re increase from \$100 million to \$100 million;
effective 770501 Supporting documentation incl
SALTZMAN, J. Antitrust & Indemnity Group 7/3/05/01 3pp

7705110200 Forwards Amend 9 to Indemnity Agreement E-36
LLOYD, D. K. Winchester Polytechnic Inst 7/3/05/08 2pp

DOCKET 30-137 UNIV OF WASHINGTON RESEARCH REACTOR

J Insurance & indemnity information

7705160102 Forwards Amend 9 to Indemnity Agreement E-36, per 10CFR140
changes re liability insurance increase from \$100 million
to \$100 million; effective 770501 Supporting documentation
incl
SALTZMAN, J. Antitrust & Indemnity Group 7/3/05/01 3pp

DOCKET 30-141 STANFORD UNIV RESEARCH REACTOR

J Insurance & indemnity information

7705160306 Forwards Amend 9 to Indemnity Agreement E-36, per 10CFR140
changes re increase from \$100 million to \$100 million;
effective 770501 Supporting documentation incl
SALTZMAN, J. Antitrust & Indemnity Group 7/3/05/01 3pp

7705220307 Forwards requested Amend 9 to Indemnity Agreement E-16,
effective 770501
BETH, R. H. Stanford Univ 7/3/05/14 3pp

DOCKET 30-142 UCLA TRAINING REACTOR

J Insurance & indemnity information

7705160325 Forwards Amend 9 to Indemnity Agreement E-16, per 10CFR140
changes re liability insurance increase from \$100 million
to \$100 million; effective 770501 Supporting documentation incl
SALTZMAN, J. Antitrust & Indemnity Group 7/3/05/01 3pp

O Inspection reports, EE Bulletin & correspondence

7705220313 Forwards EE Reg 30-142/79-01 on 770512-15-25 & 0301
No correspondence noted
BETH, R. H. Region 3, San Francisco, Fuel Facility & Materials
Safety Branch 7/3/05/02 3pp

7705220320 In Reg 30-142/79-01 on 770512-15-25 & 0301 No
noncompliance noted Major areas inspected involve
protection, emergency planning, radiologic control &
independent test effort
THOMAS, R. D. Region 3, San Francisco, Office of the Director
BETH, R. H. Region 3, San Francisco, Fuel Facility & Materials
Safety Branch 7/3/05/02 3pp

DOCKET 30-144 BAXTON NUCLEAR EXPERIMENTAL FACILITY

J Insurance & indemnity information

DOCKET 30-148 UNIV OF WISCONSIN REACTOR

J Insurance & indemnity information

7705220100 Forwards Amend 9 to Indemnity Agreement E-36, per 10CFR140
changes re liability insurance increase from \$100 million to
\$100 million; effective 770501 Supporting documentation incl
SALTZMAN, J. Antitrust & Indemnity Group 7/3/05/01 3pp

7705160117 Forwards Amend 9 to Indemnity Agreement E-36, per 10CFR140
changes re liability insurance increase from \$100 million to
\$100 million; effective 770501 Supporting documentation incl
SALTZMAN, J. Antitrust & Indemnity Group 7/3/05/01 3pp

DOCKET 30-151 UNIV OF ILLINOIS RESEARCH REACTOR

J Insurance & indemnity information

7705220370 Forwards Amend 12 to Indemnity Agreement E-36, per 10CFR140
changes re increase from \$100 million to \$100 million;
effective 770501 Supporting documentation incl
SALTZMAN, J. Antitrust & Indemnity Group 7/3/05/01 3pp

DOCKET 30-155 BLD BCK POINT NUCLEAR PLANT

C Utilizing Environmental Report (ER) amendments & correspondence

7705220408 Forwards add info re systematic evaluation program Topic
VII-1-A, requested by B McDonald on 770506. Discusses
justification of reactor protection system failures re failure in
plant computer
CASHILL, G. Consumers Power Co 7/3/04/10 5pp

F Security, medical, emergency & fire protection plans

7705160211 Provides schedule for submittal of add fire protection
info per SEC 770404 request
HOFMAN, S. P. Consumers Power Co 7/3/05/01 2pp

J Insurance & indemnity information

7705220497 Confirms increased liability limit to \$124,000,000 for
reactors AP-2, AP-3, AP-4, AP-5, AP-6, AP-7, AP-8, AP-9, AP-10, AP-11, AP-12, AP-13, AP-14, AP-15, AP-16, AP-17, AP-18, AP-19, AP-20, AP-21, AP-22, AP-23, AP-24, AP-25, AP-26, AP-27, AP-28, AP-29, AP-30, AP-31, AP-32, AP-33, AP-34, AP-35, AP-36, AP-37, AP-38, AP-39, AP-40, AP-41, AP-42, AP-43, AP-44, AP-45, AP-46, AP-47, AP-48, AP-49, AP-50, AP-51, AP-52, AP-53, AP-54, AP-55, AP-56, AP-57, AP-58, AP-59, AP-60, AP-61, AP-62, AP-63, AP-64, AP-65, AP-66, AP-67, AP-68, AP-69, AP-70, AP-71, AP-72, AP-73, AP-74, AP-75, AP-76, AP-77, AP-78, AP-79, AP-80, AP-81, AP-82, AP-83, AP-84, AP-85, AP-86, AP-87, AP-88, AP-89, AP-90, AP-91, AP-92, AP-93, AP-94, AP-95, AP-96, AP-97, AP-98, AP-99, AP-100, AP-101, AP-102, AP-103, AP-104, AP-105, AP-106, AP-107, AP-108, AP-109, AP-110, AP-111, AP-112, AP-113, AP-114, AP-115, AP-116, AP-117, AP-118, AP-119, AP-120, AP-121, AP-122, AP-123, AP-124, AP-125, AP-126, AP-127, AP-128, AP-129, AP-130, AP-131, AP-132, AP-133, AP-134, AP-135, AP-136, AP-137, AP-138, AP-139, AP-140, AP-141, AP-142, AP-143, AP-144, AP-145, AP-146, AP-147, AP-148, AP-149, AP-150, AP-151, AP-152, AP-153, AP-154, AP-155, AP-156, AP-157, AP-158, AP-159, AP-160, AP-161, AP-162, AP-163, AP-164, AP-165, AP-166, AP-167, AP-168, AP-169, AP-170, AP-171, AP-172, AP-173, AP-174, AP-175, AP-176, AP-177, AP-178, AP-179, AP-180, AP-181, AP-182, AP-183, AP-184, AP-185, AP-186, AP-187, AP-188, AP-189, AP-190, AP-191, AP-192, AP-193, AP-194, AP-195, AP-196, AP-197, AP-198, AP-199, AP-200, AP-201, AP-202, AP-203, AP-204, AP-205, AP-206, AP-207, AP-208, AP-209, AP-210, AP-211, AP-212, AP-213, AP-214, AP-215, AP-216, AP-217, AP-218, AP-219, AP-220, AP-221, AP-222, AP-223, AP-224, AP-225, AP-226, AP-227, AP-228, AP-229, AP-230, AP-231, AP-232, AP-233, AP-234, AP-235, AP-236, AP-237, AP-238, AP-239, AP-240, AP-241, AP-242, AP-243, AP-244, AP-245, AP-246, AP-247, AP-248, AP-249, AP-250, AP-251, AP-252, AP-253, AP-254, AP-255, AP-256, AP-257, AP-258, AP-259, AP-260, AP-261, AP-262, AP-263, AP-264, AP-265, AP-266, AP-267, AP-268, AP-269, AP-270, AP-271, AP-272, AP-273, AP-274, AP-275, AP-276, AP-277, AP-278, AP-279, AP-280, AP-281, AP-282, AP-283, AP-284, AP-285, AP-286, AP-287, AP-288, AP-289, AP-290, AP-291, AP-292, AP-293, AP-294, AP-295, AP-296, AP-297, AP-298, AP-299, AP-300, AP-301, AP-302, AP-303, AP-304, AP-305, AP-306, AP-307, AP-308, AP-309, AP-310, AP-311, AP-312, AP-313, AP-314, AP-315, AP-316, AP-317, AP-318, AP-319, AP-320, AP-321, AP-322, AP-323, AP-324, AP-325, AP-326, AP-327, AP-328, AP-329, AP-330, AP-331, AP-332, AP-333, AP-334, AP-335, AP-336, AP-337, AP-338, AP-339, AP-340, AP-341, AP-342, AP-343, AP-344, AP-345, AP-346, AP-347, AP-348, AP-349, AP-350, AP-351, AP-352, AP-353, AP-354, AP-355, AP-356, AP-357, AP-358, AP-359, AP-360, AP-361, AP-362, AP-363, AP-364, AP-365, AP-366, AP-367, AP-368, AP-369, AP-370, AP-371, AP-372, AP-373, AP-374, AP-375, AP-376, AP-377, AP-378, AP-379, AP-380, AP-381, AP-382, AP-383, AP-384, AP-385, AP-386, AP-387, AP-388, AP-389, AP-390, AP-391, AP-392, AP-393, AP-394, AP-395, AP-396, AP-397, AP-398, AP-399, AP-400, AP-401, AP-402, AP-403, AP-404, AP-405, AP-406, AP-407, AP-408, AP-409, AP-410, AP-411, AP-412, AP-413, AP-414, AP-415, AP-416, AP-417, AP-418, AP-419, AP-420, AP-421, AP-422, AP-423, AP-424, AP-425, AP-426, AP-427, AP-428, AP-429, AP-430, AP-431, AP-432, AP-433, AP-434, AP-435, AP-436, AP-437, AP-438, AP-439, AP-440, AP-441, AP-442, AP-443, AP-444, AP-445, AP-446, AP-447, AP-448, AP-449, AP-450, AP-451, AP-452, AP-453, AP-454, AP-455, AP-456, AP-457, AP-458, AP-459, AP-460, AP-461, AP-462, AP-463, AP-464, AP-465, AP-466, AP-467, AP-468, AP-469, AP-470, AP-471, AP-472, AP-473, AP-474, AP-475, AP-476, AP-477, AP-478, AP-479, AP-480, AP-481, AP-482, AP-483, AP-484, AP-485, AP-486, AP-487, AP-488, AP-489, AP-490, AP-491, AP-492, AP-493, AP-494, AP-495, AP-496, AP-497, AP-498, AP-499, AP-500, AP-501, AP-502, AP-503, AP-504, AP-505, AP-506, AP-507, AP-508, AP-509, AP-510, AP-511, AP-512, AP-513, AP-514, AP-515, AP-516, AP-517, AP-518, AP-519, AP-520, AP-521, AP-522, AP-523, AP-524, AP-525, AP-526, AP-527, AP-528, AP-529, AP-530, AP-531, AP-532, AP-533, AP-534, AP-535, AP-536, AP-537, AP-538, AP-539, AP-540, AP-541, AP-542, AP-543, AP-544, AP-545, AP-546, AP-547, AP-548, AP-549, AP-550, AP-551, AP-552, AP-553, AP-554, AP-555, AP-556, AP-557, AP-558, AP-559, AP-560, AP-561, AP-562, AP-563, AP-564, AP-565, AP-566, AP-567, AP-568, AP-569, AP-570, AP-571, AP-572, AP-573, AP-574, AP-575, AP-576, AP-577, AP-578, AP-579, AP-580, AP-581, AP-582, AP-583, AP-584, AP-585, AP-586, AP-587, AP-588, AP-589, AP-590, AP-591, AP-592, AP-593, AP-594, AP-595, AP-596, AP-597, AP-598, AP-599, AP-600, AP-601, AP-602, AP-603, AP-604, AP-605, AP-606, AP-607, AP-608, AP-609, AP-610, AP-611, AP-612, AP-613, AP-614, AP-615, AP-616, AP-617, AP-618, AP-619, AP-620, AP-621, AP-622, AP-623, AP-624, AP-625, AP-626, AP-627, AP-628, AP-629, AP-630, AP-631, AP-632, AP-633, AP-634, AP-635, AP-636, AP-637, AP-638, AP-639, AP-640, AP-641, AP-642, AP-643, AP-644, AP-645, AP-646, AP-647, AP-648, AP-649, AP-650, AP-651, AP-652, AP-653, AP-654, AP-655, AP-656, AP-657, AP-658, AP-659, AP-660, AP-661, AP-662, AP-663, AP-664, AP-665, AP-666, AP-667, AP-668, AP-669, AP-670, AP-671, AP-672, AP-673, AP-674, AP-675, AP-676, AP-677, AP-678, AP-679, AP-680, AP-681, AP-682, AP-683, AP-684, AP-685, AP-686, AP-687, AP-688, AP-689, AP-690, AP-691, AP-692, AP-693, AP-694, AP-695, AP-696, AP-697, AP-698, AP-699, AP-700, AP-701, AP-702, AP-703, AP-704, AP-705, AP-706, AP-707, AP-708, AP-709, AP-710, AP-711, AP-712, AP-713, AP-714, AP-715, AP-716, AP-717, AP-718, AP-719, AP-720, AP-721, AP-722, AP-723, AP-724, AP-725, AP-726, AP-727, AP-728, AP-729, AP-730, AP-731, AP-732, AP-733, AP-734, AP-735, AP-736, AP-737, AP-738, AP-739, AP-740, AP-741, AP-742, AP-743, AP-744, AP-745, AP-746, AP-747, AP-748, AP-749, AP-750, AP-751, AP-752, AP-753, AP-754, AP-755, AP-756, AP-757, AP-758, AP-759, AP-760, AP-761, AP-762, AP-763, AP-764, AP-765, AP-766, AP-767, AP-768, AP-769, AP-770, AP-771, AP-772, AP-773, AP-774, AP-775, AP-776, AP-777, AP-778, AP-779, AP-780, AP-781, AP-782, AP-783, AP-784, AP-785, AP-786, AP-787, AP-788, AP-789, AP-790, AP-791, AP-792, AP-793, AP-794, AP-795, AP-796, AP-797, AP-798, AP-799, AP-800, AP-801, AP-802, AP-803, AP-804, AP-805, AP-806, AP-807, AP-808, AP-809, AP-810, AP-811, AP-812, AP-813, AP-814, AP-815, AP-816, AP-817, AP-818, AP-819, AP-820, AP-821, AP-822, AP-823, AP-824, AP-825, AP-826, AP-827, AP-828, AP-829, AP-830, AP-831, AP-832, AP-833, AP-834, AP-835, AP-836, AP-837, AP-838, AP-839, AP-840, AP-841, AP-842, AP-843, AP-844, AP-845, AP-846, AP-847, AP-848, AP-849, AP-850, AP-851, AP-852, AP-853, AP-854, AP-855, AP-856, AP-857, AP-858, AP-859, AP-860, AP-861, AP-862, AP-863, AP-864, AP-865, AP-866, AP-867, AP-868, AP-869, AP-870, AP-871, AP-872, AP-873, AP-874, AP-875, AP-876, AP-877, AP-878, AP-879, AP-880, AP-881, AP-882, AP-883, AP-884, AP-885, AP-886, AP-887, AP-888, AP-889, AP-890, AP-891, AP-892, AP-893, AP-894, AP-895, AP-896, AP-897, AP-898, AP-899, AP-900, AP-901, AP-902, AP-903, AP-904, AP-905, AP-906, AP-907, AP-908, AP-909, AP-910, AP-911, AP-912, AP-913, AP-914, AP-915, AP-916, AP-917, AP-918, AP-919, AP-920, AP-921, AP-922, AP-923, AP-924, AP-925, AP-926, AP-927, AP-928, AP-929, AP-930, AP-931, AP-932, AP-933, AP-934, AP-935, AP-936, AP-937, AP-938, AP-939, AP-940, AP-941, AP-942, AP-943, AP-944, AP-945, AP-946, AP-947, AP-948, AP-949, AP-950, AP-951, AP-952, AP-953, AP-954, AP-955, AP-956, AP-957, AP-958, AP-959, AP-960, AP-961, AP-962, AP-963, AP-964, AP-965, AP-966, AP-967, AP-968, AP-969, AP-970, AP-971, AP-972, AP-973, AP-974, AP-975, AP-976, AP-977, AP-978, AP-979, AP-980, AP-981, AP-982, AP-983, AP-984, AP-985, AP-986, AP-987, AP-988, AP-989, AP-990, AP-991, AP-992, AP-993, AP-994, AP-995, AP-996, AP-997, AP-998, AP-999, AP-1000, AP-1001, AP-1002, AP-1003, AP-1004, AP-1005, AP-1006, AP-1007, AP-1008, AP-1009, AP-1010, AP-1011, AP-1012, AP-1013, AP-1014, AP-1015, AP-1016, AP-1017, AP-1018, AP-1019, AP-1020, AP-1021, AP-1022, AP-1023, AP-1024, AP-1025, AP-1026, AP-1027, AP-1028, AP-1029, AP-1030, AP-1031, AP-1032, AP-1033, AP-1034, AP-1035, AP-1036, AP-1037, AP-1038, AP-1039, AP-1040, AP-1041, AP-1042, AP-1043, AP-1044, AP-1045, AP-1046, AP-1047, AP-1048, AP-1049, AP-1050, AP-1051, AP-1052, AP-1053, AP-1054, AP-1055, AP-1056, AP-1057, AP-1058, AP-1059, AP-1060, AP-1061, AP-1062, AP-1063, AP-1064, AP-1065, AP-1066, AP-1067, AP-1068, AP-1069, AP-1070, AP-1071, AP-1072, AP-1073, AP-1074, AP-1075, AP-1076, AP-1077, AP-1078, AP-1079, AP-1080, AP-1081, AP-1082, AP-1083, AP-1084, AP-1085, AP-1086, AP-1087, AP-1088, AP-1089, AP-1090, AP-1091, AP-1092, AP-1093, AP-1094, AP-1095, AP-1096, AP-1097, AP-1098, AP-1099, AP-1100, AP-1101, AP-1102, AP-1103, AP-1104, AP-1105, AP-1106, AP-1107, AP-1108, AP-1109, AP-1110, AP-1111, AP-1112, AP-1113, AP-1114, AP-1115, AP-1116, AP-1117, AP-1118, AP-1119, AP-1120, AP-1121, AP-1122, AP-1123, AP-1124, AP-1125, AP-1126, AP-1127, AP-1128, AP-1129, AP-1130, AP-1131, AP-1132, AP-1133, AP-1134, AP-1135, AP-1136, AP-1137, AP-1138, AP-1139, AP-1140, AP-1141, AP-1142, AP-1143, AP-1144, AP-1145, AP-1146, AP-1147, AP-1148, AP-1149, AP-1150, AP-1151, AP-1152, AP-1153, AP-1154, AP-1155, AP-1156, AP-1157, AP-1158, AP-1159, AP-1160, AP-1161, AP-1162, AP-1163, AP-1164, AP-1165, AP-1166, AP-1167, AP-1168, AP-1169, AP-1170, AP-1171, AP-1172, AP-1173, AP-1174, AP-1175, AP-1176, AP-1177, AP-1178, AP-1179, AP-1180, AP-1181, AP-1182, AP-1183, AP-1184, AP-1185, AP-1186, AP-1187, AP-1188, AP-1189, AP-1190, AP-1191, AP-1192, AP-1193, AP-1194, AP-1195, AP-1196, AP-1197, AP-1198, AP-1199, AP-1200, AP-1201, AP-1202, AP-1203, AP-1204, AP-1205, AP-1206, AP-1207, AP-1208, AP-1209, AP-1210, AP-1211, AP-1212, AP-1213, AP-1214, AP-1215, AP-1216, AP-1217, AP-1218, AP-1219, AP-1220, AP-1221, AP-1222, AP-1223, AP-1224, AP-1225, AP-1226, AP-1227, AP-1228, AP-1229, AP-1230, AP-1231, AP-1232, AP-1233, AP-1234, AP-1235, AP-1236, AP-1237, AP-1238, AP-1239, AP-1240, AP-1241, AP-1242, AP-1243, AP-1244, AP-1245, AP-1246, AP-1247, AP-1248, AP-1249, AP-1250, AP-1251, AP-1252, AP-1253, AP-1254, AP-1255, AP-1256, AP-1257, AP-1258, AP-1259, AP-1260, AP-1261, AP-1262, AP-1263, AP-1264, AP-1265, AP-1266, AP-1267, AP-1268, AP-1269, AP-1270, AP-1271, AP-1272, AP-1273, AP-1274, AP-1275, AP-1276, AP-1277, AP-1278, AP-1279, AP-1280, AP-1281, AP-1282, AP-1283, AP-1284, AP-1285, AP-1286, AP-1287, AP-1288, AP-1289, AP-1290, AP-1291, AP-1292, AP-1293, AP-1294, AP-1295, AP-1296, AP-1297, AP-1298, AP-1299, AP-1300, AP-1301, AP-1302, AP-1303, AP-1304, AP-1305, AP-1306, AP-1307, AP-1308, AP-1309, AP-1310, AP-1311, AP-1312, AP-1313, AP-1314, AP-1315, AP-1316, AP-1317, AP-1318, AP-1319, AP-1320, AP-1321, AP-1322, AP-1323, AP-1324, AP-1325, AP-1326, AP-1327, AP-1328, AP-1329, AP-1330, AP-1331, AP-1332, AP-1333, AP-1334, AP-1335, AP-1336, AP-1337, AP-1338, AP-1339, AP-1340, AP-1341, AP-1342, AP-1343, AP-1344, AP-1345, AP-1346, AP-1347, AP-1348, AP-1349, AP-1350, AP-1351, AP-1352, AP-1353, AP-1354, AP-1355, AP-1356, AP-1357, AP-1358, AP-1359, AP-1360, AP-1361, AP-1362, AP-1363, AP-1364, AP-1365, AP-1366, AP-1367, AP-1368, AP-1369, AP-1370, AP-1371, AP-1372, AP-1373, AP-1374, AP-1375, AP-1376, AP-1377, AP-1378, AP-1379, AP-1380, AP-1381, AP-1382, AP-1383, AP-1384, AP-1385, AP-1386, AP-1387, AP-1388, AP-1389, AP-1390, AP-1391, AP-1392, AP-1393, AP-1394, AP-1395, AP-1396, AP-1397, AP-1398, AP-1399, AP-1400, AP-1401, AP-1402, AP-1403, AP-1404, AP-1405, AP-1406, AP-1407, AP-1408, AP-1409, AP-1410, AP-1411, AP-1412, AP-1413, AP-1414, AP-1415, AP-1416, AP-1417, AP-1418, AP-1419, AP-1420, AP-1421, AP-1422, AP-1423, AP-1424, AP-1425, AP-1426, AP-1427, AP-1428, AP-1429, AP-1430, AP-1431, AP-1432, AP-1433, AP-1434, AP-1435, AP-1436, AP-1437, AP-1438, AP-1439, AP-1440, AP-1441, AP-1442, AP-1443, AP-1444, AP-1445, AP-1446, AP-1447, AP-1448, AP-1449, AP-1450, AP-1451, AP-1452, AP-1453, AP-1454, AP-1455, AP-1456, AP-1457, AP-1458, AP-1459, AP-1460, AP-1461, AP-1462, AP-1463, AP-1464, AP-1465, AP-1466, AP-1467, AP-1468, AP-1469, AP-1470, AP-1471, AP-1472, AP-1473, AP-1474, AP-1475, AP-1476, AP-1477, AP-1478, AP-1479, AP-1480, AP-1481, AP-1482, AP-1483, AP-1484, AP-1485, AP-1486, AP-1487, AP-1488, AP-1489, AP-1490, AP-1491, AP-1492, AP-1493, AP-1494, AP-1495, AP-1496, AP-1497, AP-1498, AP-1499, AP-1500, AP-1501, AP-150

DOCKETED ITEMS

17

- 7905000250 Notification of 790427 meeting w/UTL to discuss status of investigation into small primary pipe coolant leak
MEMPHIS, J. G. Operating Reactors Branch 2 79/04/24 1p
- 7905000499 Response to NRC 790115 request for info consultant will be utilized to develop seismic design basis which will entail providing dynamic models of structures listed in enc 1 & response spectra at specified locations
BIDEL, D. A. Consumers Power Co. 79/04/25 3pp
- 7905000499 Forwarded revised page 5-4 inadvertently omitted from 790322 Tech Specs for license Amendment 2
ZIEHLER, J. G. Operating Reactors Branch 2 79/04/25 3pp
- 7905000595 Comments on draft evaluation "Reaction Battery Test Requirements," submitted on 4/24/79
BIDEL, D. A. Consumers Power Co. 79/05/02 3pp
- 7905010449 Response to IE Bulletin 79-03, "Atypical Held Metal in Reactor Pressure Vessel." Final report will be submitted by 79/03/31
BIDEL, D. A. Consumers Power Co. 79/03/29 1p
- 0 Inspection Reports: IE Bulletins & correspondence
- 7905010703 Forwarded IE Insp Rept 30-155/79-03 on 790224-0302 No noncompliance noted
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/03/19 3pp
- 7905010335 IE Insp Rept 30-155/79-03 on 790226-0302 No noncompliance noted Major areas inspected design changes, rod program procedures & refueling surveillance
BIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/03/19 3pp
- 7905030541 Forwarded IE Insp Rept 30-155/79-02 on 790214-16 No noncompliance noted
DAVIS, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/19 3pp
- 7905030545 IE Insp Rept 30-155/79-02 on 790216-16 No noncompliance noted Major areas inspected refueling radiation protection activities including procedures, advanced planning, training, exposure, MSL control & packing
BIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/03/19 3pp
- 7905010507 Forwarded IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/03/23 1p
- 7905040026 Forwarded IE Info Notice 79-07, "Rupture of Radwaste Tank" *
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/03/26 1p
- 7905010548 Forwarded IE Info Notice 79-08, "Interconnection of Contaminated By-Product Air Systems Used as Source of Breathing Air"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/03/26 1p
- 7905010590 Forwarded IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/03/30 1p
- 7905000806 Forwarded IE Insp Rept 30-155/79-04 on 790213-14, 0215 & 20-27
FIDELL, L. A. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/09 3pp
- 7905010849 IE Insp Rept 30-155/79-04 on 790213-14, 0215 & 20-27 No noncompliance noted Major areas inspected isotope Insp QA/QC program, implementing procedures, work activities, nondestructive examination data & repair & core spray
WATTS, R. S., BIDENHAIN, R. F., HEIDENHAIN, D. H. Region 3, Chicago, Office of the Director 79/04/09 10pp
- 7905030325 Forwarded IE Bulletin 79-04, "Review of Operational Errors & Gas Misalignments Identified During TMI Incident"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/04/11 1p
- 7905010879 Forwarded IE Bulletin 79-04A, "Review of Operational Errors & Gas Misalignments Identified During TMI Incident"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040028 Forwarded IE Bulletin 79-06a, "Review of Operational Errors & Gas Misalignments Identified During TMI Incident"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905030325 Forwarded IE Bulletin 79-07, "Events Relevant to Bolting Water Power Reactors Identified During TMI Incident"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905030325 Forwarded IE Bulletin 79-07, "Events Relevant to Bolting Water Power Reactors Identified During TMI Incident"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905030325 Forwarded IE Bulletin 79-08, "Failures of GE Type AW-2 Circuit Breaker in Safety-Related Systems"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/04/17 1p
- 7905000486 Forwarded IE Bulletin 79-08b, "Nuclear Incident at TMI-2"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/04/21 1p
- 7905030325 Response to 790329 request to allow UTL to combine review of IE Bulletin 79-02 & systematic evaluation program Topic 11-B-A Since bulletin involves safety issues, NRC refuses to extend time for review
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/04/26 1p
- 7905010908 Informal that response to IE Bulletin 79-08, "Events Relevant to Bolting Water Power Reactors Identified During TMI Incident," will be delayed one week due to plant outage considerations
HEIDENHAIN, R. F. Consumers Power Co. 79/04/27 1p
- 7905040029 Forwarded IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Operated by Setpoint in Reactor Power Increase"
HEIDENHAIN, R. F. Region 3, Chicago, Office of the Director 79/05/02 1p
- 7905030270 Provides add'l response to IE Bulletin 79-07 Forwarded verification benchmarks used for dynamic piping analysis
BIDEL, D. A. Consumers Power Co. 79/05/04 7pp
- 7905030143 Response to IE Bulletin 79-08 re events relevant to BUEs identified during TMI-2 incident No Tech Spec will be required to implement actions discussed in 790504 str
HEIDENHAIN, R. F. Consumers Power Co. 79/05/14 1p
- 7905030319 Quarterly Status Rept of Investigations & Mods.: Jan-Mar 1979, Rept 21
PACIFIC GAS & ELECTRIC CO. 79/05/22 1p
- 0 Reportable occurrences, LERs & related correspondence
- 7905030480 Forwarded LERs 79-017/02L-0 & 79-018/01Y-0
BIDEL, D. A. Consumers Power Co. 79/05/02 1p
- 7905030484 LER 79-017/02L-0 on 790418 following scan & during routine primary gas leak data testing identified leakage observed at 100 psi. Apparent cause was cooling water temp transients
* Consumers Power Co. 79/05/02 1p
- 7905030480 LER 79-018/01Y-0 on 790420 minor water leakage observed at interface between reactor vessel & P-2 rod drive bearing. Leak stopped when primary gas pressure was reduced to atmospheric conditions
* Consumers Power Co. 79/05/02 3pp
- 7905030487 Forwarded LER 79-017/02L-0
BIDEL, D. A. Consumers Power Co. 79/05/10 1p
- 7905030489 LER 79-017/02L-0 on 790418 eight mechanical shutoffs on reactor depressurization gas piping appeared inadequately installed during NRC Insp. Units deemed inoperable w/o proof until made completed 790420
* Consumers Power Co. 79/05/10 1p

DOCKETED ITEMS

DOCKET 30-154 UNIV. OF WISCONSIN RESEARCH REACTOR

J Insurance & indemnity information

7905140258 Forwards Amend 12 to Indemnity Agreement E-37, per 10CFR140 changes, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 5pg

7905140260 Forwards executed Amend 12 to Indemnity Agreement E-37 WISCONSIN Univ. of Madison 79/05/01 2pg

Q Inspection reports, IE Bulletins & correspondence

7905140187 Forwards IE Insp Rpt 30-154/79-01 re 790515-14

No noncompliance noted
ICISMAN, R. P. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/26 2pg

7905140143 IE Insp Rpt 30-154/79-01 re 790515-14 No noncompliance noted Major areas inspected operational experience, main surveillance, operator qualifications, audits & procedures
LITLLE, M. Region 3, Chicago, Reactor Operations Nuclear Support Branch, 790501 E. DANIEL, J. Region 3, Chicago, Office of the Director 79/05/23 3pg

DOCKET 30-157 CORNELL UNIV. RESEARCH REACTOR

J Insurance & indemnity information

7905140030 Forwards Amend 11 to Indemnity Agreement E-4, reflecting change in 10CFR140 increasing primary layer of liability from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 3pg

DOCKET 30-162 GEORGIA INST. OF TECH. RESEARCH REACTOR

J Insurance & indemnity information

7905140048 Forwards Amend 12 to Indemnity Agreement E-36 reflecting change in 10CFR140 increasing primary layer of liability from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 3pg

Q Inspection reports, IE Bulletins & correspondence

7905140137 Forwards IE Bulletin 79-05/79-03A & 79-05 re nuclear incidents at TSP
REILLY, J. P. Region 2, Atlanta, Office of the Director 79/05/13 1p

DOCKET 30-164 UNIV. OF MARYLAND RESEARCH REACTOR

J Insurance & indemnity information

7905140274 Forwards Amend 9 to Indemnity Agreement E-20, per 10CFR140 changes, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 3pg

DOCKET 30-170 NATIONAL HAWAII MEDICAL CENTER

J Insurance & indemnity information

7905140072 Forwards Amend 9 to Indemnity Agreement E-2, per 10CFR140 changes, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 3pg

7905140056 Statutes assigned Amend 9 to Indemnity Agreement E-21

Federal Agency re action, per 10CFR140 ID
KASBORG, D. W. Defense Dept. of Defense Nuclear Agency 79/05/23 2pg

DOCKET 30-171 PINEHOLM ATOMIC POWER STATION, UNIT 1

J Insurance & indemnity information

7905140145 Forwards Amend 30 to Indemnity Agreement E-20, per 10CFR140 changes, re increase in liability insurance from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 4pg

DOCKET 30-162 PURDUE UNIV. RESEARCH REACTOR

J Insurance & indemnity information

7905140258 Forwards Amend 9 to Indemnity Agreement E-6, per 10CFR140 changes, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 3pg

7905140242 Forwards executed Amend 9 to Indemnity Agreement E-6 SMITH, R. E. Purdue Univ 79/05/22 3pg

Q Inspection reports, IE Bulletins & correspondence

7905140041 Forwards IE Insp Rpts 30-162/79-01 & 79-0122/79-02 on 790512-13 Notice of violation withheld (ref 10CFR 290)
Region 3, Chicago, Safeguards Branch 79/05/26 3pg

7905140147 IE Insp Rpt 30-162/79-01 & 79-0122/79-02 on 790512-13 Noncompliance noted bays, racks & hardware deficiencies for fast breeder blanket fertility details withheld (ref 10CFR 290)
CHRISTOFFER, G. H. HANSEN, J. J. Region 3, Chicago, Office of the Director HIND, J. A. Region 3, Chicago, Safeguards Branch 79/05/21 1p

DOCKET 30-163 WALLECE RESEARCH REACTOR

A Application/construction stage documents & correspondence

7905140029 Summaries 790503-04 meeting WABC in San Jose, CA re piping improvement program Progress Rpt & Forwards requested action items re piping analysis
GOSLER, R. L. General Electric Co. Nuclear Energy Products Div 79/04/23 125pg

DOCKET 30-164 NATIONAL BUREAU OF STANDARDS REACTOR

J Insurance & indemnity information

7905140081 Forwards Amend 11 to Indemnity Agreement E-3, per 10CFR140 changes, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 3pg

7905140244 Forwards executed Amend 11 to Indemnity Agreement E-3 ANDER, C. Commerce Dept. of National Bureau of Standards 79/05/15 2pg

DOCKET 30-164 UNIV. OF MINNESOTA RESEARCH REACTOR

J Insurance & indemnity information

7905140039 Forwards Amend 11 to Indemnity Agreement E-4, per 10CFR140 changes, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 3pg

7905140401 Forwards executed Amends 10 & 11 to Indemnity Agreement E-20 & E-25, respectively
KRAMERT, V. Missouri Univ. of 79/05/25 3pg

DOCKET 30-167 SPACE RADIATION RESEARCH REACTOR

J Insurance & indemnity information

7905140049 Forwards Amend 12 to Indemnity Agreement E-26, per 10CFR140 changes, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 3pg

DOCKET 30-168 MINNESOTA STATE UNIV. RESEARCH REACTOR

J Insurance & indemnity information

7905140202 Forwards Amend 11 to Indemnity Agreement E-1, per 10CFR140 changes, re increase from \$140 million to \$140 million, effective 790501 Supporting documentation encl.
BALTIMAN, J. Antitrust & Indemnity Group 79/05/01 3pg

7905140004 Forwards Amend 11 to Indemnity Agreement E-1
KOPPEL, M. C. Kansas State Univ 79/05/17 3pg

DOCKETED ITEMS

19

B Inspection reports, IE Bulletin & correspondence

7905190994 Forwards IE Insp Rept. 30-108/79-01 on 790312-15 Re noncompliance noted
HARRISON G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/28 Spp

7905190404 IE Insp Rept 30-108/79-01 on 790312-15 Re noncompliance noted Major areas inspected licensee's internal review: operating procedures, radiation protection, environment protection & emergency planning
JOHNSON E H, GASTABLE G L Region 4, Dallas, Office of the Director HARRISON G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/27 Spp

DOCKET 30-191 BAKCOCK & WILCOX COMPANY CRITICAL FACILITY

J Insurance & indemnity information

7905200714 Forwards Amend 19 to Indemnity Agreement 3-B, per 10CFR140 changes, re increase from \$160 million to \$160 million, effective 790301 Supporting documentation encl
BALTIMAN J Antitrust & Indemnity Group 79/03/01 Spp

7905200427 Forwards executed Amend 1 to Indemnity Agreement 0-2 & Amend 19 to Indemnity Agreement 3-B
GILMAN A F Bakcock & Wilcox Co 79/03/21 Spp

DOCKET 30-192 UNIV. OF TEXAS RESEARCH REACTOR

J Insurance & indemnity information

7905160399 Forwards Amend 15 to Indemnity Agreement 0-25, per 10CFR140 changes, re increase from \$160 million to \$160 million, effective 790301 Supporting documentation encl
BALTIMAN J Antitrust & Indemnity Group 79/03/01 Spp

DOCKET 30-193 INDIAN ISLAND & PROVIDENCE PLANTATIONS AEC

J Insurance & indemnity information

7905160260 Forwards Amend 9 to Indemnity Agreement 0-43, per 10CFR140 changes, re increase from \$160 million to \$160 million, effective 790301 Supporting documentation encl
BALTIMAN J Antitrust & Indemnity Group 79/03/01 Spp

7905190349 Amend 9 to Indemnity Agreement 0-43
BALTIMAN J Antitrust & Indemnity Group 79/03/14 Spp

DOCKET 30-194 MAMMATHAN COLLIER RESEARCH REACTOR

J Insurance & indemnity information

7905190307 Forwards Amend 10 to Indemnity Agreement 0-41, per 10CFR140 changes, re increase from \$160 million to \$160 million, effective 790301 Supporting documentation encl
BALTIMAN J Antitrust & Indemnity Group 79/03/01 Spp

DOCKET 30-200 SAN TEST REACTOR

J Insurance & indemnity information

7905200714 Forwards Amend 19 to Indemnity Agreement 3-B, per 10CFR140 changes, re increase from \$160 million to \$160 million, effective 790301 Supporting documentation encl
BALTIMAN J Antitrust & Indemnity Group 79/03/01 Spp

7905200427 Forwards executed Amend 1 to Indemnity Agreement 0-2 & Amend 19 to Indemnity Agreement 3-B
GILMAN A F, Bakcock & Wilcox Co 79/03/21 Spp

DOCKET 30-201 WEST VALLEY REPROCESSING PLANT

D Adjudicatory correspondence

7905190720 Requests JH Hendrix to appear at 790404 hearing re safety aspects of high level radioactive tanks at Facility Test results showed leak in pan water tank containing 600,000 gallons high level liquid radioactive
NYFF, W. R. New York, State of 79/03/21, Spp

J Insurance & indemnity information

7905160301 Forwards Amend 10 to Indemnity Agreement 5-25, per 10CFR140 changes, re increase from \$160 million to \$160 million, effective 790301 Supporting documentation encl
BALTIMAN J Antitrust & Indemnity Group 79/03/01 Spp

P Operating license stage documents & correspondence

7905200204 Notification that high level tanks stored at West Valley, NY will not be moved from site 6D-2 to 6D-3 as previously stated
Action unwarranted & counterproductive to ongoing AEC studies
CLARK, J R Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/03/27 Spp

7905200303 Forwards "Evaluation of Safety Associated w/Defect in Pan 6D-2 at West Valley, NY - Defect cause unknown NO attempt should be made to repair pan w/o further detailed analysis
HARRISON, G J Fuel Reprocess & Recycle Branch 79/03/29 Spp

7905200312 Requests to 790320 for re radiation levels in Sutteraug Creek & site above Springville Power San Forwards data re site samples for 1967-69, 1971, 1977 & 1979
GARDNER, J J New York, State of 79/04/19 Spp

7905200312 Requests to 790320 for re radiation levels in Sutteraug Creek & site above Springville, NY re detection of radioactivity in site samples at Springville San W/vents on site samples for 1967-69, 1971 & 1977-79
CLARK, A T Fuel Reprocess & Recycle Branch 79/05/01 Spp

B Inspection reports, IE Bulletin & correspondence

7905100602 Forwards IE Info Notice 79-04, "Interconnection of Contaminated Sys w/Brk Air Sys Used as Source of Breathing Air."
OHLER, S H Region 1, Philadelphia, Office of the Director 79/03/28, Spp

B Periodic operating reports & related correspondence

7905200404 Forwards discharge monitoring report for Mar 1979
Radioactivity results re outfalls 001 & 022 will be reporing as data becomes available
CLARK, J R Nuclear Fuel Services, Inc (subs of Getty Oil Co) 79/04/10 Spp

DOCKET 30-204 SAN SHIPRE NUCLEAR REACTION UNIT 1

F Security, medical, emergency & fire protection plans

7905200204 Updates status of components re operating functions & plant mode of fire protection program Discusses safe shutdown cooling procedure, sprayer valve activation & hydrogen seal oil area fire.
GILMAN A F Southern California Edison Co 79/03/15 Spp

E Financial information

7905190400 Forwards Annual Financial Rept 1978 for 2 Edison Co & San Diego Gas & Electric Co
BARNES, J H Southern California Edison Co 79/04/04

DOCKETED ITEMS

790507052 Confirms increase in liability limit to \$34,000,000 for policies 88-20, 88-21, 88-25, 44-46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000.

790516034 Forwards Amend 12 to Indemnity Agreement 8-31 per 100R146 charges. re increase from \$450 million to \$650 million. effective 790501 Regarding documentation and Antitrust & Indemnity Group 79/05/01 App

790519010 Forwards executed Amend 12 to Indemnity Agreement 8-31 MILLANES P H San Diego Gas & Electric Co 79/05/14 App

P Periodic license change documents and correspondence

790502044 Forwards Amend 40 to License DPR-13 safety evaluation. notice of issuance & availability Security plan evaluation withheld (ref 100F92 7901 2180464 D L Operating Reactors Branch 2 79/04/10 App

790502040 Amend 40 to License DPR-13 requiring maint & implementation of physical security plan 2180464 D L Operating Reactors Branch 2 79/04/10 App

790502047 Notice of issuance & availability of Amend 40 to License DPR-13 2180464 D L Operating Reactors Branch 2 79/04/10 App

790504000 Requests license provide design made which will assure safe shutdown can be achieved & maintained using remote power source LARABO Plant Systems Branch 79/04/13 App

790505000 Forwards begins deleted from systematic evaluation program review of facilities Requests review & identification of errors within 30 days from receipt of ltr 2180464 D L Operating Reactors Branch 2 79/04/16 App

790505002 Forwards draft evaluation of systematic evaluation program Topic US-10 B Requests review & response within three days 2180464 D L Operating Reactors Branch 2 79/04/16 App

790505009 Evaluates possible vibration problems re operation of chemical val & control system test pump Re problems & anticipated 2180464 D L Southern California Edison Co 79/04/20 App

790505047 Forwards Amend 70 to License DPR-13 Affidavit & Certificate of Svc and 2180464 D L Southern California Edison Co 79/05/04 App

790505056 Amend 70 to License DPR-13, consisting of proposed Tech Spec Change 79, increasing allowed discharge limit of sulphuric acid to allow Units 2 & 3 to discharge startup flushing wastewater directly into Unit 1 & Southern California Edison Co 79/05/04 App

790513074 Forwards results of util examination of NRC 790515 revised systematic evaluation program topic assessments 2180464 D L Southern California Edison Co 79/05/04 App

790520004 Notices of inability to meet reply deadline for 18 Bulletin 79-124 Auditing safe from Westinghouse HEAD J T Southern California Edison Co 79/03/20 App

790510020 Forwards 18 Info Notice 79-06 "Interconnection of Contaminated Gas with Air Sys Used as Source of Breathing Air" 2180464 D L Region 3, San Francisco, Office of the Director 79/03/22 App

790510040 Forwards 18 Info Notice 79-09 "Spill of Radioactively Contaminated Resin" 2180464 D L Region 3, San Francisco, Office of the Director 79/03/30 App

790510020 Forwards 18 Bulletin 79-04A "Review of Operational Errors & Sys Reliability Identified During TMI Incident" 2180464 D L Region 3, San Francisco, Office of the Director 79/04/14 App

790510020 Forwards 18 Bulletin 79-04A "Review of Operational Errors & Sys Reliability Identified During TMI Incident" 2180464 D L Region 3, San Francisco, Office of the Director 79/04/14 App

790510081 Forwards 18 Bulletin 79-05B "Review of Operational Errors & Sys Reliability Identified During TMI Incident" 2180464 D L Region 3, San Francisco, Office of the Director 79/04/14 App

790510040 Forwards 18 Bulletin 79-08 "Events Relevant to Boiling Water Reactor Identified During TMI Incident" 2180464 D L Region 3, San Francisco, Office of the Director 79/04/14 App

790510010 Forwards 18 Bulletin 79-07 "Reactor Stress Analysis of Safety-Related Piping" 2180464 D L Region 3, San Francisco, Office of the Director 79/04/14 App

790510009 Forwards 18 Bulletin 79-06 "Failures of SE Type AN-2 Circuit Breaker in Reactor-Related Sys" 2180464 D L Region 3, San Francisco, Office of the Director 79/04/17 App

790510000 Requests to 18 Bulletin 79-04A Item 3 re initiation of auxiliary feedwater sys. Sys initiated by operator action Requests exemption from requirements of item immediate initiation is not essential HEAD J T Southern California Edison Co 79/04/19 App

790510001 Forwards 18 Bulletin 79-08 "Nuclear Incident at TMI-Supp1" 2180464 D L Region 3, San Francisco, Office of the Director 79/04/21 App

790520003 Requests to 18 Bulletin 79-07 re seismic stress analysis Computer codes containing algebraic summation errors have not been used in design & analysis at Facility Computer code confirmation will be requested by 790520 HEAD J T Southern California Edison Co 79/04/24 App

R Periodic operating reports & related correspondence

790513040 Forwards monthly operating report for Apr 1979 2180464 D L Southern California Edison Co 79/05/04 App

DOCKETED ITEMS

21

7905040100 Forwards PHD-79-678
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/12 1p

7905101415 Forwards PHD-79-677
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/13 1p

7905030024 Forwards PHD-79-679
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/14 1p

7905030026 Forwards PHD-79-678A
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/20 1p

7905010434 Forwards PHD-79-678B
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/21 1p

7905010449 Forwards PHD-79-678C & D
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/23 1p

7905010448 Forwards PHD-79-678E
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/24 1p

7905090041 Forwards PHD-79-678F
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/25 1p

7905090027 Forwards PHD-79-678G
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/26 1p

7905040586 Forwards LER 79-007/03L-5
HEAD, J. T. Southern California Edison Co 79/04/27 2pp

---7905040592 LER 79-007/03L-0 on 790404 see temp data from three sensors not obtained for three periods caused by double film image on cartridge, removed film cartridge & unit turn from on-charge. All units replaced or replaced
GURRAN, J. H. Southern California Edison Co 79/05/01 1p

7905040619 Forwards PHD-79-678H
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/27 1p

7905050031 Forwards PHD-79-678I, A2 & A6 per NRC 790401 ltr transmitting
IE Bulletin 79-05
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/04/30 1p

7905070012 Forwards PHD-79-678L per NRC 790401 ltr transmitting
IE Bulletin 79-05
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/05/01 1p

7905090418 Forwards LER 79-007/03L-0
HEAD, J. T. Southern California Edison Co 79/05/03 2pp

---7905080425 LER 79-007/03L-0 on 790404 during normal operation isolation valve on cooling water from containment air handling units failed to latch in open position. Caused by displaced wire clip & metal pin. Bolts replaced & pin secured.
GURRAN, J. H. Southern California Edison Co 79/05/03 1p

7905101034 Forwards LER 79-007/03L-0
HEAD, J. T. Southern California Edison Co 79/05/04 2pp

---7905101039 LER 79-007/03L-0 on 790404 feedwater flow indication B row is 100 above actual flow. Caused by flow straightening tube bundle disalignment. Straighteners B & C replaced & attachment strengthened.
GURRAN, J. H. Southern California Edison Co 79/05/04 1p

7905100444 Forwards PHD-79-678M
SUGELMAN, R. H. Region 5, San Francisco, Office of the Director
79/05/07 1p

7905101050 Forwards LER 79-007/03L-0
HEAD, J. T. Southern California Edison Co 79/05/11 2pp

---7905101052 LER 79-007/03L-0 on 790403 two quarterly & two quarterly neutron direct radiation TDS were lost. Caused by vandalism. TDS now in locked PVC tube & permanently fastened at sample location.
GURRAN, J. H. Southern California Edison Co 79/05/11 1p

7905030028 Forwards Interim Rept of Marine Review Committee re ECRS
MORG, B. California, State of 79/05/15 1p

---7905030070 "Interim Rept of Marine Review Committee re CA Coastal Commission/Part I General Summary of Findings/Predictions & Recommendations Concerning Cooling Bays"
CONNELL, J. H. & MCKOLAS, B. J. & NICHOLSON, J. A. California, State of 79/05/12 22pp

---7905030077 "Interim Rept of Marine Review Committee re CA Coastal Commission/Part II App of Technical Evidence in Support of General Summary"
CONNELL, J. H. & MCKOLAS, B. J. & NICHOLSON, J. A. California, State of 79/05/12 157pp

7905030438 Forwards LER 79-007/03L-0
HEAD, J. T. Southern California Edison Co 79/05/22 1p

---7905030444 LER 79-007/03L-0 on 790403 during full power operation steam flow indicator for steam generator A failed. Indicating error flow caused by failed power supply to steam flow indication circuitry. Failed power supply replaced.
GURRAN, J. H. Southern California Edison Co 79/05/22 1p

DOCKET 50-030 COLUMBIA UNIV. RESEARCH REACTOR
J Insurance & indemnity information

7905101028 Forwards Amend 2 to Indemnity Agreement E-40, per 10CFR140
changes: 74 increase from \$140 million to \$160 million effective 790501 Supporting documentation encl
BALTZMAN, J. Antitrust & Indemnity Group 79/05/01 3pp

DOCKET 50-213 HADDAM NERF PLANT
J Insurance & indemnity information

7905090073 Forwards response to NRC verbal questions re fire protection Engineering & design of mock made in progress
CONNELL, J. H. Northshore Utilities 79/05/10 1pp

J Insurance & indemnity information

7905070047 Confirms increased liability limit to \$424,000,000 for policies ME-20, 26, 28, 30, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 83, 84, 87, 88, 90, 91, 92, 93, 94, 95, & 96
ROBERTS, B. H. American Nuclear Insurers 79/05/01 1p

7905070082 Confirms increase in liability limit to \$46,000,000 for policies ME-20, 26, 28, 30, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 83, 84, 87, 88, 90, 91, 92, 93, 94, 95, & 96
ROBERTS, B. H. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905100029 Forwards Amend 12 to Indemnity Agreement E-3L per 10CFR140
changes: 74 increase from \$160 million to \$180 million effective 790501 Supporting documentation encl
BALTZMAN, J. Antitrust & Indemnity Group 79/05/01 3pp

P Operating license stage documents & correspondence

7905090016 Forwards topics deleted from systematic review of facilities. Requests review & identification errors within 30 days from receipt of ltr
EIDHARD, D. L. Operating Reactors Branch 2 79

7905040003 Inform that letter rewritten to specially described in Revision 3A to 3A re: MJ-BM-1, form
790424
CONNELL, J. H. Connecticut Yankee Atomic Power Co

G Inspection reports, IE Bulletins & correspondence

7905090142 Forwards IE Insp Rept 50-213/79-05 on 790501-02
notes. Major areas inspected: licensee status on 790501-02
BRUNNER, E. J. Region 1, Philadelphia, Reactor Support Branch 79/05/14 2pp

---7905090144 IE Insp Rept 50-213/79-05 on 790501-02 notes. Major areas inspected: licensee status on 790501-02
BRUNNER, E. J. Region 1, Philadelphia, Reactor Support Branch 79/05/14 2pp

7905010402 Forwards IE Info Notice 79-05, "Stress Analysis of Safety-Related Piping"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/03/23 1p

7905030276 Forwards IE Info Notice 79-05, "Rupture of Reducers Tanks"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/03/25 1p

7905010340 Forwards IE Info Notice 79-05, "Interconnection of Contaminated Dye with Air Dye Used as Source of Breathing Air"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/03/28 1p

7905010290 Forwards IE Info Notice 79-05, "Spill of Radioactively Contaminated Resin"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/03/30 1p

7905050036 Forwards IE Bulletin 79-05, "Review of Operational Errors & Dye Misalignments Identified During 3RI Incident - Licensee action required"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/04/11 1p

7905020034 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping - Licensee action required"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/04/14 1p

7905040010 Forwards IE Bulletin 79-08, "Review of Operational Errors & Dye Misalignments Identified During 3RI Incident"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/04/14 1p

7905040180 Forwards IE Bulletin 79-08, "Events Relevant to Belling Water Four Reactor Identified During 3RI Incident"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/04/14 1p

7905030446 Forwards IE Bulletin 79-02 re longitudinal weld defects in ASME SA-312 stainless steel pipe. Pipe not in use or planned for use in unit.
CORRIGLI, W. O. Northeast Utilities
79/04/16 1p

7905030099 Forwards IE Bulletin 79-09, "Failures of OE Type A-2 Circuit Breaker in Safety-Related Dye - Licensee action required"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/04/17 1p

7905010441 Forwards IE Bulletin 79-04a, Revision 1, "Review of Operational Errors & Dye Misalignments Identified During 3RI Incident - Licensee action required"
GRIER, S. H. Region I, Philadelphia, Office of the Director
79/04/18 1p

7905040282 Forwards IE Bulletin 79-04 & 79-04a, Revision 1 re 3RI errors. Describes changes in operating procedures, preventative measures & instructions to personnel.
CORRIGLI, W. O. Connecticut Yankee Atomic Power Co.
79/04/24 7pgs

7905010473 Forwards IE Bulletin 79-04, "Incorrect Weights for Gating Check Valves R4 by Veier Engineering Corp. - No Valve valves in use on Bellingham L piping sys"
CORRIGLI, W. O. Connecticut Yankee Atomic Power Co.
79/04/26 1p

7905070042 Forwards "Interview Log & Testing Program -" revised Jan 1978
CORRIGLI, W. O. Connecticut Yankee Atomic Power Co.
79/04/27 2pg

7905070044 "Interview Log & Testing Program -" revised Jan 1978
CORRIGLI, W. O. Connecticut Yankee Atomic Power Co.
79/04/28 8pgs

7905030023 Forwards 790331-0023 steam generator tube leak rep. rpt.
CORRIGLI, W. O. Connecticut Yankee Atomic Power Co.
79/05/20 1p

7905030027 "Eddy Current Examination Tube Sheet Cleaning & Explosive Popping" rep. rpt. for 790331-0023
CORRIGLI, W. O. Connecticut Yankee Atomic Power Co.
79/05/23 33pgs

B Periodic operating reports & related correspondence

7905010211 Forwards monthly operating rep. for Apr 1979
GRIER, S. H. Connecticut Yankee Atomic Power Co.
79/05/01 1p

7905010214 Monthly operating rep. for Apr 1979
CORRIGLI, W. O. Connecticut Yankee Atomic Power Co.
79/05/01 7pgs

B Reportable occurrences, LERS & related correspondence

7905040051 Forwards LER 79-004/988-0
GRIER, S. H. Connecticut Yankee Atomic Power Co.
79/04/26 1p

7905030070 LER 79-004/990-0 as 790118 auxiliary feed pump did not discharge at rated flow. Cause undetermined. New notes & reeler supply under resulted in acceptable flow.
PLENIGER, S. T. Connecticut Yankee Atomic Power Co.
79/04/26 2p

7905030044 Notices of 790517 RD during which 250 gallons of radon hydrocarbons were released at river's edge in 2-hr period.
GRIER, S. H. Connecticut Yankee Atomic Power Co.
79/05/23 2pg

DOCKET ID-219 DYSTER GREEN NUCLEAR POWER PLANT

G Adjudicatory correspondence

7905030049 Notices of OE proposal for reanalysis of equipment effects resulting from a combination of seismic & LOCA loads for Mark II & III plants. Adequacy of proposed methodology being reviewed w/supporting documentation.
GRIER, S. H. Branch 3
79/04/04 1p

7905030041 Board notification status of actions re program of reanalysis for Mark II & III sys. Evaluation will be included in individual safety evaluation.
MATTISON, R. J. Division of Systems Safety
79/04/03 1p

7905030044 Concludes nothing new was achieved in OE 790336 safety on safety issues. However, structured actions bringing separate issues together in equipment design program was immediate.
MATTISON, R. J. Division of Systems Safety
79/03/16 4pg

7905030046 Forwards handbook & list of attendees for meeting to identify deficiencies in acceptance criteria & modification methods proposed by OE for use in reanalysis of Mark II & III plant equipment.
MATTISON, R. J. Division of Systems Safety
79/03/06 2pg

7905030051 "Methodology for Combining Dynamic Responses"
GRIER, S. H. MATTISON, R. J. MATTISON, R. J. Office of Nuclear Reactor Regulation
79050-2486 79/09/30 2pgs Available at NTIS

7905040010 Forwards RE Section 790429 memo discussing results of recently conducted fire protection research test by UL for ASME pipe penetration research program.
MATTISON, R. J. Branch 3
79/04/03 1p

J Insurance & indemnity information

7905070047 Confirms increased liability limit to \$124,900,000 per policies NF-3, 25, 43, 74, 90, 100, 115, 145, 160, 151, 165, 184, 170, 173, 174, 176, 178, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 205, 207, 208, 210, 215, 216, 219, & others.
QUARTZBERGER, J. American Nuclear Insurance
79/05/01 1p

7905070052 Confirms increase in liability limit to \$30,000,000 per policies NF-22, 34, 39, 30, 39, 44, 45, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters
79/05/01 1p

7905040049 Forwards Amend 12 to Indemnity Agreement 8-37, per 1958 Act changes re increase from \$160 million to \$300 million effective 790501. Supporting documentation encl.
MATTISON, R. J. Accident & Indemnity Group
79/03/01 5pg

7905020051 Forwards executed Amend 12 to Indemnity Agreement 8-37.
FISHER, E. R. Jersey Central Power & Light Co.
79/05/28 3pg

7905020049 Forwards executed Amend 10 to Indemnity Agreement 8-37.
FISHER, E. R. Jersey Central Power & Light Co.
79/05/28 3pg

P Approving license stage documents & correspondence

7905040070 "Analysis of Regulations of Towing & Pooling Organisms in Vicinity of Dyster Creek Nuclear Generating Station - annual progress rep. Sept 1977-Aug 1978"
HOWLAND, M. F. CROSBY, J. Lewis Univ. PSN 8-8744 NUREG/CR-0431
79/03/28 11pgs. Available at NTIS 47, 25.

7905030052 Forwards topics detailed from systematic evaluation program review facilities. Requests review & identification of errors & omissions within 30 days from receipt of the.
ZIEGLER, D. L. Operating Reactors Branch 2
79/04/16 7pg

DOCKETED ITEMS

23

7903076630 Informs of near completion of evaluation to determine impact of operation of four recirculation pumps & on currently derated LSCA analysis & corresponding limits in Area 33 Plant operation Restricted until analysis completed
FINR0001.1 H Jersey Central Power & Light Co 79/04/30 App

7903010170 Forwards Mar 1979 Mark I containment program activity review
SEB001.1 J General Electric Co 79/03/10 App

7903025204 Submits info requested in 7903010170 re proposed mode of operation pending completion of analysis to support four pump operation. Discusses backflow through idle loop & heat generation rate curves during startup period.
SEB001.1 H GPU Service Corp 79/03/19 App

7903040147 Informs of no further comments or corrections to NRC revised safety assessment of systematic evaluation program Table 5-10 A
FINR0001.1 H Jersey Central Power & Light Co 79/03/15 App

7903010174 Forwards "Evaluation of System Creek Reactor Core Liquid Level Following Inadvertent Reactor High Pressure Scan on 7/6/78" & Implementation 7903010174 of transient analysis. Adds info on reactor effluent activity level.
FINR0001.1 H Jersey Central Power & Light Co 79/03/17 App

7903010174 "Evaluation of System Creek Reactor Core Liquid Level Following Inadvertent Reactor High Pressure Scan on 7/6/78" prepared by Texas Nuclear Co. Inc.
FINR0001.1 H Jersey Central Power & Light Co 79/03/15 App

7903010210 Forwards response to NRC info request re effect of four pump operation upon transient & accident analysis other than LSCA
SEB001.1 H GPU Service Corp 79/03/17 App

7903020088 Forwards schedule for implementation & resolution of MARK I containment loop-down program. All items done will be completed prior to Jan 1980
FINR0001.1 H Jersey Central Power & Light Co 79/03/17 App

7903030064 Briefs ERI on re status & nature of improvement of radiation protection program
SEB001.1 H Region 1, Philadelphia: Office of the Director 79/03/18 App

7903010345 Forwards "Warding loss of Constant Inventory Transient for System Creek Plant" & info clarifying several aspects of original 79030200 & 79030174 submittals
FINR0001.1 H Jersey Central Power & Light Co 79/03/19 App

7903010467 Forwards Tech Spec Change Request 72, modifying Section 2.1 D & adding Section 2.1 F
FINR0001.1 H Jersey Central Power & Light Co 79/03/19 App

7903010467 Tech Spec Change Request 72, modifying Section 2.1 D to extend applicability of safety limits & adding Section 2.1 F to prevent isolation of at least two recirculation pump loops. Certificate of Euc encl.
FINR0001.1 H Jersey Central Power & Light Co 79/03/19 App

7903040813 Forwards payment for Tech Spec Change Request 72
FINR0001.1 H Jersey Central Power & Light Co 79/03/19 App

7903030382 Responds to NRC 790301V questions re loss-of-inventory transient analysis. Pump coastdown curve encl.
FINR0001.1 H Jersey Central Power & Light Co 79/03/22 App

7903030170 Forwards Tech Spec Change Request 72, Addendum 1, adding limiting safety system Water quality test & Certificate of Euc encl.
FINR0001.1 H Jersey Central Power & Light Co 79/03/23 App

7903030170 Tech Spec Change Request 72, Addendum 1, adding limiting safety system Water quality test & Certificate of Euc encl.
FINR0001.1 H Jersey Central Power & Light Co 79/03/23 App

7903030174 Forwards Tech Spec Change Request 72, Addendum 1, re incorporation of new safety system limiting to Section 2.3 of App A
FINR0001.1 H Jersey Central Power & Light Co 79/03/23 App

7903030175 Forwards Tech Spec Change Request 72, re incorporation of HAPLOR curves & Certificate of Euc & appropriate Class 155 fee
FINR0001.1 H Jersey Central Power & Light Co 79/03/24 App

& Inspection reports, IE Bulletin & correspondence

7903010214 Forwards IE Insp Rpt 80-219/79-04 on 79030200-20 H re non-compliance noted
SEB0001.1 H Region 1, Philadelphia: Reactor Operations Nuclear Support Branch 79/03/20 App

7903010217 IE Insp Rpt 80-219/79-04 on 79030200-20 H re non-compliance noted. Major areas inspected previous insp findings, etc. Office review of periodic reports & LERs & containment spray exchange review
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/03/20 App

7903010110 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/03/23 App

7903010044 Forwards IE Info Notice 79-06, "Interconnection of Contaminated Rys w/Rys Air Rys Used as Source of Breaching Air"
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/03/20 App

7903010044 Forwards IE Info Notice 79-06, "Spill of Rad & Radioactively Contaminated Resin"
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/03/20 App

7903010028 Forwards summary of 79030200, 79030100 & 79030200 re reaction to IE Bulletin 79-06, "Subsided Explosive Gas Mixtures"
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/03/20 App

7903020045 Forwards IE Bulletin 79-06, "Review of Operational Errors & Re-Examination Identified During TMI Incident"
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/04/11 App

7903020049 Responds to IE Bulletin 79-06, "Unidentified Weld Defects in Area 33-212 Type 304 Stainless Steel Pipe Spools W/ig W/ig"
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/04/11 App

7903030337 Forwards IE Bulletin 79-07, "Reactor Pressure Amalgam of Safety-Related Piping" License action required
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/04/14 App

7903040029 Forwards IE Bulletin 79-08, "Review of Operational Errors & Re-Examination Identified During TMI Incident"
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/04/14 App

7903040024 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Reactors Identified During TMI Incident"
SEB0001.1 H Region 1, Philadelphia: Office of the Director 79/04/14 App

DOCKETED ITEMS

26

F Operating license stage documents & correspondence

7905030235 Notification of 790400 meeting w/DC to discuss methodology for predicting safety related valve loads for Mark I
SUT, T Containment Systems Branch 79/03/26 2pg

7905030347 Detailed weld procedures to demonstrate HSB safe-end & elbow replacement
PERKINS, T J Niagara Mohawk Power Corp 79/04/26 4pg

7905030414 Forward responses to Hydrology/Meteorology Branch questions
Q172, 2 & Q173 3-yr 790108 Site Design interfaces between
reductions & validation/qualification are not complete
Accident analysis to be facilitated
HIGGS, S R Niagara Mohawk Power Corp 79/05/01 32pg

7905030495 Forward table re valves made for Spring 1979 refueling
outage Analysis in continuing to determine if further work
are required Final analysis for major structural components
is expected by end of 1979
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/16 4pg

7905030478 Response to NRC 790319 ltr info re radiation levels in
containment enclosure remedial rep
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/16 1p

7905030518 Forward application for amend to License DPH-63 & 64, 000
App
THOMAS, E B LaSalle, Lab. Leiby & MacLean 79/05/29 2pg

--7905030521 Application for amend to License DPH-63 re Tech Spec
changes to safety limits
DIBBS, S P Niagara Mohawk Power Corp 79/05/29 10pg

G Despatch reports, IE Bulletins & correspondence

7905030618 Forward IE ltr Rep High 30-220/79-04 on 790304-09 & 21-22 Mo
noncompliance noted
DITTMER, H H Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 79/05/19 5pg

--7905030740 IE ltr Rep High 30-220/79-04 on 790304-09 & 21-22 Mo
noncompliance noted Major areas inspected radioactive waste
site & radiation protection during refueling
THOMAS, L H Region 1, Philadelphia, Office of the Director
SCHNEIDER, H H Region 1, Philadelphia, Fuel Facility & Materials
Safety Branch 79/05/14 5pg

7905030814 Forward IE Info Notice 79-06: "Stress Analysis of
Safety-Related Piping"
DITTMER, H H Region 1, Philadelphia, Office of the Director
79/05/23 1p

7905030835 Forward IE Info Notice 79-08: "Interconnection of
Contaminated Dry w/Dry Air Dry Used as Source of Breaching
Air"
ORLIER, B H Region 1, Philadelphia, Office of the Director
79/03/28 1p

7905030837 Forward IE Info Notice 79-09: "Spill of Radioactively
Contaminated Water"
ORLIER, B H Region 1, Philadelphia, Office of the Director
79/03/30 1p

7905030847 Forward IE Bulletin 79-06: "Review of Operational Errors &
Dry Misalignments Identified During TMI Incident"
ORLIER, B H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905030821 Response to IE Bulletin 79-07 re lapidated weld defects
Mo piping set supplied by Youngstown Welding & Engineering
Co.
SCHNEIDER, R R Niagara Mohawk Power Corp 79/04/11 1p

7905030838 Forward IE Bulletin 79-07: "Stress Stress Analysis of
Safety-Related Piping" License action required
ORLIER, B H Region 1, Philadelphia, Office of the Director
79/04/16 1p

7905040075 Forward IE Bulletin 79-08: "Review of Operational Errors &
Dry Misalignments Identified During TMI Incident"
ORLIER, B H Region 1, Philadelphia, Office of the Director
79/04/16 1p

7905040023 Forward IE Bulletin 79-08: "Events Relating to Selling
Water Power Reactors Identified During TMI Incident"
License action required
ORLIER, B H Region 1, Philadelphia, Office of the Director
79/04/16 1p

7905030814 Forward IE Bulletin 79-09: "Failures of GE Type AA-2
Circuit Breaker in Safety-Related Dry" License action
required
ORLIER, B H Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905030888 Forward IE Bulletin 79-06: Revision 1: "Review of
Operational Errors & Dry Misalignments Identified During TMI
Incident"
ORLIER, B H Region 1, Philadelphia, Office of the Director
79/04/18 1p

H Periodic operating reports & related correspondence

7905120508 Forward monthly operating rep for Apr 1979
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/16 1p

--7905120511 Monthly operating rep for Apr 1979
PERKINS, T J Niagara Mohawk Power Corp 79/05/06 4pg

I Reportable occurrences, LERs & related correspondence

7905120541 Forward LER 79-005/03L-0
SCHNEIDER, R R Niagara Mohawk Power Corp 79/04/20 1p

--7905120541 LER 79-005/03L-0 on 790405 during periodic Type C leakage
test, valves IV-60-04, IV-201-09, IV-201-10 & IV-201-12 were
found to be in excess of Tech Spec Class Unusual Repair
will be made during outage
JUTRAS, R Niagara Mohawk Power Corp 79/05/01 1p

7905120570 Forward LER 79-006/03L-0
SCHNEIDER, R R Niagara Mohawk Power Corp 79/05/16 1p

--7905120574 LER 79-006/03L-0 on 790405 overfrequency relay on motor
generator set 172 could not be called caused by bad
pulsationmeter w/adjustment. Repairs being made
DUBA, R Niagara Mohawk Power Corp 79/05/10 1p

7905120584 Forward LER-010/03L-0
LEMPER, T E Niagara Mohawk Power Corp 79/05/23 1p

--7905120584 LER 79-010/03L-0 on 790424 during refueling outage,
control system control valve 40 IV-10-10 flange failed test
rate test O-rings replaced on flange
DUBA, R Niagara Mohawk Power Corp 79/05/23 1p

DOCKET 30-220 UNIV OF LOUISIANA RESEARCH REACTOR
J Insurance & indemnity information

7905120584 Forward Amend 8 to Indemnity Agreement E-56, per 10CFR140
changes re increase from \$100 million to \$100 million
effective 790501 Supporting documentation and
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 5pg

DOCKET 30-220 UNIV OF CALIFORNIA RESEARCH REACTOR
J Insurance & indemnity information

7905300052 Forward Amend 13 to Indemnity Agreement E-15, reflecting
change in 10CFR140 increasing primary layer of liability
from \$100 million to \$100 million effective 790501
Supporting documentation and
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 5pg

P Operating license stage documents & correspondence

7905210178 Forward Tech Spec Change & Requests info re SRM possession
limits, amount, accept & accept
KAPLAN, R N California, Univ. of Berkeley 79/05/16 1p

--7905210581 Tech Spec Change & for Triga Mark III
California, Univ. of Berkeley 79/05/14 3pg

DOCKET 30-220 APS CRITICAL EXPERIMENT
J Insurance & indemnity information

7905120584 Forward Amend 9 to Indemnity Agreement E-42, per 10CFR140
changes re increase from \$100 million to \$100 million
effective 790501 Supporting documentation and
BALTIMORE, J Antitrust & Indemnity Group 79/05/01 5pg

DOCKETED ITEMS

26

A Operating license stage documents & correspondence

790320294 Requests renewal of License C2-22 for 25 years. Formal application to be submitted by 7/9/80
JOSD S Reactor Fuel Facility Unit 79/03/04 1p

B Inspection reports: IE Bulletin & correspondence

790320277 Forward IE Insp Rep 90-225/79-02 on 790320-23 No compliance noted
JANUS M S Region 3 Philadelphia: Safeguards Branch 79/03/21 2p

--790320307 IE Insp Rep 90-225/79-02 on 790320-23 No compliance noted. Major areas inspected physical security plan, including protection of DOE assets, control room, age & communications surveillance data, safety critical IFC 9022 7903
LABOR M S, DELIN M S Region 3 Philadelphia: Safeguards Branch 79/03/20 1p

DOCKET 50-227 TRIGA THEORETICAL PROTOTYPE REACTOR

A Insurance & indemnity information

790320302 Forward Amendment 20 to Indemnity Agreement B-9 reflecting change in ICRFTR-40, increasing primary layer of liability from \$140 million to \$180 million, effective 7/9/80
Supporting documentation incl
BALDWIN J Antitrust & Indemnity Group 79/03/01 5pp

DOCKET 50-228 AGRS/STRE PNEUMOPHY & RESEARCH REACTOR

A Insurance & indemnity information

790320309 Forward Amend 17 to Indemnity Agreement B-9 reflecting change in ICRFTR-40, increasing primary layer of liability from \$140 million to \$180 million, effective 7/9/80
Supporting documentation incl
BALDWIN J Antitrust & Indemnity Group 79/03/01 5pp

790320307 Forward accepted Amend 17 to Indemnity Agreement B-9
HENDRICKS R L Reactor Operations 79/03/15 2pp

DOCKET 50-230 MEXICO RESEARCH REACTOR

A Insurance & indemnity information

790320302 Forward Amendment 21 to Indemnity Agreement B-9 reflecting change in ICRFTR-40, increasing primary layer of liability from \$140 million to \$180 million, effective 7/9/80
Supporting documentation incl
BALDWIN J Antitrust & Indemnity Group 79/03/01 5pp

DOCKET 50-234 TUNSTON NUCLEAR ROCKET CRITICAL FACILITY

A Insurance & indemnity information

790320302 Forward Amendment 21 to Indemnity Agreement B-9 reflecting change in ICRFTR-40, increasing primary layer of liability from \$140 million to \$180 million, effective 7/9/80
Supporting documentation incl
BALDWIN J Antitrust & Indemnity Group 79/03/01 5pp

DOCKET 50-235 ACCELERATOR PLASMA FUEL ASSEMBLY

A Insurance & indemnity information

790320302 Forward Amendment 21 to Indemnity Agreement B-9 reflecting change in ICRFTR-40, increasing primary layer of liability from \$140 million to \$180 million, effective 7/9/80
Supporting documentation incl
BALDWIN J Antitrust & Indemnity Group 79/03/01 5pp

DOCKET 50-237 BREXIDEN NUCLEAR FUEL REACTOR UNIT 2

F Security, medical, emergency & fire protection plans

790320304 Forward modified physical security plan, Revision 5 Plus withheld (ref 790320 7901)
JRE & Commonwealth Office Co 79/04/02 1p

790320302 Forward pages of "Implementation of Nuclear Fuel Limited

Area Protection Program." In response to NRC 790320
JANUS M S Reactor Fuel Facility Unit 79/04/02 4pp

C Regulatory correspondence

790320309 Notification properly issued concerning re-shipment waste re-accepted. Contention was admitted into Data Power Co. processing, microanalysis aspects of revised Contention 11 presented by State of
SOSD HRS J Branch 2 79/03/06 2pp

J Insurance & indemnity information

790810243 Memorandum OM to NRCU Pelling 79-02
SOSD S Nuclear Energy Liability Insurance Association 79/03/27 1p

790320307 Confirms increased liability limit to \$124,000,000 for policies 79-1-20, 43, 66, 73, 103, 111, 105, 146, 150, Jan 1st, 170, 173, 176, 178, 179, 180, 182, 183, 184, 187, 188, 189, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000, 1001, 1002, 1003, 1004, 1005, 1006, 1007, 1008, 1009, 1010, 1011, 1012, 1013, 1014, 1015, 1016, 1017, 1018, 1019, 1020, 1021, 1022, 1023, 1024, 1025, 1026, 1027, 1028, 1029, 1030, 1031, 1032, 1033, 1034, 1035, 1036, 1037, 1038, 1039, 1040, 1041, 1042, 1043, 1044, 1045, 1046, 1047, 1048, 1049, 1050, 1051, 1052, 1053, 1054, 1055, 1056, 1057, 1058, 1059, 1060, 1061, 1062, 1063, 1064, 1065, 1066, 1067, 1068, 1069, 1070, 1071, 1072, 1073, 1074, 1075, 1076, 1077, 1078, 1079, 1080, 1081, 1082, 1083, 1084, 1085, 1086, 1087, 1088, 1089, 1090, 1091, 1092, 1093, 1094, 1095, 1096, 1097, 1098, 1099, 1100, 1101, 1102, 1103, 1104, 1105, 1106, 1107, 1108, 1109, 1110, 1111, 1112, 1113, 1114, 1115, 1116, 1117, 1118, 1119, 1120, 1121, 1122, 1123, 1124, 1125, 1126, 1127, 1128, 1129, 1130, 1131, 1132, 1133, 1134, 1135, 1136, 1137, 1138, 1139, 1140, 1141, 1142, 1143, 1144, 1145, 1146, 1147, 1148, 1149, 1150, 1151, 1152, 1153, 1154, 1155, 1156, 1157, 1158, 1159, 1160, 1161, 1162, 1163, 1164, 1165, 1166, 1167, 1168, 1169, 1170, 1171, 1172, 1173, 1174, 1175, 1176, 1177, 1178, 1179, 1180, 1181, 1182, 1183, 1184, 1185, 1186, 1187, 1188, 1189, 1190, 1191, 1192, 1193, 1194, 1195, 1196, 1197, 1198, 1199, 1200, 1201, 1202, 1203, 1204, 1205, 1206, 1207, 1208, 1209, 1210, 1211, 1212, 1213, 1214, 1215, 1216, 1217, 1218, 1219, 1220, 1221, 1222, 1223, 1224, 1225, 1226, 1227, 1228, 1229, 1230, 1231, 1232, 1233, 1234, 1235, 1236, 1237, 1238, 1239, 1240, 1241, 1242, 1243, 1244, 1245, 1246, 1247, 1248, 1249, 1250, 1251, 1252, 1253, 1254, 1255, 1256, 1257, 1258, 1259, 1260, 1261, 1262, 1263, 1264, 1265, 1266, 1267, 1268, 1269, 1270, 1271, 1272, 1273, 1274, 1275, 1276, 1277, 1278, 1279, 1280, 1281, 1282, 1283, 1284, 1285, 1286, 1287, 1288, 1289, 1290, 1291, 1292, 1293, 1294, 1295, 1296, 1297, 1298, 1299, 1300, 1301, 1302, 1303, 1304, 1305, 1306, 1307, 1308, 1309, 1310, 1311, 1312, 1313, 1314, 1315, 1316, 1317, 1318, 1319, 1320, 1321, 1322, 1323, 1324, 1325, 1326, 1327, 1328, 1329, 1330, 1331, 1332, 1333, 1334, 1335, 1336, 1337, 1338, 1339, 1340, 1341, 1342, 1343, 1344, 1345, 1346, 1347, 1348, 1349, 1350, 1351, 1352, 1353, 1354, 1355, 1356, 1357, 1358, 1359, 1360, 1361, 1362, 1363, 1364, 1365, 1366, 1367, 1368, 1369, 1370, 1371, 1372, 1373, 1374, 1375, 1376, 1377, 1378, 1379, 1380, 1381, 1382, 1383, 1384, 1385, 1386, 1387, 1388, 1389, 1390, 1391, 1392, 1393, 1394, 1395, 1396, 1397, 1398, 1399, 1400, 1401, 1402, 1403, 1404, 1405, 1406, 1407, 1408, 1409, 1410, 1411, 1412, 1413, 1414, 1415, 1416, 1417, 1418, 1419, 1420, 1421, 1422, 1423, 1424, 1425, 1426, 1427, 1428, 1429, 1430, 1431, 1432, 1433, 1434, 1435, 1436, 1437, 1438, 1439, 1440, 1441, 1442, 1443, 1444, 1445, 1446, 1447, 1448, 1449, 1450, 1451, 1452, 1453, 1454, 1455, 1456, 1457, 1458, 1459, 1460, 1461, 1462, 1463, 1464, 1465, 1466, 1467, 1468, 1469, 1470, 1471, 1472, 1473, 1474, 1475, 1476, 1477, 1478, 1479, 1480, 1481, 1482, 1483, 1484, 1485, 1486, 1487, 1488, 1489, 1490, 1491, 1492, 1493, 1494, 1495, 1496, 1497, 1498, 1499, 1500, 1501, 1502, 1503, 1504, 1505, 1506, 1507, 1508, 1509, 1510, 1511, 1512, 1513, 1514, 1515, 1516, 1517, 1518, 1519, 1520, 1521, 1522, 1523, 1524, 1525, 1526, 1527, 1528, 1529, 1530, 1531, 1532, 1533, 1534, 1535, 1536, 1537, 1538, 1539, 1540, 1541, 1542, 1543, 1544, 1545, 1546, 1547, 1548, 1549, 1550, 1551, 1552, 1553, 1554, 1555, 1556, 1557, 1558, 1559, 1560, 1561, 1562, 1563, 1564, 1565, 1566, 1567, 1568, 1569, 1570, 1571, 1572, 1573, 1574, 1575, 1576, 1577, 1578, 1579, 1580, 1581, 1582, 1583, 1584, 1585, 1586, 1587, 1588, 1589, 1590, 1591, 1592, 1593, 1594, 1595, 1596, 1597, 1598, 1599, 1600, 1601, 1602, 1603, 1604, 1605, 1606, 1607, 1608, 1609, 1610, 1611, 1612, 1613, 1614, 1615, 1616, 1617, 1618, 1619, 1620, 1621, 1622, 1623, 1624, 1625, 1626, 1627, 1628, 1629, 1630, 1631, 1632, 1633, 1634, 1635, 1636, 1637, 1638, 1639, 1640, 1641, 1642, 1643, 1644, 1645, 1646, 1647, 1648, 1649, 1650, 1651, 1652, 1653, 1654, 1655, 1656, 1657, 1658, 1659, 1660, 1661, 1662, 1663, 1664, 1665, 1666, 1667, 1668, 1669, 1670, 1671, 1672, 1673, 1674, 1675, 1676, 1677, 1678, 1679, 1680, 1681, 1682, 1683, 1684, 1685, 1686, 1687, 1688, 1689, 1690, 1691, 1692, 1693, 1694, 1695, 1696, 1697, 1698, 1699, 1700, 1701, 1702, 1703, 1704, 1705, 1706, 1707, 1708, 1709, 1710, 1711, 1712, 1713, 1714, 1715, 1716, 1717, 1718, 1719, 1720, 1721, 1722, 1723, 1724, 1725, 1726, 1727, 1728, 1729, 1730, 1731, 1732, 1733, 1734, 1735, 1736, 1737, 1738, 1739, 1740, 1741, 1742, 1743, 1744, 1745, 1746, 1747, 1748, 1749, 1750, 1751, 1752, 1753, 1754, 1755, 1756, 1757, 1758, 1759, 1760, 1761, 1762, 1763, 1764, 1765, 1766, 1767, 1768, 1769, 1770, 1771, 1772, 1773, 1774, 1775, 1776, 1777, 1778, 1779, 1780, 1781, 1782, 1783, 1784, 1785, 1786, 1787, 1788, 1789, 1790, 1791, 1792, 1793, 1794, 1795, 1796, 1797, 1798, 1799, 1800, 1801, 1802, 1803, 1804, 1805, 1806, 1807, 1808, 1809, 1810, 1811, 1812, 1813, 1814, 1815, 1816, 1817, 1818, 1819, 1820, 1821, 1822, 1823, 1824, 1825, 1826, 1827, 1828, 1829, 1830, 1831, 1832, 1833, 1834, 1835, 1836, 1837, 1838, 1839, 1840, 1841, 1842, 1843, 1844, 1845, 1846, 1847, 1848, 1849, 1850, 1851, 1852, 1853, 1854, 1855, 1856, 1857, 1858, 1859, 1860, 1861, 1862, 1863, 1864, 1865, 1866, 1867, 1868, 1869, 1870, 1871, 1872, 1873, 1874, 1875, 1876, 1877, 1878, 1879, 1880, 1881, 1882, 1883, 1884, 1885, 1886, 1887, 1888, 1889, 1890, 1891, 1892, 1893, 1894, 1895, 1896, 1897, 1898, 1899, 1900, 1901, 1902, 1903, 1904, 1905, 1906, 1907, 1908, 1909, 1910, 1911, 1912, 1913, 1914, 1915, 1916, 1917, 1918, 1919, 1920, 1921, 1922, 1923, 1924, 1925, 1926, 1927, 1928, 1929, 1930, 1931, 1932, 1933, 1934, 1935, 1936, 1937, 1938, 1939, 1940, 1941, 1942, 1943, 1944,

DOCKETED ITEMS

7905000257 Forwarded LER 79-001/031-1
STEPHENSON, S. B. Commonwealth Edison Co 79/05/00 1p

—7905000258 LER 79-001/031-1 on 790505 during steady state operation,
torque level exceeded space caused by operator oversight
torque torque under caused by operator oversight
Surveillance being revised
MISHT, R. Commonwealth Edison Co 79/05/00 1p

7905000261 Forwarded LER 79-001/031-1
STEPHENSON, S. B. Commonwealth Edison Co 79/05/04 1p

7905000263 LER 79-001/031-1 on 790413 measured leakage for personnel
air lock was 94.43 the cable f/w leakage identified through
outer door handle. Shaft parking was replaced & air lock
retested
PARCELL, R. Commonwealth Edison Co 79/05/08 1p

7905000264 Forwarded LER 79-001/031-1
STEPHENSON, S. B. Commonwealth Edison Co 79/05/08 1p

—7905000265 LER 79-001/031-1 on 790415 SA LCI pump was manually stopped
but water not restored properly caused by trip on overcurrent
relay motor bridge & apparent satisfactory pump returned
to use
CDRH, R. Commonwealth Edison Co 79/05/14 1p

7905000267 Forwarded LER 79-001/031-1
STEPHENSON, S. B. Commonwealth Edison Co 79/05/08 1p

—7905000268 LER 79-001/031-1 on 790424 while in shutdown for refueling,
M2 diesel generator failed to start caused by air
lines to compressor motor being reversed. Airline motor was
replaced & air lines properly tested
CHIN, J. Commonwealth Edison Co 79/05/04 1p

7905000269 Forwarded LER 79-001/031-1
STEPHENSON, S. B. Commonwealth Edison Co 79/05/08 1p

—7905000270 LER 79-001/031-1 on 790428 breaker trip logic testing
discovered motor generator was not started breaker would not
trip. Cause determined to be small piece of debris jamming
tripping mechanism. Breaker closed
DUBOIS, J. Commonwealth Edison Co 79/05/04 1p

7905000271 Forwarded LER 79-001/031-1
STEPHENSON, S. B. Commonwealth Edison Co 79/05/04 1p

—7905000272 LER 79-001/031-1 on 790425 during monthly surveillance,
switches 500-T, PE 500K & PE 500B tripped at 510 psi caused
by instrument drift during prolonged shutdown period
Bulcher, R. Commonwealth Edison Co 79/05/04 1p

7905000273 Forwarded LER 79-001/031-1
STEPHENSON, S. B. Commonwealth Edison Co 79/05/08 1p

—7905000274 LER 79-001/031-1 on 790428 during periodic
containment isolation valve surveillance, TIC TIP machine
failed to retract caused by ball valve limit switch which
did not deenergize machine control circuiting
PARCELL, R. Commonwealth Edison Co 79/05/08 1p

DOCKET 50-240 HIGH TEMP GAS SEELED CRITICAL EXPERIMENT

DOCKET 50-243 GREENHILL STATE UNIV RESEARCH REACTOR
Operating license stage documents & correspondence

7905000284 Forwarded proposed changes to Tech Specs for TRIGA reactor
& justification for new design to upgrade controls
electronics & change reactivity pulling limit during
normal change would require about two weeks
WONG, C. H. MIT/UC C. V. Wright State Univ 79/04/16 14pp

DOCKET 33-244 ROBERT SMITH DENAM NUCLEAR PLANT, UNIT 1
Security, medical, emergency & fire protection plans

7905000285 Responds to request for add info re 790514 fire protection
SER discusses piping & dust penetrations; control joint,
detector testing & electrical cable insulation
WHITE, L. D. Rochester Gas & Electric Corp 79/04/30 3pp

7905000286 Advisory of steps undertaken re items 2 & 9 & 11
of fire protection RCR, concerning adequacy of fire brigade
size & delivery from installation
WHITE, L. D. Rochester Gas & Electric Corp 79/05/05 1p

I Financial information

7905000287 Forwarded "Annual Financial Report 1979"
THOMAS, E. B. LeBoeuf, Lamb, Leiby & MacKay 79/05/02 1p

—7905000288 "Annual Financial Report 1978"
Rochester Gas & Electric Corp 79/03/10 32pp

J Insurance & indemnity information

7905000289 Confirms increased liability limit to \$24,000,000 for
policy re 79-05-03, 79-05-04, 79-05-05, 79-05-06, 79-05-07, 79-05-08, 79-05-09, 79-05-10, 79-05-11, 79-05-12, 79-05-13, 79-05-14, 79-05-15, 79-05-16, 79-05-17, 79-05-18, 79-05-19, 79-05-20, 79-05-21, 79-05-22, 79-05-23, 79-05-24, 79-05-25, 79-05-26, 79-05-27, 79-05-28, 79-05-29, 79-05-30, 79-05-31, 79-05-32, 79-05-33, 79-05-34, 79-05-35, 79-05-36, 79-05-37, 79-05-38, 79-05-39, 79-05-40, 79-05-41, 79-05-42, 79-05-43, 79-05-44, 79-05-45, 79-05-46, 79-05-47, 79-05-48, 79-05-49, 79-05-50, 79-05-51, 79-05-52, 79-05-53, 79-05-54, 79-05-55, 79-05-56, 79-05-57, 79-05-58, 79-05-59, 79-05-60, 79-05-61, 79-05-62, 79-05-63, 79-05-64, 79-05-65, 79-05-66, 79-05-67, 79-05-68, 79-05-69, 79-05-70, 79-05-71, 79-05-72, 79-05-73, 79-05-74, 79-05-75, 79-05-76, 79-05-77, 79-05-78, 79-05-79, 79-05-80, 79-05-81, 79-05-82, 79-05-83, 79-05-84, 79-05-85, 79-05-86, 79-05-87, 79-05-88, 79-05-89, 79-05-90, 79-05-91, 79-05-92, 79-05-93, 79-05-94, 79-05-95, 79-05-96, 79-05-97, 79-05-98, 79-05-99, 79-06-00, 79-06-01, 79-06-02, 79-06-03, 79-06-04, 79-06-05, 79-06-06, 79-06-07, 79-06-08, 79-06-09, 79-06-10, 79-06-11, 79-06-12, 79-06-13, 79-06-14, 79-06-15, 79-06-16, 79-06-17, 79-06-18, 79-06-19, 79-06-20, 79-06-21, 79-06-22, 79-06-23, 79-06-24, 79-06-25, 79-06-26, 79-06-27, 79-06-28, 79-06-29, 79-06-30, 79-06-31, 79-06-32, 79-06-33, 79-06-34, 79-06-35, 79-06-36, 79-06-37, 79-06-38, 79-06-39, 79-06-40, 79-06-41, 79-06-42, 79-06-43, 79-06-44, 79-06-45, 79-06-46, 79-06-47, 79-06-48, 79-06-49, 79-06-50, 79-06-51, 79-06-52, 79-06-53, 79-06-54, 79-06-55, 79-06-56, 79-06-57, 79-06-58, 79-06-59, 79-06-60, 79-06-61, 79-06-62, 79-06-63, 79-06-64, 79-06-65, 79-06-66, 79-06-67, 79-06-68, 79-06-69, 79-06-70, 79-06-71, 79-06-72, 79-06-73, 79-06-74, 79-06-75, 79-06-76, 79-06-77, 79-06-78, 79-06-79, 79-06-80, 79-06-81, 79-06-82, 79-06-83, 79-06-84, 79-06-85, 79-06-86, 79-06-87, 79-06-88, 79-06-89, 79-06-90, 79-06-91, 79-06-92, 79-06-93, 79-06-94, 79-06-95, 79-06-96, 79-06-97, 79-06-98, 79-06-99, 79-07-00, 79-07-01, 79-07-02, 79-07-03, 79-07-04, 79-07-05, 79-07-06, 79-07-07, 79-07-08, 79-07-09, 79-07-10, 79-07-11, 79-07-12, 79-07-13, 79-07-14, 79-07-15, 79-07-16, 79-07-17, 79-07-18, 79-07-19, 79-07-20, 79-07-21, 79-07-22, 79-07-23, 79-07-24, 79-07-25, 79-07-26, 79-07-27, 79-07-28, 79-07-29, 79-07-30, 79-07-31, 79-07-32, 79-07-33, 79-07-34, 79-07-35, 79-07-36, 79-07-37, 79-07-38, 79-07-39, 79-07-40, 79-07-41, 79-07-42, 79-07-43, 79-07-44, 79-07-45, 79-07-46, 79-07-47, 79-07-48, 79-07-49, 79-07-50, 79-07-51, 79-07-52, 79-07-53, 79-07-54, 79-07-55, 79-07-56, 79-07-57, 79-07-58, 79-07-59, 79-07-60, 79-07-61, 79-07-62, 79-07-63, 79-07-64, 79-07-65, 79-07-66, 79-07-67, 79-07-68, 79-07-69, 79-07-70, 79-07-71, 79-07-72, 79-07-73, 79-07-74, 79-07-75, 79-07-76, 79-07-77, 79-07-78, 79-07-79, 79-07-80, 79-07-81, 79-07-82, 79-07-83, 79-07-84, 79-07-85, 79-07-86, 79-07-87, 79-07-88, 79-07-89, 79-07-90, 79-07-91, 79-07-92, 79-07-93, 79-07-94, 79-07-95, 79-07-96, 79-07-97, 79-07-98, 79-07-99, 79-08-00, 79-08-01, 79-08-02, 79-08-03, 79-08-04, 79-08-05, 79-08-06, 79-08-07, 79-08-08, 79-08-09, 79-08-10, 79-08-11, 79-08-12, 79-08-13, 79-08-14, 79-08-15, 79-08-16, 79-08-17, 79-08-18, 79-08-19, 79-08-20, 79-08-21, 79-08-22, 79-08-23, 79-08-24, 79-08-25, 79-08-26, 79-08-27, 79-08-28, 79-08-29, 79-08-30, 79-08-31, 79-08-32, 79-08-33, 79-08-34, 79-08-35, 79-08-36, 79-08-37, 79-08-38, 79-08-39, 79-08-40, 79-08-41, 79-08-42, 79-08-43, 79-08-44, 79-08-45, 79-08-46, 79-08-47, 79-08-48, 79-08-49, 79-08-50, 79-08-51, 79-08-52, 79-08-53, 79-08-54, 79-08-55, 79-08-56, 79-08-57, 79-08-58, 79-08-59, 79-08-60, 79-08-61, 79-08-62, 79-08-63, 79-08-64, 79-08-65, 79-08-66, 79-08-67, 79-08-68, 79-08-69, 79-08-70, 79-08-71, 79-08-72, 79-08-73, 79-08-74, 79-08-75, 79-08-76, 79-08-77, 79-08-78, 79-08-79, 79-08-80, 79-08-81, 79-08-82, 79-08-83, 79-08-84, 79-08-85, 79-08-86, 79-08-87, 79-08-88, 79-08-89, 79-08-90, 79-08-91, 79-08-92, 79-08-93, 79-08-94, 79-08-95, 79-08-96, 79-08-97, 79-08-98, 79-08-99, 79-09-00, 79-09-01, 79-09-02, 79-09-03, 79-09-04, 79-09-05, 79-09-06, 79-09-07, 79-09-08, 79-09-09, 79-09-10, 79-09-11, 79-09-12, 79-09-13, 79-09-14, 79-09-15, 79-09-16, 79-09-17, 79-09-18, 79-09-19, 79-09-20, 79-09-21, 79-09-22, 79-09-23, 79-09-24, 79-09-25, 79-09-26, 79-09-27, 79-09-28, 79-09-29, 79-09-30, 79-09-31, 79-09-32, 79-09-33, 79-09-34, 79-09-35, 79-09-36, 79-09-37, 79-09-38, 79-09-39, 79-09-40, 79-09-41, 79-09-42, 79-09-43, 79-09-44, 79-09-45, 79-09-46, 79-09-47, 79-09-48, 79-09-49, 79-09-50, 79-09-51, 79-09-52, 79-09-53, 79-09-54, 79-09-55, 79-09-56, 79-09-57, 79-09-58, 79-09-59, 79-09-60, 79-09-61, 79-09-62, 79-09-63, 79-09-64, 79-09-65, 79-09-66, 79-09-67, 79-09-68, 79-09-69, 79-09-70, 79-09-71, 79-09-72, 79-09-73, 79-09-74, 79-09-75, 79-09-76, 79-09-77, 79-09-78, 79-09-79, 79-09-80, 79-09-81, 79-09-82, 79-09-83, 79-09-84, 79-09-85, 79-09-86, 79-09-87, 79-09-88, 79-09-89, 79-09-90, 79-09-91, 79-09-92, 79-09-93, 79-09-94, 79-09-95, 79-09-96, 79-09-97, 79-09-98, 79-09-99, 79-10-00, 79-10-01, 79-10-02, 79-10-03, 79-10-04, 79-10-05, 79-10-06, 79-10-07, 79-10-08, 79-10-09, 79-10-10, 79-10-11, 79-10-12, 79-10-13, 79-10-14, 79-10-15, 79-10-16, 79-10-17, 79-10-18, 79-10-19, 79-10-20, 79-10-21, 79-10-22, 79-10-23, 79-10-24, 79-10-25, 79-10-26, 79-10-27, 79-10-28, 79-10-29, 79-10-30, 79-10-31, 79-10-32, 79-10-33, 79-10-34, 79-10-35, 79-10-36, 79-10-37, 79-10-38, 79-10-39, 79-10-40, 79-10-41, 79-10-42, 79-10-43, 79-10-44, 79-10-45, 79-10-46, 79-10-47, 79-10-48, 79-10-49, 79-10-50, 79-10-51, 79-10-52, 79-10-53, 79-10-54, 79-10-55, 79-10-56, 79-10-57, 79-10-58, 79-10-59, 79-10-60, 79-10-61, 79-10-62, 79-10-63, 79-10-64, 79-10-65, 79-10-66, 79-10-67, 79-10-68, 79-10-69, 79-10-70, 79-10-71, 79-10-72, 79-10-73, 79-10-74, 79-10-75, 79-10-76, 79-10-77, 79-10-78, 79-10-79, 79-10-80, 79-10-81, 79-10-82, 79-10-83, 79-10-84, 79-10-85, 79-10-86, 79-10-87, 79-10-88, 79-10-89, 79-10-90, 79-10-91, 79-10-92, 79-10-93, 79-10-94, 79-10-95, 79-10-96, 79-10-97, 79-10-98, 79-10-99, 79-11-00, 79-11-01, 79-11-02, 79-11-03, 79-11-04, 79-11-05, 79-11-06, 79-11-07, 79-11-08, 79-11-09, 79-11-10, 79-11-11, 79-11-12, 79-11-13, 79-11-14, 79-11-15, 79-11-16, 79-11-17, 79-11-18, 79-11-19, 79-11-20, 79-11-21, 79-11-22, 79-11-23, 79-11-24, 79-11-25, 79-11-26, 79-11-27, 79-11-28, 79-11-29, 79-11-30, 79-11-31, 79-11-32, 79-11-33, 79-11-34, 79-11-35, 79-11-36, 79-11-37, 79-11-38, 79-11-39, 79-11-40, 79-11-41, 79-11-42, 79-11-43, 79-11-44, 79-11-45, 79-11-46, 79-11-47, 79-11-48, 79-11-49, 79-11-50, 79-11-51, 79-11-52, 79-11-53, 79-11-54, 79-11-55, 79-11-56, 79-11-57, 79-11-58, 79-11-59, 79-11-60, 79-11-61, 79-11-62, 79-11-63, 79-11-64, 79-11-65, 79-11-66, 79-11-67, 79-11-68, 79-11-69, 79-11-70, 79-11-71, 79-11-72, 79-11-73, 79-11-74, 79-11-75, 79-11-76, 79-11-77, 79-11-78, 79-11-79, 79-11-80, 79-11-81, 79-11-82, 79-11-83, 79-11-84, 79-11-85, 79-11-86, 79-11-87, 79-11-88, 79-11-89, 79-11-90, 79-11-91, 79-11-92, 79-11-93, 79-11-94, 79-11-95, 79-11-96, 79-11-97, 79-11-98, 79-11-99, 79-12-00, 79-12-01, 79-12-02, 79-12-03, 79-12-04, 79-12-05, 79-12-06, 79-12-07, 79-12-08, 79-12-09, 79-12-10, 79-12-11, 79-12-12, 79-12-13, 79-12-14, 79-12-15, 79-12-16, 79-12-17, 79-12-18, 79-12-19, 79-12-20, 79-12-21, 79-12-22, 79-12-23, 79-12-24, 79-12-25, 79-12-26, 79-12-27, 79-12-28, 79-12-29, 79-12-30, 79-12-31, 79-12-32, 79-12-33, 79-12-34, 79-12-35, 79-12-36, 79-12-37, 79-12-38, 79-12-39, 79-12-40, 79-12-41, 79-12-42, 79-12-43, 79-12-44, 79-12-45, 79-12-46, 79-12-47, 79-12-48, 79-12-49, 79-12-50, 79-12-51, 79-12-52, 79-12-53, 79-12-54, 79-12-55, 79-12-56, 79-12-57, 79-12-58, 79-12-59, 79-12-60, 79-12-61, 79-12-62, 79-12-63, 79-12-64, 79-12-65, 79-12-66, 79-12-67, 79-12-68, 79-12-69, 79-12-70, 79-12-71, 79-12-72, 79-12-73, 79-12-74, 79-12-75, 79-12-76, 79-12-77, 79-12-78, 79-12-79, 79-12-80, 79-12-81, 79-12-82, 79-12-83, 79-12-84, 79-12-85, 79-12-86, 79-12-87, 79-12-88, 79-12-89, 79-12-90, 79-12-91, 79-12-92, 79-12-93, 79-12-94, 79-12-95, 79-12-96, 79-12-97, 79-12-98, 79-12-99, 79-13-00, 79-13-01, 79-13-02, 79-13-03, 79-13-04, 79-13-05, 79-13-06, 79-13-07, 79-13-08, 79-13-09, 79-13-10, 79-13-11, 79-13-12, 79-13-13, 79-13-14, 79-13-15, 79-13-16, 79-13-17, 79-13-18, 79-13-19, 79-13-20, 79-13-21, 79-13-22, 79-13-23, 79-13-24, 79-13-25, 79-13-26, 79-13-27, 79-13-28, 79-13-29, 79-13-30, 79-13-31, 79-13-32, 79-13-33, 79-13-34, 79-13-35, 79-13-36, 79-13-37, 79-13-38, 79-13-39, 79-13-40, 79-13-41, 79-13-42, 79-13-43, 79-13-44, 79-13-45, 79-13-46, 79-13-47, 79-13-48, 79-13-49, 79-13-50, 79-13-51, 79-13-52, 79-13-53, 79-13-54, 79-13-55, 79-13-56, 79-13-57, 79-13-58, 79-13-59, 79-13-60, 79-13-61, 79-13-62, 79-13-63, 79-13-64, 79-13-65, 79-13-66, 79-13-67, 79-13-68, 79-13-69, 79-13-70, 79-13-71, 79-13-72, 79-13-73, 79-13-74, 79-13-75, 79-13-76, 79-13-77, 79-13-78, 79-13-79, 79-13-80, 79-13-81, 79-13-82, 79-13-83, 79-13-84, 79-13-85, 79-13-86, 79-13-87, 79-13-88, 79-13-89, 79-13-90, 79-13-91, 79-13-92, 79-13-93, 79-13-94, 79-13-95, 79-13-96, 79-13-97, 79-13-98, 79-13-99, 79-14-00, 79-14-01, 79-14-02, 79-14-03, 79-14-04, 79-14-05, 79-14-06, 79-14-07, 79-14-08, 79-14-09, 79-14-10, 79-14-11, 79-14-12, 79-14-13, 79-14-14, 79-14-15, 79-14-16, 79-14-17, 79-14-18, 79-14-19, 79-14-20, 79-14-21, 79-14-22, 79-14-23, 79-14-24, 79-14-25, 79-14-26, 79-14-27, 79-14-28, 79-14-29, 79-14-30, 79-14-31, 79-14-32, 79-14-33, 79-14-34, 79-14-35, 79-14-36, 79-14-37, 79-14-38, 79-14-39, 79-14-40, 79-14-41, 79-14-42, 79-14-43, 79-14-44, 79-14-45, 79-14-46, 79-14-47, 79-14-48, 79-14-49, 79-14-50, 79-14-51, 79-14-52, 79-14-53, 79-14-54, 79-14-55, 79-14-56, 79-14-57, 79-14-58, 79-14-59, 79-14-60, 79-14-61, 79-14-62, 79-14-63, 79-14-64, 79-14-65, 79-14-66, 79-14-67, 79-14-68, 79-14-69, 79-14-70, 79-14-71, 79-14-72, 79-14-73, 79-14-74, 79-14-75, 79-14-76, 79-14-77, 79-14-78, 79-14-79, 79-14-80, 79-14-81, 79-14-82, 79-14-83, 79-14-84, 79-14-85, 79-14-86, 79-14-87, 79-14-88, 79-14-89, 79-14-90, 79-14-91, 79-14-92, 79-14-93, 7

DOCKETED ITEMS

29

7903040000 Notice of issuance & availability of Amend 25 to License
 390-1B
 ZIERMAN, P. L. Operating Reactors Branch 2 79/04/20 App

7903070000 Response to 790120 ltr re analysis of boron dilution
 mechanisms. Summaries results of residual heat removal sys
 No single failure would result in boron dilution
 MIETZ, L. D. Rochester Gas & Electric Corp 79/04/30 App

7903010148 Provides add'l seismic info requested by NRC seismic review
 info. Forwarded info on plant structural design except for
 details of containment & internal structures. Dynamic model
 of auxiliary bldg & 25 overlaid drawings encl
 MIETZ, L. D. Rochester Gas & Electric Corp 79/03/07 lpp

7903030020 Seismic revised Attachment A, B & C to 790302 submittal
 amending Tech Specs for chemical filter testing & indine
 removal equipment operability
 MILLIGAN, R. C. Rochester Gas & Electric Corp 79/03/08 2pp

7903020037 Comments on NRC 790318 ltr deleting topics for further
 review from systematic evaluation program. Lists other topics
 to be deleted which are not applicable or have been
 resolved
 MIETZ, L. D. Rochester Gas & Electric Corp 79/03/16 App

7903020001 Response to request for add'l info re pressure shielding
 steel diaphragm. Summits info summarizing calculated pressure
 transients which result from breaks in 32-inch feedwater
 line or 12-inch steam line.
 MIETZ, L. D. Rochester Gas & Electric Corp 79/03/17 30pp

7903030044 Forwarded supplemental info to 790307 ltr re systematic
 evaluation program seismic review. Overlaid drawings
 available in Central Files
 MIETZ, L. D. Rochester Gas & Electric Corp 79/03/22 A0pp

B Inspection reports, IE Bulletin & correspondence

7903010148 Forwarded IE Info Notice 79-06, "Stress Analysis of
 Safety-Related Piping"
 ORRIS, B. H. Region 1, Philadelphia, Office of the Director
 79/03/22 1p

7903040004 Forwarded IE, Insp Rpt 90-244/79-05 on 790305-0003 No
 noncompliance noted
 ORRIS, B. H. Region 1, Philadelphia, Fuel Facility & Materials
 Safety Branch 79/03/23 2pp

7903040006 IE Insp Rpt 90-244/79-03 on 790303-08 No noncompliance
 noted. Major areas inspected: radiation protection program
 during routine refueling operations; procedures for planning &
 preparation; training; exposure control & posting
 YOUNG, D. P., CHODURA, H. M. Region 1, Philadelphia, Office of the
 Director 79/03/22 2pp

7903010073 Forwarded IE Info Notice 79-08, "Interconnection of
 Contaminated Dry Air by Air Dry Used as Source of Breathing
 Air"
 ORRIS, B. H. Region 1, Philadelphia, Office of the Director
 79/03/28 1p

7903010024 Forwarded IE Info Notice 79-09, "Spill of Radioactively
 Contaminated Resin"
 ORRIS, B. H. Region 1, Philadelphia, Office of the Director
 79/03/30 1p

7903020081 Response to IE Bulletin 79-05, "Longitudinal Weld Defects in
 ANNE RA-312 Type 304 Stainless Steel Pipe Spools W/sg by
 Youngtown Welding & Engineering Co." Class II stainless
 steel piping was inspected to ASTM A 312, IV & IV, 100% ICI
 MIETZ, L. D. Rochester Gas & Electric Corp 79/04/04 1p

7903040046 Forwarded IE Insp Rpt 90-244/79-04 on 790303-0002 No
 noncompliance noted.
 BRUNNER, C. J. Region 1, Philadelphia, Office of the Director
 79/04/10, 2pp

7903020170 IE Insp Rpt 90-244/79-04 on 790303-0002 No noncompliance
 noted. Major areas inspected: facility logs & record-plant
 safety; refueling procedures; maint activities & plant team
 BECKMAN, D. A., KALMAG, G. Region 1, Philadelphia, Office of the
 Director 790303-0002 No noncompliance noted. Major areas inspected:
 Operators Nuclear Support Branch 79/04/10 10pp

7903020104 Forwarded IE Bulletin 79-06, "Review of Operational Errors &
 Misalignments Identified During TMI Incident - Licensee
 action required."
 ORRIS, B. H. Region 1, Philadelphia, Office of the Director
 79/04/11 1p

7903020018 Forwarded IE Bulletin 79-07, "Seismic Stress Analysis of
 Safety-Related Piping - Licensee action required."
 ORRIS, B. H. Region 1, Philadelphia, Office of the Director
 79/04/14 1p

7903040109 Forwarded IE Bulletin 79-08, "Review of Operational Errors &
 Misalignments Identified During TMI Incident"
 ORRIS, B. H. Region 1, Philadelphia, Office of the Director
 79/04/14 1p

7903030108 Forwarded IE Bulletin 79-09, "Failures of GE Type AA-2
 Circuit Breaker in Safety-Related Sys - Licensee action
 required."
 ORRIS, B. H. Region 1, Philadelphia, Office of the Director
 79/04/17 1p

7903030035 Forwarded IE Bulletin 79-04A, Revision 1, "Review of
 Operational Errors & Sys Misalignments Identified During TMI
 Incident"
 ORRIS, B. H. Region 1, Philadelphia, Office of the Director
 79/04/18 1p

7903010497 Comments on IE Bulletin 79-04A re Meetinghouse FMR
 facilities implementation of Distable drip would create
 situation where safety injection activation could be
 susceptible to single bus perturbations
 COBURN, E. H. New York, State of 79/04/22 2pp

B Periodic operating reports & related correspondence

7903020023 Forwarded monthly operating rpt for Apr 1979
 ORRIS, B. H. Rochester Gas & Electric Corp 79/05/10 1p

7903020027 Monthly operating rpt for Apr 1979
 ORRIS, B. H. Rochester Gas & Electric Corp 79/05/09 1pp

B Reportable occurrences, LCRs & related correspondence

7903040101 Forwarded LER 79-007/00L-0
 MIETZ, L. D. Rochester Gas & Electric Corp 79/04/03 1p

7903040147 LER 79-007/00L-0 on 790402 surveillance requirement for
 nuclear intermediate range channel test within seven days
 was not performed for two training exercises caused by
 unclear training procedures
 PEGIN, C. H. Rochester Gas & Electric Corp 79/04/20 1p

7903040188 Forwarded LERs 79-009/01T-0 & 79-010/01T-0
 MIETZ, L. D. Rochester Gas & Electric Corp 79/04/20 1p

7903040187 LER 79-009/01T-0 on 790416 routine sample of boron boric
 acid tank showed 11.08 Reactor power reduction started.
 Caused by possible backflow of makeup water. Check valve
 replaced
 PEGIN, C. H. Rochester Gas & Electric Corp 79/04/30 2pp

7903040191 LER 79-010/01T-0 on 790420 routine sample of boric acid
 storage tanks showed less than 12% Reactor power reduction
 started. Caused by possible backflow of makeup water. Check
 valve replaced
 PEGIN, C. H. Rochester Gas & Electric Corp 79/04/30 2pp

7903010001 Forwarded LER 79-008/00L-0
 MIETZ, L. D. Rochester Gas & Electric Corp 79/03/07 1p

7903010004 LER 79-008/00L-0 on 790406 boric acid flow control valve
 leak noted on valve outlet one inch nipple. Caused by
 internal weld flow through defects & deep external pitting.
 Valve replaced
 PEGIN, C. H. Rochester Gas & Electric Corp 79/05/07 1p

7903010433 Forwarded LER 79-011/01T-0
 MIETZ, L. D. Rochester Gas & Electric Corp 79/05/25 1p

7903010435 LER 79-011/01T-0 on 790515 notified by manufacturer of
 pressure-reducing power operated relief valve that template used
 to fabricate valve internally not within specs. Caused by
 error in design. Valve replaced
 PEGIN, C. H. Rochester Gas & Electric Corp 79/05/25 2pp

ROCKET 30-240 MILLSTONE NUCLEAR POWER STATION UNIT 1

F Security, medical, emergency & fire protection plans

7905070073 Forwards response to NRC written questions re fire protection Engineering & design of most made in progress
COUNCIL M O Northeast Utilities 79/05/18 1pp

H General correspondence

7905070160 Responds to 790204 ltr expressing concern for facility cost problem associated w/anticipated short fuel cycle burning of some plates to spend fuel pool water will not alter previous conclusion that use of waste is not dangerous
COUNCIL M O Operating Reactors Branch 2 79/04/23 2pp

J Insurance & indemnity information

7905050428 Forwards Amend 14 to Indemnity Agreement 8-09 per 100M40 changes re increase in liability insurance from 4500 million to 6100 million, effective 790505 Supporting documentation
BML723MNL J Assistant & Indemnity Group 79/05/01 App

7905050375 Forwards executed Amend 14 to Indemnity Agreement 8-09
B'COMBEN L A Northeast Utilities 79/05/18 App

K Operating license stage documents & correspondence

7905050281 Forwards FR notice of proposed issuance of amend to provisional SL
COUNCIL M O Operating Reactors Branch 2 79/05/06 2pp

7905050282 Notice of proposed issuance of amend to provisional License 09-21 to revise Tech Spec 1.1 of 100 M40 fuel assemblies for Reload &
COUNCIL M O Operating Reactors Branch 2 79/04/26 2pp

7905050234 Forwards topic deleted from systematic evaluation program review of facilities Requested review & identification of errors within 30 days from receipt of ltr
COUNCIL M O Operating Reactors Branch 2 79/04/16 7pp

7905050227 Ask receipt of 790214 plan for leak of Feedwater & control rod drive return line corrosion in reactor pressure vessel
Forwards safety evaluation
COUNCIL M O Operating Reactors Branch 2 79/04/21 2pp

79050500731 Safety evaluation of proposed nozzle ins program
Operating Reactors Branch 2 79/04/21 4pp

7905050085 In 790507 ltr to NRC & 790505 ltr to SC Nuclear, unit states it would be preferable to try pump down fuel in Feedwater train, as opposed to tripping feedwater pump. Impossible to complete installation in Spring 1979
COUNCIL M O Northeast Nuclear Energy Co Northeast Utilities 79/04/23 2p

7905050096 Forwards data & analysis of suppression pool temp transients
COUNCIL M O Northeast Nuclear Energy Co Northeast Utilities 79/04/24 10pp

7905050007 Forwards Amends A0 & B1 to Licenses 09F-21 & 09F-05, respectively, EIA & notice of issuance & negative declaration.
COUNCIL M O Operating Reactors Branch 2 79/04/24 2pp

7905050010 Amends A0 & B1 to Licenses 09F-21 & 09F-05, respectively, revising EIS to provide more flexibility in sampling schedules & collection for specific monitoring & re-fueling improved & modified program objectives
COUNCIL M O Operating Reactors Branch 2 79/04/24 13pp

7905050014 EIA supporting Amends A0 & B1 to Licenses 09F-21 & 09F-05, respectively
Notice of Nuclear Reactor Regulation 79/04/24 13pp

7905050047 Notice of issuance of Amends A0 & B1 to Licenses 09F-21 & 09F-05, respectively, & negative declaration.
COUNCIL M O Operating Reactors Branch 2 79/04/24 2pp

7905050052 Forwards justification of unlimited surging of primary containment in order to provide flexibility to operators in control of containment system level & demand pressure
COUNCIL M O Northeast Utilities 79/04/27 2pp

7905050052 Informs that NRC draft evaluation of systematic evaluation program needs add clarification & should be revised accordingly
COUNCIL M O Northeast Utilities 79/04/27 2pp

7905050034 Forwards NRC-02020-4P, Revision 1, "Segmented Fuel Rod Bundle Millstone 3, Reg'd 414 Apr 1979 Reg'd withheld
(ref 100M40 300)
COUNCIL M O Northeast Utilities 79/05/02 2pp

7905050049 Informs of forthcoming detailed reply to 790207 ltr re "action power plants Plans will not start up until all past items & requirements are implemented & confirmed
HMS601E J H Commission 79/05/11 1p

7905050047 Requests reference that action required by EIS info re Bulletin have been implemented before CT plans return to operation Also requests info on other anticipated NRC actions or anticipated problems
COUNCIL M O Connecticut State of 79/05/07 2pp

7905050050 Responds to W State 790307 ltr Forwards bar-chart showing time periods for implementation of long-term program made Successful completion of program planned for end of 1980
COUNCIL M O Northeast Utilities 79/05/18 2pp

G Inspection reports, IE Bulletins & correspondence

7905040040 Forwards IE Insp Repts 30-245/78-82 & 30-306/79-79-14
79050500100 Re noncompliance noted
BML723MNL J Region 1, Philadelphia, Reactor Operations A-100 Support Branch 79/05/21 2pp

7905040074 IE Insp Repts 30-345/78-82 & 30-326/79-79-14
Re noncompliance noted Major areas (Sealed Unit 1 reactor, turbine & radiators stage, Unit 2 auxiliary & turbine stage, condensate preheating facility & radiation protection)
COUNCIL M O Region 1, Philadelphia, Office of the Director, HCRB/E, C Region 1, Philadelphia, Reactor Operations A-100 Support Branch 79/05/25 13pp

7905050021 Forwards IE Info Notice 79-04, "Stress Analysis of Sealing-Related Piping"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/23 2p

7905050030 Forwards IE Info Notice 79-03, "Interconnection of Contaminated Gas w/30c Air Gys Used as Source of Breathing Air"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/23 1p

7905050034 Forwards IE Info Notice 79-09, "April of Radioactivity Contaminated Reels"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/30 2pp

7905050040 Forwards IE Insp Repts 30-245/79-05 on 790507-0302 N2 noncompliance noted
BML723MNL J Region 1, Philadelphia, Reactor Operations A-100 Support Branch 79/05/23 2pp

7905050045 IE Insp Repts 30-245/79-05 on 790507-0302 N2 noncompliance noted Major areas inspected, facility procedures-revisions per Tech Spec amend & action on previous Insp findings
COUNCIL M O COUNCIL C L Region 1, Philadelphia, Office of the Director, HCRB/E, B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/25 13pp

7905050054 Forwards IE Bulletin 79-04, "Review of Operational Events: Key Missions Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/21 1p

7905050010 Forwards IE Bulletin 79-04, "Review of Operational Events: Key Missions Identified During TMI Incident"
NEPHER, G Region 2, Chicago, Office of the Director 79/04/21 1p

7905050030 Forwards IE Bulletin 79-07, "Definitive Stress Analysis of Sealing-Related Piping - License action required"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/16 1p

7905050037 Forwards IE Bulletin 79-06, "Review of Operational Events: Key Missions Identified During TMI Incident"
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/16 1p

7905050028 Forwards IE Bulletin 79-08, "Events Relevant to Noting Major Power Reactors Identified During TMI Incident"
License action required
GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/16 1p

DOCKETED ITEMS

31

7905020077 Forwards IE Bulletin 79-09, "Failures of SE Type AN-2 Circuit Breaker in Safety-Related Sys." Licensee action required
 GRUBER, R. H. Region I, Philadelphia, Office of the Director
 79/04/17 1p

7905020084 Forwards IE Bulletin 79-00A, Revision 1, "Review of Operational Errors & Sys. Misalignments Identified During TMI Incident"
 GRUBER, R. H. Region I, Philadelphia, Office of the Director
 79/04/18 1p

R Periodic operating reports & related correspondence

7905020090 Forwards monthly operating report for Apr 1979
 GRUBER, R. H. Northeast Utilities 79/05/15 1p

7905020094 Monthly operating report for Apr 1979
 GRUBER, R. H. Northeast Utilities 79/05/15 1p

R Reportable occurrences, LERs & related correspondence

7905020093 Forwards LER 79-012/03L-0
 GRUBER, R. H. Northeast Utilities 79/05/15 1p

7905020094 LER 79-012/03L-0 on 790420 while performing routine reactor blow down duct & refuel floor high radiation monitor functional surveillance. Channel 1 was out of calibrate caused by instrument drift
 GRUBER, R. H. Northeast Utilities 79/05/21 2pp

DOCKET 30-247 INDIAN POINT STATION, UNIT 2

J Insurance & Indemnity Information

7905020097 Confirms increased liability limit to \$124,000,000 per policies 79-01, 79-02, 79-03, 79-04, 79-05, 79-06, 79-07, 79-08, 79-09, 79-10, 79-11, 79-12, 79-13, 79-14, 79-15, 79-16, 79-17, 79-18, 79-19, 79-20, 79-21, 79-22, 79-23, 79-24, 79-25, 79-26, 79-27, 79-28, 79-29, 79-30, 79-31, 79-32, 79-33, 79-34, 79-35, 79-36, 79-37, 79-38, 79-39, 79-40, 79-41, 79-42, 79-43, 79-44, 79-45, 79-46, 79-47, 79-48, 79-49, 79-50, 79-51, 79-52, 79-53, 79-54, 79-55, 79-56, 79-57, 79-58, 79-59, 79-60, 79-61, 79-62, 79-63, 79-64, 79-65, 79-66, 79-67, 79-68, 79-69, 79-70, 79-71, 79-72, 79-73, 79-74, 79-75, 79-76, 79-77, 79-78, 79-79, 79-80, 79-81, 79-82, 79-83, 79-84, 79-85, 79-86, 79-87, 79-88, 79-89, 79-90, 79-91, 79-92, 79-93, 79-94, 79-95, 79-96, 79-97, 79-98, 79-99, 79-100, 79-101, 79-102, 79-103, 79-104, 79-105, 79-106, 79-107, 79-108, 79-109, 79-110, 79-111, 79-112, 79-113, 79-114, 79-115, 79-116, 79-117, 79-118, 79-119, 79-120, 79-121, 79-122, 79-123, 79-124, 79-125, 79-126, 79-127, 79-128, 79-129, 79-130, 79-131, 79-132, 79-133, 79-134, 79-135, 79-136, 79-137, 79-138, 79-139, 79-140, 79-141, 79-142, 79-143, 79-144, 79-145, 79-146, 79-147, 79-148, 79-149, 79-150, 79-151, 79-152, 79-153, 79-154, 79-155, 79-156, 79-157, 79-158, 79-159, 79-160, 79-161, 79-162, 79-163, 79-164, 79-165, 79-166, 79-167, 79-168, 79-169, 79-170, 79-171, 79-172, 79-173, 79-174, 79-175, 79-176, 79-177, 79-178, 79-179, 79-180, 79-181, 79-182, 79-183, 79-184, 79-185, 79-186, 79-187, 79-188, 79-189, 79-190, 79-191, 79-192, 79-193, 79-194, 79-195, 79-196, 79-197, 79-198, 79-199, 79-200, 79-201, 79-202, 79-203, 79-204, 79-205, 79-206, 79-207, 79-208, 79-209, 79-210, 79-211, 79-212, 79-213, 79-214, 79-215, 79-216, 79-217, 79-218, 79-219, 79-220, 79-221, 79-222, 79-223, 79-224, 79-225, 79-226, 79-227, 79-228, 79-229, 79-230, 79-231, 79-232, 79-233, 79-234, 79-235, 79-236, 79-237, 79-238, 79-239, 79-240, 79-241, 79-242, 79-243, 79-244, 79-245, 79-246, 79-247, 79-248, 79-249, 79-250, 79-251, 79-252, 79-253, 79-254, 79-255, 79-256, 79-257, 79-258, 79-259, 79-260, 79-261, 79-262, 79-263, 79-264, 79-265, 79-266, 79-267, 79-268, 79-269, 79-270, 79-271, 79-272, 79-273, 79-274, 79-275, 79-276, 79-277, 79-278, 79-279, 79-280, 79-281, 79-282, 79-283, 79-284, 79-285, 79-286, 79-287, 79-288, 79-289, 79-290, 79-291, 79-292, 79-293, 79-294, 79-295, 79-296, 79-297, 79-298, 79-299, 79-300, 79-301, 79-302, 79-303, 79-304, 79-305, 79-306, 79-307, 79-308, 79-309, 79-310, 79-311, 79-312, 79-313, 79-314, 79-315, 79-316, 79-317, 79-318, 79-319, 79-320, 79-321, 79-322, 79-323, 79-324, 79-325, 79-326, 79-327, 79-328, 79-329, 79-330, 79-331, 79-332, 79-333, 79-334, 79-335, 79-336, 79-337, 79-338, 79-339, 79-340, 79-341, 79-342, 79-343, 79-344, 79-345, 79-346, 79-347, 79-348, 79-349, 79-350, 79-351, 79-352, 79-353, 79-354, 79-355, 79-356, 79-357, 79-358, 79-359, 79-360, 79-361, 79-362, 79-363, 79-364, 79-365, 79-366, 79-367, 79-368, 79-369, 79-370, 79-371, 79-372, 79-373, 79-374, 79-375, 79-376, 79-377, 79-378, 79-379, 79-380, 79-381, 79-382, 79-383, 79-384, 79-385, 79-386, 79-387, 79-388, 79-389, 79-390, 79-391, 79-392, 79-393, 79-394, 79-395, 79-396, 79-397, 79-398, 79-399, 79-400, 79-401, 79-402, 79-403, 79-404, 79-405, 79-406, 79-407, 79-408, 79-409, 79-410, 79-411, 79-412, 79-413, 79-414, 79-415, 79-416, 79-417, 79-418, 79-419, 79-420, 79-421, 79-422, 79-423, 79-424, 79-425, 79-426, 79-427, 79-428, 79-429, 79-430, 79-431, 79-432, 79-433, 79-434, 79-435, 79-436, 79-437, 79-438, 79-439, 79-440, 79-441, 79-442, 79-443, 79-444, 79-445, 79-446, 79-447, 79-448, 79-449, 79-450, 79-451, 79-452, 79-453, 79-454, 79-455, 79-456, 79-457, 79-458, 79-459, 79-460, 79-461, 79-462, 79-463, 79-464, 79-465, 79-466, 79-467, 79-468, 79-469, 79-470, 79-471, 79-472, 79-473, 79-474, 79-475, 79-476, 79-477, 79-478, 79-479, 79-480, 79-481, 79-482, 79-483, 79-484, 79-485, 79-486, 79-487, 79-488, 79-489, 79-490, 79-491, 79-492, 79-493, 79-494, 79-495, 79-496, 79-497, 79-498, 79-499, 79-500, 79-501, 79-502, 79-503, 79-504, 79-505, 79-506, 79-507, 79-508, 79-509, 79-510, 79-511, 79-512, 79-513, 79-514, 79-515, 79-516, 79-517, 79-518, 79-519, 79-520, 79-521, 79-522, 79-523, 79-524, 79-525, 79-526, 79-527, 79-528, 79-529, 79-530, 79-531, 79-532, 79-533, 79-534, 79-535, 79-536, 79-537, 79-538, 79-539, 79-540, 79-541, 79-542, 79-543, 79-544, 79-545, 79-546, 79-547, 79-548, 79-549, 79-550, 79-551, 79-552, 79-553, 79-554, 79-555, 79-556, 79-557, 79-558, 79-559, 79-560, 79-561, 79-562, 79-563, 79-564, 79-565, 79-566, 79-567, 79-568, 79-569, 79-570, 79-571, 79-572, 79-573, 79-574, 79-575, 79-576, 79-577, 79-578, 79-579, 79-580, 79-581, 79-582, 79-583, 79-584, 79-585, 79-586, 79-587, 79-588, 79-589, 79-590, 79-591, 79-592, 79-593, 79-594, 79-595, 79-596, 79-597, 79-598, 79-599, 79-600, 79-601, 79-602, 79-603, 79-604, 79-605, 79-606, 79-607, 79-608, 79-609, 79-610, 79-611, 79-612, 79-613, 79-614, 79-615, 79-616, 79-617, 79-618, 79-619, 79-620, 79-621, 79-622, 79-623, 79-624, 79-625, 79-626, 79-627, 79-628, 79-629, 79-630, 79-631, 79-632, 79-633, 79-634, 79-635, 79-636, 79-637, 79-638, 79-639, 79-640, 79-641, 79-642, 79-643, 79-644, 79-645, 79-646, 79-647, 79-648, 79-649, 79-650, 79-651, 79-652, 79-653, 79-654, 79-655, 79-656, 79-657, 79-658, 79-659, 79-660, 79-661, 79-662, 79-663, 79-664, 79-665, 79-666, 79-667, 79-668, 79-669, 79-670, 79-671, 79-672, 79-673, 79-674, 79-675, 79-676, 79-677, 79-678, 79-679, 79-680, 79-681, 79-682, 79-683, 79-684, 79-685, 79-686, 79-687, 79-688, 79-689, 79-690, 79-691, 79-692, 79-693, 79-694, 79-695, 79-696, 79-697, 79-698, 79-699, 79-700, 79-701, 79-702, 79-703, 79-704, 79-705, 79-706, 79-707, 79-708, 79-709, 79-710, 79-711, 79-712, 79-713, 79-714, 79-715, 79-716, 79-717, 79-718, 79-719, 79-720, 79-721, 79-722, 79-723, 79-724, 79-725, 79-726, 79-727, 79-728, 79-729, 79-730, 79-731, 79-732, 79-733, 79-734, 79-735, 79-736, 79-737, 79-738, 79-739, 79-740, 79-741, 79-742, 79-743, 79-744, 79-745, 79-746, 79-747, 79-748, 79-749, 79-750, 79-751, 79-752, 79-753, 79-754, 79-755, 79-756, 79-757, 79-758, 79-759, 79-760, 79-761, 79-762, 79-763, 79-764, 79-765, 79-766, 79-767, 79-768, 79-769, 79-770, 79-771, 79-772, 79-773, 79-774, 79-775, 79-776, 79-777, 79-778, 79-779, 79-780, 79-781, 79-782, 79-783, 79-784, 79-785, 79-786, 79-787, 79-788, 79-789, 79-790, 79-791, 79-792, 79-793, 79-794, 79-795, 79-796, 79-797, 79-798, 79-799, 79-800, 79-801, 79-802, 79-803, 79-804, 79-805, 79-806, 79-807, 79-808, 79-809, 79-810, 79-811, 79-812, 79-813, 79-814, 79-815, 79-816, 79-817, 79-818, 79-819, 79-820, 79-821, 79-822, 79-823, 79-824, 79-825, 79-826, 79-827, 79-828, 79-829, 79-830, 79-831, 79-832, 79-833, 79-834, 79-835, 79-836, 79-837, 79-838, 79-839, 79-840, 79-841, 79-842, 79-843, 79-844, 79-845, 79-846, 79-847, 79-848, 79-849, 79-850, 79-851, 79-852, 79-853, 79-854, 79-855, 79-856, 79-857, 79-858, 79-859, 79-860, 79-861, 79-862, 79-863, 79-864, 79-865, 79-866, 79-867, 79-868, 79-869, 79-870, 79-871, 79-872, 79-873, 79-874, 79-875, 79-876, 79-877, 79-878, 79-879, 79-880, 79-881, 79-882, 79-883, 79-884, 79-885, 79-886, 79-887, 79-888, 79-889, 79-890, 79-891, 79-892, 79-893, 79-894, 79-895, 79-896, 79-897, 79-898, 79-899, 79-900, 79-901, 79-902, 79-903, 79-904, 79-905, 79-906, 79-907, 79-908, 79-909, 79-910, 79-911, 79-912, 79-913, 79-914, 79-915, 79-916, 79-917, 79-918, 79-919, 79-920, 79-921, 79-922, 79-923, 79-924, 79-925, 79-926, 79-927, 79-928, 79-929, 79-930, 79-931, 79-932, 79-933, 79-934, 79-935, 79-936, 79-937, 79-938, 79-939, 79-940, 79-941, 79-942, 79-943, 79-944, 79-945, 79-946, 79-947, 79-948, 79-949, 79-950, 79-951, 79-952, 79-953, 79-954, 79-955, 79-956, 79-957, 79-958, 79-959, 79-960, 79-961, 79-962, 79-963, 79-964, 79-965, 79-966, 79-967, 79-968, 79-969, 79-970, 79-971, 79-972, 79-973, 79-974, 79-975, 79-976, 79-977, 79-978, 79-979, 79-980, 79-981, 79-982, 79-983, 79-984, 79-985, 79-986, 79-987, 79-988, 79-989, 79-990, 79-991, 79-992, 79-993, 79-994, 79-995, 79-996, 79-997, 79-998, 79-999, 79-1000, 79-1001, 79-1002, 79-1003, 79-1004, 79-1005, 79-1006, 79-1007, 79-1008, 79-1009, 79-1010, 79-1011, 79-1012, 79-1013, 79-1014, 79-1015, 79-1016, 79-1017, 79-1018, 79-1019, 79-1020, 79-1021, 79-1022, 79-1023, 79-1024, 79-1025, 79-1026, 79-1027, 79-1028, 79-1029, 79-1030, 79-1031, 79-1032, 79-1033, 79-1034, 79-1035, 79-1036, 79-1037, 79-1038, 79-1039, 79-1040, 79-1041, 79-1042, 79-1043, 79-1044, 79-1045, 79-1046, 79-1047, 79-1048, 79-1049, 79-1050, 79-1051, 79-1052, 79-1053, 79-1054, 79-1055, 79-1056, 79-1057, 79-1058, 79-1059, 79-1060, 79-1061, 79-1062, 79-1063, 79-1064, 79-1065, 79-1066, 79-1067, 79-1068, 79-1069, 79-1070, 79-1071, 79-1072, 79-1073, 79-1074, 79-1075, 79-1076, 79-1077, 79-1078, 79-1079, 79-1080, 79-1081, 79-1082, 79-1083, 79-1084, 79-1085, 79-1086, 79-1087, 79-1088, 79-1089, 79-1090, 79-1091, 79-1092, 79-1093, 79-1094, 79-1095, 79-1096, 79-1097, 79-1098, 79-1099, 79-1100, 79-1101, 79-1102, 79-1103, 79-1104, 79-1105, 79-1106, 79-1107, 79-1108, 79-1109, 79-1110, 79-1111, 79-1112, 79-1113, 79-1114, 79-1115, 79-1116, 79-1117, 79-1118, 79-1119, 79-1120, 79-1121, 79-1122, 79-1123, 79-1124, 79-1125, 79-1126, 79-1127, 79-1128, 79-1129, 79-1130, 79-1131, 79-1132, 79-1133, 79-1134, 79-1135, 79-1136, 79-1137, 79-1138, 79-1139, 79-1140, 79-1141, 79-1142, 79-1143, 79-1144, 79-1145, 79-1146, 79-1147, 79-1148, 79-1149, 79-1150, 79-1151, 79-1152, 79-1153, 79-1154, 79-1155, 79-1156, 79-1157, 79-1158, 79-1159, 79-1160, 79-1161, 79-1162, 79-1163, 79-1164, 79-1165, 79-1166, 79-1167, 79-1168, 79-1169, 79-1170, 79-1171, 79-1172, 79-1173, 79-1174, 79-1175, 79-1176, 79-1177, 79-1178, 79-1179, 79-1180, 79-1181, 79-1182, 79-1183, 79-1184, 79-1185, 79-1186, 79-1187, 79-1188, 79-1189, 79-1190, 79-1191, 79-1192, 79-1193, 79-1194, 79-1195, 79-1196, 79-1197, 79-1198, 79-1199, 79-1200, 79-1201, 79-1202, 79-1203, 79-1204, 79-1205, 79-1206, 79-1207, 79-1208, 79-1209, 79-1210, 79-1211, 79-1212, 79-1213, 79-1214, 79-1215, 79-1216, 79-1217, 79-1218, 79-1219, 79-1220, 79-1221, 79-1222, 79-1223, 79-1224, 79-1225, 79-1226, 79-1227, 79-1228, 79-1229, 79-1230, 79-1231, 79-1232, 79-1233, 79-1234, 79-1235, 79-1236, 79-1237, 79-1238, 79-1239, 79-1240, 79-1241, 79-1242, 79-1243, 79-1244, 79-1245, 79-1246, 79-1247, 79-1248, 79-1249, 79-1250, 79-1251, 79-1252, 79-1253, 79-1254, 79-1255, 79-1256, 79-1257, 79-1258, 79-1259, 79-1260, 79-1261, 79-1262, 79-1263, 79-1264, 79-1265, 79-1266, 79-1267, 79-1268, 79-1269, 79-1270, 79-1271, 79-1272, 79-1273, 79-1274, 79-1275, 79-1276, 79-1277, 79-1278, 79-1279, 79-1280, 79-1281, 79-1282, 79-1283, 79-1284, 79-1285, 79-1286, 79-1287, 79-1288, 79-1289, 79-1290, 79-1291, 79-1292, 79-1293, 79-1294, 79-1295, 79-1296, 79-1297, 79-1298, 79-1299, 79-1300, 79-1301, 79-1302, 79-1303, 79-1304, 79-1305, 79-1306, 79-1307, 79-1308, 79-1309, 79-1310, 79-1311, 79-1312, 79-1313, 79-1314, 79-1315, 79-1316, 79-1317, 79-1318, 79-1319, 79-1320, 79-1321, 79-1322, 79-1323, 79-1324, 79-1325, 79-1326, 79-1327, 79-1328, 79-1329, 79-1330, 79-1331, 79-1332, 79-1333, 79-1334, 79-1335, 79-1336, 79-1337, 79-1338, 79-1339, 79-1340, 79-1341, 79-1342, 79-1343, 79-1344, 79-1345, 79-1346, 79-1347, 79-1348, 79-1349, 79-1350, 79-1351, 79-1352, 79-1353, 79-1354, 79-1355, 79-1356, 79-1357, 79-1358, 79-1359, 79-1360, 79-1361, 79-1362, 79-1363, 79-1364, 79-1365, 79-1366, 79-1367, 79-1368, 79-1369, 79-1370, 79-1371, 79-1372, 79-1373, 79-1374, 79-1375, 79-1376, 79-1377, 79-1378, 79-1379, 79-1380, 79-1381, 79-1382, 79-1383, 79-1384, 79-1385, 79-1386, 79-1387, 79-1388, 79-1389, 79-1390, 79-1391, 79-1392, 79-1393,

--7905200105 Response to NRC 7903226 for re violation noted in IE Insp Rept 90-003/78-13 & 90-047/79-08 on developing techniques to avoid violations leading to badge anomalies
CAILLU, M. J. Consolidated Edison Co. of New York 79/03/21 3pp

--7905200088 Forward IE Insp Repts 90-003/78-13 & 90-047/79-08 on 790327-29 & 790317-18 & notice of violation
SMITH, R. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/28 2pp

--7905200093 Notice of violation from Insp on 790327-29 & 790317-18 & Region 1, Philadelphia, Office of the Director 79/02/28 1p

--7905200196 IE Insp Rept 90-003/78-13 & 90-047/79-08 on 790327-29 & 790317-18 Noncompliance noted failure to maintain personnel exposure limits in accordance with 10CFR200.101
ROSE, R. E. & BERNDT, J. A. Region 1, Philadelphia, Office of the Director, CHSDELM, M. J. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/27 12pp

7905200096 Forward supplemental response to IE Bulletin 79-07 re recent analysis as requested on 790517 meeting
CAILLU, M. J. Consolidated Edison Co. of New York 79/03/22 5pp

B Periodic operating reports & related correspondence

7905200036 Forward efficient monitoring & development data specified in Section 401 Certification for Apr 1979
KOPF, M. A. Consolidated Edison Co. of New York 79/03/30 17pp

7905200092 Forward daily record of fish collections for Apr 1979 Monthly species breakdown & total weight for Units 2 & 3
SMITH, R. H. Region 1, Philadelphia, Office of the Director 79/03/14 5pp

7905200063 Forward monthly operating report for Apr 1979
CAILLU, M. J. Consolidated Edison Co. of New York 79/03/15 1p

--7905200047 Revise monthly operating report for Apr 1979
KOPF, M. A. Consolidated Edison Co. of New York 79/03/04 7pp

C Reportable occurrences, LERs & related correspondence

7905040004 Forward LERs 79-013/03L-0 & 79-014/03L-0
CAILLU, M. J. Consolidated Edison Co. of New York 79/04/27 1p

--7905050006 LER 79-013/03L-0 on 790329 pinhole leak at socket weld connection on seal injection header (line 802) downstream of seal injection filters 501E collar placed around leak
Paramount repairs will be made during future outages
KOPF, M. A. Consolidated Edison Co. of New York 79/04/27 1p

--7905040077 LER 79-014/03L-0 on 790331 electric heat trace NIB found to have inoperable primary circuit caused by defective Chromal strip heater elements PT-502 elements replaced & circuit returned to service
KOPF, M. A. Consolidated Edison Co. of New York 79/04/27 1p

7905100013 Forward LER 79-013/04L-1
CAILLU, M. J. Consolidated Edison Co. of New York 79/05/10 1p

--7905100008 LER 79-013/04L-0 on 790408 activity of precipitation sample exceeded 10 times control station level caused by tritium release from source returned to Facility Manufacturer in area has modified installation to prevent recurrence
KOPF, M. A. Consolidated Edison Co. of New York 79/05/10 5pp

7905100021 Forward LER 79-015/04L-0
CAILLU, M. J. Consolidated Edison Co. of New York 79/05/10 1p

--7905100025 LER 79-015/04L-0 on 790408 activity of precipitation sample exceeded 10 times control station level caused by tritium release from source returned to Facility Manufacturer in area has modified installation to prevent recurrence
KOPF, M. A. Consolidated Edison Co. of New York 79/05/10 5pp

QUEST 30-247 DESIGN NUCLEAR POWER STATION UNIT 3

Security, medical, emergency & fire protection plans

7905030044 Forward modified physical security plan-Revision 3 Plan
LIEBOWITZ, R. H. Consolidated Edison Co. of New York 79/04/26 1p

7905040002 Forward pages of "Implementation of Nuclear Mutual Liability Loss Prevention Program." In response to NRC 7903226 request for fire protection administrative controls
JAMESON, R. F. Commonwealth Edison Co. 79/04/30 8pp

D Regulatory correspondence

7905200026 Multiple properly ordered contention re submittal would be accepted Calculation & an admitted issue Duke Power Co proceeding encompasses aspects of revised Contention 21 presented by State of IL
GOSWAMI, R. J. Branch 2 79/04/04 2pp

J Insurance & indemnity information

7905100043 Endorsement 99 to NACLI Policy 79-02
GOSWAMI, R. J. Nuclear Energy Liability Insurance Association 79/03/12 1p

7905100047 Confirm increased liability limit to \$124,000,000 for policies 99-1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

DOCKETED ITEMS

33

- 7905020078 Forwards summary of EEO Nuclear, Inc. resolution/documentation of minor flexibility error which existed in versions of PHS, playing analysis computer program from Jan-Oct 1979. Review & analysis included all work through Dec 1979. PORTER, L. C. EEO Nuclear, Inc. 79/03/25 1pg
- 7905020080 Forwards EEO Nuclear, Inc. list of BWRs & piping systems which could have been impacted by deficient computer program. GE has no record of reanalysis for Cooper piping systems. GEPH/MSB, P. H. General Electric Co. Nuclear Energy Products Div. 79/01/28 1pg
- 7905020084 Holdback 790512 Request for exemption from 10CFR50 to fixed reactor vessel during integrated primary containment leak rate test. JAMESON, R. F. Commonwealth Edison Co. 79/03/24 2pg
- Q Inspection reports, IE Bulletins & correspondence
- 7905020092 Forwards response to IE Bulletin 79-12 & 79-12A: "Atypical Weld Metal in Reactor Pressure Vessel Heads". HEDC, C. Commonwealth Edison Co. 79/03/25 1pg
- 7905020093 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/03/23 1pg
- 7905020095 Forwards IE Info Notice 79-07, "Bursture of Reducers Tanks". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/03/26 1pg
- 7905020098 Forwards IE Info Notice 79-06, "Interconnection of Contaminated Gas With Air Gas Used as Source of Breathing Air". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/03/20 1pg
- 7905020099 Forwards IE Info Notice 79-06, "Spill of Radioactively Contaminated Resin". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/03/20 1pg
- 7905020103 Forwards IE Bulletin 79-06, "Review of Operational Errors & Gas Reassignments Identified During TMI Incident". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/04/11 1pg
- 7905020140 Forwards IE Insp Repts 30-010/79-07, 30-027/79-07 & 30-047/79-07 on 790304-09, 0312 & 0322 No noncompliance noted. SHUTE, A. B. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/11 2pg
- 7905020454 IE Insp Repts 30-010/79-07, 30-027/79-07 & 30-047/79-07 on 790304-09, 0312 & 0322 No noncompliance noted. Major areas inspected internal audits, off-site support agency coordination, emergency facilities, training & drills. SHUTE, A. B. Region 3, Chicago, Office of the Director 79/04/05 2pg
- 7905020460 Response to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools. Plants inspected re pipe found. HEDC, C. Commonwealth Edison Co. 79/04/12 2pg
- 7905020507 Forwards IE Bulletin 79-06A: "Review of Operational Errors & Gas Reassignments Identified During TMI Incident". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/04/14 1pg
- 7905040034 Forwards IE Bulletin 79-06D, "Review of Operational Errors & Gas Reassignments Identified During TMI Incident". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/04/14 1pg
- 7905040037 Forwards IE Bulletin 79-06, "Events Relevant to Selling Water Power Reactors Identified During TMI Incident". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/04/14 1pg
- 7905050006 Forwards IE Bulletin 79-04, "Failures of GE Type AA-2 Circuit Breaker in Safety-Related Gas". Licenses action required. NEPLER, J. D. Region 3, Chicago, Office of the Director 79/04/17 1pg
- 7905040042 Forwards IE Bulletin 79-05B: "Nuclear Incident at TMI-Beggs, I". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/04/21 1pg
- 7905040050 IE Bulletin 79-05B: "Nuclear Incident at TMI-Beggs, I". Supporting documentation incl. Region 3, Chicago, Office of the Director 79/04/21 1pg
- 7905040052 ACRB recommendations re 790326 Incident at TMI. Requests high priority to plan on development of a safety research on behavior of LWRs during anomalous transients. ACRB - Advisory Committee on Reactor Safeguards 79/04/17 2pg
- 7905040051 Forwards ACRB recommendations re TMI Incident, presented on 790417. FIDLEY, R. F. ACRB - Advisory Committee on Reactor Safeguards 79/04/18 1pg
- 7905040051 In response to NRC 790418 letter, ACRB recommendations apply to all PWRs, but were not intended to require immediate changes. Plant name should be made after study of effects on overall safety. TMI included. CARRILL, R. ACRB - Advisory Committee on Reactor Safeguards 79/04/20 2pg
- 7905040053 Forwards response to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping. Reanalysis indicates method of structural combination has little effect on pipe stresses & equipment support loads. SEEB, C. Commonwealth Edison Co. 79/04/24 2pg
- 7905050054 Act receipt of 790418 letter regarding NRC of shape taken to correct violations noted in IE Insp Repts 30-010/79-04, 30-027/79-04 & 30-047/79-04. HEDC, J. A. Region 3, Chicago, Safeguards Branch 79/04/26 1pg
- 7905050055 Response to NRC 790326 letter re violations noted in IE Insp Repts 30-010/79-04, 30-027/79-04 & 30-047/79-04. Corrective actions withheld (ref 10CFR2.209). SEEB, C. Commonwealth Edison Co. 79/04/16 1pg
- 7905100140 Forwards response to IE Bulletin 79-06A. Review of GWR events identified during TMI-2. Unit has formed task force to review GWR events & recommend corrective actions as required. HEDC, C. Commonwealth Edison Co. 79/04/27 2pg
- 7905020042 Response to IE Bulletin 79-04 Re 3.4 & 4-inch Valve using Check valves are in use at Dresden or Quad-Cities. Review of Zien has identified use of valves in same piping systems but review is incomplete. Will report later. HEDC, C. Commonwealth Edison Co. 79/05/01 2pg
- 7905100496 Forwards IE Circular 79-07, "Unplanned Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase". NEPLER, J. D. Region 3, Chicago, Office of the Director 79/05/02 1pg
- R Periodic operating reports & related correspondence
- 7905100394 Forwards monthly operating report for Apr 1979. STEPHENSON, B. B. Commonwealth Edison Co. 79/05/02 1pg
- 7905100399 Monthly operating report for Apr 1979. CIES/DIENH/IGS. Commonwealth Edison Co. 79/05/02 20pg
- G. Reportable occurrences, LERs & related correspondence
- 7905050048 Forwards LER 79-005/03L-3. STEPHENSON, B. B. Commonwealth Edison Co. 79/05/02 1pg
- 7905050050 LER 79-005/03L-3 on 790418 during routine surveillance, b1 isolation condensate flow multi differential pressure alarm triggered. Caused by instrumented drift. LINDBERGH, C. Commonwealth Edison Co. 79/05/02 1pg
- 7905040038 Forwards LER 79-006/03T-0, STEPHENSON, B. B. Commonwealth Edison Co. 79/05/04 1pg
- 7905040039 LER 79-006/03T-0 on 790418. BBO volt battery was not operable. Caused by operator error. Battery was recharged after re-fueling outage discharge test. HEDC, J. A. Commonwealth Edison Co. 79/05/04 2pg
- 7905050057 Forwards LER 79-009/01V-3. STEPHENSON, B. B. Commonwealth Edison Co. 79/05/04 1pg

3

PENDING 1987 FWD-001 LHM PP-008/23L-0
 1987-001-001 LHM Commercial Union Co 79/09/24 18

DOCKET 13-250 TORREY POINT PLANT, UNIT 2

◎ 康乐与康乐设施管理 康乐设施管理·125

7509150025 Petitioner revision to 360025 petition to unconvict
ENCLOSURE, R P affiliation unknown 79/03/19 3p

7/20/02/055 act receipt of 7/20/02 lit to Board, w/ revised position
 re interview. R Daily affidavit, w/ info for production
 of documents & entry upon land for imp & other purposes
 Requests signed & notarized affidavit from R Daily
 COOL, H & Street, Newton & Davis 7/20/02 Rye

--PAG0500794 Response by civil seeking denial on basis of unavailability
of NP Occava's position to interview P44 higher days not
available standing not offer admissible confessions
DANIEL H A LAWRENCE/McMann,Reis,Arnold & Coll GOL-N A
Steel, Hester & Davis TV/03/30 2pgs

7900299409 Grants FL Power & Light Co & AMC opportunity to submit responses to newly submitted considerations of petitioner
 RE Coverage.
 SOURCE: Atomic Safety and Licensing Board Panel. 29. 2
 See

11. General correspondence

7905240738 Forwards constituent's request that NRC grant a
petition for hearing & intervention re facility repairs
WFOE:R Senate 79/04/26 2pp

7905200400 responds to 790412 for requesting consideration of a petition in support of HF Deawave petition to intervene Broadcasting conference will be held on 790502 in Hawaii.

0005000 L V Office of the Executive Director for Operations
0005000 L V

4. Transparency & Informing Information

7903070497 Confirms increased liability limit to \$104,000 for
policies 95-1, 25, 42, 76, 82, 104, 111, 140, 144, 151, 161, 164, 170,
172, 174, 178, 179, 180, 182, 183, 186-187, 190, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206-207, 208-210, 212, 214, 215, & others
in the amount of \$200,000 to

7900070500 Confirms increase in stability limit to 476.000 °
 solutes 79-22, 26, 29, 30, 39, 44, 46, 47, 49, 50, 51, 52, 53, 74, 77, 78, 79, 80, 81, 84, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96
 80000705, 8 N Mutual Atomic Energy Liability Underwritten

7903104000 Forwards Award 10 to Indemnity Agreement & 45 per 1 -
changes/re increase in liability insurance from \$145 million
to \$100 million, effective 790301. Supporting documentation
encl

7903100386 Forwards Enforcement AG to NELA Police ME: 117
FISLER, J. Mark & Release. R & R Nuclear Consultants, Inc.
79/08/03 Zpp

7805100307 Forwarded Endorsement #7 to HELIA Policy ME-015
FIGUER, J. Marsh & McLennan, M & H Nuclear Consultants, Inc.
78/05/04, Rpp

7905250411: Forwards executed Amend 10 to Indemnity Agreement # 4
Increasing coverage to \$100 million
UNRIS, S E Florida Power & Light Co 79/05/21 Cpo

79/03/24 Res

7900000011 Forwards Endorsement 41 to H&M/J Policy HF-30
FIDDER, J. Marsh & McLennan, H & M Nuclear Consultants, Inc.
79/05/84 gpp

DOCKETED ITEMS

35

Re Antitrust correspondence

7/01/82/234 Motion by FL Citrus seeking antitrust hearing rehearse request to argue position re review & consolidation of antitrust hearing Certificate of Div. encl
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/237 Forwards motion for consolidated hearings on behalf of FL Citrus
JAMES H. A. Spiegel & McElwain 7/01/82 1p

7/01/82/238 Motion for consolidated hearings by FL Citrus Certificate of Div. encl
JAMES H. A. Spiegel & McElwain 7/01/82 App

7/01/82/242 Response to 7/01/82/237 & 7/01/82/238 motions filed by FL Citrus to schedule antitrust hearing. In response to RSC 700227 order Certificate of Div. encl
JAMES H. A. Spiegel & McElwain 7/01/82 1p

P Operating license stage documents & correspondence

7/01/82/243 Forwards Amends 40 & 31 to Licenses DPH-01 & DPH-01, respectively; safety evaluation & notice of issuance & availability
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/244 Amends 40 & 31 to Licenses DPH-01 & 01, respectively; adding license conditions re completion of facility rules & implementation of administrative controls for fire protection
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/245 Safety evaluation supporting Amends 40 & 31 to Licenses DPH-01 & 01, respectively
JAMES H. A. Spiegel & McElwain 7/01/82 4pp

7/01/82/246 Notice of issuance & availability of Amends 40 & 31 to Licenses DPH-01 & 01, respectively
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/247 Forwards Amend 40 to License DPH-01; safety evaluation & notice of issuance & availability
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/248 Amend 40 to License DPH-01; permitting continued operation of Unit 3 for six equivalent months of operation
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/249 Safety evaluation supporting Amend 40 to License DPH-01
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/250 Notice of issuance & availability of Amend 40 to License DPH-01
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/251 Summary of 7/01/82 meeting w/Unit 1 & Westinghouse re seismic analysis of reaction coolant piping
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/252 Forwards request to amend App A of Licenses DPH-01 & DPH-01 re prescriber level Affidavit & safety evaluation encl
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/253 Forwards replacement first page for safety evaluation-Forwards 7/01/82 w/affidavit Spec change proposal re safety inspection trip log
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/254 Forwards initial response re emergency power sys periodic tests requested in ABC 700335 ltr
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/255 Instructions for Amp & tests of lockout relays
JAMES H. A. Spiegel & McElwain 7/01/82 App

7/01/82/256 Forwards request for amend to App A of Licenses DPH-01 & DPH-01 Amend changes Tech Spec limits re ECC cooling performance in light of Westinghouse reevaluation
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/257 Seismic analysis supporting amend to App A of Licenses DPH-01 & DPH-01 RSC safety limit of 1.24 is consistent w/CDRMA 111C computer code Forwards "RSC Safety Limit for CDRMA 111C Analysis"
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/258 "RSC Safety Limit for CDRMA 111C Analysis"
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/259 Forwards summary of RSC Nuclear, Inc. resolution/documentation of above flexibility error which existed in version of P100 piping analysis computer program from Jan-Oct 1979 Review & analysis included all work through Dec 1979
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/260 Forwards RSC Nuclear, Inc. list of BME & piping sys which could have been impacted by deficient computer program
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

9 Inspection reports, IE Bulletin & correspondence

7/01/82/261 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/262 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/263 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/DC Air Sys Used as Source of Breathing Air"
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/264 Forwards IE Info Notice 79-09, "Status of Radioactively Contaminated Resin"
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/265 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident" Licensee action required
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/266 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/267 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/268 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Identified During TMI Incident"
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

7/01/82/269 Forwards IE Bulletin 79-09, "Features of GC Type AA-2 Circuit Breaker in Safety-Related Sys" Licensee action required
JAMES H. A. Spiegel & McElwain 7/01/82 2pp

DOCKETED ITEMS

B. Periodic operating reports & related correspondence

44-38861-100 Forensic analysis of annual aerial photograph of century
catal: Bay Boundary
Lab: D. E. Florida Power & Light Co 7/4/88/11 Bay

G. Senechal et al. / Journal of Great Lakes Research 36 (2010) 78–90

*400130667 Parameter LER 79-001/00L-b
SCHMIDT, A D Florida Power & Light Co TX/04/20 1

-740160Z471 LER 79-007432-8 on 79232; Authorization (act) of RMR 794 not performed caused by misinterpretation of scheduling info reflected from OC to operations personnel named proposed to change date individual
SCOPORAN M A Florida Power & Light Co 7904/20 1c

FRIDWOLD MARINE LER 78-007431-0
Schmidt, A D Florida Power & Light Co 78/04/27 1a

7702995932 LER 79-009/03L-0 on 790320 during reducing shutdown, leak observed from temporary leak-indication line near base of refueling water storage tank. About 25 gallons of water leaked out. Cause undetermined. Investigation in progress. S'HOFFMAN, R. A. Florida Power & Light Co. 79/04/27 1a

7955796094 Forwards LER 79-088/002.-p
BIOGOST, A. D. Florida Power & Light Co 79/08/03 to

-P03501000: LEW 79-00403-0 on PRODAN chemical & vol control sys holds tank overfilled causing vapors through vent line & header, resulting in low internal tank pressure & tank damage caused by erroneous level indication
SIMPSON M.A. Florida Power & Light Co. TROY,AL 360

50528103 forward LEE 79-001/004-0
SOMER-A D Florida Power & Light Co 28/08/08 14

-1905020012 LEW 77-01102L-C on 770110 during preparation for routine startup following refueling shutdown. Condensate storage tank had to be drained. Caused by chloride contamination tank of other unit slipped change in Tank Spec wording proposed SCHOPPMAN, R A Florida Power & Light Co 70/05/00 24

4520428 Forwards LHM 78-012703L-0
SCHWARTZ, A D Florida Power & Light Co. Orlando, FL

7/25/2008 UGR 74-018700-0 on 7/25/08 during startup, steam supply stop valves HDV-3-1424 & HDV-3-1425 leading to turbine drives at auxiliary feedwater pumps failed to open fully caused by damaged torque on valve operator stem nut Not replaced JAMES D W Florida Power & Light Co. Maitland

8506088 Forward LHM 79-01243E,-O
80WIST-A D Florida Power & Light Co. 7900000

Fullly close when turbine was tripped by balance exciter
Cause unknown Valve leaked & operated satisfactorily Valve
performance will be monitored regularly
JAMES D. W. Florida Power & Light Co. Jacksonville

Hearing transcripts on demand/linked content

20140567 Transcript of T90952 Proceeding in Miami-FL, Py 1-132
JAMES E. M. HALL, S. E. FINE, C. H. STANLEY

Copyright © 2006 John Wiley & Sons, Ltd.

Security, medical, emergency & fire protection plans

AMOS & S Pierce Paper & Light Co 79/05/01

Adjunctary correspondence

8300025 Lohmeyer, Raymond M. re: Coverage 790225 Request for
 Series Argonne that request is unlikely to result for
 documents regarding Supporting Documentation Affidavits &
 affidavits of Ove and
 ROBERT M. Lohmeyer, Raymond M. Affidavit & Test
 Affidavit
 Volume 790225
 COLN

7503130170 Forwards Revision to 750309 petition to intervene
ONCAWALE, M P Affiliation Unknown 79/03/19 1p

--790850102 Revision to 790209 petition to intervene re proposed
 need to permit these generator repairs Affidavit, motion for
 production of documents & Certification of Sw. and
 OBCAWGE, re Affiliation Unknown 79/03/10 1999

7509130789 Act receipt of 794329 ltr to Board, all revised pending to interview. 8 Daily attestation for production of documents & entry upon land for crop & other purposes. Requests signed & notarized affidavit from 8 daily. C.D.L.N. 8 (Sgt. Hester & Davis 79/03/23. Two

TS00190793 Answer by still in application to TS00190793 motion by re
Schedules for production of documents Certificate of Use
and
DAVIDER-H A Loewenstein, Neuman, Bels, Newland & Toll Cult. W &
Eliel, Nathan & Bels. 30-073-000 Doc

-7508153799 Response by still seeking denial on basis of unavailability of AP O'Connell's petition to interview witnesses; does not demonstrate standing over other admissible contenders
BRIGGS, H A Louisville, Ky., New York, N.Y., Assisted & Tell CHIT, H A
Shelby, Tenn., D. C. [redacted] [redacted]

7905240479 Forwarding conference to rule on petition of IP-Onceva
will be held on 790502 in Hialeah, FL
SOURCES: S S Abella Hefsey and Licensing Board Panel 10/04/05
2pp

NY0320481 Requests granting W's Onyango petition for hearings &
intervenor status re dwelling repairs
SUVED.L : MEMOGIA,H D ; SMITH,W B Affiliation Unknown PYJON
ltp

98506022 Response to HP Coverage 79014V revised petition to
intervene in preceding Certificate of Env act

985240973 requests NA Coll be included on avc list
C01-B-A. Sign: [unclear] [unclear]

Y052500d Forwards version malignans requesting granting of peti
for hearing & intervention re facility repairs
F05BACHN Affiliation Unknown 29/04/12 One

000000000 Requests granting of HF Encourage petition for hearing
interview in this proceedings
COUSINS, R. WILLIAM - EWING, S Affiliation Unknown P2014219
120p

[illegible]

AS280499 Grants PL Power & Light Co & AMC opportunity to submit
responses to newly submitted petitions of petitioner
HP Damages
EDWARDS & Atomic Safety and Licensing Board Panel 7/10/79

References

00290486 Forward constituent's letter requesting support of
of MF coverage petition for hearing & intervention re steam
generator repair
LDHAW:4 House of Rep 79/04/12 1a

00020100 Forwards R Purcell telegram requesting granting of
of Cuckage petition for hearing & intervention Request
recommendation on appropriate action
LEHMAN:W House of Rep 24/06/10 to

2243854 Requests Comments on correspondence from constituents +
 re Decrease petition to intervene in hearing on proposed
 LBMAW House of Rep 2004000

03240718 Forwards constituent's request that MRC grant HF Oncaya petition for hearing & intervention re decision re...

DOCKETED ITEMS

7905040404 Forwards IE Bulletin 79-05, "Reactive Relays to Soling Major Power Reactor Classified During TMI Incident" C. McELLY, J. P. Region 2, Atlanta; Office of the Director 7/30/81 1p

7905050404 Forwards IE Bulletin 79-05, "Evaluation of RE Type A-2 Circuit Breaker in Safety-Related Area - Licensee action required" C. McELLY, J. P. Region 2, Atlanta; Office of the Director 7/30/81 7p

790505047 ACN Tachist of IE Imp Regs 50-250/79-08 & 50-251/79-08 on 790521-0304 per proprietary info WMBR, R. E. Florida Power & Light Co. 7/30/81 1p

7905050505 Forwards IE Imp Regs 50-250/79-08 & 50-251/79-08 on 790527-0301 No correspondence noted LMBR, R. E. Region 2, Atlanta; Reactor Operations Nuclear Support Branch 7/30/81 2p

7905050508 IE Imp Regs 50-250/79-08 & 50-251/79-08 on 790527-0308 No correspondence noted Major areas of concern regarding action: 1. Main Steam Isolation Valve Failure; 2. IE Isolation & Circulator Failure WMBR, R. E., CAGBELL, F. B. Region 2, Atlanta; Reactor Operations Nuclear Support Branch 7/30/81 2p

7905050504 Forwards response to IE Bulletin 79-07 Note of methods specified are used by AEC in various aspects of safety-related piping Item 2 not applicable to AEC & NRC Vendor indicates that computer error listings are proprietary WMBR, R. E. Florida Power & Light Co. 7/30/81 2p

7905050504 Forwards "Reactor Operator Imp Program" Imp should not now be accepted. Verified general pattern of testing is within practicable limits. Requests permission to return facility to power operation WMBR, R. E. Florida Power & Light Co. 7/30/81 2p

7905050504 "Reactor Operator Imp Program" 4 Florida Power & Light Co. 7/30/81 2p

Periodic operating reports & related correspondence

7905050505 Forwards analysis of annual aerial photograph of cooling canal exit boundary WMBR, R. E. Florida Power & Light Co. 7/30/81 2p

Reportable occurrences, LERs & related correspondence

7905060504 Forwards LER 79-06/05-0 BOROUT, A. O. Florida Power & Light Co. 7/30/81 1p

7905060505 LER 79-06/05-0 on 790502 process radiation monitors R-11 & R-12 were out of spec caused by failure of air purifying filter which supplies monitors. Filter replaced & monitors returned to spec. BOROUT, A. O. Florida Power & Light Co. 7/30/81 1p

7905060507 Forwards LER 79-06/05-0 BOROUT, A. O. Florida Power & Light Co. 7/30/81 1p

7905060507 LER 79-06/05-0 on 790502 process radiation monitors R-11 & R-12 were out of spec caused by failure of air purifying filter which supplies monitors. Filter replaced & monitors returned to spec. BOROUT, A. O. Florida Power & Light Co. 7/30/81 2p

F. Operating license stage documents & correspondence

7905060504 Inform that operational portions of operator qualification must be delayed despite written & operational portions of qualification program is completed by 790510 COLLINS, P. F. Operator Licensing Branch 7/30/81 1p

DOCKET 50-004 RAND-CITING QUATION, UNIT 1

F. Security, medical, emergency & fire protection plans

7905060504 Forwards section of fire protection UCR which requires further UCR review under emergency, air breaking equipment & interior hose stations. HILL, R. E. Brookhaven National Laboratory 7/30/81 2p

7905060504 Forwards modified physical security plan, Revision 5 Plan withheld (ref 590702 7905) LEE, B. Commonwealth Edison Co. 7/30/81 1p

G. Adjudicatory correspondence

7905060508 Notification properly worded concerning re sabotage would be accepted. Contention has been admitted into Duke Power Co. proceedings. Adjudicatory aspects of revised Contention is presented by Duke of IL. GORDON, E. J. Branch 2 7/30/81 2p

J. Insurance & indemnity information

7905060504 Endorsement 99 to NMLB Policy NP-22 GORDON, T. Nuclear Energy Liability Insurance Association 7/30/81 1p

7905070497 Confirms increased liability limit to \$124,000,000 for policies NP-1, NP-2, NP-3, NP-4, NP-5, NP-6, NP-7, NP-8, NP-9, NP-10, NP-11, NP-12, NP-13, NP-14, NP-15, NP-16, NP-17, NP-18, NP-19, NP-20, NP-21, NP-22, NP-23, NP-24, NP-25, NP-26, NP-27, NP-28, NP-29, NP-30, NP-31, NP-32, NP-33, NP-34, NP-35, NP-36, NP-37, NP-38, NP-39, NP-40, NP-41, NP-42, NP-43, NP-44, NP-45, NP-46, NP-47, NP-48, NP-49, NP-50, NP-51, NP-52, NP-53, NP-54, NP-55, NP-56, NP-57, NP-58, NP-59, NP-60, NP-61, NP-62, NP-63, NP-64, NP-65, NP-66, NP-67, NP-68, NP-69, NP-70, NP-71, NP-72, NP-73, NP-74, NP-75, NP-76, NP-77, NP-78, NP-79, NP-80, NP-81, NP-82, NP-83, NP-84, NP-85, NP-86, NP-87, NP-88, NP-89, NP-90, NP-91, NP-92, NP-93, NP-94, NP-95, NP-96, NP-97, NP-98, NP-99, NP-100, NP-101, NP-102, NP-103, NP-104, NP-105, NP-106, NP-107, NP-108, NP-109, NP-110, NP-111, NP-112, NP-113, NP-114, NP-115, NP-116, NP-117, NP-118, NP-119, NP-120, NP-121, NP-122, NP-123, NP-124, NP-125, NP-126, NP-127, NP-128, NP-129, NP-130, NP-131, NP-132, NP-133, NP-134, NP-135, NP-136, NP-137, NP-138, NP-139, NP-140, NP-141, NP-142, NP-143, NP-144, NP-145, NP-146, NP-147, NP-148, NP-149, NP-150, NP-151, NP-152, NP-153, NP-154, NP-155, NP-156, NP-157, NP-158, NP-159, NP-160, NP-161, NP-162, NP-163, NP-164, NP-165, NP-166, NP-167, NP-168, NP-169, NP-170, NP-171, NP-172, NP-173, NP-174, NP-175, NP-176, NP-177, NP-178, NP-179, NP-180, NP-181, NP-182, NP-183, NP-184, NP-185, NP-186, NP-187, NP-188, NP-189, NP-190, NP-191, NP-192, NP-193, NP-194, NP-195, NP-196, NP-197, NP-198, NP-199, NP-200, NP-201, NP-202, NP-203, NP-204, NP-205, NP-206, NP-207, NP-208, NP-209, NP-210, NP-211, NP-212, NP-213, NP-214, NP-215, NP-216, NP-217, NP-218, NP-219, NP-220, NP-221, NP-222, NP-223, NP-224, NP-225, NP-226, NP-227, NP-228, NP-229, NP-230, NP-231, NP-232, NP-233, NP-234, NP-235, NP-236, NP-237, NP-238, NP-239, NP-240, NP-241, NP-242, NP-243, NP-244, NP-245, NP-246, NP-247, NP-248, NP-249, NP-250, NP-251, NP-252, NP-253, NP-254, NP-255, NP-256, NP-257, NP-258, NP-259, NP-260, NP-261, NP-262, NP-263, NP-264, NP-265, NP-266, NP-267, NP-268, NP-269, NP-270, NP-271, NP-272, NP-273, NP-274, NP-275, NP-276, NP-277, NP-278, NP-279, NP-280, NP-281, NP-282, NP-283, NP-284, NP-285, NP-286, NP-287, NP-288, NP-289, NP-290, NP-291, NP-292, NP-293, NP-294, NP-295, NP-296, NP-297, NP-298, NP-299, NP-300, NP-301, NP-302, NP-303, NP-304, NP-305, NP-306, NP-307, NP-308, NP-309, NP-310, NP-311, NP-312, NP-313, NP-314, NP-315, NP-316, NP-317, NP-318, NP-319, NP-320, NP-321, NP-322, NP-323, NP-324, NP-325, NP-326, NP-327, NP-328, NP-329, NP-330, NP-331, NP-332, NP-333, NP-334, NP-335, NP-336, NP-337, NP-338, NP-339, NP-340, NP-341, NP-342, NP-343, NP-344, NP-345, NP-346, NP-347, NP-348, NP-349, NP-350, NP-351, NP-352, NP-353, NP-354, NP-355, NP-356, NP-357, NP-358, NP-359, NP-360, NP-361, NP-362, NP-363, NP-364, NP-365, NP-366, NP-367, NP-368, NP-369, NP-370, NP-371, NP-372, NP-373, NP-374, NP-375, NP-376, NP-377, NP-378, NP-379, NP-380, NP-381, NP-382, NP-383, NP-384, NP-385, NP-386, NP-387, NP-388, NP-389, NP-390, NP-391, NP-392, NP-393, NP-394, NP-395, NP-396, NP-397, NP-398, NP-399, NP-400, NP-401, NP-402, NP-403, NP-404, NP-405, NP-406, NP-407, NP-408, NP-409, NP-410, NP-411, NP-412, NP-413, NP-414, NP-415, NP-416, NP-417, NP-418, NP-419, NP-420, NP-421, NP-422, NP-423, NP-424, NP-425, NP-426, NP-427, NP-428, NP-429, NP-430, NP-431, NP-432, NP-433, NP-434, NP-435, NP-436, NP-437, NP-438, NP-439, NP-440, NP-441, NP-442, NP-443, NP-444, NP-445, NP-446, NP-447, NP-448, NP-449, NP-450, NP-451, NP-452, NP-453, NP-454, NP-455, NP-456, NP-457, NP-458, NP-459, NP-460, NP-461, NP-462, NP-463, NP-464, NP-465, NP-466, NP-467, NP-468, NP-469, NP-470, NP-471, NP-472, NP-473, NP-474, NP-475, NP-476, NP-477, NP-478, NP-479, NP-480, NP-481, NP-482, NP-483, NP-484, NP-485, NP-486, NP-487, NP-488, NP-489, NP-490, NP-491, NP-492, NP-493, NP-494, NP-495, NP-496, NP-497, NP-498, NP-499, NP-500, NP-501, NP-502, NP-503, NP-504, NP-505, NP-506, NP-507, NP-508, NP-509, NP-510, NP-511, NP-512, NP-513, NP-514, NP-515, NP-516, NP-517, NP-518, NP-519, NP-520, NP-521, NP-522, NP-523, NP-524, NP-525, NP-526, NP-527, NP-528, NP-529, NP-530, NP-531, NP-532, NP-533, NP-534, NP-535, NP-536, NP-537, NP-538, NP-539, NP-540, NP-541, NP-542, NP-543, NP-544, NP-545, NP-546, NP-547, NP-548, NP-549, NP-550, NP-551, NP-552, NP-553, NP-554, NP-555, NP-556, NP-557, NP-558, NP-559, NP-560, NP-561, NP-562, NP-563, NP-564, NP-565, NP-566, NP-567, NP-568, NP-569, NP-570, NP-571, NP-572, NP-573, NP-574, NP-575, NP-576, NP-577, NP-578, NP-579, NP-580, NP-581, NP-582, NP-583, NP-584, NP-585, NP-586, NP-587, NP-588, NP-589, NP-590, NP-591, NP-592, NP-593, NP-594, NP-595, NP-596, NP-597, NP-598, NP-599, NP-600, NP-601, NP-602, NP-603, NP-604, NP-605, NP-606, NP-607, NP-608, NP-609, NP-610, NP-611, NP-612, NP-613, NP-614, NP-615, NP-616, NP-617, NP-618, NP-619, NP-620, NP-621, NP-622, NP-623, NP-624, NP-625, NP-626, NP-627, NP-628, NP-629, NP-630, NP-631, NP-632, NP-633, NP-634, NP-635, NP-636, NP-637, NP-638, NP-639, NP-640, NP-641, NP-642, NP-643, NP-644, NP-645, NP-646, NP-647, NP-648, NP-649, NP-650, NP-651, NP-652, NP-653, NP-654, NP-655, NP-656, NP-657, NP-658, NP-659, NP-660, NP-661, NP-662, NP-663, NP-664, NP-665, NP-666, NP-667, NP-668, NP-669, NP-670, NP-671, NP-672, NP-673, NP-674, NP-675, NP-676, NP-677, NP-678, NP-679, NP-680, NP-681, NP-682, NP-683, NP-684, NP-685, NP-686, NP-687, NP-688, NP-689, NP-690, NP-691, NP-692, NP-693, NP-694, NP-695, NP-696, NP-697, NP-698, NP-699, NP-700, NP-701, NP-702, NP-703, NP-704, NP-705, NP-706, NP-707, NP-708, NP-709, NP-710, NP-711, NP-712, NP-713, NP-714, NP-715, NP-716, NP-717, NP-718, NP-719, NP-720, NP-721, NP-722, NP-723, NP-724, NP-725, NP-726, NP-727, NP-728, NP-729, NP-730, NP-731, NP-732, NP-733, NP-734, NP-735, NP-736, NP-737, NP-738, NP-739, NP-740, NP-741, NP-742, NP-743, NP-744, NP-745, NP-746, NP-747, NP-748, NP-749, NP-750, NP-751, NP-752, NP-753, NP-754, NP-755, NP-756, NP-757, NP-758, NP-759, NP-760, NP-761, NP-762, NP-763, NP-764, NP-765, NP-766, NP-767, NP-768, NP-769, NP-770, NP-771, NP-772, NP-773, NP-774, NP-775, NP-776, NP-777, NP-778, NP-779, NP-780, NP-781, NP-782, NP-783, NP-784, NP-785, NP-786, NP-787, NP-788, NP-789, NP-790, NP-791, NP-792, NP-793, NP-794, NP-795, NP-796, NP-797, NP-798, NP-799, NP-800, NP-801, NP-802, NP-803, NP-804, NP-805, NP-806, NP-807, NP-808, NP-809, NP-810, NP-811, NP-812, NP-813, NP-814, NP-815, NP-816, NP-817, NP-818, NP-819, NP-820, NP-821, NP-822, NP-823, NP-824, NP-825, NP-826, NP-827, NP-828, NP-829, NP-830, NP-831, NP-832, NP-833, NP-834, NP-835, NP-836, NP-837, NP-838, NP-839, NP-840, NP-841, NP-842, NP-843, NP-844, NP-845, NP-846, NP-847, NP-848, NP-849, NP-850, NP-851, NP-852, NP-853, NP-854, NP-855, NP-856, NP-857, NP-858, NP-859, NP-860, NP-861, NP-862, NP-863, NP-864, NP-865, NP-866, NP-867, NP-868, NP-869, NP-870, NP-871, NP-872, NP-873, NP-874, NP-875, NP-876, NP-877, NP-878, NP-879, NP-880, NP-881, NP-882, NP-883, NP-884, NP-885, NP-886, NP-887, NP-888, NP-889, NP-890, NP-891, NP-892, NP-893, NP-894, NP-895, NP-896, NP-897, NP-898, NP-899, NP-900, NP-901, NP-902, NP-903, NP-904, NP-905, NP-906, NP-907, NP-908, NP-909, NP-910, NP-911, NP-912, NP-913, NP-914, NP-915, NP-916, NP-917, NP-918, NP-919, NP-920, NP-921, NP-922, NP-923, NP-924, NP-925, NP-926, NP-927, NP-928, NP-929, NP-930, NP-931, NP-932, NP-933, NP-934, NP-935, NP-936, NP-937, NP-938, NP-939, NP-940, NP-941, NP-942, NP-943, NP-944, NP-945, NP-946, NP-947, NP-948, NP-949, NP-950, NP-951, NP-952, NP-953, NP-954, NP-955, NP-956, NP-957, NP-958, NP-959, NP-960, NP-961, NP-962, NP-963, NP-964, NP-965, NP-966, NP-967, NP-968, NP-969, NP-970, NP-971, NP-972, NP-973, NP-974, NP-975, NP-976, NP-977, NP-978, NP-979, NP-980, NP-981, NP-982, NP-983, NP-984, NP-985, NP-986, NP-987, NP-988, NP-989, NP-990, NP-991, NP-992, NP-993, NP-994, NP-995, NP-996, NP-997, NP-998, NP-999, NP-1000, NP-1001, NP-1002, NP-1003, NP-1004, NP-1005, NP-1006, NP-1007, NP-1008, NP-1009, NP-1010, NP-1011, NP-1012, NP-1013, NP-1014, NP-1015, NP-1016, NP-1017, NP-1018, NP-1019, NP-1020, NP-1021, NP-1022, NP-1023, NP-1024, NP-1025, NP-1026, NP-1027, NP-1028, NP-1029, NP-1030, NP-1031, NP-1032, NP-1033, NP-1034, NP-1035, NP-1036, NP-1037, NP-1038, NP-1039, NP-1040, NP-1041, NP-1042, NP-1043, NP-1044, NP-1045, NP-1046, NP-1047, NP-1048, NP-1049, NP-1050, NP-1051, NP-1052, NP-1053, NP-1054, NP-1055, NP-1056, NP-1057, NP-1058, NP-1059, NP-1060, NP-1061, NP-1062, NP-1063, NP-1064, NP-1065, NP-1066, NP-1067, NP-1068, NP-1069, NP-1070, NP-1071, NP-1072, NP-1073, NP-1074, NP-1075, NP-1076, NP-1077, NP-1078, NP-1079, NP-1080, NP-1081, NP-1082, NP-1083, NP-1084, NP-1085, NP-1086, NP-1087, NP-1088, NP-1089, NP-1090, NP-1091, NP-1092, NP-1093, NP-1094, NP-1095, NP-1096, NP-1097, NP-1098, NP-1099, NP-1100, NP-1101, NP-1102, NP-1103, NP-1104, NP-1105, NP-1106, NP-1107, NP-1108, NP-1109, NP-1110, NP-1111, NP-1112, NP-1113, NP-1114, NP-1115, NP-1116, NP-1117, NP-1118, NP-1119, NP-1120, NP-1121, NP-1122, NP-1123, NP-1124, NP-1125, NP-1126, NP-1127, NP-1128, NP-1129, NP-1130, NP-1131, NP-1132, NP-1133, NP-1134, NP-1135, NP-1136, NP-1137, NP-1138, NP-1139, NP-1140, NP-1141, NP-1142, NP-1143, NP-1144, NP-1145, NP-1146, NP-1147, NP-1148, NP-1149, NP-1150, NP-1151, NP-1152, NP-1153, NP-1154, NP-1155, NP-1156, NP-1157, NP-1158, NP-1159, NP-1160, NP-1161, NP-1162, NP-1163, NP-1164, NP-1165, NP-1166, NP-1167, NP-1168, NP-1169, NP-1170, NP-1171, NP-1172, NP-1173, NP-1174, NP-1175, NP-1176, NP-1177, NP-1178, NP-1179, NP-1180, NP-1181, NP-1182, NP-1183, NP-1184, NP-1185, NP-1186, NP-1187, NP-1188, NP-1189, NP-1190, NP-1191, NP-1192, NP-1193, NP-1194, NP-1195, NP-1196, NP-1197, NP-1198, NP-1199, NP-1200, NP-1201, NP-1202, NP-1203, NP-1204, NP-1205, NP-1206, NP-1207, NP-1208, NP-1209, NP-1210, NP-1211, NP-1212, NP-1213, NP-1214, NP-1215, NP-1216, NP-1217, NP-1218, NP-1219, NP-1220, NP-1221, NP-1222, NP-1223, NP-1224, NP-1225, NP-1226, NP-1227, NP-1228, NP-1229, NP-1230, NP-1231, NP-1232, NP-1233, NP-1234, NP-1235, NP-1236, NP-1237, NP-1238, NP-1239, NP-1240, NP-1241, NP-1242, NP-1243, NP-1244, NP-1245, NP-1246, NP-1247, NP-1248, NP-1249, NP-1250, NP-1251, NP-1252, NP-1253, NP-1254, NP-1255, NP-1256, NP-1257, NP-1258, NP-1259, NP-1260, NP-1261, NP-1262, NP-1263, NP-1264, NP-1265, NP-1266, NP-1267, NP-1268, NP-1269, NP-1270, NP-1271, NP-1272, NP-1273, NP-1274, NP-1275, NP-1276, NP-1277, NP-1278, NP-1279, NP-1280, NP-1281, NP-1282, NP-1283, NP-1284, NP-1285, NP-1286, NP-1287, NP-1288, NP-1289, NP-1290, NP-1291, NP-1292, NP-1293, NP-1294, NP-1295, NP-1296, NP-1297, NP-1298, NP-1299, NP-1300, NP-1301, NP-1302, NP-1303, NP-1304, NP-1305, NP-1306, NP-1307, NP-1308, NP-1309, NP-1310, NP-1311, NP-1312, NP-1313, NP-1314, NP-1315, NP-1316, NP-1317, NP-1318, NP-1319, NP-1320, NP-1321, NP-1322, NP-1323, NP-1324, NP-1325, NP-1326, NP-1327, NP-1328, NP-1329, NP-1330, NP-1331, NP-1332, NP-1333, NP-1334, NP-1335, NP-1336, NP-1337, NP-1338, NP-1339, NP-1340, NP-1341, NP-1342, NP-1343, NP-1344, NP-1345, NP-1346, NP-1347, NP-1348, NP-1349, NP-1350, NP-1351, NP-1352, NP-1353, NP-1354, NP-1355, NP-1356, NP-1357, NP-1358, NP-1359, NP-1360, NP-1361, NP-1362, NP-1363, NP-1364, NP-1365, NP-1366, NP-1367, NP-1368, NP-1369, NP-1370, NP-1371, NP-1372, NP-1373, NP-1374, NP-1375, NP-1376, NP-1377, NP-1378, NP-1379, NP-1380, NP-1381, NP-1382, NP-1383, NP-1384, NP-1385, NP-1386, NP-1387, NP-1388, NP-1389, NP-1390, NP-1391, NP-1392, NP-1393, NP-1394, NP-1395, NP-1396, NP-1397, NP-1398, NP-1399, NP-1400, NP-1401, NP-1402, NP-1403, NP-1404, NP-1405, NP-1406, NP-1407, NP-1408, NP-1409, NP-1410, NP-1411, NP-1412, NP-1413, NP-1414, NP-1415, NP-1416, NP-1417, NP-1418, NP-1419, NP-1420, NP-1421, NP-1422, NP-1423, NP-1424, NP-1425, NP-1426, NP-1427, NP-1428, NP-1429, NP-1430, NP-1431, NP-1432, NP-1433, NP-1434, NP-1435, NP-1436, NP-1437, NP-1438, NP-1439, NP-1440, NP-1441, NP-1442, NP-1443, NP-1444, NP-1445, NP-1446, NP-1447, NP-1448, NP-1449, NP-1450, NP-1451, NP-1452, NP-1453, NP-1454, NP-1455, NP-1456, NP-1457, NP-1458, NP-1459, NP-1460, NP-1461, NP-1462, NP-1463, NP-1464, NP-1465, NP-1466, NP-1467, NP-1468, NP-1469, NP-1470, NP-1471, NP-1472, NP-1473, NP-1474, NP-1475, NP-1476, NP-1477, NP-1478, NP-1479, NP-1480, NP-1481, NP-1482, NP-1483, NP-1484, NP-1485, NP-1486, NP-1487, NP-1488, NP-1489, NP-1490, NP-1491, NP-1492, NP-1493, NP-1494, NP-1495, NP-1496, NP-1497, NP-1498, NP-1499, NP-1500, NP-1501, NP-1502, NP-1503, NP-1504, NP-1505, NP-1506, NP-1507, NP-1508, NP-1509, NP-1510, NP-1511, NP-1512, NP-1513, NP-1514, NP-1515, NP-1516, NP-1517, NP-1518, NP-1519, NP-1520, NP-1521, NP-1522, NP-1523, NP-1524, NP-1525, NP-1526, NP-1527, NP-1528, NP-1529, NP-1530, NP-1531, NP-1532, NP-1533, NP-1534, NP-1535, NP-1536, NP-1537, NP-1538, NP-1539, NP-1540, NP-1541, NP-1542, NP-1543, NP-1544, NP-1545, NP-1546, NP-1547, NP-1548, NP-1549, NP-1550, NP-1551, NP-1552, NP-1553, NP-1554, NP-1555, NP-1556, NP-1557, NP-1558, NP-1559, NP-1560, NP-1561, NP-1562, NP-1563, NP-1564, NP-1565, NP-1566, NP-1567, NP-1568, NP-1569, NP-1570, NP-1571, NP-1572, NP-1573, NP-1574, NP-1575, NP-1576, NP-1577, NP-1578, NP-1579,

DOCKETED ITEMS

39

- 790510014 Forwards current schedule for implementation of Herb I containment long-term mode. Discusses constraints inhibiting shorter time frame completion including sig load requirements & current fuel cycles.
REED, C Commonwealth Edison Co 79/05/11 3pp
- 790510057 Requests correction of error discovered in 790423 ltr re repacting of Nuclear Assurance Corp NAC-1 truck cab used in spent fuel transfer. Cash has capacity of two DRB assemblies.
JAMES, R F Commonwealth Edison Co 79/05/11 1p
- 790505091 Forwards current licensing open items status ltr.
REED, C Commonwealth Edison Co 79/05/10 3pp
- 790505093 Forwards "Quad-Cities Nuclear Power Station Unit 1-Cycle 5 Startup Test Results"
JAMES, R F Commonwealth Edison Co 79/05/01 1p
- 790520036 "Quad-Cities Nuclear Power Station Unit 1-Reload 4-Cycle 5 Startup Test Results"
" Commonwealth Edison Co. 79/05/21 10pp
- B Inspection reports, IE Bulletins & correspondence
- 790505042 Forwards response to IE Bulletin 79-12 & 79-12A: "Atypical Weld Heat in Reactor Pressure Vessel Noles"
REED, C Commonwealth Edison Co 79/05/02 10pp
- 790510035 Forwards IE Info Notice 79-06: "Stress Analysis of Borehole-Related Piping"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/23 1p
- 790505070 Forwards IE Info Notice 79-07: "Rupture of Radiactive Tank"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/26 1p
- 790505075 Forwards IE Info Notice 79-08: "Interconnection of Contaminated Gas W/Brk Air Gas Used as Source of Breathing Air"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/28 1p
- 790510091 Forwards IE Info Notice 79-09: "Spill of Radioactively Contaminated Resin"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/30 1p
- 790505080 Response to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools. Plants inspected no pipe found.
SFLD, C Commonwealth Edison Co 79/04/12 3pp
- 790510059 Forwards IE Bulletin 79-06A: "Review of Operational Errors & Day Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p
- 790505034 Forwards IE Bulletin 79-08A: "Review of Operational Errors & Day Misalignments Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p
- 790504052 Forwards IE Bulletin 79-06: "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14 1p
- 790505066 Forwards IE Bulletin 79-09: "Failures of SE Type MW-2 Circuit Breaker in Safety-Related Gas - Licensee action required."
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/17 1p
- 790504042 Forwards IE Bulletin 79-05B: "Nuclear Incident at TMI-Bugby"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/21
- 790504020 Forwards ACRB recommendations re TMI incident, presented on 790417
FRANKE, R F ACRB - Advisory Committee on Reactor Safeguards 79/04/18 1p
- 790504022 In response to IBC 790408 ltr, states all ACRB 790417 recommendations apply to all BWRs, but were not intended to require immediate changes. Plant mode should be made after study of effects on overall safety. TMI excluded.
CARSON, R X ACRB - Advisory Committee on Reactor Safeguards 79/04/20 2pp
- 790504032 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping. Response indicates method of intramural combination has little effect on pipe stresses & equipment support loads.
REED, C Commonwealth Edison Co 79/04/24 3pp
- 790510048 Forwards response to IE Bulletin 79-05A, Revision 1 re BWR events identified during TMI-2. Until has formed task force to review BWR events & recommend corrective action as required.
REED, C Commonwealth Edison Co 79/04/27 20pp
- 790505048 Response to IE Bulletin 79-04 Re 3.4 or 4-inch weld joint check valves are in use at Dresden & Quad-Cities. Review of Zion has identified use of valves in some piping as but review is incomplete. Will rep later.
REED, C Commonwealth Edison Co 79/05/01 2pp
- 790510048 Forwards IE Circular 79-07: "Unexpected Speed Increase of Reactor Recirculation Water Generator Set Resulting in Reactor Power Increase"
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/02 1p
- R Periodic operating reports & related correspondence
- 790510032 Forwards monthly operating rep for Apr 1979
KALLIVANAKIS, M Commonwealth Edison Co 79/05/17 1p
- 790510038 Monthly operating rep for Apr 1979
HARRIS, D Commonwealth Edison Co 79/05/17 20pp
- G Reportable occurrences, LERs & related correspondence
- 790510024 Forwards LER 79-017/02-3
KALLIVANAKIS, M Commonwealth Edison Co 79/04/26 1p
- 790510027 LER 79-017/02-3 on 790416 leak between RHR water & evc water side of heat exchanger. Caused by crack in pipe to flange weld of helium venting pipe repaired.
HARRIS, D J Commonwealth Edison Co 79/04/26 1p
- 790504039 Informs that release rate of radionuclides & radioactive particulate well within limits greater than eight days week & 52 times higher than Tech Spec design objective for first quarter 1979. Caused by steam leaks & "spilling"
KALLIVANAKIS, M Commonwealth Edison Co 79/04/30 2pp
- 790504057 Forwards LER 79-018/017-0
KALLIVANAKIS, M Commonwealth Edison Co 79/05/01 1p
- 79

7905010277 Forwards 18 Bulletin 79-046, "Review of Operational Errors & Risk Assessments Identified During TMI Incident" Licensee
HPPFLER, J. G Region 3, Chicago, Office of the Director 79/04/14
1p

7905010320 Forwards 18 Bulletin 79-046, "Review of Operational Errors & Risk Assessments Identified During TMI Incident" Licensee
HPPFLER, J. G Region 3, Chicago, Office of the Director 79/04/14
1p

7905010348 Forwards 18 Bulletin 79-046, "Events Relevant to Rolling Motor Power Reactors Identified During TMI Incident" Licensee
HPPFLER, J. G Region 3, Chicago, Office of the Director 79/04/14
1p

7905010348 Forwards 18 Bulletin 79-046, "Events Relevant to Rolling Motor Power Reactors Identified During TMI Incident" Licensee
HPPFLER, J. G Region 3, Chicago, Office of the Director 79/04/14
1p

7905010320 Forwards 18 Bulletin 79-046, "Failures of 600 Type M-2 Circuit Breaker in Safety-Related Sys." Licensee action required
HPPFLER, J. G Region 3, Chicago, Office of the Director 79/04/17
1p

7905010348 Forwards 18 Bulletin 79-046, "Nuclear Incident at TMI-Dagbl" Licensee
HPPFLER, J. G Region 3, Chicago, Office of the Director 79/04/21
1p

7905010335 Responds to 790329 request to allow until to combine reviews of TMI-1 & TMI-2 & systematic evaluation program Topic 211-2 A Since licensee involves safety issues, NRC refuses to extend time for review
HPPFLER, J. G Region 3, Chicago, Office of the Director 79/04/26
1p

7905010301 Responds to 18 Bulletin 79-046 re TMI errors Conditions & events which led to TMI Incident were reviewed w/employees
HPPFLER, J. G Consumers Power Co 79/04/27 10pp

7905010348 Responds to 18 Bulletin 79-046 per 790501 discussion w/HJ
HPPFLER, J. G Region 3, Chicago, Office of the Director 79/05/03 3pp

8 Periodic operating reports & related correspondence

7905010314 Forwards monthly operating report for Apr 1979
ADMMS, M. E Consumers Power Co 79/05/07 1p

--7905010314 Monthly operating report for Apr 1979
ADMMS, M. E Consumers Power Co 79/05/07 3pp

9 Repeatable occurrences, LERs & related correspondence

7905010388 Forwards LER 79-016/02L-0
HPPFLER, J. G Consumers Power Co 79/04/30 1p

--7905010407 LER 79-016/02L-0 on 790502 diesel generator output breaker has potential to incite open. Caused by failure of contact as shutdown sequence to operate sequencer repaired
Consumers Power Co 79/04/30 1p

7905010337 Forwards LER 79-017/02L-0
HPPFLER, J. G Consumers Power Co 79/05/04 1p

--7905010337 LER 79-017/02L-0 on 790404 while taking battery voltage readings, two cells in station battery 2 burst due to explosion of hydrogen inside cells. Battery taken out of use. Two replacement cells ordered
Consumers Power Co 79/05/06 1p

7905010349 Forwards LER 79-008/02L-1
HPPFLER, J. G Consumers Power Co 79/05/07 1p

--7905010320 LER 79-008/02L-1 on 790320 design review indicated butterfly valves may not close under accident conditions. Caused by valve purchase specs which did not include requirements for closing against pressure
Consumers Power Co 79/05/07 1p

7905010328 Forwards LER 79-018/02L-0
HPPFLER, J. G Consumers Power Co 79/05/07 1p

--7905010299 LER 79-018/02L-0 on 790301 reactor made critical w/o conducting rise test of lines. Caused by misinterpretation of Tech Spec Personnel instructed to exercise care when reviewing operability requirements
Consumers Power Co 79/05/07 1p

7905010518 Forwards LER 79-019/02L-0
HPPFLER, J. G Consumers Power Co 79/05/10 1p

--7905010408 LER 79-019/02L-0 on 790301 temp drained to auxiliary bldg floor drains through test restriction located between containment bldg isolation valves. Caused by communication failure. Corrective action still being evaluated
Consumers Power Co 79/05/10 1p

7905010329 Forwards LER 79-020/01T-0
HPPFLER, J. G Consumers Power Co 79/05/15 1p

--7905010329 LER 79-020/01T-0 on 790301 restraints for piping between power conversion & safety injection located between containment bldg isolation valves. Caused by program error used by consultant to determine hanger placement
Consumers Power Co 79/05/15 1p

7905010340 Forwards LER 79-013/01L-1
HPPFLER, J. G Consumers Power Co 79/05/15 1p

--7905010340 LER 79-013/01L-1 on 790327 level in T-02C safety injection tank decreased while draining. D tank to permit increase in level concentration. Caused by seal leakage CV 3054 drain valve will be repaired during next refueling outage
Consumers Power Co 79/05/15 1p

T Hearing transcripts on non-antitrust matters

7905010330 Transcript of 790504 meeting in St. Joseph, HI Pg 1-17
BCHENEFER, C. C. LIVINGSTON, B. Atomic Safety and Licensing Board Panel 79/05/07 17pp

DOCKET 80-239 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

7905010404 Forwards Amend 12 to Indemnity Agreement 8-92 per 100FL140
J. Insurance & Indemnity Group 79/05/01 3pp

7905010390 Forwards Endorsement 47 to ANI Policy M-100
FIDLER, J. Marsh & McLennan, R. B. Marsh Nuclear Consultants, Inc. Div 79/05/03 3pp

7905010394 Forwards Endorsement 48 to ANI Policy M-100
FIDLER, J. Marsh & McLennan, R. B. Marsh Nuclear Consultants, Inc. Div 79/05/03 3pp

K Utility Final Safety Analysis Report (FSAR) & amendments

7905010304 Forwards Amend 48 to FSAR
GILLILAND, J. E. Tennessee Valley Authority 79/05/06 2pp

--7905010301 Amend 48 to FSAR w/overlaid drawings
Tennessee Valley Authority 79/05/06 160pp

P. Operating license stage documents & correspondence

7905010323 Ack receipt of Class II Fee & application for amend to Licensee PFR-33, PFR-32 & PFR-35 Requests payment of add'l fee.
MILLER, W. D. License Fee Management Branch 79/04/04 1p

7905010177 Rubens schedule for torus work in response to NRC 790312 1hr to B. Harris
GILLILAND, J. E. Tennessee Valley Authority 79/05/04 3pp

7905010391 Forwards "Summary Rept. Refueling Test Program, Cycle 3"
GILLILAND, J. E. Tennessee Valley Authority 79/05/07 1p

--7905010391 "Summary Rept. Refueling Test Program, Cycle 3"
Tennessee Valley Authority 79/05/07 3pp

7903020044 Notification of 790323 meeting until in Chattanooga, TN to discuss HRC presentation on status of facility vital area conformity analysis. Discussion will cover 10/29/79 info & will be closed to public.
CLARK, R. A. Reactor Safeguards Licensing Branch 79/03/08 1p

7903020045 Forward summary of EDC Nuclear, Inc. resolution/documentation of safety planning effort to be avoided in terms of PSED piping analysis computer program from JMC-011 1979. Review & recommendations included all work through Dec 1979.
DRENNAN, L. EDC Nuclear, Inc. 79/03/22 2pp

7903020046 Forward EDC Nuclear, Inc. list of BMS & piping systems which could have been impacted by deficient computer program. EDC has no record of materials for Cooper piping system.
STODOLSKY, M. General Electric Co. Nuclear Energy Products Div 79/01/28 10pp

0 Inspection reports, IE Bulletins & correspondence

7903020047 Forward IE Insp Repts 90-299/79-05, 90-263/79-04 & 90-294/79-04 on 790302-0302 No noncompliance noted.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/22 2pp

7903020048 IE Insp Repts 90-299/79-04, 90-263/79-04 & 90-294/79-04 on 790302-0302 No noncompliance noted. Major areas inspected plant operations, refueling & restart of Unit 1, spent fuel & liquid radwaste processing.
DALLMAN, R. P. Region 2, Atlanta, Office of the Director
DANCE, W. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/19 2pp

7903020049 Forward IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping".
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/22 2pp

7903020050 Forward IE Insp Repts 90-299/79-05, 90-263/79-05 & 90-294/79-05 on 790302-0302 No noncompliance noted.
LEHR, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/22 2pp

7903020051 IE Insp Repts 90-294/79-05, 90-263/79-05 & 90-294/79-05 on 790302-0302 No noncompliance noted. Major areas inspected reportable noncompliance containment leak rate testing, IE circulars & bulletins.
PRICE, D. B. Region 2, Atlanta, Office of the Director
DANCE, W. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/22 4pp

7903020052 Forward IE Info Notice 79-06, "Interconnection of Contaminated Dry or Wet Air Gas Used as Source of Breathing Air".
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/22 2pp

7903020053 Forward IE Info Notice 79-06, "Bill of Radiologically Contaminated Resin".
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/22 2pp

7903020054 Response to IE Bulletin 79-03. No evidence that any stainless steel pipe mfg by Thompson-Walsh & Engineering Co. was used in any BMS Class 1, 2 or 3 safety-related systems.
GILLILAND, J. E. Tennessee Valley Authority 79/04/12 1p

7903020055 Forward IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping".
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

7903020056 Forward IE Bulletin 79-08, "Review of Operational Errors & System Malfunctions Identified During TMI Incident".
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

7903020057 Forward IE Bulletin 79-09, "Stress Analysis to BMS Identified During TMI Incident." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

7903020058 Forward IE Bulletin 79-09, "Failure of BMS Type AA-2 Circuit Breaker in Safety-Related System." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17 2pp

7903020059 Forward IE Bulletin 79-06, Revision 8, "Review of Operational Errors & System Malfunctions Identified During TMI Incident".
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/18 3pp

7903020060 Forward response to item 7 b of IE Insp Repts 90-299/79-05, 90-263/79-04 & 90-294/79-04 re deterioration of Bunsen burner. In ASSE statement, as follows: IE Bulletin 79-16.
GILLILAND, J. E. Tennessee Valley Authority 79/04/20 3pp

7903020061 Forward response to IE Bulletin 79-08. Plant superintendent will present review of TMI incident to all managers & supervisors. Organizational responsibility containment isolation design & procedures have been reviewed.
GILLILAND, J. E. Tennessee Valley Authority 79/04/20 10pp

7903020062 Ack receipt of 790423 list informing HRC of steps taken to correct violations noted in IE Insp Repts 90-299/79-07, 90-263/79-07 & 90-294/79-07.
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30 2pp

7903020063 Response to HRC 790326 for re violations noted in IE Insp Repts 90-299/79-07, 90-263/79-07 & 90-294/79-07. Corrective actions active radwaste bldg properly posted as radioactive area.
GILLILAND, J. E. Tennessee Valley Authority 79/04/20 4pp

7903020064 Forward IE Insp Repts 90-299/79-07, 90-263/79-07 & 90-294/79-07 on 790302-0302 & notice of violation.
BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/30 3pp

7903020065 Notice of violations from Insp on 790326-0302.
Region 2, Atlanta, Office of the Director 79/03/26 2pp

7903020066 IE Insp Repts 90-299/79-07, 90-263/79-07 & 90-294/79-07 on 790302-0302 Noncompliance noted. Failure to post radioactive area label containers of radioactive material & barricade high radiation area.
JACKSON, L. L. Region 2, Atlanta, Office of the Director
DANCE, W. C. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp

7903020067 IE Insp Repts 90-299/79-07, 90-263/79-07 & 90-294/79-07 on 790302-0302 Noncompliance noted. Failure to post radioactive area label containers of radioactive material & barricade high radiation area.
JACKSON, L. L. Region 2, Atlanta, Office of the Director 79/03/29 2pp

7903020068 Forward responses to IE Bulletin 79-08 re incorrect valve check valve weights. Corrected valve weights do not create any overbreathing in class, except on supports. A441 info will be provided by 790331.
GILLILAND, J. E. Tennessee Valley Authority 79/03/01 4pp

0 Periodic operating reports & related correspondence

7903020069 Forward "Environ Radioactivity Levels, Annual Rept 1979".
GILLILAND, J. E. Tennessee Valley Authority 79/03/27 1p

7903020070 Forward "Environ Radioactivity Levels, Annual Rept 1978".
Tennessee Valley Authority 79-79-002 79/04/27 30pp

7903020071 Forward "Fish Impingement Rept" for first quarter 1979.
GILLILAND, J. E. Tennessee Valley Authority 79/03/31 2pp

7903020072 Forward "Fish Impingement Rept" for first quarter 1979.
Tennessee Valley Authority 79/03/31 14pp

7903020073 Forward monthly operating report for Apr 1979.
DANCE, W. C. Tennessee Valley Authority 79/04/30 10pp

0 Repeatable occurrences, LERs & related correspondence

7903020074 Forward LER 79-007/03L-0 on 790404. One zone of initiation logic fan spreader room sprinkler eye found inoperative. Caused by failure of contact on auxiliary relay to make up relay replaced.
Tennessee Valley Authority 79/03/28 2pp

7903020075 Forward LER 79-007/03L-0 on 790404. One zone of initiation logic fan spreader room sprinkler eye found inoperative. Caused by failure of contact on auxiliary relay to make up relay replaced.
Tennessee Valley Authority 79/03/28 2pp

DOCKETED ITEMS

790501005 IE Soap Bags 90-039/79-05-360/79-07 & 30-096/79-07 on 790501-2502 Noncompliance noted failure to post radiation area label containers of radioactive material and inadequate high radiation area
JACKSON, L. Region 2, Atlanta, Office of the Director
SILVER, J. F. Region 2, Atlanta, Post Facility & Materials Safety Branch, 79/03/29 2pp

7905010432 Forwarded responses to IE Bulletin 79-08 re incorrect using check valve weights. Corrected valve weights do not create any overpressuring in piping/bags of supports. All info will be provided by 790511
SILVER, J. F. E. Tennessee Valley Authority 79/05/06 App

B. Periodic operating reports & related correspondence

7905010043 Forwarded "Environ Radioactivity Levels Annual Rpt 1978" *
SILVER, J. F. E. Tennessee Valley Authority 79/04/27 1p

7905010047 "Environ Radioactivity Levels Annual Rpt 1978" *
Tennessee Valley Authority 79/04/27 2pp

7905010475 Forwarded "Fish Impingement Rpt" for 4th quarter 1979
SILVER, J. F. E. Tennessee Valley Authority 79/03/01 2pp

7905010476 "Fish Impingement Rpt" for 4th quarter 1979
Tennessee Valley Authority 79/03/01 2pp

7905010046 Forwarded monthly operating rpt for Apr 1979
SILVER, J. F. E. Tennessee Valley Authority 79/05/09 1p

7905010052 Monthly operating rpt for Apr 1979
SILVER, J. F. E. Tennessee Valley Authority 79/05/09 3pp

B. Reportable occurrences, LERs & related correspondence

7905010363 Forwarded LER 79-004/02-0
FOLLO, H. E. Tennessee Valley Authority 79/05/07 1p

7905010308 LER 79-005/02-0 on 790401 reactor bldg turbine stop & refusing to start exhaust member 99-00-028 failed surveillance test 01 & 02 & 3, Section 4a caused by failure of input card for radiation monitor
Tennessee Valley Authority 79/05/07 2pp

7905010308 Forwarded LER 79-005/02-0
FOLLO, H. E. Tennessee Valley Authority 79/05/17 1p

7905010308 LER 79-005/02-0 on 790401 broken terminal discovered on shutdown board B battery Cassen unknown affected coils replaced & personnel instructed to proper tightening methods
Tennessee Valley Authority 79/05/17 2pp

7905010308 Forwarded LER 79-005/02-0
FOLLO, H. E. Tennessee Valley Authority 79/05/08 1p

7905010308 Notification of change in 790501 submittal Fire protection penetrations fitted w/9 inches of Pen instead of 12 inches
WILF, K. E. Carolina Power & Light Co. 79/05/09 1p

7905010301 Forwarded application for amend to License 898-23-revising Tech Specs re Fire protection w/9
WILF, K. E. Carolina Power & Light Co. 79/05/17 1p

7905010301 Application for amend to License 898-23-revising Tech Specs re Fire protection w/9
WILF, K. E. Carolina Power & Light Co. 79/05/17 10pp

D. Adjudicatory correspondence

7905010194 Forwarded 17 Carter 790502 memo describing recent draft document re salvage of spent nuclear fuel info is being forwarded ASAR will be notified upon completion
WILF, K. E. H. Branch 2 79/05/09 2pp

7905010433 Forwarded 85 Case 790403 memo to S Levine re studies to determine capability of existing personnel neutron dosimetry
WILF, K. E. H. Branch 2 79/04/02 7pp

7905010473 Advises that Suppl 2 of SER was issued 790500 Recommendations conference call to discuss ASAR plans for future action
WILF, K. E. H. Branch 2 79/04/04 1p

J. Insurance & indemnity information

7905010497 Confirming increased liability limit to \$104,000,000 for policies 07-1, 20, 43, 76, 02, 100, 111, 148, 149, 151, 161, 164, 170, 175, 176, 179, 180, 185, 186, 189, 190, 197, 198, 199, 200, 201, 202, 203, 204, 205, 210, 212, 214, 215 & others
WILF, K. E. H. American Nuclear Insurers 79/05/01 1p

7905010392 Confirming increase in liability limit to \$26,000,000 for policies 07-1, 20, 43, 76, 02, 100, 111, 148, 149, 151, 161, 164, 170, 175, 176, 179, 180, 185, 186, 189, 190, 197, 198, 199, 200, 201, 202, 203, 204, 205, 210, 212, 214, 215 & others
WILF, K. E. H. Mutual Atomic Group Liability Underwriters 79/05/01 1p

7905010403 Forwarded Amend 6 to Indemnity Agreement 8-02, per 100CR140 changes re liability insurance increase from \$140 million to \$160 million effective 790501 Supporting documentation w/1
WILF, K. E. H. Antitrust & Indemnity Group 79/05/01 7pp

7905010200 Forwarded Enforcement 46 to NRC Policy 79-09
WILF, K. E. H. Carolina Power & Light Co. 79/05/07 2pp

7905010520 Forwarded Amend 9 to Indemnity Agreement 8-02 & 8-71 reflecting increase in primary liability insurance provided by AM/INDU
WILF, K. E. H. Douglas & Barham 79/05/11 2pp

F. Operating license change documents & correspondence

7905010207 Forwarded Suppl 2 to 790520 safety evaluation of proposed power increase
SCHMIDT, A. Operating Reactors Branch 1 79/03/30 2pp

7905010309 Suppl 2 to 790520 safety evaluation of proposed amend 1 License 898-23, allowing power increase from 3.000 MW to 3.500 MW
SCHMIDT, A. Operating Reactors Branch 1 79/03/30 30pp

7905010326 Forwarded Amend 26 to License 898-23-safety evaluation & notice of issuance & availability
SCHMIDT, A. Operating Reactors Branch 1 79/04/11 2pp

7905010346 Amend 26 to License 898-23 authorizing removal of all parts-inch control rods from reactor
SCHMIDT, A. Operating Reactors Branch 1 79/04/11 10pp

7905010317 Safety evaluation supporting Amend 26 to License 898-23
SCHMIDT, A. Office of Nuclear Reactor Regulation 79/04/11 2pp

7905010310 Notice of issuance & availability of Amend 26 to License 898-23
SCHMIDT, A. Operating Reactors Branch 1 79/04/11 2pp

#700130240 Notifies that 790036 application for refund to Licensee BFF-2D has been received w/No. 400 for two Class 2 & one Class 3 above Review Determined First & second changes each require Class 3 and Fee
HILLIER, R. C. License Fee Management Branch 79/04/20 1p

#700130331 Notifies that still will perform extended burnup test for four assemblies during Cycle 3 Forward program description
UTLEY, E. E. Carolina Power & Light Co. 79/04/23 3pp

#700130333 Forwards \$2,800 add license fee requested in NRC 790420
UTLEY, E. E. Carolina Power & Light Co. 79/04/27 1p

#700130437 Requests extension until 790731 to submit evaluation justifying extended purging of containment bldg during normal operation
UTLEY, E. E. Carolina Power & Light Co. 79/05/08 1p

#700130463 Forwards overlaid maps & photo attachments to w/ 701129 rept on main cam core trench features w/o drawings
FLYNN, B. C. Carolina Power & Light Co. 79/05/08 3pp

#700130524 Requests change in Tech Spec to restrict deletion of pressure/pressure signal w/supplementing documentation & Class III and Fee
UTLEY, E. E. Carolina Power & Light Co. 79/05/08 3pp

#700130574 Forwards seismic reanalysis of RCS in response to 790517 & 790518 seismic loads & moments meet PWR drawings
UTLEY, E. E. Carolina Power & Light Co. 79/05/28 3pp

B Inspection reports, IE Bulletins & correspondence

#700130583 Forwards IE Insp Rept 50-261/79-04 on 790213-16 No noncompliances noted
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/19 3pp

#700130592 IE Insp Rept 50-261/79-04 on 790213-16 No noncompliance noted Rept areas inspected Licensee event followup & plant operation
MCHEERY, T. J. Region 2, Atlanta, Office of the Director
BANKS, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/19 3pp

#700130586 Forwards IE Info Notice 79-04, "Bisness Analysis of Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 3pp

#700130594 Forwards IE Info Notice 79-07, "Repture of Radiaste Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/26 3pp

#700130595 Forwards IE Info Notice 79-08, "Interconnection of Contaminated H₂O/W Air Sys Used as Source of Breathing Air"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/28 3pp

#700130646 Forwards IE Info Notice 79-09, "Bill of Radioactivity Contaminated Rept."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/30 3pp

#700130618 Forwards IE Bulletin 79-26, "Review of Operational Errors & Sys Misalignments Identified During THE Incident" - Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/11 1p

#700130613 Requests to IE Bulletin 79-03. No plus spots from Youngstown Welding & Engineering Co are used or planned to be used
UTLEY, E. E. Carolina Power & Light Co. 79/04/13 1p

#700130612 Forwards IE Bulletin 79-08B, "Review of Operational Errors & Sys Misalignments Identified During THE Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

#700130621 Forwards IE Bulletin 79-07, "Seismic Bisness Analysis of Safety-Related Piping." - Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14 1p

#700130629 Forwards IE Bulletin 79-38, "Keweenaw relevant to Boiling Water Power Reactors identified During THE Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

#700130641 Forwards IE Bulletin 79-09, "Failures of GE Type AA-2 Circuit Breaker in Safety-Related Sys." - Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17 3pp

#700130645 Forwards IE Bulletin 79-04A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During THE Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/19 3pp

#700130646 Ask receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/79-05
BUTNER, R. J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/19 1p

#700130644 Response to NRC 790323 ltr re violation noted in IE Insp Rept 50-261/79-05 Corrective actions only health physics technicians w/ proper qualifications will be utilized for back shift coverage
BANKS, H. C. Carolina Power & Light Co. 79/04/14 3pp

#700130646 Forwards IE Insp Rept 50-261/79-05 on 790226-0302 & notice of violation
BUTNER, R. J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/23 3pp

#700130644 Notice of violation from Insp on 790226-0302
Region 2, Atlanta, Office of the Director. 79/03/23 1p

#700130642 IE Insp Rept 50-261/79-05 on 790226-0302 Noncompliance noted technicians used in responsible positions w/o sufficient health physics experience
JENKINS, G. E. Region 2, Atlanta, Office of the Director
BUTNER, R. J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/23 3pp

#700130617 Forwards restated paragraph from 790330 ltr, submitted as revision to QA program, in response to IE Insp Rept 50-261/79-02 & 50-261/79-02 Paragraph discusses radiation survey/measuring instruments
UTLEY, E. E. Carolina Power & Light Co. 79/04/23 3pp

#700130644 Requests that present invasive testing program for pumps & valves, conditionally accepted by NRC on 79/04/26 be allowed to continue through 8/8/87
UTLEY, E. E. Carolina Power & Light Co. 79/04/23 1p

#700130582 Forwards w/ 790426 response to IE Bulletin 79-07, "Seismic Bisness Analysis of Safety-Related Piping" - Request review & reply
UTLEY, E. E. Carolina Power & Light Co. 79/04/27 1p

#700130587 Response to IE Bulletin 79-07 requesting info on seismic stress analysis of safety-related piping Westinghouse reanalysis revealed max stress was well below allowable limit
UTLEY, E. E. Carolina Power & Light Co. 79/04/24 3pp

#700130626 Response to IE Bulletin 79-04, Request extension of response date to 79/05/31
UTLEY, E. E. Carolina Power & Light Co. 79/05/01 1p

#700130631 Preliminary response to IE Bulletin 79-04, "Pipe Support Base Plate Design Using Concrete Expansion Anchor Bolts"
Review of records revealed QC documentation not available to sufficiently support proper bolt installation
UTLEY, E. E. Carolina Power & Light Co. 79/05/22 3pp

B Periodic operating reports & related correspondence

#700130618 Forwards monthly operating rept for Apr 1979
FURBER, G. Carolina Power & Light Co. 79/05/01 3pp

#700130642 Monthly operating rept for Apr 1979
HATFIELD, L. L. Carolina Power & Light Co. 79/05/02 3pp

B Reportable occurrences, LERs & related correspondence

#700130631 Forwards LER 79-066/031-0
FURBER, G. Carolina Power & Light Co. 79/05/01 1p

#700130635 LER 79-066/031-0 on 790402 Coric acid transfer pump B tripped due to high temp. Caused by broken shaft. Pump repaired & tested satisfactorily
BANKS, H. C. Carolina Power & Light Co. 79/05/01 3pp

DOCKETED ITEMS

- 790130450 Forwards LER 79-087/03L-0
FURNER, B J Carolina Power & Light Co 79/05/10 1p
- 790130451 LER 79-087/03L-0 on 790415 seal found in steam generator B
(exp revealed s/s tubes w/encl seals Cause Unexplained
Leaks will be repaired s/s replace plug)g
STANLEY, R D Carolina Power & Light Co 79/05/10 3pp
- 790130461 Forwards LER 79-011/01T-0
FURNER, B J Carolina Power & Light Co 79/05/10 1p
- 790130462 LER 79-011/01T-0 on 790426 small pin hole leaks found on
front canopy seal welds Caused by weld degradation 8055
supplier examining this type failure
STANLEY, R D Carolina Power & Light Co 79/05/10 3pp
- 790130463 Discusses 790415 operation of overpressure protection s/s
while proceeding to cold shutdown Requests license amend re
overpressure protection Forwards 790415 RD & 791322 requests
for license amend
STANLEY, R D Carolina Power & Light Co 79/05/14 1p
- 790130464 RD on 790412 while proceeding to cold shutdown overpressure
protection s/s activated Caused by operator error Event
details are being studied
* Carolina Power & Light Co 79/05/14 3pp
- 790130465 Request for license amend to revise Tech Specs re
overpressure protection Unrevised pages to implement
changes
UTLER, H R Carolina Power & Light Co 77/12/22 13pp
- 790130467 Forwards LER 79-009/02L-0
FURNER, B J Carolina Power & Light Co 79/05/10 1p
- 790130468 LER 79-009/02L-0 on 790414 safety injection pump A failed to
start Cause unknown Pump's in-leak & timing relay were
checked electrically problems obtained PMS started
initially & returned to svc
STANLEY, R D Carolina Power & Light Co 79/05/10 3pp
- 790130469 Forwards LER 79-009/03L-0
STANLEY, R D Carolina Power & Light Co 79/05/10 1p
- 790130470 LER 79-009/03L-0 on 790414 diesel failed to ensure
electric loadings in regulated 50-4. Caused by timing
relays being set too long due to instrument drift Timing
relays reset Permanent change being considered
STANLEY, R D Carolina Power & Light Co 79/05/10 3pp
- 790130480 Forwards LER 79-026/02L-0
STANLEY, R D Carolina Power & Light Co 79/05/16 1p
- 790130481 LER 79-010/02L-0 on 790415 engine driven fire pump rendered
ineffective due to fuel leak Caused by failure of solenoid
operated fuel shutoff valve to close fully due to plates of
slag between valve seating surfaces Slag removed
STANLEY, R D Carolina Power & Light Co 79/05/16 3pp
- 790130482 Forwards LER 79-012/01T-0
STANLEY, R D Carolina Power & Light Co 79/05/22 1p
- 790130483 LER 79-012/01T-0 on 790508 during normal operation s/s of
ten supports of solid lag safety injection stem failed,
allowing section of pipe to fall on floor Caused by
underlagger New supports to be installed
STANLEY, R D Carolina Power & Light Co 79/05/22 3pp
- SECRET 50-942 BRIGHAM YOUNG UNIV RESEARCH REACTION
- J Insurance & indemnity information
- 790130507 Forwards Amend 9 to Indemnity Agreement B-02, per 105P014
changes re liability increase from \$140 million to \$160 million.
effective 790501 Supporting documentation incl
SMLT0040 J Antitrust & Indemnity Group 79/05/01 3pp
- SECRET 50-243 FONTICELLO NUCLEAR GENERATING PLANT
6. Anticipating correspondence
- 790130508 Denies 791208 request to prohibit further installation of
spend fuel storage racks pending hearing to determine if
license amend should be issued
BOOTHBY, H R Office of Nuclear Reactor Regulation 79/04/24 1p
- 790130509 Director's decision per 105P012 206 request Permit
fuel storage rack made do not require license amend Request
by NW Pollution Control Agency to prohibit installation
of racks at 24165
BOOTHBY, H R Office of Nuclear Reactor Regulation 79/04/24 17p
- 790130510 Notice or issuance of Director's decision per 105P012 216
denying NW Pollution Control Agency's request for
suspension of fuel rack installation
BOOTHBY, H R Office of Nuclear Reactor Regulation 79/04/24 3pp
- I Financial information
- 790130523 Forwards "Financial & Statistical Info" as suppl to "Annual
Financial Rept 1978"
STANLEY, R D Northern States Power Co 79/05/10 1p
- 790130524 "Financial & Statistical Info" submitted as suppl to
"Annual Financial Rept 1978"
* Northern States Power Co 79/05/21 21pp
- J Insurance & indemnity information
- 790130547 Confirms increased liability limit to \$126,000,000 for
policies 79-1, 28, 33, 34, 35, 100, 111, 140, 146, 191, 193, 194, 195,
196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236,
237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000
- 790130548 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
- 790130549 Confirms increase in liability limit to \$36,000,000 for
policies 79-22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89

DOCKETED ITEMS

DOCKET 20-244 DOW CHEMICAL CO

J Insurance & indemnity information
*****790310233 Forwards Amend 10 to Indemnity Agreement 8-24, per 10CFR140 changes, re increase from \$450 million to \$100 million, effective 790301 Supporting documentation encl
SALTPMAM-J Antitrust & Indemnity Group 79/05/01 5pp790310234 Forwards executed Amend 10 to Indemnity Agreement 8-24
COALWELL-T H Dow Chemical Co 79/05/09 5pp

DOCKET 20-245 DUNE-CITIZEN STATION UNIT 2

F Security, medical, emergency & fire protection plans
*****790310245 Forwards sections of fire protection plan which require further NRC review valve apparatus, steam breaking equipment & interior hose stations
HALL-R E Brookhaven National Laboratory 79/04/12 5pp790303036 Forwards modified physical security plan, Revision 5 Plan, unclassified draft 10CFR 7901
LSE-B Commonwealth Edison Co 79/04/26 1p

O Adjudicatory correspondence

790303038 Notify/Reply properly worded contention addressing contention of sabotage would be accepted into proceeding Contention 6 as admitted into Data Base & providing comprehensive aspects of revised Contention 11 presented by State of IL
GODDARD-R J Branch 2 79/04/26 2pp

J Insurance & indemnity information

790303043 Enforcement 99 to NRC/IL Policy 99-22
SERMS-T Nuclear Energy Liability Insurance Association 79/03/27 1p790303047 Confirms increased liability limit to \$124,000,000 for policies 99-22, 24, 26, 28, 30, 32, 34, 36, 38, 40, 42, 44, 46, 48, 50, 52, 54, 56, 58, 60, 62, 64, 66, 68, 70, 72, 74, 76, 78, 80, 82, 84, 86, 88, 90, 92, 94, 96, 98, 100
GRIFFIN-C J American Nuclear Insurers 79/03/01 1p790303050 Confirms increase in liability limit to \$24,000,000 for policies 99-22, 24, 26, 28, 30, 32, 34, 36, 38, 40, 42, 44, 46, 48, 50, 52, 54, 56, 58, 60, 62, 64, 66, 68, 70, 72, 74, 76, 78, 80, 82, 84, 86, 88, 90, 92, 94, 96, 98, 100
ROBERTS-R B Mutual Atomic Energy Liability Underwriters 79/05/01 1p790310436 Forwards Amend 11 to Indemnity Agreement 8-27 per 10CFR140 changes, re increase in liability insurance from \$100 million to \$160 million, effective 790301 Supporting documentation encl
SALTPMAM-J Antitrust & Indemnity Group 79/03/05 5pp

F Operating license stage documents & correspondence

790303067 Forwards notes re 790305 15 & 22 conference telcons between NRC consultants & staff re isolation "Potential Explosive Gas Mixtures Accumulations Related w/DR Offgases Gas Operations"
BPPFLIS-J A Operating Reactors Branch 2 79/04/16 4pp790303068 Responds to 790305 for circulating application for approval of proposed license amend that would allow shipment of spent fuel between stations Provides info on packaging bearing
BPPFLIS-J A Operating Reactors Branch 2 79/04/16 1p790303071 Opposes application for approval of proposed license amend that would allow shipment of spent fuel between stations
BONENBROOK-P Application Branch 79/03/10 5pp790310026 Forwards response to NRC 781025 request for addl info re instrument output changes
JANCOEN-R P Commonwealth Edison Co 79/04/25 3pp790304082 Notice of intention to develop safety analysis using existing computer codes Requests addl info
BOLMIRE-C W Commonwealth Edison Co 79/04/24 1p790310016 Forwards current schedule for implementation of NRC's containment long-term mode, Division's constraints inhibiting shorter time frame resolution including gas load requirements & current fuel cycles
REED-C Commonwealth Edison Co 79/05/11 5pp790303077 Requests correction to error discovered in 780421 St-P capacity of Nuclear Emergency Corp (NEC) truck tank used in spent fuel transfer Study truck tank has capacity of two tank assemblies
JANCOEN-R P Commonwealth Edison Co 79/05/11 1p

F Operating license stage documents & correspondence

790303081 Forwards current licensing upon item status list
REED-C Commonwealth Edison Co 79/05/10 11pp

G Inspection reports, IE Bulletins & correspondence

790303082 Forwards response to IE Bulletin 79-02 & 79-12, "Analysis of Weld Metal in Reactor Pressure Vessel Nozzle"
REED-C Commonwealth Edison Co 79/03/22 10pp790310204 Forwards IE Info Notice 79-04, "Direct Analysis of Safety-Related Piping"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790303070 Forwards IE Info Notice 79-07, "Rupture of Mainsteam Pipes"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790303083 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Gas w/DR Air Gas Used as Source of Breathing Air"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790303084 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790303087 Forwards IE Bulletin 79-06, "Review of Operational Events & Gas Mixtures Identified During TMI Incident"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790303088 Responds to IE Bulletin 79-03 re voiding defects in certain institutionally ordered pipe spools Plants inspection in pipe spools
REED-C Commonwealth Edison Co 79/04/12 3pp790303089 Forwards IE Bulletin 79-04, "Review of Operational Events & Gas Mixtures Identified During TMI Incident"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790303094 Forwards IE Bulletin 79-03, "Review of Operational Events & Gas Mixtures Identified During TMI Incident"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790304094 Forwards IE Bulletin 79-05, "Events Relevant to Existing Meter Power Reactors Identified During TMI Incident"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790303094 Forwards IE Bulletin 79-05, "Failures of Off-Gas AP or Circuit Breaker in Safety-Related Gas - Licensee action required"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790304042 Forwards IE Bulletin 79-08, "Nuclear Incident at TMI - Bagg"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 1p790304018 IE Bulletin 79-08, "Nuclear Incident at TMI Bagg"
BPPFLIS-J A Region 3, Chicago, Office of the Director 79/04/11 12pp790304017 NRC recommendations re 790305 incident at TMI 6-085555 re priority to be placed on development of safety research on behavior of LBMS during anomalous transients
ACRS - Advisory Committee on Reactor Safeguards 79/04/17 3pp

DOCKETED ITEMS

49

--7905040201 Forwards ACRS recommendations re TMI incident, presented on 7/6/81
FRLEY, E F ACRS - Advisory Committee on Reactor Safeguards
7/6/81 8 1p

--7905040202 In response to NRC 790408 ltr-states all ACRS 790407 recommendations apply to all PWRs, but were not intended to require immediate changes. Plant needs must be made after study of effects on overall safety. TMI excluded.
FRLEY, E F ACRS - Advisory Committee on Reactor Safeguards
7/6/81 20 2pp

7905040203 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping. Response indicates effects of intranodal combination has little effect on pipe stresses & equipment support loads.
REED, C Commonwealth Edison Co 7/6/81 24 4pp

7905050145 Forwards responses to IE Bulletin 79-06A. Revision 1 re BWR events identified during TMI-2 Unit 1 has formed task force to review BWR events & recommend corrective actions.
REED, C Commonwealth Edison Co 7/6/81 27 2pp

7905050242 Response to IE Bulletin 79-04 Re 3.4 or 4-inch Valve using check valves are in use at Dresden or Quad-City Review of ED has identified use of valves in same piping vs but review is incomplete will report later.
REED, C Commonwealth Edison Co 7/6/81 31 2pp

7905100408 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Water Generator Not Resulted in Reactor Power Increase".
HOPKINS, J E Region 3, Chicago, Office of the Director 7/6/81 32 1p

N Periodic operating reports & related correspondence

7905170025 Forwards monthly operating report for Apr 1979
KALVIANAKIS, N Commonwealth Edison Co 7/6/81 33 1p

--7905170248 Monthly operating report for Apr 1979
HOPKINS, J E Commonwealth Edison Co 7/6/81 37 2pp

E Significant occurrences, LERs & related correspondence

7905050209 Inform that release rate of radiolabel & radioactive particulate matter withheld greater than eight days was 2.5 times higher than Tech Spec design objective for first quarter 1979 caused by steam leaks & "spiking".
KALVIANAKIS, N Commonwealth Edison Co 7/6/81 38 2pp

7905060478 Forwards LER 79-004/02L-0
KALVIANAKIS, N Commonwealth Edison Co 7/6/81 39 1p

--7905240687 LER 79-024/02L-0 re 790521 while in cold shutdown, suction valve HD 2-1001-85 failed to close from control room caused by stuck auxiliary contact in valve motor control circuit breaker. Contact cleaned & proved acceptable.
WHITMAN, J V Commonwealth Edison Co 7/6/81 39 2pp

7905060702 Forwards LER 79-027/02L-0
KALVIANAKIS, N Commonwealth Edison Co 7/6/81 40 1p

--7905240707 LER 79-027/02L-0 re 790628 small leak discovered at weld edge in transition weld. Cause unknown. Leaks filled with weld metal & permanent tested to verify removal of indications.
TIEZ, C Commonwealth Edison Co 7/6/81 42 2pp

7905240401 Forwards LER 79-028/02L-0
KALVIANAKIS, N Commonwealth Edison Co 7/6/81 44 1p

--7905240409 LER 79-028/02L-0 re 790409 suppression chamber level determined to be below Tech Spec min. Cause by instrument miscalibrated drift. Level indicator recalibrated & water added to suppression pool.
SMALL, R C Commonwealth Edison Co 7/6/81 44 2pp

DOCKET NO-266 POINT BEACH NUCLEAR PLANT, UNIT 1

P. Security, medical, emergency & fire protection plans

7905060446 Submits proposed memo to fire protection plan as set forth in BWR Recommendations fire hydrant inspection & supervision of valves controlling fire water system.
SMALL, R C Brookhaven National Laboratory 7/6/81 47 2pp

W Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NP-1, 2B, 43, 76-03, 100-181, 840-144, 151-144, 164-173, 174-178, 179-180, 182-185, 186-187, 188-189, 192-193, 194-195, 197-198, 200-201, 204, 206, 207, 208-210, 212, 214, 215 & others.
QUAY, ROBERT J American Nuclear Insurers 7/6/81 1p

7905070508 Confirms increase in liability limit to \$35,000,000 for policies NP-20, 26, 29, 38, 39, 44-46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 61, 64, 66, 67, 68, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D H Mutual Atomic Energy Liability Underwriters 7/6/81 1p

7905100420 Forwards Amend 11 to Indemnity Agreement B-41 per ICFR140 changes re increase in liability insurance from \$100 million to \$100 million effective 7/9/81 Supporting documentation attached.
SMITH, J W J Antitrust & Indemnity Group 7/6/81 1p

7905230443 Forwards executed Amend 11 to Indemnity Agreement B-41 per NRC 790301 request.
BURDICK, W J Wisconsin Electric Power Co 7/6/81 17 2pp

P Operating license stage documents & correspondence

7905140518 Forwards Amends 25 & 41 to Licenses DPR-24 & DPR-27, respectively, safety evaluation, EIA & notice of issuance & availability.
SCHNEIDER, A Operating Reactors Branch 1 7/6/81 4pp

--7905140520 Amends 25 & 41 to Licenses DPR-24 & DPR-27, respectively, authorizing installation & use of modified spent fuel storage racks in spent fuel pool, which increases capacity for storage from 395 assemblies to 1,390 assemblies.
ZICHMAN, D L Assistant Director for Systems & Projects 7/6/81 54 2pp

--7905140526 Safety evaluation supporting Amends 25 & 41 to Licenses DPR-24 & DPR-27, respectively.
* Office of Nuclear Reactor Regulation 7/6/81 56pp

--7905140529 EIA of Amends 25 & 41 to Licenses DPR-24 & DPR-27, respectively.
* Office of Nuclear Reactor Regulation 7/6/81 64 23pp

--7905140533 Notice of issuance & availability of Amends 25 & 41 to Licenses DPR-24 & DPR-27, respectively.
SCHNEIDER, A Operating Reactors Branch 1 7/6/81 4pp

7905050503 Forwards Amend 36 to License DPR-24, safety evaluation & notice of issuance & availability.
SCHNEIDER, A Operating Reactors Branch 1 7/6/81 5pp

--7905050508 Amend 36 to License DPR-24, extending reactor coolant system pressure-temp startup & shutdown curves from 7 to 11 effective full power years.
SCHNEIDER, A Operating Reactors Branch 1 7/6/81 6pp

--7905050707 Safety evaluation supporting Amend 36 to License DPR-24 * Office of Nuclear Reactor Regulation 7/6/81 66 2pp

--7905100506 Notice of issuance & availability of Amend 36 * DPR-24
SCHNEIDER, A Operating Reactors Branch 1 7/6/81 6pp

7905100509 Forwards Amends 37 & 42 to Licenses DPR-24 & DPR-27, respectively & notice of issuance & availability. Security plan evaluation withheld (ref ICFR140).
SCHNEIDER, A Operating Reactors Branch 1 7/6/81 12

--7905100442 Amends 37 & 42 to Licenses DPR-24 & DPR-27, re-implementing provisions of NRC-approved physical security plan.
SCHNEIDER, A Operating Reactors Branch 1 7/6/81 13

--7905100445 Notice of issuance & availability of Amends 37 Licenses DPR-24 & DPR-27, respectively.
SCHNEIDER, A Operating Reactors Branch 1 7/6/81 13

7905100507 Forwards info in response to 790301 request re 4 plant shutdowns.
DENTON, H S Office of Nuclear Reactor Regulation 7/6/81

7905020278 Request amends to Licensee 098-24 & 098-27, changing Tech Specs re initiation instrument setting limits for engineered safety functions Licensee Class III and for BURSTEIN, S Wisconsin Electric Power Co 79/04/27 App

7905020282 Response to IE Bulletin 79-04A, Item 3 re TMI error Presurizer low level stopped bleedoff return line interrupted position until logic change requested in 7905020282 Licensee Class III implemented BURSTEIN, S Wisconsin Electric Power Co 79/04/20 App

7905020282 Forwarded add info re reactor vessel leak & surveillance unit status BURSTEIN, S Wisconsin Electric Power Co 79/05/04 App

7905020288 Forwarded add info re Tech Spec Change Request add permitting safety function location (inserted) and to two out of three presurizer low pressure logic requests approval by 7905020288, piping analysis computer program from Jan-Cor 1500 Review & reanalysis included all units through Dec 1979 BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Forwarded summary of ESB Reactor line resolution/documentation of allow flexibility error which existed in versions of ESB, piping analysis computer program from Jan-Cor 1500 Review & reanalysis included all units through Dec 1979 BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Forwarded ESB Reactor line resolution & piping analysis which could have been impacted by Reactor computer program. ESB has no record of reanalysis for Canger piping test BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Forwarded ESB Reactor line resolution & piping analysis which could have been impacted by Reactor computer program. ESB has no record of reanalysis for Canger piping test BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

0 Inspection reports, IE Bulletin & correspondence

7905020288 Forwarded IE Insp Repts 50-244/79-04 & 50-245/79-03 as 7905020288 & notice of violation BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Notice of violation from Insp as 7905020288 & 7905020288 Wisconsin Electric Power Co 79/05/07 App

7905020288 IE Insp Repts 50-244/79-04 & 50-245/79-03 as 7905020288 & notice of violation BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Forwarded IE Insp Notice 79-04, "Stress Analysis of Safety-Related Piping" BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Forwarded IE Insp Notice 79-07, "Review of Reactor Tank" BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Forwarded IE Insp Notice 79-08, "Interconnection of Containment Air with Air Gas Used as Source of Breathing Air" BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Forwarded IE Insp Notice 79-09, "Mill of Radioactively Contaminated Fuel" BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Forwarded IE Bulletin 79-04, "Review of Operational Errors & Misalignments Identified During TMI Incident" Licensee action required BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Forwarded IE Bulletin 79-04A, "Review of Operational Errors & Misalignments Identified During TMI Incident" Licensee action required BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Forwarded IE Bulletin 79-04B, "Review of Operational Errors & Misalignments Identified During TMI Incident" Licensee action required BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Forwarded IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping" Licensee action required BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Forwarded IE Bulletin 79-08, "Events Relevant to Rolling Water Power Reactor Identified During TMI Incident" Licensee action required BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Forwarded IE Bulletin 79-09, "Failures of GE Type M-2 Circuit Breaker in Safety-Related Bus" Licensee action required BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Response to IE Bulletin 79-04A Expresses concern re emergency operating procedures for reactor coolant pump re magnetic flux re immediate tripping of low level detection BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Forwarded IE Bulletin 79-05B, "Nuclear Incident at TMI-Bapt" BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Response to IE Bulletin 79-07 re computer program used re stress analysis of safety-related piping re no computer codes used which utilized algebraic solution techniques BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Response to IE Bulletin 79-03 re possibility of longitudinal defect in AHC 84-342 Type 304 stainless steel pipe re review of pipe documentation records indicates no use of such tubing BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Response to IE Bulletin 79-04A & 79-04A, Revision II, re established back force to facilitate review & understanding of TMI incident & impact on facility BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Response to IE Bulletin 79-09 re GE Type M-2 circuit breakers item not in use at plant BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

8 Periodic operating reports & related correspondence

7905020288 Forwarded monthly operating report for Apr 1979 BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 Monthly operating report for Apr 1979 Wisconsin Electric Power Co 79/05/07 App

9 Reportable occurrences, LERs & related correspondence

7905020288 Forwarded LER 79-006/02-0 BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 LER 79-006/02-0 as 7905020288 during biweekly test re heat tracing circuit of Boric acid gas Circuit 47 found (2000) re heat tracing circuit of Boric acid gas Circuit 47 found Cable replaced & circuit returned to operation BURSTEIN, S Wisconsin Electric Power Co 79/04/21 App

7905020288 Forwarded LER 79-007/02-0 BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

7905020288 LER 79-007/02-0 as 7905020288 vendor issued bulletin re potential problem with Turbogear bearing lubrication administrative controls instituted, re to be made as soon as possible BURSTEIN, S Wisconsin Electric Power Co 79/05/07 App

EOCNY 80-267 PORT ST. VINCENT NUCLEAR GENERATING STATION

10 Insurance & indemnity information

7905020288 Confirmed increased liability limit to \$100,000,000 for policies 001-28, 45, 70, 83, 100, 110, 114, 131, 135, 144, 170, 173, 174, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

DOCKETED ITEMS

51

- 7905070082 Confirm increase in liability limit to \$20,000,000 for policies HF-22, 26, 29, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 57, 58, 60, 61, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 94, 95, 96, 98, 99, 100
ROBERTS, D M Nuclear Atomic Energy Liability Underwriters 79/05/01 1p
- 7905100176 Forwards Amend H to Indemnity Agreement E-30, per 1005140 changes re liability insurance increase from \$100 million to \$600 million effective 790501. Supporting documentation incl BALTZMAN, J Anti-trust & Indemnity Group 79/05/01 2pp
- 7905200254 Amend D to Indemnity Agreement E-30, changing amount of financial protection, L
BALTZMAN, J Anti-trust & Indemnity Group 79/05/13 2pp
- P Operating license steps documents & correspondence
- 7905100179 Notification of 790322 meeting w/UTL in Bethesda, MD to discuss status of inservice loop program, primary wgs valves, steam generators & Agnada items
WUJHPC2, G Advanced Reactors Branch 79/04/17 3pp
- 7905100180 Forwards Amend 30 to License 39H-34, safety evaluation & notice of issuance & availability
EPIC1, T P Advanced Reactors Branch 79/04/20 2pp
- 7905100191 Amend 30 to License 39H-34 to revise Tech Spec to include eight test fuel elements into reactor core at first refueling & to install graphite surveillance specimens into five bottom transition reflector elements
EPIC1, T P Advanced Reactors Branch 79/04/20 4pp
- 7905040100 Safety evaluation supporting Amend 30 to License 39H-34
C Office of Nuclear Reactor Regulation 79/04/25 2pp
- 7905100104 Notice of issuance & availability of Amend 30 to License 39H-34
EPIC1, T P Advanced Reactors Branch 79/04/20 1p
- 7905030021 Inform that will not alter existing Tech Spec to accommodate BTR format format of present Tech Spec is adequate & meets intent of proposed BTR
FULLER, J K Public Service Co of Colorado 79/04/22 1p
- 7905030021 Describes proposed mod resulting from various analyses of P10123 power failure of steamwater two loop dump wgs
EPIC1, T P Advanced Reactors Branch 79/03/04 3pp
- 7905050024 Responds to 790130 request for temporary alteration to scheduled refueling program in order to correlate planned refueling outage not acceptable
COLLMER, P T Operator Licensing Branch 79/05/07 2pp
- 7905100310 Submit outline describing special tests to be performed during startup & rise to power, per 790204 request
WHEATBURN, B Public Service Co of Colorado 79/05/11 20pp
- 7905030025 Forwards list of outstanding items & requests for Tech Spec changes Overlaid and Available in Control Files only
WHEATBURN, B Public Service Co of Colorado 79/05/14 4pp
- G Inspection reports, IE Bulletins & correspondence
- 7905100064 Forwards IE Circular 79-04, "Loose Locking Nut on Linkage Valve Operator"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/14 1p
- 7905050044 Forwards IE Bulletin 79-12B, "Atypical Weld Heat in Reactor Pressure Vessel Head - Licensee action required"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/19 1p
- 7905020444 Forwards IE Circular 79-08, "Moisture Leakage in Stranded Wire Conductors"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/30 1p
- 7905100279 Forwards IE Info Notice 79-04, "Business Analysis of Safety-Related Piping"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/23 1p
- 7905020411 Forwards IE Info Notice 79-07, "Repair of Reducible Tank"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/24 1p
- 7905030044 Forwards IE Info Notice 79-03, "Interconnection of Containment Relief w/SC Air Box Used as Source of Drafting Air"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/28 1p
- 7905050044 Responds to IE Bulletin 79-12B Bulletin was sent to all by mistake & no response is required
WHEATBURN, B Public Service Co of Colorado 79/03/28 1p
- 7905050034 Ack receipt of 790322 item informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/79-03
WHEATBURN, B Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/29 1p
- 7905010034 Responds to NRC 790201 item re violations noted in IE Insp Rept 50-247/79-03 Corrective actions Tech Spec requirements reviewed & established w/representative involved
MILLER, C N Public Service Co of Colorado 79/03/15 2pp
- 7905100280 Forwards IE Insp Rept 50-247/79-03 on 790227-0302 No nonconformance noted
WHEATBURN, B Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/03/29 2pp
- 7905050044 IE Insp Rept 50-247/79-03 on 790227-0302 No nonconformance noted Major areas inspected radiation protection program & analytical measurement results
WHEATBURN, B WHEATBURN, B Region 4, Dallas, Fuel Facilities & Materials Safety Branch 79/03/28 2pp
- 7905100143 Forwards IE Bulletin 79-04, "Incorrect Heights for Euting Check Valves Hg by Union Engineering Corp - Licensee action required"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/20 1p
- 7905100031 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/03/20 1p
- 7905030047 Responds to IE Bulletin 79-03 UHLL has no intention of using stainless steel pipe mfg by Youngstown Welding & Engineering Co
FULLER, J K Public Service Co of Colorado 79/04/06 1p
- 7905040040 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Ops Missions Identified During TMI Incident"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p
- 7905040047 Forwards IE Bulletin 79-05, "Events Relevant to Rolling Water Pump Reactors Identified During TMI Incident"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p
- 7905050077 Forwards IE Bulletin 79-07, "Relistic Strain Analysis of Safety-Related Piping - Licensee action required"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/14 1p
- 7905050040 Forwards 1001 to IE Bulletin 79-05B, "Nuclear Incident at TMI"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16 1p
- 7905030020 Forwards IE Bulletin 79-04, "Failures of SE Type AN-2 Circuit Breaker in Safety-Related Sys - Licensee action required"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/17 1p
- 7905050035 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI Rept 1"
SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/16 1p
- 7905100020 Requests 30-day extension to respond to IE Bulletin 79-07
SEYFRIT, K V Public Service Co of Colorado 79/04/26 1p
- 7905100795 Ack receipt of 790406 item informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/79-04
WHEATBURN, B Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/26 1p

DOCKETED ITEMS

--790310300 Response to LSC 790313 ltr re violations noted in 16 Insp
Rept 86-2677-08 Corrective actions supervisors informed
that surveillance tests & other controlled work procedures
must be reviewed before being signed off
HILLMAN, K. Public Service Co of Colorado 79/04/06 1p

M Periodic operating reports & related correspondence

790301007 Forwards monthly operating rept for Mar 1979
HARRINGTON, D. Public Service Co of Colorado 79/04/25 1p

--790301034 Monthly operating rept for Mar 1979
GARR, J. W. Public Service Co of Colorado 79/04/01 10pp

790301035 Forwards monthly operating rept for Apr 1979
HARRINGTON, D. Public Service Co of Colorado 79/05/02 1p

--790301037 Monthly operating rept for Apr 1979
GARR, J. W. Public Service Co of Colorado 79/05/01 3pp

S Reportable occurrences, LERs & related correspondence

790301038 Forwards LER 79-022/031-0
GARR, J. W. Public Service Co of Colorado 79/02/01 1p

--790301039 LER 79-022/031-0 re 790318 data indicates temp of control
rod drives in power operated relief valve has been
penetrations greater than expected by analytical model
Surveillance frequency increased
HILLMAN, K. Public Service Co of Colorado 79/02/01 3pp

790301041 Forwards LER 79-021/034-0
GARR, J. W. Public Service Co of Colorado 79/02/14 1p

--790301042 LER 79-021/034-0 re 790315 at 864 thermal level, average core
coolant temp exceeded 1,200 F, resulting in operation in
degraded mode caused by operators ingress into of being
constant eye from steam generator tube leak. Quicker removed
HILLMAN, K. Public Service Co of Colorado 79/02/16 3pp

790301043 Forwards PNO-79-676 & 79-7710001
HARRINGTON, D. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/11 1p

--790301044 PNO-79-7710001
Office of Nuclear Reactor Regulation 79/04/12 4pp

790301045 Forwards PNO-79-676
HARRINGTON, D. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/12 1p

790301046 Forwards PNO-79-677 correction
HARRINGTON, D. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/13 1p

--790301048 PNO-79-677 correction
Office of Inspection & Enforcement 79/04/13 4pp

790301049 Forwards PNO-79-676 U & V
HARRINGTON, D. L. Region 4, Dallas, Office of the Director 79/04/16 1p

790301048 Forwards PNO-79-676 U & V
HARRINGTON, D. L. Region 4, Dallas, Office of the Director 79/04/16 1p

790301046 Forwards PNO-79-676A, B, C & D
HARRINGTON, D. L. Region 4, Dallas, Office of the Director 79/04/16 1p

790301046 Forwards PNO-79-676A, B, C & D
HARRINGTON, D. L. Region 4, Dallas, Office of the Director 79/04/16 1p

790301046 Forwards PNO-79-676A, B, C & D
HARRINGTON, D. L. Region 4, Dallas, Office of the Director 79/04/16 1p

--790301049 LER 79-016/031-0 re 790320 during routine surveillance of
circulator speed, visible trip, but high speed trip setpoints
found higher than met acceptable speeds. Caused by electronic
instrument drift, detectable adjustment
GARR, J. W. Public Service Co of Colorado 79/04/27 3pp

790301050 Forwards PNO-79-676, 677, 678, 679 & A2 re nuclear incident at
THE
HARRINGTON, D. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/29 1p

790301050 Forwards LER 79-011/031-0
HARRINGTON, D. L. Public Service Co of Colorado 79/05/01 1p

--790301050 Forwards LER 79-011/031-0 re 790320 during post-test testing,
discussed water pressure differential indicating switches
inoperable. Caused by failure of range adjustment mechanism
due to thermal wear. New movement & thermal mode installed
GARR, J. W. Public Service Co of Colorado 79/05/01 3pp

790301052 Forwards PNO-79-676 & A2
HARRINGTON, D. L. Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/05/02 1p

790301053 Forwards LER 79-012/031-0
HARRINGTON, D. L. Public Service Co of Colorado 79/05/02 1p

--790301054 LER 79-012/031-0 re 790310 white flushing basin effluent
exceeded for time caused by large amount of sediment
GARR, J. W. Public Service Co of Colorado 79/05/07 3pp

790301055 Forwards LER 79-027/034-0
HARRINGTON, D. L. Public Service Co of Colorado 79/05/07 1p

--790301057 LER 79-027/034-0 re 790319 five of nine helium circulator
test malfunction differential pressure switches tripped
Caused by dirt accumulation in ITT Barnham Model 289 pressure
differential switches
GARR, J. W. Public Service Co of Colorado 79/05/07 4pp

790301059 Forwards LER 79-014/031-0
HARRINGTON, D. L. Public Service Co of Colorado 79/05/16 1p

--790301060 LER 79-014/031-0 re 790317 wastewater big pump program
sample inoperable, daily direct sample of pump effluent
were not taken, nor was sample availability verified daily
Caused by improper personnel procedures
GARR, J. W. Public Service Co of Colorado 79/05/16 4pp

DOCKET 50-847 GEORGE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

790301060 Discussed 790312 submission of security plan for storage of
spent fuel & 790313 request for requirement for security plan
mode initial plan is sub to withholding from public record of
transmittal is required
HARRINGTON, D. L. Fuel Elements & Recycle Branch 79/03/29 2p

790301063 Forwards emergency procedure EP/DA/1900/4, "Loss of Reactor
Coolant," containing instructions for operator action for
shell break
HARRINGTON, D. L. Duke Power Co 79/03/29 2pp

W General correspondence

790301064 Urges careful review of staff rept before ordering shutdown
of facility, since action could cause extensive power
curtailments & higher fuel costs for 1 & 2 million customers
in Carolina piedmont
HARRINGTON, D. L. Duke Power Co 79/05/26 1p

790301065 Expresses gratitude for decision to allow facility
THORP/DA/1900/4 79/05/26 1p

J Insurance & indemnity information

790301066 Confirms increase in liability limit to \$26,000,000 for
policy 79-22-26-29, 28, 29, 30, 31, 32, 33, 34, 35, 36,
37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87,
88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100
HARRINGTON, D. L. Mutual Atomic Energy Liability Underwriters 79/05/12 1p

790301068 Forwards Amend 13 to Indemnity Agreement 8-44 per 100FR142
changes re increase in liability insurance from \$140 million
to \$160 million effective 790301 Supporting documentation
encl
HARRINGTON, D. L. Actinon & Indemnity Group 79/05/01 4pp

790301069 Liability executed copy of Amend 13 to Indemnity Agreement
8-44 reflecting changes in 100FR142
HARRINGTON, D. L. Duke Power Co 79/05/01 3pp

790301068 Forwards replacement copy of Amend 13 to Indemnity Agreement
8-44 in response to 790301 request WFOG of unit 790312
transmittal ltr
HARRINGTON, D. L. Duke Power Co 79/05/02 3pp

DOCKETED ITEMS

53

P Operating license stage documents & correspondence

790110125 Agrees to close block valve RC-66 until approval of well business analysis for electromagnetic relief valve RC-66 is received. However, valve will be opened for reactor transients
THIEB.A.C. Duke Power Co. 7/31/05 2pp

790110128 On 7/31/05 pressurizer electromagnetic relief block valve RC-4 was opened while unit was in transient mode BSG & unit have avoided continued plant operation upsurges. 4849g valve inoperable & found to be acceptable
THIEB.A.C. Duke Power Co. 7/31/05 1p

790205014 Forwards Amends 69.69 & 66 to Licensees DPF-56, DPF-47 & DPF-53, respectively. EIA & notice of issuance & availability
REID.R.W. Operating Reactors Branch 4 7/9/03 3pp

--790205018 Amends 69.69 & 66 to Licensees DPF-56, DPF-47 & DPF-53, respectively, which revises EIS by deleting aquatic surveillance program & special study programs
REID.R.W. Operating Reactors Branch 4 7/9/03 5pp

--790205021 EIA supporting Amends 69.69 & 66 to Licensees DPF-56, DPF-47 & DPF-53, respectively
* Operating Reactors Branch 4 7/9/03 3pp

790190525 Responds to R. Hutton & S. Ross concerning value of running natural circulation test on BSG reactor
TEDD500.BL Assistant Director for Plant Systems 7/9/04 4pp

7903090120 Responds to 790329 submittal re radiological effluent Tech Spec which shifted waste reduction process control program
Requester: submitted revision
REID.R.W. Operating Reactors Branch 4 7/9/04 10 2pp

790309021 Forwards documentation, design info & projected implementation schedule re emergency feedwater sys. as submitted in NRC 790425 meeting
PARMER.W.D. Duke Power Co. 7/9/04 20 4pp

790310550 Forwards addl info re DFC of Nuclear Reactor Regulation Unit re Tech Spec addl design info re control sys
LEE.H.W. Duke Power Co. 7/9/04 25 1p

790303071 Informs that will be conducted review of plant design & operation, including goal of improving reliability of normal feedwater sys. & added assurance of emergency feedwater supply to steam generators design adequate
OWEN.M.H. Duke Power Co. 7/9/04 25 2pp

790304047 Corrects error in 790419 ltr to NRC regarding period of facility mode should be Jan-Dec 1979
PARMER.W.D. Duke Power Co. 7/9/04 25 1p

790310048 Informs that small break analysis review is complete. Analyses are unacceptable & incomplete
ROBERTSON.T.H. Analysis Branch 7/9/04 25 1p

--790310074 Comments on draft report received 790326 has lengthy, does not concentrate on reactor issues & has dozens of incorrect & misleading statements that should be reorganized
ROBERTSON.T.H. Analysis Branch 7/9/04 25 3pp

790304088 Responds to 790320 ltr requesting advice on allowable time interval for submittal of reply to NRC
REID.R.W. Operating Reactors Branch 4 7/9/04 26 2pp

790305003 Informs of still position on issuance of formal order re continued plant operation written issuance is undesirable as policy & legally unenforceable
LEE.H.W. Duke Power Co. 7/9/04 29 1p

790304032 Forwards responses to 790329 request for addl info re revision changes to hydraulic pump emergency Tech Spec
PARMER.W.D. Duke Power Co. 7/9/04 25 2pp

790308032 Forwards proposed revision to Tech Spec covering reactor bldg hydrogen purge sys, venting room ventilation sys, reactor bldg purge filters & reactor fuel pool ventilation sys
PARMER.W.D. Duke Power Co. 7/9/03 01 11pp

790306036 Forwards proposed revision to Tech Spec, deleting Tech Spec 4.12 which is no longer required
PARMER.W.D. Duke Power Co. 7/9/03 01 4pp

790305038 Responds to questions raised re 790301 meeting Forwards addl info re proposed installation of high capacity storage waste info supplements 790325 & 790320 submittals.
PARMER.W.D. Duke Power Co. 7/9/03 02 3pp

790304044 Documents completion of 761001 proposal to delete Tech Specs re tendon-anchorage & liner plate surveillance programs
Licensee Fee not required
PARMER.W.D. Duke Power Co. 7/9/03 02 1p

790310104 Activities re refund of Fees, reinitiated 790305, for authority to transfer fuel between facility & Crystal River Unit 3 Refund will be sent when processed
KILBEE.H.D. License Fee Management Branch 7/9/03 03 1p

790310309 In response to NRC 790418 request, forwards proposed Tech Spec re plant safety reduction process control program
PARMER.W.D. Duke Power Co. 7/9/03 07 5pp

790308031 Forwards status on improvements to emergency feedwater sys. per WD Parker 790425 ltr & WD Lee 790426 ltr
PARMER.W.D. Duke Power Co. 7/9/03 07 10pp

790310317 Clarifies 790307 conversation re ALARA program associated w/venting of spent fuel pool
PARMER.W.D. Duke Power Co. 7/9/03 08 2pp

790310326 Lists drawings used for installation of automatic shutoff of interconnected emergency feedwater sys. which were sent to NRC on 7/9/03
PARMER.W.D. Duke Power Co. 7/9/03 08 1p

790310328 Forwards "Emergency Feedwater Sys. Sys Concept & Analysis" POC installation to be complete by 790325 Overlaid drawing in Central Files
PARMER.W.D. Duke Power Co. 7/9/03 10 4pp

790310339 Forwards "BWR 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluation Program, Phase 2," & add 790410 Supercedes program provided on 7/9/01
PARMER.W.D. Duke Power Co. 7/9/03 10 1p

--790310370 "BWR 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluation Program, Phase 2"
* Duke Power Co. 7/9/04 19 3pp

790302070 Submits request for relief from requirement of ASME Boiler & Pressure Vessel Code, Section III, impracticability of doing hydrostatic test on emergency feedwater header due to excessive leakage through boundary isolation valves
PARMER.W.D. Duke Power Co. 7/9/03 11 7pp

790302035 Forwards "Steam Generator Operating History"
PARMER.W.D. Duke Power Co. 7/9/03 14 1p

--790302039 "Steam Generator Operating History"
* Duke Power Co. 7/9/03 14 30pp

790303049 Forwards revised sys concept & analysis re addition of two motor-driven emergency feedwater pumps Supercedes 790310 submittal & reviewed drawing
PARMER.W.D. Duke Power Co. 7/9/03 17 10pp

790304078 Responds to IE Bulletin 79-040 re TMI incident. Forwards proposed amend to Tech Specs, changing actinoids of pressurizer electromagnetic relief valve & reactor coolant sys high pressure trip
PARMER.W.D. Duke Power Co. 7/9/03 21 11pp

790304043 Forwards design description for safety grade anticipators reactor trip re turbine trip on loss of main condenser RWLS will be installed for each refueling outage following NRC approval
PARMER.W.D. Duke Power Co. 7/9/03 21 3pp

790305028 Forwards summary of EDR Nuclear, Inc. resolution/commitment of any flexibility error which existed in violation of PDRLO piping analysis computer program from Jan-Oct 1999 Review & materials included all work through Dec 1970
PORTER.P.L. EDR Nuclear, Inc. 7/9/03 21 1pp

--790303043 Forwards EDR Nuclear, Inc. list of BWRs & piping sys which could have been impacted by deficient computer program
Sys has no record of materials for Cooper piping was
BTFPHENAM.P. General Electric Co. Nuclear Energy Products Div. 7/9/01 24 10pp

790310311 Forwards proposed Tech Spec revision re limiting conditions for operation & surveillance requirements
PARMER.W.D. Duke Power Co. 7/9/03 23 3pp

DOCKETED ITEMS

D Inspection reports, IE Bulletin & correspondence

7903050482 Forwards IE Insp Repts 80-046/79-04, 80-270/79-04, & 80-287/79-04 to 790305-07 No noncompliance noted
LEWIS, R. L. Region 2, Atlanta, Reactor Operations Nuclear Support Branch
79/03/12. 2pp

7903050503 IE Insp Repts 80-046/79-04, 80-270/79-04, 80-287/79-04 & 790305-07 No noncompliance noted. Major areas inspected: fire protection/prevention program, fire extinguishers, fire insurance maps & administrative control procedures
BRADFORD, M. H. TAYLOR, F. A. J. MELLON, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch
79/03/05. 4pp

7903050505 IE Insp Repts 80-046/79-04, 80-270/79-04, 80-287/79-04 & 790305-07 No noncompliance noted. Major areas inspected: fire protection/prevention program, fire extinguishers, fire insurance maps & administrative control procedures
BRADFORD, M. H. Region 2, Atlanta, Office of the Director
79/03/05. 4pp

7903050517 Forwards IE Info Notice 79-04, "Boron Analysis of Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/03. 2pp

7903050507 Forwards IE Info Notice 79-07, "Boron of Redundant Tanks"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/04. 2pp

7903050572 Discusses BSW reph: "Research Investigation Rep Related to Air-Changing Valve in Heat Surveillance System & Response to IE Bulletin 79-03 & 79-04" was accurately rephrased data for reactor pressure vessels
PARKER, M. D. Duke Power Co. 79/03/27. 1p

7903050590 Forwards IE Info Notice 79-06, "Interconnection of Contaminated Bays with Air Gas Used as Source of Breathing Air"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/26. 2pp

7903050536 Forwards IE Info Notice 79-09, "Bill of Materials/Inventory Contaminated Basin"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/26. 2pp

7903050579 Responds to IE Bulletin 79-02 re longitudinal weld defects on ASME B-W-312, Type 304 piping on or after welding w/ a filler metal piping w/ a toughness holding in its use or planned for use
PARKER, M. D. Duke Power Co. 79/04/04. 1p

7903050596 Forwards responses to IE Bulletin 79-08 & 79-09A, "Nuclear Incident at TH-1"
PARKER, M. D. Duke Power Co. 79/04/10. 3pp

7903050599 Forwards Abnormal Occurrence Rept 80-287/79-07
PARKER, M. D. Duke Power Co. 79/04/27. 1p

7903050501 80-287/79-07 on 790305-07 excessive reactor coolant age condition note occurred after operator error & failure of power-actuated pressurizer relief valve 360-64 to close
PARKER, M. D. Duke Power Co. 79/04/27. 1p

7903050603 Forwards add info re 80-287/79-07 corrective actions. Shutdown procedures revised; relief valves will be attended & speech unit repairs also replaced.
PARKER, M. D. Duke Power Co. 79/03/03. 2pp

7903050598 Ack receipt of 790305-10 re informing NRC of steps taken to correct violations noted in IE Insp Repts 80-046/79-04, 80-270/79-04 & 80-287/79-04
KARMA, M. D. Region 2, Atlanta, Safeguards Branch. 79/04/12. 1p

7903050604 Responds to NRC 790304-10 re violations noted in IE Insp Repts 80-046/79-04, 80-270/79-04 & 80-287/79-04 corrective actions withheld (ref 100967703)
PARKER, M. D. Duke Power Co. 79/03/26. 1p

7903050607 Forwards IE Insp Repts 80-046/79-04, 80-270/79-04 & 80-287/79-04 to 790305-06 Notice of violation withheld (ref 100967703)
KARMA, M. D. Region 2, Atlanta, Safeguards Branch. 79/03/04. 2pp

7903050607 IE Insp Repts 80-046/79-04, 80-270/79-04 & 80-287/79-04 to 790305-06 Notice of violation withheld (ref 100967703)
KARMA, M. D. Region 2, Atlanta, Office of the Director
KARMA, M. D. Region 2, Atlanta, Safeguards Branch. 79/03/04. 1p

7903050604 Responds to IE Bulletin 79-09A, Items 7.9, 10 & 11 re TH-1 incident all manual valves which could defeat or compromise flow are locked open.
PARKER, M. D. Duke Power Co. 79/04/12. 2pp

7903050617a Forwards IE Bulletin 79-04, "Review of Operational Error & Safety-Related Piping & Licensee action required"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14. 1p

7903050623 IE Bulletin 79-07, "Boron Offsets Analysis of Safety-Related Piping & Licensee action required"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14. 2pp

7903050631 Forwards IE Bulletin 79-08, "Events Related to Boiling Water Reactor Identified During TH-1 Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14. 1p

7903050640 Forwards IE Bulletin 79-09, "Failures of GC Type A-W-2 Circuit Breaker in Safety-Related Bays"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/17. 2pp

7903050657 Forwards IE Bulletin 79-09A, Revision 1, "Review of Operational Error & Safety-Related Piping & Licensee action required"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/10. 2pp

7903050652 Responds to IE Bulletin 79-05, Item 3, re TH-1 incident Reactor protection age high RCS pressure setpoint increased to not greater than 2,365 psig. Pressurizer power operated relief valve raised normally to 2,450 psig.
PARKER, M. D. Duke Power Co. 79/04/02. 1p

7903050639 Forwards responses to IE Bulletin 79-07 re computer program used for piping analysis. Algebraic summation methods were not used in piping analysis.
PARKER, M. D. Duke Power Co. 79/04/26. 2pp

7903050644 Forwards P90305 response to IE Bulletin 79-09B, Items 1-2, 4 & 5 re TH-1 incident.
PARKER, M. D. Duke Power Co. 79/03/05. 1p

7903050650 Responds to IE Bulletin 79-09B, Items 1, 2, 4 & 5 re Emergency procedures for loss of reactor coolant flow when supply w/ a repairable, uncontrolled flooding of turbine bldg & loss of normal IPE makeup or letdown have been revised.
PARKER, M. D. Duke Power Co. 79/03/05. 4pp

7903050655 Forwards Inservice Insp program
PARKER, M. D. Duke Power Co. 79/03/15. 1p

7903050656 Inservice Insp program
PARKER, M. D. Duke Power Co. 79/03/15. 2pp

7903050680 Forwards description of post-TH-1 operator training, per 790305 discussions & IE Bulletin 79-05, 79-08A & 2. Operating status have adequate knowledge to operate reactor in all modes.
PARKER, M. D. Duke Power Co. 79/03/16. 4pp

B. Periodic operating reports & related correspondence

7903050618 Forwards Monthly operating report for Apr 1979
PARKER, M. D. Duke Power Co. 79/05/15. 1p

7903050633 Monthly operating report for Apr 1979
PARKER, M. D. Duke Power Co. 79/05/15. 1pp

7903050617 80-287/79-07 on 790305-07 excessive reactor coolant age became erratic. Feedwater problem resulted from operation of the same feeder valve. Power tests have been failed.
PARKER, M. D. Duke Power Co. 79/03/13. 2pp

7903050673 Describes 80-267/79-10, which was to have been suggested 790305 re removal from art of high pressure act water pump. Caused by leakage from water cooler. Cooler repaired & returned to use.
PARKER, M. D. Duke Power Co. 79/04/13. 1p

7903050682 Forwards LER 79-03/03-0-0.
PARKER, M. D. Duke Power Co. 79/04/27. 1p

DOCKETED ITEMS

55

7905030340 LTR 79-010/03-0 on 790501 & 23 redundant high pressure wet water pump & 14 redundant pumps was out of sync to repair leakage from pump water meter. Last source required 5 replacement meters ordered
14010.0 M Duke Power Co 79/04/27 3pp

7905030303 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 LTR 79-032/020-0 on 790419 during performance test. HB spray gun 12 declared inoperative. Caused by water leakage through pipe threads on short vent line on pump during Vent line replaced & other TB spray pumps inspected
14010.0 M Duke Power Co 79/05/03 3pp

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/21 1p

7905030408 LTR 79-010/01-0 on 790507 quadrant power test exceeded steady state limit w/o nuclear overpower trip setpoint being reduced. Caused by difference in core inlet temp which occurred as result of conditions required for reactor test
14010.0 M Duke Power Co 79/05/02 3pp

7905030403 Forwards LTR 79-010/01-0 on 790507
14010.0 M Duke Power Co 79/05/21 1p

7905030407 LTR 79-010/01-0 on 790507 nuclear instrumentation phase indications from dual channel power levels caused by changes in core characteristics which accompany changes in power levels
14010.0 M Duke Power Co 79/05/21 3pp

REACTOR 50-240 REACTOR NUCLEAR STATION, UNIT 2

I Security, medical, emergency & fire protection plans
7905030301 Forwards 790501 submission of security plan for storage of spent fuel & 790501 action re requirement for security plan note initial plan in work in unclassified from public record of transmission is required
14010.0 M Duke Power Co 79/05/27 1p

7905030301 Forwards emergency procedure 790501/020/04, "Loss of Reactor Load," containing instructions for operator action for fuel leaks
14010.0 M Duke Power Co 79/05/09 2pp

II General correspondence
7905030301 Forwards emergency procedure 790501/020/04, "Loss of Reactor Load," containing instructions for operator action for fuel leaks
14010.0 M Duke Power Co 79/05/09 2pp

III General correspondence
7905030301 Forwards emergency procedure 790501/020/04, "Loss of Reactor Load," containing instructions for operator action for fuel leaks
14010.0 M Duke Power Co 79/05/09 2pp

7905030301 LTR 79-010/03-0 on 790501 & 23 redundant high pressure wet water pump & 14 redundant pumps was out of sync to repair leakage from pump water meter. Last source required 5 replacement meters ordered
14010.0 M Duke Power Co 79/04/27 3pp

7905030303 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

J Insurance & Indemnity Information

7905030301 LTR 79-010/03-0 on 790501 & 23 redundant high pressure wet water pump & 14 redundant pumps was out of sync to repair leakage from pump water meter. Last source required 5 replacement meters ordered
14010.0 M Duke Power Co 79/04/27 3pp

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

K Operating license change documents & correspondence

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

7905030301 Forwards LTR 79-010/03-0 on 790501 & 23
14010.0 M Duke Power Co 79/05/01 1p

DOCKETED ITEMS

57

7905240492 Responds to EC Bulletin 79-05, item 3, re TWO Incident Reactor protective sys high RCS pressure setpoint lowered to set greater than 20.250 psig Pressurizer power operated relief valve raised minimally to 20.450 psig
PARKER, W D Duke Power Co 79/04/21 1p

7905240502 Forwards response to SF Bulletin 79-07 re computer program used for piping analysis ALGEBRAIC symbolic methods were not used in piping analysis
PARKER, W D Duke Power Co 79/04/24 2pp

7905110264 Forwards 790502 response to EC Bulletin 79-05, items 1, 2, 4 & 5 re TBI incident
PARKER, W D Duke Power Co 79/05/05 1p

--7905110509 Responds to EC Bulletin 79-05, items 1, 2, 4 & 5 Emergency procedures for loss of reactor coolant flow when supply was ruptured, uncontrollable flooding of turbine bldg & loss of normal IPI makeup or letdown have been revised
PARKER, W D Duke Power Co 79/05/08 2pp

7905100741 Forwards insurance loss program
PARKER, W D Duke Power Co 79/05/13 1p

--7905050090 Insurance loss program
Duke Power Co 79/05/13 7pp

7905220191 Forwards description of post-TBI operator training, PWR 790519 discussions & EE Bulletin 79-05, 19-05A & B Operating shifts have adequate knowledge to operate reactors in all modes
PARKER, W D Duke Power Co 79/05/14 4pp

8. Periodic operating reports & related correspondence

7905200301 Forwards monthly operating report for Apr 1979
PARKER, W D Duke Power Co 79/05/13 1p

--7905200305 Monthly operating report for Apr 1979
PARKER, W D Duke Power Co 79/05/13 1pp

9. Reportable occurrences, LERs & related correspondence

7905020147 Forwards LER 79-010/033-0
PARKER, W D Duke Power Co 79/04/27 1p

--7905020340 LER 79-010/033-0 on 790513 & 25 redundant high pressure svc water pump & inoperable valve pump & use not of svc to repair leakage from pump motor cooler Leak source repaired & replacement cooler ordered
LEWIS, R H Duke Power Co 79/04/27 3pp

7905100574 Forwards LER 79-050/031-0
PARKER, W D Duke Power Co 79/05/11 1p

--7905100544 LER 79-050/031-0 on 790511 during monthly performance test, pressurizer sample valve QC-7 failed to close on actuation
PARKER, W D Duke Power Co 79/05/11 1p

J Insurance & Indemnity Information

7905010241 Forwards GA Carlson ltr re Price-Anderson act retroactive insurance premiums
BUEHL, R Green Mountain Power Corp 79/05/15 3pp

7905070497 Confirms increased liability limit to \$124,000,000 per policy, MF-1, 25, 43, 76, 82, 100, 111, 140, 146, 151, 161, 174, 175, 176, 179, 189, 190, 193, 194, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 212, 214, 215 & 216
SMITH, TROSCHEID, J American Nuclear Resources 79/05/01 1p

7905070569 Confirms increase in liability limit to \$34,000,000 per policy, MF-25, 43, 76, 82, 100, 111, 140, 146, 151, 161, 174, 175, 176, 179, 189, 190, 193, 194, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 212, 214, 215 & 216
SMITH, TROSCHEID, J American Nuclear Resources 79/05/01 1p

7905160215 Forwards Amend T to Indemnity Agreement B-49, per 10CFR145 changes, re liability insurance increase from \$100 million to \$150 million, effective 790501 Supporting documentation sent
BALTIMORE, J Ashby & Indemnity Group 79/05/01 2pp

7905100341 Forwards Amend R to Indemnity Agreement B-49 re increase in liability insurance, effective 790501
CAREY, W M Vermont Yankee Nuclear Power Corp 79/05/11 2pp

8. Generating license stage documents & correspondence

7905050039 Responds to 770420 ltr requesting amend delay in Licensee 10CFR20.35 requirements Review amend delay in Licensee 10CFR20.35 requirements Review amend delay in Licensee 10CFR20.35 requirements
GILBERT, B R Assistant Director for Engineering & Projects 79/04/11 2pp

7905050429 Supplementa 790404 ltr re environ qualification of Class 1K equipment Limit violation will be repaired within 30 days
GILBERT, B R Assistant Director for Engineering & Projects 79/04/24 1p

7905270058 Responds to 790413 request re QA program Supports revision number of 790413 ltr to be designated
GILBERT, B R Vermont Yankee Nuclear Electric Co 79/04/24 1p

7905070058 Forwards Revision 5 to Amend 1 to Revision 6 of operational QA program as requested in 790410 ltr
GILBERT, B R Vermont Yankee Nuclear Electric Co 79/04/30 4pp

--7905070058 Inform ltr revisions to QA program are acceptable
GILBERT, B R Quality Assurance Branch 79/04/10 17pp

7905100317 Responds to MEC 790312 ltr requesting schedule for completion of Part 2 containment program structural & major and planned for completion before Dec 1980
GILBERT, B R Vermont Yankee Nuclear Power Corp 79/05/06 3pp

7905160215 Forwards add ltr re Tech Spec changes to Average power reboiler gain adjustment
HARRIS, R E Vermont Yankee Nuclear Power Corp 79/05/09 2pp

DOCKETED ITEMS

D Inspection reports, IE Bulletins & correspondence

790510030 Forwards IE Insp Rept 30-071/79-04 on 790323-16 & 21-02 No noncompliance noted
 EPPENBERG, R J Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/22 2pg

--790510094 IE Insp Rept 30-071/79-04 on 790323-16 & 21-02 No noncompliance noted Major areas inspected plant operations, organization & administration, onsite review committee, LERs & licensee action on previous findings
 STEWART, F J, FOLEY, J Region I, Philadelphia, Office of the Director
 REAGAN, R C Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/19 14pg

790510150 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
 CRIST, B H Region I, Philadelphia, Office of the Director 79/03/22 1p

790510073 Forwards IE Info Notice 79-06, "Interconnection of Contaminated Gas w/Boiler Air Gas Used as Source of Breathing Air"
 CRIST, B H Region I, Philadelphia, Office of the Director 79/03/22 1p

790510036 Forwards IE Info Notice 79-06, "Spill of Radioactively Contaminated Resin"
 CRIST, B H Region I, Philadelphia, Office of the Director 79/03/22 1p

790510060 Responds to IE Bulletin 79-03 re welding defects No further action required since same weld inspection requirement in ASME III Only plants fabricated under these rules are affected
 HOSBY, D E Vermont Yankee Nuclear Power Corp 79/03/20 1p

790510019 Forwards IE Bulletin 79-04, "Review of Operational Errors & Misalignments Identified During TMI Incident"
 CRIST, B H Region I, Philadelphia, Office of the Director 79/04/11 1p

790510060 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
 CRIST, B H Region I, Philadelphia, Office of the Director 79/04/14 1p

790510018 Forwards IE Bulletin 79-04, "Review of Operational Errors & Misalignments Identified During TMI Incident"
 CRIST, B H Region I, Philadelphia, Office of the Director 79/04/14 1p

790510027 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Reactors Identified During TMI Incident"
 Licensee action required
 CRIST, B H Region I, Philadelphia, Office of the Director 79/04/14 1p

790510018 Forwards IE Bulletin 79-08, "Failures of One Type AWD Circuit Breaker in Safety-Related Gas" Licensee action required
 CRIST, B H Region I, Philadelphia, Office of the Director 79/04/17 1p

790510030 Forwards IE Bulletin 79-04a/Revision 1, "Review of Operational Errors & Misalignments Identified During TMI Incident"
 CRIST, B H Region I, Philadelphia, Office of the Director 79/04/18 1p

790510100 Submits second request for six month delay until 8/00/86 for implementation of pump & valve testing portion of updated Inservice Insp Program
 WARDENBURG, S E Vermont Yankee Nuclear Power Corp 79/04/20 2pg

790510050 Forwards Class III license amend fee for decrease insp charges to Each Spec Bellevue fee schedule is 110000
 Submits fee vendor protest via upcoming right to contract fee validity
 GRACE, S M Vermont Yankee Nuclear Power Corp 79/04/23 2pg

790510040 Forwards proposed "Inservice Insp Program" w/18 sgs flow drawings
 CRIST, B H Vermont Yankee Nuclear Power Corp 79/04/23 2pg

--790510040 "Inservice Insp Program" exam schedule & sgs flow drawings
 PLUMBAGE, J, WILKINSON, B C, HODGE, T E Vermont Yankee Nuclear Power Corp 79/04/23 23pg

790510009 Submits addl info to 790427 response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping
 WOLFE, R M Vermont Yankee Nuclear Power Corp 79/05/04 2pg

H Periodic operating reports & related correspondence

790510060 Forwards "Ecological Studies of CT River, Vernon, VT." sgs
 WILSON, D Vermont Yankee Nuclear Power Corp 79/04/23 1p

--790510042 "Ecological Studies of CT River, Vernon, VT." Rept WILSON
 Vermont Yankee Nuclear Power Corp 79/04/23 10pg

790510060 Forwards "Hydrothermal & Biological Studies of CT River, Vernon, VT. Phase V." Oct 1977-May 1978
 HARRIS, J Vermont Yankee Nuclear Power Corp 79/05/01 1p

790510062 "Hydrothermal & Biological Studies of CT River, Vernon, VT. Phase V." Oct 1977-May 1978
 Vermont Yankee Nuclear Power Corp 79/05/21 10pg

790510041 Forwards monthly operating rept for Apr 1979
 HOSBY, D E Vermont Yankee Nuclear Power Corp 79/05/12 1p

--790510042 Monthly operating rept for Apr 1979
 HOSBY, D E Vermont Yankee Nuclear Power Corp 79/05/12 1p

I Reportable occurrences, LERs & related correspondence

790510020 Forwards LER 79-011/02, -0
 CONWAY, W F Vermont Yankee Nuclear Power Corp 79/05/03 1p

--790510053 LER 79-011/02, -0 on 790403 spring plate of actuator was stuck on guide staffs. Caused by rough surface on guide staffs. Surface smoothed & verified operable
 CONWAY, W F Vermont Yankee Nuclear Power Corp 79/05/03 2pg

790510007 Forwards LER 79-001/02, -1
 CONWAY, W F Vermont Yankee Nuclear Power Corp 79/05/23 1p

--790510040 LER 79-001/02, -1 on 790110 through well leak near reactor water cleanup was action piping noted. Caused by cracks in well neck due to improper welding. Corrected. Repairs made & sgs returned to svc
 CONWAY, W F Vermont Yankee Nuclear Power Corp 79/05/23 2pg

DOCKET 80-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

E NRC Safety Evaluation Report (SER), sgs & correspondence

790510019 Forwards SER & SER w/smt
 SMITH, B H Branch 2 79/05/25 1p

G Adjudicatory correspondence

790510030 Forwards resolution of storage of spent fuel in Lower Alloways Creek Township, NJ
 HOSBY, D E, J Pennsylvania, NJ 79/05/04 1p

--790510030 Resolution opposing increase in spent fuel storage credits at plant in Lower Alloways Creek Township, NJ
 SPANGL, S M, HOSBY, D E, J Pennsylvania, NJ 79/05/01 2pg

790510023 Answer of Intervenor Township of Lower Alloways Creek, NJ seeking denial of licensee motion for summary disposition
 Statement of mail facts affidavit & Certificate of Mvt and
 VALERIE, C Lower Alloways Creek, NJ 79/05/12 1pg

790510041 Forwards Amend 42 to PWR, per 790513 prehearing conference
 PERLIN, S Public Service Electric & Gas Co of New Jersey 79/05/26 1p

790510040 Discusses actions taken at 790513 prehearing conference
 Possible settlement & consolidation of concerns.
 Identification of witnesses & social of action to consolidate conferences discussed. Hearing schedule set.
 MILLER, S G, Atomic Safety and Licensing Board Panel 3 79/05/27 1pg

790510010 Response in support of licensee's action for summary disposition Forwards response to licensee's statement of facts Forwards licensee's statement in support of its motion for summary disposition
 SMITH, B H, HOSBY, J E Branch 2 79/05/30 1p

--790510010 Response to licensee's statement of mail facts. No genuine
 SMITH, B H, HOSBY, J E Branch 2 79/05/30 1pg

DOCKETED ITEMS

6 Inspect 4000 Reports, IE Bulletin & correspondence

7905010130 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
GRIER, S. H. Region 1, Philadelphia, Office of the Director
79/03/23 1p

7905010049 Forwards IE Info Notice 79-02, "Interconnection of Contaminated Sps w/Hot Air Sps w/As Source of Breaching Air"
GRIER, S. H. Region 1, Philadelphia, Office of the Director
79/03/28 1p

7905010320 Forwards IE Info Notice 79-06, "Spill of Radioactive Contaminated Waste"
GRIER, S. H. Region 1, Philadelphia, Office of the Director
79/03/30 1p

7905010345 Response to IE Bulletin 79-03, "On safety-related pipe assemblies from Youghioghenis and Engineering Co are used"
SCHNEIDER, P. M. Public Service Electric & Gas Co. of New Jersey
79/04/04 2pp

7905020019 Forwards IE Bulletin 79-06, "Review of Operational Errors & Spill Investigations Identified During TMI Incident - Licensee action required"
GRIER, S. H. Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905010133 Act receipt of 790323 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-272/79-08
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
79/04/11 1p

7905010140 Response to NRC 790323 ltr re violation noted in IE Insp Rpt 50-272/79-08 corrective action operators restructured; reactor engineering manual revised & surveillance procedures revised
SCHNEIDER, P. M. Public Service Electric & Gas Co. of New Jersey
79/03/23 2pp

7905010145 Forwards IE Insp Rpt 50-272/79-08 on 790213-16 & notice of violation
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
79/03/25 2pp

7905010149 Notice of violation from Insp on 790213-16
Region 1, Philadelphia, Office of the Director
79/03/25 1p

7905010158 IE Insp Rpt 50-272/79-08 on 790213-16 Nonconformance noted surveillance procedures for determination of axial flow not performed as required
CONTE, M. J., BLUMBERG, H. Region 1, Philadelphia, Office of the Director
BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch
79/03/28 12pp

7905010025 Forwards IE Bulletin 79-06, "Review of Operational Errors & Spill Investigations Identified During TMI Incidents"
GRIER, S. H. Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905010273 Forwards IE Bulletin 79-06, "Events Relating to Duffing Motor Power Reactors Identified During TMI Incident"
GRIER, S. H. Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905010053 Forwards IE Bulletin 79-02, "Stress Analysis of Safety-Related Piping - Licensee action required"
GRIER, S. H. Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905020008 Forwards IE Bulletin 79-06, "Failure of IE Type 40-2 Circuit Breaker in Safety-Related Sps" Licensee action required
GRIER, S. H. Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905010017 Forwards IE Bulletin 79-06, Revision 1, "Review of Operational Errors & Spill Investigations Identified During TMI Incident"
GRIER, S. H. Region 1, Philadelphia, Office of the Director
79/04/18 1p

7905010012 Response to IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping - Provides results of Westinghouse analysis of reactor coolant loop 1 Loop Home Class 1"
SCHNEIDER, P. M. Public Service Electric & Gas Co. of New Jersey
79/05/03 2pp

H Periodic operating reports & related correspondence

7905010140 Forwards Mar 1979 operating rpt for industrial waste treatment plant
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/08 2pp

7905010146 Forwards Mar 1979 wastewater treatment rpt for sewage treatment plant
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/12 2pp

7905010147 Forwards rpt of subsurface water diversion & effluent control of unit water for water making 790221
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/16 2pp

7905010350 Forwards "Implementation Monitoring Program Rpt 24" for Mar 1979
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/28 2pp

7905010142 Forwards Natl Pollution Discharge Elimination Rpt discharge monitoring rpt for Mar 1979
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/28 13pp

7905010147 Forwards "Operating Rpt for Apr 1979 for Industrial Waste Treatment Plant"
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/05 1p

7905010142 "Operating Rpt for Apr 1979 for Industrial Waste Treatment Plant"
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/05 1p

7905010295 Forwards monthly operating rpt for Apr 1979
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/05 1p

7905010298 Monthly operating rpt for Apr 1979
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/05 13pp

7905010143 Forwards Apr 1979 wastewater treatment rpt for sewage treatment plant
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/10 2pp

7905010143 Forwards discharge monitoring rpt for Apr 1979
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/05 12pp

S Reportable occurrences, SGRs & related correspondence

7905010075 Confirms 790405 taken re EO 79-38/01P high pressure flame pump act of NRC per planned main fire suppression water header pressure around below 125 psig & five pump 2 did not start act as req
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/28 1p

7905010145 EO 79-38/01P re apparent design deficiency associated differential rates protection currently evaluating solution involving design change
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/11 1p

7905010125 Forwards Ltr 79-036/011-0
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/24 1p

7905010125 Ltr 79-036/011-0 re 790410-0111 notified of design deficiency re differential rates not meeting seismic design qualifications. Problem notice in both units delays will be disconnected until design change implemented
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/26 2pp

7905010141 Confirms EO 79-41/01P on 790425 re missing water tube plug. Subsequent investigation have not located missing reactor coolant piping.
MILMAN, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/26 1p

DOCKETED ITEMS

61

7905040308 Forwards LER 79-031/03L-0
LBR121.F P Public Service Electric & Gas Co. of New Jersey
79/04/27 1p

--7905040341 LER 79-031/03L-0 on 790329 ISO elevation containment
personnel air lock failed to pass leak rate test. Caused by
split inner door seal snagged by waste object passing through
door seal replaced
KAPPLC.A M Public Service Electric & Gas Co. of New Jersey
79/04/27 3pp

7905040370 Forwards LER 79-032/03L-0
LBR121.F P Public Service Electric & Gas Co. of New Jersey
79/04/30 1p

--7905040371 LER 79-032/03L-0 on 790330 during normal operation, auxiliary
ignition started printing meaningless messages. Caused by
failed solid state component & circuit board in ignitor
logic control cabinet component board replaced
KAPPLC.A M Public Service Electric & Gas Co. of New Jersey
79/04/30 3pp

7905040408 Forwards LER 79-034/03L-0
LBR121.F P Public Service Electric & Gas Co. of New Jersey
79/05/01 1p

--7905040428 LER 79-034/03L-0 on 790331 Loop 12 shunt line pressure 100
psi less than Loop 11. Caused by failed evaporator module
Compressor calibrator & channel setpoints verified
KAPPLC.A M Public Service Electric & Gas Co. of New Jersey
79/05/01 3pp

7905100227 Forwards LER 79-011/01L-2
LBR121.F P Public Service Electric & Gas Co. of New Jersey
79/05/02 1p

--7905100238 LER 79-011/01L-2 on 790114 RMC channel which had alarmed &
cleared had been reset at control console but not at RMC
panel. Caused by procedure inadequacy. Procedure changed
initiated to clarify functions
KAPPLC.A M Public Service Electric & Gas Co. of New Jersey
79/05/02 3pp

7905100444 Forwards LER 79-041/01T-0
LBR121.F P Public Service Electric & Gas Co. of New Jersey
79/05/09 1p

--7905100446 LER 79-041/01T-0 on 790425 loss of eddy current template
plug assembly inside reactor coolant sys. Caused by error of
contractor maint supervisor. Supervisor will be properly
instructed
KAPPLC.A M Public Service Electric & Gas Co. of New Jersey
79/05/09 3pp

7905100442 Forwards LER 79-027/03L-0
LBR121.F P Public Service Electric & Gas Co. of New Jersey
79/05/11 1p

--7905100444 LER 79-027/03L-0 on 790416 source range nuclear
instrumentation channel N-02 indication became erratic
Caused by disconnected shield on source range high voltage
drawer connector. Drawer connection reconnected
KAPPLC.A M Public Service Electric & Gas Co. of New Jersey
79/05/11 3pp

7905200127 Forwards LER 79-038/03L-0
LBR121.F P Public Service Electric & Gas Co. of New Jersey
79/05/15 1p

--7905200132 LER 79-038/03L-0 on 790417 ground fault on station power
Transformer 21 resulted in loss of Transformer 1, 5 & 25
Caused by failed cable in posthead supplying transformer
Failed cable & posthead replaced
KAPPLC.A M Public Service Electric & Gas Co. of New Jersey
79/05/15 3pp

7905200350 Forwards LER 79-039/03L-0
LBR121.F P Public Service Electric & Gas Co. of New Jersey
79/05/15 1p

--7905200314 LER 79-039/03L-0 on 790418 unit load/unloading meter Rods
when used were proper to remove reactor head. Caused by meter
supervisor not verifying that ROD had been brought up to
refueling station
KAPPLC.A M Public Service Electric & Gas Co. of New Jersey
79/05/15 3pp

7905200408 RD 79-43/01P on 790322 procedure to demonstrate operability
of steam driven auxiliary feedwater pump 1D permitted
discharge of discharge control valves. Procedure changed to
ensure operability.
HISBIA, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/22 1p.

T Hearing transcripts on non-contested matters

7905140558 Transcript of 790503 hearing in Salem, NJ Pg. 317-343
HILKEL, J. L. L. KORNBLITH, L. LAMB, J. C. Atomic Safety and Licensing
Board Panel 79/05/02 15pp

7905140561 Transcript of 790503 hearing in Salem, NJ Pg. 350-700
HILKEL, J. L. L. KORNBLITH, L. LAMB, J. C. Atomic Safety and Licensing
Board Panel 79/05/03 170pp

7905140558 Transcript of 790504 hearing in Salem, NJ Pg. 701-918
HILKEL, J. L. L. KORNBLITH, L. LAMB, J. C. Atomic Safety and Licensing
Board Panel 79/05/04 228pp

DOCKET NO-273 BENEVO NUCLEAR STATION, UNIT 1

0 Adjudicatory correspondence

7905160227 Review impact of TMS on upcoming hearings. Lists hearings
scheduled for Apr 5 May
CHURCHMAN, S. H. Branch 2 79/04/03 2pp

DOCKET NO-274 U S GEOLOGICAL SURVEY RESEARCH REACTION

0 Insurance & indemnity information

7905160244 Forwards Amend 9 to Indemnity Agreement D-10, per 10CR190
changes. Increase from \$140 million to \$140 million
effective 790505 Supporting documentation incl
SALTMAN, J. Arbitrator & Indemnity Group 79/05/01 3pp

7905130485 Forwards Amend 9 to Indemnity Agreement D-10
HARRINGTON, A. P. Interior Dept. w/ Geological Survey 79/05/02

DOCKET NO-275 CABLE CANYON NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

7905200274 Forwards replacement pages for Amends 1 & 4 to CFFR-24 &
CFFR-49
STOL, J. F. Light Water Reactors Branch 1 79/05/29 10pp

7905200490 Discusses 790318 telcon w/B. Bero of Westinghouse re
increased weights for Valves Model 2450 Orinck check valves
used in safety injection sys
SCHMIDT, A. Operating Reactors Branch 1 79/04/02 1p

7905200578 Updates event completion dates to 790620 for Unit 1 & 009229
for Unit 2
STOL, J. F. Light Water Reactors Branch 1 79/04/13 3pp

--7905200582 PR review ongoing extension of event completion dates to
790620 for Unit 1 & 009229 for Unit 2
BRYD, R. G. Division of Project Management 79/04/13 3pp

DOCKETED ITEMS

G Adjudicatory correspondence

7905030164 Request by intervenors Seismic (Shoreline Preservation Conference, San Luis Obispo Mothers for Peace Ecology Action Club, SA Silver & Jo Parker for late filing of proposed findings of fact & conclusions of law w/certificate of due diligence. D G Fleischaker. D G 79/02/25 App

--7905030175 Proposed findings of fact & conclusions of law by intervenors Seismic (Shoreline Preservation Conference, San Luis Obispo Mothers for Peace Ecology Action Club, SA Silver & Jo Parker, KRISTOVICH, D G, FLEISCHAKER, D G, PHILLIPS, J. R., KRISTOVICH, D G Center for Law in the Public Interest 79/03/25 App

--7905030202 Informa of inability to submit proposed findings of fact on adequacy of plant security systemized access to evidence & access to hearing on security plan Certificate of due diligence. D G Fleischaker, D G 79/03/25 App

7905030208 Group of 19 late protesting opening of facility. HANCOCK, R. H., KYLE, B. Affiliation Unknown 79/03/30 App

7905030113 Forward request for Board certification re nonseafly-grade equipment to mitigate transients. MCINTOSH, J. P. Hearings Division 79/04/02 App

--7905030136 Board certification staff assessment re nonseafly-grade equipment to mitigate transients. WARRALL, D. B. Assistant Director for Light Water Reactors 79/03/29 App

--7905030138 Board certification report issue on nonseafly-grade equipment to mitigate transients. More info to be required. WARRALL, D. B. Assistant Director for Light Water Reactors 79/03/16 App

7905040255 Request info on facility & earthquake safety w/nuclear power. SMITH, D. Affiliation Unknown 79/04/04 App

--7905040278 Requests that facility not be allowed to operate. HANZEN, R., HANZEN, R. Affiliation Unknown 79/05/30 App

7905030204 Motion of extension of time until 790410 to file proposed findings of fact & conclusions of law Certificate of due diligence. KETCHUM, B. O. Branch 2 79/04/24 App

7905030184 Grants NRC 790404 motion for extension until 790410 in which to file findings of fact. KETCHUM, B. O. Atomic Safety and Licensing Board Panel 79/04/03 App

7905030104 Write sheet to joint intervenors' proposed findings of fact & conclusions of law Certificate of due diligence. FLEISCHAKER, D. G., KETCHUM, B. O., KRISTOVICH, D. G. Center for Law in the Public Interest 79/04/03 App

7905050303 Responds to 790506 ltr re status of facility licensing. Significant record on proceeding closed 790502 last meeting scheduled to be filed by 790414. Practice date for initial decision cannot be made. NORD, J. R. Atomic Safety and Licensing Board Panel 79/04/04 App

7905030270 Forwards corrected pages to NRC 790410 proposed findings. Changing words "Initial Decision" to "Conclusions of Law". TOURTELLOTTIE, J. Branch 4 79/04/12 App

7905030724 Responds to 790506 & 790502 ltrs requesting denial of the ASL will consider issue. View to be included in docket file of proceedings. HANCOCK, R. H. Deputy Executive Legal Director 79/04/12 App

7905030598 Forwards resolution adopted re 790416 Resolution requests deferment of action on license application pending determination that safety systems are adequate to ensure public safety. HANCOCK, R. H. Santa Barbara County, CA 79/04/10 App

--7905030625 Resolution of Board of Supervisors of Santa Barbara Co., CA urging NRC to defer final action on license application until facility safety systems are adequate to ensure public safety. YAGER, D. H. Santa Barbara County, CA 79/04/14 App

7905030118 Responds to mail ltr opposing operation of facility because of proximity to active earthquake fault & concern for disposal of high level radioactive wastes. Motion being considered by ASL. KENDRICK, R. Division of Project Management 79/04/30 App

7905040364 Requests denial w/o prejudice of joint intervenors' motion to withhold issuance of DL Certificate of due diligence. TOURTELLOTTIE, J. Branch 4 79/04/02 App

7905030007 Response in opposition to joint intervenors' request to withhold issuance of DL Certificate of due diligence. KETCHUM, B. O. Pacific Gas & Electric Co. 79/04/04 App

7905030014 Ack receipt of 790405 & 790406 ltrs re opposition to operation of facility due to proximity to Hogshead Fault. Facility designed to withstand seismic event of 7.9 MBL in preparing decision re licensing based on 790503 hearing. SMITH, D. B. Office of Nuclear Reactor Regulation 79/03/14 App

--7905030019 Expresses opposition to operation of facility due to proximity to Hogshead Fault. MATHERS, D. E. Affiliation Unknown 79/04/26 App

--7905030020 Expresses opposition to operation of facility due to proximity to Hogshead Fault. MATHERS, D. E. Affiliation Unknown 79/04/26 App

H General correspondence

7905030482 Requests immediate halt to construction of facility. ANDERSON, R. House of Rep 79/04/02 App

7905070081 Notification of change of address for DR Brindenberg & AS. Husband to 1025 Hamilton Ave, Suite 100, San Jose, CA 95128. COOPER, K. F. RRB Technical Associates 79/04/25 App

7905050713 Requests suspension of DL until necessary safety made. App. Implementation. BRIDENBAUGH, D. G. California, State of 79/05/04 App

7905040245 Responds to 790502 ltr re constituent concerns re granting of license to facility. Seismic event of 7.9 magnitude can be withstood & quality of construction is controlled by license OR program. GIBBONS, L. W. Office of the Executive Director for Operations 79/05/08 App

I Financial information

7905030148 Forwards "Annual Financial Rept 1978." CHAMBERLAIN, A. Pacific Gas & Electric Co 79/03/20 App

--7905030174 "Annual Financial Rept 1978." Pacific Gas & Electric Co 79/03/31 App

7905030205 Forwards "Estimated Internal Fund Generation for CY79" & "Annual Financial Rept 1978." CHAMBERLAIN, A. Pacific Gas & Electric Co 79/03/24 App

--7905030205 "Annual Financial Rept 1978." Pacific Gas & Electric Co 79/03/25 App

DOCKETED ITEMS

63

J Insurance & Indemnity Information

7905140512 Forwards Amends 4 to Indemnity Agreement 8-75 per 10051410 changes re increases in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl
ENELMKN.H J Antitrust & Indemnity Group 79/05/01 App

7905140493 Forwards Amends executed Amends 25 & 4 to Indemnity Agreement 8-21 & 8-75, respectively
GRAMP.P A Pacific Gas & Electric Co 79/05/00 Dpp

D Advisory Committee on Reactor Safeguards reports & correspondence

7905100349 Responds to request for written report after cancellation of ACRS 790303 meeting re possibility of problem w/instrument guide tubes. Brief report encl
ENELMKN.H J Division of Project Management 79/03/03 App

F. Operating license stage documents & correspondence

7905020244 Responds to NRC 790314 request for addl info re containment purge values. Forwards results of CSRS/SLI program to calculate containment purge valve closing data coincident w/0204
GRAMP.P A Pacific Gas & Electric Co 79/04/10 App

7905020182 Forwards \$1,600 fee to extend CP. In response to NRC 790410 ltr. Negative acknowledgment
GRAMP.P A Pacific Gas & Electric Co 79/04/27 App

G Inspection reports, IE Bulletins & correspondence

7905040747 Forwards IC Insp Rpt 50-275/79-03 on 790220-02 Re noncompliance noted
ENELMKN.H J Region 3, San Francisco, Fuel Facility & Materials Safety Branch 79/03/19 App

7905030574 IC Insp Rpt 50-275/79-03 on 790220-02 Re noncompliance noted. Major areas inspected: emergency planning facilities & equipment, training, radiation protection staffing, radioactive waste sys & Offsite Dose Calculation. Manual
ENELMKN.H J Region 3, San Francisco, Fuel Facility & Materials Safety Branch 79/03/19 App

7905030447 Forwards IC Insp Rpts 50-275/79-03 & 50-0323/79-03 on 7904-09 & 50. No noncompliance noted.
ENELMKN.H J Region 3, San Francisco, Reactor Operations Nuclear Support Branch 79/03/25 App

7905030440 IC Insp Rpts 50-275/79-03 & 50-0323/79-03 on 790409-09 & 13. No noncompliance noted. Major areas inspected: preoperational testing, evaluation & verification of test results, IE building & circulation followed
ENELMKN.H J Region 3, San Francisco, Office of the Director
ENELMKN.H J Region 3, San Francisco, Reactor Operations Nuclear Support Branch 79/03/25 App

7905050587 Forwards IF Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ENELMKN.H J Region 4, Dallas, Office of the Director 79/05/03 App

7905040801 Forwards IE Info Notice 79-07, "Review of Radiaste Tanks"
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/03/26 App

7905050547 Forwards IC Insp Rpt 50-275/79-03 on 790220-02 Re noncompliance noted.
ENELMKN.H J Region 3, San Francisco, Reactor Operations Nuclear Support Branch 79/04/10 App

7905050547 Forwards IC Insp Rpt 50-275/79-03 on 790220-02 Re noncompliance noted. Major areas inspected: preoperational testing, plant start-up, safety verification testing & fuel storage
ENELMKN.H J Region 3, San Francisco, Office of the Director
ENELMKN.H J Region 3, San Francisco, Reactor Operations Nuclear Support Branch 79/04/10 App

7905050603 Forwards IC Bulletin 79-04A, "Review of Operational Errors & Misalignments Identified During IMI Incident,"
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/14 App

7905040809 Forwards IC Bulletin 79-04B, "Review of Operational Errors & Misalignments Identified During IMI Incident,"
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/14 App

7905070099 Forwards IC Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." License action required
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/14 App

7905030291 Forwards IE Bulletin 79-08, "Failure of GE Type AP-2 Circuit Breaker in Safety-Related Sys." License action required
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/17 App

7905050366 Forwards IE Bulletin 79-09, "Nuclear Incident at IMI-Suppl."
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/21 App

H Repairable occurrences, LERs & related correspondence

7905150003 Board notification Seabrook refueling water storage tank design deficiency
ENELMKN.H J Hearings Division 79/03/29 App

7905150040 Forwards PNO-79-67L
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/05 App

7905150367 Forwards PNO-79-67M
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/11 App

7905040123 Forwards PNO-79-67E
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/12 App

7905150141 Forwards PNO-79-67F
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/12 App

7905150041 Forwards PNO-79-67U
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/14 App

7905050507 Forwards PNO-79-67AA
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/20 App

7905104225 Forwards PNO-79-67AB
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/21 App

7905104444 Forwards PNO-79-67AC & AD
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/22 App

7905050507 Forwards PNO-79-67AF
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/20 App

7905050507 Forwards PNO-79-67AG
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/20 App

7905070005 Forwards PNO-79-67AH
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/04/21 App

7905050507 Forwards PNO-79-67AL summary of items re -----
7905050507 Forwards PNO-79-67AL summary of items re -----
Office of Inspection & Review status 79/04/22 App

7905070007 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-05
ENELMKN.H J Region 3, San Francisco, Office of the Director 79/05/01 App

7905050330 Nucleon followup report to 790404 notification of WD Opening progress of routine weld repairs on pipe rupture restrainers. Corrective discovered in immediate vicinity of repairs full report will be submitted
GRAMP.P A Pacific Gas & Electric Co. 79/05/03 App

DOCKETED ITEMS

790810007Z Forwards PWG-74-47AM
ENCLAREN R H Region 5, San Francisco Office of the Director
200000Z 10

7905140403 Forwards Amend 20 to Indemnity Agreement to change re increase in liability insurance from \$1.5 billion to \$350 million effective 790501 (Supporting document) 001

750220047 Forwards Endorsement 04 to AMI February 1964
BUDLEY, E J Philadelphia Electric Co 14 1 64 117

T. Haecia fraxetula on cornelinated mallee

F. Operating license stage documents & turnover to us

7902240084 informs that Amend 33 to PHAR (100-444444) is in response to WRC 790221 request
GAL190FF, S L Philadelphia Electric Co 100-444444

DOCID: 32-276, G609354, TECH. RESEARCH PROJECT

2. Insurance & Identity Information

7903030348 Forwards application for award of 100,000 shares of common stock to the
 fee
 BRADLEY, E J Philadelphia Electric Co 100,000 shares of common stock

© Jesselton resorts, IE Holdings & arrangements

==700500032 Application for amend of license: to be a
surveillance frequency to reflect change: at a
from 12 to 0 months Certificate of No: a
DAUER, E O. BRADLEY, E J Philadelphia Pa. 19101
das

DOCKET 99-272 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

Q Adjudicators correspondence

790910673 Forwards application for award of \$1,000.
BOWLEY, E J Philadelphia Electric Co

Tech Specs re reactor vessel mail enclosure, 4 x 4 ft
Certificate of Grc and
a Philadelphia Electric Co. Transformer 1912

1985270045 Forwards schedule for implementation of the
necessary for long-term program development
to be completed during Spring 1980 refueling
to Spring 1981 for Unit 3

7903300000 Forward's summary of LSI Waiver in 1991
of silicon flexibility error which existed in 1990 - 1991

Review & reanalysis included all work by: p# 1 1
PORTER, F L. CBS Nuclear, Inc. 7/9/75/24 - 11

2 Insurance & Identity Information

could have been impacted by deficient computer systems.
OE has no record of maintenance for equipment used in the
STEPHENSON General Electric Co. Review Case.
7/9/01/24 10pp

0 Inspection report; E. Ballentine & Associates, Inc.

DOCKETED ITEMS

66

7903020032 Forwards IF Bulletin 79-06: "Review of Operational Errors & Missions Identified During The Incident"
GRIFFIN, E. J. Region I, Philadelphia, Office of the Director
79/04/14 1p

7903020044 Ack receipt of 790314 Ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 90-277/79-02 & 90-278/79-02
GRIFFIN, E. J. Region I, Philadelphia, Fuel Facility & Materials Safety Branch
79/04/12 1p

7903020070 Response to NRC 790228 Ltr re violations noted in IL Insp Repts 90-277/79-02 & 90-278/79-02 corrective actions detailed station procedures proposed & approved & surveillance test procedures revised
DALY, J. H. Region I, Philadelphia Electric Co
79/03/16 3pp

7903020072 Forwards IL Insp Repts 90-277/79-02 & 90-278/79-02 on 790228-05 & 06 to NRC of violations
GRIFFIN, E. J. Region I, Philadelphia, Fuel Facility & Materials Safety Branch
79/02/26 1pp

7903020073 Notice of violation from Insp on 790124 03 & 04 to a Region I, Philadelphia, Office of the Director
79/04/14 3pp

7903020075 IL Insp Repts 90-277/79-02 & 90-278/79-02 on 790124-03 & 04 on noncompliance noted failure to maintain efficient valves within Tech Spec limits & failure to have procedures for lock loss & closure
DALY, J. H. Region I, Philadelphia, Office of the Director
79/04/14 2pp

7903020076 Forwards IL Insp Repts 90-277/79-02 & 90-278/79-02 on 790124-03 & 04 on noncompliance noted
DALY, J. H. Region I, Philadelphia, Office of the Director
79/04/14 3pp

7903020125 IL Insp Repts 90-277/79-02 & 90-278/79-02 on 790124-03 & 04 on noncompliance noted Major areas inspected plant operations, facility tour, H. circular fallow & H. review in aft. & on site
GRIFFIN, E. J. Region I, Philadelphia, Office of the Director
79/04/14 3pp

7903020242 Forwards IF Bulletin 79-06: "Review of Operational Errors & Missions Identified During The Incident"
GRIFFIN, E. J. Region I, Philadelphia, Office of the Director
79/04/14 1p

7903040034 Forwards IF Bulletin 79-06: "Review of Operational Errors & Missions Identified During The Incident"
GRIFFIN, E. J. Region I, Philadelphia, Office of the Director
79/04/14 1p

7903040229 Forwards IF Bulletin 79-06: "Review of Operational Errors & Missions Identified During The Incident"
GRIFFIN, E. J. Region I, Philadelphia, Office of the Director
79/04/14 1p

7903050038 Forwards IF Bulletin 79-06: "Review of Operational Errors & Missions Identified During The Incident"
GRIFFIN, E. J. Region I, Philadelphia, Office of the Director
79/04/14 1p

7903050039 Forwards IF Bulletin 79-06: "Review of Operational Errors & Missions Identified During The Incident"
GRIFFIN, E. J. Region I, Philadelphia, Office of the Director
79/04/14 1p

7903050037 Forwards IF Insp Repts 90-277/79-02 & 90-278/79-02 on 790409-02 & notice of violation
DALY, J. H. Region I, Philadelphia, Reactor Operations Nuclear Support Branch
79/04/20 3pp

7903050214 Notice of violation from Insp on 790409-02
Region I, Philadelphia, Office of the Director
79/04/19 3pp

7903050223 IL Insp Repts 90-277/79-02 & 90-278/79-02 on 790409-02 on noncompliance noted improper valve positioning & positive control, improper approval & review
GRIFFIN, E. J. Region I, Philadelphia, Office of the Director
79/04/19 3pp

II Periodic operating reports & related correspondence

7903040044 Forwards Annual Plant Rad Rep 1978
ALLEN, H. H. Philadelphia Electric Co
79/04/27 1p

7903040045 Annual Plant Rad Rep 1979
ALLEN, H. H. Philadelphia Electric Co
79/02/21 12pp

7903040036 Forwards monthly operating report for Apr 1979
GRIFFIN, E. J. Philadelphia Electric Co
79/05/11 1p

7903040041 Monthly operating report for Apr 1979
ALLEN, H. H. Philadelphia Electric Co
79/05/10 9pp

III Reportable occurrences, LDEs & related correspondence

7903020080 Forwards LER 79-007/017-0
GRIFFIN, E. J. Philadelphia Electric Co
79/02/15 1p

7903020084 LER 79-007/017-0 on 790125 standby gas treatment gas system valve was not opened following leak sensor test
Caused by operator error Operator was retrained in proper procedures
GRIFFIN, E. J. Philadelphia Electric Co
79/02/15 1p

7903040070 LER 79-012/012-0 on 790228 2 hr logic APCD area damp switches 17P-0910, 420-420, 440-440 indicated less than 50% closing routine surveillance caused by dirty contacts
as power supply for damp switch card unit
GRIFFIN, E. J. Philadelphia Electric Co
79/04/23 1p

7903040077 Forwards LER 79-012/012-0
GRIFFIN, E. J. Philadelphia Electric Co
79/04/26 3pp

7903040092 LER 79-012/012-0 on 790411 engineering review discovered valve associated with electrically qualified emergency vent water system was normally open caused by faulty plant design
Open valves locked closed
GRIFFIN, E. J. Philadelphia Electric Co
79/04/26 1p

7903040094 Forwards LER 79-012/012-0
GRIFFIN, E. J. Philadelphia Electric Co
79/04/27 3pp

7903050036 LER 79-012/012-0 on 790411, effluent pH of 5.3 identified, exceeding Tech Spec range Cause could not be determined
Aeration tank neutralized to bring effluent pH within limits Mod of treatment plant under investigation
GRIFFIN, E. J. Philadelphia Electric Co
79/04/27 1p

7903040091 Forwards LER 79-012/012-0 Discussion results of continuing investigation re design errors in recirculation gas valves
GRIFFIN, E. J. Philadelphia Electric Co
79/04/28 3pp

7903050044 LER 79-012/012-0 on 790428 power & control cable associated with recirculation pump discharge valves & bypass valves were fractured in nonapproved cable trays Caused by improperly designated cables during design phase
GRIFFIN, E. J. Philadelphia Electric Co
79/05/12 1p

7903040047 LER 79-012/012-0 on 790410 limit switch on H failed Cause not found due to high temp & radiation 3 in HSVI room Appropriate logic channel was placed in condition
GRIFFIN, E. J. Philadelphia Electric Co
79/05/07 1p

7903020081 IL Insp Repts 90-277/79-02 on 790304 HPCI control cable 1 w/MS cables far short distance in cable spreading re
Caused by failure of supplier to provide proper cable interface documents to AVE during design phase
GRIFFIN, E. J. Philadelphia Electric Co
79/05/07 2p

7903040083 LER 79-012/012-0 on 790428 channel D refusal: reactor big area ventilation exhaust radiation monitor failed due to cable while at power Caused by defective converter in common radiation monitor power supply
GRIFFIN, E. J. Philadelphia Electric Co
79/05/11 1p

7903050214 Forwards LER 79-021/017-0
GRIFFIN, E. J. Philadelphia Electric Co
79/05/18 3

7903050226 LER 79-021/017-0 on 790304 HPCI cables in
Caused by errors in design Borewing of cables w/ affected during outage
GRIFFIN, E. J. Philadelphia Electric Co
79/05/18 3

DOCKETED ITEMS

67

7905290116 Forwarded EC Insp Regts 50-27779-05 & 50-27879-04 on 790129-0255 No noncompliance noted
BURNHAM, J. J. Region I, Philadelphia, Office of the Director
79/04/13 App

7905290120 EC Insp Regts 50-27779-05 & 79-28879-01 on 790129-0255 No noncompliance noted Major areas inspected plant operations, facility tour, H. circular followup & LER review in etc & on site
OFTENBERG, C. D. Region I, Philadelphia, Office of the Director
BURNHAM, J. J. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/11 App

7905290201 Forwarded H. Bulletin JV 06, "Initial Stress Analysis of Safety-Related Piping - Licensee action required"
OFTENBERG, C. D. Region I, Philadelphia, Office of the Director
79/04/14 App

7905290207 Forwarded H. Bulletin JV 06, "Review of Operational Errors & Design Missalignments Identified During HRI Incident"
OFTENBERG, C. D. Region I, Philadelphia, Office of the Director
79/04/14 App

7905290259 Forwarded H. Bulletin JV 06, "Events Related to Boiling Water Pump Reactors Identified During HRI Incident"
Licensee action required
OFTENBERG, C. D. Region I, Philadelphia, Office of the Director
79/04/14 App

7905290300 Forwarded H. Bulletin JV 06, "Failures of G1 Type AM-2 Circuit Breaker in Safety Related Sys - Licensee action required"
OFTENBERG, C. D. Region I, Philadelphia, Office of the Director
79/04/17 App

7905290310 Forwarded H. Bulletin JV 06, Revision 1, "Review of Operational Errors & Design Missalignments Identified During HRI Incident"
OFTENBERG, C. D. Region I, Philadelphia, Office of the Director
79/04/18 App

7905290407 Forwarded H. Insp Regts 50-27779-01 & 79-28879-02 on 790129-0255 & notice of violation
BURNHAM, J. J. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/20 App

7905290414 Notice of violation from Insp on 790409-01 & 790409-02
BURNHAM, J. J. Region I, Philadelphia, Office of the Director 79/04/19 App

7905290521 EC Insp Regts 79-27779-01 & 50-27879-01 on 790129-0255 Noncompliance noted improper valve positioning & positive control, improper approval & review
OFTENBERG, C. D. Region I, Philadelphia, Office of the Director
BURNHAM, J. J. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/19 App

B. Periodic operating reports & related correspondence

7905290444 Forwarded "Annual Plant Mod Rept 1978"
ALLEN, W. H. Philadelphia Electric Co 79/04/27 App

7905290456 "Annual Plant Mod Rept 1978"
ALLEN, W. H. Philadelphia Electric Co 79/04/28 App

7905290524 Forwarded monthly operating report for Apr 1979
CORNEY, H. J. Philadelphia Electric Co 79/05/11 App

7905290544 Monthly operating report for Apr 1979
ALLEN, W. H. Philadelphia Electric Co 79/05/10 App

B. Reportable occurrences, LIRs & related correspondence

7905290577 Forwarded LIR JV 01-017-0
CORNEY, H. J. Philadelphia Electric Co 79/04/26 App

7905290592 LIR JV 01-017-0 on 790401 engineering review discredited valving associated with manually qualified emergency sec water sys was normally open caused by faulty plant design
Barn Valves locked closed
CORNEY, H. J. Philadelphia Electric Co 79/04/26 App

7905290601 Forwarded LIR JV 01-017-0 Discusses results of continuing investigation re design errors in recirculation sys valves
CORNEY, H. J. Philadelphia Electric Co 79/04/30 App

7905290611 RG 2-79-21/1P on 790504 HPCI control cable improperly routed W/ASD cables for short distance in cable spreading rack caused by failure of welder to provide proper size interference decoupler to A/C during design phase
ALLEN, W. H. Philadelphia Electric Co 79/05/07 App

7905290624 Forwarded LIR JV 01-017-0
CORNEY, H. J. Philadelphia Electric Co 79/05/10 App

7905290626 LIR JV 01-017-0 on 790504 HPCI cables improperly routed caused by errors in design. Rerouting of cables will be effected during outages
CORNEY, H. J. Philadelphia Electric Co 79/05/10 App

DOCKET 80-280 GARRY POWER STATION, UNIT 1

A. Application/Construction stage documents & correspondence

7905290206 Requests NRC reconsider its 3-month moratorium on issuance of new OL because of large added costs of replacement power
RADNICK, R. J. Virginia Electric & Power Co 79/05/22 App

D. Adjudicatory correspondence

7905290646 Orders extension until 790804 for NRC review of 790606 denial of enforcement action
OFTENBERG, C. D. Office of the Secretary of the Commission 79/04/13 App

7905290648 Forwarded petition of Patonco Alliance et al for emergency & remedial action
DOUGHERTY, J. E. Patonco Alliance 79/04/18 App

7905290658 Petition for emergency & remedial action re NRC violations of NRC in issuing Amends 46 & 47 to CL
DOUGHERTY, J. E. Patonco Alliance 79/04/18 App

7905290400 Receipt of 790405 ltr requesting NRC to revoke OLs Ltr is currently under consideration Forwarded FR notice re Allen
790405 ltr
OFTENBERG, C. D. Office of Nuclear Reactor Regulation 79/05/04 App

7905290461 FR notice re J. Allen 790408 request for revocation of OLs
OFTENBERG, C. D. Office of Nuclear Reactor Regulation 79/05/04 App

7905290503 Forwarded J. Allen 790408 ltr requesting NRC revoke facility OLs & FR notice of revocation request H/790500 ltr to AGLA re Westinghouse ECCS deficiencies
OFTENBERG, C. D. Office of Nuclear Reactor Regulation 79/05/04 App

J. Insurance & indemnity information

7905291017 Amended Underpayment \$1 to NELA Policy NF-196 Constitutes Underpayment \$4
A. Nuclear Energy Liability Insurance Association 79/04/27 App

7905290497 Confirms increased liability limit to \$194,000,000 for policies 1971, 201, 43, 76, 03, 100, 111, 140, 146, 191, 161, 144, 170, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 211, 214, 215, & others
BARTTROCK, J. American Nuclear Insurers 79/05/03 App

DOCKETED ITEMS

P Operating license stage documents & correspondence

7903000047 Operating responsibility for prompt meeting notification re

7903030300 Division of Operating Reactors 79/03/29 3pp
STALLINS, V

7903000470 Discusses 7903010 follow up items of Westinghouse re
incorrect weights for Valve Model 6600 limit check valves
used in safety injection sig
SCHNEIDER, A Operating Reactors Branch 1 79/04/08 1p

7903000489 Forwards 790308 ltr requesting NRC to conduct hearing &
prepare EIS on proposed replacement of steam generators
Related fr notices and
BENTON, H R Office of Nuclear Reactor Regulation 79/04/04 2pp

7903000499 Requests reconsideration of issuance of License Amendments 46 &
47 for replacement of steam generators Also requests public
hearing & EIS
BENTON, H R Environmental Policy Institute 79/02/20 2pp

7903000504 Notification of "Director's Decision under 10CFR 206."
requesting request for public hearing & EIS preparation re
steam generator repair program
BENTON, H R Office of Nuclear Reactor Regulation 79/04/04 8pp

7903000510 Summary of 790404 meeting w/BSM & Util in Boston, MA re
successful operations of safety sig required to reach
shutdown in all conditions & pipe sig stress analysis
NECHORS, D Operating Reactors Branch 1 79/04/04 3pp

7903000516 Responds to 790300 ltr re analysis of piping sig per 790313
that cause order Use of soil structure interaction
techniques in calculation of amplified response spectra is
acceptable if appropriate documentation is included
STALLINS, V Division of Operating Reactors 79/04/13 2pp

7903000523 Requests review and testing plans re action taken to
correct design deficiency identified in electrical load
study Request application for appropriate license amendments
made as soon as possible
VALLANDER, H Assistant Director for Systems & Projects 79/04/15 2pp

7903000529 Summary of 790419 meeting w/BSM & Util in Boston, MA re
review of pipe stress analysis
NECHORS, D Operating Reactors Branch 1 79/04/26 3pp

7903000542 Summary of 790419 meeting w/BSM & Util in Boston, MA re
review of pipe stress analysis
NECHORS, D Operating Reactors Branch 1 79/04/26 3pp

7903000548 Forwards WEP-FPD-30, "Burst Unit 2 Cycle 4 Core Performance
Test"
THORNB, H H Virginia Electric & Power Co 79/04/27 1p

7903000549 "Burst Unit 2 Cycle 4 Core Performance Test"
ROSE, T H, LEBERSTEIN, J C Virginia Electric & Power Co
WEP-FPD-30 79/04/20 4pp

7903000555 Forwards status report on 790327 "Plan for Verification of
Dynamic Analysis Codes."
JACOBS, B B Stone & Webster Engineering Corp 79/04/27 3pp

7903000563 Notifies that has completed pipe stress problems were sent
to contractor subsequent to 790419 meeting Specific info
and
SCHNEIDER, C Virginia Electric & Power Co 79/04/27 2pp.

7903000565 Requests reconsideration requirements should be modified to
agree w/ASME Section XI Code requirements Change to Tech
Spec 2 & 3 designated as suppl to ASME Change 4
STALLINS, V Virginia Electric & Power Co 79/05/01 4pp

7903000569 Notifies that steam generator replacement program initial
progress report for 790303-0326 is being prepared Reporting
initial should cover two months rather than 40 days
STALLINS, V Virginia Electric & Power Co 79/05/02 1p

7903000580 Responds to 790413 ltr Forwards summary of soil structure
interaction analysis, summary of vibrational modal properties &
sampling values which were calculated by Stone Program
Summary of sample pipe stress analysis
SCHNEIDER, C Virginia Electric & Power Co 79/05/02 8pp

7903000587 Requests NRC recommend to Commissioners that Unit 1 be
returned to ops immediately Unit will supply any supportive
technical presentations deemed necessary
STALLINS, V Virginia Electric & Power Co 79/05/02 2pp

7903000588 Responds to NRC 790328 ltr requesting add info re seismic
qualification testing performed on containment instrument
cable previously in ops
SCHNEIDER, C Virginia Electric & Power Co 79/05/03 1pp

7903000590 Forwards add info re organizational chart to support
proposed Tech Spec Change 25
STALLINS, V Virginia Electric & Power Co 79/05/04 3pp

7903000591 Responds to 790300 telegram re shutdown of units NRC review
of pipe stress levels will be limited to safety
considerations
BENTON, H R Office of Nuclear Reactor Regulation 79/05/04 3pp

7903000595 Comments on areas of concern re shutdown units Unit 1
analysis of effects of shutdown
BENTON, H R Virginia, State of 79/03/20 3pp

7903000599 Forwards preliminary documents requested during 790301-04
special insp
SCHNEIDER, C Stone & Webster Engineering Corp 79/05/03 1p

7903000604 Requests withholding Technical Guideline NRC-22-B &
Technical Reg NRC-102 (and 100P2 7903 Affidavit) and
SCHNEIDER, C Stone & Webster Engineering Corp 79/05/04 10pp

7903000608 Confirms 790604 letter w/RT Russell re computer disk
associated w/SHECO II program
SCHNEIDER, C Stone & Webster Engineering Corp 79/05/05 1p

7903000609 Notifies that review of computer disk is completed SHECO II
program still unsuccessful Piping was conservatively designed
& will perform intended function
SCHNEIDER, C Stone & Webster Engineering Corp 79/05/05 1p

7903000611 Forwards SHECO II computer program listing Operates
submittal of 790406 Program listing withheld draft
100P2 7901
SCHNEIDER, C Stone & Webster Engineering Corp 79/05/14 1p

7903000625 Summarizes procedures & calculational techniques used in
design of piping sig designed w/SHECO II computer
program Parameters will satisfy 790313 order to show cause
SCHNEIDER, C Stone & Webster Engineering Corp 79/05/18 6pp

7903000630 Submits corrections to 790300 proposed Tech Spec Change 23
re listing of hydraulic shock suppressors
STALLINS, V Virginia Electric & Power Co 79/05/22 1p

7903000642 Submits response to 790318 request for info concerning
review of methodology in use of all structure interaction
SCHNEIDER, C Virginia Electric & Power Co 79/05/24 3pp

7903000643 Submits add info in response to 790403 request re safety
sig analysis by SHECO II code-pipe stress analysis & verification
of dynamic analysis codes info relates to 790313 order to
show cause
SCHNEIDER, C Virginia Electric & Power Co 79/05/24 7pp

7903000651 Requests 761203 Tech Spec change request as Change 24 No
unresolved safety question involved
STALLINS, V Virginia Electric & Power Co 79/05/24 10pp

G Inspection reports, IE Bulletin and correspondence

7905000340 Forwards IE Insp Repts 90-080/79-10 & 90-201/79-12 an
790314-16 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/05/12 2pp

7905000349 IE Insp Repts 90-080/79-10 & 90-201/79-12 an 790314-16 No
noncompliance noted, Major areas inspected protection of
components in containment, tag out practices, long-term layup
& temporary ventilation
ELROD, B A Region 2, Atlanta, Office of the Director
CONTRILL, F B Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/05/09 7pp

7905000352 Forwards IE Insp Repts 90-080/79-10 & 90-201/79-12 an
790314-16 No noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/05/12 2pp

7905000357 IE Insp Repts 90-080/79-10 & 90-201/79-12 an 790314-16 No
noncompliance noted, Major areas inspected plant physical
barriers & preparation for steam generator replacement
BURKE, D J Region 2, Atlanta, Office of the Director
CONTRILL, F B Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/05/12 7pp

DOCKETED ITEMS

--790319032 LER 79-017/017-0 on 790302 problem could develop in thrust bearing of turbocharger for emergency diesel generators under recent start upgrading noise Engineering design problem occurs only under restrictive conditions
STEWART, H. L. Virginia Electric & Power Co. 79/03/19 2pp

790320541 Forwards LERs 79-014/031-0, 79-015/031-0 & 79-016/031-0
STALLINGS, C. H. Virginia Electric & Power Co. 79/03/22 1p

--790309156 LER 79-014/031-0 on 790302 liquid waste disposal monitor failed to give high alarm & trip release valve closed by instrument drift in high alarm respect All liquid waste releases were secured & alarm heard checked
STEWART, H. L. Virginia Electric & Power Co. 79/03/22 2pp

--790309156 LER 79-015/031-0 on 790302 liquid waste disposal monitor failed to give high alarm & trip release valve closed by procedural infractions Procedures modified
STEWART, H. L. Virginia Electric & Power Co. 79/03/22 2pp

--790309157 LER 79-014/031-0 on 790302 cracks noted in concrete support for 1-360-P-1A & 1-360-P-1B Caused by thermal expansion of heat exchanger Cracks repaired Heat exchanger supports will be modified to allow for thermal expansion
STEWART, H. L. Virginia Electric & Power Co. 79/03/22 2pp

790309003 Forwards LER 79-035/017-0
STALLINGS, C. H. Virginia Electric & Power Co. 79/03/23 1p

--790309019 LER 79-018/017-0 on 790309 solenoid valve Model 0360A102 mfg. by Automatic Switch Co. found environmentally unclassified & reportable per DE Bulletin 79-01 & Tech Spec Valve could fail to control admission & venting of air during LSCA
STEWART, H. L. Virginia Electric & Power Co. 79/03/23 2pp

DOCKET 30-201 BARRY POWER STATION, UNIT 2

6 Adjunctory correspondence

790320346 Orders extension until 790324 for NRC review of 790404 denial of enforcement action
DILLON, J. Office of the Secretary of the Commission 79/04/23 1p

790320362 Forwards petition of Potomac Alliance at all for emergency & remedial action
GOSWERTY, J. E. Potomac Alliance 79/04/19 2pp

--7903100320 Petition for emergency & remedial action re NRC violations of NRC in issuing Amends 46 & 47 to GL
GOSWERTY, J. E. Potomac Alliance 79/04/19 6pp

790320435 Ack receipt of 790403 ltr requesting NRC to revoke GLA ltr is currently under consideration Forwards FR notice re Allen 790403 ltr
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/04 1p

--790320441 FR notice re J. Allen 790403 request for revocation of GLA
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/04 2pp

7903210032 Forwards J. Allen 790403 ltr requesting NRC revoke Facility GLA & FR notice of revocation request M/790330 ltr to ASAS re Westinghouse KCOB deficiencies
DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/04 3pp

J. Insurance and indemnity information

790310167 Amend to Endorsement 31 to NELA Policy NP-186 Constitutes Endorsement 31
e Nuclear Energy Liability Insurance Association 79/04/27 1p

790310167 Amend to Endorsement 31 to NELA Policy NP-186 Constitutes Endorsement 31
e Nuclear Energy Liability Insurance Association 79/04/27 1p

7903070477 Confirmed Increased liability limit to \$124,000,000 per policy NP-129: 43,76,93,109,111,140,146,183,181,164,176,179,174,178,179,180,182,183,185,187,188,189,190,192,194,195,197,198,199,201,204,206,207,208,210,212,214,215,216 above
QUARTERMASTER, J. American Nuclear Insurers 79/03/01 1p

7903070477 Confirmed Increase in liability limit to \$24,000,000 per policy NP-129: 26,29,35,37,46,44,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,81,82,83,84,85,86,87,88,89,90,91,92,93,94,95 & 96
QUARTERMASTER, J. Mutual Atomic Energy Liability Underwriters, 79/03/01 1p

790310590 Endorsements 16-36 & 47 to NELA Policy NP-186
NAREB, C. E. Nuclear Energy Liability Insurance Association 79/03/01 1p

790310444 Forwards Amend 10 to Indemnity Agreement B-45 per 1007846 changes re increase in liability insurance from \$100 million to \$100 million effective 790501 Supporting documentation sent
STALLINGS, C. H. Antitrust & Indemnity Group 79/03/01 App

790320403 Forwards executed Amend 10 to Indemnity Agreement B-45, effective 790501
STALLINGS, C. H. Virginia Electric & Power Co. 79/03/02 3pp

P. Operating license stage documents & correspondence

7903080047 Assigns responsibility for prompt meeting notification re 790312 show cause orders
STALLINGS, C. H. Division of Operating Reactors 79/03/28 3pp

7903090049 Discusses 790312 ltr re West of Westinghouse re incorrect weights for Valon Model C85 6-inch check valves used in safety injection sys
STALLINGS, C. H. Operating Reactors Branch 1 79/04/02 1p

7903204038V Forwards 790320 ltr requesting NRC to conduct hearing & prepare EIS on proposed replacement of steam generators
Beltzer, F. R. Notice 8001
DENTON, H. R. Office of Nuclear Reactor Regulation 79/04/04 2pp

--790320419V Requests reconsideration of issuance of license Amends 46 & 47 for replacement of steam generators Also requests public hearing & EIS
BARETT, B. Environmental Policy Institute 79/02/20 2pp

--790320420V Request of "Director's" Decision under 16CFR 256.4 denying request for public hearing & EIS preparation re steam generator repair program
DENTON, H. R. Office of Nuclear Reactor Regulation 79/04/04 3pp

7903205010 Summary of 790404 meeting w/ASAS & staff in Switch-HA re sequential operations of safety sys required to reach shutdown in all conditions & pipe stress management
HECHINGER, D. Operating Reactors Branch 1 79/04/08 2pp

7903100138 Responds to 790320 ltr re analysis of piping sys per 790312 show cause under Use of soil structure interaction techniques in calculation of amplified response spectra is available if appropriate documentation is included
STALLINGS, C. H. Division of Operating Reactors 79/04/13 2pp

7903100070 Requests reviewed & testing plans re action taken to correct design deficiencies identified in electrical load study Supports application for appropriate license amend to be made as soon as possible
VOLLMER, S. H. Assistant Director for Systems & Projects 79/04/18 2pp

7903040458 Forwards VEP-FRD-32, "Barry Unit 2 Cycle 4 Core Performance Report"
THERIAULT, M. N. Virginia Electric & Power Co. 79/04/27 1p

--7903040470 "Barry Unit 2 Cycle 4 Core Performance Report" - ASAS V.E. & LEBBINGHOUSE, J. W. Virginia Electric & Power Co. VEP-FRD-32 79/04/30 47pp

7903040418 Forwards status report on 790427 "Plan for Verification of Specific Analysis Codes"
JACOBS, E. E. Stone & Webster Engineering Corp. 79/04/27 2pp

7903070473 Notifies that two completed pipe stress problems were sent to contractor subsequent to 790418 meeting Specific info sent
BEPCHER, W. C. Virginia Electric & Power Co. 79/04/27 2pp

7903040024 Bellows recordkeeping requirements should be modified to permit w/ASAS Decision re 506 requirements Change to Tech Spec 5.0.7 designated as Request to Amend Change 44
STALLINGS, C. H. Virginia Electric & Power Co. 79/03/01 App

7903040030 Notifies that steam generator replacement program initial progress report for 790303-0201 is being prepared Reporting period should cover two months rather than 40 days
STALLINGS, C. H. Virginia Electric & Power Co. 79/03/02 1p

- 7903076450 Response to 790414 IIR: Forwarded summary of soil structure interaction analysis summary of subgrade wall properties & damping values which were calculated by State Program
BENECHE, H.C. Virginia Electric & Power Co. 79/03/02 8pp
- 7903076457 Requests NRC recommend to Commissioners that Unit 1 be returned to not immediately until will apply any supportive technical presentations deemed necessary
STALLINGS, C.N. Virginia Electric & Power Co. 79/03/02 2pp
- 7903076458 Notification of 790500 meeting w/units in Bethesda, MD to discuss startup
NEEDHAM, B. Operating Reactors Branch 1 79/03/02 1p
- 7903076459 Response to NRC 790323 IIR requesting add info re unit-on qualification testing performed on continental instrument cable presently in use
O'REILLY, J.P. Virginia Electric & Power Co. 79/03/02 8pp
- 7903076459 Forwarded add info re organizational chart to support proposed Tech Spec Change 79
STALLINGS, C.N. Virginia Electric & Power Co. 79/03/04 3pp
- 7903076470 Response to 790320 telegram re shutdown of units NRC review of pipe stress levels will be limited to safety considerations
DENTON, H.R. Office of Nuclear Reactor Regulation 79/03/04 2pp
- 7903076478 Comments on areas of concern re shutdown units Urges prompt analysis of effects of shutdown
BENECHE, H.C. Virginia, State of 79/03/02 3pp
- 7903076482 Forwarded proprietary documents requested during 790501-04 special insp
DR, ENRI, J.A. Stone & Webster Engineering Corp. 79/03/08 1p
- 7903076488 Requests withholding Technical Guidelines ENTO-22-0 & Technical Rep ENR-652 (ref IDP282 7901 Affidavit and)
KENDRICK, W.J. Stone & Webster Engineering Corp. 79/03/04 10pp
- 7903076488 Confirms 790324 bulletin w/RT Russell re computer deck associated w/ROCK II program
HEINEN, H.J. Stone & Webster Engineering Corp. 79/03/09 1p
- 7903076493 Request that review of computer deck is completed ENR-652 O program still uncovered piping app conservatively designed & will perform intended function
KENDRICK, W.J. Stone & Webster Engineering Corp. 79/03/11 1p
- 7903076493 Forwarded ENR-652 computer program listing Bapenexes submitted of 790406 Program listing withheld (ref IDP282 7901)
KENDRICK, W.J. Stone & Webster Engineering Corp. 79/03/14 1p
- 7903076493 Summaries procedures & calculational techniques used in reanalysis of piping app designed w/ROCK II computer program Reanalysis will satisfy 790313 order to allow cause
KENDRICK, H.J. Stone & Webster Engineering Corp. 79/03/10 4pp
- 7903076500 Bulletin corrections to 790920 proposed Tech Spec Change 70 re listing of hydraulic shock suppressors
STALLINGS, C.N. Virginia Electric & Power Co. 79/03/02 1p
- 7903076502 Bulletin response to 790518 request for info concerning review of methodology in use of all structure interaction
BENECHE, H.C. Virginia Electric & Power Co. 79/03/26 30pp
- 7903076502 Bulletin add info in response to 790402 request re safety app analyzed by ROCK II code, pipe stresses & verification of dynamic analysis codes info relates to 790313 order to show cause
BENECHE, H.C. Virginia Electric & Power Co. 79/03/24 5pp
- 7903076501 Resubmits 790320 Tech Spec change request as Change 24 Re requested safety specifications
STALLINGS, C.N. Virginia Electric & Power Co. 79/03/24 14pp
- 0 Inspection reports, IE Bulletins & correspondence
- 7903076504 Forwarded IE Insp Repts 50-280/79-10 & 50-281/79-12 on 790324-14 Re noncompliance noted Major areas inspected protection of components in containment, tag out practices, loop-burn tests & temporary ventilation
ELROD, S.A. Region 2, Atlanta, Office of the Director
CANTRELL, P.B. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/17 7pp
- 7903076504 Forwarded IE Insp Repts 50-280/79-02 & 50-281/79-02 on 790324-0202 Re noncompliance noted
LOHMEYER, C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/13 2pp
- 7903076504 IE Insp Repts 50-280/79-02 & 50-281/79-02 on 790324-0202 Re noncompliance noted Major areas inspected plant physical barriers & preparations for steam generator replacement
BUNKE, D.J. Region 2, Atlanta, Office of the Director
CANTRELL, P.B. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/12 7pp
- 7903076515 Forwarded IE Insp Repts 50-281/79-11 on 790323-14 Re noncompliance noted
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/19 2pp
- 7903076515 IE Insp Repts 50-281/79-11 on 790323-14 Re noncompliance noted Major areas inspected steam generator replacement
MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/14 3pp
- 7903076524 Forwarded IE Info Notice 79-06 "Stress Analysis of Safety-Related Piping"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/23 3pp
- 7903076524 Forwarded IE Info Notice 79-07, "Reburn of Reactor Tanks"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/26 2pp
- 7903076524 Forwarded IE Info Notice 79-07, "Interconnection of Contaminated IE w/IEC Air Gys Used as Source of Breathing Air"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/26 2pp
- 7903076524 Forwarded IE Info Notice 79-07, "Status of Radioactively Contaminated Basin"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/26 2pp
- 7903076524 Forwarded IE Insp Repts 50-280/79-12 & 50-281/79-14 on 790321-03 Re noncompliance noted
KENDRICK, H. Region 2, Atlanta, Safeguards Branch 79/04/11 3pp
- 7903076524 IE Insp Repts 50-280/79-12 & 50-281/79-14 on 790321-03 Re noncompliance noted Major areas inspected independent loop effort re IDP282 7901 interior measures details withheld
HEINEN, H.J. Region 2, Atlanta, Office of the Director
TOLSON, W. Region 2, Atlanta, Safeguards Branch 79/04/11 1p
- 7903076524 Forwarded IE Bulletin 79-04, "Review of Operational Errors & Key Missions Identified During THE Incident" Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/11 1p
- 7903076524 Forwarded IE Bulletin 79-04, "Review of Operational Errors & Key Missions Identified During THE Incident" Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/11 1p
- 7903076524 Forwarded IE Bulletin 79-07, "Reburn of Reactor Tanks" Licensee action required
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/11 1p
- 7903076524 Forwarded IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During THE Incident"
O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/04/11 1p
- 7903076524 Response to IE Bulletin 79-03, "Longitudinal Weld Defects in AGRS A-212 Tube 304 Stainless Steel Pipe Spools Affected by Youngstown Welding & Engineering Co. North Anne 1 uses no 304B2 piping, survey & B records are still under review.
STALLINGS, C.N. Virginia Electric & Power Co. 79/04/16 2pp

DOCKETED ITEMS

72

[illegible]

U.S. Air Force AFM 70-100, Revision 1, "Review of Operational Errors & Sub-Minimalities Identified During the Vietnam War".

A 10,000 Btu-per-hour gas furnace by GE Bulletin 78-60 was selected for analysis of safety-related design and will be provided to NRC, then shipped to show cause the TRS315. The GE 78-60 is a gas furnace electric and power to 10,000 Btu/hr.

1. FATALITY Resulting to IR Building 39-004 - Review of Operational Factors & Fire Readjustments Identified During the Incident - Review Committee was established & detailed review of the incident has been completed

drawings : R. Varganese Electric & Power Co. 77-04126

7-242356 ACN receipt of 79p412 ltr informing HRC of steps taken to
-+PACI -ISSUANCE PAPERS IN DE ISS REPT 80-281/79-00
WYNNER C E Region 2 Atlanta Reactor Construction & Engineering
Division Branch 79A05701 to

- 7/26/90132 Response to NRC 7/26/90 per re violations noted on IE Insp
Wkst 5/30/89/79-08 Corrective actions installation of fire
protection header in progress
DRA/L2428 C N Virginia Electric & Power Co 7/26/90 12 Dca

-75204 PG333 Forwarded 3E ltrg Rept 89-201/79-82 on 79d812-16 & notice of
 violation
 MURPHY C E Region 2 Atlanta Reactor Construction &
 Engineering Support Branch 79003/80 Doc

--F035293392 Notice of violation from Insp on 7/30/83-16
 1 Region 2, Atlanta, Office of the Director 7/30/83 09 00

7-72703Q196 IL has Regn 80-20177A-00 re 720232nd Assembly House noted lack of fire protection sys & equipment for civil area
chairman & loss of organized round since fire brigade for
steel generator repair program

MILLER, M H Region 2: Atlanta, Office of the Director
BRYANT, J C Region 2: Atlanta, Manager Construction &
Engineering Support Branch 78/03019 See

ZYG3330086: Forwarded response to IE Bulletin 79-04 (alan smith chest
 x-rays of legs & hip bones installed on chemical vat &
 control & safety instructions app
 STALLING C N Virginia Electric & Power Co 79/03/02 4pp

NY0210275 Responds to IE Bulletin 39-044, Revision 2 Previous requested info on design changes re containment sump pump trip valve activation & safety injection logic.
STALLINGS, C M Virginia Electric & Power Co 39/05/13 2pp

© Replicable scenarios, LBNs & related correspondence

7805000104 Forwards LER 79-011/127-0
STALLINGS, C M Virginia Electric & Power Co 79/04/27 10

--7908060007 LER 79-012/LER-0 on 790614 individual received radiation dose while inspecting area beneath ventral fin caused by elevated radiation levels due to incorrect instrumentation referring studies individual disciplined

STANLEY, W.L. Virginia Electric & Power Co 79/04/27 Dep

7903070600 Parsons "Analysis & Sys Mod for 400 Volt Emergency Power
Sys." is response to RRC 790466 for
STALLINGS C R Virginia Electric & Power Co 79/03/06 sp

7905200041 Forward LSR 79-012/001-0
STALLONE, C. M. Vineland Electric & Power Co 79/05/01 1a

--79622604 LOR 79-002/OST-0 on 790307 caustic residue discovered at
all new fuel assemblies caused by industrial sabotage
Fuel removed & assemblies stored investigation continuing
ORRANT, M.C. Virginia Electric & Power Co 790301/01 Rm

7100240003 Feranda LER 79-018/017-0
STALL906,C H Virginia Electric & Power Co 79/05/21 1a

77903290000 LER 79-0100017-0 on 776004 material valve Model 38L27A122 V. by Automatic Switch Co found environmentally unqualified & replaceable per IC Bulletin 79-01 & Tech Spec Valve could fail to control admission & venting of air during IDSA
DTICART.M.L Virginia Electric & Power Co 79/03/23 App

P Security, medical, emergency & fire protection plans

790507049Y Forward info requested in MEC 790205 per re file protection
program Reviewer to 780510 fire protection outline and
RAYE.L.S. Northern States Power Co 79/05/02 gdp

7903000406 Forwards supplemental info on status of security plan
implementation info withheld (ref) 10CFR2.3901
NATURAL D. Northern States Power Co. 79/03/25 5p

Financial information

79010025 Forwards "Financial & Statistical Info" as suppl to "Ann. of
Financial Regt 1970"
BRUNSWICK & Norfers Stages Four Co 04/09/70 1a

--P0051023: "Financial & Statistical Info." submitted as suppl to
 "Annual Financial Rpt 1978"
 * Northern States Power Co 78/03/31 Rile.

DOCKETED ITEMS

73

7903010474 Forwarded application for amend to Licenses DPH-42 & DPH-60, changing Tech Specs re pressurizer initiating signals for safety injection signals Amend fee & proposed Tech Specs changes met
MAYHEW, L. J. Northern States Power Co 79/04/26 10pp

7903040462 Forwarded ambient sound level survey in response to recent J Lab request for addl info re ETS
MAYHEW, L. J. Northern States Power Co 79/04/27 3pp

7903030474 Forwarded amend fee of \$1,400 for Licenses DPH-42 & DPH-60 & Northern States Power Co 79/05/01 1p

7903100324 Mobility Dev/Plan Event Rept 79-03 for 790326-0302 discharge seal gate structure under water, rendering control & monitoring or shutdown flow inoperable
MAYHEW, L. J. Northern States Power Co 79/05/02 1p

Operating License stage documents & correspondence

7903020490 Discrepancy 790305 heliport with State of Washington re incorrect weight for Valon Model C880 4-inch check valves used in safety injection tank
SCHMIDT, A. Operating Reactors Branch 1 79/04/02 1p

7903030306 Forwarded PURFT computer code input & affidavit requesting exemption from public disclosure Computer code input with license (ref 10CFR2.790)
MAYHEW, L. J. Northern States Power Co 79/04/18 35pp

7903040304 Forwarded Amends 38 & 29 to Licenses DPH-42 & DPH-60, respectively-safety evaluation & notice of issuance & availability
SCHMIDT, A. Operating Reactors Branch 1 79/04/20 3pp

--7903040328 Amends 38 & 29 to Licenses DPH-42 & DPH-60, respectively, changing common station Tech Specs re refueling & interconnecting changes to App A Tech Specs to support operation in Cycle 0 sustained fuel by Extern Nuclear Co
SCHMIDT, A. Operating Reactors Branch 1 79/04/20 19pp

--7903040329 Safety evaluation supporting Amends 38 & 29 to Licenses DPH-42 & DPH-60, respectively
A. Office of Nuclear Reactor Regulation 79/04/20 11pp

--7903040333 Notice of issuance & availability of Amends 38 & 29 to Licenses DPH-42 & DPH-60, respectively
SCHMIDT, A. Operating Reactors Branch 1 79/04/20 3pp

0 Inspection reports, IE Bulletin & correspondence

7903010262 Forwarded IE Info Notice 79-05, "Stress Analysis of Safety-Related Piping"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/02/03, 1p

7903040400 Forwarded IE Info Notice 79-07, "Rupture of Reducers Tanks"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/03/26 1p

7903090126 Forwarded IE Insp Repts 50-282/79-05 & 50-036/79-06 on 790327-28 & 0301-02
GAVIN, A. E. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/03/28 2pp

--7903090131 IE Insp Repts 50-282/79-05 & 50-036/79-06 on 790327-28 & 0301-02, No noncompliance noted Rept areas inspected, emergency plan, emergency facilities, equipment & supplies, radioactive effluent sys & emergency training
SCHMIDT, A. E. Region 3, Chicago, Office of the Director 79/03/28 8pp

7903090134 Forwarded IE Info Notice 79-08, "Interconnection of Contaminated Sys w/DCR Air Sys Used as Source of Breathing Air"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/03/28 1p

7903090140 Forwarded IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/03/28, 1p

7903070344 Responds to IE Bulletin 79-03 All longitudinal welds of ASTM-A31 stainless steel piping 100% radiographed & free of defects, Addl testing unnecessary
MAYHEW, L. J. Northern States Power Co 79/04/30 1p

7903030404 Forwarded IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident" - Licensee action required
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

7903010600 Forwarded IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident" - Licensee action required
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p

7903040405 Forwarded IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p

7903040451 Forwarded IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping" - Licensee action required
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/18 1p

7903040376 Forwarded IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Reactors Identified During TH1 Incident"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/18 1p

7903030327 Forwarded IE Bulletin 79-09, "Patterns of GE Type AA-2 Circuit Breaker in Safety-Related Sys" - Licensee action required
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/17 1p

7903080805 Forwarded IE Bulletin 79-08B, "Nuclear Incident at DCR-Duppi"
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/21 1p

7903140100 Ack receipt of 790401 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/79-05 & 50-036/79-06
GAVIN, A. E. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/25 1p

--7903140104 Responds to NRC 790333 ltr re violations noted in IE Insp Repts 50-282/79-05 & 50-036/79-06 Corrective actions taken values were reduced & new bolts were retrofitted to specified value
MAYHEW, L. J. Northern States Power Co 79/04/10 8pp

7903070290 Responds to IE Bulletin 79-09 GE Type AA-2 breakers not in use at 2015
MAYHEW, L. J. Northern States Power Co 79/04/04 1p

Periodic operating reports & related correspondence

7903010007 Forwarded monthly operating rept for Feb 1979
MAYHEW, L. J. Northern States Power Co 79/04/25 1p

--7903010011 Monthly operating rept for Feb 1979
MAYHEW, L. J. Northern States Power Co 79/03/26 1pp

790

#

7903030344 Forwarded LER 79-029/017-0
MAYHEW, L. J. Northern States Power Co 79/04/26 1p

--7903030347 LER 79-029/017-0 on 790412 satisfied by vendor that small break in pressurizer indicator ls may hang up while Ps decreases, delaying safety injection availability; recommends manually indicating safety injection implement
MAYHEW, L. J. Northern States Power Co 79/04/26 1p

7903040521 RD 79-54 on 790407 fuel loading pattern of Cycle 3 core is in error, CORE has not achieved criticality; unit core is in refueling shutdown Core loading pattern will be corrected
TIERNEY, P. P. Northern States Power Co 79/04/27 1p

7903080543 Forwarded LER 79-012/017-0
MAYHEW, L. J. Northern States Power Co 79/03/02 1p

DOCKETED ITEMS

--790508066 LER 79-010/017-0 on 790408 stop of Region 4 assemblies
 returned during refueling terminated and cooling greater than
 previously discharged assemblies All Region 4 fuel has been
 discharged from core vessel investigations
 HUNTINGDALE A Northern States Power Co 79/05/02 1p

790510127 Forwarded LER 79-008/001-0
 HANER, L. O. Northern States Power Co 79/05/08 1p

--790510428 LER 79-003/001-0 on 790408 safety injection pump 11 failed to
 start automatic failability in reactor. Cause unknown. Event
 could not be repeated. Possibility of reactor light to detect
 failures being studied
 HUNTINGDALE A Northern States Power Co 79/05/08 1p

790514332 Forwarded LER 79-010/001-0
 HANER, L. O. Northern States Power Co 79/05/10 1p

--790514039 LER 79-010/001-0 on 790410 high head safety injection valve
 to reactor vessel; 79-020/001 failed to open on demand
 Subsequent opening attempts were successful. Cause of failure
 not found
 HUNTINGDALE A Northern States Power Co 79/05/10 2p

790520466 Forwarded LER 79-014/017-0
 HANER, L. O. Northern States Power Co 79/05/11 1p

--790520466 LER 79-014/017-0 on 790407 informed by Exxon of error in
 core loading pattern. Specifically, gelatinizing-101 in
 assemblies not properly located. Assemblies transmitted as
 790403
 HUNTINGDALE A Northern States Power Co 79/05/11 1p

DOCKET 90-204 IDAHO STATE UNIV. RESEARCH REACTOR

Insurance & Indemnity Information

790514039 Forwarded Amend II to Indemnity Agreement 8-49 per 10CFR140
 changes. Increase from \$142 million to \$142 million.
 Effective 790501. Supporting documentation incl
 BALTSMAN, J. Antitrust & Indemnity Group 79/05/08 2p

790520466 Forwarded executed Amend II to Indemnity Agreement 8-49
 BALTSMAN, P. H. Idaho State Univ. 79/05/11 2p

DOCKET 90-208 PORT CALIFORNIA BRATION, UNIT 1

Security, nuclear, emergency & fire protection plans

900700246 Forwarded revision to physical security plan Revision
 without leaf 10CFR2 7901
 SHURT, F. E. Omaha Public Power District 79/05/08 1p

Financial Information

900330038 Forwarded "Annual Financial Report 1978"
 PETERSEN, H. E. Omaha Public Power District 79/05/22 1p

--790500030 "Annual Financial Report 1978"
 Omaha Public Power District 79/05/23 2p

Insurance & Indemnity Information

900700477 Confirms increased liability limit to \$125,000,000 for
 policies 89-01, 89-02, 89-03, 89-04, 89-05, 89-06, 89-07, 89-08, 89-09, 89-10, 89-11, 89-12, 89-13, 89-14, 89-15, 89-16, 89-17, 89-18, 89-19, 89-20, 89-21, 89-22, 89-23, 89-24, 89-25, 89-26, 89-27, 89-28, 89-29, 89-30, 89-31, 89-32, 89-33, 89-34, 89-35, 89-36, 89-37, 89-38, 89-39, 89-40, 89-41, 89-42, 89-43, 89-44, 89-45, 89-46, 89-47, 89-48, 89-49, 89-50, 89-51, 89-52, 89-53, 89-54, 89-55, 89-56, 89-57, 89-58, 89-59, 89-60, 89-61, 89-62, 89-63, 89-64, 89-65, 89-66, 89-67, 89-68, 89-69, 89-70, 89-71, 89-72, 89-73, 89-74, 89-75, 89-76, 89-77, 89-78, 89-79, 89-80, 89-81, 89-82, 89-83, 89-84, 89-85, 89-86, 89-87, 89-88, 89-89, 89-90, 89-91, 89-92, 89-93, 89-94, 89-95, 89-96, 89-97, 89-98, 89-99, 89-100, 89-101, 89-102, 89-103, 89-104, 89-105, 89-106, 89-107, 89-108, 89-109, 89-110, 89-111, 89-112, 89-113, 89-114, 89-115, 89-116, 89-117, 89-118, 89-119, 89-120, 89-121, 89-122, 89-123, 89-124, 89-125, 89-126, 89-127, 89-128, 89-129, 89-130, 89-131, 89-132, 89-133, 89-134, 89-135, 89-136, 89-137, 89-138, 89-139, 89-140, 89-141, 89-142, 89-143, 89-144, 89-145, 89-146, 89-147, 89-148, 89-149, 89-150, 89-151, 89-152, 89-153, 89-154, 89-155, 89-156, 89-157, 89-158, 89-159, 89-160, 89-161, 89-162, 89-163, 89-164, 89-165, 89-166, 89-167, 89-168, 89-169, 89-170, 89-171, 89-172, 89-173, 89-174, 89-175, 89-176, 89-177, 89-178, 89-179, 89-180, 89-181, 89-182, 89-183, 89-184, 89-185, 89-186, 89-187, 89-188, 89-189, 89-190, 89-191, 89-192, 89-193, 89-194, 89-195, 89-196, 89-197, 89-198, 89-199, 89-200, 89-201, 89-202, 89-203, 89-204, 89-205, 89-206, 89-207, 89-208, 89-209, 89-210, 89-211, 89-212, 89-213, 89-214, 89-215, 89-216, 89-217, 89-218, 89-219, 89-220, 89-221, 89-222, 89-223, 89-224, 89-225, 89-226, 89-227, 89-228, 89-229, 89-230, 89-231, 89-232, 89-233, 89-234, 89-235, 89-236, 89-237, 89-238, 89-239, 89-240, 89-241, 89-242, 89-243, 89-244, 89-245, 89-246, 89-247, 89-248, 89-249, 89-250, 89-251, 89-252, 89-253, 89-254, 89-255, 89-256, 89-257, 89-258, 89-259, 89-260, 89-261, 89-262, 89-263, 89-264, 89-265, 89-266, 89-267, 89-268, 89-269, 89-270, 89-271, 89-272, 89-273, 89-274, 89-275, 89-276, 89-277, 89-278, 89-279, 89-280, 89-281, 89-282, 89-283, 89-284, 89-285, 89-286, 89-287, 89-288, 89-289, 89-290, 89-291, 89-292, 89-293, 89-294, 89-295, 89-296, 89-297, 89-298, 89-299, 89-300, 89-301, 89-302, 89-303, 89-304, 89-305, 89-306, 89-307, 89-308, 89-309, 89-310, 89-311, 89-312, 89-313, 89-314, 89-315, 89-316, 89-317, 89-318, 89-319, 89-320, 89-321, 89-322, 89-323, 89-324, 89-325, 89-326, 89-327, 89-328, 89-329, 89-330, 89-331, 89-332, 89-333, 89-334, 89-335, 89-336, 89-337, 89-338, 89-339, 89-340, 89-341, 89-342, 89-343, 89-344, 89-345, 89-346, 89-347, 89-348, 89-349, 89-350, 89-351, 89-352, 89-353, 89-354, 89-355, 89-356, 89-357, 89-358, 89-359, 89-360, 89-361, 89-362, 89-363, 89-364, 89-365, 89-366, 89-367, 89-368, 89-369, 89-370, 89-371, 89-372, 89-373, 89-374, 89-375, 89-376, 89-377, 89-378, 89-379, 89-380, 89-381, 89-382, 89-383, 89-384, 89-385, 89-386, 89-387, 89-388, 89-389, 89-390, 89-391, 89-392, 89-393, 89-394, 89-395, 89-396, 89-397, 89-398, 89-399, 89-400, 89-401, 89-402, 89-403, 89-404, 89-405, 89-406, 89-407, 89-408, 89-409, 89-410, 89-411, 89-412, 89-413, 89-414, 89-415, 89-416, 89-417, 89-418, 89-419, 89-420, 89-421, 89-422, 89-423, 89-424, 89-425, 89-426, 89-427, 89-428, 89-429, 89-430, 89-431, 89-432, 89-433, 89-434, 89-435, 89-436, 89-437, 89-438, 89-439, 89-440, 89-441, 89-442, 89-443, 89-444, 89-445, 89-446, 89-447, 89-448, 89-449, 89-450, 89-451, 89-452, 89-453, 89-454, 89-455, 89-456, 89-457, 89-458, 89-459, 89-460, 89-461, 89-462, 89-463, 89-464, 89-465, 89-466, 89-467, 89-468, 89-469, 89-470, 89-471, 89-472, 89-473, 89-474, 89-475, 89-476, 89-477, 89-478, 89-479, 89-480, 89-481, 89-482, 89-483, 89-484, 89-485, 89-486, 89-487, 89-488, 89-489, 89-490, 89-491, 89-492, 89-493, 89-494, 89-495, 89-496, 89-497, 89-498, 89-499, 89-500, 89-501, 89-502, 89-503, 89-504, 89-505, 89-506, 89-507, 89-508, 89-509, 89-510, 89-511, 89-512, 89-513, 89-514, 89-515, 89-516, 89-517, 89-518, 89-519, 89-520, 89-521, 89-522, 89-523, 89-524, 89-525, 89-526, 89-527, 89-528, 89-529, 89-530, 89-531, 89-532, 89-533, 89-534, 89-535, 89-536, 89-537, 89-538, 89-539, 89-540, 89-541, 89-542, 89-543, 89-544, 89-545, 89-546, 89-547, 89-548, 89-549, 89-550, 89-551, 89-552, 89-553, 89-554, 89-555, 89-556, 89-557, 89-558, 89-559, 89-560, 89-561, 89-562, 89-563, 89-564, 89-565, 89-566, 89-567, 89-568, 89-569, 89-570, 89-571, 89-572, 89-573, 89-574, 89-575, 89-576, 89-577, 89-578, 89-579, 89-580, 89-581, 89-582, 89-583, 89-584, 89-585, 89-586, 89-587, 89-588, 89-589, 89-590, 89-591, 89-592, 89-593, 89-594, 89-595, 89-596, 89-597, 89-598, 89-599, 89-600, 89-601, 89-602, 89-603, 89-604, 89-605, 89-606, 89-607, 89-608, 89-609, 89-610, 89-611, 89-612, 89-613, 89-614, 89-615, 89-616, 89-617, 89-618, 89-619, 89-620, 89-621, 89-622, 89-623, 89-624, 89-625, 89-626, 89-627, 89-628, 89-629, 89-630, 89-631, 89-632, 89-633, 89-634, 89-635, 89-636, 89-637, 89-638, 89-639, 89-640, 89-641, 89-642, 89-643, 89-644, 89-645, 89-646, 89-647, 89-648, 89-649, 89-650, 89-651, 89-652, 89-653, 89-654, 89-655, 89-656, 89-657, 89-658, 89-659, 89-660, 89-661, 89-662, 89-663, 89-664, 89-665, 89-666, 89-667, 89-668, 89-669, 89-670, 89-671, 89-672, 89-673, 89-674, 89-675, 89-676, 89-677, 89-678, 89-679, 89-680, 89-681, 89-682, 89-683, 89-684, 89-685, 89-686, 89-687, 89-688, 89-689, 89-690, 89-691, 89-692, 89-693, 89-694, 89-695, 89-696, 89-697, 89-698, 89-699, 89-700, 89-701, 89-702, 89-703, 89-704, 89-705, 89-706, 89-707, 89-708, 89-709, 89-710, 89-711, 89-712, 89-713, 89-714, 89-715, 89-716, 89-717, 89-718, 89-719, 89-720, 89-721, 89-722, 89-723, 89-724, 89-725, 89-726, 89-727, 89-728, 89-729, 89-730, 89-731, 89-732, 89-733, 89-734, 89-735, 89-736, 89-737, 89-738, 89-739, 89-740, 89-741, 89-742, 89-743, 89-744, 89-745, 89-746, 89-747, 89-748, 89-749, 89-750, 89-751, 89-752, 89-753, 89-754, 89-755, 89-756, 89-757, 89-758, 89-759, 89-760, 89-761, 89-762, 89-763, 89-764, 89-765, 89-766, 89-767, 89-768, 89-769, 89-770, 89-771, 89-772, 89-773, 89-774, 89-775, 89-776, 89-777, 89-778, 89-779, 89-780, 89-781, 89-782, 89-783, 89-784, 89-785, 89-786, 89-787, 89-788, 89-789, 89-790, 89-791, 89-792, 89-793, 89-794, 89-795, 89-796, 89-797, 89-798, 89-799, 89-800, 89-801, 89-802, 89-803, 89-804, 89-805, 89-806, 89-807, 89-808, 89-809, 89-810, 89-811, 89-812, 89-813, 89-814, 89-815, 89-816, 89-817, 89-818, 89-819, 89-820, 89-821, 89-822, 89-823, 89-824, 89-825, 89-826, 89-827, 89-828, 89-829, 89-830, 89-831, 89-832, 89-833, 89-834, 89-835, 89-836, 89-837, 89-838, 89-839, 89-840, 89-841, 89-842, 89-843, 89-844, 89-845, 89-846, 89-847, 89-848, 89-849, 89-850, 89-851, 89-852, 89-853, 89-854, 89-855, 89-856, 89-857, 89-858, 89-859, 89-860, 89-861, 89-862, 89-863, 89-864, 89-865, 89-866, 89-867, 89-868, 89-869, 89-870, 89-871, 89-872, 89-873, 89-874, 89-875, 89-876, 89-877, 89-878, 89-879, 89-880, 89-881, 89-882, 89-883, 89-884, 89-885, 89-886, 89-887, 89-888, 89-889, 89-890, 89-891, 89-892, 89-893, 89-894, 89-895, 89-896, 89-897, 89-898, 89-899, 89-900, 89-901, 89-902, 89-903, 89-904, 89-905, 89-906, 89-907, 89-908, 89-909, 89-910, 89-911, 89-912, 89-913, 89-914, 89-915, 89-916, 89-917, 89-918, 89-919, 89-920, 89-921, 89-922, 89-923, 89-924, 89-925, 89-926, 89-927, 89-928, 89-929, 89-930, 89-931, 89-932, 89-933, 89-934, 89-935, 89-936, 89-937, 89-938, 89-939, 89-940, 89-941, 89-942, 89-943, 89-944, 89-945, 89-946, 89-947, 89-948, 89-949, 89-950, 89-951, 89-952, 89-953, 89-954, 89-955, 89-956, 89-957, 89-958, 89-959, 89-960, 89-961, 89-962, 89-963, 89-964, 89-965, 89-966, 89-967, 89-968, 89-969, 89-970, 89-971, 89-972, 89-973, 89-974, 89-975, 89-976, 89-977, 89-978, 89-979, 89-980, 89-981, 89-982, 89-983, 89-984, 89-985, 89-986, 89-987, 89-988, 89-989, 89-990, 89-991, 89-992, 89-993, 89-994, 89-995, 89-996, 89-997, 89-998, 89-999, 90-000, 90-001, 90-002, 90-003, 90-004, 90-005, 90-006, 90-007, 90-008, 90-009, 90-010, 90-011, 90-012, 90-013, 90-014, 90-015, 90-016, 90-017, 90-018, 90-019, 90-020, 90-021, 90-022, 90-023, 90-024, 90-025, 90-026, 90-027, 90-028, 90-029, 90-030, 90-031, 90-032, 90-033, 90-034, 90-035, 90-036, 90-037, 90-038, 90-039, 90-040, 90-041, 90-042, 90-043, 90-044, 90-045, 90-046, 90-047, 90-048, 90-049, 90-050, 90-051, 90-052, 90-053, 90-054, 90-055, 90-056, 90-057, 90-058, 90-059, 90-060, 90-061, 90-062, 90-063, 90-064, 90-065, 90-066, 90-067, 90-068, 90-069, 90-070, 90-071, 90-072, 90-073, 90-074, 90-075, 90-076, 90-077, 90-078, 90-079, 90-080, 90-081, 90-082, 90-083, 90-084, 90-085, 90-086, 90-087, 90-088, 90-089, 90-090, 90-091, 90-092, 90-093, 90-094, 90-095, 90-096, 90-097, 90-098, 90-099, 90-100, 90-101, 90-102, 90-103, 90-104, 90-105, 90-106, 90-107, 90-108, 90-109, 90-110, 90-111, 90-112, 90-113, 90-114, 90-115, 90-116, 90-117, 90-118, 90-119, 90-120, 90-121, 90-122, 90-123, 90-124, 90-125, 90-126, 90-127, 90-128, 90-129, 90-130, 90-131, 90-132, 90-133, 90-134, 90-135, 90-136, 90-137, 90-138, 90-139, 90-140, 90-141, 90-142, 90-143, 90-144, 90-145, 90-146, 90-147, 90-148, 90-149, 90-150, 90-151, 90-152, 90-153, 90-154, 90-155, 90-156, 90-157, 90-158, 90-159, 90-160, 90-161, 90-162, 90-163, 90-164, 90-165, 90-166, 90-167, 90-168, 90-169, 90-170, 90-171, 90-172, 90-173, 90-174, 90-175, 90-176, 90-177, 90-178, 90-179, 90-180, 90-181, 90-182, 90-183, 90-184, 90-185, 90-186, 90-187, 90-188, 90-189, 90-190, 90-191, 90-192, 90-193, 90-194, 90-195, 90-196, 90-197, 90-198, 90-199, 90-200, 90-201, 90-202, 90-203, 90-204, 90-205, 90-206, 90-207, 90-208, 90-209, 90-210, 90-211, 90-212, 90-213, 90-214, 90-215, 90-216, 90-217, 90-218, 90-219, 90-220, 90-221, 90-222, 90-223, 90-224, 90-225, 90-226, 90-227, 90-228, 90-229, 90-230, 90-231, 90-232, 90-233, 90-234, 90-235, 90-236, 90-237, 90-238, 90-239, 90-240, 90-241, 90-242, 90-243, 90-244, 90-245, 90-246, 90-247, 90-248, 90-249, 90-250, 90-251, 90-252, 90-253, 90-254, 90-255, 90-256, 90-257, 90-258, 90-259, 90-260, 90-261, 90-262, 90-263, 90-264, 90-265, 90-266, 90-267, 90-268, 90-269, 90-270, 90-271, 90-272, 90-273, 90-274, 90-275, 90-276, 90-277, 90-278, 90-279, 90-280, 90-281, 90-282, 90-283, 90-284, 90-285, 90-286, 90-287, 90-288, 90-289, 90-290, 90-291, 90-292, 90-293, 90-294, 90-295, 90-296, 90-297, 90-298, 90-299, 90-300, 90-301, 90-302, 90-303, 90-304, 90-305, 90-306, 90-307, 90-308, 90-309, 90-310, 90-311, 90-312, 90-313, 90-314, 90-315, 90-316, 90-317, 90-318, 90-319, 90-320, 90-321, 90-322, 90-323, 90-324, 90-325, 90-326, 90-327, 90-328, 90-329, 90-330, 90-331, 90-332, 90-333, 90-334, 90-335, 90-336, 90-337, 90-338, 90-339, 90-340, 90-341, 90-342, 90-343, 90-344, 90-345, 90-346, 90-347, 90-348, 90-34

DOCKETED ITEMS

75

790514014 Forwarded IE Bulletin 79-04, "Incorrect Weights for Spring Check Valves May by Union Engineering Corp." Licensee action required
DEWITT, R. V. Region 4, Dallas, Office of the Director 79/03/30 1p

790519049 Forwarded IE Info Notice 79-08, "Spill of Radioactively Contaminated Rain" -
DEWITT, R. V. Region 4, Dallas, Office of the Director 79/03/30 1p

790519051 Notifies that C-R informed staff that generic response to IE Bulletin 79-02A is met in reactor vessel which cannot be provided before. 790512 Unit will submit plant-specific response by 790516
BERRY, T. E. Omaha Public Power District 79/04/03 1p

790523048 Responds to IE Bulletin 79-03B call has in intention of using ASME B31-212 Type 304 or other welded pipe as by "Longitudinal Welding & Engineering Co."
BERRY, T. E. Omaha Public Power District 79/04/10 1p

790524048 Forwarded IE Bulletin 79-06B, "Review of Operational Errors & Non-Identifications Identified During TMI Incident." - Licensee action required
DEWITT, R. V. Region 4, Dallas, Office of the Director 79/04/14 1p

790524062 Forwarded IE Bulletin 79-08, "Events Relevant to Rolling Water Pump Reactors Identified During TMI Incident." - Licensee action required
DEWITT, R. V. Region 4, Dallas, Office of the Director 79/04/14 1p

790527007 Forwarded IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." - Licensee action required
DEWITT, R. V. Region 4, Dallas, Office of the Director 79/04/14 1p

790529014 Forwarded reply to IE Bulletin 79-05A, "Nuclear Incident at TMI - Reply." -
DEWITT, R. V. Region 4, Dallas, Office of the Director 79/04/14 1p

790529020 Forwarded IE Bulletin 79-09, "Failures of GE Type AW-2 Circuit Breaker in Safety-Related Systems." - Licensee action required
DEWITT, R. V. Region 4, Dallas, Office of the Director 79/04/17 1p

790529094 Forwarded IE Bulletin 79-09B, "Nuclear Incident at TMI - Reply." -
DEWITT, R. V. Region 4, Dallas, Office of the Director 79/04/21 1p

790529098 Forwarded responses to IE Bulletin 79-09B "Review of Operational Errors & Non-Identifications Identified During TMI." - Operators reminded to check confirmation indication when responding to accident conditions
BERRY, T. E. Omaha Public Power District 79/04/23 34pp

790529092 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Unit used not use methods described in bulletin
BERRY, T. E. Omaha Public Power District 79/04/23 4pp

790529099 Responds to IE Bulletin 79-04 re Union using check valves are installed or scheduled to be installed in seismic piping.
BERRY, T. E. Omaha Public Power District 79/04/23 1p

790529097 Forwarded IE Insp Regt 30-285/79-08 re 790528-20 Notice of violation withheld (ref 302752 799)
HARRIS, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/24 2pp

790529098 IE Insp Regt 30-285/79-08 re 790528-20 Noncompliance noted physical barriers do not meet requirements Bulletin withheld (ref 302752 799)
CALDWELL, R. A., HARRIS, G. L. Region 4, Dallas, Office of the Director, HARRIS, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch, 79/04/17 1p

790529098 Notifies that certain safety-related electrical equipment failed to meet minimum qualification criteria per IE Bulletin 79-01 Valve will be replaced
BERRY, T. E. Omaha Public Power District 79/04/15 2pp

R. Periodic operating reports & related correspondence

790514020 Forwarded monthly operating report for Apr 1979.
BERRY, T. E. Omaha Public Power District 79/05/09 1p

790514020 Monthly operating report for Apr 1979
HICKLE, S. J. Omaha Public Power District 79/04/21 7pp

B. Regulatory occurrences: LERs & related correspondence

790514087 Forwarded LER 79-08/03L-0
HARRIS, G. L. Omaha Public Power District 79/04/05 1p

790524084 LER 79-03/03L-0 on 790516 during monthly calibr of rectification protection signal pressure switches found switch AW-2-303 drifted from setpoint tolerance
BLAIR, D. R. Region 4, Dallas, Reactor Operations Nuclear Support Branch, PETERSON, G. L. Omaha Public Power District 79/01/20 2pp

7905180123 Forwarded PWR-79-07R & 79-07/02R)
HARRIS, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/11 2p

790524012 Forwarded PWR-79-02R
HARRIS, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/10 1p

790518004 Forwarded PWR-79-07T correction
HARRIS, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/13 1p

790529023 Forwarded PWR-79-07U & V
HARRIS, G. L. Region 4, Dallas, Office of the Director 79/04/16 1p

790529034 Forwarded PWR-79-07T & V
HARRIS, G. L. Region 4, Dallas, Office of the Director 79/04/16 1p

790529037 Forwarded PWR-79-07T
HARRIS, G. L. Region 4, Dallas, Office of the Director 79/04/16 1p

790529048 Forwarded PWR-79-07A, AW-2 & B
HARRIS, G. L. Region 4, Dallas, Office of the Director 79/04/16 1p

790529041 Forwarded LER 79-09/03L-0
HARRIS, G. L. Omaha Public Power District 79/04/20 1p

790529048 LER 79-09/03L-0 on 790406 at matrix failed test Caused by failure of mercury wetted relay to break contact Relay searched & found normal Matrix will continue to be tested
BERRY, T. E., PETERSON, G. L. Omaha Public Power District 79/04/19 4pp

790529048 Forwarded PWR-79-07A, AW-2 & B re incident at TMI
HARRIS, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/20 1p

790529048 Forwarded PWR-79-07A & B
HARRIS, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/20 1p

790529028 Forwarded LER 79-01/03L-0
HARRIS, G. L. Omaha Public Power District 79/03/07 1p

790529029 LER 79-01/03L-0 on 790404 channel A dc sequencer EI-1 demagnetized matrix lights Caused by OE CR20A 125 volt dc relay feeding internally relay replaced & sequencer tested satisfactorily
COMBLEY, J. L., PETERSON, G. L. Omaha Public Power District 79/04/24 4pp

790529028 Forwarded LER 79-01/03L-0
HARRIS, G. L. Omaha Public Power District 79/03/14 1p

790529021 LER 79-01/03L-0 on 790404 containment spray pump EI-38 failed to start by control switch Caused by packing of circuit breaker breaker connected position, resulting in tripping of breaker Breaker packed out & back in
COMBLEY, J. L. Omaha Public Power District 79/03/16 3pp

790529020 Forwarded LER 79-01/03L-0
HARRIS, G. L. Omaha Public Power District 79/03/14 1p

790529028 LER 79-01/03L-0 on 790807 during surveillance test, matrix test failed for IC matrix Caused by failure of mercury wetted relay to matrix circuit OE CR20A 125 volt dc wetted relay replaced & contacts tested
BERRY, T. E., PETERSON, G. L. Omaha Public Power District 79/05/16 4pp

DOCKETED ITEMS

- 7905020348 Forwards LER 79-018/017-0
ANDREWS, R. L. Onaka Public Power District 7/6/82 1p
- 7905030507 LER 79-018/017-0 on 79050111 sends support appeared inadequate for component cooling water piping-to-connection cooling & filtering unit 50-20 Analysis indicated that clamping piping-to-cooling unit will provide needed support
MALLON, R. Onaka Public Power District 7/6/82 4pp
- DOCKET 80-286 INDIAN POINT STATION, UNIT 3
Security, medical, emergency & fire protection plans
- 7905020360 Forwards, under protest, filing fee for NRC review of revised emergency plan
EARLY, P. J. Power Authority State of New York 7/6/82 1p
- 6 Adjudicatory correspondence
- 7905020309 Offers to provide Board "Comparison of Simulation Models Used in Assessing Effects of Power Plant-Induced Mortality of Fish Population." by G. Quaranta, R. B. Davis & C. Conner of Univ of MA
LEWIS, S. H. Branch 2 7/6/82/30 1p
- 7905020198 Forwards "Comparison of Simulation Models Used in Assessing Effects of Power Plant-Induced Mortality on Fish Populations" per telcon request 7/6/82
RODGE, J. E. Branch 2 7/6/82/30 1p
- J Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$125,000,000 for policies NF-1, 25, 42, 74, 83, 150, 111, 140, 146, 181, 261, 164, 176, 175, 176, 179, 180, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215 & others
GANTT, D. J. American Nuclear Insurers 7/6/82/01 1p
- 7905070502 Confirms increase in liability limit to \$35,000,000 for policies NF-23, 28, 29, 38, 39, 44, 54, 57, 77, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000
- ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 7/6/82/08 1p
- 7905040607 Forwards Amend 21 to Indemnity Agreement 8-17 per 10078140 changes, no increase in liability insurance from \$140 million to \$160 million effective 790501 Supporting documentation and
MALLON, R. J. Antitrust & Indemnity Group 7/6/82/01 4pp
- P Operating license stage documents & correspondence
- 7905030511 Forwards Amend 20 to License DFR-64 & notice of insurance availability
ROMAN, R. A. Operating Reactors Branch 1 7/6/82/29 4pp
- 7905070310 Amend 25 to License DFR-64 revising Tech Specs to allow continuous operation of plant discharge from raw sewage treatment facility
ROMAN, R. A. Operating Reactors Branch 1 7/6/82/29 4pp
- 7905040512 Forwards "Steam Generator Operating History Questionnaire," Revision 1
EARLY, P. J. Power Authority State of New York 7/6/82/30 1p
- 7905040518 "Steam Generator Operating History Questionnaire," Revision 1
Power Authority State of New York 7/6/82/30 1pp
- 7905070549 Ask receipt of NRC 790412 lettering to cooperate in planned analysis scheduled for week of 790504
CANTILL, M. J. Consolidated Edison Co. of New York 7/6/82/30 1p
- 7905100134 Forwards application to amend License DFR-64, proposed Tech Spec changes & \$4,000 fee w/4 check
EARLY, P. J. Power Authority State of New York 7/6/82/30 3pp
- 7905100161 Application for amend to License DFR-64, adding definition to Section 1 App A to new spec for limiting conditions for operation & surveillance requirements to radiological effluent Tech Spec
Power Authority State of New York 7/6/82/30 7pp
- 7905100244 Forwards "Evaluation of Effectiveness of Continuously Operating Fine Mesh Traveling Screen for Reducing Inhibitory Substances Entrainment" Affidavit & Certificate of No Violation
CANTILL, M. J. Consolidated Edison Co. of New York 7/6/82/30 3pp
- 7905100249 "Evaluation of Effectiveness of Continuously Operating Fine Mesh Traveling Screen for Reducing Inhibitory Substances Entrainment"
Consolidated Edison Co. of New York 7/6/82/30 3pp
- 7905030551 Forwards responses to 790501 request for info re heaters, relief valves, loss of Reactor, events, class operator & small break analysis
BAYNE, J. P. Power Authority State of New York 7/6/82/30 3pp
- 7905030554 Forwards request for info re ability of currently operating PWR to safely withstand TMI-2 type events
ROMAN, R. A. Operating Reactors Branch 1 7/6/82/30 4pp
- 6 Inspection reports, SE Bulletin & correspondence
- 7905030599 Forwards IE Insp Rpt 80-286/79-02 on 790521-0217 No noncompliance noted
ROMAN, R. A. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 7/6/82/30 2pp
- 7905060116 IE Insp Rpt 80-286/79-03 on 790521-0217 No noncompliance noted Major areas inspected log & reactor nucleus follows on previous Insp items & observation of control room personnel during simulated emergency drill
ROMAN, R. A. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 7/6/82/30 2pp
- 7905050129 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ROMAN, R. A. Region 1, Philadelphia, Office of the Director 7/6/82/30 1p
- 7905030577 Forwards IE Info Notice 79-07, "Structure of Reactor Tanks"
ROMAN, R. A. Region 1, Philadelphia, Office of the Director 7/6/82/30 1p
- 7905050518 Forwards IE Info Notice 79-08, "Interconnection of Sanitized Air w/Reactor Air Box Used as Source of Breathing Air"
ROMAN, R. A. Region 1, Philadelphia, Office of the Director 7/6/82/30 1p
- 7905030101 Requests extension of time to respond to IE Bulletin 78-12, 124, & 124b to delay in response
BAYNE, J. P. Power Authority State of New York 7/6/82/30 1p
- 7905030513 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ROMAN, R. A. Region 1, Philadelphia, Office of the Director, 7/6/82/30 2pp
- 7905030575 Forwards IE Bulletin 79-05, "Review of Operational Errors & Safety Violations Identified During TMI Incident" License action required
ROMAN, R. A. Region 1, Philadelphia, Office of the Director 7/6/82/30 1p
- 7905070541 Ask receipt of 790503 letter informing NRC of steps taken to correct violations noted in IE Insp Rpt 80-286/79-04
ROMAN, R. A. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 7/6/82/30 1p
- 7905070548 Responds to NRC 790501 letter violations noted in IE Insp Rpt 80-286/79-04 Corrective actions warranted procedures removed from file, procedures & test schedule revised
BAYNE, J. P. Power Authority State of New York 7/6/82/30 3pp
- 7905070572 Forwards IE Insp Rpt 80-286/79-04 on 790506-09 & notice of violation
ROMAN, R. A. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 7/6/82/30 4pp
- 7905070577 Notice of violation from Insp on 790506-09
Region 1, Philadelphia, Office of the Director 7/6/82/30 1pp

DOCKETED ITEMS

77

--7900270102 RE Insp Regs 20-28A/79-04 on 790206-09. Noncompliance with
failure to use latest revision of procedure & failure to
adhere to procedures
BARNACK, R R ; BLUMBERG, R J Region 6, Philadelphia, Office of
the Director KESTER, H B Region 1, Philadelphia, Reactor
Operations Nuclear Support Branch 790202 1504

7900220033 LEM 79-008 has been voided
* Power Authority State of New York 79078400 1

7905220334 LRR 79-009 has been voided
* Power Authority State of New York 79/04/01 10

79002200228 LBN 79-006 has been voided
* Power Authority State of New York 79/034/80 10

7903010516 Forwarded LEE 79-034/001-0
SWWE, J P Power Authority State of New York 79/04/26 10

--PROSECUTOR LEE T. COOPER, JR. at 79:22:27 condensate storage tank level fell below Tech Spec limits during hot shutdown. Caused by use of steam generator blowdown gas which was being held at max. Despite demineralization plant to be added

7405070201 Forward LER 79-025/09L-0
Source: I.R. - Bureau Authority State of New York 78/05/08 16

--9405093305 LER 79-005/03L-0 on 790405 s/c water pump 34 received due to
low discharge pressure/air in pump shaft broke, disabling one
of three essential header pumps caused by bearing failure
mating shaft break repairs are pending
GURBLE-E Power Authority State of New York 79/05/04 12

7825090015 Forwarded LER 78-022/DK-1
CAGILL, W J Consolidated Edison Co of New York 79/05/50 49

--7905198010 LBN 79-012/242-1 on 790525 activity of precipitation sample exceeded 10 times control station level caused by friction released from source external to facility Manufacturer in area has modified installation to prevent recurrence
UNSCCLASS. Consolidated Edition Co. of New York 79/05/80 3ps

7700140021	Forwards UER 79-013/045-0		
CANES, M. J.	Consolidated Edison Co. of New York	79/03/10	Sp

--7908190025 IER 79-015/00T-2 on 790425 activity of precipitation sample exceeded 10 times control station level caused by tritium released from source external to Facility Manufacturer in area has modified installation to prevent recurrence

BUDGET 90-267 OLIVE HAZARD STATION, UNIT 3

7902290090 Discrepancy 790213 submission of security plan for storage of spent fuel & 790226 telcom re requirement for security plan made initial plan is suby to withholding from public record of transmittal is required

80056-0, C Fuel Repurchase & Receipt Branch 79403/27 1a

9905140283 Forward emergency procedure EP-05/A/1800/4, "Loss of Reactor Coolant," containing instructions for operator action for small breaks
 QUERCY, W.B. Duke Power Co 79/05/09 20pp

as General correspondence

7905250131 Urges careful review of staff rep before ordering shutdown
of facility, since action could cause extensive power
curtailments & higher fuel costs for 1.2 million customers
in Carolina piedmont
wired J. R. Rouse 79/04/26 ip

7905020294 Expresses gratitude for decision to close
 79/04/20 11

4. Insurance & indemnity information

7905070302 Confirms increase in liability limit to \$25,000,000 for
petitions MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 24, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERT G M Mutual Atomic Energy Liability Underwriters 79/05/05
In.

7905140438 Forwards Amend 13 to Indemnity Agreement 9-44 per 100R140
changes, re increase in liability insurance from \$140 million
to \$150 million, effective 790501 Supporting documentation
and
BALTIMORE, J. Ambridge & Indemnity Group 79/05/01 App

0325024: Responds to IC Bulletin 79-03 re longitudinal weld defects in certain pipe spools mfg by Youngtown Welding Co. Engineering Co piping used in construction at w/o #1111 main piping under 8-inches will be investigated by 790505 EAYNE, J F Power Authority of State of New York 790404/02 Doc

RD5920298 Forwards: EK Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Licensee action required.
GDSIN:R Region I, Philadelphia, Office of the Director
JWC/RLR

ASAC0803/04 Forwarded to Bulletin 79-268, "Review of Operational Errors & Site Misalignments Identified During TMI Incident."
SEPH, H. H. Region 1, Philadelphia, Office of NRC Director
7/27/84 1a

903846245 Forwarded IR Bulletin JV-08, "Events Relevant to Sol
Water Power Reactors Identified In Incident"
0031N, D II Region 1, Philadelphia, Office of the Director
000000000

Y00210034 Forwarded IL Bulletin 74-09, "Failures of GE Type AR-2
Circuit Breaker in Safety-Related Sys - Licensee action
required"
GSHH, E.H. Region I, Philadelphia, Office of the Director
30-08447 1a

900020278 Newark NJ Bulletin 97-00A, Revision 1. "Review of Operational Errors & Ops Misalignments Identified During TMI Incidents"
 000000000 Region 1, Philadelphia, Office of the Director
 09/04/00 10

190001044/ Comments on IE Bulletin 79-06A re Westinghouse PWR
facilities implementation of bistable trip would create
situation where safety injection activation could be
susceptible to single bus perturbations
MARCO T.M. New York, State of 74/04/25 Zep

7902010004 Forwards addi response to SE Bulletin 79-07 re islandic pig
stress reanalysis, as requested by SEC on 790317. Mail
supplements info in 790424 for
occupational & Power Authorities State of New York 79/05/22 34pp

7903310440 Forwarded addl info to SE Bulletin 79-07 re rising violent
stress analytic method. in response to 790322 request Mail
supplements 790426 & 790302 ltr
Walt R. Brown, Assistant State of New York 79/05/24 Jpp

8. Periodic updates & related correspondence

7003220175: Forwarded effluent monitoring & impingement data specific
in Section 401 Certification for Apr 1979
MONTI, W A Consolidated Edison Co of New York 79/05/10 17pp

AB05150002 Forward's monthly operating report for Apr 1979
 Author: G. L. Brown
 Authoring Office: Office of New York 79/05/11 1

--7909103304 Monthly operating rept for Apr 1979.
COMBUST.C Power Authority State of New York 79/05/01 69

2465230372 Forwards daily record of fish collections for Apr 1
Weekly species breakdown & total weight for Units 2 & 3
0810N.E.H Region 1, Philadelphia, Office of the Director
10/04/14 Ben

© Reversible arrangements, LRS & related correspondence

7903050132 Describes LER-603-947-Q on 790320 Westinghouse review revealed potential for safety analysis methodology to lead to calculated GMI ratios less conservative than previously required. Constitutes 24-hr required notification
 RAYOR, J * Power Authority State of New York 79/03/29 2pp

7905220319 LER 79-011 has been voided
 Bureau, Southern State of New York 79/04/O.L. 19

7905200302 LDR 79-010 has been voided. m04/01. 12

7905220327 LCR 79-307 has been voided. 79/06/01 10

DOCKETED ITEMS

790510231 Submits executed copy of Amend 12 to Indemnity Agreement
B-44 reflecting changes to 10CFR140
PARNER, M. O. Duke Power Co. 7/9/05/06 App

790510348 Forwards replacement copy of Amend 10 to Indemnity Agreement
B-44 in response to 790316 request MRCap of Unit 740412
transmittal ltr
PARNER, M. O. Duke Power Co. 7/9/05/02 App

P Operating license stage documents and correspondence

790510204 Notices of refund of fees, reinitiated 780703, for authority to
transfer fuel between facilities & Crystal River Unit 3. Refund
will be sent when processed.
HILLER, M. O. License Fee Management Branch 7/9/05/03 App

790520014 Forwards Amends 69, 49 & 46 to Licenses 099-38, 370-47 &
099-53, respectively. EIA & notice of issuance & availability
REQD. H. W. Operating Reactors Branch 4 7/9/05/02 App

790520018 Amends 69, 49 & 46 to Licenses 099-38, 370-47 & 099-53,
respectively, which revises EIS by deleting aquatic
surveillance program & adding Woods program
REQD. H. W. Operating Reactors Branch 4 7/9/05/02 App

790510015 Response to R Hattison & D Rose concerning value of passing
natural circulation test on BWR reactor
TEDESCO, B. Assistant Director for Plant Systems 7/9/04/05 App

790508030 Response to 790329 submitted re radiological effluent Tech
Spec, which omitted solid radwaste process control program
Requests omitted portion.
REQD. H. W. Operating Reactors Branch 4 7/9/04/10 App

790508081 Forwards documentation, design info & project
implementation schedule re emergency feedwater sys. as
submitted in NRC 790425 meeting of emergency feedwater
supply to steam generators design adequate
PARNER, M. O. Duke Power Co. 7/9/04/25 App

790501090 Forwards add info re QIC of Nuclear Reactor Regulation
status reft Requests addt'l dialogue re NRC re control sys
REQD. H. W. Duke Power Co. 7/9/04/25 App

790502071 Informs that still has requested review of plant design &
operation, including goal of improved reliability of normal
feedwater sys. & added assurance of emergency feedwater
supply to steam generators design adequate
GRIFFIN, H. Duke Power Co. 7/9/04/25 App

790504047 Corrects error in 790419 ltr to NRC Reported period of
facility mode should be Jan-Mar 1979
PARNER, M. O. Duke Power Co. 7/9/04/25 App

790510516 Informs that small reft analysis review is complete
Analyses are unacceptable & incomplete
ROBERTSON, J. R. Analysis Branch 7/9/04/25 App

790511074 Comments on draft reft received 790420 too lengthy, does not
concentrate on important issues & has claims of incorrect &
misleading statements Reft should be reanalyzed
ROBERTSON, J. R. Analysis Branch 7/9/04/25 App

790504092 Response to 790385 ltr requesting advice on allowable time
interval for submittal of refts to NRC
REQD. H. W. Operating Reactors Branch 4 7/9/04/26 App

790502082 Informs of util position on issuance of formal order re
continued giant operation Written issuance is undesirable as
policy & legally unnecessary
LEW, M. O. Duke Power Co. 7/9/04/29 App

790504032 Forwards response to 790329 request for add'l info re
proposed changes to hydrolic shock suppressor Tech Spec
PARNER, M. O. Duke Power Co. 7/9/04/25 App

790505043 Forwards proposed revision to Tech Specs covering reactor
bleed hydrogen purge gas penetration room ventilation sys.
reactor bleed purge filters & spent fuel pool ventilation
sys.
PARNER, M. O. Duke Power Co. 7/9/05/01 App

790508066 Forwards proposed revision to Tech Specs, relating Tech Spec
4.12 which is no longer required
PARNER, M. O. Duke Power Co. 7/9/05/01 App

790504046 Documents completion of 781006 proposal to delete Tech Spec
re vendor, anchorage & liner plate surveillance programs.
License fee not required
PARNER, M. O. Duke Power Co. 7/9/05/02 App

790510109 In response to NRC 790418 request, forwards proposed Tech
Spec re plant solid radwaste process control program
PARNER, M. O. Duke Power Co. 7/9/05/07 App

790510231 Forwards status on improvements to emergency feedwater sys.
per MRC 790423 ltr & MRC 790426 ltr
PARNER, M. O. Duke Power Co. 7/9/05/07 App

790510348 Lists drawings used for installation of automatic starting
of interconnect emergency feedwater sys. which were sent
to NRC on 7/9/05/03
PARNER, M. O. Duke Power Co. 7/9/05/09 App

790510228 Forwards "Emergency Feedwater Sys. Sys Concept & Analysis"
Pump Installation to be complete by 790509 Overhead drawing
in Central Files
PARNER, M. O. Duke Power Co. 7/9/05/10 App

790510209 Forwards "DSM 177 Fuel Assembly Quenches Group Asymmetric LCA
Load Evaluation Program, Phase 2." & 790410 Supersede
program provided on 7/9/05/11
PARNER, M. O. Duke Power Co. 7/9/05/10 App

790510230 "DSM 177 Fuel Assembly Quenches Group Asymmetric LCA Load
Evaluation Program, Phase 2"
* Duke Power Co. 7/9/04/10 App

790502167 Specifies that analyses were performed w/actual Cycle 4
burnup to ascertain changes required for operation at full
rated power during Cycle 3 Results indicate no need for
changes in core loading or Tech Spec
PARNER, M. O. Duke Power Co. 7/9/05/17 App

790502093 Forwards revised sys concept & analysis re addition of an
autorotational emergency feedwater pump Supersede 790510
submitted Nonpowered drawing
PARNER, M. O. Duke Power Co. 7/9/05/17 App

790504092 Submits results of add'l analysis re 790329 proposed Tech
Spec changes for operation at full rated power during Cycle 3
PARNER, M. O. Duke Power Co. 7/9/05/17 App

790504075 Reverts to EIS Bulletin 79-030 re TH1 incident Forwards
proposed amend to Tech Spec, changing setpoint of
pressure-actuated automatic relief valve & reactor coolant
sys high pressure trip
PARNER, M. O. Duke Power Co. 7/9/05/21 App

790504047 Forwards design description for safety grade anticipatory
reactor trip on burnup trip or loss of main feedwater mode
will be installed for each refueling outage following NRC
approval
PARNER, M. O. Duke Power Co. 7/9/05/21 App

790502028 Forwards summary of EIS Nuclear Inc regulation/documentation
of allow flexibility where allow existed in versions of
FIDE, piping analysis computer program from Jan-Oct 1969
Review & reanalysis included all work through Dec 1970
PORTER, P. L. EIS Nuclear Inc 7/9/05/21 App

790505043 Forwards EIS Nuclear Inc list of HWRs & piping sys which
could have been impacted by deficient computer program
QIC on record of reanalysis for Gaspar piping sys.
GREGG, R. H. General Electric Co. Nuclear Energy Products Div
7/9/05/24 App

790510231 Forwards proposed Tech Spec revision re limiting details
for operation & surveillance requirements
PARNER, M. O. Duke Power Co. 7/9/05/25 App

Q Inspection reports, EIS Bulletin and correspondence

790502042 Forwards IE Insp Repts N0-048/79-04, N0-270/79-04,
& N0-289/79-04 on 790325-07 Re noncompliance noted
LEWIS, R. L. Region 2, Atlanta, Reactor Operations Nuclear Supp.
Branch 7/9/05/15 App

790502093 IE Insp Repts N0-289/79-04, N0-270/79-04, N0-282/79-04 &
790525-07 Re noncompliance noted Major areas inspected fire
protection/prevention program, fire surveillance, fire detection
sys & administrative control procedures
BRADFORD, M. W. TAYLOR, P. A. KELLER, P. J. Region 2, Atlanta,
Reactor Operations Nuclear Support Branch 7/9/05/05 App

790510177 Forwards IE Insp Notice 79-04, "Stress Analysis of
Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
7/9/05/23 App

DOCKETED ITEMS

79

7905100071 Forwarded to Info Notice 79-07, "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100072 Response to HMI Investigation Report Related to Off-Changing Media in HMI Investigation (HMI-1) - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100073 Forwarded to Info Notice 79-08, "Interpretation of Contaminated Gas within Air Gas Used as Source of Draining Air" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100074 Forwarded to Info Notice 79-09, "Spill of Radioactively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100075 Response to HMI Bulletin 79-02 on Longitudinal weld defects on RBB RA 34-type B4 piping or any other welding or filler metal piping or by Vapour/Welding in use or planned for use
79/03/26 App

7905100076 Forwarded responses to HMI Bulletin 79-05 & 79-06, "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100077 Forwarded Response to HMI Bulletin 79-07 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100078 Forwarded Response to HMI Bulletin 79-08 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100079 Forwarded Response to HMI Bulletin 79-09 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100080 Forwarded Response to HMI Bulletin 79-10 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100081 Forwarded Response to HMI Bulletin 79-11 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100082 Forwarded Response to HMI Bulletin 79-12 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100083 Forwarded Response to HMI Bulletin 79-13 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100084 Forwarded Response to HMI Bulletin 79-14 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100085 Forwarded Response to HMI Bulletin 79-15 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100086 Forwarded Response to HMI Bulletin 79-16 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100087 Forwarded Response to HMI Bulletin 79-17 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100088 Forwarded Response to HMI Bulletin 79-18 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100089 Forwarded Response to HMI Bulletin 79-19 on "Hazardous of Radiatively Contaminated Reactor" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100090 Forwarded to HMI Bulletin 79-04, Revision 1, "Review of Operational Errors & Safety Misalignments Identified During TMI Incident" - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100091 Response to HMI Bulletin 79-05, Item 3, re TMI Incident Reactor Protection - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100092 Forwarded Response to HMI Bulletin 79-07 re computer program used for piping analysis - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100093 Forwarded Response to HMI Bulletin 79-08, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100094 Response to HMI Bulletin 79-09, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100095 Forwarded Response to HMI Bulletin 79-10, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100096 Forwarded Response to HMI Bulletin 79-11, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100097 Forwarded Response to HMI Bulletin 79-12, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100098 Forwarded Response to HMI Bulletin 79-13, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100099 Forwarded Response to HMI Bulletin 79-14, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100100 Forwarded Response to HMI Bulletin 79-15, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100101 Forwarded Response to HMI Bulletin 79-16, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100102 Forwarded Response to HMI Bulletin 79-17, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100103 Forwarded Response to HMI Bulletin 79-18, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100104 Forwarded Response to HMI Bulletin 79-19, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100105 Forwarded Response to HMI Bulletin 79-20, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100106 Forwarded Response to HMI Bulletin 79-21, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100107 Forwarded Response to HMI Bulletin 79-22, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100108 Forwarded Response to HMI Bulletin 79-23, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100109 Forwarded Response to HMI Bulletin 79-24, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100110 Forwarded Response to HMI Bulletin 79-25, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100111 Forwarded Response to HMI Bulletin 79-26, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100112 Forwarded Response to HMI Bulletin 79-27, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100113 Forwarded Response to HMI Bulletin 79-28, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100114 Forwarded Response to HMI Bulletin 79-29, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100115 Forwarded Response to HMI Bulletin 79-30, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100116 Forwarded Response to HMI Bulletin 79-31, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

7905100117 Forwarded Response to HMI Bulletin 79-32, Item 1, 2, 4 & 5 re TMI Incident - Region 2, Atlanta, Office of the Director
79/03/26 App

DOCKETED ITEMS

7705050429 Forwarded personnel exposure & monitoring report for 1978
HERSHBACH, J. G. Metropolitan Edison Co. 7/9/04/02 App

7705050404 Forwarded LER 79-018/03L-0
FARRER, W. E. Duke Power Co. 7/9/05/23 App

7705050405 LER 79-018/03L-0 re 770423 reactor trip gamma radiation
sensors made inadequate when containment violation valve on
reactor inlet line failed caused by ruptured operator
diaphragm
LEHNER, B. Duke Power Co. 7/9/05/22 App

DOCKET 79-089 REED COLLEGE RESEARCH REACTOR

J Insurance & liability information

7705050505 Forwarded Amend 9 to Indemnity Agreement E-02/leg 100PR140
changes re increase from \$100 million to \$150 million
effective 7/6/01 supporting documentation mail
SALTSMAN, J. Antitrust & Industry Group 7/9/05/03 App

7705050506 Forwarded Amend 9 to Indemnity Agreement E-02
McFARLANE, E. D. Reed College 7/9/05/07 App

DOCKET 79-097 THREE HILE ISLAND NUCLEAR STATION, UNIT 1

F Security, nuclear, emergency & fire protection plans

7705050506 Forwarded Rept 2 to fire protection RER in response to
770502 Ltr
REED, R. M. Operating Reactors Branch 4 7/9/04/14 App

7705050509 Rept 2 to fire protection RER accepting proposed change in
evacuation rate for proposed new fire service
penetration & electrical cable penetration seals to 770427
Office of Nuclear Reactor Regulation 7/9/04/14 App

7705050510 Requests approval of plan to eliminate four fire detectors
in nuclear instrumentation & reactor protection sys
cabinets
HERSHBACH, J. G. Metropolitan Edison Co. 7/9/05/18 App

G Adjudication correspondence

7705050605 Forwarded close action completed re THE accident
filed against UTG & vendors in G Robert Lammert, et al.,
vs Metropolitan Edison Co. et al.
CARRISON, J. C. American Nuclear Insurance 7/9/05/22 App

J Insurance & liability information

7705050606 Forwarded Amend 8 to Indemnity Agreement E-04 per decPR140
changes re increase in liability insurance from \$100 million
to \$150 million effective 7/6/01
mail
SALTSMAN, J. Antitrust & Industry Group 7/9/05/01 App

7705050607 Reprints assigned Amend 8 to Indemnity Agreement E-04 Nuclear
Liability Insurance Policy will not provide add coverage
CERTIFY, H. F. SFM Service Corp. 7/9/05/26 App

F Operating license stage documents & correspondence

7705050640 Forwarded "Initial Startup Rept"
MORRIS, H. C. Metropolitan Edison Co. 7/9/11/27 App

7705050628 "Initial Startup Rept"
Metropolitan Edison Co. 7/9/11/26 200pp

7705050678 Applies for license authorizing until he receives process &
border radiometric mail at temporary field locations outside
site boundaries
MORRIS, H. C. Metropolitan Edison Co. 7/7/04/10 55pp

7705050679 Forwarded add info on procedures requested in NRC 770219 ltr
re application for approval mail license
HERSHBACH, J. G. Metropolitan Edison Co. 7/9/01/09 143pp

7705050691 EIS supporting Amend 07, 08 & A6 to license 070-028, 070-47 &
070-08, respectively
Operating Reactors Branch 4 7/9/03/02 App

7705050691 Forwarded personnel exposure & monitoring report for 1978
HERSHBACH, J. G. Metropolitan Edison Co. 7/9/04/02 App

7705050694 Confirms 770328 oral commitment to provide advance notice
prior to taking unit out of present safe shutdown condition
HERSHBACH, J. G. Metropolitan Edison Co. 7/9/04/16 App

7705050695 Notifies that Class III Fee required for 770370 application
re ring drive surveillance test has not been received Fee
should be forwarded within 10 days of receipt of ltr
MILLER, W. G. License Fee Management Branch 7/9/04/26 App

7705050697 Requests 90-day extension to 770415 deadline for submitting
draft radiological effluent Tech Spec & Offsite Dose
Calculation Manual
HERSHBACH, J. G. Metropolitan Edison Co. 7/9/04/28 App

7705050702 Notifies that submission of final rept re implementation/
equipment monitoring program at TMI will be delayed to
770513
HERSHBACH, J. G. TROPER, J. G. Metropolitan Edison Co. 7/9/05/03 App

7705050703 Responds to NRC 770205 ltr re potential consequences of
prohibited fuel handling accident include containment
consequences of potential accident are within guidelines of
10CFR100 be further action required
HERSHBACH, J. G. Metropolitan Edison Co. 7/9/05/02 App

7705050704 Forwarded amend for Tech Spec Change Request 77
HERSHBACH, J. G. Metropolitan Edison Co. 7/9/05/15 App

G Inspection reports, EE Bulletin & correspondence

7705050705 EE Bulletin 79-07, "Protection Afforded by Air-Line
Inspector & Supplied-Air Hoses"
Region I, Philadelphia, Office of the Director 7/9/04/12 App

7705050706 Forwarded EE Insp Rept 50-089/77-05 on 770515, 51-02 & 52-04
noncompliance noted
CARLSON, R. T. Region I, Philadelphia, Reactor Construction &
Engineering Support Branch 7/9/05/20 App

7705050707 EE Insp Rept 50-089/77-05 on 770515, 51-02 & 52-04
noncompliance noted Major areas inspected: Service Line
Program
MILLER, W. G. Region I, Philadelphia, Office of the Director 7/9/05/16 App

7705050708 Forwarded EE Insp Rept 50-089/77-05 on 770521-23 & 24-26
noncompliance noted
MORRIS, H. C. Region I, Philadelphia, Reactor Operations Nuclear
Support Branch 7/9/05/21 App

7705050709 EE Insp Rept 50-089/77-05 on 770521-23 & 24-26
noncompliance noted Major areas inspected: Refueling
activities, preparation for refueling, outage related maint,
size supports & restraints, shift logs & records
MORRIS, H. C. Region I, Philadelphia, Office of the Director 7/9/05/26 App

7705050710 Forwarded EE Safe Notice 79-06, "Basis Analysis of
Defect-Related Piping"
MILLER, W. G. Region I, Philadelphia, Office of the Director 7/9/05/13 App

7705050711 Forwarded EE Info Notice 79-06, "Interconnection of
Contaminated Sys w/Env Air Sys Used as Source of Breathing
Air"
MORRIS, H. C. Region I, Philadelphia, Office of the Director 7/9/05/26 App

7705050712 Forwarded EE Info Notice 79-06, "Basis of Radioactively
Contaminated Reim."
MILLER, W. G. Region I, Philadelphia, Office of the Director 7/9/05/30 App

7705050713 Forwarded EE Bulletin 79-06, "Review of Operational Errors
By Management Identified During TMI Incident"
MILLER, W. G. Region I, Philadelphia, Office of the Director 7/9/05/11 App

7705050714 Documents schedule for completing actions required by EE
Bulletin 79-02 Search of presentment documents to determine
set of specified welded pipe will be complete by 770501
HERSHBACH, J. G. Metropolitan Edison Co. 7/9/04/13 App

7905010282 Forwards IC Info Notice 79-09, "Spill of Radioactive Contaminated Resin" failed to satisfy Tech Spec requirements for operability under design basis earthquake loading caused by design error. Embetter will be modifying.
PULTON, J. H. Boston Edison Co. 79/03/30 1p

7905030004 Forwards IE Bulletin 79-06: "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."
GRIER, S. H. Region 1, Philadelphia: Office of the Director 79/04/11 1p

7905020397 Forwards IE Bulletin 79-07, "Balanced Strain Analysis of Safety-Related Piping." Licensee action required.
GRIER, S. H. Region 1, Philadelphia: Office of the Director 79/04/14 1p

7905030004 Forwards IE Bulletin 79-06B: "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."
GRIER, S. H. Region 1, Philadelphia: Office of the Director 79/04/14 1p

7905040167 Forwards IE Bulletin 79-08, "Events Relevant to Selling Water Power Reactors Identified During TMI Incident."
Licensee action required.
GRIER, S. H. Region 1, Philadelphia: Office of the Director 79/04/14 1p

7905030092 Forwards IE Bulletin 79-09, "Failures of DE Type AM-2 Circuit Breaker in Safety-Related Bys." Licensee action required.
GRIER, S. H. Region 1, Philadelphia: Office of the Director 79/04/17 1p

7905010630 Forwards IE Bulletin 79-04a Revision 1, "Review of Operational Errors & Bys Misalignments Identified During TMI Incident."
GRIER, S. H. Region 1, Philadelphia: Office of the Director 79/04/18 1p

7905010630 Provides supplemental info in initial response to IE Bulletin 79-07 & to LER 79-016/01-0. All lines indicating all stresses remain below code allowances. All embetter locations were verified by debris map.
HODGINS, D. C. Boston Edison Co. 79/03/23 2pp

R Periodic operating reports & related correspondence

7905160420 Forwards monthly operating report for Apr 1979
HODGINS, P. J. Boston Edison Co. 79/03/28 1p

7905160423 Monthly operating report for Apr 1979
HODGINS, C. J. Boston Edison Co. 79/03/28, 2pp

D Reportable occurrences, LERs & related correspondence

7905010536 Forwards LER 79-018/01-0
HODGINS, P. J. Boston Edison Co. 79/03/24 1p

7905010540 LER 79-012/01-0 on 790426 until informed that OMB computer program used by DE for seismic analysis is not consistent w/ current requirements. Caused by static program applied during design of Pilgrim affected piping reanalysis.
HODGINS, C. J. Boston Edison Co. 79/04/04, 1p

7905030031 Forwards LER 79-013/01-0
HODGINS, P. J. Boston Edison Co. 79/04/26, 1p

7905020387 LER 79-012/01-0 on 790325 during OPER-09 surveillance testing, design 1 to suppress chamber pressure was less than 1.20 psid as pressure Instruments FI-5047 A & B were greater than 1.20 elsewhere. Caused by signal drift.
HODGINS, C. J. Boston Edison Co. 79/04/26 1p

7905160444 Forwards LER 79-012/01-0
HODGINS, P. J. Boston Edison Co. 79/03/03 1p

7905160447 LER 79-012/01-0 on 790426 seismic analysis computer program for main steam & recirculation piping area overestimates results caused by outdated static analysis software. Different program gave satisfactory results.
HODGINS, C. J. Boston Edison Co. 79/03/09 2pp

7905170625 Requests extension until 790708 for weld & hydrostatic testing program.
HODGINS, D. C. Boston Edison Co. 79/03/09 1p

7905160533 Forwards LER 79-064/01-X-0.
HODGINS, P. J. Boston Edison Co. 79/03/29 1p

7905160533 LER 79-064/01-X-0 on 790509 four recirculation sgt. high, embetter failed to satisfy Tech Spec requirements for operability under design basis earthquake loading caused by design error. Embetter will be modifying.
PULTON, J. H. Boston Edison Co. 79/05/09 1p

7905160534 Forwards LER 79-013/01-0
HODGINS, P. J. Boston Edison Co. 79/03/11 1p

7905160539 LER 79-013/01-0 on 790415 reactor core isolation control, emergency condenser condensate pump tripped caused by damaged relay contacts in pump starting logic. Contacts cleaned & pump logic action successfully tested.
PULTON, J. H. Boston Edison Co. 79/05/10 1p

7905270005 Forwards LER 79-017/01-0
HODGINS, P. J. Boston Edison Co. 79/03/22 1p

7905290560 LER 79-017/01-0 on 790427 control rod 24-25 unwarranted insert signal cause undetermined. Corrective actions relay contacts & relay socket contacts on relay 24-25/2C spray cleaned.
HODGINS, C. J. Boston Edison Co. 79/05/10 1p

7905290472 Forwards LER 79-016/01-0
HODGINS, P. J. Boston Edison Co. 79/03/23 1p

7905300482 LER 79-016/01-0 on 790311 inoperable embetter shaft driven. Cause by embetter 5053 (Bergner-Patterson Model) HSS shafts being disconnected. New embetter installed on 790312.
PULTON, J. H. Boston Edison Co. 79/05/22 2pp

7905300535 Forwards LER 79-018/01-0
HODGINS, P. J. Boston Edison Co. 79/03/23 1p

7905300540 LER 79-018/01-0 on 790319 recirculation pump 3-20A sgt. w/ reactor coolant temp greater than 212 F. primary containment integrity not maintained & delta temp between loops greater than 25 F. Caused by operator error.
HODGINS, C. J. Boston Edison Co. 79/03/23 1p

DOCKET 90-096 RICHMOND STATE UNIV. RESEARCH REACTOR
J. Insurance & indemnity information

7905160246 Forwards Amendment 9 to Indemnity Agreement 8-51 per DOE/RIAT change. re increase from \$100 million to \$200 million, effective 790501. Indemnity information and
SALTZMAN, J. Antitrust & Indemnity Group 79/03/01 5pp

Q Inspection reports, IE Bulletins & correspondence

7905040141 Ack receipt of 790401 & 0407 ltr. Informing ARE of site taken to correct noncompliance noted in NRC 790321 ltr.
HODGINS, D. C. Region 3, Chicago: Reactor Operations Nuclear Support Branch 79/04/20 1p

7905340445 Response to NRC 790321 ltr re noncompliance noted in NRC 790321-0202. Corrective actions 1979 requalification exam will be given to operators during Apr.
TERRY, S. H. & GARRICK, J. T. Michigan State 79/04/07 1p

7905340445 Response to NRC 790321 ltr re 790321-0202. Insp details annex avail.
TERRY, S. H. & GARRICK, J. T. Michigan State 79/04/04 1p

DOCKET 90-249 IZOM NUCLEAR POWER STATION, UNIT 1

7905290475 Forwards DER & EIA re plant spent fuel pool made W/o incl.
HODGINS, D. C. Branch 2 79/04/03, 1p

F Security, medical, emergency & fire protection plans

7905030046 Forwards modified physical security plan/revision 3 Plan withheld (ref DOE/RIAT 7905).
LEE, B. Commonwealth Edison Co. 79/04/26 1p

7905030009 Forwards Chamber drawings PLS7432-7 sheets 1 through 5; w/ design details for fire suppression system to be installed for auxiliary feedwater system & component cooling pumps. Clarify drawings w/mt.
MAJUMDAR, V. P. Commonwealth Edison Co. 79/05/03 2pp

DOCKETED ITEMS

83

D Adjudicatory correspondence

790520094 Affidavit of H. Boushoff re spent fuel issue Professional qualifications & Certificate of the unit
BOSHOFF, H. B. Illinois, State of 79/04/27 13pp

790520071 Response to State of Ill.'s 790420 motion for continuance & request to allow future implementation of intervenor's affidavits Certificate of the unit
BOSHOFF, H. B. Branch 2 79/04/23 App

790520094 Forwards DR & TR re spent fuel pool made H/E unit
BOSHOFF, H. B. Branch 2 79/04/01 1p

7905200130 Provision list of witnesses for unit in Zion spent fuel case
BILFLO, P. John, Illinois & Davis 79/04/01 App

7905200042 Request by unit on its own behalf & on behalf of State of Ill. & NRC for ALE to begin hearings on 790514 Certificate of the unit
BILFLO, P. John, Illinois & Davis 79/04/03 App

7905100121 Interrogatories submitted to state of Ill. per ALE 790519
unit Certificate of the unit
BILFLO, P. John, Illinois & Davis 79/04/09 App

7905100513 Motion to file supplementary Affidavits to response to unit & NRC motions for summary disposition Affidavits of Dr. Boushoff & Dr. Wilson & Certificate of the unit
BILFLO, P. John, Illinois, State of 79/04/10 App

7905100249 Forwards completed Affidavit of H. Boushoff Certificate of the unit
BILFLO, P. John, Illinois, State of 79/04/11 App

7905100011 Forwards Chapter 1 of BAAFF 1713, "Plant Fuel Backup Following Loss of Water During Storage," which contains info relevant to unit's application to increase spent fuel storage pool capacity Request to be filed on unit list
BILFLO, P. John, Illinois, State of 79/04/13 App

7905200347 Motion for summary disposition of State of Ill.'s Contention 21a-1d for lack of specific issue of unit's Affidavits, notices of appearance & withdrawal & Certificate of the unit
BILFLO, P. John, Illinois, State of 79/04/22 App

7905100247 Series summary disposition of Intervenor's Contentions 21F1 12b, 21G1, 21H1 & 21I1. Summary summary disposition of Intervenor's Contentions 21J1
LUTINSKI, Adam, Safety and Licensing Board Panel 79/05/01 App

II General correspondence

7905276014 Response to 790516 list requesting info re leakage of water through liner of spent fuel pool at Facility NRC is monitoring unit's efforts to control seepage
MONTAGU, V. Division of Operating Reactors 79/04/19 App

III Insurance & indemnity information

7905100163 Endorsement W to NRC's Policy #7 2J
DOHART, T. Nuclear Energy Liability Insurance Association 79/04/27 1p

7905100497 Confirms increased liability limit to \$124,000,000 for policies #F 23, 26, 27, 28, 29, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & others
QUARTRELL, J. American Nuclear Insurance 79/05/01 1p

7905270562 Confirms increase in liability limit to \$26,000,000 for policies #F 23, 26, 27, 28, 29, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & others
NRC's E. H. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7905100470 Forwards Amend 9 to indemnity Agreement 8-29 per 10076140 change in increase in liability insurance from \$140 million to \$160 million-effective 790501 Supporting documentation
BILFLO, P. John, Antitrust & Indemnity Group 79/05/01 App

7905100399 Confirms 790501 & 90 agreement w/NRC that Heatingshore need not sign Amend 7 to indemnity Agreement 8-29
GANN, G. T. Johnson & Higgins Insurance 79/05/02 1p

7905100262 Forwards Endorsements 20 & 29 to NRC's Policy #F-107 & Endorsements 47 & 48 to NRC's Policy #F-201
DOHART, T. Commonwealth Edison Co 79/05/16 App

F Operating license stage documents & correspondence

7905200183 Amends 47 & 48 to Licenses DR-29 & DR-46 respectively revising Tech Specs re rad dump time
DOHART, T. Operating Reactors Branch 1 79/04/09 App

7905200180 Safety evaluation supporting Amends 47 & 48 to Licenses DR-29 & DR-46 respectively
DOHART, T. Operating Reactors Branch 1 79/04/09 App

7905200180 Notice of issuance & availability of Amends 47 & 48 to Licenses DR-29 & DR-46 respectively
DOHART, T. Operating Reactors Branch 1 79/04/09 App

7905000482 Notice of intention to develop safety analysis using existing computer codes Request add info
DOHART, T. Operating Reactors Branch 1 79/04/26 1p

7905000482 Requests amend to Tech Specs to require actuation of safety injection based on two out of three channels of low pressurizer pressure & to delete pressurizer level from safeguards logic Class 2 & 3 amend fees unit
NRC's Commonwealth Edison Co 79/04/29 App

7905100251 "Basis Data Measurements at Zion & Fort Calhoun Stations" DR-10, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & others
NRC's Commonwealth Edison Co 79/04/30 App

7905100786 Forwards response to request for addl info re review of proposed license amend to increase allowable SSCA peaking factor limit to 3.93 based on PSCD results
NRC's Commonwealth Edison Co 79/05/03 App

7905200425 Forwards Amends 49 & 46 to Licenses DR-29 & DR-46, respectively
DOHART, T. Operating Reactors Branch 1 79/05/03 App

7905200425 Amends 49 & 46 to Licenses DR-29 & DR-46, respectively
DOHART, T. Operating Reactors Branch 1 79/05/03 App

7905200425 Safety evaluation supporting Amends 49 & 46 to Licenses DR-29 & DR-46, respectively
DOHART, T. Operating Reactors Branch 1 79/05/03 App

7905200440 Notice of issuance & availability of Amends 49 & 46 to Licenses DR-29 & DR-46, respectively
DOHART, T. Operating Reactors Branch 1 79/05/03 App

7905100270 Forwards revised Tech Specs re heating & condenser curves & added provision for overpressure protection.
NRC's Commonwealth Edison Co 79/05/11 App

7905100280 Revised Tech Specs re heating & condenser curves & added provision for overpressure protection
NRC's Commonwealth Edison Co 79/05/11 App

7905200291 Forwards current licensing action items list
NRC's Commonwealth Edison Co 79/05/15 1pp

G Inspection reports, IE Bulletin & correspondence

7905200421 Forwards response to IE Bulletin 70-12 & 70-10A, "Applied Weld Heat in Reactor Pressure Vessel Welds."
NRC's Commonwealth Edison Co 79/05/22 10pp

7905100234 IE Info Notice 79-06, "Basis Analysis of Defective Related Piping"
NRC's Region 3, Chicago, Office of the Director 79/05/23 1p

7905200378 Forwards IE Info Notice 79-07, "Repture of Reactor Tube"
NRC's Region 3, Chicago, Office of the Director 79/05/26 1p

7905100125 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Air w/Out Air Sys Used as Source of Breathing Air"
NRC's Region 3, Chicago, Office of the Director 79/05/28 1p

7905100084 Forwards IE Insp Repts 80-293/79-05 & 80-364/79-06 on 790521-23 No noncompliance noted.
NRC's Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/28 App

7905100407 IE Insp Repts 80-293/79-05 & 80-364/79-06 on 790521-23 No noncompliance noted. Major areas inspected: preparations made for refueling & work during refueling outage.
NRC's Region 3, Chicago, Office of the Director 79/05/28 App

DOCKETED ITEMS

3605010234 Forwards IE info Notice 79-09, "Bill of Radioactively Contaminated Paper"
REFLEK 2/6 Region 3 Chicago, Office of the Director 19/03/90
SA

--7905040323 "Annual Operating Rept 1978" *
* Camerawith Edison Co 79/04/26 24cc

PROB0000007 Forwarded to Bulletin 79-26. "Review of Operational Errors &
Sua Misadventures Identified During THE Accident" - Licensee
action required
KEMPLE, J O Region 3, Chicago, Office of the Director 79/04/11
1x

§ Reportable occurrences, LERs & related correspondence

7980320272 February LES 39-024/03L-0
UNCLASS. & C. Controlling Info. Edison Co. 79/08/08 10

Y005290260 Response to IE Bulletin 79-03 re welding defects in certain
inconspicuously welded pipe spools Plants inspected/re pipe
found
RSCS-C Commercial Edison Co. Unk/6/12 On

--7905000282 LEN 19-026/00L-0 on 790300 during normal operations
discovered channel IL-SSD was 4X higher than other ID stream
stream generator channels Fischer-Porter transmitter
zero-shifted for unknown reason zero result
00000M.F Communistic Bikes Co 79/04/20 .ip

79001092z Forwards IE Bulletin 79-064, "Review of Operational Errors &
Sys Misalignments Identified during SM Incident" - Licensee
action required
APPLER-J G Region 3, Chicago, Office of the Director 7900414
E

7908240543 Farwanda LBS 79-028/03L-0 791008400 4

7902040336 Forwards IE Bulletin 79-068, "Review of Operational Errors &
By Missions Identified During TMI Incident."
REPLER J G Region 3 Chicago, Office of the Director 79/04/14

--7905240846 LTR 79-028/00L-D on 790408 during normal operation
discovered low reading on pressurizer level channel is 45%
caused by transmitter drift (Dayton DP XHTH Model) (NEA)
Adjustment made
ROGERS, C L Commonwealth Edison Co 79/05/08 is

20080327 Forward 3E Bulletin T9-08, "Events Relevant to Boiling
Water Reactor Reactors Identified During THE Incident -
#EPPLER,J G Region 3 Chicago, Office of the Director 09/06/14

7605246838 Forwards LCR 79-031/ABL-6

79C3303035 Forward SE Bulletin 79-04, "Failures of GE Type AB-2
Circuit Breaker in Safety-Related Sys - Licensee action
required."
WFFFLD:J D Region 3, Chicago, Office of the Director 79/04/17
in

7905240354) LER 79/031/80L-D on 79041A' instrument failure alarm for containment purge exhaust ledine monitor repeatedly alarmed Event repeated after alarm repaired Caused by poor solder possibly causing short circuit
METHUEN D A COMMUNICABLE Edition Gc 79/05/08 10

790040142 Forward to Bulletin 79-038: "Nuclear Incident at
TMI-Supp 1"
ADP/PLM:J S Repley J. Chicago, Office of the Director 79/04/21

DOCKET 20-296 OREGON FORTY NUCLEAR POWER STATION, UNIT 1

4 Insurance & indemnity information

--7905040128 IE Bulletin 79-058: "Nuclear Incident at Tho-Supp1 =
Supporting documentation and
* Region 3, Chicago Office of the Director 79/04/26 im

7903140462 Forward Amend 12 to Indemnity Agreement B-52 per 1 CFR610
chapter 6 increases in liability insurance from \$140 million
to \$160 million, effective 790300 supporting documentation
encl
BALPDAM d Antitrust & Indemnity Group 79/03/01 And

7908040070 ACRS recommendations re 790329 incident at TMI suggest high priority be placed on development of safety research on behavior of LMRs during abnormal transients
* ACRS - Advisory Committee on Reactor Safeguards 79/04/07
DAN

FIELDER, J. Harold & Kenneth, H & H Nuclear Consultants, Inc. St.
79/05/03 Doc

--7009040201 Forwards ACRS recommendations re TMI incident, presented on
7/29/87
FRALLY, R P ACRS - Advisory Committee on Reactor Safeguards
10/28/88 In.

7000000000 Forwards Enforcement 4D to AWI Policy 90-190
FEDERAL J Marsh & McLennan, M & H Nuclear Consultants, Inc To
78/03/00 200

--7905040221 In Response to NRC 790418 ltr, states all 790417 ADRG recommendations apply to all PWRs, but were not intended to require immediate changes. Plant made should be made after study of effects on overall safety. TMI excluded. CARBON-X X ADRG - Advisory Committee on Reactor Safeguards 7905040221 Doc.

PROS10024 Forman's Aired 60 to FARM.
DILLIDLAND J E Tennessee Valley Authority 79/05/00 2x

-FRONT10001 Amend 50 to FEAR. Unrevised drawings,
 * Tennessee Valley Authority, 29/05/00 1000

5. Operating license stage September 4, 2002-present.

495380000 Art receipt of Class II fee & application for users in
Licenses 899-33, 899-52 & 899-58 Requests payment of addl
fee
MILLER, W O License Fee Management Branch, 899-0000

PO5292222 Proposes seeking w/Gardia address final test plan based on review of PO5292222 second draft of Gardia connector test plan. List of items needing resolution encl.

05050, V Division of Operating Sections 7/9/06/10 4aa

40010177 Submits schedule for virus mode, in response to WFO 79032
 1br to HB Harris
 WILLIAMS, J E. Tennessee Valley Authority. 79/03/04. 2p.

00010000 Confirms plans for feedwater nozzle insp during Fall 1976
refueling outage as well as feedwater sparger final fit mod.
and removal of ultrasonic test
GILLESPIE, J E Tennessee Valley Authority, TN/05/02 1a

FOUO00029 Forward summary of EDO Nuclear, Inc. resolution/decision(s) of above flexibility award which existed in version(s) of FDSB, citing analysis computer program from Jan-Oct 1969 Review & reanalysis included all went through Dec 1970 PORTER, F L EDO Nuclear, Inc. 79/05/01 gaa

DOCKETED ITEMS

86

--790500067 Forwards EDR Nuclear Inc list of BMEs and piping systems which could have been impacted by deficient computer program
 GE has no record of availability for Cooper piping re
 STEPHENS, P. W. General Electric Co. Nuclear Energy Products Div
 79/01/24 18pp

B Inspection reports, IE Bulletins & correspondence

790500063 Forwards IE Insp Repts 50-259/79-04, 50-260/79-04 &
 50-261/79-04 to 790500062 Re recommendations noted
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director
 79/03/22 2pp

--790500107 IE Insp Repts 50-259/79-04, 50-260/79-04 & 50-261/79-04 on
 790500062 No noncompliance noted Major areas inspected
 plant operations, refueling & status of Unit 1, plant tour &
 liquid radwaste treatment
 SULLIVAN, R. F. Region 2, Atlanta, Office of the Director
 DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear
 Support Branch 79/03/19 2pp

7905001021 Forwards IE Info Notice 79-06, "Stress Analysis of
 Safety-Related Piping"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director
 79/03/23 2pp

790500068 Forwards IE Insp Repts 50-259/79-03, 50-260/79-03 &
 50-261/79-03 on 790500062 No noncompliance noted
 Lusk, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support
 Branch 79/03/23 2pp

--790500147 IE Insp Repts 50-259/79-03, 50-260/79-03 & 50-261/79-03 on
 790500062 No noncompliance noted Major areas inspected
 secondary containment, tank area, testing, IE
 circular & ballistics
 PRICE, D. B. Region 2, Atlanta, Office of the Director
 DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear
 Support Branch 79/03/22 2pp

7905001513 Forwards IE Info Notice 79-08, "Interconnection of
 Contaminated Air w/Boiler Air Used as Source of Breathing
 Air"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director
 79/03/29 2pp

79050010343 Forwards IE Info Notice 79-07, "Bill of Radioactively
 Contaminated Resin"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director
 79/03/26 2pp

7905000516 Responds to IE Bulletin 79-03 No evidence that any stainless
 steel pipe mfg by Youngstown Welding & Engineering Co. is
 used in any AEC Class 1, 2 or 3 safety-related app
 SULLIVAN, R. F. Tennessee Valley Authority 79/04/10 2pp

7905000368 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
 Safety-Related Piping." Licensee action required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director
 79/04/14 2pp

7905000225 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
 Site Misalignments Identified During The Incident"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director
 79/04/14 2pp

7905000700 Forwards IE Bulletin 79-06, "Events Relevant to DMRs
 Identified During The Incident." Licensee action required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director
 79/04/14 2pp

7905000372 Forwards IE Bulletin 79-06, "Failures of SC Type AA-2
 Circuit Breaker in Safety-Related Sys." Licensee action
 required
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director
 79/04/17 2pp

7905000479 Forwards IE Bulletin 79-06A, Revision 1, "Review of
 Operational Errors & Site Misalignments Identified During The
 Incident"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director
 79/04/18 2pp

7905000344 Forwards response to Item 7 & 8 of IE Insp Repts 50-259/79-03,
 50-260/79-03 & 50-261/79-03 re deterioration of Bus-M
 components in AEC Class 1, 2 or 3 safety-related app
 79-18
 SULLIVAN, R. F. Tennessee Valley Authority. 79/04/20 2pp

7905000748 Forwards response to IE Bulletin 79-08 Plant superintendent
 will present review of The Incident to all managers &
 supervisors w/appropriate responsibilities. Containment
 isolation device & procedures have been reviewed.
 SULLIVAN, R. F. Tennessee Valley Authority 79/04/25 14pp

7905000467 Ask receipt of 790423 ltr informing NRC of steps taken to
 correct violations noted in IE Insp Repts 50-259/79-03,
 50-260/79-03 & 50-261/79-03
 SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials
 Safety Branch 79/04/30 2pp

--7905000572 Responds to NRC 790330 ltr re violations noted in IE Insp
 Repts 50-259/79-03, 50-260/79-03 & 50-261/79-03 corrective
 actions entire radwaste bldg properly posted as radioactive
 area
 SULLIVAN, R. F. Tennessee Valley Authority 79/04/23 2pp

--7905000492 Forwards IE Insp Repts 50-259/79-03, 50-260/79-03 &
 50-261/79-03 re violations noted in IE Insp Repts 50-259/79-03,
 50-260/79-03 & 50-261/79-03
 SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials
 Safety Branch 79/03/30 2pp

--7905001003 Notice of violation from Insp on 7905000302
 * Region 2, Atlanta, Office of the Director 79/03/30 2pp

--7905001000 IE Insp Repts 50-259/79-03, 50-260/79-03 & 50-261/79-03 on
 790500062 No noncompliance noted, failure to post radiation
 area, label containers of radioactive melt & barricade high
 radiation area
 JACKSON, L. L. Region 2, Atlanta, Office of the Director
 O'REILLY, J. P. Region 2, Atlanta, Fuel Facility & Materials Safety
 Branch 79/03/27 2pp

7905000452 Forwards response to IE Bulletin 79-04 re incorrect using
 check valve weights. Corrected valve weights do not create
 any overtraveling in pipe, bungs or supports. Add info
 will be provided by 790501
 SULLIVAN, R. F. Tennessee Valley Authority 79/05/01 2pp

7905000502 Forwards add licensee Insp program revisions based on
 further review & comparison of facility design w/requirements
 ASME, ASME & pressure vessel code requirements
 SULLIVAN, R. F. Tennessee Valley Authority 79/05/02 2pp

B Periodic operating reports & related correspondence

79050003243 Forwards "Environ Radioactivity Levels, Annual Rept 1978"
 SULLIVAN, R. F. Tennessee Valley Authority 79/04/27 1p

--7905000504 "Environ Radioactivity Levels, Annual Rept 1978"
 * Tennessee Valley Authority 79-79-3-872 79/04/27 80pp

7905000473 Forwards "Fish Impingement Rept" for first quarter 1979
 SULLIVAN, R. F. Tennessee Valley Authority 79/05/01 2pp

--7905000474 "Fish Impingement Rept" for first quarter 1979
 * Tennessee Valley Authority 79/05/01 2pp

7905000334 Forwards monthly operating rept for Apr 1979
 BEMASE, J. G. Tennessee Valley Authority 79/05/01 2pp

--7905000335 Monthly operating rept for Apr 1979
 BEMASE, J. G. Tennessee Valley Authority 79/04/30 2pp

B Repeatable occurrences, LEDs & related correspondence

79050010114 Forwards LER 79-034/03L-0
 PSL, H. B. Tennessee Valley Authority 79/05/07 1p

--7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001
 FOX

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001
 FOX

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

7905001020 LER 79-034/03L-0 on 790411 during normal operation, heat
 detector alarmed & would not clear Alarm would have
 masked signals from other detectors required to be
 operational. Corrected by personnel. Damaging detector
 * Tennessee Valley Authority 79/05/07 2pp

DOCKETED ITEMS

SECRET 50-200 CODES NUCLEAR STATION

A Applications/instruction stage documents & correspondence

7903140020 Forwards schedule for implementation & revision of Part I
 construction program in response to 790302 ltr
 FILANT, J. H. Nebraska Public Power District 79/05/07 Top

F Security, medical, emergency & fire protection plans

7903030335 Forwards modified physical security plan Plan withheld
 ltr 10/29/82 7903
 FILANT, J. H. Nebraska Public Power District 79/05/14 1p

I Financial information

7903050487 Forwards "Annual Financial Rept 1978"
 FILANT, J. H. Nebraska Public Power District 79/05/04 1p

7903050490 "Annual Financial Rept 1978"
 Nebraska Public Power District 79/05/04 3pp

J Insurance & indemnity information

7903070447 Confirm increased liability limit to \$24,000,000 for
 policies NP-1, 23, 45, 76, 82, 80, 111, 85, 146, 181, 181, 184, 178,
 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 190, 191, 194, 195,
 197, 199, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, 6 others
 BMT79030411, J. American Nuclear Insurers 79/03/01 Top

7903050502 Confirm increase in liability limit to \$24,000,000 for
 policies NP-1, 23, 45, 76, 82, 80, 111, 85, 146, 181, 181, 184, 178,
 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 190, 191, 194, 195,
 197, 199, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, 6 others
 HUBBARD, D. H. Mutual Atomic Energy Liability Underwriters 79/05/01
 1p

7903100365 Forwards Amend V to Indemnity Agreement B-37, per 10CFR46
 changes re increase from \$100 million to \$100 million
 effective 790301 Supporting documentation incl
 BMT79030411, J. Antitrust & Indemnity Group 79/05/01 5pp

7903100384 Forwards executed Amend V to Indemnity Agreement B-37
 FILANT, J. H. Nebraska Public Power District 79/05/01 1p

7903100387 Forwards Endorsements 43 & 46 to NELA Policy NP-209
 FILANT, J. H. Nebraska Public Power District 79/05/11 3pp

P Operating license stage documents & correspondence

7903100404 Forwards Amend 30 to License DPR-46, safety evaluation &
 notice of issuance & availability
 Operating Reactors Branch 3 79/04/27 2pp

7903100502 Amend 30 to License DPR-46, revising App A & B of Tech Specs
 re primary containment & reactor vessel isolation
 instrumentation
 IFP031007, T. A. Operating Reactors Branch 3 79/04/27 25pp

7903100503 Safety evaluation supporting Amend 30 to License DPR-46
 re Office of Nuclear Reactor Regulation 79/04/27 12pp

7903100505 Notice of issuance & availability of Amend 30 to License
 DPR-46
 IFP031007, T. A. Operating Reactors Branch 3 79/04/27 2pp

7903030849 Forwards fee payment for Amends 30 & 43 to PNR Discharge
 information of Class III fees
 FILANT, J. H. Nebraska Public Power District 79/05/02 1p

7903030470 Requests that GE rept MED-20070, "Analytical Model for
 Estimating Drop Forces on Riser Support Structures Caused
 by Condensation Oscillations & Chugging" be included in
 docket
 FILANT, J. H. Nebraska Public Power District 79/03/04 1p

7903030250 Forwards summary of EDG Nuclear, Inc. revision/documentation
 of allow flexibility error which existed in versions of
 PASCAL piping analysis computer program from Jan-01-79
 Review & reanalysis included all work through Dec 1979.
 PORTER, F. L. EDG Nuclear, Inc. 79/05/02 1pp

7903030443 Forwards EDG Nuclear, Inc. list of BWH & piping work which
 could have been initiated by sufficient computer program.
 GE has no record of reanalysis for Cooper piping work.
 STEPHENSON, R. W. General Electric Co./Nuclear Energy Products Div
 79/05/04 1pp

Q Inspection reports, IE Bulletins & correspondence

7903100303 Forwards IE Circular 79-04, "Leakage Locking Risk on Locking
 Valve Operators"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/03/10
 1p

7903030491 Forwards IE Bulletin 79-02B, "Atypical Weld Weld In Reactor
 Pressure Vessel Welds"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/03/03
 1p

7903030494 Forwards IE Circular 79-05, "Moisture Leakage in Steam
 Valve Connections"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/03/03
 1p

7903030473 Forwards IE Info Notice 79-04, "Stress Analysis of
 Safety-Related Piping"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/03/03
 1p

7903030415 Forwards IE Info Notice 79-07, "Capture of Radiactive Steam"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/03/03
 1p

7903030428 Forwards IE Info Notice 79-08, "Interconnection of
 Containment Bays with Air Bay Used as Source of Breathing
 Air"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/03/03
 1p

7903030432 Ack receipt of 790303 ltr re violations noted in IE Bu
 Rept 90-298/79-03 Correction actions alcohol removed from
 reactor room floor & importance of procedures stressed to
 employees
 FILANT, J. H. Nebraska Public Power District 79/03/01 1pp

7903030439 Responds to NRC 790303 ltr re violations noted in IE Bu
 Rept 90-298/79-03 Correction actions alcohol removed from
 reactor room floor & importance of procedures stressed to
 employees
 FILANT, J. H. Nebraska Public Power District 79/03/01 1pp

7903030448 Forwards IE Bulletin 79-04, "Incorrect Heights for Raising
 Check Valves 100 lb Valve Engineering Corp." License action
 required
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/03/10
 1p

7903100514 Forwards IE Info Notice 79-06, "Spill of Radioactive
 Contaminated Resin"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/03/10
 1p

7903040857 Forwards IE Bulletin 79-04B, "Review of Operational Error
 Six Misalignments Identified During TMI Incident"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/04/10
 1p

7903040421 Forwards IE Bulletin 79-08, "Events Relevant to Bidding
 Water Power Reactors Identified During TMI Incident"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/04/10
 1p

7903070072 Forwards IE Bulletin 79-07, "Dynamic Stress Analysis of
 Safety-Related Piping" License action required
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/04/10
 1p

7903050105 Forwards suppl to IE Bulletin 79-05B, "Nuclear Incident at
 TMI"
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/04/10
 1p

7903030473 Forwards IE Bulletin 79-06, "Failures of OE Type AK-3
 Circuit Breaker in Safety-Related Bay" License action
 required.
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/04/10
 1p

7903030427 Forwards IE Bulletin 79-06, "Failures of OE Type AK-3
 Circuit Breaker in Safety-Related Bay" License action
 required.
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/04/10
 1p

7903030427 Forwards IE Bulletin 79-08B, "Nuclear Incident at
 TMI-Suppl."
 SEYFRIE, K. V. Region 4, Dallas, Office of the Director 79/04/10
 1p

R Periodic operating reports & related correspondence

7903100503 Forwards monthly operating report for Apr 1979
 LEBRON, L. C. Nebraska Public Power District 79/05/03 1p

DOCKETED ITEMS

87

--790318025 Monthly operating report for Apr 1979
DOCKED, P D Nebraska Public Power District 79/03/08 4pp

B Reportable occurrences, LERs & related correspondence

7903180120 Forwards PWD-79-A28 & 79-77(MMR)
HADDEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/11 1p

7903040110 Forwards PWD-79-A75
HADDEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/12 1p

7903180280 Forwards PWD-79-A77 correction
HADDEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/12 1p

7903180310 Forwards PWD-79-A76, V & W
HADDEN, G L Region 4, Dallas, Office of the Director 79/04/16 1p

7903180344 Forwards PWD-79-A76 & V
HADDEN, G L Region 4, Dallas, Office of the Director 79/04/16 1p

7903180366 Forwards PWD-79-A72
HADDEN, G L Region 4, Dallas, Office of the Director 79/04/19 1p

7903140308 Forwards LER 79-097/03L-0
LEHRSER, C Nebraska Public Power District 79/04/20 2pp

--7903180326 LER 79-027/02L-0 on 790321 during same spring eye
surveillance testing; CR-790-116 valve failed to reopen by
remote switch caused by axial movement of worm set clutch
collar on linkage; CR-3 operator
FLANNAGAN, E D Nebraska Public Power District 79/04/20 1p

7903010375 Forwards PWD-79-A74A, B, C & D
HADDEN, G L Region 4, Dallas, Office of the Director 79/04/24 1p

7903180397 Forwards PWD-79-A76F, AG, AH, AI & Ahr nuclear incident at
TRI
HADDEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/30 1p

7903180445 Forwards PWD-79-A76E & AL
HADDEN, G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/03/02 1p

300MEET 30-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

7903030464 Submits proposed add to fire protection plan as set forth
in SER Recommends fire hydrant map & supervision of valves
controlling fire water use
HALL, R C Brookhaven National Laboratory 79/04/27 3pp

J Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for
policies 96-1, 29, 43, 76, 83, 100, 111, 140, 145, 151, 161, 164, 170,
175, 174, 170, 176, 180, 182, 185, 186, 187, 188, 189, 190, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 209, 210, 212, 214, 215 & others
QUATTROCHI, J American Nuclear Insurers 79/03/01 1p

7903070382 Confirms increase in liability limit to \$20,000,000 for
policies 96-23, 26, 29, 38, 39, 44, 45, 47, 49, 50, 51, 56, 53, 54, 55, 56,
57, 58, 63, 64, 64, 66, 67, 68, 69, 70, 71, 72, 74, 75, 77, 78, 79, 85, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, S H Mutual Atomic Energy Liability Underwriters 79/03/01 1p

7903140321 Forwards Amend II to Indemnity Agreement 8-41 per 10CFR140
changes re increase in liability insurance from \$140 million
to \$140 million effective 790301 Supporting documentation
WOL
BALTZMAN, J Antitrust & Indemnity Group 79/05/01 4pp

7903030403 Forwards executed Amend II to Indemnity Agreement 8-41 per
10CFR140 request
BURGMAN, W J Wisconsin Electric Power Co 79/05/27 3pp

F Operating license stage documents & correspondence

7903140510 Forwards Amends 38 & 41 to Licenses DPR-24 & DPR-27,
respectively; safety evaluation; EA & notice of issuance &
availability
SCHMIDGER, A Operating Reactors Branch 1 79/04/04 2pp

--7903140520 Amends 35 & 41 to Licenses DPR-24 & DPR-27, respectively
authorizing installation & use of modified spent fuel
storage racks in spent fuel pool which increases capacity
for storage from 325 assemblies to 4,000 assemblies
ZIMMERMANN, L Assistant Director for Systems & Projects
79/04/04 2pp

--7903140526 Safety evaluation supporting Amends 35 & 41 to Licenses
DPR-24 & DPR-27, respectively
A Office of Nuclear Reactor Regulation 79/04/04 1pp

--7903140329 EA of Amends 35 & 41 to Licenses DPR-24 & DPR-27,
respectively
A Office of Nuclear Reactor Regulation 79/04/04 33pp

--7903140333 Notice of issuance & availability of Amends 35 & 41 to
Licenses DPR-24 & DPR-27, respectively
SCHMIDGER, A Operating Reactors Branch 1 79/04/04 3pp

7903160429 Forwards Amends 37 & 42 to Licenses DPR-24 & DPR-27,
respectively & notice of issuance & availability Security
plan evaluation withheld (ref 10CFR27.702)
SCHMIDGER, A Operating Reactors Branch 1 79/04/13 3pp

--7903100442 Amends 37 & 42 to Licenses DPR-24 & DPR-27, respectively;
provisions of NRC-approved physical security
plan
SCHMIDGER, A Operating Reactors Branch 1 79/04/13 4pp

--7903100444 Notice of issuance & availability of Amends 37 & 42 to
Licenses DPR-24 & DPR-27, respectively
SCHMIDGER, A Operating Reactors Branch 1 79/04/13 3pp

7903150071 Forwards info in response to 790321 request re details of
plant shutdown
DENTON, H R Office of Nuclear Reactor Regulation 79/04/16 4pp

7903150071 Request amends to Licenses DPR-24 & DPR-27, changing Tech
Specs re initiation instrument setting limits for
engineered safety features Forwards Class III amend fee
BURDETTE, B Wisconsin Electric Power Co 79/04/27 7pp

7903150081 Responds to IE Bulletin 79-044, item 3 re THE errors
Prescriber low level setpoint bistable returned to
untrip position until logic change requested in 790427
license amend is implemented
BURDETTE, B Wisconsin Electric Power Co 79/04/30 2pp

7903150092 Forwards add info re reactor vessel weld & surveil-
lance metals
BURDETTE, B Wisconsin Electric Power Co 79/05/06 3pp

7903150448 Forwards add info re Tech Spec Change Request &
safety injection actuation circuitry mod to low cut of low
prescriber low pressure logic Requests approval by 79031
to permit made on 790312-13 & 790319-20
BURDETTE, B Wisconsin Electric Power Co 79/05/07 3pp

7903150097 Forwards drawings for piping & instrumentation of
Section 3 of reactor back plan ENL 28 overrider drain
available in Central Files only
BURDETTE, B Wisconsin Electric Power Co 79/05/17 7pp

7903030208 Forwards summary of CES Nuclear, Inc resolution of
all other flexibility error which existed in version of
PIDL piping analysis computer program from Jan-Dec 1969
Review & reanalysis included all work through Dec 1970
ORTER, P L CES Nuclear, Inc 79/05/21 7pp

--7903260460 Forwards EOG Nuclear, Inc list of BWRs & piping
could have been impacted by deficient computer program
SE has no record of reanalysis for Cooper piping re
BUTCHER, R W General Electric Co Nuclear Energy Prod
79/01/24 1pp

7903160329 Submits formal responses to 790310 questionnaire
prescriber heater, limit of prescriber event & steam
generator
BURDETTE, B Wisconsin Electric Power Co 79/05/22 8pp

DOCKETED ITEMS

790304043 Forwards staffing physics testing report re rod worth measurements which employ "rod swap" methodology. Report demonstrates adequacy of nuclear design rod worth predictions.
FAT, C.H. Wisconsin Electric Power Co 7/9/83/24 7pp

790304044 Forwards IE Insp Report 50-046/79-04 & 50-001/79-02 on 79020-03 re notice of violation
DAVID, A.B. Region 3, Chicago, Office of the Director 7/9/83/26 2pp

790304045 Notice of violation from Insp on 79020-03 re Region 3, Chicago, Office of the Director 7/9/83/19 1p

790304046 IE Insp Report 50-046/79-04 & 50-001/79-02 on 79020-03 Noncompliance noted failure to provide 7-day holdup of radioactive gas before release
GROSS, L.M. & HART, J.M. Region 3, Chicago, Office of the Director FIOREN, H.L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 7/9/83/19 10pp

790304047 Forwards IE Info Notice 79-06: "Stress Analysis of Safety-Related Piping"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/22 1p

790304048 Forwards 3b Info Notice 79-07: "Waters of Radwaste Tanks"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/26 1p

790304049 Forwards IE Info Notice 79-06: "Interconnection of Contaminated Dry Air/Wet Air Dry Used as Source of Breathing Air"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/28 1p

790304050 Forwards IE Info Notice 79-06: "Spill of Radioactively Contaminated Resin"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/30 1p

790304051 Forwards IE Bulletin 79-04: "Review of Operational Errors & Non-Compliance Identified During The Incident" Licensee action required
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/11 1p

790304052 Forwards IE Bulletin 79-04: "Review of Operational Errors & Non-Compliance Identified During The Incident" Licensee action required
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/14 1p

790304053 Forwards IE Bulletin 79-04: "Review of Operational Errors & Non-Compliance Identified During The Incident"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/14 1p

790304054 Forwards IE Bulletin 79-07: "Stress Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/18 1p

790304055 Forwards IE Bulletin 79-08: "Gross Element to Boiling Water Pump Reactors Identified During The Incident"
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/14 1p

790304056 Forwards IE Bulletin 79-09: "Evaluation of BE Type AR-2 Circuit Breaker in Safety-Related Dry" Licensee action required
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/17 1p

790304057 Response to IE Bulletin 79-04 Express concern re emergency operating procedures for reactor coolant pump & requirements for immediate tripping of low level actuators
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/17 3pp

790304058 Forwards IE Bulletin 79-08: "Minor Incident at BR-1 Supp."
KEPPLER, J.O. Region 3, Chicago, Office of the Director 7/9/83/21 1p

790304059 Response to IE Bulletin 79-07 re computer programs used in seismic stress analysis of safety-related piping has no computer codes used which utilized algebraic summation techniques
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/23 2pp

790304060 Response to IE Bulletin 79-03 re possibility of laminar void defects in ADRE BR-312 Type 304 stainless steel pipe
Nuclear Review of pipe documentation records indicates no use of such tubing
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/26 4pp

790304061 Response to IE Bulletin 79-04 & 79-04: Revision 1 has established task force to facilitate review & understanding of 7901 incident & impact on facility
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/17 10pp

790304062 Response to IE Bulletin 79-09 re BE Type AR-2 circuit breaker item not to be used at plant
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/07 1p

B Periodic operating reports & related correspondence

790304063 Forwards monthly operating report for Apr 1979
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/09 1p

790304064 Monthly operating report for Apr 1979
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/04 10pp

B Reportable occurrences, ALES & related correspondence

790304065 Forwards LER 79-029/01-0
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/17 1p

790304066 LER 79-023/01-0 on 79010, during refueling leakage in the valve was found with excessive leakage caused by foreign matter accumulation in internal valve. Cleaned, reassembled & successfully retested
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/17 3pp

790304067 Forwards LER 79-034/01-0
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/20 1p

790304068 LER 79-054/01-0 on 790402 overcurrent protection (OCP) contacts for OCP2 reconfigured as bus supply breaker exhibited erratic long time delay trip time caused by hairline cracks in dampen caps cracked caps will be replaced
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/20 3pp

790304069 Forwards LER 79-053/01-0
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/27 1p

790304070 LER 79-065/01-0 on 790407 hydraulic doubler 3/14/19 located on main steam line at top of B steam generator inoperable caused by piston rod O ring leakage doubler repaired
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/27 2pp

790304071 Forwards LER 79-067/01-0
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/27 1p

790304072 LER 79-077/01-0 on 790404 under issued bulletin re potential problem with bearing lubrication administrative controls instituted have to be made as soon as possible
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/27 2pp

790304073 Submit add info on LER 79-004/01-0 re testing of shop based circuit breakers. Margis of shop 27-a exists between wet wet condition & overheat delay setting verified by multi-wire calibrator
BURSTEIN, S. Wisconsin Electric Power Co 7/9/83/10 3pp

DOCKET 50-002 ORBITAL RIVER NUCLEAR PLANT, UNIT 2

J Insurance & indemnity information

790304074 Confirms increase in liability limit to \$104,000,000 for policies 10-1, 20, 43, 78, 83, 100, 111, 140, 146, 191, 161, 144, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 190, 191, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 213, 214, 215 & others
GUTHRIE, J. American Nuclear Insurers 7/9/83/05 1p

790304075 Confirms increase in liability limit to \$36,000,000 for policies 10-26, 28, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96
BURSTEIN, S. Mutual American Energy Liability Underwriters 7/9/83/11 1p

DOCKETED ITEMS

89

7905100292 Forwards Amend & to Indemnity Agreement 8-04 per 10078140 change. Re increase from \$150 million to \$500 million effective 7/9/93. Supporting documentation sent.
SALZMAN, J. Antitrust & Indemnity Group 7/9/93/01 3pp

7905000474 Forwards Endorsement 36 to MELIA Policy NF-105 FIDLER, J. Marsh & McLennan, H & N Nuclear Consultants, Inc. Div 7/9/93/03 3pp

7905000476 Forwards Endorsement 37 to MELIA Policy NF-105 FIDLER, J. Marsh & McLennan, H & N Nuclear Consultants, Inc. Div 7/9/93/03 3pp

7905010399 Ack receipt of NRC ltr indicating info submitted by utility met requirements of 10CFR140.23 Assumes no addl info needed prior to June 1993
HENSE, C. M. Florida Power Corp 7/9/93/03 1p

P Operating license stage documents & correspondence

7905090020 Forwards request for addl info in order to complete review of proposed change to more additive sig
RILEY, B. W. Operating Reactors Branch 8/7/93/04 3pp

7905050291 Agrees to meet w/NRC to resolve & implement safety concerns identified in 790425 Oic of Nuclear Reactor Regulation "Status Report in Commission" re BWR-designed reactors intends to resolve items before 790501 startup
GIBBS, H. L. Florida Power Corp 7/9/93/02 3pp

7905050276 Bypasses interim action in response to 790425 Oic of Nuclear Reactor Regulation "Status Report in Commission" re BWR-designed reactor safety items will be resolved prior to 790503 startup
GIBBS, H. L. Florida Power Corp 7/9/93/01 3pp

7905100254 Responds to NRC 790329 ltr re addition of reactor coolant pump power monitors
HENSE, C. M. Florida Power Corp 7/9/93/07 3pp

7905210072 Forwards actions & design modifications to safety concerns of 790425 status report re NRC actions include implementation of hard-wired control-guards reactor trip on loss of main fuelwater or turbine trip Maffei/val
HENSE, C. M. Florida Power Corp 7/9/93/14 20pp

7905010290 Forwards Tech Spec Change Requests 40, 41, 43, 44, 45 & 46 for amend to App A & B of license 898-V2, consisting of changes to administrative controls, emergency fuelwater sig & electrical power sig Certificate of Doc encl
STEWART, M. P. Florida Power Corp 7/9/93/03 23pp

7905010109 Forwards page change for Tech Spec change Request 46 Also forwards "Borated Water & Sodium Hydroxide Storage Tanks Drawdown Transient Analysis."
STEWART, M. P. Florida Power Corp 7/9/93/03 3pp

7905050144 "Borated Water & Sodium Hydroxide Storage Tanks Drawdown Transient Analysis"
Florida Power Corp 7/9/93/03 20pp

7905050185 Forwards revised pages to 790129 Tech Spec Change Request 27 & "Test Report for Boron Qualification Testing of Potential Transformer Model J2M4 & Current Transformer Model J2M4" Certificate of Doc encl
STEWART, M. P. Florida Power Corp 7/9/93/03 10pp

7905050189 "Test Report for Boron Qualification Testing of Potential Transformer Model J2M4 & Current Transformer Model J2M4"
Florida Power Corp 7/9/93/03 19pp

7905030944 Forwards revised pages to BWP-1001, Feb 1993 Cycle 2 reload sig & to Tech Spec Change Request 30, 44 790310 Certificate of Doc encl
STEWART, M. P. Florida Power Corp 7/9/93/03 18pp

Q Inspection reports, IE Bulletin & correspondence

7905010192 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping"
Florida Power Corp 7/9/93/03 2pp

7905030404 Forwards IE Info Notice 79-07, "Buphore of Reducible Tanks"
Florida Power Corp 7/9/93/04 1p

7905010302 Forwards IE Info Notice 79-05, "Interconnection of Contaminated Dry Air/Br Air Sys Used as Source of Breathing Air"
Florida Power Corp 7/9/93/02 2pp

7905010303 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
Florida Power Corp 7/9/93/03 1p

7905050009 Forwards response to items 1, 2, 3, 4 & 5 in IE Bulletin 79-05A re TH Incident. Review demonstrates that similar events would not result in similar consequences at Crystal River
STEWART, M. P. Florida Power Corp 7/9/93/09 7pp

7905010313 Forwards IE Insp Rept 50-302/79-14 on 790323 Re noncompliance noted Discussions w/ Insp
Florida Power Corp 7/9/93/03 2pp

7905030264 IE Insp Rept 50-302/79-14 on 790323 Re noncompliance noted Major areas inspected enforcement history license reported actions, safety performance, radiation protection, environment, security & QA
Florida Power Corp 7/9/93/09 3pp

7905010403 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-04
Florida Power Corp 7/9/93/12 1p

7905010400 Responds to NRC 790313 ltr re violations noted in IE Insp Rept 50-302/79-04 Corrective actions welding rod holding even temp gauges calibrator at regular intervals & calibrator ethylene dispensed
Florida Power Corp 7/9/93/03 2pp

7905050418 Forwards IE Insp Rept 50-302/79-04 on 790323-08 & notice of violation
Florida Power Corp 7/9/93/13 2pp

7905010421 Notice of violation from Insp on 790323-08
Florida Power Corp 7/9/93/08 1p

7905010471 IE Insp Rept 50-302/79-04 on 790323-08 Noncompliance noted Failures to follow calibrator control procedure & inadequate welding rod control procedures
Florida Power Corp 7/9/93/08 7pp

7905040207 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Sig Misalignments Identified During TH Incident"
Florida Power Corp 7/9/93/14 2pp

7905040204 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping" License Action required
Florida Power Corp 7/9/93/14 1p

7905040205 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Reactor Identified During TH Incident"
Florida Power Corp 7/9/93/14 1p

7905100239 Responds to IE Bulletin 79-03 Re welded pipe from Youngman Welding & Engineering Co. in help note
STEWART, M. P. Florida Power Corp 7/9/93/14 1p

7905030142 Forwards IE Bulletin 79-09, "Failures of CR Type AM-2 Circuit Breaker in Safety-Related Sys" License action required
Florida Power Corp 7/9/93/17 2pp

7905020403 Forwards IE Bulletin 79-04A, Revision 1, "Review of Operational Errors & Sig Misalignments Identified During TH Incident"
Florida Power Corp 7/9/93/18 2pp

7905030620 Ack receipt of 790409 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-08
Florida Power Corp 7/9/93/18 1p

DOCKETED ITEMS

- 7903290432 Forwards IE Insp Rept 50-032/79-05 on 790304-08 Notice of violation withheld (ref 102982 7903)
MENNAN, W. Region 2, Atlanta, Safeguards Branch 79/03/14
2pp
- 7903290441 IE Insp Rept 50-032/79-05 on 790304-08 Noncompliance noted deficiency in records & repts re program for safeguarding nuclear msh. Details withheld (ref 102982 7903)
DAVID, C. & OILCOFF, P. Region 2, Atlanta, Office of the Director 79/03/15 1p
- 79032904502 Responds to IE Bulletin 79-07, P/PM/PI If program used on all project made. Response based on review of analytical methods used to predict stresses in safety-related piping approved by BAW & Gilbert Associates
STEWART, M. P. Florida Power Corp. 79/04/24 4pp
- 7903290451 Act receipt of 790416 ltr informing MRC of steps taken to correct violations noted in IE Insp Rept 50-032/79-03
LEWIS, B. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 1p
- 7903290452 Responds to MRC 790323 ltr re violations noted in IE Insp Rept 50-032/79-03 Corrective actions lacking data being reviewed & forwarded in retrospective manner & surveillance procedures being revised
STEWART, M. P. Florida Power Corp. 79/04/14 2pp
- 7903290453 Forwards IE Insp Rept 50-032/79-03 on 790315-14 & notice of violation
LEWIS, B. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/01 2pp
- 7903290454 Notice of violation from Insp on 790315-19
Region 2, Atlanta, Office of the Director 79/03/23 1p
- 7903290455 IE Insp Rept 50-032/79-03 on 790315-19 Noncompliance noted failure to review & approve variable chemistry data sheet & failure to conduct supervisory review of surveillance test results
DAVID, C. & OILCOFF, P. WHIT, M. W. Region 2, Atlanta, Office of the Director 79/05/27 7pp
- 7903290456 Responds to IE Bulletin 79-04 Results of reanalysis indicate piping stresses to be very close to original values & will within seismic stress allowable
STEWART, M. P. Florida Power Corp. 79/05/01 2pp
- 7903290457 Forwards response to IE Bulletin 79-03B BAW has provided guidelines to assist in writing procedures for establishing & maintaining natural circulation flowdown will describe actions to take in event flowdown flow is lost
STEWART, M. P. Florida Power Corp. 79/03/24 2pp
- B Periodic operating reports & related correspondence
- 7903290458 Forwards revised pages (Bapt 2) to Annual Review Operating Rept. Vol 1
STEWART, M. P. Florida Power Corp. 79/04/27, 7pp.
- 7903290459 Forwards monthly operating rep for Apr 1979
STEWART, M. P. Florida Power Corp. 79/05/10 1p.
- 7903290459A LER 79-032/03L-0 on 790404 discovered a decay heat discharge shutoff valve BW-110 would not control flow in automatic Gaseous Venting ECCB pump operability demonstration performed w/public factors results
COOPER, J. Florida Power Corp. 79/04/23 2pp
- 7903290460 Forwards LER 79-040/03L-0
STEWART, M. P. Florida Power Corp. 79/05/01 1p
- 7903290462 LER 79-040/03L-0 on 790403 containment purge supply line AHW-2 would not fully open caused by cracked right angle drive gear drive Motor & drive assembly removed
COOPER, J. Florida Power Corp. 79/04/27 2pp
- 7903290463 Forwards supplemental info re LER 79-056/04L-1 on 790304 neutron sample analyzed w/inadequate procedures caused by inadequate sample time in connecting action proposed
STEWART, M. P. Florida Power Corp. 79/05/01 2pp
- 7903290467 Forwards LER 79-035/03L-0
STEWART, M. P. Florida Power Corp. 79/05/01 1p
- 7903290468 LER 79-035/03L-0 on 790404 radioactivity monitor BW-4-1 to be inaccurately positioned while changing particulate filters Detector repositioned & returned to use Personnel retrained on correct method of installation
COOPER, J. Florida Power Corp. 79/04/23 2pp
- 7903290469 Forwards LER 79-036/03L-0
STEWART, M. P. Florida Power Corp. 79/05/01 1p
- 7903290470 LER 79-036/03L-0 on 790404 failure of meteorological monitoring tower base monitoring device discovered during reactor bldg purge caused by loose terminal box at 125 foot elevation Terminal tightened & returned to use on 790407
COOPER, J. Florida Power Corp. 79/04/24 2pp
- 7903290474 Forwards supplemental info re LER 79-036/03L-0 on 790404 operational & preoperational studies of discharge rates variations differed more than six std deviations caused by natural & seasonal variations & unit thermal output
STEWART, M. P. Florida Power Corp. 79/05/01 4pp
- 7903290475 Forwards LER 79-037/03L-0
STEWART, M. P. Florida Power Corp. 79/05/01 1p
- 7903290476 LER 79-037/03L-0 on 790407 ECCB sample valve TAV-2 water-steam Gaseous Venting DAV-2 tested & returned to use on 790423
COOPER, J. Florida Power Corp. 79/04/26 2pp
- 7903290482 Forwards LER 79-038/03L-0
STEWART, M. P. Florida Power Corp. 79/05/01 1p
- 7903290484 LER 79-038/03L-0 on 790409 pressurizer water level high time isolation valve DAV-3 would not close Gaseous Venting DAV-3 tested & returned to use on 790415
COOPER, J. Florida Power Corp. 79/05/01 2pp
- 7903290485 Forwards supplemental info re LER 79-016/03L-1 on Jan 79 neutron sample were not analyzed using procedures required in LTD caused by inadequate sample time
STEWART, M. P. Florida Power Corp. 79/05/01 1p.
- 7903290486 Forwards LER 79-041/03L-0
STEWART, M. P. Florida Power Corp. 79/05/01 1p
- 7903290488 LER 79-041/03L-0 on 790409 methyl iodine removal effluents less than 99% caused by five gases & other side streams particulate interfering chemical & its impregnated charcoal will be removed following plant refueling
COOPER, J. Florida Power Corp. 79/05/01 2pp
- 790310241 Forwards LER 79-042/03L-0
STEWART, M. P. Florida Power Corp. 79/05/01 1p
- 790310244 LER 79-042/03L-0 on 790415 storage tank SA level down to 325,500 gallons caused by improper lineup Tank filled to Tech Spec limits
COOPER, J. Florida Power Corp. 79/05/02 2pp.
- 7903140023 Forwards LER 79-043/03L-0
STEWART, M. P. Florida Power Corp. 79/05/14 1p.
- 7903140028 LER 79-043/03L-0 on 790420 channel functional & corr. operability of fine particulate line instrumentation SP-190 not performed in required time caused by personnel error in scheduling surveillance procedure
COOPER, J. Florida Power Corp. 79/05/08 2pp

DOCKETED ITEMS

91

7905203049 Forwards LER 79-044/03L-0
STEWART, M P Florida Power Corp 79/05/16 1p

---7905203073 LER 79-044/03L-0 on 790423 while attempting to add boron acid to RCD-chemical addition pump 3B would not operate
Cause under investigation Corrective actions will be based on evaluation results
COOPER, J Florida Power Corp 79/05/10 2pp

7905203078 Forwards LER 79-044/04E-2
STEWART, M P Florida Power Corp 79/05/10 1p

---7905203089 LER 79-044/04E-2 on 790511 environ samples not analyzed
using procedures providing lowest level of detection equal to or less than Tech Specs requirements Caused by inadequate sample time
Florida Power Corp 79/05/13 2pp

7905203093 Forwards LER 79-044/04L-0
STEWART, M P Florida Power Corp 79/05/22 1p

---7905203098 LER 79-044/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

7905203097 Forwards LER 79-045/03L-0
STEWART, M P Florida Power Corp 79/05/22 1p

---7905203098 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

7905203098 Forwards LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

---7905203099 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

7905203099 Forwards LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

---7905203100 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

7905203100 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

---7905203101 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

7905203101 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

---7905203102 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

7905203102 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

---7905203103 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

7905203103 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

---7905203104 LER 79-045/03L-0 on 790428 during plant shutdown for refueling outage decay heat removal valve & failed to open upon remote activation Caused by washer binding at stem nut interface & inadequate lubrication & torque limiter setting
COOPER, J Florida Power Corp 79/05/10 2pp

7905203111 Responds to State of IL's 790221 notice for continuance & request to allow future suppression of intervenor's affidavit Certificate of Swc encl
9005ARD, R J Branch 2 79/03/13 4pp

7905203114 Forwards SER & EIA re spent fuel pool mod W/o encl
9005ARD, R J Branch 2 79/04/03 1p

7905203120 Provides list of witnesses for trial in lien spent fuel case
STEWART, M P Branch 2 79/04/03 2pp

7905203022 Request by util on its own behalf & on behalf of State of IL & NRC, for AUSA to begin hearings on 790518 Certificate of Swc encl
9014ARD, R J Branch 2 79/04/06 4pp

7905203012 Interrogatories submitted to state of IL per AUSA 790119 order Certificate of Swc encl
9056ARD, R J Branch 2 79/04/29 4pp

7905203026 Motion to file supplementary affidavit to response to util & NRC motions for summary disposition Affidavits of Swc encl
9014ARD, R J Branch 2 79/04/10 2pp

7905203028 Forwards unexecuted affidavit of N Bernstein Certificate of Swc encl
9014ARD, R J Branch 2 79/04/13 4pp

7905203040 Forwards Chapter 1 of EMD77-1371, "Spent Fuel Heatup Following Loss of Water During Storage," which contains info relevant to util's application to increase spent fuel storage pool capacity Request to be placed on evc list
9005ARD, R J Branch 2 79/04/13 40pp

7905203067 Moves for summary disposition of State of IL's Contentions 21(f) & 21(g) for lack of genuine issue of fact Affidavits, motions of appearance & withdrawal Certificate of Swc encl
9014ARD, R J Branch 2 79/04/27 25pp

7905203063 Denies summary disposition of intervenors' Contentions 21(f) & 21(g) Grants summary disposition of intervenors' Contentions 21(f) & 21(g)
LUTSEN, E Atlantic Safety & Licensing Board Panel 79/05/06 2pp

H General correspondence

7905203014 Responds to 790202 ltr requesting info re leakage of water from tank accessed level of Tech Specs Caused by inadequate design Request for engineering info was initiated to provide corrective measure
STEWART, M P Division of Operating Reactors 79/04/19 7pp

J Insurance & indemnity information

7905203013 Enforcement W/ re NRELI Policy 79-02
683AG, T Nuclear Energy Liability Insurance Association 79/03/27 1p

7905203047 Confirms increased liability limit to \$126,000,000 For policies 79-1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

7905203048 Affidavit of N Bernstein re spent fuel issues, Professional qualifications & Certificate of Swc encl
9014ARD, R J Branch 2 79/02/23 4pp

DOCKETED ITEMS

- 7905020636 Forwarded IE Insp Rept 80-302/79-05 on 790204-08 Notice of violation withheld (ref 100PR2 7901)
REDA, H W Region 2, Atlanta, Safeguards Branch 79/03/16
App
- 7905020641 IE Insp Rept 80-302/79-05 on 790204-08 Noncompliance noted deficiencies in records & reports re program for safeguarding nuclear waste details withheld (ref 100PR2 7901)
DAVIS, C L, DILLON, P E Region 2, Atlanta, Office of the Director 79/03/16 1p
- 7905040002 Response to IE Bulletin 79-07 P10701 re program used on all project code Revisions based on review of analytical methods used to predict behavior in safety-related piping app.
contacted by RSM & DILLON Associates
STEAMER, M P Florida Power Corp 79/04/28 App
- 7905020701 Act receipt of 790416 for deferring NRC of steps taken to correct violations noted in IE Insp Rept 80-302/79-01
LEWIS, C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/01 1p
- 7905020905 Response to NRC 790320 for re violations noted in IE Insp Rept 80-302/79-03 Corrective actions pending data being reviewed & forwarded in subsequent manner & surveillance procedures being revised
STEAMER, M P Florida Power Corp 79/04/16 App
- 7905020994 Forwarded IE Insp Rept 80-302/79-03 on 790318-19 & notice of violation
LEWIS, C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 App
- 7905020402 Notice of violation from Insp on 790318-19
Region 2, Atlanta, Office of the Director 79/03/23 1p
- 7905020410 IE Insp Rept 80-302/79-03 on 790318-19 Noncompliance noted failures to review & approve radiation monitoring data sheet & failure to document supervisory review of surveillance test results
SHAFER, W D, WOOD, D D, WHITE, K W Region 2, Atlanta, Office of the Director 79/03/27 7pp
- 7905040493 Response to IE Bulletin 79-04 Results of analysis indicate piping stressors to be very close to original values & well within seismic stress allowable
STEAMER, M P Florida Power Corp 79/05/04 App
- 7905070012 Forwarded response to IE Bulletin 79-03B RSM Acc provided guidelines to assist in writing procedures for establishing & maintaining material circulation procedures until describe actions to take in event procedure plan is lost
STEAMER, M P Florida Power Corp 79/05/04 App
- B Periodic operating reports & related correspondence**
- 7905030351 Forwarded revised pages 10ppg 21 to "Annual Enduser Operating Rept." Vol 1
STEAMER, M P Florida Power Corp 79/04/27 7pp
- 7905010103 Forwarded monthly operating rept for Apr 1979
STEAMER, M P Florida Power Corp 79/05/13 1p
- 7905020104 Monthly operating rept for Apr 1979
KERNEDY, H W Florida Power Corp 79/05/07 App
- B Reportable occurrences, LDRs & related correspondence**
- 7905070038 Forwarded LER 79-008/017
STEAMER, M P Florida Power Corp 79/03/27 1p
- 7905070040 LER 79-003/017-E on 790423 until was notified that Rachael Mfg Co M2V may not close within Tech Rept 3-a limit during accident. Caused by discovery of add forces on valve drive valve to be modified
COOPER, J Florida Power Corp 79/04/23 10pp
- 7905040043 Forwarded LER 79-036/03L-0
STEAMER, M P Florida Power Corp 79/04/26 1p
- 7905040020 LER 79-036/03L-0 on 790403 power supply breaker for reactor bldg radiometric monitor BNA-6 was in tripped position. Cause unknown. Breaker reset & BNA-6 returned to svc after satisfactory completion of IP-050 test
COOPER, J Florida Power Corp 79/04/23 App
- 7905040088 Forwarded LER 79-033/03L-0
STEAMER, M P Florida Power Corp 79/04/22 1p
- 7905040078 LER 79-033/03L-0 on 790404 discovered A decay heat pump discharge check valve BNA-110 would not conduct flow in automatic. Cause unknown. BSC pump operability demonstration performed & satisfactory results
COOPER, J Florida Power Corp 79/04/23 App
- 7905040039 Forwarded LER 79-040/03L-0
STEAMER, M P Florida Power Corp 79/05/01 1p
- 7905040052 LER 79-040/03L-0 on 790403 containment purge supply to drive gear case motor & drive assembly removed
IP-010 would not fully open. Cause by cracked right angle
COOPER, J Florida Power Corp 79/04/27 App
- 7905070037 Forwarded supplemental info re LER 79-016/040-1 on 790403 analysis sample analyzed inadequate procedures caused by inadequate sample size. No corrective action proposed
STEAMER, M P Florida Power Corp 79/05/01 App
- 7905070037 Forwarded LER 79-035/03L-0
STEAMER, M P Florida Power Corp 79/05/01 1p
- 7905070002 LER 79-035/03L-0 on 790404 radiometric monitor BNA-6 was incorrectly positioned while changing particulate filters. Failure reported & returned to svc. Personnel restricted on proper method of installation
COOPER, J Florida Power Corp 79/04/23 App
- 7905070043 Forwarded LER 79-036/03L-0
STEAMER, M P Florida Power Corp 79/05/01 1p
- 7905070026 LER 79-036/03L-0 on 790404 failure of meteorological monitoring tower heat monitoring device discovered during reactor bldg purge. Cause by loose thermal box at 175 ft. 440 elevation. Terminal tightened & returned to svc on 790407
COOPER, J Florida Power Corp 79/04/24 App
- 7905070034 Forwarded supplemental info re LER 79-039/040-0 on 790403 operational & preoperational studies of discharge well marshes differed more than two std deviations caused by natural or seasonal variations & unit thermal output
STEAMER, M P Florida Power Corp 79/05/01 App
- 7905070045 Forwarded LER 79-037/03L-0
STEAMER, M P Florida Power Corp 79/05/01 1p
- 7905070048 LER 79-037/03L-0 on 790407 close sample valve CAV 2 a-c close. Cause unknown. CAV-2 applied & returned to svc on 790423
COOPER, J Florida Power Corp 79/04/26 App
- 7905070049 Forwarded LER 79-038/03L-0
STEAMER, M P Florida Power Corp 79/05/01 1p
- 7905070049 LER 79-038/03L-0 on 790407 pressure water system. Line isolation valve CAV-3 would not close. Cause unknown. CAV-3 tested & returned to svc on 790412
COOPER, J Florida Power Corp 79/05/01 App
- 7905080029 Forwarded supplemental info re LER 79-016/040-1 on Jan 1979 environ samples were not analyzed using procedures required in STD. Caused by inadequate sample time
STEAMER, M P Florida Power Corp 79/05/01 1p
- 7905080028 Forwarded LER 79-041/03L-0
STEAMER, M P Florida Power Corp 79/05/04 1p
- 7905080031 LER 79-041/03L-0 on 790409 methyl iodine recd. 48 hrs less than 90% caused by flow gases & other alle effects. Instruments deteriorating. Chemical & its improvement. Chemical will be removed following plant refueling
COOPER, J Florida Power Corp 79/05/01 App
- 7905100044 Forwarded LER 79-042/03L-0
STEAMER, M P Florida Power Corp 79/05/07 1p
- 7905100044 LER 79-042/03L-0 on 790410 interstage heat exchanger to 308,500 gallons. Caused by improper lineup. Heat filled by Tech Rept 1011.
COOPER, J Florida Power Corp 79/05/02 App
- 7905100023 Forwarded LER 79-043/03L-0
STEAMER, M P Florida Power Corp 79/05/14 1p
- 7905100023 LER 79-043/03L-0 on 790409 channel function test & operability of fire protection instrumentation SP-190 not performed in required time. Caused by personnel error in scheduling surveillance procedures
COOPER, J Florida Power Corp 79/05/06 App

DOCKETED ITEMS

91

- 7902303049 Forwards LER 79-04/03L-0
STEWART, W.P. Florida Power Corp 79/03/10 1p
- 7902303073 LER 79-04/03L-0 on 790423 while attempting to add borate acid to RCS chemical addition pump 1B would not operate
Cause under investigation Corrective Action will be based on evaluation results
COOPER, J. Florida Power Corp 79/03/10 2pp
- 7902303075 Forwards LER 79-04/03L-0
STEWART, W.P. Florida Power Corp 79/03/10 1p
- 7902303083 LER 79-04/03L-0 on 790511 environ samples not analyzed using procedures involving 1000s level detectors equal to or less than Tech Specs requirements Caused by inadequate sample time
Florida Power Corp 79/03/10 2pp
- 7902303089 Forwards LER 79-04/03L-0
STEWART, W.P. Florida Power Corp 79/03/10 1p
- 7902303095 LER 79-04/03L-0 on 790423 during plant condition for refueling outage, decay tank removal valve 4 failed to open upon remote activation Caused by weather binding at valve not interface & inadequate lubrication & torque limiter setting
COOPER, J. Florida Power Corp 79/03/10 2pp
- 7902303097 Forwards LER 79-04/03L-0
STEWART, W.P. Florida Power Corp 79/03/10 1p
- 7902303099 LER 79-04/03L-0 on 790424, core flood valve CFV-B annunciator did not activate properly Cause unknown
Corrective action to be taken prior to ascension into Mode 3
COOPER, J. Florida Power Corp 79/03/10 2pp
- 7902303094 Forwards LER 79-04/03L-0
STEWART, W.P. Florida Power Corp 79/03/10 1p
- 7902303096 LER 79-04/03L-0 on 790501 reactor coolant scrubber RSH-WO found inoperable Caused by inadvertent damage to scrubber by unknown persons Scrubber replaced & spare tested safe for long
COOPER, J. Florida Power Corp 79/03/10 2pp
- 7902303094 Forwards LER 79-04/03L-0
STEWART, W.P. Florida Power Corp 79/03/10 1p
- 7902303098 LER 79-04/03L-0 on 790423 boron concentration in BWR acid tank exceeded level of Tech Spec Caused by inadequate design Request for engineering info was initiated to provide corrective measure
COOPER, J. Florida Power Corp 79/03/10 2pp
- DOCKET 30-309 CRYSTAL RIVER NUCLEAR PLANT, UNIT 4
P Operating license stage documents & correspondence
- 7902303098 Forwards Tech Spec Change Requests 40,41,43,44,45 & 48 for amend to App A & B of License DPM-72, consisting of changes to administrative controls, emergency feedwater sig & electrical power sig Certificate of Rev encl
STEWART, W.P. Florida Power Corp 79/03/10 2pp
- DOCKET 30-304 ZION NUCLEAR POWER STATION, UNIT 2
R NRC Safety Evaluation Report (SER), update & correspondence
- 7902303099 Forwards SER & ISA re plant spent fuel pool made W/O encl
COOPER, J. Florida Power Corp 79/04/03 1p
- F Security, medical, emergency & fire protection plans
- 7902303096 Forwards modified physical security plan, Revision 5, Plan withheld (encl 100592 790)
LER 3 Commonwealth Edison Co 79/04/26 1p
- 7902303097 Forwards Chondron drawings PL74527-7, sheets 1 through 3, w/drawing details for fire suppression sys to be installed for existing feedwater sig & component control pumps
Oversee drawings encl
RAUHTON, W.P. Commonwealth Edison Co 79/03/23 2pp
- 0 Adjudicatory correspondence
- 7902303076 Affidavit of H. Reinhoff re spent fuel issue Professional qualifications & Certificate of Rev encl
REINHOFF, H.R. Illinois State of 79/02/22 1pp
- 7902303071 Response to State of IL's 790221 motion for continuance & request to allow future supplementation of intervenor's affidavits Certificate of Rev encl
COOPER, J. Florida Power Corp 79/04/03 2pp
- 7902303084 Forwards SER & ISA re spent fuel pool made W/O encl
COOPER, J. Florida Power Corp 79/04/03 1p
- 7902303089 Provides list of witnesses for trial in Zion spent fuel case
STEPHENS, P. Indiana, Lincoln & Beale 79/04/03 2pp
- 7902303092 Request by util on its own behalf & on behalf of State of IL & ARC for ASL to begin hearings on 790234 Certificate of Rev encl
STEPHENS, P. Indiana, Lincoln & Beale 79/04/03 2pp
- 7902303091 Interrogatories submitted to state of IL per ASL 790119 order Certificate of Rev encl
COOPER, J. Florida Power Corp 79/04/03 2pp
- 7902303088 Motion to file supplementary affidavits to responses to util & ARC motions for summary disposition Affidavits of 30 Granddads & 30 Minor & Certificate of Rev encl
STEPHENS, P. Illinois State of 79/04/10 2pp
- 7902303094 Forwards unexecuted affidavit of H. Reinhoff Certificate of Rev encl
REINHOFF, H.R. Illinois State of 79/04/10 2pp
- 7902303091 Forwards Chapter 1 of 540077-1271, "Spent Fuel Handling Following Loss of Water During Storage," which contains info relevant to util's application to increase spent fuel storage pool capacity Request to be placed on file
STEPHENS, P. Affidavit Unknown 79/04/10 40pp
- 7902303097 Motion for summary disposition of State of IL's Contention 2(a)-(d) for Lack of genuine issue of fact Affidavits, notices of appearance & withdrawal & Certificate of Rev encl
COOPER, J. Florida Power Corp 79/04/10 20pp
- 7902303094 Series summary disposition of intervenor's Contentions 2(a)-(d) & 2(c) & 2(c) & 2(c) Summary disposition of intervenor's Contentions 2(a)-(d)
LUTON, E. Atomic Safety and Licensing Board Panel 79/04/01 2pp
- H General correspondence
- 7902303094 Response to 790202 re requesting info re leakage of water through liner of spent fuel pool at facility NRC is monitoring util's efforts to control leakage
STEPHENS, P. Division of Operating Reactors 79/04/10 2pp
- J Insurance & indemnity information
- 7902303094 Endorsement 99 to NRCUL Policy PF-02
ORRIS, Y. Nuclear Energy Liability Insurance Association 79/03/27 1p
- 7902303097 Confirms increased liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & 216
GALTHER, J. American Nuclear Insurers 79/03/31
- 7902303094 Confirms increase in liability limit to \$120,000,000
policy NF-1, 28, 43, 74, 82, 100, 111, 140, 146, 151, 161, 164, 173, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203,

DOCKETED ITEMS

--7903200507 Safety evaluation supporting Amends 47 & 48 to Licensee DPM-39 & DPM-48, respectively
Office of Nuclear Reactor Regulation 79/04/09 3pp

--7903200510 Notice of issuance & availability of Amends 47 & 48 to Licensee DPM-39 & DPM-48, respectively
SCHMEICER, A Operating Reactors Branch 1 79/04/09 3pp

7903200502 Notice of intention to develop safety analysis using existing computer codes Requests add info
WOLBRIDGE, C Commonwealth Edison Co 79/04/26 1p

7903200502 Requests amend to Tech Spec to require activation of safety injection based on two out of three channels of low pressurizer pressure & to delete pressurizer level from emergency logic Class 1 & 2 amend page one
REED, C Commonwealth Edison Co 79/04/30 3pp

7903200521 "Gamma Dose Measurements at Five & Four Calhoun Stations"
EUS, M. C., WRIGHT, S. L., REED, S. H. & J. E. & J. C. P. P. A-0075
NABISCH, C-075 79/04/30 127pp Available at NTS 47 25

7903200534 Forwards response to request for addl info re review of proposed license amend to increase allowable LOCA peaking factor limit to 1.03 based on ECCS availability
NABISCH, C-075 Commonwealth Edison Co 79/05/03 4pp

7903200542 Forwards Amends 49 & 48 to Licensee DPM-39 & DPM-48, respectively, safety evaluation & notice of issuance & availability
SCHMEICER, A Operating Reactors Branch 1 79/05/03 3pp

--7903200542 Amends 49 & 48 to Licensee DPM-39 & DPM-48, respectively
SCHMEICER, A Operating Reactors Branch 1 79/05/03 3pp

--7903200543 Safety evaluation supporting Amends 49 & 48 to Licensee DPM-39 & DPM-48, respectively
Operating Reactors Branch 1 79/05/03 3pp

--7903200544 Notice of issuance & availability of Amends 49 & 48 to Licensee DPM-39 & DPM-48, respectively
SCHMEICER, A Operating Reactors Branch 1 79/05/03 3pp

7903200527 Forwards revised Tech Spec re heating & cooldown curves & added provision for overpressure protection
REED, C Commonwealth Edison Co 79/05/11 3pp

--7903200527 Revised Tech Spec re heating & cooldown curves & added provision for overpressure protection
Commonwealth Edison Co 79/05/11 3pp

7903200591 Forwards current licensing open item reactor list.
REED, C Commonwealth Edison Co 79/05/11 1pp

6 inspection reports, IE Bulletin & correspondence

7903200621 Forwards response to IE Bulletin 79-102 & 79-104: "Atypical Heat Map in Reactor Pressure Vessel Head"
REED, C Commonwealth Edison Co 79/03/22 10pp

7903200634 Forwards IE Info Notice 79-06: "Stress Analysis of Safety-Related Piping"
NABISCH, C-075 Region 3, Chicago, Office of the Director 79/03/22

Forwards IE Info Notice 79-07: "Stress of Reactor Tanks"
Region 3, Chicago, Office of the Director 79/03/26

7903200634 Forwards IE Info Notice 79-09: "Spill of Radioactively Contaminated Resin"
NABISCH, C-075 Region 3, Chicago, Office of the Director 79/03/26

7903200607 Forwards IE Bulletin 79-04: "Review of Operational Error By Missions Identified During TMS Incident" - Licensee action required
NABISCH, C-075 Region 3, Chicago, Office of the Director 79/04/12

7903200620 Response to IE Bulletin 79-03 re welding defects in steel longitudinally welded pipe spools Plants inspected: pipe found
REED, C Commonwealth Edison Co 79/04/12 3pp

7903200632 Forwards IE Bulletin 79-06A: "Review of Operational Error By Missions Identified During TMS Incident" - Licensee action required
NABISCH, C-075 Region 3, Chicago, Office of the Director 79/04/12

7903200634 Forwards IE Bulletin 79-06B: "Review of Operational Error By Missions Identified During TMS Incident" - Licensee action required
NABISCH, C-075 Region 3, Chicago, Office of the Director 79/04/12

7903200637 Forwards IE Bulletin 79-06: "Events Relevant to Reactor Water Purity Reactors Identified During TMS Incident"
NABISCH, C-075 Region 3, Chicago, Office of the Director 79/04/12

7903200638 Forwards IE Bulletin 79-07: "Failure of 8E Type AB-2 Circuit Breaker in Safety-Related Sys" - Licensee action required
NABISCH, C-075 Region 3, Chicago, Office of the Director 79/04/12

7903200642 Forwards IE Bulletin 79-05B: "Nuclear Incident at TMS-Bogal"
NABISCH, C-075 Region 3, Chicago, Office of the Director 79/04/12

--7903200642 IE Bulletin 79-05B: "Nuclear Incident at TMS-Bogal" - Supporting documentation incl
Region 3, Chicago, Office of the Director 79/04/21 10pp

--7903200642 ACES recommendations re 790320 incident at TMS Bogal: primary to be placed on development of safety research on behavior of LWRs during anomalous transients
ACES - Advisory Committee on Reactor Safeguards 79/04/22 3pp

--7903200601 Forwards ACES recommendations re TMS incident, primary
NABISCH, C-075 ACES - Advisory Committee on Reactor Safeguards 79/04/12 1p

--7903200621 In response to IWS 790318 letter all 790417 ACES recommendations apply to all PWRs, but were not intended to require immediate changes plant needs should be made after study of effects on overall safety. This included
NABISCH, C-075 ACES - Advisory Committee on Reactor Safeguards 79/04/22 3pp

7903200623 Forwards response to IE Bulletin 79-07 requesting info re stress analysis of safety-related piping. Reanalysis indicates most of intramural combination has little effect on pipe stresses & equipment support loads.
REED, C Commonwealth Edison Co 79/04/24 4pp

7903200630 Forwards IE Insp Repts 79-295/79-26 & 79-004/79-07 re 790219-23 Notice of violation withheld (ref 107FR 790)
REED, C-075 Region 3, Chicago, Safeguards Branch 79/04/24

--7903200777 IE Insp Repts 79-295/79-26 & 79-004/79-07 re 790219-23 Noncompliance details withheld (ref 107FR 790)
REED, C-075 Region 3, Chicago, Safeguards Branch 79/04/19 1p

7903200642 Response to IE Bulletin 79-04 re 3.4 or 4-inch Vessel re check valves are in use at Dresden or Quad Cities. Review of files has identified one of sub valves in some piping sys but review is incomplete until next later.
REED, C Commonwealth Edison Co 79/04/24 3pp

DOCKETED ITEMS

93

R Periodic operating reports & related correspondence

7905030323 Forwarded "Annual Operating Report 1978"
WANDRE, H. E. Commonwealth Edison Co. 7/9/04/26 1p
--7905030323 "Annual Operating Report 1978"
WANDRE, H. E. Commonwealth Edison Co. 7/9/04/26 2pp

B Reportable occurrences, LERs & related correspondence

7905100309 Forwarded LER 79-027/03L-0
WANDRE, H. E. Commonwealth Edison Co. 7/9/04/30 1p
--7905100302 LER 79-027/03L-0 on 790419 DLT-446 found to be 77 higher
than other two channels. Caused by turbine sealant ref. log
level transmitter being out of calibration.
WANDRE, H. E. Commonwealth Edison Co. 7/9/04/30 1p
7905100306 Forwarded LER 79-021/03L-0
WANDRE, H. E. Commonwealth Edison Co. 7/9/04/30 1p
--7905100309 LER 79-025/03L-0 on 790320 transmitters ZFT-444, 445 & 446
for reactor coolant flow loss B high by 4.7%, 4.4% & 4.125%
respectively. Caused by instrument drift. New calibration
technique being used.
CAMPELLO, J. Commonwealth Edison Co. 7/9/04/30 1p
7905100300 Forwarded LER 79-025/03L-0
WANDRE, H. E. Commonwealth Edison Co. 7/9/05/08 1p
--7905100309 LER 79-025/03L-0 on 790412 temp control module TR-43
circumventing interlock on hydrogen recombiner. Caused by
mechanic's failure to notify shift engineer of removal for
repair. Then reinstalled.
JOHNSON, J. H. Commonwealth Edison Co. 7/9/05/08 1p

DOCKET 50-303 Kewaunee Nuclear Power Plant

o Adjudicatory correspondence

7905030070 Notifies that preparing conference & hearing will be held
on alleged violations by licensee & imposition of
penalties.
CHILK, B. J. Office of the Secretary of the Commission. 7/9/04/30
3pp

N General correspondence

7905100304 Notifies that ER Mathews is now vice president of company
EN Jones retired on 7/9/03
FDR, Wisconsin Public Service Corp. 7/9/05/07 1p

J. Insurance & indemnity information

7905030487 Confirms increased liability limit to \$124,000,000 for
policyholders 1-25, 43, 74, 82, 100, 111, 140, 145, 181, 181, 181, 170,
175, 176, 178, 179, 180, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
GUATTROCCIO, J. American Nuclear Insurance. 7/9/05/01 1p
7905030502 Confirms increase in liability limit to \$26,000,000 for
policyholders 1-25, 43, 74, 82, 100, 111, 140, 145, 181, 181, 181, 170,
175, 176, 178, 179, 180, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
GUATTROCCIO, J. American Nuclear Insurance. 7/9/05/01 1p
7905030502 Confirms increase in liability limit to \$26,000,000 for
policyholders 1-25, 43, 74, 82, 100, 111, 140, 145, 181, 181, 181, 170,
175, 176, 178, 179, 180, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
GUATTROCCIO, J. American Nuclear Insurance. 7/9/05/01 1p

7905100303 Forwarded Amend & to Indemnity Agreement B-50, per 100%140
changes in increase from \$140 million to \$160 million,
effective 7/9/01. Supporting documentation encl.
BALTIC, M. J. Actuarial & Indemnity Group. 7/9/05/01 3pp.

7905100304 Forwarded accepted Amend & to Indemnity Agreement B-50,
effective 7/9/01.
MATHIAS, E. R. Wisconsin Public Service Corp. 7/9/05/18 3pp

P. Operating license stage documents & correspondence

7905030493 Discovers 790320 Nelson with GRS of Westinghouse re
incorrect weights for Nelson Model 5085 Smith check valves
used in safety injection system.
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/02 1p
7905030493 Forwarded Amend 27 to License DPR-43 & notice of issuance &
availability.
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/03 3pp

--7905030493 Amend to License DPR-43 changing titles of functional
sections & renumbering add'l positions
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/03 1pp

--7905100301 Notice of issuance & availability of Amend 27 to License
DPR-43
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/03 2pp

7905100303 Forwarded Amend 28 to License DPR-43 & notice of issuance &
availability. Security plan evaluation withheld
until 10/30/03.
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/10 3pp

--7905100303 Amend 28 to License DPR-43, incorporating industrial security
manual.
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/10 2pp

--7905100302 Notice of issuance & availability of Amend 28 to License
DPR-43
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/10 3pp

7905100307 Forwarded info in response to 790321 request re details of
plant shutdowns.
BENTON, H. H. Office of Nuclear Reactor Regulation. 7/9/04/10 4pp

7905040471 Discovers draft safety evaluation of Mod to drop pressurizer
level as required. SCCH indicating signal Mod 5 Test Stop
changes acceptable.
LOMBARD, R. Plant Systems Branch. 7/9/04/27 1p

7905100300 Forwarded Amend 29 to License DPR-43, safety evaluation &
notice of issuance & availability.
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/27 3pp

--7905030304 Amend 29 to License DPR-43 revising Test Space to require
attestation of safety injection. Based on flow out of three
channels of low pressurizer pressure.
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/27 3pp

--7905030304 Amend 29 to License DPR-43 revising Test Space to require
attestation of safety injection. Based on flow out of three
channels of low pressurizer pressure.
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/27 3pp

--7905030304 Amend 29 to License DPR-43 revising Test Space to require
attestation of safety injection. Based on flow out of three
channels of low pressurizer pressure.
SCHNEIDER, A. Operating Reactors Branch 1 7/9/04/27 3pp

7905100309 Forwarded Excess Nuclear Co report 3N-WP-79-27, "Cycle 5 SAR" &
WJ Nuclear Co report "Refined Safety Evaluation" dated 7/9/03.
& "Reactor Test Program" dated 7/9/03.
MATHIAS, E. R. Wisconsin Public Service Corp. 7/9/05/08 1p

--7905100309 "Cycle 5 SAR"
JEROME, R. L. CHEN, J. C. & BROWN, F. B. Excess Nuclear Co., Inc.
Excess of Excess Corp. 1 3N-WP-79-27 7/9/04/03 33pp

--7905100309 "Reactor Test Program"
MATHIAS, E. R. Wisconsin Public Service Corp. 7/9/05/08 27pp

--7905100309 "Refined Safety Evaluation"
JOLLY, J. F. & BROWN, F. B. & BROWN, F. B. Wisconsin Public Service
Corp. 7/9/04/03 35pp

7905100309 Forwarded "Reactor Test Program"
MATHIAS, E. R. Wisconsin Public Service Corp. 7/9/05/08 1p

--7905030309 "Reactor Test Program, Revision 5"
MATHIAS, E. R. Wisconsin Public Service Corp. 7/9/05/08 35pp.

Q Inspection reports, IR Bulletins & correspondence

7905100303 Forwarded IR Info Notice 79-04, "Stress Analysis of
Safety-Related Piping"
REPLER, J. J. Region 2, Chicago, Office of the Director. 7/9/03/23 1p

7905040408 Forwarded IR Info Notice 79-07, "Rupture of Radiaste Tanks"
REPLER, J. J. Region 2, Chicago, Office of the Director. 7/9/03/26 1p

7905101016 Forwarded IR Info Notice 79-08, "Interconnection of
Combustion Gas with Air Gas Used as Source of Breathing
Air"
REPLER, J. J. Region 2, Chicago, Office of the Director. 7/9/03/28, 1p

DOCKETED ITEMS

- 7905030049 Forwards IE Bulletin 79-06: "Review of Operational Errors & Non-Identifications Identified During THE Incident" - Licensee action required
NEFFLER, J. D. Region 3, Chicago, Office of the Director 79/04/11 1p
- 7905010419 Forwards IE Bulletin 79-06A: "Review of Operational Errors & Non-Identifications Identified During THE Incident" - Licensee action required
NEFFLER, J. D. Region 3, Chicago, Office of the Director 79/04/16 1p
- 7905040428 Forwards IE Bulletin 79-06B: "Review of Operational Errors & Non-Identifications Identified During THE Incident" - Licensee action required
NEFFLER, J. D. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040443 Forwards IE Bulletin 79-07: "Seismic Stress Analysis of Safety-Related Piping" - Licensee action required
NEFFLER, J. D. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040400 Forwards IE Bulletin 79-08: "Wentz Release is Noting Water Pump Reactors Identified During THE Incident" - Licensee action required
NEFFLER, J. D. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905020501 Response to IE Bulletin 79-03 Investigation of piping records reveals that welded seam pipe mfg by Youngstown Welding & Engineering Co not used in fabrication of safety-related pipe at facility
MATHIAS, E. R. Wisconsin Public Service Corp 79/04/16 1p
- 7905030295 Forwards IE Bulletin 79-09: "Failures of 6C Type AA-2 Circuit Breaker in Safety-Related Sys" - Licensee action required
NEFFLER, J. D. Region 3, Chicago, Office of the Director 79/04/17 1p
- 7905020319 Forwards IE Bulletin 79-09B: "Nuclear Incident at THE-Bay" - Licensee action required
NEFFLER, J. D. Region 3, Chicago, Office of the Director 79/04/21 1p
- 7905040289 Response to IE Bulletin 79-07 re seismic stress analysis of safety-related piping. Method used in analysis of seismic loading is square root of sum of squares, not that mentioned in bulletin
MATHIAS, E. R. Wisconsin Public Service Corp 79/04/25 13pp
- 7905040319 Response to IE Bulletin 79-04: "Incorrect Weights for Swing Check Valves Mfg by Valian Engineering Corp" - Accepted weights re-analyzed & found to be within allowable safety limits.
MATHIAS, E. R. Washington Public Power Supply System 79/04/26 3pp
- R Periodic operating reports & related correspondence
- 7905030200 Forwards monthly operating report for Apr 1979
MATHIAS, E. R. Wisconsin Public Service Corp. 79/05/07 1p
- 7905030335 Monthly operating report for Apr 1979.
MATHIAS, E. R. Wisconsin Public Service Corp 79/04/20 4pp
- table occurrences, LERs & related correspondence
- 7905030039 LER 79-002/011-2 re 790221 level generator in Manual speed Control failed on 790221 0002 & 13 Caused by excessive wear to bronze pinion in synchro-motor gear housing due to improper gear alignment
MATHIAS, E. R. Wisconsin Public Service Corp 79/05/12 3pp
- DOCKET 80-004 PHABRIE ISLAND NUCLEAR STATION, UNIT 2
P. Security: medical, emergency & fire protection plans
- 7905030459 Forwards info requested in NRC 790204 ltr re fire protection program Revision to 790318 fire protection outline encl.
MATHIAS, E. R. Northern States Power Co 79/05/02 18pp
- 7905030462 Forwards supplemental info on status of security plan implementation info withheld (ref 10CR92 790)
MATHIAS, E. R. Northern States Power Co 79/05/25 1p
- I Financial Information
- 7903100228 Forwards "Financial & Statistical Info" as suppl to 'tense Financial Rep 1978'
MATHIAS, E. R. Northern States Power Co 79/05/10 1p
- 7905010021 "Financial & Statistical Info" submitted as suppl to "Annual Financial Rep 1978"
MATHIAS, E. R. Northern States Power Co 79/03/30 21pp
- J Insurance & Indemnity Information
- 7905020497 Confirms increased liability limit to \$104,000,000 for policies NR-1, 25, 42, 76, 83, 105, 111, 145, 146, 151, 161, 164, 170, 173, 174, 175, 176, 180, 183, 185, 186, 187, 188, 199, 192, 193, 194, 195, 197, 199, 200, 201, 204, 206, 207, 209, 210, 212, 214, 215 & others.
SMITH, D. H. American Nuclear Insurers 79/05/01, 1p
- 7905020282 Confirms increase in liability limit to \$36,000,000 for policies HF-22, 26, 29, 30, 33, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 61, 62, 63, 64, 67, 68, 70, 71, 72, 74, 76, 77, 79, 80, 86, 87, 88, 89, 90, 92, 93, 94, 95 & 96.
SMITH, D. H. Mutual Atomic Energy Liability Underwriters 79/05/01 1p
- 7905100477 Forwards Amend 7 to Indemnity Agreement B-60 per 10CR916 change re increase in liability insurance from \$100 million to \$160 million, effective 790501 Supporting documentation encl.
SMITH, D. H. Antitrust & Indemnity Group 79/05/01, 4pp
- 7905020374 Forwards Amend 9 to Indemnity Agreement B-62 & Amend 7 to Indemnity Agreement B-60.
MATHIAS, E. R. Northern States Power Co 79/05/10, 8pp
- F Operating License change documents & correspondence
- 7905020493 Discusses 790318 ltr re 790221 level generator & incorrect weights for Valian Model C450 6-inch check valves used in safety injection sys.
MATHIAS, E. R. Operating Reactors Branch 1 79/04/22 1p
- 7905020234 Forwards PHABRIE computer code input & affidavit requests exemption from public disclosure Computer code input withheld (ref 10CR92 790)
MATHIAS, E. R. Northern States Power Co 79/04/18 35pp
- 7905040308 Forwards Amends 35 & 29 to Licensee EPR-42 & EPR-60, respectively, safety evaluation & notice of issuance & availability.
MATHIAS, E. R. Operating Reactors Branch 1 79/04/20, 8pp
- 7905040322 Amends 35 & 29 to Licensee EPR-42 & EPR-60, respectively changing common station Tech Spec re refueling & incorporating changes to App A Tech Spec to support operation in Cycle B unfueled fuel by Exten Nuclear Co.
MATHIAS, E. R. Operating Reactors Branch 1 79/04/20, 8pp
- 7905040329 Safety evaluation supporting Amends 35 & 29 to Licensee EPR-42 & EPR-60, respectively.
Office of Nuclear Reactor Regulation 79/04/20 19pp
- 7905040300 Notice of issuance & availability of Amends 35 & 29 to Licensee EPR-42 & EPR-60, respectively.
MATHIAS, E. R. Operating Reactors Branch 1 79/04/20, 3pp

DOCKETED ITEMS

95

790501034 Forwards application for amend to Licenses DFR-42 & DFR-40, changing Tech Spec re pressurizer initiating signals for safety injection signals Amend fee & proposed Tech Spec Change incl
MAYER, L. J Northern States Power Co 79/04/26 10pp

790502042 Forwards ambient sound level survey in response to recent J Lake request for add info re ETS
MAYER, L. J Northern States Power Co 79/04/27 2pp

790501047 Forwards amend fee of \$6,400 for Licenses DFR-42 & DFR-40
Mayer, L. J Northern States Power Co 79/05/01 1p

790501024 Submits Environ Event Rep 79-03 for 790426-2902 discharge canal gate structure under water-rendering control & monitoring of floodwater flow operable
MAYER, L. J Northern States Power Co 79/05/08 1p

G Inspection reports, IE Bulletin & correspondence

7905010242 IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping"
MAYER, L. J Region 3, Chicago, Office of the Director 79/05/23 1p

790504034 Forwards IE Info Notice 79-07, "Rupture of Redundant Tanks"
MAYER, L. J Region 3, Chicago, Office of the Director 79/05/24 1p

7905050126 Forwards IE Insp Repts 90-282/79-04 & 90-204/79-04 on 790527-00 & 7901-02
MAYER, L. J Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/26 2pp

7905050121 IE Insp Repts 90-282/79-04 & 90-204/79-04 on 790527-00 & 7901-02 Re components noted Major areas inspected: emergency plan, emergency facilities, equipment & supplies, radioactive effluent sys & emergency training
MAYER, L. J Region 3, Chicago, Office of the Director 79/05/26 4pp

7905010176 Forwards IE Info Notice 79-03, "Interconnection of Contaminated Dye w/Buc Air Sys Used as Source of Breathing Air"
MAYER, L. J Region 3, Chicago, Office of the Director 79/05/23 1p

7905010416 Forwards IE Info Notice 79-09, "Hills of Radioactively Contaminated Rain"
MAYER, L. J Region 3, Chicago, Office of the Director 79/05/20 1p

7905070344 Responds to IE Bulletin 79-03 All longitudinal welds of AETH-A31 stainless steel piping 100% radiographed & free of defects Add testing unnecessary
MAYER, L. J Northern States Power Co 79/04/10 1p

7905030340 Forwards IE Bulletin 79-04, "Review of Operational Errors & Re Assignments Identified During BHI Incident" Licensee action required
MAYER, L. J Region 3, Chicago, Office of the Director 79/04/11 1p

7905010303 Forwards IE Bulletin 79-04a, "Review of Operational Errors & Re Assignments Identified During BHI Incident" Licensee action required
MAYER, L. J Region 3, Chicago, Office of the Director 79/04/14 1p

7905040303 Forwards IE Bulletin 79-04b, "Review of Operational Errors & Re Assignments Identified During BHI Incident" Licensee action required
MAYER, L. J Region 3, Chicago, Office of the Director 79/04/14 1p

7905040435 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping" Licensee action required
MAYER, L. J Region 3, Chicago, Office of the Director 79/04/14 1p

7905040376 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During BHI Incident"
MAYER, L. J Region 3, Chicago, Office of the Director 79/04/14 1p

7905030257 Forwards IE Bulletin 79-09, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Sys" Licensee action required
MAYER, L. J Region 3, Chicago, Office of the Director 79/04/17 1p

7905030328 Forwards IE Bulletin 79-03b, "Nuclear Incident at TSC-Duppi"
MAYER, L. J Region 3, Chicago, Office of the Director 79/04/21 1p

7905040140 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-282/79-03 & 90-204/79-03
MAYER, L. J Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/25 1p

7905040104 Responds to NRC 790323 ltr re violations noted in IE Insp Repts 90-282/79-03 & 90-204/79-03 Corrective actions torque valves were reduced & new Safety were retrofitted to specified values
MAYER, L. J Northern States Power Co 79/04/10 2pp

ROCKET 90-304 PRAIRIE ISLANDS NUCLEAR STATION, UNIT 2
G Inspection reports, IE Bulletin & correspondence

7905010240 Responds to IE Bulletin 79-09 GE Type AM-2 breakers not in use at unit
MAYER, L. J Northern States Power Co 79/05/04 1p

H Periodic operating reports & related correspondence

7905010504 Forwards monthly operating rept for Feb 1979
MAYER, L. J Northern States Power Co 79/04/23 1p

7905010501 Monthly operating rept for Feb 1979
MAYER, L. J Northern States Power Co 79/03/01 2pp

7905010494 Forwards monthly operating rept for Apr 1979
MAYER, L. J Northern States Power Co 79/05/10 1p

7905010495 Monthly operating rept for Apr 1979
MAYER, L. J Northern States Power Co 79/05/01 1pp

I Reportable occurrences, LERs & related correspondence

7905020334 Forwards LER 79-009/011-0
MAYER, L. J Northern States Power Co 79/04/26 1p

7905020336 LER 79-009/011-0 on 790412 notified by vendor that shell break in pressurizer indicator Ltr may hang up while P decreases, delaying safety injection Westinghouse recommends manually initiating safety injection implants
MAYER, L. J Northern States Power Co 79/04/26 1p

7905010127 Forwards LER 79-008/03L-0
MAYER, L. J Northern States Power Co 79/05/05 1pp

7905010131 LER 79-008/03L-0 on 790408 safety injection pump II failed to start automatically checked in manual. Cause without event could not be repeated Feasibility of monitor light to detect failure being studied
MAYER, L. J Northern States Power Co 79/05/05 1p

7905010279 Forwards LER 79-011/03L-0
MAYER, L. J Northern States Power Co 79/05/16 1p

7905010283 LER 79-011/03L-0 on 790416 transformer failed, leaving plant without source of offsite power Caused by switching error Transformer replaced prior to restart, investigation continuing
MAYER, L. J Northern States Power Co 79/05/16 1p

7905020114 Forwards LER 79-013/03L-0
MAYER, L. J Northern States Power Co 79/05/17 1p

7905020116 LER 79-013/03L-0 on 790417, during investigation of disengaged status light indication, diesel cooling water pump SB engine use inadvertently tripped Caused by personnel error, Personnel to review event
MAYER, L. J Northern States Power Co 79/05/17 1p

BOONBY 90-309 WAINE YANKEE ATOMIC POWER PLANT
F Security, medical, emergency & fire protection plans

7905030017 Details expansion of fire brigade plan
BOONBY, E. C. Waine Yankee Atomic Power Co 79/05/24 1p

DOCKETED ITEMS

B Adjudicatory correspondence

7903250044 Forwards Legislation Util Consumers' Council's petition to Intervene
JMS:H F New Hampshire State of 79/04/02 App

--7903250046 Petition to Intervene re 790313 order to show cause
JMS:H F New Hampshire State of 79/04/02 App

7903250052 Ack receipt of 790314 telegram mentioning shutdown of
facilities Director of Nuclear Reactor Regulation will shortly
be in position to re-evaluate whether continuous suspension of
operations remains necessary
HNS:RLE:J H Connecticut 79/04/12 Ip

--7903250053 Prefects show come order mandating shutdown of facility &
requests modification of order
THURLONG E W Maine Yankee Atomic Power Co 79/02/14 Ip

H General correspondence

7903250011 Response to 790312 request forwards 790302 submission re
transformer failure & statistical report for Sept 1978
WED:R W Operating Reactors Branch 4 79/03/26 Ip

7903250019 Urges NRC to get facility back on line
WED:R W Maine Merchants Association, Inc 79/03/26 Ip

7903250019 In response to 790319 ltr. forwards addl info re control rod
take out during reviews of guide tube wear & expansion
LOGA loads on rod require plant shutdown at this time
WED:R W Operating Reactors Branch 4 79/04/16 App

7903250061 Review NRC actions taken to expedite returning plant to
operation
HENDRICK J H Connecticut 79/03/02 App

--7903250066 Review untimely review impact of NRC decision to close
plant upon expenditures rework
COHEN W S Maine 79/03/26 App

Financial information

7903250038 Forwards statement of capital requirements & sources for
CVR in response to 790309 request
CRANFELD R A Maine Yankee Atomic Power Co 79/03/16 App

Insurance & indemnity information

7903250077 Confirms increased liability limit to \$100,000,000 per
policy for 1979-80: 25, 35, 45, 55, 65, 75, 85, 95, 105, 115, 125, 135, 145, 155, 165, 175, 185, 195, 205, 215, 225, 235, 245, 255, 265, 275, 285, 295, 305, 315, 325, 335, 345, 355, 365, 375, 385, 395, 405, 415, 425, 435, 445, 455, 465, 475, 485, 495, 505, 515, 525, 535, 545, 555, 565, 575, 585, 595, 605, 615, 625, 635, 645, 655, 665, 675, 685, 695, 705, 715, 725, 735, 745, 755, 765, 775, 785, 795, 805, 815, 825, 835, 845, 855, 865, 875, 885, 895, 905, 915, 925, 935, 945, 955, 965, 975, 985, 995, 1005, 1015, 1025, 1035, 1045, 1055, 1065, 1075, 1085, 1095, 1105, 1115, 1125, 1135, 1145, 1155, 1165, 1175, 1185, 1195, 1205, 1215, 1225, 1235, 1245, 1255, 1265, 1275, 1285, 1295, 1305, 1315, 1325, 1335, 1345, 1355, 1365, 1375, 1385, 1395, 1405, 1415, 1425, 1435, 1445, 1455, 1465, 1475, 1485, 1495, 1505, 1515, 1525, 1535, 1545, 1555, 1565, 1575, 1585, 1595, 1605, 1615, 1625, 1635, 1645, 1655, 1665, 1675, 1685, 1695, 1705, 1715, 1725, 1735, 1745, 1755, 1765, 1775, 1785, 1795, 1805, 1815, 1825, 1835, 1845, 1855, 1865, 1875, 1885, 1895, 1905, 1915, 1925, 1935, 1945, 1955, 1965, 1975, 1985, 1995, 2005, 2015, 2025, 2035, 2045, 2055, 2065, 2075, 2085, 2095, 2105, 2115, 2125, 2135, 2145, 2155, 2165, 2175, 2185, 2195, 2205, 2215, 2225, 2235, 2245, 2255, 2265, 2275, 2285, 2295, 2305, 2315, 2325, 2335, 2345, 2355, 2365, 2375, 2385, 2395, 2405, 2415, 2425, 2435, 2445, 2455, 2465, 2475, 2485, 2495, 2505, 2515, 2525, 2535, 2545, 2555, 2565, 2575, 2585, 2595, 2605, 2615, 2625, 2635, 2645, 2655, 2665, 2675, 2685, 2695, 2705, 2715, 2725, 2735, 2745, 2755, 2765, 2775, 2785, 2795, 2805, 2815, 2825, 2835, 2845, 2855, 2865, 2875, 2885, 2895, 2905, 2915, 2925, 2935, 2945, 2955, 2965, 2975, 2985, 2995, 3005, 3015, 3025, 3035, 3045, 3055, 3065, 3075, 3085, 3095, 3105, 3115, 3125, 3135, 3145, 3155, 3165, 3175, 3185, 3195, 3205, 3215, 3225, 3235, 3245, 3255, 3265, 3275, 3285, 3295, 3305, 3315, 3325, 3335, 3345, 3355, 3365, 3375, 3385, 3395, 3405, 3415, 3425, 3435, 3445, 3455, 3465, 3475, 3485, 3495, 3505, 3515, 3525, 3535, 3545, 3555, 3565, 3575, 3585, 3595, 3605, 3615, 3625, 3635, 3645, 3655, 3665, 3675, 3685, 3695, 3705, 3715, 3725, 3735, 3745, 3755, 3765, 3775, 3785, 3795, 3805, 3815, 3825, 3835, 3845, 3855, 3865, 3875, 3885, 3895, 3905, 3915, 3925, 3935, 3945, 3955, 3965, 3975, 3985, 3995, 4005, 4015, 4025, 4035, 4045, 4055, 4065, 4075, 4085, 4095, 4105, 4115, 4125, 4135, 4145, 4155, 4165, 4175, 4185, 4195, 4205, 4215, 4225, 4235, 4245, 4255, 4265, 4275, 4285, 4295, 4305, 4315, 4325, 4335, 4345, 4355, 4365, 4375, 4385, 4395, 4405, 4415, 4425, 4435, 4445, 4455, 4465, 4475, 4485, 4495, 4505, 4515, 4525, 4535, 4545, 4555, 4565, 4575, 4585, 4595, 4605, 4615, 4625, 4635, 4645, 4655, 4665, 4675, 4685, 4695, 4705, 4715, 4725, 4735, 4745, 4755, 4765, 4775, 4785, 4795, 4805, 4815, 4825, 4835, 4845, 4855, 4865, 4875, 4885, 4895, 4905, 4915, 4925, 4935, 4945, 4955, 4965, 4975, 4985, 4995, 5005, 5015, 5025, 5035, 5045, 5055, 5065, 5075, 5085, 5095, 5105, 5115, 5125, 5135, 5145, 5155, 5165, 5175, 5185, 5195, 5205, 5215, 5225, 5235, 5245, 5255, 5265, 5275, 5285, 5295, 5305, 5315, 5325, 5335, 5345, 5355, 5365, 5375, 5385, 5395, 5405, 5415, 5425, 5435, 5445, 5455, 5465, 5475, 5485, 5495, 5505, 5515, 5525, 5535, 5545, 5555, 5565, 5575, 5585, 5595, 5605, 5615, 5625, 5635, 5645, 5655, 5665, 5675, 5685, 5695, 5705, 5715, 5725, 5735, 5745, 5755, 5765, 5775, 5785, 5795, 5805, 5815, 5825, 5835, 5845, 5855, 5865, 5875, 5885, 5895, 5905, 5915, 5925, 5935, 5945, 5955, 5965, 5975, 5985, 5995, 6005, 6015, 6025, 6035, 6045, 6055, 6065, 6075, 6085, 6095, 6105, 6115, 6125, 6135, 6145, 6155, 6165, 6175, 6185, 6195, 6205, 6215, 6225, 6235, 6245, 6255, 6265, 6275, 6285, 6295, 6305, 6315, 6325, 6335, 6345, 6355, 6365, 6375, 6385, 6395, 6405, 6415, 6425, 6435, 6445, 6455, 6465, 6475, 6485, 6495, 6505, 6515, 6525, 6535, 6545, 6555, 6565, 6575, 6585, 6595, 6605, 6615, 6625, 6635, 6645, 6655, 6665, 6675, 6685, 6695, 6705, 6715, 6725, 6735, 6745, 6755, 6765, 6775, 6785, 6795, 6805, 6815, 6825, 6835, 6845, 6855, 6865, 6875, 6885, 6895, 6905, 6915, 6925, 6935, 6945, 6955, 6965, 6975, 6985, 6995, 7005, 7015, 7025, 7035, 7045, 7055, 7065, 7075, 7085, 7095, 7105, 7115, 7125, 7135, 7145, 7155, 7165, 7175, 7185, 7195, 7205, 7215, 7225, 7235, 7245, 7255, 7265, 7275, 7285, 7295, 7305, 7315, 7325, 7335, 7345, 7355, 7365, 7375, 7385, 7395, 7405, 7415, 7425, 7435, 7445, 7455, 7465, 7475, 7485, 7495, 7505, 7515, 7525, 7535, 7545, 7555, 7565, 7575, 7585, 7595, 7605, 7615, 7625, 7635, 7645, 7655, 7665, 7675, 7685, 7695, 7705, 7715, 7725, 7735, 7745, 7755, 7765, 7775, 7785, 7795, 7805, 7815, 7825, 7835, 7845, 7855, 7865, 7875, 7885, 7895, 7905, 7915, 7925, 7935, 7945, 7955, 7965, 7975, 7985, 7995, 8005, 8015, 8025, 8035, 8045, 8055, 8065, 8075, 8085, 8095, 8105, 8115, 8125, 8135, 8145, 8155, 8165, 8175, 8185, 8195, 8205, 8215, 8225, 8235, 8245, 8255, 8265, 8275, 8285, 8295, 8305, 8315, 8325, 8335, 8345, 8355, 8365, 8375, 8385, 8395, 8405, 8415, 8425, 8435, 8445, 8455, 8465, 8475, 8485, 8495, 8505, 8515, 8525, 8535, 8545, 8555, 8565, 8575, 8585, 8595, 8605, 8615, 8625, 8635, 8645, 8655, 8665, 8675, 8685, 8695, 8705, 8715, 8725, 8735, 8745, 8755, 8765, 8775, 8785, 8795, 8805, 8815, 8825, 8835, 8845, 8855, 8865, 8875, 8885, 8895, 8905, 8915, 8925, 8935, 8945, 8955, 8965, 8975, 8985, 8995, 9005, 9015, 9025, 9035, 9045, 9055, 9065, 9075, 9085, 9095, 9105, 9115, 9125, 9135, 9145, 9155, 9165, 9175, 9185, 9195, 9205, 9215, 9225, 9235, 9245, 9255, 9265, 9275, 9285, 9295, 9305, 9315, 9325, 9335, 9345, 9355, 9365, 9375, 9385, 9395, 9405, 9415, 9425, 9435, 9445, 9455, 9465, 9475, 9485, 9495, 9505, 9515, 9525, 9535, 9545, 9555, 9565, 9575, 9585, 9595, 9605, 9615, 9625, 9635, 9645, 9655, 9665, 9675, 9685, 9695, 9705, 9715, 9725, 9735, 9745, 9755, 9765, 9775, 9785, 9795, 9805, 9815, 9825, 9835, 9845, 9855, 9865, 9875, 9885, 9895, 9905, 9915, 9925, 9935, 9945, 9955, 9965, 9975, 9985, 9995, 10005, 10015, 10025, 10035, 10045, 10055, 10065, 10075, 10085, 10095, 10105, 10115, 10125, 10135, 10145, 10155, 10165, 10175, 10185, 10195, 10205, 10215, 10225, 10235, 10245, 10255, 10265, 10275, 10285, 10295, 10305, 10315, 10325, 10335, 10345, 10355, 10365, 10375, 10385, 10395, 10405, 10415, 10425, 10435, 10445, 10455, 10465, 10475, 10485, 10495, 10505, 10515, 10525, 10535, 10545, 10555, 10565, 10575, 10585, 10595, 10605, 10615, 10625, 10635, 10645, 10655, 10665, 10675, 10685, 10695, 10705, 10715, 10725, 10735, 10745, 10755, 10765, 10775, 10785, 10795, 10805, 10815, 10825, 10835, 10845, 10855, 10865, 10875, 10885, 10895, 10905, 10915, 10925, 10935, 10945, 10955, 10965, 10975, 10985, 10995, 11005, 11015, 11025, 11035, 11045, 11055, 11065, 11075, 11085, 11095, 11105, 11115, 11125, 11135, 11145, 11155, 11165, 11175, 11185, 11195, 11205, 11215, 11225, 11235, 11245, 11255, 11265, 11275, 11285, 11295, 11305, 11315, 11325, 11335, 11345, 11355, 11365, 11375, 11385, 11395, 11405, 11415, 11425, 11435, 11445, 11455, 11465, 11475, 11485, 11495, 11505, 11515, 11525, 11535, 11545, 11555, 11565, 11575, 11585, 11595, 11605, 11615, 11625, 11635, 11645, 11655, 11665, 11675, 11685, 11695, 11705, 11715, 11725, 11735, 11745, 11755, 11765, 11775, 11785, 11795, 11805, 11815, 11825, 11835, 11845, 11855, 11865, 11875, 11885, 11895, 11905, 11915, 11925, 11935, 11945, 11955, 11965, 11975, 11985, 11995, 12005, 12015, 12025, 12035, 12045, 12055, 12065, 12075, 12085, 12095, 12105, 12115, 12125, 12135, 12145, 12155, 12165, 12175, 12185, 12195, 12205, 12215, 12225, 12235, 12245, 12255, 12265, 12275, 12285, 12295, 12305, 12315, 12325, 12335, 12345, 12355, 12365, 12375, 12385, 12395, 12405, 12415, 12425, 12435, 12445, 12455, 12465, 12475, 12485, 12495, 12505, 12515, 12525, 12535, 12545, 12555, 12565, 12575, 12585, 12595, 12605, 12615, 12625, 12635, 12645, 12655, 12665, 12675, 12685, 12695, 12705, 12715, 12725, 12735, 12745, 12755, 12765, 12775, 12785, 12795, 12805, 12815, 12825, 12835, 12845, 12855, 12865, 12875, 12885, 12895, 12905, 12915, 12925, 12935, 12945, 12955, 12965, 12975, 12985, 12995, 13005, 13015, 13025, 13035, 13045, 13055, 13065, 13075, 13085, 13095, 13105, 13115, 13125, 13135, 13145, 13155, 13165, 13175, 13185, 13195, 13205, 13215, 13225, 13235, 13245, 13255, 13265, 13275, 13285, 13295, 13305, 13315, 13325, 13335, 13345, 13355, 13365, 13375, 13385, 13395, 13405, 13415, 13425, 13435, 13445, 13455, 13465, 13475, 13485, 13495, 13505, 13515, 13525, 13535, 13545, 13555, 13565, 13575, 13585, 13595, 13605, 13615, 13625, 13635, 13645, 13655, 13665, 13675, 13685, 13695, 13705, 13715, 13725, 13735, 13745, 13755, 13765, 13775, 13785, 13795, 13805, 13815, 13825, 13835, 13845, 13855, 13865, 13875, 13885, 13895, 13905, 13915, 13925, 13935, 13945, 13955, 13965, 13975, 13985, 13995, 14005, 14015, 14025, 14035, 14045, 14055, 14065, 14075, 14085, 14095, 14105, 14115, 14125, 14135, 14145, 14155, 14165, 14175, 14185, 14195, 14205, 14215, 14225, 14235, 14245, 14255, 14265, 14275, 14285, 14295, 14305, 14315, 14325, 14335, 14345, 14355, 14365, 14375, 14385, 14395, 14405, 14415, 14425, 14435, 14445, 14455, 14465, 14475, 14485, 14495, 14505, 14515, 14525, 14535, 14545, 14555, 14565, 14575, 14585, 14595, 14605, 14615, 14625, 14635, 14645, 14655, 14665, 14675, 14685, 14695, 14705, 14715, 14725, 14735, 14745, 14755, 14765, 14775, 14785, 14795, 14805, 14815, 14825, 14835, 14845, 14855, 14865, 14875, 14885, 14895, 14905, 14915, 14925, 14935, 14945, 14955, 14965, 14975, 14985, 14995, 15005, 15015, 15025, 15035, 15045, 15055, 15065, 15075, 15085, 15095, 15105, 15115, 15125, 15135, 15145, 15155, 15165, 15175, 15185, 15195, 15205, 15215, 15225, 15235, 15245, 15255, 15265, 15275, 15285, 15295, 15305, 15315, 15325, 15335, 15345, 15355, 15365, 15375, 15385, 15395, 15405, 15415, 15425, 15435, 15445, 15455, 15465, 15475, 15485, 15495, 15505, 15515, 15525, 15535, 15545, 15555, 15565, 15575, 15585, 15595, 15605, 15615, 15625, 15635, 15645, 15655, 15665, 15675, 15685, 15695, 15705, 15715, 15725, 15735, 15745, 15755, 15765, 15775, 15785, 15795, 15805, 15815, 15825, 15835, 15845, 15855, 15865, 15875, 15885, 15895, 15905, 15915, 15925, 15935, 15945, 15955, 15965, 15975, 15985, 15995, 16005, 16015, 16025, 16035, 16045, 16055, 16065, 16075, 16085, 16095, 16105, 16115, 16125, 16135, 16145, 16155, 16165, 16175, 16185, 16195, 16205, 16215, 16225, 16235, 16245, 16255, 16265, 16275, 16285, 16295, 16305, 16315, 16325, 16335, 16345, 16355, 16365, 16375, 16385, 16395, 16405, 16415, 16425, 16435, 16445, 16455, 16465, 16475, 16485, 16495, 16505, 16515, 16525, 16535, 16545, 16555, 16565, 16575, 16585, 16595, 16605, 16615, 16625, 16635, 16645, 16655, 16665, 16675, 16685, 16695, 16705, 16715, 16725, 16735, 16745, 16755, 16765, 16775, 16785, 16795, 16805, 16815, 16825, 16835, 16845, 16855, 16865, 16875, 16885, 16895, 16905, 16915, 16925, 16935, 16945, 16955, 16965, 16975, 16985, 16995, 17005, 17015, 17025, 17035, 17045, 17055, 17065, 17075, 17085, 17095, 17105, 17115, 17125, 17135, 17145, 17155, 17165, 17175, 17185, 17195, 17205, 17215, 17225, 17235, 17245, 17255, 17265, 17275, 17285, 17295, 17305, 17315, 17325, 17335, 17345, 17355, 17365, 17375, 17385, 17395, 17405, 17415, 17425, 17435, 17445, 17455, 17465, 17475, 17485, 17495, 17505, 17515, 17525, 17535, 17545, 17555, 17565, 17575, 1758

DOCKETED ITEMS

97

- 7903190138 Forwards response to 790316 request for info re thymine nucleoside info by Southern States Canada Ltd
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/14 2pp
- 7903201011 Forwards SHOCK I computer program listing Supersedes submittal of 790306 Program listing withheld info
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/14 1p
- 7903202043 Submits info re containment isolation non-purging sys & ECCS in response to 790309 request
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/14 4pp
- 7903202081 Submits info re pressurizer heaters, feedwater & steam generators in response to 790310 request
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/14 7pp
- 7903203130 Forwards Black Outcheck 1 piping comparisons
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/15 22pp
- 7903203161 Requests 790313 order to show cause be lifted
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/15 4pp
- 7903203159 Submits info relating position re adequacy of good title seismic design & piping Piping stresses within FEMA criteria & in many cases lower than previously calculated
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/15 2pp
- 7903204005 Summarizes procedures & calculational techniques used in analysis of existing sys designed w/SHOCK I computer program
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/15 4pp
- 7903204036 Forwards Offsite Base Calculation Manual
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/21 1p
- 7903204039 Offsite Base Calculation Manual
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/14 43pp
- 0 Inspection reports, IE Bulletin & correspondence
- 7903201018 Forwards IE info Notice 79-06, "Stress Analysis of Safety-Related Piping"
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/03/23 1p
- 7903201030 Forwards IE info Notice 79-06, "Interconnection of Contaminated Sys w/Re Air Sys Used as Source of Breaching Air"
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/03/23 1p
- 7903203018 Responds to IE Bulletin 79-02 re design & fabrication of piping sys No action necessary by unit
HEINER, E. H. Maine Yankee Atomic Power Co. 79/03/23 1p
- 7903201031 Forwards IE info Notice 79-06, "Status of Redirection of Contaminated Sys"
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/03/23 1p
- 7903203025 Forwards IE Bulletin 79-04, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident" - Licensee action required
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/04/11 1p
- 7903203134 Forwards IE Insp Rpt 80-369/79-05 on 790404-04 No noncompliance noted
HEINER, E. H. Region I, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/12 2pp
- 79032030127 IE Insp Rpt 80-369/79-05 on 790404-04 No noncompliance noted Major areas inspected seismic design concerns, review of seismic drawings for reactor sys & setting of affected lines per site spec
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/04/12 2pp
- 7903203042 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/04/14 1p
- 7903204046 Forwards IE Bulletin 79-08, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident." Licensee action required
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/04/14 1p
- 7903204031 Forwards IE Bulletin 79-08, "Events Relevant to Safety Water Pwr Reactors Identified During TH1 Incident" - Licensee action required
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/04/14 1p
- 7903203070 Forwards IE Bulletin 79-09, "Failure of GE Type AA-2 Circuit Breaker in Safety-Related Sys" - Licensee action required
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/04/17 1p
- 7903203078 Forwards IE Bulletin 79-08, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TH1 Incident" - Licensee action required
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/04/18 1p
- 7903204046 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping Currently addressing Bulletin under NRC order to show cause 4/16 790313
HEINER, E. H. Maine Yankee Atomic Power Co. 79/04/24 1p
- 7903203025 Responds to IE Bulletin 79-08 re TH1 errors Forwards info re review of operational errors & sys misalignments identified during TH1
HEINER, E. H. Maine Yankee Atomic Power Co. 79/04/24 1p
- 7903203077 Submits addl info to IE Bulletin 79-08 re TH1 errors will evaluate design change to isolate component cooling to reactor coolant pumps as reqd
HEINER, E. H. Maine Yankee Atomic Power Co. 79/05/14 1p
- 0 Periodic operating reports & related correspondence
- 7903203016 Forwards monthly operating rpt for Apr 1979
HEINER, E. H. Maine Yankee Atomic Power Co. 79/05/12 1p
- 7903203020 Monthly operating rpt for Apr 1979
HEINER, E. H. Maine Yankee Atomic Power Co. 79/05/12 5pp
- 1 Operating transcripts on non-nuclear matters
- 7903203021 Transcript of 790303 briefing in Washington, DC Pg 1-18
HEINER, E. H. Region I, Philadelphia, Office of the Director 79/05/03 8pp
- DOCKET 50-31: BAKEN NUCLEAR DEMONSTRATION STATION UNIT 2
- A Application/Consentation documents & correspondence
- 7903203094 Notifies that demonstration of integrity of channels must be undertaken through direct monitoring To maintain review schedule, monitoring plan should be forwarded promptly
HEINER, E. H. Light Water Reactors Branch 2 79/04/29 2pp
- 7903203014 Forwards response to request for addl info re rpt on structural integrity containment test & valve data for 3-inch & 10-inch valves associated w/containment pumps & pressure vacuum relief sys
HEINER, E. H. Public Service Electric & Gas Co. of New Jersey 79/04/24 4pp
- 7903203042 Notifies that 790300 application for extension of facility completion date was not accompanied by amend fee Requested action falls into Fee Class II Requester prompt submittal of fee
HEINER, E. H. License Fee Management Branch 79/04/24 1p
- 7903203026 Requests addl info to continue evaluating request for extension of plant completion date
HEINER, E. H. Light Water Reactors Branch 2 79/05/01 2pp
- 7903203041 Forwards supplemental test data re seismic qualification of 3" w/valves related to safety request for addl info submitted by review team during 790328-29 site audit
HEINER, E. H. Public Service Electric & Gas Co. of New Jersey 79/05/02 2pp
- 7903203043 "Protective Relay Seismic Data: NRC-1AC & 1AV Ref Documentation for NRC 8887 Review, Response Item 3" - Licensee action required
HEINER, E. H. Public Service Electric & Gas Co. of New Jersey 79/05/23 402pp
- 7903203020 Forwards updated listings of items, including preoperational tests which may not be completed until after initial fuel loading Requester deferral of incomplete test items
HEINER, E. H. Public Service Electric & Gas Co. of New Jersey 79/05/04 4pp

7905020309 Responds to Westinghouse 790208 notification of potential single dropped bus events which could lead to SRM action lower than reported limits are four bus plants & do not have potential problem
MTTL, R. L. Public Service Electric & Gas Co. of New Jersey
79/05/10 2pp

7905020100 Submits addl info re MPEL available for SRM pump during accident recovery recirculation 0009
MTTL, R. L. Public Service Electric & Gas Co. of New Jersey
79/05/17 4pp

7905020410 Forwards excerpts from Myle Lab seismic qualification test report
MTTL, R. L. Public Service Electric & Gas Co. of New Jersey
79/05/20 30pp

H General correspondence

7905070490 Act receipt of 790204 resolution regarding storage of high level radioactive wastes in New Jersey. Resolutions should be made at AEC hearing. Expansion of storage pools is unlikely. No independent facilities are planned.
DOH, D. H. Office of Nuclear Reactor Regulation 79/05/24 5pp

7905040204 Responds to 790318 letter re resolution adopted on 790204 by Township of Lower Alloways Creek. Resolution opposes storage of high level wastes. Forwards NRC response
DOH, D. H. Office of the Executive Director for Operations
79/04/11 1p

I Financial information

7905070447 Forwards "Annual Financial Rep. 1978" for Public Serv. Electric & Gas Co. Atlantic City Electric Co. Delaware Power & Light Co. & Philadelphia Electric Co.
PSEL, J. H. Public Service Electric & Gas Co. of New Jersey
79/04/30 162pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$104,000,000 for policies NF-23, 25, 43, 75, 85, 100, 141, 142, 144, 145, 146, 174, 175, 176, 180, 182, 183, 184, 187, 188, 189, 190, 191, 192, 193, 194, 195, 197, 198, 200, 201, 204, 205, 207, 209, 210, 213, 214, & others
BART, D. J. American Nuclear Insurers 79/05/01 1p

7905070302 Confirms increase in liability limit to \$26,000,000 for policies NF-22, 26, 27, 35, 39, 48, 49, 47, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96
DOH, D. H. Nuclear Atomic Energy Liability Underwriters 79/05/01 1p

7905090009 Forwards Endorsements 33-34 & 35 to ANI Policy NF-230
CONRA, C. Marsh & McLennan, R. B. Nuclear Consultants, Inc. Div
79/05/22 4pp

K Inspection reports, IE Bulletin & correspondence

7905010140 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping"
OHLER, B. H. Region I, Philadelphia, Office of the Director
79/05/20 1p

7905030343 Forwards IE Insp Rpt 35-211/77-17 on 790504-08 Re noncompliance noted
BRINCH, E. J. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/23 2pp

7905030752 IE Insp Rpt 35-211/77-17 on 790504-08 Re noncompliance noted. Major areas inspected: startup test program test procedure review & verification; plant for plant operational tests & plant tour
BETTMAN, R. L. Region I, Philadelphia, Office of the Director, SWP, D. L. Region I, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/01 5pp

7905030508 Responds to IE Bulletin 79-07 Re safety-related pipe assemblies from Youngstown Welding & Engineering Co. are used
SCHNEIDER, P. H. Public Service Electric & Gas Co. of New Jersey
79/04/04, 4pp

7905020100 Forwards IE Bulletin 79-06, "Review of Operational Errors & Gas Misalignments Identified During THO Incident."
OHLER, B. H. Region I, Philadelphia, Office of the Director
79/04/11 1p

7905020309 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping - Licensee action required"
OHLER, B. H. Region I, Philadelphia, Office of the Director
79/04/18 1p

7905040204 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Gas Misalignments Identified During THO Incident"
OHLER, B. H. Region I, Philadelphia, Office of the Director
79/04/14 1p

7905040202 Forwards IE Bulletin 79-03, "Events Relevant to Boiling Water Reactor Operation Identified During THO Incident"
OHLER, B. H. Region I, Philadelphia, Office of the Director
79/04/14 1p

7905030101 Forwards IE Bulletin 79-09, "Failures of GE Type A-2 Circuit Breaker in Safety-Related Bays - Licensee action required"
OHLER, B. H. Region I, Philadelphia, Office of the Director
79/04/17 1p

7905020302 Forwards IE Bulletin 79-04A, Revision 1, "Review of Operational Errors & Gas Misalignments Identified During THO Incident"
OHLER, B. H. Region I, Philadelphia, Office of the Director
79/04/18 1p

7905050072 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping - Provides results of Westinghouse analysis of reactor coolant loop & large bore Class 1 piping"
SCHNEIDER, P. H. Public Service Electric & Gas Co. of New Jersey
79/05/03 27pp

L Periodic operating reports & related correspondence

7905030442 Forwards Mar 1979 operating report for industrial waste treatment plant
HIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/03 2pp

7905050046 Forwards Mar 1979 wastewater treatment report for sewage treatment plant
HIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/12 2pp

7905050049 Forwards report of subsurface water diversions & chloride analysis of well water for quarter ending 790331
HIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/16 3pp

7905050421 Forwards Water Pollution Discharge Elimination Act discharge monitoring report for Mar 1979
HIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/20, 10pp

7905030417 Forwards "Operating Rpt for Apr 1979 for Industrial Waste Treatment Plant"
HIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/08 1p

7905030421 "Operating Rpt for Apr 1979 for Industrial Waste Treatment Plant"
HIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/04/26 1p

7905030431 Forwards Apr 1979 wastewater treatment report for sewage treatment plant
HIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/10, 3pp

7905030363 Forwards discharge monitoring reports for Apr 1979
HIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/22 13pp

7905040408 RD 79-42/01P on 790302 procedure to demonstrate operability of steam driven auxiliary feedwater pump is permitted closure of discharge control valves. Procedure changed to ensure operability
HIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
79/05/22 1p

DOCKETED ITEMS

99

DOCKET 90-312 RANGE SECO NUCLEAR GENERATING STATION

H. General correspondence

7905070443 Requests NRC honor Governor Brown's request to shutdown Rancho Seco
 HANCO, B. C. Affiliation Unknown 79/04/02 1p

7905100045 Requests closing of plant/respondent & husband are starting family & are concerned about radiation & cancer risk
 TAVENNER, B. W. Affiliation Unknown 79/04/02 1p

7905060018 Requests temporary shutdown of Rancho Seco until present uncertainties re TH-2 incident are clarified
 HATFIELD, R. T. House of Rep 79/04/04 2pp

7905100036 Requests temporary shutdown of Rancho Seco in view of incident of TH-2
 BROWN, E. D. California, State of 79/04/04 1p

7905100444 Favors precautionary shutdown of facility in light of TH-2 incident
 HOGARTHY, L. T. California, State of 79/04/04 1p

7905100033 Notifies that if Rancho Seco is shut down, availability of power from add sources is sub to transmission limitations & other factors unique in age
 SHAKELFORD, B. Sacramento Municipal Utility District 79/04/06 2pp

7905020286 Expresses gratitude re concern for safety problems of nuclear power plants
 KNOTT, M. Affiliation Unknown 79/04/27 1p

J. Insurance and indemnity information

7905070497 Confirms increase in liability limit to \$150,000,000 for policies NF-1,25,43,76,83,100,111,100,144,151,161,164,170,173,174,176,178,180,182,185,186,187,188,189,194,193,194,198,199,198,200,201,204,206,209,200,210,212,216,218, & others
 GUTTERBACH, J. American Nuclear Insurers 79/05/02 1p

7905100243 Forwards Amend & to Indemnity Agreement B-66 per 7905100240
 SHAWNEE re Increase from \$140 million to \$145 million, effective 7/90
 SHAWNEE Supporting documentation and
 ENLITMAN, J. Actitrust & Indemnity Group 79/05/01 2pp

7905090369 Forwards executed Amend & to Indemnity Agreement B-66
 HATFIELD, J. Sacramento Municipal Utility District 79/05/01 2pp

P. Operating license stage documents & correspondence

7905101114 Forwards safety evaluation re loss of non-safety-grade instrument power safely causing reactor turbine trips on 7905050286
 RICHARDSON, D. Division of Operating Reactors 79/03/30 1p

7905101117 Safety evaluation re loss of non-safety-grade instrument supply causing 7905020 reactor & turbine trips B&B & independent staff analysis conducted B&B considered appropriate regions of when generators findings acceptable
 Engineering Branch 79/03/20 4pp

7905100030 Comments on 790320 evidence transient points out significant deficiencies in present control & STS for RCS heating/cooling rates & pressure-temp limits
 HELLER, V. Division of Operating Reactors 79/04/07 1p

7905100004 Forwards committee report on 790320 transient resulting from loss of non-reactor instrumentation & power supply
 DUNN, J. D. Sacramento Municipal Utility District 79/04/19 2pp

7905101103 Informs of intention to return to full power operation on 790701, pending approval of small break LOCA analysis B&B
 HATFIELD, J. J. Sacramento Municipal Utility District 79/06/19 1p

7905020038 Determines 790316 application involves single safety issue & is therefore categorized as Class I-II per
 HELLER, M. D. License Fee Management Branch 79/04/19 1p

7905030631 Requests add info re ground motion input
 DAVIS, J. F. California, State of 79/04/24 2pp

7905030034 Responds to IE Bulletin 79-038 Requests extension to reply date due to very much underway as described in 790227 1st
 Answers will be provided prior to startup following 790508 shutdown
 HATFIELD, J. J. Sacramento Municipal Utility District 79/04/27 1p

7905100307 Forwards procedural change approval forms for turbine trip-loss of steam generator feed-loss of reactor coolant flow & auxiliary feedwater sgs
 COLUNDO, R. M. Sacramento Municipal Utility District 79/05/04 3pp

7905190156 Forwards procedural changes re auxiliary feedwater sgs load rejection, condenser & feedwater sgs & main feedwater stop sgs
 HATFIELD, J. J. Sacramento Municipal Utility District 79/05/14 2pp

7905100180 Submits current status of 790427 proposed actions re feedwater sgs & feed rejection in response to 790307 order Suspending Instrumentation sgs
 HATFIELD, J. J. Sacramento Municipal Utility District 79/05/14 2pp

7905100134 Forwards revised radiological effluent Tech Specs which include requirements of 50102-0472
 HATFIELD, J. J. Sacramento Municipal Utility District 79/05/15 2pp

G. Inspection reports, IE Bulletins & correspondence

7905110083 Forwards IE Insp Rep 50-312/79-03 on 790321-02, 20-31 & 3457
 CRAWF, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/04/01 2pp

7905110086 IE Insp Rep 50-312/79-03 on 790321-02, 20-31 & 3457
 No noncompliance noted Major areas inspected design change control, procedures, procedures safety limits & limiting conditions for operations
 CRAWF, J. L., HOGARTHY, L. T. Region 5, San Francisco, Office of the Director 7904/01, CRAWF, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/04/01 2pp

7905100291 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
 HOGARTHY, L. T. Region 4, Dallas, Office of the Director 79/03/23 1p

7905100333 Forwards IE Insp Rep 50-312/79-05 on 790325-0302, 12 & 15
 No noncompliance noted
 CRAWF, J. L. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/23 2pp

7905100339 IE Insp Rep 50-312/79-05 on 790325-0302, 12 & 15
 No noncompliance noted Major areas inspected callout, shutoff, breaking, main, followup on LERs & IE Bulletin
 HOGARTHY, L. T., HOGARTHY, A. D., FAULKNER, B. B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/03/23 2pp

7905100222 Forwards IE Info Notice 79-06, "Interconnection of Contaminated Sgs w/ Air May Used as Source of Breaths Air"
 HOGARTHY, L. T. Region 5, San Francisco, Office of the Director 79/03/23 1p

DOCKETED ITEMS

- 7905046022 Forwards IF Bulletin 79-08, "Events Relevant to Cooling Water Power Reactors Identified During TMI Incident"
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p
- 7905070108 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping - Licensee action required"
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p
- 7905090306 Forwards IE Bulletin 79-06, "Failures of GE Type AB-2 Circuit Breaker in Safety-Related Sys - Licensee action required"
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/17 1p
- 7905090374 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-2 - Licensee action required"
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/18 1p
- 7905090469 Responds to IE Bulletin 79-07 re seismic analysis computer codes. No analysis methods specified in bulletin were used in computer codes lists computer codes which have been used in seismic stress analysis
MULLER, G. C. Sacramento Municipal Utility District 79/04/24 2p
- 7905100270 Believes proposed Amend 62 dtd 790310 re licensee map requirements is exempt from license fees per 10CFR150.62
WATTS, J. J. Sacramento Municipal Utility District 79/04/26 1p
- F Periodic operating reports & related correspondence**
- 7905100281 Forwards monthly operating report for Apr 1979
RODMAN, C. J. Sacramento Municipal Utility District 79/03/23 1p
- 7905100282 Monthly operating report for Apr 1979
COLMERS, R. M. Sacramento Municipal Utility District 79/04/30 1p
- G Reportable occurrences, LERs & related correspondence**
- 7905110006 PMO-79-56 Issue of instrument power supply resulting in reactor & turbine trips on 790320. Excessive seal/leak caused reactor coolant pressure to decrease
WHITT, R. M., HOLMAN, P. J., SMITH, J. H. Office of Inspection & Enforcement 79/03/21 1p
- 7905110003 Discusses lead transfer on B&W instrumentation in response to 790517 request Test definitions wcd
REID, R. M. Operating Reactors Branch 3 79/04/06 2p
- 7905110008 Transfer of lead responsibility re 790320 non-nuclear instrumentation power loss & overloading of primary cooling sys. Discusses recommendations for generic aspects
WISDOM, R. M. Office of Inspection & Enforcement 79/04/25 2p
- 7905110009 Forwards LER 79-05/01T-2
WATTS, J. J. Sacramento Municipal Utility District 79/03/21
- 7905030328 Forwards PMO-79-ATU
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p
- 7905030325 Forwards PMO-79-67A
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/20 1p
- 7905100437 Forwards PMO-79-67B
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/21 1p
- 7905090430 Forwards PMO-79-67AC & AB
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/23 1p
- 7905100269 PMO-79-67B on 790420 coolant sys pressure on 790422 resulted in automatic reactor shutdown caused by failure of A Inverter pump apply unit returned to operation on 790423
BROWN, S. J., KLEIN, D. R. Office of Inspection & Enforcement 79/04/23 2p
- 7905100440 Forwards PMO-79-67AC
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/24 1p
- 7905090405 Forwards PMO-79-67AF
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/25 1p
- 7905090308 Forwards PMO-79-67AG
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p
- 7905090120 Forwards PMO-79-67AH
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/27 1p
- 7905100320 Forwards PMO-79-67AJ, AJ & AK per REC 790401 for transmitting IE Bulletin 79-03
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/30 1p
- 7905070015 Forwards PMO-79-67AL per REC 790401 for transmitting IE Bulletin 79-03
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/05/01 1p
- 7905100308 Forwards PMO-79-67AN
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/05/07 1p
- 7905030434 Forwards LER 79-05/03L-0
WATTS, J. J. Sacramento Municipal Utility District 79/03/21 2p
- 7905030437 LER 79-05/03L-0 on 790422 reactor trip occurred when B Inverter failed. Caused by 120 mV-125 volts DC inverter input breaker tripping when breaker overvoltage trip coil failed
COLMERS, R. M. Sacramento Municipal Utility District 79/03/21 1p
- 7905090604 LER 79-005/03L-0 on 790422 BIA vital power inverter failed twice within four months. Caused by undersized UV trip coil. Breaker added to circuit
COLMERS, R. M. Sacramento Municipal Utility District 79/03/21 1p
- 7905030403 Forwards LER 79-004/03L-0
WATTS, J. J. Sacramento Municipal Utility District 79/03/23 2p
- 7905030409 LER 79-004/03L-0 on 790422 leak revealed that bypass valve did not fully close. Caused by misadjustment of mechanical interlock linkage. Linkage adjusted & tested satisfactorily
COLMERS, R. M. Sacramento Municipal Utility District 79/03/23 1p
- ROCKET 79-DLS ARKANSAS NUCLEAR ONE, UNIT 1**
- F Security, medical, emergency & fire protection plans**
- 7905030318 Requests change in implementation date for complete installation of 2 1/2 rated fire dampers in ventilation ducts. Proposes to install dampers by mid of fourth refueling outage.
WATTS, J. J. Arkansas Power & Light Co 79/03/13 2p

DOCKETED ITEMS

101

7903090300 Responds to 790309 plans for seeking cable penetration fire
extinguisher installed in metal tanks & plecter walls Proposed test
acceptable
REID, R. M. Operating Reactors Branch 4 79/04/03 App

7903020201 Inform that fire protection made required to be implemented
during this refueling outage will be completed as scheduled
TRIMBLE, D. C. Arkansas Power & Light Co 79/04/04 1p

7903090208 Forwards second revision to fire protection plan
TRIMBLE, D. C. Arkansas Power & Light Co 79/04/04 1p

--7903090201 Revision 2 to fire protection plan
Arkansas Power & Light Co 79/04/14 20pp

I General correspondence

7903240400 Responds to 790412 ltr to JH Wendle re nuclear power plant
near Russellville, AR Outlines steps for license renewal
Forwards "Transportation of Nuclear Fuel & Waste" &
"Disposal of Radioactive Waste" w/ no encl
DEWANG, R. C. Division of Site Safety & Environmental Analysis
79/04/07 2pp

--7903240400 Expresses concern re nuclear plants at Russellville, AR
Requests public investigation re safety of facility Forwards
policy statement of Arkansas for Safe Energy
BERRY, J. A. Affiliation Unknown 79/04/12 2pp

J Insurance & indemnity information

7903070197 Confirms increased liability limit to \$124,000,000 for
policies AP-1, 2b, 3b, 7b, 8b, 100, 101, 14b, 14b, 151, 161, 164, 170,
172, 174, 176, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 195,
197, 199, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
BLATTBERG, J. American Nuclear Insurance 79/03/01 1p

7903070202 Confirms increase in liability limit to \$26,000,000 for
policies AP-22, 2b, 29, 3b, 39, 44, 4b, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 6b, 6b, 67, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87,
88, 90, 91, 92, 93, 94, 95, & 96
BICKERT, D. H. Mutual Atomic Energy Liability Underwriters 79/03/01
1p

7903140400 Forwards Amend G to Indemnity Agreement B-35 per DECRI40
change re increase in liability insurance from \$160 million
to \$160 million effective 790301 Supporting documentation
encl
BICKERT, D. H. Actuarial & Indemnity Group 79/03/01 App

7903190167 Forwards executed Amend B to Indemnity Agreement B-05
TRIMBLE, D. C. Arkansas Power & Light Co 79/03/10 App

K Operating license stage documents & correspondence

7903030376 Forwards Amend A to License SPR-93, safety evaluation &
notice of issuance & availability
REID, R. M. Operating Reactors Branch 4 79/04/11 2pp

--7903030376 Amend A to License SPR-93, revising Tech Specs for steam
generator tube surveillance
REID, R. M. Operating Reactors Branch 4 79/04/11 App

--7903030376 Safety evaluation supporting Amend A to License SPR-93
Arkansas Nuclear Regulation 79/04/11 App

--7903030376 Notice of issuance & availability of Amend A to License
SPR-93
REID, R. M. Operating Reactors Branch 4 79/04/11 App

7903050204 Agrees to have requested action re resolve problems
associated w/ RSM plants Necessary adjustments will be made
re emergency feedwater sys equipment/procedures & operator
training
FESTER, A. P. Arkansas Power & Light Co 79/04/04 App

7903190203 Forwards revised response to Question 1 re proposed Tech
Specs for Cycle 4 operation
TRIMBLE, D. C. Arkansas Power & Light Co 79/04/26 App

7903070403 Responds to 790425 ltr re safety concerns Proctor upgrading
emergency feedwater sys & completing sufficient small break
LOCA analysis to develop & implement necessary operator
instructions in emergency procedures
DEWANG, R. C. Arkansas Power & Light Co 79/05/03 3pp

7903030404 Forwards Amends 42 & 43 to Licenses SPR-91 & NP-91
respectively, safety evaluation & notice of issuance &
availability
REID, R. M. Light Water Reactors Branch 4 REID, R. M.
Operating Reactors Branch 4 79/03/03 2pp

--7903030303 Amends 42 & 43 to Licenses SPR-91 & NP-91, respectively,
modifying App A & B Tech Specs re mgt organization
REID, R. M. Operating Reactors Branch 4 79/03/03 4pp

--7903030303 Safety evaluation supporting Amends 42 & 43 to Licenses
SPR-91 & NP-91, respectively
Arkansas Nuclear Regulation 79/03/03 2pp

--7903030303 Notice of issuance & availability of Amends 42 & 43 to
Licenses SPR-91 & NP-91, respectively
REID, R. M. Operating Reactors Branch 4 79/03/03 2pp

7903130309 Requests presence at 790506 annual review meeting in Little
Rock, AR re environ monitoring program
TRIMBLE, D. C. Arkansas Power & Light Co 79/03/00 1p

7903150200 Responds 790303 ltr w/ answer wording changes re timeliness &
availability of emergency feedwater sys & increased margin of
safety
DEWANG, R. C. Arkansas Power & Light Co 79/03/09 2pp

7903160279 Responds 790309 ltr responding to NRC safety concerns
expressed in 790323 status report Proposed corrective actions
Design change for emergency feedwater sys & implementation
of hard-wired control-grade reactor trip
DEWANG, R. C. Arkansas Power & Light Co 79/03/10 2pp

7903190302 Provides addl requested info re safety concerns Superseded
790310 ltr
DEWANG, R. C. Arkansas Power & Light Co 79/03/11 2pp

7903230300 Provides addl info re main being used to provide reactor
trip upon loss of main feedwater Main turbine tripper
790329 meeting request
TRIMBLE, D. C. Arkansas Power & Light Co 79/03/11 2pp

7903230204 Discusses with 790310 ltr re commitment to perform flow test
of long-term small break and following design change Design
and completed & flow test performed to verify required
790320 flow split
TRIMBLE, D. C. Arkansas Power & Light Co 79/03/14 1p

7903010266 Responds to questions from 790315 still/NRC meeting Rescribes
measures taken to assure that anticipatory stress on turbine
trip & loss of main feedwater will be reset during power
excitation Discusses desirability of SWR tests
TRIMBLE, D. C. Arkansas Power & Light Co 79/03/16 2pp

7903240303 Provides update on progress made in implementing commitments
contained in 790311 ltr re emergency feedwater pump
TRIMBLE, D. C. Arkansas Power & Light Co 79/03/17 2pp

7903240712 Responds to NRC 790318 questions re activation of
anticipatory reactor scram, procedural training & existing
emergency feedwater pump capacities
TRIMBLE, D. C. Arkansas Power & Light Co 79/03/17 2pp

7903250100 Updates 790311 ltr re emergency feedwater re
verification of sys & progress of post-trip operator
program
TRIMBLE, D. C. Arkansas Power & Light Co 79/03/17 App

7903030208 Forwards summary of EOB Nuclear, Inc resolution/documentation
of elbow flexibility error which existed in version of
790302 piping analysis Computer program from Jan-Dec 1989
Review & reanalysis indicated all were through BAC 1970.
BARTON, F. L. EOB Nuclear, Inc 79/03/21 2pp

--7903030203 Forwards EOB Nuclear, Inc list of BAC & piping sys which
could have been impacted by deficient computer program
OE has no record of reanalysis for Cooper piping sys.
STEPHENS, W. S. General Electric Co, Nuclear Energy Products Div.
79/01/24 2pp

7903030408 Forwards info requested by NRC at 790327 meeting re results
of voltage calculations Info is provided to clarify
analysis performed to justify existing configuration
TRIMBLE, D. C. Arkansas Power & Light Co 79/03/21 11pp

7903030000 Updates 790311 for re assignments & comments of 790327 order Test on reactor conducted w/o unusual occurrence other tests on reactor conducted w/o any use responsible failures TRIMBLE, D C Arkansas Power & Light Co 79/03/22 3pp

7903030300 Plans to qualify retainer described in 84M-148, "SRPA Retainer Design Rep." for three cycles of operation. Some retainers will be reinstated at facility during next refueling. TRIMBLE, D C Arkansas Power & Light Co 79/03/23 1p

Q Inspection reports, IE Bulletins & correspondence

7903030300 Forwards IE Insp Repts 80-313/79-08 & 80-366/79-02 on 790115-0211 & notice of violation. RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/01 2pp

7903030300 Notice of violation from Insp on 790115-0211. Region 4, Dallas, Office of the Director 79/03/01 1p

7903030300 IE Insp Repts 80-313/79-08 & 80-366/79-02 on 790115-0211 Noncompliance noted. Failure to prepare weekly report of avoidance action. WERTHOFF, T F Region 4, Dallas, Office of the Director 79/03/01 1p

7903030300 Forwards IE Circular 79-04, "Leak Locking Not on Line" to Valve Operators. RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/16 1p

7903030300 Forwards IE Bulletin 79-02B, "Abnormal Weld Heat in Reactor Pressure Vessel Under". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Circular 79-05, "Moisture Leakage in Stranded Wire Conductors". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/20 1p

7903030300 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/23 1p

7903030300 Forwards IE Info Notice 79-07, "Shutdown of Radwaste Tanks". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/26 1p

7903030300 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-09, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-10, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-11, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-12, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-13, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-14, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-15, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-16, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-17, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-18, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-19, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards IE Info Notice 79-20, "Interconnection of Contaminated Gas w/ Gas Air Gas Used as the Source of Breathing Air". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/28 1p

7903030300 Forwards responses to items 4-c-f & 5-d of IE Bulletin 79-05A & 790311 for re assignments & comments of 790327 order Test on reactor conducted w/o unusual occurrence other tests on reactor conducted w/o any use responsible failures TRIMBLE, D C Arkansas Power & Light Co 79/03/16 13pp

7903030300 Forwards reply to IE Bulletin 79-05A, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/16 1p

7903030300 Forwards IE Bulletin 79-05, "Failures of Q Type 66-2 Circuit Breaker in Safety-Related Sys". Licensee action required. RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05B, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05C, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05D, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05E, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05F, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05G, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05H, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05I, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05J, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05K, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05L, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05M, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05N, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05O, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05P, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05Q, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05R, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05S, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05T, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05U, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05V, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05W, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05X, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05Y, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

7903030300 Forwards IE Bulletin 79-05Z, "Nuclear Incident at the". RUSSELL, D C Region 4, Dallas, Office of the Director 79/03/17 1p

DOCKETED ITEMS

103

7905180203 Forwards FWD-T9-6TT correction
MADSEN-D L Region 4, Dallas Reenter Operations Nuclear Support
Branch 79/04/10 sp

7905010529 Forwards RMD-79-676, V & W
RMD5830 L Region 4, Dallas, Office of the Director 79/05/16
to

7903060338 Forwards FMO-79-472 & Y
HAGSEN, G L Region 4, Dallas, Office of the Director 79/04/10
50

7905050554 Forwards FMO-79-672
RABBIT:O L. Region 4, Dallas, Office of the Director 79/06/19
1a

7906030367 Forwards PMD-79-67AA, AA, AC & AD
HAGSEN, G L. Region 4, Dallas, Office of the Director 79/04/24
lp

790600000 Forwards PWG-79-67AE
NADSD&G L Region 4, Dallas, Reactor Operations Nuclear Support
Branch 79/04/20 tp

790510094, Formwarz PWG-79-674F.A3, AH-A1 & Adj. re nuclear incident at
THE
HENDERSON, G L. Region 4, Dallas, Reactor Operations Nuclear Support

7905040455 Forwards PWG-75-07AK & AL
RADSSM G L Region 4: Sales, Fuel Facility & Materials Safety

7905140000 Forwarded LHM 79-003/007-0
TRIMBLE, D C Arkansas Power & Light Co 79/03/00H 1a

--7905100333 LKH 74-003/017-C on 790425 Jack discovered in heat affected zone of 1 inch drainline socket weld in B dense heat discharge cross connect to a loop caused by vibration Fatigue Deter drainline isolation valves replaced
BHEVELY, C H Arkansas Power & Light Co 79/05/08 App

7903270100 Forwards LCR 79-004/03L-0
TRIMBLE, B C Arkansas Power & Light Co 79/05/22 Rec

--J905290109 LER 79-064/03L-D on 790424 reactor hldg spray pump
unresponsive to engineered safeguards signal caused by
intermittent Agastak 3000 relay setting Relay adjusted
SHEVELY, C N Arkansas Power & Light Co 79/05/22 1p

DECRET 50-919 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1

H General correspondence

7903240602 Notification of termination of License 80P-3099 due to
resignation of employee: JH Randolph
HCL054.0 0 , SHALLER, D V Indiana & Michigan Power Co 79/03/02

1. Personal information

79030-00000 Forwards Endorsements 2 & 3 to NELA Binders 83-85 & 86.
Endorsements 31 & 32 to NELA policy NF-79 & Endorsements 38
& 39 to AML policy NF-206.
DOLAN, J E Indiana & Michigan Power Co 79/04/26. BPP

d Insurance & indemnity information

7905020400 Forwards Endorsements 2 & 3 to NELA policies ED-45 & ED-46.
Endorsements 31 & 32 to NELA policy NF-79 & Endorsements
38 & 39 to AMT policy NF-236
Dolan, J.E., Indiana & Michigan Power Co 79/04/26 Goo

7903070497 Confirms increased liability limit to \$624,000.000 for policies NF-1,25,43,76,83,103,111,140,146,181,185,186,192,193,194,195,197,198,200,201,204,206,207,208,210,212,214,218, & others
QUATROREMI, J American Nuclear Insurers 09/05/01 to

7905070002 Confirms increase in liability limit to \$36,000,000 for
policies NF-22, 24, 25, 26, 27, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87,
88, 94, 95, 92, 93, 94, 95 & 96
ROBERTS P H Mutual Atomic Energy Liability Underwriters. 79/05/06
14.

7903140581	Forwards Amend 9 to Indemnity Agreement B-85 per 10CFR540 changes: increase in liability insurance from \$180 million to \$160 million effective 790301 Supporting documentation encl			
BALZHAM, J	Asbestos & Indemnity Group	79/05/01	app	

7903290346 Forwards executed Amend 9 to Indemnity Agreement D-61
05/24/11 J E Indiana & Michigan Power Co 29/03/20 App

790330440 Forwards Indemnity fee per Unit 1 for 790326-800
for Unit 2 for 790318-790317
DELAN, J E Indiana & Michigan Power Co 79/03/29 Jyy

2. Operating license state documents & correspondence

790520A90 Discusses 790315 taken w/R Bern of Westinghouse re incorrect weights for Valves Model C45B 4-inch check valves used in safety injection sys

7908040511 Forwards operating history info re pressure/vol
operated relief valves in response to 790427 request
GOSLICK, D W Indians & Michiken Power Co 79/04/27 3pg

7905240500 Ack receipt of 790027 application proposing App A & B Tech
Wper charges Application requires two Class III fees & two
Class I fees Requests addl fee
MULLER-W O License Fee Management Branch 79/05/27 1p

7908110883 Advices of removal of Packard transmitters on pressurized
pressure & steam generator steam flow applications, as
identified in TADSOI Itr. Transmitters will be replaced
during current refueling outage, no later than Oct-Nov 1979
MLC/CCV, G. P. Indiana & Michigan Power Co 79/COR/GC 399

7905290504 Describes correspondence w/NRC re application for expansion of spent fuel storage capacity to 2,050 fuel assemblies. Requests add info re technical review of related public health & safety matters. RE:IN. H.G. Nickerson, State of 79/05/14 1a

7905290447 Forwards \$4,400 addl fee for 790327 proposed To
changes
003-004 of 8 Indiana & Michigan Power Co 79/05/21 Geo

B. Inspection results, IC Bulletin 5 correspondence

7903020202 Forwarded IE Insp Repts 80-315/79-02 & 80-316/79-02 on
790302-05, 02-15-19, 02-24, 29-03 & 0203-09, & notice of
violation Partitions withheld (ref LOORPZ 7901
HEIGHMAN, F. Region 3 Chicago Reactor Operations Nuclear
Research Branch 79/03/02. C&G)

--7905030205 Notice of violation from Insp on 790502-03.8-11.15-19.22-3
29-31 & 0501-02
* Region 3, Chicago, Office of the Director 79/02/21. tp.

—7902020808 IE Insp Repts 80-315/79-02 & 80-316/79-02 on 790102-00-11, 19-19, 02-29, 29-31 & 0201-02. Noncompliance noted. Failure to report safety injection event & failure to sample as specified observed.

BAKER, K. R. - WATNECK, R. F. Region 3, Chicago, Office of the Director. 79/02/01 ltp

7908010233 Forwards IS Info Notice 79-06, "SWPees Analysis of
Safety-Related Piping"
KFFLEH, J.O. Region 3, Chicago, Office of the Director 79/03/23

7905040037 Forward: IE Info Notice 79-07, "Rupture of Sediments Tanks
SUPPLIER, J.O. Region 3, Chicago; Office of the Director 79/02/1
1a.

9905010171 Forwards IE Info Notice 79-08. "Interconnection of
Contaminated Gas w/Vec Air Gas Used as Source of Breathing
Air."
KOPPLER, J.O. Region 3: Chicago; Office of the Director 79/03/28.
JA

790326017 Forwarded IE Insp Repts 80-018/79-03 & 80-314/79-03 on
790313-14 & notice of violation
DAVID, A. S. Region 3, Chicago, Fuel Facility & Materials Safety
Branch 79/03/20, 2p.

--7903130219 Notice of violation from Insp on 790313-16
* Region 3, Chicago, Office of the Director 79/03/27. sp.

- 7903138820 IE Insp Repts 30-315/79-Q2 & 30-316/79-Q3 on 790313-16
Noncompliance noted failure to conduct required emergency
plan drill
DOLAN, J. E. NRC Regional Office 88510.1 H Region 3
Chicago, Office of the Director 79/03/27 App
- 7903040404 Forwards IE Info notice 79-04, "Bail of Radioactively
Contaminated Reels"
NEFFLER, J. G. Region 3, Chicago, Office of the Director 79/03/30
lp
- 7903030004 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Ree Misalignments Identified During TMI Incident - License
action required"
NEFFLER, J. G. Region 3, Chicago, Office of the Director 79/04/11
lp
- 7903010092 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Ree Misalignments Identified During TMI Incident - License
action required"
NEFFLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
lp
- 7903040404 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping - License action required"
NEFFLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
lp
- 7903040502 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Reactor Identified During TMI Incident"
NEFFLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
lp
- 7903070007 Forwards IE Bulletin 79-08B, "Review of Operational Errors &
Ree Misalignments Identified During TMI Incident"
NEFFLER, J. G. Region 3, Chicago, Office of the Director 79/04/14
lp
- 7903030094 Forwards IE Bulletin 79-09, "Failure of US Type AA-2
Circuit Breaker in Safety-Related Sys - License action
required"
NEFFLER, J. G. Region 3, Chicago, Office of the Director 79/04/17
lp
- 7903030099 Forwards IE Bulletin 79-09B, "Nuclear Incident at
TMI-Bapt"
NEFFLER, J. G. Region 3, Chicago, Office of the Director 79/04/21
lp
- 7903030096 Response to IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping" Forwards description of computer
program used in design of safety-related piping
DOLAN, J. E. Indiana & Michigan Power Co. Inc 79/04/24 App
- 7903100102 Ack receipt of 790329 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 30-315/79-Q2 &
30-316/79-Q3
NEFFLER, J. G. Region 3, Chicago, Reactor Operations Nuclear
Report Branch 79/04/25 App
- 7903100106 Response to NRC 790302 ltr re violations noted in IE Insp
Repts 30-315/79-Q2 & 30-316/79-Q3 corrective action
withheld (ref 10CFR2 790)
DOLAN, J. E. Indiana & Michigan Power Co. Inc 79/04/25 lp
- 7903150340 Forwards responses to IE Bulletin 79-08A, Revision 1.
Discusses major differences between Westinghouse & BWR
designs
DOLAN, J. E. Indiana & Michigan Power Co. 79/05/01 2pp
- 7903030071 Ackl response to IE Bulletin 79-07 Twenty-two piping
lines analyzed using elastostatic simulation technique proved
capable of withstanding seismic event. Remaining piping sys
also proved capable.
DOLAN, J. E. Indiana & Michigan Power Co. 79/05/04 App
- 7903100446 Response to 790305 ltr requesting extension of time to
respond to IE Bulletin 79-10, 79-10A & 79-10B Request
denied
NEFFLER, J. G. Region 3, Chicago, Office of the Director 79/05/03
2p
- 7903100449 Requests time extension to respond to IE Bulletin 79-10,
79-10A & 79-10B
DOLAN, J. E. Indiana & Michigan Power Co. 79/05/03 App
- B. Periodic operating reports & related correspondence
- 7903070028 Forwards "Annual Environ Operating Rept 1978"
DOLAN, J. E. Indiana & Michigan Power Co. 79/05/16 App.
- 7903070024 "Annual Environ Operating Rept 1978"
Indiana & Michigan Power Co. 79/05/16 2pp
- 7903050332 Forwards revised page 15 in 1978 Annual Radiological Environ
Monitoring Report
DOLAN, J. E. Indiana & Michigan Power Co. 79/04/26 App
- 7903100440 Forwards monthly operating rept for Apr 1979
DOLAN, J. E. Indiana & Michigan Power Co. 79/05/02 lp
- 7903100440 Monthly operating rept for Apr 1979
DOLAN, J. E. Indiana & Michigan Power Co. 79/05/03 7pp
- C. Reportable occurrences, LERs & related correspondence
- 7903030298 Forwards LERs 79-02A/02L-0 & 79-02B/02L-0
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/02 2p
- 7903050004 LER 79-02A/02L-0 on 790208 during normal operation, 4700,
4700A ac electrical supply became inoperative. Caused by
high winds during severe windstorm. Damaged jumper replaced &
sys returned to operable status
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/02 2p
- 7903050013 LER 79-02B/02L-0 on 790314 time response data not collected
during Apr 1979 refueling outage for low steam pressure
operating safety feature channel caused by inadvertent
procedural omission. Checklist will be used in future
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/02 lp
- 7903101028 Forwards LER 79-010/03L-1
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/07 lp
- 7903101024 LER 79-010/03L-1 on 790322 diesel essential aux water ch-
circuit 1-400-111 & 1-400-114 not functioning properly. Caused by
extensive wear at split disk hinge points. Disc replaced
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/07 lp
- 7903050428 Forwards LERs 79-010/03L-0, 79-027/02L-0 & 79-028/03L-0
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/09 lp
- 7903100430 LER 79-010/03L-0 on 790410 while performing hydraulic
surveillance test, 4700-4700A, 4700-4700B & 4700-4700C feed
surveillance system. Caused by loose pipe unions. Bolts
removed & remote reservoirs. Bolts replaced
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/09 lp
- 7903100430 LER 79-027/02L-0 on 790414 during refueling, Westinghouse
diesel generator AB inoperative. 400 volt bus 114 mode
inoperative by removal of normal feed breaker T112 for
cleaning. Caused by personnel error. Operator returned
LERs: R. B. Indiana & Michigan Power Co. 79/03/09 lp
- 7903100441 LER 79-028/02L-0 on 790416 torque required in 4th steam
condenser inlet door 2-4 exceeded Tech Spec. Caused by
sheet metal screws loose at bottom of door. Frame clip
depressed
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/09 2pp
- 7903050135 Forwards LER 79-029/02L-0
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/14 lp
- 7903050140 LER 79-029/02L-0 on 790414 cracks discovered in divider
barrier seal. Caused by excessive compression of seal mat by
steel plates. Work in progress to replace cracked section.
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/14 lp
- 7903050339 Forwards LERs 79-030/03L-0, 79-031/03L-0 & 79-034/03L-0
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/16 lp
- 7903050339 LER 79-030/03L-0 on 790417 while performing routine
surveillance test on AB diesel generator, load conservator
circuits did not fully function as design. Cause under
investigation
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/16 lp
- 7903050339 LER 79-031/03L-0 on 790418 during routine channel walk-
down, 4700-4700A trip point was nonconformative w/ respect to
Tech Spec limit. Caused by excess drift. Bistable will be
replaced
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/16 lp
- 7903050339 LER 79-034/03L-0 on 790418 during routine channel walk-
down, 4700-4700A trip point was nonconformative w/ respect to
Tech Spec limit. Caused by excess drift. Bistable will be
replaced
DOLAN, J. E. Indiana & Michigan Power Co. 79/03/16 lp

DOCKETED ITEMS

- 7905150135 Rec receipt of 790305 Ltr informing NRC of steps taken to correct violations noted in IE Insp 80-015/79-02 & 80-016/79-02
NRCBUREAU, H P Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/20 1p
- 7905150136 Response to NRC 790302 Ltr re violations noted in IE Insp 80-015/79-02 & 80-016/79-02 Corrective actions initiated (ref 100782 7901)
DIBBLE, R E Indiana & Michigan Power Co 79/04/05 1p
- 7905150345 Forwards responses to IE Bulletin 79-06A, Revision 1 Describes major differences between Huntington & BSA designs
DOLAN, J E Indiana & Michigan Power Co, 79/05/01 25pp
- 7905250271 Addl response to IE Bulletin 79-07 Twenty-three piping lines analyzed using absolute summation technique proved capable of withstanding seismic event Remaining piping was also proved capable
DOLAN, J E Indiana & Michigan Power Co 79/05/06 App
- 7905250445 Response to 790505 Ltr requesting extension of time to respond to IE Bulletin 79-12B, 79-12C & 79-12D Request denied
DOLAN, J E Region 3, Chicago, Office of the Director 79/05/04 App
- 7905250449 Request time extension to respond to IE Bulletin 79-12B, 79-12C & 79-12D
DOLAN, J E Indiana & Michigan Power Co 79/05/05 2pp
- R Periodic operating reports & related correspondence**
- 7905070320 Forwards "Annual Environ Operating Reps 1970"
DOLAN, J E Indiana & Michigan Power Co 79/04/16 App
- 7905070437 "Annual Environ Operating Reps 1971"
Indiana & Michigan Power Co 79/04/16 20pp
- 7905250352 Forwards revised page 15 to 1978 Annual Radiological Environ Monitoring Rpt, transmitted 790328 Ltr from contractor wmt
SMALLER, D V Indiana & Michigan Power Co 79/04/26 App
- 7905170501 Forwards monthly operating rep for Apr 1979
SMALLER, D V Indiana & Michigan Power Co 79/05/11 1p
- 7905170502 Monthly operating rep for Apr 1979
SMALLER, D V Indiana & Michigan Power Co 79/05/03 10pp
- B Reportable occurrences, LERs & related correspondence**
- 7905050501 Forwards LER 79-052/03L-0
SMALLER, D V Indiana & Michigan Power Co 79/04/27 1p
- 7905040502 LER 79-012/03L-0 on 790303 hydraulic control valves did not return to normal position placing hydraulic lock on operator cylinder caused by dirt in hydraulic pilot valve, hydraulic fluid recalled
BROOK, H B Indiana & Michigan Power Co 79/04/27 1p
- 7905070359 Forwards LERs 79-012/03L-0 & 79-014/03L-0
SMALLER, D V Indiana & Michigan Power Co 79/05/02 1p
- 7905070360 LER 79-012/03L-0 on 790407 during rep shutdown pressure was allowed to drop to 21.90 psig. Covered by spray valve which was slow to respond Spray placed in manual & throttled back
MURPHY, C E Indiana & Michigan Power Co 79/05/02 1p
- 7905070595 LER 79-014/03L-0 on 790408 on two occasions rod position indication exceeded 10-step limit. Caused by drifting of signal transmitting module, which was adjusted for proper output
RIBBLE, J L Indiana & Michigan Power Co 79/05/23 2pp
- 7905250408 Forwards LERs 79-012/03L-0 & 79-014/03L-0
SMALLER, D V Indiana & Michigan Power Co 79/05/09 1p
- 7905150445 LER 79-012/03L-0 on 790409 during start startup, small crack & pinhole leak found in body of 790-22241 inlet side of valve in contact with cover of check valve. Replaced.
Diagrams of area reviewed
WINTER, D O Indiana & Michigan Power Co 79/05/09 1p
- 7905150501 LER 79-014/03L-0 on 790402 failure of interlock, which prevents opening both containment GDF 79 level airlocks. Source caused by slack in actuator cable & weak spring. One cable & spring replaced
MIDNER, G D Indiana & Michigan Power Co 79/05/09 1p
- 7905250329 Forwards LER 79-017/03L-0
SMALLER, D V Indiana & Michigan Power Co 79/05/16 1p
- 7905250330 LER 79-017/03L-0 on 790402 while performing BTP O&M, essential valve water-142, essential MW valve to D CB closed did not seal properly. Caused by excessive wear of split disc hinge points. Replaced with new discs were substituted
SMITH, H B Indiana & Michigan Power Co 79/05/16 1p
- DOCKET 80-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1**
J Insurance & Indemnity Information
- 7905070407 Confirm increased liability limit to \$124,000,000 for policies 80-1, 25, 42, 74, 82, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 200, 210, 212, 214, 215, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000
- 7905250409 Forwards Amends D-70 to Indemnity Agreement B-70 per 100784 changes re increase in liability insurance from \$140 million to \$160 million, effective 790501 Supporting documentation wmt
DOLAN, J E Antitrust & Indemnity Group 79/05/01 App
- 7905250325 Submit executed copy of Indemnity Agreement B-70, Amend 8, to responses to 790501 request
SMITH, H B Baltimore Gas & Electric Co 79/05/09 App
- F Operating license stage documents & correspondence**
- 7905060120 Forwards request for addl info re Cycle 4 reload, in reply to submittal
REID, R W Operating Reactors Branch 4 79/04/10 3pp
- 7905250500 Forwards Amends D8 & D1 to Licenses D98-03 & D98-01, respectively, safety evaluation & notice of issuance & availability
REID, R W Operating Reactors Branch 4 79/04/24 App
- 7905250502 Amends D8 & D1 to Licenses D98-03 & D98-01, respectively, limiting max boron concentration in safety injection & reducing water tanks & allowing reduced shutdown cooling flow when coolant gas is partially drained.
REID, R W Operating Reactors Branch 4 79/04/24 4pp
- 7905250503 Safety evaluation supporting Amends D8 & D1 to Licenses D98-03 & D98-01, respectively
Office of Nuclear Reactor Regulation, 79/04/24 App
- 7905250507 Notice of issuance & availability of Amends D8 & D1 to Licenses D98-03 & D98-01, respectively
REID, R W Operating Reactors Branch 4 79/04/26 3pp
- 7905050419 Forwards proprietary & nonproprietary versions of response to Cycle 4 reload questions. Proprietary version available in Central Files.
LINDVALL, A C Baltimore Gas & Electric Co 79/05/07 3pp
- 7905250508 Response to NRC Questions on Calvert Cliffs Unit 1, Cycle 4 Reload Submittal, App 1-NP, 790425, nonproprietary version & Construction Engineering, Inc. ERM 107-123-0P, 79/04/28 2pp
- 7905250509 Submit nonnegative radiological environ operating rep & safety summary per 7904 App B requirements.
HOUT, J M Baltimore Gas & Electric Co 79/05/17 App
- 7905050508 Forwards summary of ERM Nuclear, Inc. resolution/documents of new flexibility error which related to core analysis of P&ID, piping analysis chapter program from Jan-Oct 1967. Review & analysis included all work through Dec 1970.
FORD, J L ERM Nuclear, Inc 79/05/21 App

DOCKETED ITEMS

107

--7903300203 Forwards EGS Nuclear, Inc. list of RWBs & piping age which could have been impacted by deficient computer program
EGS has no record of reevaluation for Cooper piping age
STEVENSON, P. M. General Electric Co. Nuclear Energy Products Div
79/01/24. 1pp

B Inspection reports, IE Bulletins & correspondence

7905140508 Forwards IE Insp Rpt 50-31/79-03 on 760319-19
no noncompliance noted
BRUNEN, E. J. Region 1, Philadelphia, Office of the Director
76/04/07 3pp

--7905140510 IE Insp Rpt 50-31/79-02 on 790310-19 No noncompliance noted
Major areas inspected minutes, facility change request & operating & event logs
GULLBERG, P. J. OMBIA, S. Region 1, Philadelphia, Office of the Director
76/04/07 3pp

7903050501 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/03/23 1p

7903050527 Forwards IE Info Notice 79-07, "Repair of Radiaste Tanks"
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/03/23 1p

7903050506 Forwards IE Info Notice 79-06, "Interconnection of Contaminated Gas w/Boiler Air Gas Used as Source of Breathing Air"
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/03/23 1p

7903050504 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/03/23 1p

7903050505 Forwards IE Bulletin 79-06, "Review of Operational Errors & Gas Misalignments Identified During TMI Incident"
Licensee action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905150072 Notification that in-plant fuel shop will be performed between 790430-0502
Site visit can be handled under "Excluded Access to Controlled Area" requirements
REID, R. H. Operating Reactors Branch 4
79/04/13 2pp

7903050509 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping"
Licensee action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/14 1p

7903050508 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Gas Misalignments Identified During TMI Incident"
Licensee action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/16 1p

7903040174 Forwards IE Bulletin 79-06, "Events Relevant to Bellows Master Power Reactors Identified During TMI Incident"
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905050504 Forwards IE Bulletin 79-07, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Sys." Licensee action required
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905050505 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Gas Misalignments Identified During TMI Incident"
GRIER, B. H. Region 1, Philadelphia, Office of the Director
79/04/18 1p

7905050712 Response to IE Bulletin 79-06B re changes in operating procedures, preventative measures & briefing of personnel since TMI. Add info re RCB will be completed by 790430
LUNDVALL, A. E. Baltimore Gas & Electric Co.
79/04/26 11pp

7903300742 Response to IE Bulletin 79-04, "Incorrect Weights Per Being Check Valves Rpt by Valon Engineering Corp." Bomb analysis indicates piping or support overstress supports will be modified by accurate increased valve weights.
LUNDVALL, A. E. Baltimore Gas & Electric Co.
79/04/30 3pp

R Periodic operating reports & related correspondence

7903030356 Forwards monthly operating report for Apr 1979
ROSEN, G. D. Baltimore Gas & Electric Co.
79/03/18 1p

--7903030356 Monthly operating report for Apr 1979
ROSEN, G. D. Baltimore Gas & Electric Co.
79/03/18 11pp

S Reportable occurrences, LERs & related correspondence

7905100348 20-00-31/73/50 on 791203 condensate storage tank supply valve to auxiliary feedwater pumps found shut, cutting off water supply. Caused by valve mispositioning. Valve opened.
RUBELL, L. S. Baltimore Gas & Electric Co.
79/12/03 3pp

7905100318 Forwards Abnormal Occurrence 50-31/75/50 on 791203
LUNDVALL, A. E. Baltimore Gas & Electric Co.
79/12/16 1p

--7905100312 40-00-31/75/50 on 791203 discovered condensate storage tank supply valve to auxiliary feedwater pumps shut, cutting off water supply. Caused by administrative error. Valve opened. Listed valve deviation form will be used.
RUBELL, L. S. Baltimore Gas & Electric Co.
79/12/16 3pp

7903010024 Forwards LER 79-01/03L-0
RUBELL, L. S. Baltimore Gas & Electric Co.
79/04/26 1p

--7905100308 LER 79-01/03L-0 on 790411 during surveillance testing, auxiliary high pressure safety injection feeder isolation valve (SI-404) required 20-00 to open. Operating instructions revised to maintain SI-404 in open mode 1, 2 & 3.
GARRICK, J. T. Baltimore Gas & Electric Co.
79/04/26 3pp

7903020385 Forwards LER 79-01/03L-0
RUBELL, L. S. Baltimore Gas & Electric Co.
79/03/02 1p

--7903020384 LER 79-03/03L-0 on 790417 while performing routine surveillance test, discovered hydrogen analyzer was inoperable. Caused by failure of internal power supply transformer. Transformer & two associated capacitors replaced.
GANDHA, N. A., GANDHA, B. N. Baltimore Gas & Electric Co.
79/03/02 1p

7905100300 Forwards LER 79-04/04L-0
RUBELL, L. S. Baltimore Gas & Electric Co.
79/05/14 1p

--7905100303 LER 79-04/04L-0 on 790302 only 89 spray needles are installed on containment spray header. 12/1980 mandates 90 needles. Engineering evaluation of effort indicates as-built spray header exceeds design flow rate.
MIDENHALL, J. T., GARRICK, J. T. Baltimore Gas & Electric Co.
79/05/14 1p

7905050426 Forwards LER 79-01A/03L-0
RUBELL, L. S. Baltimore Gas & Electric Co.
79/05/19 1p

--7905050430 LER 79-03A/03L-0 on 790421 one of eight main steam safety valves tested found out of tolerance in conservative direction. Caused by difference in ambient conditions between time when valve last tested & time of test.
GARRICK, J. T., MIDENHALL, J. T. Baltimore Gas & Electric Co.
79/05/19 3pp

DOCKETED ITEMS

7905160225 Submits executed copy of Indemnity Agreement E-70: Amend B in Response to 790304 request
RHEINBERG, C. L. Baltimore Gas & Electric Co. 79/05/09 App

P Operating license change documents & correspondence

7905000123 Forwards Request for add'l info re Cycle 4 release in response to submittal
REID, R. H. Operating Reactors Branch 4 79/04/13 App

7905000202 Forwards Amends 2B & 2I to Licensee 2PR-22 & 2PR-29, respectively, safety evaluation & notice of issuance & availability
REID, R. H. Operating Reactors Branch 4 79/04/24 App

--7905000505 Amends 2B & 2I to Licensee 2PR-22 & 2PR-29, respectively, limiting max boron concentration in safety injection & refueling water tanks & allowing reduced shutdown cooling flow when coolant sys is partially drained
REID, R. H. Operating Reactors Branch 4 79/04/24 App

--7905000509 Safety evaluation supporting Amends 2B & 2I to Licensee 2PR-22 & 2PR-29, respectively
Office of Nuclear Reactor Regulation 79/04/24 App

--7905000507 Notice of issuance & availability of Amends 2B & 2I to Licensee 2PR-22 & 2PR-29, respectively
REID, R. H. Operating Reactors Branch 4 79/04/24 App

7905000203 Submits nonroutine radiological environ operating reqs on nuclear samples, per ETS App & requirements
KOTCO, J. M. Baltimore Gas & Electric Co. 79/05/17 App

7905000202 Forwards summary of EEO Nuclear, Inc resolution/documentation of alleged disability error which existed in version of PIRSEL piping analysis computer program from Jan-Oct 1978
Review & reanalysis included all work through Dec 1978
PIRSEL, P. L. EEO Nuclear, Inc. 79/05/21 App

--7905000503 Forwards EEO Nuclear, Inc list of 3BAs & piping sys which could have been impacted by defective computer program
SE has no record of reanalysis for Cosep piping sys
EEO Nuclear, P. L. General Electric Co., Nuclear Energy Products Div. 79/05/24 App

B Inspection reports, EE Bulletin & correspondence

7905010101 Forwards IE Info Notice 79-06, "Direct Analysis of Safety-Related Piping"
SEIDL, S. H. Region 1, Philadelphia, Office of the Director 79/03/23 App

7905000370 Forwards IE Info Notice 79-07, "Rupture of Radiactive Tank"
SEIDL, S. H. Region 1, Philadelphia, Office of the Director 79/03/26 App

7905010306 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Re Air Sys Used as Source of Breaching Air"
ORRIS, S. H. Region 1, Philadelphia, Office of the Director 79/03/28 App

7905010306 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ORRIS, S. H. Region 1, Philadelphia, Office of the Director 79/03/30 App

7905000300 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During THE Incident." Licensee action required
ORRIS, S. H. Region 1, Philadelphia, Office of the Director 79/04/11 App

7905000309 Forwards IE Bulletin 79-07, "Dynamic Stress Analysis of Safety-Related Piping." Licensee action required
ORRIS, S. H. Region 1, Philadelphia, Office of the Director 79/04/11 App

7905000308 Forwards IE Bulletin 79-08, "Review of Operational Errors & Sys Misalignments Identified During THE Incident." Licensee action required
ORRIS, S. H. Region 1, Philadelphia, Office of the Director 79/04/14 App

7905040374 Forwards IE Bulletin 79-09, "Events Relevant to Selling Water Power Reactors Identified During THE Incident."
SEIDL, S. H. Region 1, Philadelphia, Office of the Director 79/04/16 App

7905000504 Forwards IE Bulletin 79-09, "Failures of OR Type AC-2 Circuit Breaker in Safety-Related Sys." Licensee action required
ORRIS, S. H. Region 1, Philadelphia, Office of the Director 79/04/17 App

7905010323 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During THE Incident."
ORRIS, S. H. Region 1, Philadelphia, Office of the Director 79/04/16 App

7905000702 Responds to IE Bulletin 79-08 re changes in operating procedures/preventative measures & briefing of personnel since THE add'l info re RCR will be completed by 790420
LAWHALL, A. E. Baltimore Gas & Electric Co. 79/04/26 App

7905000742 Responds to IE Bulletin 79-04, "Incorrect Heights for Guide Check Valves RFG by Velan Engineering Corp." Should analysis indicate piping or support overstress, supports will be modified to accommodate increased valve weights
LAWHALL, A. E. Baltimore Gas & Electric Co. 79/04/30 App

R Periodic operating reports & related correspondence

7905020356 Forwards monthly operating rpt for Apr 1979
HERGENROTZ, S. D. Baltimore Gas & Electric Co. 79/05/10 App

--7905020356 Monthly operating rpt for Apr 1979
HERGENROTZ, S. D. Baltimore Gas & Electric Co. 79/05/13 App

G Repeatable occurrences, LDRs & related correspondence

7905030494 Forwards LDR 79-002/02L-0
RUSSELL, S. D. Baltimore Gas & Electric Co. 79/05/02 App

7905030248 LDR 79-052/02L-5 on 790408 fused circuit within power supply in PWR24 250, 2750A for plant process computer failed. Caused by internal high current drain function was restored using the power supply unit.
BAVILL, R. M. Baltimore Gas & Electric Co. 79/05/02 App

SCENET 30-223 THREE MILE ISLAND NUCLEAR REACTION UNIT 2

A Applications/construction stage documents & correspondence

7905030202 Forwards preliminary review of Section 6.2 of FRAM Section not adequately complete to allow initiation of detailed technical review
HERGENROTZ, S. D. Atomic Energy Commission (Cfr 1975). 79/02/23 App

7905110004 Forwards milestones & activity list for THE, status etc 790320, for period ending 790307 Explains extension of fuel load data & cost schedule
GUMM, W. T. GPU Service Corp. 79/05/06 App

7905110337 Forwards milestones & activity list for THE, status etc 790320, for period ending 790307
GUMM, W. T. GPU Service Corp. 79/05/07 App

7905110337 Forwards milestones & activity list for THE, status etc 790320, for period ending 790307
GUMM, W. T. GPU Service Corp. 79/05/08 App

7905110367 Forwards milestones & activity list for THE, status etc 790320, for period ending 790307
GUMM, W. T. GPU Service Corp. 79/05/08 App

7905110387 Forwards milestones & activity list for THE, status etc 790320, for period ending 790307
GUMM, W. T. GPU Service Corp. 79/05/14 App

7905110394 Forwards milestones & activity list for THE, status etc 790320, for period ending 790307
GUMM, W. T. GPU Service Corp. 79/05/16 App

7905110401 Forwards milestones & activity list for THE, status etc 790320, for period ending 790307
GUMM, W. T. GPU Service Corp. 79/05/16 App

7905110397 Forwards milestones & activity list for THE, status etc 790320, for period ending 790307
GUMM, W. T. GPU Service Corp. 79/05/17 App

DOCKETED ITEMS

109

790510330 Act receipt of WFO 790424 ltr re check status reph "Yellow Book" - Forwards summary of WFO "Yellow Book" activity dates as submitted by General Public Utility
AMNOLB.R.C. Metropolitan Edison Co. 7/6/04/24 Spp

790510370 Forwards milestones & activity list for THL status dtd 7/6/03/01 for period ending 7/6/03/07
GNNM.H.T. CPU Service Corp. 7/6/07/06 Spp

790510372 Forwards milestones & activity list for THL status dtd 7/6/03/01 for period ending 7/6/03/07
GNNM.H.T. CPU Service Corp. 7/6/08/04 Spp

790510160 Forwards application for byproduct mat'l license
AMNOLB.R.C. Metropolitan Edison Co. 7/4/05/19 1p

---790510170 Application for mat'l/byproduct license by Metropolitan Edison Co. for possession of any byproduct mat'l w/atomic numbers between 1 & 84; Co-137; Am-241 & Pu-239
AMNOLB.R.C. Metropolitan Edison Co. 7/6/10/19 1Spp

790510292 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 7/6/11/08 Spp

790510403 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07 Fuel load data extended because of budgetary restrictions
GNNM.H.T. CPU Service Corp. 7/6/12/03 Spp

790510403 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 77/01/06 Spp

790510403 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 77/02/04 Spp

790510403 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 77/03/04 Spp

790510160 Requests add info for processing 790109 application for byproduct mat'l license Forwards mat'l lab use guide
GNNM.H.T. Radiotopes Licensing Branch (Pw 790501) 77/03/25 Spp

---790510162 Draft "Guide for Preparation of Application for Lab Use of Small Quantities of Byproduct Mat'l"
Radiotopes Licensing Branch (Pw 790501) 75/12/31 Spp

790510403 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07 Fuel load data extended because of budgetary restrictions
GNNM.H.T. CPU Service Corp. 77/04/04 Spp

790510176 Application for mat'l/byproduct license to authorize possession of any byproduct mat'l w/atomic numbers 1 through 83 inclusive
AMNOLB.R.C. Metropolitan Edison Co. 77/04/18 Spp

790510336 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 77/05/06 Spp

790510389 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 77/06/02 Spp

790510356 Add info requested on 790325 by NRC re application for mat'l/byproduct license dtd 7/6/12/01 has not been received. Info sent by received within 30 days.
AMNOLB.R.C. Radiotopes Licensing Branch (Pw 790501) 77/06/16 1p

790510149 Forwards add info re byproduct mat'l license requested in WFO 790424 ltr
AMNOLB.R.C. Metropolitan Edison Co. 77/06/28 Spp

790510389 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 77/07/08 Spp

790510364 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 77/09/02 Spp

790510144 Mat'l/Byproduct License 37-17037-01 for Metropolitan Edison Co. authorizing possession of any byproduct mat'l w/atomic numbers between 1 & 84; Co-137; Am-241 & Pu-239
GNNM.H.T. Radiotopes Licensing Branch (Pw 790501) 77/09/26 Spp

790510389 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07 Lists reasons for extension of Fuel load date
GNNM.H.T. CPU Service Corp. 77/10/07 Spp

790510378 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 77/11/02 Spp

790510376 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 77/12/09 Spp

790510174 Requests add info for processing mat'l/byproduct license application dtd 770410 WFO sent
AMNOLB.R.C. Radiotopes Licensing Branch (Pw 790501) 77/12/19 1p

790510329 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 78/01/09 Spp

790503074 Various update sheets for Blue Book from 790417-790422
Commission 78/02/03 27Spp

790510368 Forwards milestones & activity list for THL status dtd 7/6/12/01 for period ending 7/6/12/07
GNNM.H.T. CPU Service Corp. 78/02/09 Spp

E. NRC Safety Evaluation Report (ESR) - supply & correspondence
NATTON.R.J. Division of Systems Safety 79/03/14 Spp

790502432 Drafts draft input to ESR section re degradation in core meltdown
CUMMINGS.H.M. Office of Nuclear Regulatory Research. 79/04/13 Spp

790510401 Outline for ESR
NATTON.R.J. Division of Systems Safety 79/03/14 Spp

F. Security, medical, emergency & fire protection plans
BUEYER.R. Division of Security 7/6/08/26 1p

790504022 Notices of fulfillment of util security packet request
BUEYER.R. Division of Security 7/6/08/26 1p

790510416 Forwards 430 00 security clearance fee from Metropolitan Edison representative, L.L. Langer WFO sent
GNNM.H.T. Personnel Security Branch 7/6/11/01 1p

790510410 Forwards 450 00 security clearance fee from Metropolitan Edison representative, M.R. Credit WFO sent
GNNM.H.T. Personnel Security Branch 7/6/11/19 1p

790510417 Forwards requested fingerprints card Provides add'l info --
Form 1
CREDIT.M.H. Metropolitan Edison Co. 7/6/11/24 1p

790510464 Notification of "L" access authorization for I
Edison representative, L.L. Langer
BUEYER.R. Personnel Security Branch 77/04/18 1p

790520419 Requests three personnel security packets be
Metropolitan Edison Co.
GNNM.H.T. Division of Security 77/03/17 1p

790510417 Notification of receipt of request for access packet from Metropolitan Edison employee, M.R. Credit
HIMMELBACH.L. Personnel Security Branch 77/05/17 1p

790510417 Forwards 430 00 security clearance fee from Metropolitan Edison representative, M.R. Credit
GNNM.H.T. Personnel Security Branch 77/05/17 1p

790510417 Notification of "L" access authorization for I
Edison representative, M.R. Credit
BUEYER.R. Personnel Security Branch 77/03/08 1p

790510416 Emergency Procedure 23032-2, 1. Situation Blackout version
Metropolitan Edison Co. 77/12/30 Spp

DOCKETED ITEMS

FD-36 (Rev. 5-22-64) Notification of "L" access authorization to Metropolitan
Edison representative, JA Newalling
BRADY, E A Personnel Security Branch 7/1/02/26 1p

795150107 Notes re emergency planning & evacuation
* Commission 79/00/21 9pp

7905140046 Discusses emergency procedures for major sequence of events following loss of forced circulation of ROK
* Office of Nuclear Reactor Regulation 79/04/01. 20pp

7905220416 Forwards review of earliest evacuation points from PSAR &
PA Disaster Operations Plan
On: C Office of Police Evaluations 79/04/86 19pp

790520457 Discusses Reorganizing Procedure & no loss of information
w/feedback available upon removal
BETTERCO, S.L. Consultant Director der Elant Systems. 28/04/00

7909070262 Discusses emergency preparedness needs in light of the incident. Urges assignment of 11 persons to State Program until end of fiscal year & eight personnel positions remain. RNN:R G Office of State Programs 79/08/10 (5pp)

79032000076 Notifies State of WA that WSC has not received emergency plan Offense assistance in resolving problem
HENDRIE, J M Comaction 79/03/09 3pp

7705300094 Notifies State of MS that NRC has not received emergency plan Office assistance in resolving problem
1000288Z J M Commission 78/08/89 2pg

7/13/2009 10:01 AM: Notifies State of GA that HRE has not received emergency plan. Offers assistance in resolving problem.
HENDRICK, J M Commission 7/13/09 2pp

770330GIGG Habitual Users of IL that FRC has not received
emergency plan Offers assistance in resolving problem
HENDRIE, J R Comedian 79/03/08. 2pg

7905360157 Notifies State of VA that NRE has not received acceptable emergency plan Offers assistance in resolving problem
HENDERIE, J M. Comelision 29/03/99 2ss

2903200115 HRRIFLES State of NE that NRC has not received
emergency plan Offsite assistance in resolving problem
HRRIFLES, J H. Commission 79405/09 See

7903300119 Notifies State of CO that HRC has not received
emergency plan Offers assistance in resolving problem
HRC0118 J.M. Commission 79105/08 Sec.

7903360120 Notifies State of MN that NRC has not received emergency plan. Offers assistance in resolving problem. (ENR)SIC: 2-8. Commission. TRANSFER See

7903601X2 Memphis State of MD that HWC has not received emergency plan. Officers assistance in resolving problem

7903300124 Notifies State of RI that HQC has not received emergency plan. Offers assistance in resolving problem.

7900000126 Notifies State of AC that ABC has not received
emergency plan Offers assistance in resolving problem

790330G12E Notified State of KY that NRC has not received
emergency plan. Offers assistance in resolving problem

7903260138. Notifies State of HI that NRC has not received emergency plan. Offers assistance in resolving problem

7905300i34 Notify State of OH that NRO has not received
emergency plan offers assistance in resolving problem

7903000139 Notified State of ME that NRC has not received appropriate emergency plan. Offers assistance in resolving problem.
HMCN01E, J M. Completion 79/05/09 Gpp

7703300144 Modify the State of PA that emergency plan must be updated
Request cooperation during Review
NEJORSE, J H Commission 79/08/09 Zpp

7905140063 Comments on security assistance at THI
ROBERTSON, L. Division of Security 79/05/10 2pg

2905300428 Comments on fire protection & security deficiencies at ON
MOTLEY, D P Engineering Technology Standards Branch Hydrli
Rpt

Q Adjudicatory correspondence

7905090225 Response to stay motion by interveners Graft order denying
interveners' motion but affirming ASLAM to consider Bx-222
issue and
MILLEY, J. L. Office of the General Counsel BEEF-A-7B-16 09/20/16

--PROSECUTOR Opposition is still to RECORD request from joint intervenors for Safe Environments and Youth Committee for Safe Environments for stay of initial decision Affidavit of AG Horta & Certificate of Doc and
TOWNSEND, D. F., BLAKE, L. Shaw, Pittman, Potts, & Townbridge
JUL 10/2018 1:00 PM

7105220426 Forwards requested documents re Chairman Hendrix's participation in review of Board decision.
BLADDER, E L. Office of the General Counsel. 28/02/24. 1c

7903090246 Reviews ALAB-645 issued by ASLAS on 790327 No petition for review have been filed/decision does not warrant Commission review.

MELBY:J L. Office of the General Counsel SECY-A-79-04 12/18/79
324

--7803050249 Remands radon issue to ABLD w/directions to reagent issue
for receipt of new evidence & for further hearings Partial
dismiss of MR Johnson and
DAVID M H Atomic Safety and Licensing Appeal Panel 7803027
Gos

7908090232 Inform Commission of ASLAW ALAW-474 decision on what re
petitions for review have been filed & does not warrant
review on its own merits.
REJUEY, J.L. Office of the General Counsel SECY-A-79-47 7/10/79
3pg.

796928034 Forwards 780606 memo re Chairman's participation in rules of ALAB-474 on THE CIO/PGO. M. Office of the General Counsel. 78/06/06. in

--796020436 Supplies background info re Chairman's participation in ALAB-474 on TMI Since Board decision does not deal w/ substantive issues, no conflict of interest is involved
CHOPPING, R. Office of the General Counsel 78/06/06 is

7930900008 Informs Commission of ASLAW decision ALAW-8086 for which petition for review has been filed. Decision concerned emergency plans & risk of heavy aircraft crashing into plant.

ELPERIN-8 F. Office of the General Counsel. DECV-A-78-18

7905040022: Provides info re Hapgood v. NRC, DC Circuit Number 79-1033
Plaintiff seeks judicial review of ALJ's-400 finding re: as
decision affects TMS proceeding. Not likely to be substantiated
by courts

==7855090225 Provides info re Kayford v ARC-SC Circuit Number 18-171
Plaintiff seeks judicial review of ALAB-480 only insofar as
decision affects THJ proceeding WILL be informed.

==7965090203 Provides info re Kayford v MRC, DC Circuit Number 79-112
Plaintiff seeks judicial review of ALAD-850 only insofar as
decision affects THJ proceeding. Will keep informed.

==790809202 Provides info re Karpford v MEC, DC Circuit Number 79-192
Plaintiff seeks judicial review of ALAB-ADO only insofar as
decision affects THH proceeding. Will keep informed.
CLOUTIER v. E. HARRIS, C. 79-192, 79-193, 79-194, 79-195, 79-196, 79-197, 79-198, 79-199, 79-200, 79-201, 79-202, 79-203, 79-204, 79-205, 79-206, 79-207, 79-208, 79-209, 79-210, 79-211, 79-212, 79-213, 79-214, 79-215, 79-216, 79-217, 79-218, 79-219, 79-220, 79-221, 79-222, 79-223, 79-224, 79-225, 79-226, 79-227, 79-228, 79-229, 79-230, 79-231, 79-232, 79-233, 79-234, 79-235, 79-236, 79-237, 79-238, 79-239, 79-240, 79-241, 79-242, 79-243, 79-244, 79-245, 79-246, 79-247, 79-248, 79-249, 79-250, 79-251, 79-252, 79-253, 79-254, 79-255, 79-256, 79-257, 79-258, 79-259, 79-260, 79-261, 79-262, 79-263, 79-264, 79-265, 79-266, 79-267, 79-268, 79-269, 79-270, 79-271, 79-272, 79-273, 79-274, 79-275, 79-276, 79-277, 79-278, 79-279, 79-280, 79-281, 79-282, 79-283, 79-284, 79-285, 79-286, 79-287, 79-288, 79-289, 79-290, 79-291, 79-292, 79-293, 79-294, 79-295, 79-296, 79-297, 79-298, 79-299, 79-300, 79-301, 79-302, 79-303, 79-304, 79-305, 79-306, 79-307, 79-308, 79-309, 79-310, 79-311, 79-312, 79-313, 79-314, 79-315, 79-316, 79-317, 79-318, 79-319, 79-320, 79-321, 79-322, 79-323, 79-324, 79-325, 79-326, 79-327, 79-328, 79-329, 79-330, 79-331, 79-332, 79-333, 79-334, 79-335, 79-336, 79-337, 79-338, 79-339, 79-340, 79-341, 79-342, 79-343, 79-344, 79-345, 79-346, 79-347, 79-348, 79-349, 79-350, 79-351, 79-352, 79-353, 79-354, 79-355, 79-356, 79-357, 79-358, 79-359, 79-360, 79-361, 79-362, 79-363, 79-364, 79-365, 79-366, 79-367, 79-368, 79-369, 79-370, 79-371, 79-372, 79-373, 79-374, 79-375, 79-376, 79-377, 79-378, 79-379, 79-380, 79-381, 79-382, 79-383, 79-384, 79-385, 79-386, 79-387, 79-388, 79-389, 79-390, 79-391, 79-392, 79-393, 79-394, 79-395, 79-396, 79-397, 79-398, 79-399, 79-400, 79-401, 79-402, 79-403, 79-404, 79-405, 79-406, 79-407, 79-408, 79-409, 79-410, 79-411, 79-412, 79-413, 79-414, 79-415, 79-416, 79-417, 79-418, 79-419, 79-420, 79-421, 79-422, 79-423, 79-424, 79-425, 79-426, 79-427, 79-428, 79-429, 79-430, 79-431, 79-432, 79-433, 79-434, 79-435, 79-436, 79-437, 79-438, 79-439, 79-440, 79-441, 79-442, 79-443, 79-444, 79-445, 79-446, 79-447, 79-448, 79-449, 79-450, 79-451, 79-452, 79-453, 79-454, 79-455, 79-456, 79-457, 79-458, 79-459, 79-460, 79-461, 79-462, 79-463, 79-464, 79-465, 79-466, 79-467, 79-468, 79-469, 79-470, 79-471, 79-472, 79-473, 79-474, 79-475, 79-476, 79-477, 79-478, 79-479, 79-480, 79-481, 79-482, 79-483, 79-484, 79-485, 79-486, 79-487, 79-488, 79-489, 79-490, 79-491, 79-492, 79-493, 79-494, 79-495, 79-496, 79-497, 79-498, 79-499, 79-500, 79-501, 79-502, 79-503, 79-504, 79-505, 79-506, 79-507, 79-508, 79-509, 79-510, 79-511, 79-512, 79-513, 79-514, 79-515, 79-516, 79-517, 79-518, 79-519, 79-520, 79-521, 79-522, 79-523, 79-524, 79-525, 79-526, 79-527, 79-528, 79-529, 79-530, 79-531, 79-532, 79-533, 79-534, 79-535, 79-536, 79-537, 79-538, 79-539, 79-540, 79-541, 79-542, 79-543, 79-544, 79-545, 79-546, 79-547, 79-548, 79-549, 79-550, 79-551, 79-552, 79-553, 79-554, 79-555, 79-556, 79-557, 79-558, 79-559, 79-560, 79-561, 79-562, 79-563, 79-564, 79-565, 79-566, 79-567, 79-568, 79-569, 79-570, 79-571, 79-572, 79-573, 79-574, 79-575, 79-576, 79-577, 79-578, 79-579, 79-580, 79-581, 79-582, 79-583, 79-584, 79-585, 79-586, 79-587, 79-588, 79-589, 79-590, 79-591, 79-592, 79-593, 79-594, 79-595, 79-596, 79-597, 79-598, 79-599, 79-600, 79-601, 79-602, 79-603, 79-604, 79-605, 79-606, 79-607, 79-608, 79-609, 79-610, 79-611, 79-612, 79-613, 79-614, 79-615, 79-616, 79-617, 79-618, 79-619, 79-620, 79-621, 79-622, 79-623, 79-624, 79-625, 79-626, 79-627, 79-628, 79-629, 79-630, 79-631, 79-632, 79-633, 79-634, 79-635, 79-636, 79-637, 79-638, 79-639, 79-640, 79-641, 79-642, 79-643, 79-644, 79-645, 79-646, 79-647, 79-648, 79-649, 79-650, 79-651, 79-652, 79-653, 79-654, 79-655, 79-656, 79-657, 79-658, 79-659, 79-660, 79-661, 79-662, 79-663, 79-664, 79-665, 79-666, 79-667, 79-668, 79-669, 79-670, 79-671, 79-672, 79-673, 79-674, 79-675, 79-676, 79-677, 79-678, 79-679, 79-680, 79-681, 79-682, 79-683, 79-684, 79-685, 79-686, 79-687, 79-688, 79-689, 79-690, 79-691, 79-692, 79-693, 79-

continued

443

DOCKETED ITEMS

181

7903100404 Notifies that DFC of Executive Legal Director will assist in developing response to 790309 petition by Involve Coalition on Nuclear Power
HARRIS, J. P. Hearing and Enforcement Division 79/04/04 App

7903100216 Forwards final evaluation of items discussed in 790301 memo re BSA-designed nuclear plants. Requests add info be forwarded to licensing boards
HARRIS, J. P. Division of Nuclear Operations Inspections 79/03/20 App

7903100403 Petition to suspend NRC for all NRCs
LUCHEIT, H. A. Environmental Coalition on Nuclear Power 79/03/29 App

7903100123 Forwards Board Notification 79/03 on reactor inspection concerns re BSA plants. Certificate of the Board
HARRIS, J. P. Hearing and Enforcement Division 79/03/29 App

7903100105 Board notification re: reactor inspection concerns re BSA plants
HARRIS, J. P. Assistant Director for Light Water Reactors 79/03/20 App

7903100201 Forwards two hearing to Thompson memo for Board
HARRIS, J. P. Office of the Executive Director for Operations 79/03/29 App

7903100209 Informs that preliminary evaluation of item J contained in 790302 memo will be included in light of the transient Add info may cause change in previous assessment
HARRIS, J. P. Division of Nuclear Operations Inspections 79/03/29 App

7903100203 Comments on delay in processing 790306 Board notification request
HARRIS, J. P. Hearing and Enforcement Division 79/03/29 App

7903100117 Forwards request for Board notification re non-safety grade equipment to mitigate transients
HARRIS, J. P. Hearing and Enforcement Division 79/04/02 App

7903100125 Board notification staff assessment re non-safety grade equipment to mitigate transients
HARRIS, J. P. Assistant Director for Light Water Reactors 79/03/29 App

7903100101 Board notification recent issue on non-safety grade equipment to mitigate transients. This is safe is required
HARRIS, J. P. Assistant Director for Light Water Reactors 79/03/29 App

7903100107 Forwards draft order to assume and confirm direct NRC regulatory authority over emergency situation at TMI-2
HARRIS, J. P. Office of the Executive Director for Operations 79/04/02 App

7903100205 Draft of order to assume and confirm direct NRC regulatory authority over emergency situation at TMI-2
HARRIS, J. P. Office of the Executive Director for Operations 79/04/02 App

7903100106 Recommendations pending determination of extraordinary nuclear occurrence at TMI-2 and of accident and assessment of consequences. FPLA Nuclear questions should be delayed
HARRIS, J. P. Office of the Executive Director for Operations 79/04/02 App

7903100103 Discusses effects of TMI on pending Branch IV hearings
HARRIS, J. P. Branch 2 79/04/03 App

7903100109 Discusses effects of TMI on hearing schedules. Lists proceedings scheduled from Apr through June. Forwards questions to be answered at 790404 hearing
HARRIS, J. P. Branch 2 79/04/03 App

7903100412 Lists questions to be answered at 790404 hearing re liquid pathway generic study & PFD
HARRIS, J. P. Atomic Safety and Licensing Board Panel 79/03/29 App

7903100102 Board notification nuclear incident at TMI. Recommendations re: cases involving BSA reactors be provided w/IE Bulletin
HARRIS, J. P. Assistant Director for Light Water Reactors 79/04/03 App

7903100207 Reviews impact of TMI on upcoming hearings. Lists hearings scheduled from Apr & May
HARRIS, J. P. Branch 2 79/04/03 App

7903100101 Details major issues & possible approaches re legal aspects of NRC inquiry into TMI incident
HARRIS, J. P. Office of the General Counsel 79/04/04 App

7903100101 Reviews delay in processing requests for Board
HARRIS, J. P. Office of the General Counsel 79/04/03 App

7903100203 Forwards latest notice to reopen safety hearings by TMI-2 on behalf of Dore the Valley - Dore Harbor Hill.
HARRIS, J. P. Office of the General Counsel 79/04/03 App

7903100203 Motion to suspend & revoke CP for proposed facility because of the incident
HARRIS, J. P. Hearing and Enforcement Division 79/04/04 App

7903100203 Suggests appropriate response to TMI testimony re closed valves on auxiliary feedwater pumps
HARRIS, J. P. Office of the General Counsel 79/04/02 App

7903100106 Discusses legal authority to shut down BSA reactor plants due to TMI incident
HARRIS, J. P. Office of the General Counsel 79/04/10 App

7903100104 Response to ALAB-BW re radon emissions & de minimus theory from Parsons re: Certificate of DFC and
HARRIS, J. P. Hearing and Enforcement Division 79/04/11 App

7903100101 Response to 790404 brief of Philadelphia Electric Co. Public Use Electric & Gas, & Atlantic City (AC) Electric Co. re de minimus theory. Certificate of the Board
HARRIS, J. P. Office of the General Counsel 79/04/11 App

7903100103 Forwards list of actions underway re TMI-2
HARRIS, J. P. Office of the Executive Director for Operations 79/04/11 App

7903100102 Notifies of consolidation of five subcommittee groups re radon emissions issue. Parsons have until 790320 to which to file for summary disposition
HARRIS, J. P. Atomic Safety and Licensing Appeal Panel 79/04/03 App

7903100104 Lists complaints filed against several utility companies associated with TMI-2. Complaints filed and
HARRIS, J. P. American Nuclear Insurers 79/04/27 App

7903100104 Postpones 790404 evidentiary hearing re aircraft crash probability issue. Assessment of situation will be made by
HARRIS, J. P. Atomic Safety and Licensing Appeal Panel 79/05/02 App

7903100103 Forwards class action complaint CA 79-208 filed in US District Court, Middle District of PA, brought against utility associated with TMI
HARRIS, J. P. American Nuclear Insurers 79/05/04 App

7903100103 Forwards class action complaint NRC vs BSA 79-223, US District Court, Southern District of NY
HARRIS, J. P. American Nuclear Insurers 79/05/15 App

7903100103 Forwards class action complaint re TMI accident filed against utility & vendors in US District Court, Middle District of PA
HARRIS, J. P. American Nuclear Insurers 79/05/22 App

7903100103 Forwards class action complaint re TMI accident filed against utility & vendors in US District Court, Middle District of PA
HARRIS, J. P. American Nuclear Insurers 79/05/22 App

7903100103 Forwards class action complaint re TMI accident filed against utility & vendors in US District Court, Middle District of PA
HARRIS, J. P. American Nuclear Insurers 79/05/22 App

7903100103 Forwards class action complaint re TMI accident filed against utility & vendors in US District Court, Middle District of PA
HARRIS, J. P. American Nuclear Insurers 79/05/22 App

7903100103 Forwards class action complaint re TMI accident filed against utility & vendors in US District Court, Middle District of PA
HARRIS, J. P. American Nuclear Insurers 79/05/22 App

7903100103 Forwards class action complaint re TMI accident filed against utility & vendors in US District Court, Middle District of PA
HARRIS, J. P. American Nuclear Insurers 79/05/22 App

- 7903140528 Requests rough estimate of probability of the accident computed on basis of methodology used in reactor safety study
BLAUER, J. F. A. Commission 79/03/29 1p
- 7903140527 Public comments on the incident: 790320-0409
* Affiliation Unknown 79/03/29 60pp
- 7903140528 Insists unit has placed corporate interests far above concern for public welfare until presence in area is no longer desired
SUGGESTS REQUESTS CANCELLATION
RYBICKI, J. A. Cumberland County, PA 79/04/03 2pp
- 7903140529 Urges stationing of permanent units federal inspectors at nuclear power plants in operation & under const in USA
SLIGERMAN, D. House of Rep 79/04/04 1p
- 7903110202 Confirms 790329 Request for telephone log re NRC situation
HOBBS, R. A. Commission 79/03/30 1p
- 7903110220 Confirms telcon w/ E. Ray regarding names of Congressmen who were informed of the situation & at what time
HOBBS, R. A. Commission 79/03/30 1p
- 7903140527 Suggests naming outside individuals & NRC members to accident review board
AHEARN, J. F. Commission 79/03/28 1p
- 7903140524 Requests complete investigation of the NRC incident since Licensing Board is to make decision on Diablo Canyon.
requests comparison of structural & operational designs for both plants
PACIFIC, L. E. House of Rep 79/03/30 1p
- 7903140524 Expresses concern re discharge of hazardous waste from the NRC
Requests notification of NRC activities & offers assistance
MATHIAS, C. H. Senate 79/03/31 4pp
- 7904100110 Requests listing of all facility employees for health monitoring
Scientists or film badges should be issued to all personnel
CALIFANO, J. A. Health, Education & Welfare, Dept. of 79/04/01 1p
- 7904100113 Notes from Commissioners' 790401 meeting re preliminary investigation
THOMPSON, K. L. Commission 79/04/04 2pp
- 7903070143 Requests NRC honor Governor Brown's request to shut down Ranch Rock
FISHER, R. Affiliation Unknown 79/04/02 1p
- 7903160071 Schedule for 790404 meeting w/ACER representatives, NRC & other representatives in Washington, DC to discuss chronology of the incident, current plant status, generic & health aspects
MORLEY, J. C. ACER - Advisory Committee on Reactor Safeguards 79/04/02 1p
- 7903160072 Suggests no more CRs or DRs should be issued until the events have been analyzed
MATHIAS, C. H. Commission 79/04/02 1p
- 7903160077 Press concerns from E. Denton's 790402 press conference on the conditions
GARRISON, J. Commission 79/04/03 1p
- 7903160124 Type of H. Denton's press conference should arrive 3 PM on 790402. Expects PWR completion same day
GARRISON, J. Commission 79/04/02 1p
- 7903160128 Discusses NRC response to Congressman Packer 790402 letter. All possible meetings will be open to public. Transcripts of closed meetings will be released w/o proprietary info
GARRISON, J. Office of the General Counsel 79/04/03 1p
- 7903160133 Summary of telcon w/ E. Cole re decommissioning costs for the
CALIFANO, J. A. Fuel Process Systems Standards Branch 79/04/03 1p
- 7903160201 Describes telcon between J. Califo of NRC & J. Cole of Kennedy subcommittee re cost of decommissioning the
KENNEDY, E. Commission 79/04/03 1p
- 7903160201 Outlines action plan for developing regulatory options on older BWR operating reactors.
* Commission 79/04/03 2pp.
- 7903160201 Comments on areas which will be covered by NRC review & suggests a blue ribbon panel be established
AHEARN, J. F. Commission 79/04/03 2pp
- 7903160202 Suggests NRC in-house review plans re the incident. Suggests president establish blue ribbon panel to study technical issues
HOBBS, R. A. Commission 79/04/03 2pp
- 7903160203 Forwards Chapter 5, "Reactor Coolant Sys" & Chapter 6, "Contingency Safety Features" from PWR
HOBBS, R. A. Office of State Programs 79/04/04 1p
- 7903160203 Forwards EE Bulletin 79-03 & PWRs on the 790403
HOBBS, R. A. Office of State Programs 79/04/04 1p
- 7903160203 Requests info re NRC's levels of gamma radiation at reactor facilities & instrument failures on Diablo at the NRC
HOBBS, R. A. Office of State Programs 79/04/03 6pp
- 7903160204 Expresses thanks for assistance re issue of origin survey site within NRC
HOBBS, R. A. Office of Nuclear Regulatory Research 79/04/03 1p
- 7903160205 Expresses thanks for suggestions re hydrogen overpressure during incident
HOBBS, R. A. Office of Nuclear Regulatory Research 79/04/03 1p
- 7903160206 Expresses thanks for suggestions re assistance during the incident
HOBBS, R. A. Office of Nuclear Regulatory Research 79/04/03 1p
- 7903160207 Expresses thanks for assistance re hydrogen bubble problem during incident
HOBBS, R. A. Office of Nuclear Regulatory Research 79/04/03 1p
- 7903160208 Expresses thanks for assistance during the incident
HOBBS, R. A. Office of Nuclear Regulatory Research 79/04/03 1p
- 7903160209 Recommends formation of accident review commission. Requests meeting
AHEARN, J. F. Commission 79/04/03 1p
- 7903160210 Expresses thanks for assistance during the incident
HOBBS, R. A. Office of Nuclear Regulatory Research 79/04/03 1p
- 7903160211 Requests FBI communications re the incident w/ a suit
BLAUER, J. F. Division of Security 79/04/04 1p
- 7903160212 Forwards background questions & answers re reactor decommissioning & decommissioning to support meeting between Moderator & Senator Hart
HOBBS, R. A. Office of Standards Development 79/04/04 11pp
- 7903160213 Draft chronology of contacts between Commissioners, NRC staff & Governor of PA re the incident 790320-01
GARRISON, J. F. Commission 79/04/04 2pp
- 7903160214 Forwards draft letter to Secretary Schlesinger expressing appreciation for support provided by DOE re the incident & requesting continued support
GARRISON, J. F. Office of the Executive Director for Operations 79/04/04 4pp
- 7903160215 Ack receipt of 790402 letter re the incident. Complete response will be forwarded as soon as possible. Forwards NRC press releases & preliminary notifications re incident
GARRISON, J. F. Office of Congressional Affairs 79/04/04 1p
- 7903160216 Requests info re hypothetical radiation dispersion pattern resulting from possible explosion w/ or w/o meltdown at the
HOBBS, R. A. House of Rep 79/04/04 3pp
- 7903160217 Forwards 790402 letter from T. Frensch expressing concern re aircraft flight paths over the incident
HOBBS, R. A. House of Rep 79/04/04 4pp
- 7903160218 Ack receipt of 790320 letter re the incident. Complete response will be forwarded as soon as possible. Forwards NRC press releases & preliminary notifications re incident
GARRISON, J. F. Office of Congressional Affairs 79/04/04 3pp

DOCKETED ITEMS

113

- 7903160020 Forwarded backup questions & answers to use in preparation for hearing on the before Senate Subcommittee on Nuclear Regulation
KAMMERER, C Office of Congressional Affairs 79/04/09 1p
- 7903160027 Backup questions & answers to use in preparation for hearing on the before Senate Subcommittee on Nuclear Regulation
KAMMERER, C Office of Congressional Affairs 79/04/09 30pp
- 7903160076 Advises that JM Hendrie thinks it unnecessary to establish position on issuing licenses prior to hearing
GILBERT, Y Commission 79/04/09 1p
- 7903160096 Discusses assessment of radiological doses from the accident by ad hoc group
PETERSON, H T Office of Standards Development 79/04/09 8pp
- 7903160110 Notification of time change for 790410 hearing HJ Deeken will not attend
GILBERT, Y Commission 79/04/09 1p
- 7903160134 Forwarded proposed addition to JM Hendrie's THN testimony before Senator Herb re evacuation plans
BRADFORD, P A Commission 79/04/09 2pp
- 7903200303 Forwarded "Preliminary Description of Events at THN-2 Facility Accident" & "Basic Considerations of THN-2 Incident" as background info for 790410 Senate hearing
KAMMERER, C Office of Congressional Affairs 79/04/09 15pp
- 7903200601 In response to 790320 ltr re safety of nuclear power plants by CT in light of THN-2 Hendrie's testimony
before Senate Subcommittee on Nuclear Regulation W/ encl
KAMMERER, C Office of Congressional Affairs 79/04/10 2pp
- 7903200773 Requests info re THN mechanical malfunctions & possibility of similar occurrences at CT nuclear plants
DOUG, G J House of Rep 79/03/30 1p
- 7903160346 Forwarded congressional ltr which NRC has answered w/ interim responses but containing questions which require further response. Lists priorities W/ encl
KAMMERER, C Office of Congressional Affairs 79/04/10 1p
- 7903160401 Comments on inferring Congress about THN situation
KAMMERER, C Office of Congressional Affairs 79/04/10 2pp
- 7903160437 Requests that THN info be sent to J Dewitt, PA Secretary for Review Affairs
HEARNE, J F Commission 79/04/10 1p
- 7903160501 List of individuals chosen to comprise Presidential Commission to investigate THN
KAMMERER, C Office of Congressional Affairs 79/04/11 2pp
- 7903160524 Responds to suggestion to help improve conditions at facility. Suggestions considered & appreciated
DENTON, H R Office of Nuclear Reactor Regulation 79/04/11 5pp
- 7903160581 Ack receipt of 790410 ltr forwarding correspondence from HL Pennabaker re THN response will be forwarded as soon as possible
KAMMERER, C Office of Congressional Affairs 79/04/12 2pp
- 7903160596 Responds to 790412 memo re actions on the Lists contact persons in Dir of Administration for FDA request processing
FELTSM, J H Division of Rules and Records 79/04/12 3pp
- 7903160647 Comments on conversation w/ Hgts. special consultant to House Subcommittee on Energy & Environment re transcript of Commission closed meeting on THN
HEINTZ, B Office of Congressional Affairs 79/04/12 1p
- 7903160693 Requests statement of basis for providing transcripts of closed THN meetings to Congress re 790412
GILBERT, Y Commission 79/04/13 1p
- 7903160785 Requests ltr by 790420 of all THN work
LEVINE, G Office of Nuclear Regulatory Research 79/04/13 1p
- 7903200240 Summary of questions raised on loss-of-coolant loop at THN during current shutdown. Results of work being performed by Nuclear Energy Reactor Commission by THN re credibility
Office of Nuclear Reactor Regulation 79/04/13 3pp
- 7903160246 Recommends additional review procedure for THN transcripts
GILBERT, Y Commission 79/04/14 1p
- 7903160247 Describes status of THN transcripts. Records of 790320-31 & 0325-09 are in THN Transcripts of 790404-10, 12 & 13 will be available to Commissioners by 790417
HSDGDPH, A Commission 79/04/14 1p
- 7903160544 Forwarded reconstruction by E Ray of circumstances surrounding transmission of transcripts of closed Commission meetings on THN
KAMMERER, C Office of Congressional Affairs 79/04/14 1p
- 7903160584 Responds to request for chronology of events re release of transcripts of closed meetings of Commission during THN emergency
PARK, B S Office of Congressional Affairs 79/04/14 4pp
- 7903160102 Submits chronological environmental monitoring info at THN
BRADFORD, P A Commission 79/04/14 2pp
- 7903200175 Confirms 790408 letter re willingness to attend any meeting re THN. Includes text of letter sent to General Public Utility re familiarity w/ various models & ion exchange
TILMER, H R London Nuclear Decontamination Ltd 79/04/15 1p
- 7903160490 Expresses appreciation for contribution to NRC efforts at THN
HENDRIE, J H Commission 79/04/17 1p
- 7903160191 Expresses appreciation of JF Hensburg's work during THN incident
DENTON, H R Office of Nuclear Reactor Regulation 79/04/13 1p
- 7903160350 Forwarded Ltr Sussex 790419 memo directing NRC personnel to keep written record of anyone pertaining to THN Requests copies of all notes
HENDRIE, J H Office of Nuclear Regulatory Research 79/04/17 1p
- 7903200204 Ack receipt of 790415 ltr re THN incident. Complete responses will be made as soon as possible. Forwarded G Hensburg's Senate testimony summarizing significant events W/ encl
KAMMERER, C Office of Congressional Affairs 79/04/18 3pp
- 7903160191 Confirms understanding of 790416 meeting re coordination of NRC responses to THN incident. Assigns R Cornell as Head point for info
GILBERT, Y Commission 79/04/18 1p
- 7903160600 Ack receipt of 790328 ltr will consider suggestions in analyzing THN incident
HENDRIE, J H Commission 79/04/18 1p
- 7903160171 Forwarded transcripts released 790418 & preceding week. More will be sent as they are released W/ encl
GILBERT, Y Commission 79/04/18 1p
- 7903160173 Forwarded transcripts released 790418 & preceding week. More will be sent as they are released W/ encl
GILBERT, Y Commission 79/04/18 1p
- 7903160173 Forwarded transcripts released 790418 per V Gilman's directions W/ encl
HENDRIE, J H Office of the General Counsel 79/04/18 1p
- 7903160603 Forwarded proposed witness list for second THN hearing on THN
KAMMERER, C Office of Congressional Affairs 79/04/18 2pp
- 7903200125 Lists add personnel to be authorized for access to turbine sig
GILBERT, Y Division of Operating Reactors 79/04/18 1p
- 7903200234 Believes nuclear power plants should be closed until emergency plan for 100% of crisis are available. Wants no plants built pending improved safety assurance
WERNER, L Affiliation Unknown 79/04/19 1p
- 7903160200 Responds to 790415 invitation NRC representatives unable to attend European nuclear conference in Hamburg to discuss THN
HENDRIE, J H Commission 79/04/20 1p
- 7903160200 Invites NRC representative to 790307 European Nuclear Conference in Hamburg re THN
HENDRIE, J H European Nuclear Conference 79/04/19 1p
- 7903160546 Notification that SMO will conduct investigation of THN incident
KAMMERER, C Office of Congressional Affairs 79/04/20 1p

- 7903100338 Forwards update to partial responses to Congressional Request & Gooding's 790309 letter to JM Hendrie Update includes shutdown of TH1-B from "deposited capability" provided by without Reliability Council
YOUNG, L. J. Cost Benefit Analysis Branch 79/04/23 3pp
- 7903100375 Suggests communication system be upgraded to handle two events simultaneously: manual interface between incident response and Commission during unusual events
KEMMER, R. T. Commission 79/04/23 1p
- 7903200154 Requests addition of NE Pipeline & NP Fish to NRC Access List
4/27/80
KOSCIAN, J. J. Region I, Philadelphia, Office of the Director 79/04/23 3pp
- 7903200163 Request addition of RM Expulsion to NRC Access List 4/27/80
KOSCIAN, J. J. Region I, Philadelphia, Office of the Director 79/04/23 1p
- 7903200201 Recommends temporary shutdown of Reactor B until present uncertainties re TH1-B incident are clarified
MELBY, R. T. House of Rep 79/04/24 2pp
- 7903200405 Requests NRC assistance for college survey re average citizens' feelings about nuclear power
MULLER, G. Affiliation Unknown 79/04/24 3pp
- 7903100364 Requests temporary shutdown of Reactor B in view of incident of TH1-B
MORAN, L. G. California, State of 79/04/24 1p
- 7903200201 Believes that coast waiting period should be enforced until nuclear cook & waste problems are solved Requests info re:
Nuclear safety
MORAN, L. G. Affiliation Unknown 79/04/25 1p
- 7903100321 Forwards 790312 letter from AD Faidan to J. Carher volunteering to work w/ Presidential Commission on TH1 accident
KOSCIAN, J. J. Office of Congressional Affairs 79/04/25 1pp
- 7903200145 Requests 8 TH1-B be thanked for excellent job in preparing charts for briefings
WILLIAMS, R. H. Assistant Director for Site Analysis 79/04/25 1p
- 7903200248 Discusses delay in appointing non-NRC individual to head TH1-B investigation Requests initiating NRC coordinating staff
GINSBERG, V. Commission 79/04/25 1p
- 7903200123 Comments on TH1-B NRC should order all operating BSM designed nuclear facilities shut down pending appropriate design corrections
WILSON, R. E. House of Rep 79/04/26 1p
- 7903200216 Expresses appreciation for way in which TH1 incident was handled
PICKER, K. L. Affiliation Unknown 79/04/26 1p
- 7903100303 Notifies that if Reactor B is shut down, availability of power from area sources is only to Transmission Stations & other facilities unique in area
WILSON, R. E. Sacramento Municipal Utility District 79/04/26 2pp
- 7903100309 Favors thorough analysis before decision to shut down nine nuclear power plants
LITVINSON, D. L. Congress (Joint & Staffing Committee, etc.) 79/04/26 1p
- 7903100312 Forwards 790310 letter from Chairman Conigli to E. Shabo, Controller General of US, requesting OASD initiate comprehensive investigation of TH1 incident
KEMMER, R. T. Office of Congressional Affairs 79/04/26 3pp
- 7903200112 Discusses methods of measurement for gamma radiation exposure, doses of radiation levels & radiation levels prior to TH1 incident Info submitted for review & update for Congressional input
Office of Inspection & Enforcement 79/04/26 3pp
- 7903200447 Comments on current nuclear power plant problems in US and safety record at Canadian plants
BOSCH, R. H. Affiliation Unknown 79/04/27 1p
- 7903200414 Discusses bus transportation for 790304 Congressional visit
KOSCIAN, J. J. Region I, Philadelphia, Office of the Director 79/04/27 1p
- 7903200231 Public comments re incident at TH1 & nuclear power in general
Affiliation Unknown 79/05/01 103pp
- 7903100227 Requests to end 790305 letter demanding earlier suggestion concerning use of oxygen to reduce hydrogen bubble Adding that oxygen could have adversely affected plant safety
GENTILE, R. E. Office of Nuclear Reactor Regulation 79/05/01 1p
- 7903100327 Suggests addition of oxygen to reduce hydrogen bubble
ANDERSON, L. Affiliation Unknown 79/04/26 1p
- 7903100373 Forwards responses to questions asked by Senator Harkins re TH1-B PWR authorization after TH1 incident
MULLER, R. T. Office of Management and Program Analysis 79/05/01 11pp
- 7903100328 Advises that Joint Chiefs of Staff assigned task: "1. To prepare" re operations in support of TH1 incident
GOSSEL, L. V. Office of the Executive Director for Operations 79/05/10 1p
- 7903100307 Forwards anti-nuclear flyers
Commission 79/05/10 3pp
- J Insurance & indemnity information
- 7903100364 Forwards Amended B to Indemnity Agreement B-A per 67-4847 changes re increase in liability insurance from \$100 million to \$150 million-effective 790301
and
SCLTHPM, J. Antitrust & Indemnity Group 79/05/01 3pp
- 7903200268 Returns original Amended B to Indemnity Agreement B-A Nuclear Liability Insurance Pool will not provide additional coverage
BREYER, H. F. GPU Service Corp 79/05/10 2pp
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 7903100328 Submits summary of NRC 790327 briefing on TH1 incident
LUMBER, R. H. ACNS - Advisory Committee on Reactor Safeguards 79/05/28 3pp
- 7903100321 Forwards portion of Subcommittee meeting transcript questioning whether operator could diagnose accident & assess core status
BOSCH, R. H. ACNS - Advisory Committee on Reactor Safeguards 79/05/05 13pp
- 7903200216 Discusses ACNS concerns re TH1-B incident
ACNS - Advisory Committee on Reactor Safeguards 79/04/10 1p
- 7903100311 Summary of 790310 hearing by Senate Subcommittee on Nuclear Regulation re TH1 accident investigation will last six months & report issued after one year
BOSCH, R. H. ACNS - Advisory Committee on Reactor Safeguards 79/04/11 3pp
- 7903100324 Summary of ACNS 790409-14 site visit re plant status recovery plans & core assessment Forwards BSM 790410 report on natural circulation cooling
KOSCIAN, J. J. ACNS - Advisory Committee on Reactor Safeguards 79/04/19 42pp
- 7903100328 Summary of Natural Circulation Alternatives for Long Term Core Cooling at TH1-B
KOSCIAN, J. J. Babcock & Wilcox Co 79/04/10 33pp
- 7903100374 "Closed Interim Report on Recent Incident at TH1" draft report to be completed during 790510 meeting
ACNS - Advisory Committee on Reactor Safeguards 79/04/11 1p
- 7903100312 Notes recommendations to NRC re TH1 Recommends initiation of operator training NRC work in chemical expertise
BOSCH, R. H. ACNS - Advisory Committee on Reactor Safeguards 79/04/10 2pp
- 7903200268 Forwards summary of highlights of special ACNS meeting re TH1-B-17 to discuss TH1 incident
GOSSEL, L. V. Division of Project Management, 79/04/18 11pp
- 7903200371 Statement by vice president of Nuclear Power Corporation to ACNS re BSM activities as result of TH1 incident
KOSCIAN, J. J. Babcock & Wilcox Co 79/04/16 103pp

DOCKETED ITEMS

115

- 7905140139 Details topics to be covered at special ACRS meeting on 790416 topics include small breaks & transients in BSM plants in light of TMI incident
CRICKEN, L. P. Division of Project Management 79/04/12 1p
- 7905140137 Responds to 790418 ltr ACRS 790413 recommendations are generic & apply to all PWRs. Procedural changes should be made only after study of effect on overall safety
CARROLL, M. W. ACRS - Advisory Committee on Reactor Safeguards 79/04/25 2pp
- 7905140133 Submits current preliminary chronology package of operational events & results of interviews w/operators & others re TMI incident
LENNARD, M. W. ACRS - Advisory Committee on Reactor Safeguards 79/04/25 4pp
- 7905140138 Forwards to Harley 790413 memo re research program changes resulting from TMI incident
MCCORMACK, T. ACRS - Advisory Committee on Reactor Safeguards 79/04/26 1p
- 7905140137 Details changes in safety research program as result of TMI incident
MCCORMACK, T. E. Division of Reactor Safety Research 79/04/12, 4pp
- 7905140134 Invitation for 790511 appearance before ACRS to discuss causes, lessons & corrective actions of TMI incident & advise re what done on other BSM reactors
FRALBY, V. F. ACRS - Advisory Committee on Reactor Safeguards 79/04/27 1p
- 7905140134 Forwards 790413 memo re TMI core damage assessment, updating 790406 report based on early data. Memo also forwarded to ACRS members attending 790508 meeting on reactor fuel
GOSWAMI, P. ACRS - Advisory Committee on Reactor Safeguards 79/04/27 1p
- 7905140139 Forwards Metropolitan Edison 790424 ltr w/emergency shutdown procedures & preliminary sequence of TMI-B accident events
MCCORMACK, T. E. ACRS - Advisory Committee on Reactor Safeguards 79/04/28 1p
- 7905140135 Submits emergency procedures 2202-B 1-reactor trip/2202-B 2-loss of reactor coolant/2202-B 3-pressure/2202-B 4-station blackout & preliminary sequence of events w/sg
AMNOLD, R. C. GPU Service Corp 79/04/28 8pp
- 7905140139 Responds to ACRS recommendations re TMI incident as requested in NRC 790317 ltr
ANDERSON, T. H. Westinghouse Electric Corp. 79/05/21 2pp
- 7905140135 Discusses initial review of best force to evaluate safety implications for nuclear plant design & operation of TMI accident. Individual ACRS recommendations will be evaluated as part of overall design review program.
MCHUGH, R. A. E. C-E Power Systems 79/05/20 2pp
- F. Operating license stage documents & correspondence
- 7905140131 Mail/Byproduct License 30-17237-02 for Metropolitan Edison Co. authorizing possession of one byproduct mail shipment
numbers 1-30 inclusive
MROGUE, E. O. Radioisotopes Licensing Branch (Pps 790501) 79/03/14 3pp
- 7905140136 Forwards allocations & activity list for TMI status chd 790220-2 for period ending 790307
GURNEY, H. T. GPU Service Corp 79/03/19 3pp
- 7905140139 Rept on reactor trip/engineered sgs of 790424 MNRG meeting
WILLIAMS, J. L. Metropolitan Edison Co. 79/04/23 4pp
- 7905140139 "Nuclear Power Plant Evacuation Plans"
CLARK, P. O., CONY, D. B. Citizens for a Better Environment. 79-7849 79/05/01 3pp
- 7905140134 Forwards statement issued by B Cony of Citizens for Better Environment re emergency planning for nuclear accidents
FOURHARD, J. J. Office of Public Affairs. 79/05/02 3pp
- 7905140134 Responds to remarks of IL Emergency Rvc representative's reactions to federal radiological emergency response planning effort.
COLLINS, H. E. Office of State Programs 79/05/21 2pp
- 7905140135 NRC examination results for 1978-1979 power reactor operator applicants/until operator applicants previously licensed & senior operator applicants initial application
Commission 79/05/21 2pp
- 7905140137 "Power Plant Examination Results Summary Sheet" for various plants for 1977-1979
COLLEY, R. A. Operator Licensing Branch 79/05/23 16pp
- 7905140134 Tech Spec changes re emergency feedwater sgs
Metropolitan Edison Co. 79/05/24 4pp
- 7905140139 Notification of breakdown in communication lines for TMI
info
GARRIS, G. New York State 79/05/16 2pp
- 7905140138 790508 incident no injuries reported & turbine shutdown caused by reduction in flow of feedwater to steam generators
Office of Inspection & Enforcement 79/05/20 2pp
- 7905140134 Comments on TMI meeting release of radioactivity
CARROLL, M. W. Commission 79/05/20 1p
- 7905140138 Nuclear reactor info re technical experts called to TMI site
Office of Nuclear Reactor Regulation 79/05/21 1p
- 7905140139 "Preliminary Test Results, Rods/Cladding Prescriptions Called Valve Venting from TMI-Type Conditions"
Office of Nuclear Reactor Regulation 79/05/21 1pp
- 7905140137 Test results of hydrogen solubility experiment 1 at Provo, UT
Office of Nuclear Reactor Research 79/04/01 1p
- 7905140138 Forwards videotape used at Commission meeting
GOSWAMI, P. C. Assistant Director for Systems & Projects 79/04/01 2pp
- 7905140134 Tech Spec for 2202-B
Metropolitan Edison Co. 79/04/01 4pp
- 7905140131 Discusses NRC procedures for decision to recommend evacuation
Commission 79/04/01 2pp
- 7905140138 Forwards 790402 memo from C. Bishop re issues which NRC should consider in recommending demands for investigation into TMI incident
BISHOP, T. L. Office of the General Counsel 79/04/02 1p
- 7905140137 Forwards preliminary thoughts on decontamination of TMI-B in response to ALBAMA request
HARRIS, E. A. Office of Policy Evaluation 79/04/02 4pp
- 7905140138 Ward notification recommends IE evaluation of reactor
Licensee concerns re BSM plants be sent to Board now
WILLIAMS, J. L. Assistant Director for Light Water Reactors 79/04/02 1p
- 7905140137 Rept & TMI update on situation as of 790422 re evacuation options
WILSON, M. H. Housing & Urban Development Dept of 79/04/02 3pp
- 7905140138 Forwards possible action plan by J. Harley & L. Slagle for consideration of regulatory options on BSM operating status
status to TMI
BISHOP, T. L. Office of the General Counsel 79/04/02 3pp
- 7905140139 Forwards Facilities & Sgs Security Branch notes on TMI
Division of Security 79/04/02 3pp
- 7905140139 Meeting notes re legal issues for TMI
MCCORMACK, T. E. Office of the General Counsel 79/04/02 1p
- 7905140134 Forwards personal exposure & monitoring report for 1978
HARRIS, E. A. Metropolitan Edison Co. 79/04/02 3pp
- 7905140137 Outlines methods of accident review for TMI
WILLIAMS, J. L. Commission 79/04/02 4pp

DOCKETED ITEMS

- 7903140304 Summary of info re nuclear incident as of 790402 Describes plant & environ status
LAFLEUR, J. B. Office of International Programs 79/04/02 3pp
- 7903140305 Forwards three sets of TLD data collected near TH1 facility
M/S encl
KARNEN, D. C. Office of Congressional Affairs 79/04/02 1p
- 7903140306 Discusses possible detonation of extraordinary nuclear
accident as TH1-2 re activation of Price-Anderson Act
DEWITT, H. H. Office of Nuclear Reactor Regulation SHARP, H. A.
Office of the Executive Legal Director 8007-79-325 79/04/02
13pp
- 7903140307 Forwards statement of PA Governor Thornberry re incident re
mile & background info on federal guidelines for radioactive
levels in milk
KERN, R. A. Office of Policy Evaluations 79/04/02 3pp
- 7903140308 Forwards excerpts of documents relevant to emergency
planning EPA protective action guides, PA action guides &
PSM conditions for general emergency action
KERN, R. A. Office of Policy Evaluations 79/04/02 80pp
- 7903140309 Lists points to be included in TH1-2 study & forwards
proposed public announcement re incident prepared by
F. Legner
KERN, R. A. Office of Policy Evaluations 79/04/02 10pp
- 7903140310 Requests background info for Commission re status of BWR
reactors. IE Bulletin 79-05, description of IE action re BWR
plants & description of last group of reactor transient
EYBRIGHT, G. Commission 79/04/02 2pp
- 7903140311 Discusses requirements for qualification of TH1 pumps &
valves & possible changes in Tech Specs
NEFF, D. Office of Nuclear Regulatory Research 79/04/02 3pp
- 7903140312 Lists status of BWR reactors as of 790402
+ Commission 79/04/02 1p
- 7903140313 Took results of hydrogen solubility experiments 2 & 3 run
at Provo, UT
+ Office of Nuclear Regulatory Research 79/04/02 1p
- 7903140314 Notifies OGL of Telco numbers & individual to be contacted
re TH1 inquiries
SHARP, H. A. Office of the Executive Legal Director 79/04/02 1p
- 7903140315 Forwards three sets of thermoluminescent dosimeter data
collected around TH1 M/S encl
KARNEN, D. C. Office of Congressional Affairs 79/04/02 4pp
- 7903140316 Suggests actions in response to TH1 accident Forwards
possible series of events at TH1 & suggests comments
KARNEN, D. C. Commission 79/04/02 3p
- 7903140317 Summary of 790402 meeting w/ GPU Div Corp & Petroskillen
Edison re base case
+ Commission 79/04/02 4pp
- 7903140318 Comments on reactor pressure oscillations at the
possibility of real oscillations between the gas valve seems
likely
MORSE, J. F. M. General Electric Co 79/04/02 3pp
- 7903140319 Discusses radiation levels in industrial waste treatment
sampling & hydrogen recombiner
LAUNER, S. GPU Services Corp 79/04/02 1p
- 7903140320 Forwards organizational chart, prerequisite for reactor
reactant recovery & charts of pressure & heat curves
BERNARD, D. M. Babcock & Wilcox Co 79/04/02 4pp
- 7903140321 Forwards JO Harkin 790402 memo & agenda for 790404 daily
planning meeting
VOLLNER, R. H. Assistant Director for Site Analysis 79/04/02
4pp
- 7903140322 Submits brief summary of results of review of radiochemical
data reported to date.
RDV, D. H. Babcock & Wilcox Co 79/04/02 3pp
- 7903140323 Forwards miscellaneous handwritten notes on TH1-2
+ Office of Nuclear Reactor Regulation 79/04/02 4pp
- 7904160377 Suggests program to alleviate concern among pregnant women
evaluate effects on fetus & develop epidemiologic data base
for possible future studies
GOLDMITH, R. A. Radiological Health Standards Branch
79/04/04 2pp
- 7903140324 Notification of development of preliminary plan to conduct
series of health impact studies related to TH1 incident
TOLMATH, G. K. Health, Education & Welfare: Dept of 79/04/04
2pp
- 7903140325 Draft text on TH1 requested by Vice President Mondavi's Co.
for possible use
+ Commission 79/04/04 2pp
- 7903140326 Recommends change to natural circulation at TH1-2 site
present cooling mode becomes unstable
TERPICH, R. L. Assistant Director for Plant Systems 79/04/04
3pp
- 7903140327 Notes on 790404 telecon w/ Banning
HARRIS, E. H. Assistant Director for Plant Systems 79/04/04 1p
- 7903140328 Discusses engineering fit to hydrogen solubility data of
Frag. Babcock & Wilcox
FELDER, C. Assistant Director for Advanced Reactor Safety Research
79/04/04 1p
- 7903140329 Submits background info on TH1-2 incident
ETHELINGTON, H. A. BATELLE - ACSC - Advisory Committee on Reactor
Safety 79/04/04 3pp
- 7903140330 Summarizes assumptions in SANDIA-BRIGGS calculations re TH1
operating history Provides fuel composition data, decay phase
data & long-term data of fabricated reactor operating power
BENNETT, D. E. Sandia Laboratories 79/04/04 3pp
- 7903140331 Submits background info on TH1-2 incident
ETHELINGTON, H. A. BATELLE - ACSC - Advisory Committee on Reactor
Safety 79/04/04 2pp
- 7903140332 Discusses opinion that scenario surrounding TH1-2 incident
was thoroughly evaluated by WASH-1400
RICHEL, J. H. ACSC - Advisory Committee on Reactor Safety
79/04/04 2pp
- 7903140333 Handwritten notes of 790404 meeting at TH1
GOLDMITH, R. Office of Standards Development 79/04/04 3pp
- 7903140334 Discusses causes for hydrogen levels produced at TH1
Suggests use of chemical inhibitors in ECOS for/or regular
reactant to minimize potential hydrogen production
KARNEN, D. C. & Associates 79/04/04 2pp
- 7903140335 Discusses implications of TH1 incident for licensed BWR
reactors & reactors undergoing review
GRAY, J. R. Branch 1 79/04/04 12pp
- 7903140336 Handwritten notes re schedules as result of TH1
+ Office of the Executive Legal Director 79/04/04 13pp
- 7903140337 Outlines options for TH1 accident review
KARNEN, D. C. Commission 79/04/04 3pp
- 7903140338 Discusses estimated radiological exposure doses & BWR data
for cold shutdown
GIBSON, T. Commission 79/04/04 1p
- 7903140339 Lists licensing actions scheduled to occur between
790408-790423, including voluntary hearings, prehearing
conferences & TH1 impact on future actions
TERPICH, R. L. 79/04/04 3pp
- 7903140340 Discusses several recirculation questions/concerns
+ Office of Inspection & Enforcement 79/04/04 3pp
- 7903140341 Notifies of NRC procedure maintaining telephone logs from
outside operations CTR
GIBSON, T. V. Office of the Executive Director for Open
79/04/04 1p

DOCKETED ITEMS

117

- 7905210047 Discusses problems identified at BSM facilities re TH1 occurrence identified problems include pressurizer level instrumentation, integrated control sys & lack of hydrogen LMSB.R.C Region 3, Atlanta: Reactor Operations Nuclear Support Branch 79/04/04 13pp
- 7905230037 Forwards JO Herskelt 790404 memo & agenda for 790405 daily planning meeting
VOLLMEIR.H Assistant Director for Site Analysis 79/04/04 3pp
- 7905230137 Requests attendance at first meeting of TH1 recovery organization to be held on 790409 in Treadler 22 Organization chart encl
ARMSTRONG.C GPU Service Corp 79/04/04 3pp
- 7905230123 Summary of meetings w/TH1-2 study groups re reaching natural circulation & depressurization status
HATFIELD.V Division of Operating Reactors HATFIELD.R Division of Systems Safety 79/04/04 16pp
- 7905230126 Requests info re daily planning meeting in Treadler 22 daily planning meeting agenda encl
VOLLMEIR.H Assistant Director for Site Analysis 79/04/04 3pp
- 7905050042 Notifies that Commissioner H White of the Japanese Nuclear Safety Commission will arrive 790407 to review status & activities of TH1-2 events
LAFLEUR.J.D Office of International Programs 79/04/03 2pp
- 7905110043 Questions & answers for Vice President Honda on TH1
Commission 79/04/03 4pp
- 7905110271 Details efforts re equipment survivability
Office of Nuclear Reactor Regulation 79/04/03 4pp
- 7905110278 Description of proposed organization for NRC operation at TH1-2
Office of the Executive Director for Operations 79/04/03 5pp
- 7905110280 "Evaluation of Failure Modes for Reactor Pressure Vessels, Containment & Other Safety-Related Equipment Subjected to Inert Gas Evacuation - Proposed Investigation
O'BRIEN.J Office of Nuclear Regulatory Research 79/04/03 1p
- 7905110281 Lists now or augmented research projects suggested as result of TH1 incident & shutdown of five plants for seismic research Project details encl
RICHMAN.DONALD.E Mechanical Engineering Branch 79/04/03, 14pp
- 7905110315 Lists info required from Battelle Columbus Labs
CORREIA.W.H. Probabilistic Analysis Branch 79/04/03 1p
- 7905110321 Describes areas where General Reactor Safety Research can provide assistance re TH1 incident
GILFILLAN.D Division of Reactor Safety Research 79/04/03 5pp
- 7905110326 Considers value of running natural circulation test on reactor-in hopes of obtaining info helpful to TH1-2 situation
TUDENCO.B.L Assistant Director for Plant Systems 79/04/03 3pp
- 7905110332 Handwritten notes of 790405 meeting at PA State Health Dept
GOLDENTHORN.R Office of Standards Development 79/04/03 4pp
- 7905110343 Handouts from 790403 briefing
LEVINE.S Office of Nuclear Regulatory Research 79/04/03 10pp
- 7905110377 Requests steps to be taken following TH1 Forwards list of options, summary of investigations into civil air accidents
A Kestute 790404 memo & C Stabler 790404 memo
ARMSTRONG.J Commission 79/04/03 16pp
- 7905110388 Requests to General Public Units guard re alternative methods for long-term cooling Procedures for natural circulation flow J4 790404 encl
BOYD.H Babcock & Wilcox Co 79/04/03 4pp
- 7905110379 Special Operating Procedure 2-37 re pressure reduction during depressurization Operations support plans encl
WALLACE.A, Babcock & Wilcox Co 79/04/03 4pp
- 7905110372 Discusses pressure reduction for head saving depressurization
HOLLIS.R.E Babcock & Wilcox Co 79/04/04, 2pp
- 7905110374 Notes re NRC comments on special operating procedure 2-37 re pressure reduction during depressurization
Babcock & Wilcox Co 79/04/04 4pp
- 7905110377 Forwards status of BSM procedures & site comments/emergency procedures as of 4 AM on 790405
WRIGHT.H.L Babcock & Wilcox Co 79/04/05 4pp
- 7905110379 Forwards cross-reference of major BSM contingency procedures w/TH1 procedures
BOYD.H Babcock & Wilcox Co 79/04/05 3pp
- 7905110380 Forwards organizational charts for TH1-2 recovery
BIRCKAMP.H.H GPU Service Corp. 79/04/05 3pp
- 7905110383 Requests to R Hattson & S Ross concerning value of running natural circulation test on BSM reactor
TUDENCO.B.L Assistant Director for Plant Systems 79/04/05 4pp
- 7905230032 Forwards JO Herskelt 790405 memo & agenda for 790406 daily planning meeting
VOLLMEIR.H Assistant Director for Site Analysis 79/04/05 3pp
- 7905230033 Forwards organizational chart for General Public Utility' recovery operations Provides guidelines for communicating organization
BENTON.H.R Office of Nuclear Reactor Regulation 79/04/05 4pp
- 7905230047 Summary of 790406 meeting of Technical Working Group in discuss desirability of reducing RCS temp from 550 F to 230 F
GPU Service Corp 79/04/05 1p
- 7905230059 Discusses iodine & cesium concentrations in containment surge
DANIEL.T.L Environmental Evaluation Branch 79/04/05 3pp
- 7905270178 Notification of plans to conduct systematic review of stds in determining adequacy & completeness
HINCHCOCK.R Office of Standards Development 79/04/04 1p
- 7905050212 Forwards estimated core inventory of important fission & actinide products for TH1 reactor.
KIMBLE.A Office of Policy Evaluations 79/04/04 4pp
- 7905110243 Minutes of 790405 meeting of technical working group
Commission 79/04/05 18pp
- 7905110417 Discusses events within primary sys re core assessment
MARTIN.M.M Commission 79/04/05 7pp
- 7905110327 Notifies of 1A primary coolant pump tripped offline & 2A pump started 3 minutes later Some change in thermocouple temp distribution noted, but not serious
WELBY.P.F ACRS - Advisory Committee on Reactor Safeguards 79/04/05 1p
- 7905110412 Handwritten notes of 790405 meeting w/Reel Cancer Inst
GOLDENTHORN.R Office of Standards Development 79/04/05, 2pp
- 7905110202 Rehears summary of population dose for accident 790328-0405
BATTISTON.L Environ Protect Standards Branch 79/04/04 4pp
- 7905110382 TH1-2 control room manning assignments
Office of Nuclear Reactor Regulation, 79/04/04, 1p
- 7905110375 Notifies of reduction in 1E personnel at TH1
Organizational chart encl
O'BRIEN.H.H Region 3, Philadelphia: Office of the Director 79/04/05 3pp
- 7905110385 Notification of completion of RELAP-4 TH1 simulations
FITCHED.S.E EG & S, Inc. 79/04/05 2pp
- 7905110386 Forwards draft of chronology of events & 790406 memo from E Gouvier
HOWARD.R Office of Inspection & Enforcement 79/04/06 1p
- 7905110395 Forwards chronology of events from 790328 at 7 05 on to 790402 at midnight
CHAMBERS.R Office of Management and Program Analysis 79/04/05 10pp

DOCKETED ITEMS

7905010500 Forwards 790404 memo to R Graber which lists NRC personnel who have been trained in radiation safety per 150CM19
BENTLEY, R. V. Region 4, Dallas. Office of the Director 79/04/06 1p

--7905010503 Submits list of NRC personnel who have been trained in radiation safety per 150CM19 & should be allowed unrestricted access to areas requiring radiation work permits
BENTLEY, R. V. Region 4, Dallas. Office of the Director 79/04/06 2pp

7905010504 Responds to 790403 memo & suggests another possible cause of the pressure oscillation
HARRIS, J. T. F. General Electric Co 79/04/06 1p

7905010507 Notifies that Trailer 27 will be used as working area for technical review team & safety assessment team. Requests principal staff at work area
ROBB, D. F. Assistant Director for Reactor Safety 79/04/06 1p

7905010510 Forwards JO Herbert 790406 memo & agenda for 790407 daily planning meeting
VALLINDER, R. H. Assistant Director for Site Analysis 79/04/06 10pp

7905010517 Summary of 790405 technical working group meeting re venting waste gas in containment & long-term cooling
SPW Service Corp 79/04/06 3pp

7905010523 Forwards description of staff organization & personnel assignments for NRC operations at TH-2
BENTLEY, R. V. Office of Nuclear Reactor Regulation 79/04/06 7pp

7905010546 Notes on hydrogen in RCS & procedure for measuring reactor coolant hydrogen concentration
HARRIS, J. T. F. Industry Advisory Group 79/04/06 3pp

7905010529 Provides calculation of heat load in containment due to decay of airborne fission products & activity in sump water
TATLUM, R. H. Office of Nuclear Reactor Regulation 79/04/06 11pp

7905010528 Forwards concept for benign control of TH-2 primary cooling system
HARRIS, J. T. F. Division of Systems Safety 79/04/07 4pp

7905010533 Summary of 790407 meeting w/Herrington Edison to discuss auxiliary cooled bldg exhaust/pressure tank of waste gas group & radiation exposure tracking
PETERSON, T. Safeguards Standards Branch 79/04/07 3pp

7905010535 Discusses plans for post-event liquid radwaste release apparent not program for immediate future action. Requests using radwaste/chemical waste filters to eliminate iodine
BENTLEY, R. V. Auxiliary Systems Branch 79/04/07 4pp

7905010536 Forwards concept for benign control of TH-2 primary coolant system proposed by Levinson's study group. Believes long-term water level in reactor vessel can conceivably be controlled by using accumulator line T111
HARRIS, J. T. F. Division of Systems Safety 79/04/07 3pp

7905010538 Minutes of 790407 technical working group meeting w/Herrington Edison Co. re spent fuel pool/sump tank leakage radwaste release & noise analysis
SPW Service Corp 79/04/07 2pp

7905010536 Forwards JO Herbert 790407 memo & agenda for 790408 daily planning meeting
COLLINS, J. T. Effluent Treatment Systems Branch 79/04/07 11pp

7905010510 Summary of 790407 planning meeting re establishment of bench actions for TH-2 study groups.
HARRIS, J. T. F. SPW Service Corp 79/04/07 14pp

7905010543 Observations & estimates re containment bldg & estimator of lower bound for total radwaste release
HARRIS, J. T. F. Industry Advisory Group 79/04/07 2pp

7905010512 Forwards Commissioner Olinick's meeting of Chairman Hendrick's testimony before House Subcommittee on Nuclear Regulation on 790410.
HARRIS, J. T. F. Commission 79/04/08 14pp

7905010519 Discusses 790407 briefing by Westinghouse re preliminary

7905010520 Revises procedures to be followed to assume coordination of TH-2 lab support for NRC activities at TH-2 per 790407
HARRIS, J. T. F. Division of Systems Safety 79/04/08 1p

--7905010507 Summary of TH-2 lab support work per TH-2
HARRIS, J. T. F. Division of Systems Safety 79/04/08 12pp

7905010516 Requests authorization to ship four chemical filters from NRCB plant in Richmond, VA to Harrisburg, PA
HARRIS, J. T. F. CPU Service Corp 79/04/08 1p

7905010528 Recommends deferral of permission to use add'l bench policy work water sample
ROBB, D. F. Division of Project Management 79/04/08 1p

7905010535 Submits revised list of 16 personnel who should be authorized access to Unit 2 control room
HARRIS, J. T. F. Region 1, Philadelphia. Office of the Director 79/04/08 2pp

7905010541 Provides agenda for 790408 planning meeting. Includes two lists & 72nd slide
HARRIS, J. T. F. Office of Inspection & Enforcement 79/04/08 2pp

7905010538 Suggests realignment in senior personnel at TH-2 long-term. Are unacceptable & suggest in case of 111-considered decision process
ROBB, D. F. Division of Project Management 79/04/08 1p

7905010535 Summary of 790407 meeting w/16 personnel at site to better understand overall response to event & onsite capabilities & activities
HARRIS, J. T. F. Office of Inspection & Enforcement 79/04/08 1p

7905010548 Discusses B&W recommendations that add'l boron be added to primary coolant loop
ROBB, D. F. Assistant Director for Reactor Safety 79/04/08 1p

--7905010533 Discusses Westinghouse proposal to build decay tank, re. use to serve as backup to existing sys. Suggests modification was design
SPW Service Corp 79/04/08 5pp

7905010535 Preliminary thoughts on lessons learned from TH-2 incident
HARRIS, J. T. F. Pennsylvania State Univ 79/04/08 4pp

7905010535 Discusses Westinghouse 790407 briefing on preliminary conceptual design of mode of TH-2 decay tank removal system. Must intend to increase long-term reliability of sys.
HARRIS, J. T. F. Division of Systems Safety 79/04/08 3pp

7905010574 Forwards JO Herbert 790408 memo & agenda for 790409 TH-2 recovery daily planning meeting.
COLLINS, J. T. Effluent Treatment Systems Branch 79/04/08 10pp

7905010535 Submits procedures to be followed to assume coordination of TH-2 lab support for NRC activities.
HARRIS, J. T. F. Division of Systems Safety 79/04/08 2pp

7905010538 Forwards questions & answers for hearing before subcommittee on TH-2 incident to be provided to Chairman
HARRIS, J. T. F. Technical Services 79/04/08 24pp

7905010538 Summarizes 790408 offer by London Nuclear Reactor to assist in TH-2 cleanup. Recommends meetings w/London Nuclear, PHE, & B&W. Considers re decontamination
O'CONNOR, P. W. Operating Reactors Branch 2 79/04/08 2p

7905010538 Preliminary chronology of 790328 TH-2 incident.
SPW Service Corp 79/04/08 70pp

7905010549 Requests continuing reports re analysis of TH-2 incident
HARRIS, J. T. F. Atomic Energy Control Board, Canada 79/04/08 4p

7905010512 Outlines scope of fact finding board investigation TH-2 technical & procedural viewpoints
HARRIS, J. T. F. Office of Policy Evaluations 79/04/08 2pp

7905010538 Lists options for authorizing new mode of operation for TH-2 discussion w/E. B. & L. Chandler.
HARRIS, J. T. F. Branch 1 79/04/08 3pp

DOCKETED ITEMS

119

- 790514002 Ack receipt of info re decontamination & recovery procedures following nuclear incident
AUBREY D Atomic Industrial Forum 79/04/09 12pp
- 790519012 Discusses establishment of data reduction & mgt group Copies of all TRG-2 related documents must be provided to group Collection packets will be placed in each trailer.
LUNDH R L Metropolitan Edison Co 79/04/09 2pp
- 790510029 Submits revised list of 16 personnel who should be authorized access to Unit 2 control room
ALLAN J H Region 1, Philadelphia, Office of the Director 79/04/09 5pp
- 790510055 Requests NRC staff members at TRS site provide summary rept of activities
GRIBB R H Region 1, Philadelphia, Office of the Director 79/04/09 1p
- 790510097 Describes new organizational arrangements for shift activities to improve IE coordination
GRIBB R H Region 1, Philadelphia, Office of the Director 79/04/09 2pp
- 790510081 Forwards 790409 planning meeting agenda & action items discussed in 790408 technical mtg meeting
STELLV V Division of Operating Reactors 79/04/09 20pp
- 790510082 Announces establishment of data reduction & mgt group responsible for collecting mgt re incident
LUNDH R L Metropolitan Edison Co 790510082 G OPU Service Corp 79/04/09 4pp
- 790510010 Forwards flow chart delineating procedure path to be followed by control group members & 790404 technical working group minutes
#00000000 Metropolitan Edison Co 79/04/09 4pp
- 790510028 Advises that NRC has decided to defer any determination of extraordinary nuclear emergency & should not consider pre-announced Act implications
CHILDS J D Office of the Secretary of the Commission 79/04/09 1p
- 790509045 Part 21 rept AECN website HP-831643 disc holder is Dairin Electric which can become inoperable if subjected to max. overvoltage conditions 35" butterfly valve may fail
BAUM R F Application Unknown 79/04/10 3pp
- 790510025 Discusses need for containing radioactive fent spillo at site since island is permeable Recommends leakage on 50m feeding & processing waste through demineralizers
MCHISTON B H Environmental Evaluation Branch 79/04/10 1p
- 790510145 Forwards rept on penetration availability for info Summarizes ability to monitor TRS reactor pressure & level using instruments outside containment.
HIRSTBLA F J Program Support Branch 79/04/10 4pp
- 790510193 Testimony of Dr Elsenbier before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works re TRS-2 incident
ELSENBIER D O Assistant Director for Systems & Projects 79/04/10 7pp
- 790510197 Testimony of Chairman Nordlie on 790410 before Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works re TRS incident IE Bulletin 79/05 & GSA mci
NORDLIE J H Commission 79/04/10 42pp
- 790510090 Forwards summary statement for vice president's trip-790410 testimony before Senator Hart's subcommittee & addl background mci.
NORDLIE J H Commission 79/04/10 3pp
- 790510056 Directs preparation of verbal containment conceptual design at TRS within five day-span in Boston request
MCHISTON B J Office of Nuclear Regulatory Research 79/04/10 1p
- 790510090 Describes telcon from JR Reed re chemical behavior of boric acid in primary coolant sys during incident Suggests research into behavior of boric acid under pressure.
MCHISTON B J Office of Nuclear Regulatory Research 79/04/10 1p
- 790510094 Submits delivery rept on caustic from 280 F to 150 F at 1,000 psi.
DAVIDS D Office of Nuclear Reactor Regulation. 79/04/10 20pp
- 790510058 Forwards questions & answers re containment liner & decontamination techniques steel covering over insulation & reactor cocants prepared 790403 for use by R Hingens
MCHISTON B J Transportation & Product Standards Branch 79/04/10 2pp
- 790510092 Forwards questions & answers as backup for 790410 Congressional hearing re TRS incident
* Office of Policy Evaluation 79/04/10 16pp
- 790510017A "Behavior of RBS w/Steam Generators in Condensing Mode"
* Infantry Advisory Group 79/04/10 4pp
- 790510026 Issues temporary Tech Spec mod re operability of reactor 350 emergency cooling booster pumps
VOLLMER R H Assistant Director for Site Analysis 79/04/10 1p
- 790510047 Submits temporary changes to Tech Specs re operability of reactor 350 emergency cooling booster pumps
VOLLMER R H Assistant Director for Site Analysis 79/04/10 1p
- 790510032 Forwards Westinghouse responses to NRC 790408 questions re resolution of TRS incident
NATTESS R Division of Systems Safety 79/04/10 3pp
- 790510038 Provides ground rules for conducting interview w/licenscees employees during TRS investigation
GRIBB R H Region 1, Philadelphia, Office of the Director 79/04/10 2pp
- 790510055 Announces RCB behavior in percolating mode before buildup of large amounts of noncondensibles
THIBBS J H Infantry Advisory Group 79/04/09 1p
- 790510047 Suppl 790409 memo re RCB behavior-stating percolation frequency articulated at 0.3 to 0.5
THIBBS J H Infantry Advisory Group 79/04/09 1p
- 790510080 Forwards mod criteria for use of steam generators for short & long-term coolant
CAPADONAS G S OPU Service Corp 79/04/10 16pp
- 790510035 Forwards 790410 planning meeting agenda, lists of action items discussed in 790309 technical review meeting & status of plant mode
STELLV V Division of Operating Reactors. 79/04/10. 22pp
- 790510056 Agenda for 790410 technical review meeting
* Office of Nuclear Reactor Regulation. 79/04/10 1p
- 790510094 Submits evaluation of General Public Utilis/Burns & Roe design for short- & long-term water solid steam generator operation
* Office of Nuclear Reactor Regulation. 79/04/10 7pp
- 790510097 Notes of 4 PH 790410 technical mgt meeting
* Office of Nuclear Reactor Regulation 79/04/10 2pp.
- 790510078 Forwards list of action items being carried out by Metropolitan Edison co. consultants. Requests prompt notification of progress
VOLLMER R H Assistant Director for Site Analysis 2pp
- 790510028 Forwards NRC lists of licensee's priority at TILFORD, J T Office of Nuclear Reactor Regulation
- 790510004 Submits status of "requests for work" to nat have been made since 790408. Forwards documentation of Lab work
BIXBY H W Commission 79/04/10 2pp
- 790510001 Submits brief synopsis of info furnished & personnel to NRC re TRS accident.
BRYDER A W Randco Laboratories 79/04/09 3pp
- 790510123 Assessment of pressurizer level instrumentat TRS-2
BATTERFIELD R H Electric Instrumentation & Contr Branch 79/04/11 8pp
- 790509045 Recommends that Commission host lunch for re US Nuclear Safety Commission investigating the activities of TRS-2 events
LAPLURE J D Office of International Programs 79/0

- 7903190132 Lists info requirements for in-plant data for inclusion in daily PMO
SMITH D H Office of Inspection & Enforcement 79/04/12 1p
- 7903190135 Lists requested replacements for JE Region 1 personnel at
THI-2 site
NEHRING R K Region 1, Philadelphia, Reactor Operations Nuclear
Report Branch 79/04/12 1p
- 7903190137 Guidelines to facilitate NRC info exchange w/DOE & other
agencies
GROSS J P Region 1, Philadelphia, Office of the Director
79/04/12 2pp
- 7903190206 Forwards safety analysis rept re proposed transition to
natural circulation as requested at NRC 790404 meeting
Lorenz natural circulation in violation for establishing
NRCSEIN J O Metropolitan Edison Co 79/04/12 1p
- 7903190240 Agenda of meeting re recovery from incident
Metropolitan Edison Co 79/04/12 15pp
- 7903190244 Catechistic, Inc can provide technical & field support
CAFFERTY D L Region 1, Philadelphia, Office of the Director
79/04/12 1p
- 7903190246 Forwards Insp Plan IP-3 for operating reactors in PA,
effective immediately
BURANDS C J Region 1, Philadelphia, Office of the Director
79/04/11 7pp
- 7903190248 Final version of testimony before Senate Subcommittee on
Nuclear Regulation re six main factors causing accident
Supporting recommendation and
HENDERIE J H Commission 79/04/10 16pp
- 7903190256 Recommends duty officer program for immediate notification
of incidents, effective 790412
SMITH D H Office of Inspection & Enforcement 79/04/12 2pp
- 7903190310 Forwards DOE illustrative mail re releases near plant site
STONER J P Region 1, Philadelphia, Office of the Director
79/04/12 7pp
- 7903190312 Requests review info to be gathered & picked up regularly
at JE command post re facilitating info exchange w/DOE &
other agencies
STONER J P Region 1, Philadelphia, Office of the Director
79/04/12 2pp
- 7903190314 Lists Metropolitan Edison Co & contractor exposures by
group to 790411
BLANDSSEN Region 1, Philadelphia, Office of the Director
79/04/12 1p
- 7903190358 Summarized meeting w/ETC for Disease Control & PA Dept of
Health re possible epidemiologic studies
COLBERT M R Rediological Health Standards Branch 79/04/12
2pp
- 7903190362 Forwards advisory on effect of loss of recombiner operation
on hydrogen concentration in containment, due to 790413
failure of Atomic Intl recombiner heater assembly
HARRIS F J Office of Nuclear Reactor Regulation 79/04/12 7pp
- 7903190399 Forwards preliminary evaluations & bases of sodium
analysis for TH2 covering core melt penetration, hydrogen
generation & potential for explosion
HARRIS F J, LONG J, GIBBS T Advanced Reactors Branch
79/04/12 1p
- 7903190406 Forwards list of TH2 related followup actions currently
underway or planned in response to LU Serial 790412 memo
HENDERIE J H Office of Standards Development 79/04/12 2pp
- 7903190408 Discusses how transcript of NRC meetings held 790503, 79, 10 &
13 re THI-2 incident will be made available
GIBBS T L Office of the General Counsel 79/04/12 4pp
- 7903190424 Summary of 790412 meeting w/Bucks County River Basin
Commission to discuss TH2 threat, 8 ci of 1-131 discharged to
river, increased water monitoring program & NRC rule re
water quality during TH2 clean-up
ELANDS D T C Office of Risk Management 79/04/12 2pp
- 7903190530 Forwards list of useful electrical instrumentation & control
equipment
LARNAG D Plant Systems Branch 79/04/12 2pp
- 7903190533 Forwards NRC advisory by RD Meyer recommending all inciner
thermocouples be read in continuous manner w/provisions for
rapid retrieval & permanent storage
LARNAG D Plant Systems Branch 79/04/12 2pp
- 7903190535 Lists Division actions re TH2 w/essential personnel
title of action & estimate completion dates
Office of Nuclear Regulatory Research 79/04/12 4pp
- 7903190540 Lists JE personnel who are on duty at THI
HENDERIE J P Region 1, Philadelphia, Office of the Director
79/04/12 2pp
- 7903190543 Forwards interoffice memo dated by NRC re radioactive
sample analysis, alternative method to measure steam generator
level & modified criteria for use of steam generators for
cooldown
SMITH D H - GPU Service Corp 79/04/12 2pp
- 7903190544 Recommends procedures re utility effluent monitoring
STONER J P Region 1, Philadelphia, Office of the Director
79/04/12 2pp
- 7903190546 Discusses nondestructive examinations of weld joints
Requests resolution of inconsistencies on data sheets &
recommendations for utility taking credit for loss
STONER J P Metropolitan Edison Co 79/04/12 2pp
- 7903190549 Summary of 790412 meeting w/Bucks County River Basin
Commission re TH2 incident
ELANDS D T C Region 1, Philadelphia, Office of the Director
79/04/12 2pp
- 7903190550 Summary of 790413 meeting re plan TH-3 strategy
Office of Nuclear Reactor Regulation 79/04/12 4pp
- 7903190561 Forwards list of electrical instrumentation & control
equipment w/enclosure
LARNAG D C Office of Inspection & Enforcement 79/04/12 1p
- 7903190567 Forwards summary of Metropolitan Edison Co & contractor
personnel on 790414
BLANDSSEN J O Region 1, Philadelphia, Office of the Director
79/04/14 1p
- 7903190571 Comments on Task 1 qualifications of vent header sys
190413/14 of note re tank qual.
LARNAG D C ACRS - Advisory Committee on Reactor Safeguards
79/04/14 1p
- 7903190579 Preliminary Estimates of Population on Dose & Health
Effects
BATTIST L, BUCHANAN J, CONSOLE P Division of Site Safety &
Environmental Analysis 79/04/15 70pp
- 7903190587 Ad hoc interagency dose assessment group preliminary
estimate of population dose & health effects re TH2
events
BATTIST L, BUCHANAN J, CONSOLE P Division of Site Safety &
Environmental Analysis 79/04/15 80pp
- 7903190588 Forwards TH2/General Public Units Data Reduction & Mgt Group
Status Report 1, includes info re temp & environ readings
METZGER J L GPU Service Corp 79/04/12 2pp
- 7903190589 Agenda of 790415 technical group meeting w/Metropolitan
Edison
Commission 79/04/15 2pp
- 7903190606 Conceptual design for TH2-2 venting Supercodes previous
versions
BLANDSSEN D Office of Nuclear Regulatory Research 79/04/15 2pp
- 7903190610 Requests clearance for JE Collins to drive to processing
site
DELMORE R H Assistant Director for Site Analysis 79/04/15 1p
- 7903190648 Forwards preliminary sequence of events for first 20-h
following accident on 790412
HENDERIE J O Metropolitan Edison Co 79/04/16 16pp
- 7903190650 Forwards requested telephone log & states no significant
contacts made on 790401
BLANDSSEN D Office of State Programs 79/04/16 2pp

DOCKETED ITEMS

- 7903000258 Forwards request for info re involvement in NRC activities relating to the Karpis period from 790309-0401
BROOKHOLM, T. F. Office of the Executive Legal Director 79/04/16 1p
- 7903000260 Request that all personnel engaged in NRC responses to the accident record their actions on paper
GOSBICK, L. V. Office of the Executive Director for Operations 79/04/13 1p
- 7903010151 Forwards compilation of analysis of 790329 & 0410 primary coolant samples
HARRIS, J. P. J. Office of Nuclear Reactor Regulation 79/04/16 4pp
- 7903010330 Summarizes Branch recommendations for addl operational safety research based on preliminary review of the incident
SCHNEITZ, D. L. Research Support Branch 79/04/16 1pp
- 7903010151 Requests actions in response to ACSB TMI report should be provided to get direct water level reading in reactor core
ARMSTRONG, J. P. Commission 79/04/19 2pp
- 7903010152 Requests comments on Axel J. Vailin 790402 letter re the incident
KORWITZ, R. T. Commission 79/04/19 1p
- 7903010159 Requests that ground dose measurements/steped composition & time pattern of activity released from plant & number of exposed workers be recorded for later analysis
WALLACE, J. R. Research Support Branch 79/04/16 1p
- 7903010412 Requests chronology of arrival times of Federal & state representatives at site; copy of Interagency Radiological Assessment Plan & NRC regulations re emergency planning
KORWITZ, R. T. Commission 79/04/19 1p
- 7903010124 Confirms 790409 letter re willingness to attend TMI related meeting
TILLEY, H. C. London Nuclear Decommissioning Ltd. 79/04/16 1p
- 7903010328 Tank car lease agreement between Union Tank Car Co. & General Public Utility
GPU Service Corp. 79/04/16 1pp
- 7903030123 Summarizes NRC comments on acceptability of design criteria for new nuclear electrical power and design criteria for new non-nuclear generators & use of 10 S IV condenser power source is acceptable
STOLLOV, V. Division of Operating Reactors 79/04/16 2pp
- 7903030129 Requests retention of DM Paters & DL Barstow as drivers until 790401
STOLLOV, V. Division of Operating Reactors 79/04/16 1p
- 7903030281 Requests updated status of various proposals for achieving cold shutdown
MORAN, T. H. Office of Nuclear Reactor Regulation 79/04/16 4pp
- 7903030287 Provides summary of QA practices associated w/ facility water returned to dome
GILMAN, J. Quality Assurance Branch. 79/04/16 1pp
- 7903030106 Forwards inventory of current TMI-2 related actions
GOSBICK, L. V. Office of the Executive Director for Operations 79/04/16 1p
- 7903030105 Forwards inventory of current TMI-2 related actions
GOSBICK, L. V. Office of the Executive Director for Operations 79/04/16 1pp
- 7903030111 Responds to LV Gosick 790412 memo re listing current TMI related actions
BIRCH, J. R. Office of International Programs 79/04/13 1pp
- 7903030118 Details personnel actions re the incident
BIRCH, J. R. Office of Administration. 79/04/13 1pp
- 7903030156 Forwards info requested in 790412 memo re personnel in div of contracts who will review & list all procurement actions resulting from the incident
HARRIS, J. P. J. Division of Contracts 79/04/13 1pp
- 7903030162 Responds to 790412 memo listing personnel from GPC of Administration involved in communications at TMI-2 site
WALLACE, J. R. Division of Facilities & Operations. 79/04/13 1pp
- 7903030171 Responds to 790412 memo listing current div projects re the incident
BIRCH, J. R. Technical Information & Document Control. 79/04/16 1pp
- 7903030114 Ack receipt of 790412 memo & accompanying proposal re NRC contract & control center to improve communications system for dealing w/ events similar to the degraded communications system will be considered
HARRIS, J. P. J. Commission 79/04/17 1p
- 7903030171 Forwards proposal for NRC contract & control center for nuclear reactors & transport of BBN
HARRIS, J. P. J. Radiological Health Standards Branch 79/04/17 1pp
- 7903030113 Proposes study of feasibility of NRC contract & control center for nuclear reactors & transportation of BBN
HARRIS, J. P. J. Radiological Health Standards Branch. 79/04/17 1pp
- 7903030322 Forwards 790329 & 790409 suggestions by E. Petrol re computer controlled communications link & legislative authority to prosecute for Federal Request 90-day review period
GOSBICK, L. V. Office of the Executive Director for Operations & Analysis 79/04/16 1p
- 7903030324 Suggests that NRC holder effectiveness can be using legislative authority to prosecute individuals who are personally responsible for various NRC violations
HARRIS, J. P. J. Radiological Health Standards Branch 79/04/17 1p
- 7903030345 Discusses Bessie Lab study of controllability of reduced core debris high safety accident safety for cooling the core at atmospheric pressure by heating debris natural convection
WILSON, R. H. Experimental Fast Reactor Safety Research Branch 79/04/17 1pp
- 7903030114 Requests further info re GPC of Nuclear Reactor Regulation action re the incident
HARRIS, J. P. J. Commission. 79/04/17 1p
- 7903030329 Forwards 790409 letter from S. Bessie of AEP re background articles used in attempt to put TMI in perspective
BIRCH, J. R. Assistant Director for Materials Safety Branch 79/04/17 1p
- 7903030345 Authorizes NRC to ship breathing air manifolds & 350 cubic ft gas mixture compressor/womanifolds & air suit bags
NRC will be reimbursed all reasonable expenses
HARRIS, J. P. J. GPU Service Corp. 79/04/17 1p
- 7903030345 Authorizes NRC to ship three charcoal filters from TMI-2 to Columbia, OH NRC will be reimbursed reasonable costs
HARRIS, J. P. J. GPU Service Corp. 79/04/17 1p
- 7903030345 Authorizes shipment of three charcoal filters from TMI-2 to Columbia, OH
HARRIS, J. P. J. GPU Service Corp. 79/04/17 1p
- 7903030101 Forwards TMI/General Public Utility Data Reduction Report
Bessie Report 3 info includes reactor & reactor hole temp & pressure 790403-0416
HARRIS, J. P. J. GPU Service Corp. 79/04/17 1pp
- 7903030345 Forwards summary report on gas analyses performed on the primary water sample received 790416
HARRIS, J. P. J. Allied Chemical Corp. 79/04/17 1pp
- 7903030345 Describes Test II system monitoring of core exit flow group of detectors provide info re core conditions
Stokes monitor sources & location
HARRIS, J. P. J. Special Instrument Group 79/04/17 1pp
- 7903030345 Requests that Mission pass TMI-related info to NRC official contacts
LAFORCE, J. D. Office of International Programs. 79/04/17 1p
- 7903030345 Discusses sequence of events to be followed if reactor coolant pump 2A fails in forward operations support plants.
HARRIS, J. P. J. HARRIS, J. P. J. GPU Service Corp. 79/04/17 1pp
- 7903030345 Summary of 790412 visit to Susquehanna River Islands Re-lease mill & glass samples. No evidence of recent cement or activity
HARRIS, J. P. J. HARRIS, J. P. J. Region 5, Philadelphia. Office of the Director. 79/04/18 1p

DOCKETED ITEMS

123

- 7905030017 Forwards recommendations re handling FOIA requests for documents on THO-2 Requests concerns & occurrences by
790419
GREGORY, L. Office of the General Counsel 79/04/19 3pp
- 7905030041 Responds to 790417 memo re need to apply special measures for transportation of radioactive wastes from THO-2 site for disposal. Requests to be kept informed of shipments
BUSEMPT, R. P. Division of Safeguards 79/04/19 1p
- 7905030051 Summary of 790419 meeting w/TH Turpin et al re response to re preparing for Secretary Callahan re recent issues released at THO & nature of final cleanup efforts
GREGORY, M. Assistant Director for Engineers & Projects 79/04/19 1p
- 7905030057 Forwards requested questions re loss of main coolant pump, RHR heat exchanger, operation of air conditioning power & loss of pressurizer vent capability
HARRIS, J. A. Office of Nuclear Regulatory Research 79/04/19 3pp
- 7905030058 Forwards RH Power & Light answers to effectiveness of adding hydrogen to primary gas to scavenge oxygen since there is indication of dissolved oxygen in primary coolant
HARRIS, J. A. Division of Systems Safety 79/04/19 2pp
- 7905030073 Forwards analysis results of boron measurements from 790411 primary gas sample (nonpressurized)
TILPSON, J. Division of Operating Reactors 79/04/19 3pp
- 7905030075 Review & evaluation of personnel desisting data from 790328-0405
GREGORY, M. J. Region 1, Philadelphia: Office of the Director 79/04/19 3pp
- 7905030078 Forwards list of people to be interviewed, list of procedures to be certified, list of requested documents & list of add'l procedures in effect on 790328
HARRIS, J. A. Division of Systems Safety 79/04/19 11pp
- 7905030084 Change designation of new diesel generator to "gray" in accident confinement analysis. Is also div
GREGORY, M. J. CPU Service Corp 79/04/19, 1p
- 7905030085 Technical support procedures group has developed variation on method to predict pressurizer level from indicated temp. Recommendations procedure be initiated
HARRIS, J. A. CPU Service Corp 79/04/19 1p
- 7905030089 Discusses analyses of boron measurements from 790411 nonpressurized primary gas sample
TILPSON, J. T. Office of Nuclear Reactor Regulation 79/04/19 3pp
- 7905030445 Concerns re cleanup of auxiliary bldg & containment
LAWRENCE, M. ACRS - Advisory Committee on Reactor Safeguards 79/04/19, 1p
- 7905030457 Discusses current status of safety-related operator action study
HARRIS, J. L. Reactor Systems Standards Branch 79/04/19 3pp
- 7905030458 Draft re: "Safety-Related Operator Action."
BETTER, P. HARRIS, M. Oak Ridge National Laboratory FIN 8-0425
GREGORY, M. J. 79/04/19, 11pp.
- 7905030510 Responds to LV General 790423 request for record of actions on THO accident. Summarizes 790420-0424 discussions re reactor coolant pump & containment integrity
HARRIS, J. E. C. Reactor Systems Standards Branch 79/04/20, 1p
- 7905030519 Forwards copies on Categories A & B rap guides being prepared for inclusion as result of THO-2 event data
EHRHARDT, A. L. Division of Engineering Standards 79/04/20, 12pp.
- 7905030521 Summary of 790412 meeting w/PA State Health Dept in Harrisburg, PA re strategy for evaluating health impact of THO incident
GREGORY, M. J. Radiological Health Standards Branch 79/04/20 3pp.
- 7905030523 Responds to 790420 request for names of candidates for THO Internal team to investigate accident. Suggests H. Collins, R. Davis, W. Kerr, S. Schwartz
RYAN, B. J. Office of Nuclear Regulatory Research 79/04/20, 1p
- 7905030524 Forwards requested info prepared by R. Ench & P. Abelskiwicz showing dose rate from 12-inch N68 pipe containing primary coolant.
HARRIS, J. A. P. Office of Nuclear Reactor Regulation 79/04/20 3pp.
- 7905030534 Forwards Bendix Lab rept on calculations of controllability of published THO core debris
HARRIS, M. W. Experimental Fast Reactor Safety Research Branch 79/04/20 3pp
- 7905030537 Forwards rept "Cooling of THO Core Debris" *
RYAN, B. J. B. Bendix Laboratories 79/04/19 1p
- 7905030540 "Cooling of THO Core Debris" *
* Bendix Laboratories 79/04/19 3pp
- 7905030579 Suggests improvements in way of communications for emergency response situations & need for public radiation monitoring units available to each site. Requests rept
RYAN, B. J. T. Commission 79/04/20 1p
- 7905030588 Requests info re THO including license conditions re fixed levels, status of spent fuel pools & whether any add'l plants are planned for area
HARRIS, J. F. Commission 79/04/20 1p
- 7905030617 Forwards info from Logistics Management Institute offering to discuss maint procedures to help NRC establish procedures for nuclear power plants
HARRIS, J. F. Commission 79/04/20 1p
- 7905030635 Updates R. Bell's 790417 memo detailing rationale for high counting rate of B-P-G neutron detecting starter channel
BELL, G. V. Division of Operating Reactors 79/04/20 10pp
- 7905030641 Details synopsis of aircon analyses performed since 790418
ALLIANT, J. B. For 8-035
GREGORY, M. J. Office of Inspection & Enforcement 79/04/20 3pp
- 7905030649 Requests update of JS. Cassell, Dr. Hunter, SC. Kirkpatrick, T. Staudt, R. Somers, P. Bissett to list for EE per Amend 3 to NRC access list dtd 790413
HARRIS, J. A. Region 1, Philadelphia: Office of the Director 79/04/20 2pp
- 7905030649 Clarifies that Ofc of Executive Legal Director THO documents w/related info must be transmitted to FOIA officer per encl. Announcement
HARRIS, J. A. Administrative Branch 79/04/20 1p
- 7905030649 Announcement 3P re preservation of records re THO incident. Forwards list of FOIA coordinators
FELTON, J. B. Division of Rules and Records 79/04/20 3pp
- 7905030689 Forwards list of Region 1 personnel dispatched to site from 790328-0405
HARRIS, J. A. Division of Systems Safety 79/04/20 3pp
- 7905030691 Forwards "Criteria for Loss of Offsite Balance of Plant Electrical Power"
GREGORY, M. J. CPU Service Corp 79/04/21 1p
- 7905030691 "Criteria for Loss of Offsite Balance of Plant Electrical Power" *
CPU Service Corp 79/04/22 3pp
- 7905030718 Lists 12 personnel to be added to NRC Access List dtd 790413
HARRIS, J. A. Region 1, Philadelphia: Office of the Director 79/04/20 1p

- 7905290270 Discusses L. Kovach's recommendations to carbon adsorbents in auxiliary bldg traps should be removed from site and cleaned of carbon
COLLINS, J. T. Off/Env't Treatment System Branch 79/04/22 1p
- 7905290603 Synopsis of info obtained re operating history of TMI-2 info re inventories of significant fission products expected in core will be collected. Plans of decontamination made where feasible
NEILL, D. D. Transportation & Product Standards Branch 79/04/22 2pp
- 7905290624 Comments on Commissioner Abrams's 790403 "test of thoughts on how we could possibly go about TMI accident review"
Review must distinguish what's what happened
HODGINS, H. Office of Management and Program Analysis 79/04/22 1p
- 7905290625 "Testimony of R. Moore & L. Abramson"
HODGINS, R. & ABRAMSON, L. Office of Management and Program Analysis 78/11/20 1pp
- 7905290626 Supplemental Testimony of R. Moore & L. Abramson in response to ACR-925
HODGINS, R. Office of Management and Program Analysis 79/02/16 1pp
- 790510026 Act receipt of 790413 offer to serve on safety review panel. Offer will be considered
HODGINS, J. H. Commission 79/04/22 1p
- 790510022 Offers to serve on review committees re TMI
HODGINS, C. J. Affiliation Unknown 79/04/22 1p
- 790510024 Testimony before Subcommittee on Nuclear Regulation of Senate Committee on Environment & Public Works re TMI-2 incident
O'BRIEN, M. General Public Utilities 79/04/22 2pp
- 790510048 Suggests Nuclear Regulatory Research staff members to serve on TMI incident investigation
LEVINE, R. Office of Nuclear Regulatory Research 79/04/22 1p
- 790510022 Handwritten notes re TMI incident for period 790404-0425
CUMMINGS, R. Probabilistic Analysis Branch 79/04/22 2pp
- 790510033 Responds to 790426 memo requesting comments re environ qualification & instrumentation to follow course of an accident
MILLER, C. F. Electric, Instrumentation & Control Systems Branch 79/04/23 2pp
- 7905140034 Observations made at meeting of Senate Subcommittee on Nuclear Regulation Committee on Environment & Public Works concerning TMI accident
JOHNSON, D. H. Office of the Secretary of the Commission 79/04/22 1pp
- 7905140036 Forwards prepared testimony given at hearing before 790423 Senate Subcommittee on Nuclear Regulation. W/te testimony
KARNHEIMER, C. Office of Congressional Affairs 79/04/22 2pp
- 7905140018 Details actions taken in response to RJ Seditz 790410 memo to file re vented containment conceptual design at TMI
BIDALVO, R. Office of Nuclear Regulatory Research 79/04/22 7pp
- 7905140148 Requests info re min requirements for control room manning by licensed reactor operators & advantages & disadvantages of presence of third operator
KARNHEIMER, R. T. Commission 79/04/22 1p
- 7905290506 Forwards Revision D of "Reactor Control Pressure Control Sys Design Criteria-Backup Partition," dtd 790420
CRONENBERG, G. CPU Service Corp 79/04/22 1p
- 7905290618 Test dtd "Reactor Control Pressure Control Sys Design Criteria-Backup Partition," Revision D
SMITH, L. L. T. CPU Service Corp 79/04/22, 1pp.
- 7905290623 Lists members of newly formed Natural Circulation Initiation Task Force
MILLER, R. C. CPU Service Corp 79/04/22 3p.
- 7905290717 Forwards draft of work statement for contract to review Federal Agency Interactions
MORRIS, C. Office of Inspection & Enforcement 79/04/22 4pp
- 7905290424 Requests that TMI Bulletin & NRC plans for future info dissemination be forwarded to NRC official contacts.
LUTHE, J. E. Office of International Programs 79/04/22, 2pp.
- 7905290005 Forwards H. Mazette's comments on review of Emergency Procedure 3
HARRIS, L. P. J. Office of Nuclear Reactor Regulation 79/04/24 2p
- 7905100518 Telex summary describes valve misalignment at TMI during change of feedwater flow from main to auxiliary sys
BROWN, B. Office of Inspection & Enforcement 79/04/24 1p
- 7905140131 Forwards rough estimate of initial source term that was potentially available in auxiliary bldg for release to atmosphere
SLONCH, B. Office of Nuclear Regulatory Research 79/04/24 3pp
- 7905290260 Rehears evaluation re sys analysis of filling & operation-through steam generator 3 water valve
B. Office of Inspection & Enforcement 79/04/24 3pp
- 7905100041 Requests info re site related activities from 790426
MORRIS, A. Region 5, Philadelphia, Office of the Director 79/04/24 3pp
- 7905290501 Savannah River life support air sys will be used by site personnel
HODGINS, J. D. CPU Service Corp 79/04/24 1p
- 7905290505 Outlines priorities & procedures for waste disposal w/ environmental chart & list of responsibilities w/it
BUSH, G. E. & ARNOLD, D. R. C. CPU Service Corp HERRIN, J. D. Natraction Edison Co 79/04/24 2pp
- 7905290004 Forwards revised criteria for use in designing plant made to use A & B steam generators as high pressure water to water heat exchangers for deep heat removal
SARFEDMAN, D. CPU Service Corp 79/04/24 2pp
- 7905290207 "TMI-2 Sys Criteria for Use of Steam Generator A to Air & Loop-Tank Condenser," Revision 3
B. CPU Service Corp 79/04/24 11pp
- 7905290208 "TMI-2 Sys Criteria for Use of Steam Generator B to Condenser at High Pressure," Revision 3
B. CPU Service Corp 79/04/24 2pp
- 7905290204 Details recapitulation of waste mgmt activities
MORRIS, J. & HODGINS, J. D. & ARNOLD, D. R. C. CPU Service Corp 79/04/24 1pp
- 7905290212 Discusses efficient & process gas monitoring sys & nitrogen air monitor
BUSH, G. E. P. Division of Site Safety & Environmental Analysis 79/04/24 2pp
- 7905290172 Reports that main turbine was manually tripped when water was heard in steam line around turbine control valves
OLSHANSKY, J. Division of Systems Safety 79/04/24 1p
- 7905290170 Unrelated memo of understanding re exchange review info & data between NRC, EPA, & DOE. Forwards meeting notes for 790423-25
STULL, V. Division of Operating Reactors COX, S. Health, Education & Welfare, Dept of BETHENHAUSEN, E. Environmental Protection Agency 79/04/24 4pp
- 7905290276 Forwards comments on sys analysis of filling and emptying steam-through steam generator & water solid Secondary side should be filled slowly to avoid water hammer
MORRIS, T. H. Office of Nuclear Reactor Regulation 79/04/24 3pp
- 7905290247 Discusses security assistance for NRC press site in Hildesheim, Germany
BUSH, C. L. Division of Security 79/04/24 2pp
- 7905102119 Questions for Commission 790423 meeting re BWR plants & Commission 79/04/23 2pp
- 7905100253 Forwards correspondence summarizing evaluation of hydrogen gas in primary coolant sys & containment bldg atmosphere
RIS, L. M. Assistant Director for Advanced Reactor Safety Research 79/04/23 2pp
- 7905100257 Forwards table summarizing calculation of hydrogen gas at several pressures & temp conditions corresponding to w/it condensation pressure reduction & rapid depressurization
RIS, L. M. Assistant Director for Advanced Reactor Safety Research 79/04/23 2pp
- 7905100258 Presents results of parametric appraisal of hydrogen solubility data base & estimates hydrogen release to TMI
PETERSON, L. H. Fuel Elements & Reactor Branch 79/04/23 2pp

DOCKETED ITEMS

125

- 790510028 Discusses upper limit estimates of hydrogen formation via circumferential reaction & from radiolysis
LABINS, J. T. Experimental Reactor Safety Research Branch 79/04/11 2pp
- 790510029 Discusses need for thorough review of radiation & physical chemistry of LWR primary coolant suggest formation of test facility & review of SRS & DOE
METT, F. J. Fuel Process Systems Standards Branch 79/04/23 4pp
- 790510030 Summarizes info on hydrogen reduction methods
BIB, J. H. Assistant Director for Advanced Reactor Safety Research 79/04/23 3pp
- 790510040 Provides preliminary assessment of core damage at TH1
Pursuant to discussion calculations by NRC & others to determine extent of damage
HARRIS, D. P. Fuel Behavior Branch 79/04/28 22pp
- 790510040 Discusses GRASS-BUT calculations for TH1 to explain release of 20-400 total core inventory of fission gas
BENT, J. Argonne National Laboratory 79/04/16 2pp
- 790510050 Discusses new steady-state clad temp reached to TH1 after voiding any means of ensuring moderate flow or steam should have prevented serious rod damage
HARRIS, D. P. Fuel Behavior Branch 79/04/04 4pp
- 790510060 Discusses preliminary calculations for outside limits of possible core damage between 23-25% core damage near air to upper limit at J O hours transient
BECNER, Division of Reactor Safety Research 79/04/06 2pp
- 790510067 Notifies NRC Investigative Team in writing & available for private meeting by appointment
HARRIS, D. P. Region 2, Chicago, Office of the Director 79/04/23 2pp
- 790510089 Recommends actions to be taken in case of water delays due to conflict of and operating procedures
MULLER, T. J. Metropolitan Edison Co 79/04/23 2pp
- 790510094 Summary of 790505 meeting w/DOE re future support of NRC operations at site
BIB, J. H. Region 1, Philadelphia, Office of the Director 79/04/23 1p
- 790510098 Forwards list of communications equipment sent to TH1 that cannot be properly accounted for suggests identification of contents of properly stored gear or delay at Trailer City
JONES, J. G. Telecommunications Branch 79/04/23 3pp
- 790510099 In response to 790419 memo forwards assessment of impact of TH1-2 on eff. resources
BIB, J. H. Office of State Programs 79/04/26 4pp
- 790510075 Documents supply of emergency instrumentation at TH1 site to collect air samples & measure radioactivity
BARNES, P. Environmental Effects Research Branch 79/04/26 2pp
- 790510084 Provides prepared notes on supply to LV Gaseous 790420 memo re actions re TH1
DAVIDSON, E. Office of Nuclear Regulatory Research 79/04/26 4pp
- 790510093 Discusses 790323-0408 actions while part of NRC team at TH1
Duties involved review of handling of accident & radioactive gathering of info re plant age status from logs & personnel
BELL, M. J. Assistant Director for Waste Management (Ops 790505) 79/04/26 4pp
- 790510098 Forwards record of actions involving NRC staff which are not logged in Incident Response Card
BARNES, P. Office of Nuclear Material Safety & Safeguards 79/04/26 1p
- 790510097 Comments on report on hydrogen solubility database & estimated hydrogen releases at TH1
PERRON, B. N. Fuel Process & Analysis Branch 79/04/11 3pp
- 790510098 Discusses actions of group working on radioactive gas at TH1
Current procedures for handling of radioactive material generated by accident are under review
BELL, M. J. Low Level Waste Branch (Ops 790505) 79/05/10 1p
- 790510098 Report of activities on 790509 at site, initial assignment
COLLINS, D. M. Region 2, Atlanta, Office of the Director 79/04/26 2pp
- 7905100108 Responds to questions of C. K. Kephart re radiation releases at TH1
His info substantiating claim of 0.5 mCi/min/hour 30 min period from TH1 TLDs have been limited but call for sensitivity to beta radiation
BETH, D. H. Region 1, Philadelphia, Office of the Director 79/04/26 3pp
- 7905100273 Discusses Branch actions associated w/TH1 accident
COLBURN, D. C. Systems Performance Branch 79/04/27 1p
- 7905100412 Discusses health physics coverage for transition to normal circulation, both efforts to advise
BIB, J. H. Office of Inspection & Enforcement 79/04/27 1p
- 7905100500 Recommends procedure for helping NRC employees
BIB, J. H. Office of Inspection & Enforcement 79/04/28 4pp
- 7905100450 Provides data re system component & instrument operability status
WILBERT, H. Office of Inspection & Enforcement 79/04/28 2pp
- 7905100273 Forwards Revision 1 of procedure for helping NRC employees
BIB, J. H. Region 1, Philadelphia, Office of the Director 79/04/26 4pp
- 7905100516 Forwards liquid discharge data for 790410-25
BIB, J. H. Office of Inspection & Enforcement 79/04/29 2pp
- 7905100522 Forwards info re system component operability status
BIB, J. H. Assistant Director for Engineers & Projects 79/04/29 1pp
- 7905100279 "Generic Considerations of TH1-2 Incident"
* Office of Nuclear Reactor Regulation 79/04/30 3pp
- 7905100319 Input for items needed for requalification of TH1 discusses decontamination, imp of primary coolant gas & type of water chemistry
BARNES, P. J. Office of Nuclear Regulatory Research 79/04/26 4pp
- 7905100501 Suggests proposed Westinghouse decay heat removal system design to modified to better prevent any leakage Flanged connections should be welded & sealed pumps should be used
* Office of Nuclear Reactor Regulation 79/04/30 3pp
- 7905100508 Summary of reactor decontamination study
* Commission 79/04/30 4pp
- 7905100299 Transition of IE in-house health effort to normal regulatory position
BIB, J. H. Office of Inspection & Enforcement 79/04/30 2pp
- 7905100510 Chart of review committee responsibilities
* CPU Service Corp 79/04/30 1p
- 7905100507 Forwards results of analysis of model liquid discharge data
FENSTER, D. Science Applications, Inc 79/04/30 13pp
- 7905100513 Informs that Joint Chiefs of Staff assigned outline "Every Purpose" to operations to support of TH1 incident
BIB, J. H. Office of the Executive Director for Operations 79/05/01 1p
- 7905100527 Forwards "Preliminary Licensing Regt for Westinghouse Decay Heat Removal Sys" Final regt will follow
BERNARD, J. G. Metropolitan Edison Co 79/05/01 1p
- 7905100527 "Preliminary Licensing Regt for Westinghouse Decay Heat Removal Sys"
* Westinghouse Electric Corp, WP-TH1-003, 79/05/01 2pp
- 7905100118 Agenda for 790420-0501 planning meetings
* Office of Nuclear Reactor Regulation 79/05/01 10pp
- 7905100522 Discusses help for 3-day period following TH1-2 incident
BARNES, P. N. Region 5, San Francisco, Office of the Director 79/05/01 1p
- 7905100513 Discusses plans for epidemiology followup studies on populations exposed during TH1-2 event Contractor will be selected soon
BIB, J. H. Office of Standards Development 79/05/08 2pp

DOCKETED ITEMS

- 7905040302 Notifies that submission of final report re Impingement/entrainment monitoring program at TH1 will be delayed re
790515
HOLMES, J. P. & THOMPSON, G. J. Metropolitan Edison Co. 79/05/03 1p
- 7905140002 Summarizes 790325 letter from C. Heath of Ctr for Disease Control re air's role in responding to the incident. Forwards summary of subsequent action with SCILAR
ROBERTS, I. C. Assistant Director for Site Analysis 79/05/03 1p
- 7905050003 Details agenda of Natl Conference of State Legislatures, Energy & Resources Committee's 790517 presentation to Congress re TH1
SCHMARTZ, S. A. Office of State Programs 79/05/04 1p
- 7905140007 Forwarded analysis results for sample of primary coolant water from TH1
COURTNEY, R. F. E. I. du Pont de Nemours & Co., Inc. 79/05/07 3pp
- 7905050070 FR notice of ACRS 790510-12 meeting in Washington, DC to discuss reports on TH1 accident
CHILKIN, J. Office of the Secretary of the Commission 79/05/07 3pp
- 79050500234 Proposed temporary freeze on any new CP or GL assessment of ongoing control projects. Forwards draft instructions from EJ Chalk to IR Section
HAGSTED, J. H. Commission 79/05/08 3pp
- 7905110277 "Fictitious Representation of Reactor Scaled Relief Valve Venting Test from TH1 Conditions"
Office of Nuclear Regulatory Research 79/05/10 3pp
- 7905140002 Plant computer print-out for 790320
Probabilistic Analysis Branch 79/05/10 10pp
- 7905140000 Miscellaneous notes on various Commission meetings
GIBSON, T. R. Commission 79/05/10 13pp
- 7905140007 Miscellaneous notes on TH1
CARPISSE, L. M. Commission 79/05/10 34pp
- 7905160042 Various sheets for updating Mar 1978 Yellow Book
Commission 79/05/10 33pp
- 7905160049 Commission meeting notes for 790328-31
GIBSON, T. R. Commission 79/05/10 27pp
- 7905160051 Various sheets for updating Feb 1978 Gray Book to Feb 1979
Commission 79/05/10 23pp
- 7905050030 "Population Base & Health Impact of Accident at TH1 Nuclear Reactor"
BATTIST, L., BUCHANAN, J., CONLEY, P. Commission NUREG-0380 79/05/10 104pp
- 7905160064 Lists info required re Battelle Columbus Lab analysis
COMMISSIONER, M. Probabilistic Analysis Branch 79/05/11 1p
- 7905160039 Discusses definition of TH1-2 event in nonconformities of NUREG-1403
COMMISSIONER, M. Probabilistic Analysis Branch 79/05/11 1p
- 7905160043 Questions natural circulation if main coolant pumps are lost
Probabilistic Analysis Branch 79/05/11 1p
- 7905160149 Draft chronology of 790320 accident until core cooling restored
Probabilistic Analysis Branch 79/05/11 3pp
- 7905200430 Forwards report "Radioactivity Potential of TH1-2 Core"
HAGSTED, J. H. Transportation Branch 79/05/14 1p
- 7905200424 "Radioactivity Potential of TH1-2 Core."
HAGSTED, J. H. Transportation Branch 79/05/14 2pp
- 7905160081 Comments on Special Operation Procedure 2-37.
Office of Nuclear Reactor Regulation 79/05/22 1p
- 7905200018 Amends Tech Spec to permit channel calibrator currently required to be performed by 790420 to be extended up to 14 days following cold shutdown.
VOLLMER, R. H. Assistant Director for Site Analysis 79/05/17 1p
- 7905210049 Clarifies organizational responsibility in control room, re health physics & effluent age
Office of Nuclear Reactor Regulation 79/05/17 1p
- 7905210032 Requests assistance in locating documents re TH1-2 incident for accurate reproduction. Related manual page & sample documents which may be discarded sent for guidance
GRIER, D. H. Region 1, Philadelphia, Office of the Director 79/05/17 3pp
- 7905200197 Discusses radiological consequences of operation of once-through steam generator B in solid mode
COLLINS, J. T. Effluent Treatment Systems Branch 79/05/17 1p
- 7905160148 Procedures for environ shift leaders re preparation of daily RWD
GRIER, D. H. Office of Inspection & Enforcement 79/05/18 1p
- 7905200170 Procedures for environ shift leaders re daily TIB data
GRIER, D. H. Office of Inspection & Enforcement 79/05/18 1p
- 7905200030 Discusses radiological assessment of operation of once-through steam generator B in solid mode. Comments on radiative heat inventory, leakage paths & effluents
COLLINS, J. T. Effluent Treatment Systems Branch 79/05/22 1p
- 7905210076 Discusses restrictions on use of waste w/canisters from decontamination of auxiliary fuel bldg
Office of Inspection & Enforcement 79/05/18 1p
- 7905260034 Requests info re incident investigation
GRIER, D. H. Region 1, Philadelphia, Office of the Director 79/05/18 3pp
- 7905200130 Notifies of amend to Tech Spec 4.3.2.4 adding 14 days to 790420 deadline for performance of channel calibrator
VOLLMER, R. H. Assistant Director for Site Analysis 79/05/18 1p
- 7905200028 Results of analysis of Ag canister cartridges from third mobile lab
ADAMS, D. H. Region 1, Philadelphia, Office of the Director 79/05/21 1p
- 7905200014 Recommends establishment of QA staff & delineation of responsibilities to ensure supervision re W. Stello 790420 memo
HAGSTED, J. H. Office of Inspection & Enforcement 79/05/21 1p
- 7905200023 Forwards info from Battelle Lab & GE re potential for radiolysis contributing oxygen to bubble over reactor core
Office of Nuclear Reactor Regulation 79/05/21 7pp
- 7905200018 Forwards procedure production flow chart
PORTER, E. Metropolitan Edison Co. 79/05/21 3pp
- 7905200026 Meeting file index for TH1-2 incident
Office of Nuclear Reactor Regulation 79/05/21 3pp
- 7905200012 Requests core availability review in national circulation. For deceler hand removal & review of Metall Lab work summary
HAGSTED, J. H. Assistant Director for Reactor Safety 79/05/21 1p
- 7905200048 Forwards background info on NRC action re TH1 reactor since TH1 incident & GE Davis to RD Case memo re establishment of Task Group on General Review of Passively Trained to GAD-Configured Reactors.
EYERHART, G. Commission 79/05/22 24pp
- B Inspection reports, IE Bulletin & correspondence
- 7905200005 IE Bulletin 78-07, "Protection Afforded by Air-Line Respirators & Supplied-Air Masks."
Region 1, Philadelphia, Office of the Director 78/04/12 3p
- 7905200122 Forwards proposed IE circular re interconnections of contaminated gas w/cool air age used as source of breathing air. Circular describes 790034 test for radon entry age in breathing air source at Peach Bottom Unit 3.
GRIER, D. H. Region 1, Philadelphia, Office of the Director 79/05/22 3pp
- 7905200118 Forwards IE Info Notice 79-06, "Stress Analysis of Reactor-Related Piping"
GRIER, D. H. Region 1, Philadelphia, Office of the Director 79/05/22 1p

DOCKETED ITEMS

127

7903010041 Forwards IE Info Notice 79-03, "Interconnection of Contaminated By w/By Air Age Used as Source of Breaching Air"
ORRER, R. H. Region 1, Philadelphia, Office of the Director
79/03/28 1p

7903010050 Forwards IE Info Notice 79-05, "Spill of Radioactively Contaminated Resin"
ORRER, R. H. Region 1, Philadelphia, Office of the Director
79/03/28 5pp

7903010059 Act request to close plant in light of TMI events. Actions are being taken to reexamine individual situations
IE Bulletin 79-08 encl
HERSCHEL, J. H. Commission 79/04/02 12pp

7903010034 Requested investigation into scope, procedures, & current status of NRC & SE analysis of TMI to complete Task Force assigned to examine BSM reactors
HERSCHEL, J. H. Office of Policy Evaluation 79/04/04 2pp

790410040 IE Bulletin 79-05A, "Nuclear Incident at NRI-Seguel" w/ 790403 telegram from JH Herdrie to all BSM licensees
* Office of Inspection & Enforcement 79/04/05 12pp

7903010014 Forwards temporary instruction 2295/02, "Ins. Requirements to Review BSM License Actions Taken in Response to IE Bulletin 79-05 & 79-05A"
* Office of Inspection & Enforcement 79/04/06 1pp

7903010009 Discusses steps to be taken prior to returning TMI-2 to power operation IE bulletin, circulars, & info notices will be properly addressed
HERSCHEL, J. H. Metropolitan Edison Co 79/04/10 1p

7903010107 Forwards IE Bulletin, "Review of Operational Errors & BSM Misalignments Identified During TMI Incident," & draft cover letters
HERSCHEL, J. H. Office of Inspection & Enforcement 79/04/11 3pp

7903010413 Forwards IE Bulletin 79-06B, "Review of Operation Errors & BSM Misalignments Identified During TMI Incident"
HERSCHEL, J. H. Division of Reactor Operations Inspections 79/04/13 3pp

7903010015 Discusses schedule for completing actions required by IE Bulletin 79-03 Search of procurement documents to determine end of specified welded pipe will be complete by 790303
HERSCHEL, J. H. Metropolitan Edison Co 79/04/13 1p

7903010045 Forwards requested revision to development of policies & implementation programs for TMI
STERN, J. P. Region 1, Philadelphia, Office of the Director
79/04/16 4pp

7903010012 Lists IE reactor operations shift organization, 790410-9420, re TMI-2
HERSCHEL, J. H. Office of Inspection & Enforcement 79/04/16 1p

7903010029 Amend 1 to NRC 790410 access list for SE personnel
HERSCHEL, J. H. Region 1, Philadelphia, Office of the Director
79/04/18 3pp

7903010034 Forwards IE Bulletin 79-06A Revision 1, "Review of Operational Errors & BSM Misalignments Identified During TMI Incident," list of licensees & CP holders receiving bulletins & sample information & action required lists
STERN, J. P. Region 1, Philadelphia, Office of the Director
79/04/18 1p

7903010063 Forwards proposed outline & draft scope paragraph for TMI investigation report Requests review
ALLRED, R. J. Region 1, Philadelphia, Office of the Director
79/04/22 3pp

7903010084 Forwards IE Bulletin 79-08B, "Nuclear Incident at TMI," & draft cover letters
HERSCHEL, J. H. Office of Inspection & Enforcement 79/04/23 3pp

7903010106 IE Bulletin 79-08B, "Nuclear Incident at TMI" w/extract of BSM 790420 communication encl
* Office of Inspection & Enforcement 79/04/21 3pp

7903010067 Requests IE Bulletin 79-05B be dispatched for action by 790420 to all BSM reactors w/IE & by 790425 to facilities w/CP. Drafts for facilities encl.
HERSCHEL, J. H. Division of Reactor Operations Inspections 79/04/21 3pp

7903010053 Responds to 790418 for requesting advice on action needed as 790417 oral recommendations Recommendations involve all PMRs & careful study should precede any action
GARDNER, M. W. ACRS - Advisory Committee on Reactor Safeguards
79/04/20 2pp

7903010014 Forwards PMR & IE Bulletin re TMI incident
COLLINS, H. E. Assistant Director for Emergency Preparedness
79/04/20 1p

7903010017 Forwards NUREG-0303 dtd 790330 & requests comments by 790330 w/IE encl
RYAN, R. G. Office of State Programs 79/04/10 1p

7903010030 Submits draft response to 790418 for requesting permission to accompany inspectors during loop of nuclear reactor operated by Batten Nuclear Experimental Corp in Batten, PA
Invitation must be attended by licensee
BRIDGER, D. L. Region 1, Philadelphia, Office of the Director
79/04/26 2pp

7903010036 Summary of 790304 site visit to TMI re plans for monitoring worker radiation exposure
KROTHOLZ, C. Environmental Evaluation Branch 79/05/19 4pp

7903010011 File Index - IE 3B,
* Office of Inspection & Enforcement 79/05/23 2pp

R Periodic operating reports & related correspondence

7903010023 Summary paper re BSM results for site & composition of BSM in reactor vessel, in response to NRC 790402 request
ROY, B. H. Babcock & Wilcox Co 79/04/02 3pp

7903010014 Recommends log books for control room personnel as opposed to procedures outlined in L. Device 790404 memo
STOLLOV, V. Division of Operating Reactors
HERSCHEL, J. H. Division of Systems Safety
ORRER, R. H. Region 1, Philadelphia, Office of the Director
79/04/03 2pp

7903010041 Plant status info
HERSCHEL, J. H. Region 1, Philadelphia, Office of the Director
79/04/07 3pp

7904020032 Forwards summary of preliminary estimates of radioactivity releases as of 790407 At of midday 790409, population dose due to public gases is estimated to be 2400 man-rems when individual exposure at less than 100 man-rems
BARNETT, L. H. Environmental Evaluation Branch 79/04/12 20pp

7903010032 Week update of environ monitoring data for 790409 to 790412
* Energy Dept 79/04/12 4pp

7903010013 Forwards monthly operating report for Mar 1979
HERSCHEL, J. H. Metropolitan Edison Co 79/04/18 1p

7903010030 Monthly operating report for Mar 1979
LEON, R. A. Metropolitan Edison Co 79/04/18 4pp

7903010035 Forwards "Decay Heat Removal During Very Small Break LCA for BSM 205 Fuel Assembly PMR," prepared for TMI
HERSCHEL, J. H. ACRS - Advisory Committee on Reactor Safeguards
79/04/02 1p

7903010037 "Decay Heat Removal During Very Small Break LCA for BSM 205 Fuel Assembly PMR," preliminary copy
HERSCHEL, J. H. ACRS - Advisory Committee on Reactor Safeguards
79/04/02 1p

7

DOCKETED ITEMS

- 7903210060 Requests assistance in responding to questions proposed at meeting w/Commission for Advancement for Public Interest Organizations
MISCHERMAN, L. Division of Fuel Facility & Materials Safety
79/04/28 1p
- 7903210062 Describes testing conditions used by NRC for thermoluminescence dosimeters to radiation per NRC request
Olant TH1 waste shipment log and
BERNARD, E. H. Commerce Dept of 79/04/28 1p
- 7903200038 Forwards monthly operating report for Mar 1979 WRA and
TAPPEER, G. J. Metropolitan Edison Co 79/04/27 1p
- 7903200031 Forwards "Environ Operating Rep 1978," "Hydraulic Survey, June 1978," & "Monitoring of Cooling Tower Operation Effects on Vegetation in Vicinity of TH1, 1978."
BERNARD, J. D. Metropolitan Edison Co 79/03/01 2pp
- 7903200033 "Environ Operating Rep 1978"
Metropolitan Edison Co 79/03/28 18pp
- 7903200032 "Hydraulic Survey, June 1978"
Metropolitan Edison Co 78/06/31 13pp
- 7903200031 "Monitoring of Cooling Tower Operational Effects on Vegetation in Vicinity of TH1-2, 1978"
Metropolitan Edison Co 78/12/31 41pp
- 2 Reportable occurrences, LCR & related correspondence
- 7903200021 LCR 78-29/03L-D on 780415 ventilation damper 4-6000 did not close as required upon receipt of high alarm signal
Caused by improperly adjusted damper linkage
Metropolitan Edison Co 78/05/10 1p
- 7903100180 Info re emergency situation & investigation
LAFLEUR, J. D. Office of International Programs 79/03/28 3pp
- 7903100003 Board notification Westport refueling water storage tank design deficiencies
SCHEIDT, J. Hearings Division 79/03/29 20pp
- 7903100009 Provides preliminary unclassified info re incident
LAFLEUR, J. D. Office of International Programs 79/03/29 2pp
- 7903100154 Report info re TH1 emergency situation per dispatch ahead
LAFLEUR, J. D. Office of International Programs 79/03/29 4pp
- 7903100146 Provides details of plant & environ status as of 790330 Unit 2 continuing to remove decay heat through A-loop steam generator using one reactor
LAFLEUR, J. D. Office of International Programs 79/03/30 4pp
- 7903100153 Provides preliminary info re plant & environ status as of 790330 Reactor radioactivity from primary coolant mix system has been contained in waste gas decay tanks
LAFLEUR, J. D. Office of International Programs 79/03/31 4pp
- 7903100143 Provides details of plant & environ status as of 790331 for dispatch ahead
LAFLEUR, J. D. Office of International Programs 79/03/31 5pp
- 7903100142 Preliminary plant status as of 790331 No change in method of cooling since last report
LAFLEUR, J. D. Office of International Programs 79/04/01 4pp
- 7903100151 Summary of info re nuclear incident as of 7 AM 790401
Describes plant & environ status
LAFLEUR, J. D. Office of International Programs 79/04/01 3pp
- 7903100011 Preliminary info re plant status as of 790402 Measurements indicate vol of gases within bubble significantly reduced
LAFLEUR, J. D. Office of International Programs 79/04/02 4pp
- 7903100150 Preliminary info re plant status as of 790402 Reactor pressure remains at 1,050 psf without core coolant inlet & outlet
LAFLEUR, J. D. Office of International Programs 79/04/03 2pp
- 7903100178 Summary of info re nuclear incident as of 790402 Reactor pressure remains near 1,050 psf without core coolant inlet & outlet temperatures at 203 F
LAFLEUR, J. D. Office of International Programs 79/04/03 3pp
- 7903000080 Discusses release of preliminary notices on TH1-2 & status of emergency response operations
GOSBICK, L. V. Office of the Executive Director for Operations 79/04/03 3pp
- 7903000069 Forwards results of preliminary radiological impact analysis of TH1 incident
GOSBICK, L. V. Office of the Executive Director for Operations 79/04/03 12pp
- 7903100005 Summary of preliminary info re nuclear incident as of 790404 Cooling path to remove core decay heat continues to be through A-loop steam generator
LAFLEUR, J. D. Office of International Programs 79/04/04 2pp
- 7903100214 Summary of info re nuclear incident as of 7 AM 790404 Describes plant & environ status
LAFLEUR, J. D. Office of International Programs 79/04/04 3pp
- 7903000076 Discusses possible determination of extraordinary nuclear occurrence at TH1-2
BERNARD, E. H. T. Commission 79/04/04 1p
- 7903100009 Preliminary info re plant status Replenishment shutters measurements indicate about 25 hydrogen
LAFLEUR, J. D. Office of International Programs 79/04/05 4pp
- 7903100081 Provides details of plant & environ status
LAFLEUR, J. D. Office of International Programs 79/04/05 4pp
- 7903100076 Forwards excerpts of LCR re Reactor related & other transients at BWC facilities other than TH1 Related correspondence incl
GOSBICK, L. V. Office of the Executive Director for Operations 79/04/06 18pp
- 7903100267 PHO-79-71 vapor binding of shutdown cooling system & 790314 Section restricted to radioactive material released to environ
KILBINGER, D., MOLAN, P., BRYAN, B. E. Office of Inspection & Enforcement 79/04/23 1p
- 7903100066 Summary of info re incident as of 790406 Reactor continues stable shutdown Unit 2 Bulletin 79-004
LAFLEUR, J. D. Office of International Programs 79/04/26 2pp
- 7903100138 Provides details of plant status as of 790406 Reactor continues stable shutdown heat removal cooling at 1,075 psi, using one primary coolant pump & one steam generator
LAFLEUR, J. D. Office of International Programs 79/04/26 5pp
- 7903100130 Provides preliminary chronology of NRC actions in connection with summary description of emergency containment, summary of survey/health effects & insap.
GOSBICK, L. V. Office of the Executive Director for Operations 79/04/29 32pp
- 7903100123 Preliminary chronology of TH1 incident on 790409 & subsequent status through 790407
Commission 79/04/29 App
- 7903100175 Provides details of plant status as of 790410 Shutdown evacuation & environ status
LAFLEUR, J. D. Office of International Programs 79/04/19 2pp
- 7903100002 PHO-79-70 Facility shutdown on 790410 due to Reactor regulating valve malfunction which caused reactor to trip as result of low steam generator water level.
MOLAN, P., BRYAN, B. E. Office of Inspection & Enforcement 79/04/19 1p
- 7903100028 Discusses schedule for reports re 790328 event & follow up. Because of incident & corrective actions involved, details will be delayed until 790510
BERNARD, J. D. Metropolitan Edison Co 79/04/19 1p
- 7903000040 Reviews TH1-2 incident. Requests that TH1-related info be sent to BWC contracts in next parts
LAFLEUR, J. D. Office of International Programs 79/04/19 2pp
- 7903000087 Discusses EE responsibility for drafting final preliminary notice re TH1 status. Requests procedures be established to assure necessary info is available for input
GOSBICK, L. V. Region 1 Philadelphia, Office of the Director 79/04/19 1p

DOCKETED ITEMS

131

- 7705280108 Forwarded IE Insp Repts 50-321/79-04 & 50-366/79-07 on 7902/4-14 No nonconformance noted
LEHNER, H. C. Region 2, Atlanta, Reactor Operations Nuclear--
Support Branch 79/03/31 2pp
- 7705280110 IE Insp Repts 50-321/79-04 & 50-366/79-07 on 7902/4-14 No nonconformance noted Major areas inspected plant operations, followup of unresolved items, LERs & test witnessing
DUNCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear--
Support Branch HENKLEY, G. G. Region 2, Atlanta, Office of the Director 79/03/31 3pp
- 7705280456 Forwarded IE Bulletin 79-03B, "Review of Operational Errors & Site Misassignments Identified During THE Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7705280504 Forwarded IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping - Licensee action required"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7705280413 Forwarded IE Bulletin 79-09, "Events Relevant to Boiling Water Reactor Reactant Identified During THE Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7705100044 Responds to IE Bulletin 79-03 No evidence of Youngstown Welding & Engineering seam welds ASME SA-512 Type 304 stainless steel piping is being used in safety-related systems SA-512 Type 304 steel is used
STAFFA, R. W. Georgia Power Co 79/04/16 1p
- 7705030145 Forwarded IE Bulletin 79-09, "Failures of OR Type AM-2 Circuit Breaker in Safety-Related Systems - Licensee action required"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7705030447 Forwarded IE Bulletin 79-05A, Revision 1, "Review of Operational Errors & Site Misassignments Identified During THE Incident,"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7705270029 Responds to IE Bulletin 79-08 Addresses events relevant to BWRs identified during THE Incident Response to Item II will be forwarded in 30 days
NEIDER, H. A. Georgia Power Co 79/04/25 12pp
- 7705270039 Responds to IE Bulletin 79-04, Review of design records indicates there are no 3-4 or 4-inch diameter valves using check valves used at facility
STAFFA, R. W. Georgia Power Co 79/05/02 1p
- 7705270035 Forwarded revised responses to IE Bulletin 79-08, "Events Relevant to BWRs Identified During THE Incident" Replaces previous 770428 submittal (conditioned as 770415 in present list) Includes response to Item II
NEIDER, H. A. Georgia Power Co 79/05/09 13pp
- 8 Reportable occurrences, LERs & related correspondence
- 7705140514 Notifies that LERs 50-366/1979-22 & 50-321/1979-16 have been voided They were later determined to be not reportable
HANNY, M. Georgia Power Co 79/03/13 1p
- 7705101002 LER 50-021/1979-22 has been voided, Rept will be incorporated into LER 79-25
HANNY, M. Georgia Power Co 79/04/19 1p
- 7705000545 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/04/24 1p
- 7705280020 LER 79-021/03L-0 on 770410, during steady state operation, "MCP1 isolation trip logic & interlock alarm received, closing inboard isolation valve S41-7002 Caused by high delta temp in WPC room Bys reset"
GREENE, T. V. Georgia Power Co 79/04/24 2pp
- 7705080473 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/04/30 1p
- 7705080479 LER 79-021/03L-0 on 770420 during steady state power operation, radioactive water observed boiling from ground near closed generator kld, caused by burned open line, Line closed immediately
BOSCH, H. H. Georgia Power Co 79/04/30 2pp
- 7705080520 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/04/30 1p
- 7705080504 LER 79-021/03L-0 on 770427 during steady state power operation, H2O2 analyzer pumps were inoperative Caused by incorrect 19P-1-355 procedure Procedure will be revised by 770501
BAXLEY, S. J. Georgia Power Co 79/04/27 1p
- 7705130517 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/05/07 1p
- 7705130528 LER 79-021/03L-0 on 770422 while performing procedure 19P-1-311, valves S21-7008 & S21-7003 closed too fast Caused by improper adjustment drift Followup report of corrective action will be sent
HANNY, M. Georgia Power Co 79/05/07 1p
- 7705130543 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/05/07 1p
- 7705130549 LER 79-021/03L-0 on 770427 Initial tests of various Type C low level radiation test containment isolation valves proved unacceptable during local leak rate testing Caused by scratches on valve seat from valve closing on debris
GREENE, T. V. Georgia Power Co 79/05/07 2pp
- 7705130551 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/05/18 1p
- 7705130603 LER 79-021/03L-0 on 770428 both doors of strike E106 were opened simultaneously Caused by personnel error Glass installed to cover emergency override pushbuttons of both strike doors
GREENE, T. V. Georgia Power Co 79/05/18 1p
- 7705130627 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/05/17 1p
- 7705130633 LER 79-021/03L-0 on 770505 five containment isolation valves did not meet acceptance criteria during initial tests Cause under investigation Corrective action will be performed to eliminate satisfactory leakage rate for valves
GREENE, T. V. Georgia Power Co 79/05/17 2pp
- 7705130644 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/05/17 1p
- 7705130658 LER 79-021/03L-0 on 770505 door interlock defeated & both bldg airlock doors were open at same time Caused by personnel error Personnel retrained & engineering design is being reevaluated
BAXLEY, S. J. Georgia Power Co 79/05/17 1p
- 7705130664 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/05/21 1p
- 7705130670 LER 79-021/03L-0 on 770508 main steam line tunnel temp switch S21-ND118 opened at 200F Caused by safety drift Switch recalibrated & functionally tested.
HANNY, M. Georgia Power Co 79/05/21 1p
- 7705050603 Forwarded LER 79-021/03L-0
HANNY, M. Georgia Power Co 79/03/17 1p
- 7705050608 LER 79-021/03L-0 on 770508 air open were improperly installed, Caused by insufficient Installation safe Haint procedure revised & installation
GREENE, T. V. Georgia Power Co 79/05/17 2p
- DOCKET 30-332 SHREDHAM NUCLEAR POWER STATION
A. Application/permit/operation stage documents & cc

- 7705280435 Responds to 770320 memo re polling & meetings to public
BENTON, R. Office of Nuclear Reactor Regulator
- 7705280667 Requests NRC views on whether price NRC & all representatives should be open to BRASCHER, P. A. Office of Nuclear Reactor Reg. 1p
- 7705040316 Summary of 770320 meeting of Mark II Use, CA re intermediate plant program tests
ANDERSON, C. J. Containment System Branch

DOCKETED ITEMS

7905030512 Transcript of 790427 press conference in Middleboro, MA
Pg. 1-22
BTELLER, V. Division of Operating Reactors 79/04/27 3pp

7905030513 Transcript of 790430 Ad Hoc Subcommittee on TMI Incident in
Washington, DC Pg. 5-263
DORRANT, D., CARROLL, H. M., BIEBER, C. ACES - Advisory Committee on
Reactor Safeguards 79/04/30 31pp

7905030520 Transcript of 790501 Ad Hoc Subcommittee on TMI Incident
meeting in Washington, DC Pg. 341-364
DORRANT, D., CARROLL, H. M., BIEBER, C. ACES - Advisory Committee on
Reactor Safeguards 79/05/01 30pp

7905030523 Transcript of 790503 briefing on off-site radiation levels
at TMI and radiological assistance program Pg. 1-67
KENNEDY, J. H., GILMARTIN, V., KENNEDY, R. T. Commission 79/05/03
48pp

7905030524 Transcript of 790507 press briefing in Middleboro, MA
BTELLER, V. Division of Operating Reactors 79/05/07 32pp
Assistant Director for Site Analysis

7905030549 Forwards transcripts of interview w/TMI-2 operators at time
of incident
THOMPSON, G. F. Shaw, Pittman, Fette, & Traubridge 79/05/07
63pp

7905040507 Response to FEMA request for transcripts of NRC closed
meetings re Harrisburg incident Gives price list of
transcripts available in PDF
BTELLER, V. Division of Rules and Records 79/05/09 5p

7905040523 Transcript of ACES Ad Hoc Subcommittee 790504 w/TMI-2
meeting Pg. 1-309
DORRANT, D., CARROLL, H. M., BIEBER, C. ACES - Advisory Committee on
Reactor Safeguards 79/05/04 310pp

7905040527 Transcript of 790518 public meeting re Pg. 1-129 w/copies of
presentation transparencies
KENNEDY, J. H., GILMARTIN, V., KENNEDY, R. T. Commission 79/05/18
127pp

7905050431 Response to 790514 memo Advises that transcripts of
interview w/TMI-2 operators have been submitted to FOR &
Dir. of Congressional Affairs.
COMBELL, E. K. Office of the Executive Director for Operations
79/05/17 1p

--7905050435 Forwards of Transbridge re E Case 790507 for submitting
transcript of interview w/TMI-2 operators Transcripts will
be considered in IE investigation of accident
HATTGBLER, J. Division of Systems Safety 79/05/14 1p

DOCKET 80-321 EDENH HATCH NUCLEAR PLANT, UNIT 1
Security, medical, emergency & fire protection plans

7905050468 Response to 790502 letter reporting reasons for delay in
implementing 10CFR72.50 requirements & describing
contingency measures provided to meet these requirements
Measures are acceptable
IPFOL, T. T. A. Operating Reactors Branch 3 79/04/16 2pp

I. Financial Information

7905050497 Forwards "Annual Financial Rept 1978"
VANDERKAM, R. O. Metropolitan Electric Authority of Georgia 79/05/02
1p

--7905050502 "Annual Financial Rept 1978"
Metropolitan Electric Authority of Georgia 79/02/01 2pp.

7905070497 Confirms increased liability limit to \$126,000,000 for
policy 197-1-25, 45, 76, 83, 105-111, 140, 144, 151, 161, 164-170,
173, 174, 176, 179, 180, 182, 185, 186, 187, 188, 189, 190, 192, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 218, & others
BARTHOLOMEW, J. American Nuclear Insurers 79/05/01 1p

7905070502 Confirms increase in liability limit to \$36,000,000 for
policy 197-22, 24, 29, 30, 33, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95, & 96
BARTHOLOMEW, J. H. Mutual Atomic Energy Liability Underwriters 79/05/01
1p

7905080427 Forwards Amend 10 to Indemnity Agreement B-89
BTELLER, C. F. Georgia Power Co. 79/05/01 3pp.

7905080430 Forwards Amend 11 to Indemnity Agreement B-89 per DOE/DOE
change re increase in liability insurance from \$150 million
to \$160 million, effective 790505 Supporting documentation
etc.
BARTHOLOMEW, J. H. Indemnity & Indemnity Group 79/05/01 4pp

7905080432 Forwards Endorsement 49 to NELA Policy NP-215
BTELLER, C. F. Marsh & McLennan, H. & M. Nuclear Consultants, Inc. 79/05/02 2pp

7905080432 Forwards Endorsement 50 to NELA Policy NP-215
BTELLER, C. F. Marsh & McLennan, H. & M. Nuclear Consultants, Inc. 79/05/02 2pp

F. Operating license stage documents & correspondence

7905070544 Response to 790319 letter questioning license amend for
requirement for 791321 application Fee paid and justified
BTELLER, V. O. License Fee Management Branch 79/04/03 1p

7905100512 Amends 790325 submittal of Tech Spec changes in support of
Reactor 3 Licensing application Class IV amend Fee sheet
BTELLER, C. F. Georgia Power Co. 79/05/11 32pp

7905100524 Forwards schedule for implementation & verification of Reactor
containment long-term program Only vent header deflectors
are necessary An major and for compliance to long-term
program acceptance criteria
BTELLER, C. F. Georgia Power Co. 79/05/14 4pp

7905100529 Forwards proposed amend to Tech Spec re turbine control
valve fast closure trip setpoint.
BTELLER, C. F. Georgia Power Co. 79/05/14 4pp

7905050547 Forwards Revise & Amend Sheet 1 to NEDS-04175,
"Supplemental Revised Licensing Request for Edulis 1 Unit,
Unit 1-Revised 3"
BTELLER, C. F. Georgia Power Co. 79/05/16 4pp

7905050538 Response to 3 Revell's request for add. info re end
of reactor nozzle & spacer 3C licensing repts HEDS-21021, HED
Rev 1978, provides discussion of issues & proposed solutions
in existing problem in DWR
BTELLER, C. F. Georgia Power Co. 79/05/16 1p

7905050506 Requests change to Tech Spec App A to DL modifying
Surveillance Requirement 4.9.0 due to incorporation of
redundant breaker on output of reactor protection logic water
generator sets
BTELLER, C. F. Georgia Power Co. 79/05/02 2pp

G. Inspection reports, IE Bulletin & correspondence

7905040501 Forwards IE Info Notice 79-56, "Stress Analysis of
Safety-Related Piping"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
79/03/23 2pp

7905050497 Forwards IE Insp Repts 80-321/79-09 & 80-364/79-11 on
790210-0352 No noncompliance noted
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Branch
79/03/23 2pp

--7905050497 IE Insp Repts 80-321/79-09 & 80-364/79-11 on 790210-0352
noncompliance noted. Major areas inspected Unit 1 plant
noncompliance, Unit 2 startup testing, Tech Spec compliance,
reportable occurrences & Unit 2 transient test witnessing
8005050507 R. P. Region 2, Atlanta, Office of the Director
BARTHOLOMEW, J. H. Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/23 2pp

7905050512 Forwards IE Info Notice 79-07, "Regime of Radiolytic Reactions"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
79/03/26 2pp

7905050517 Forwards IE Info Notice 79-36, "Interconnection of
Contained Air w/ Dry Air Box Used as Source of Breathing Air"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
79/03/26 2pp

7905050505 Forwards IE Info Notice 79-09, "Spill of Radioactive
Contained Resin"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
79/03/26 2pp

7905050505 Requests page 6 of IE Insp Repts 80-321/79-09 & 80-364/79-11
to be reprinted w/ corrected pages
BTELLER, C. F. Georgia Power Co. 79/04/04 2pp.

DOCKETED ITEMS

131

--7902200500 Forwards IE Inspec Repts 80-021/79-06 & 80-066/79-07 on 790220-16 Hs noncompliance noted
LEWIS, R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 3/9/02/21 App

--7902200510 IE Inspec Repts 80-021/79-06 & 80-066/79-07 on 790220-16 Hs noncompliance noted Major areas inspected plant operations, follow-up of unresolved items, LERs & test witnessing
DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 3/9/02/21 App Region 2, Atlanta, Office of the Director 3/9/02/21 App

7902040215 Forwards IE Bulletin 79-008, "Review of Operational Errors & Reconfigurations Identified During TMI Incident"
Region 2, Atlanta, Office of the Director 3/9/04/14 App

7902040204 Forwards IE Bulletin 79-007, "Statistical Process Analysis of Safety-Related Piping" - Licensee action required
Region 2, Atlanta, Office of the Director 7/9/04/14 App

7902040213 Forwards IE Bulletin 79-006, "Events Relevant to Boiling Water Reactor Identified During TMI Incident"
Region 2, Atlanta, Office of the Director 7/9/04/14 App

7902040244 Responds to IE Bulletin 79-005 No evidence of Youngstown Welding & Engineering team used APRR 80-212 Type 204 stainless steel piping in being used in safety-related systems
APRR 80-200 Type 204 steel is used
BTFPA, R M Georgia Power Co 3/9/04/14 App

7902020265 Forwards IE Bulletin 79-009, "Failures of OE Type AA-2 Circuit Breaker in Safety-Related Area" - Licensee action required
Region 2, Atlanta, Office of the Director 7/9/04/17 App

7902020247 Forwards IE Bulletin 79-008, Revision 1, "Review of Operational Errors & Reconfigurations Identified During TMI Incident"
Region 2, Atlanta, Office of the Director 7/9/04/18 App

7902020209 Responds to IE Bulletin 79-008 Addresses events relevant to BWRs identified during the incident Response to item ii will be provided by 30 days
MIDNER, M A Georgia Power Co 7/9/04/25 App

7902020209 Responds to IE Bulletin 79-008 Review of design records indicates there are no 3.4 or 6-inch diameter valves using chest valves used at facility
BTFPA, R M Georgia Power Co 7/9/02/02 App

7902020200 Forwards revised response to IE Bulletin 79-008, "Events Relevant to BWRs Identified During TMI Incident" - Replaces previous 7904020200 submitted (submitted as 790413 in present list). Includes response to item ii
MIDNER, M A Georgia Power Co 7/9/03/29 App

B. Repeatable occurrences, LERs & related correspondence

7902040215 Notice that LERs 80-066/1979-07 & 80-021/79-16 have been voided They were later determined to be not reportable
NANRY, H Georgia Power Co 7/9/03/13 App

7903010502 LER 80-021/1979-02 has been voided Rept will be incorporated into LER 79-021
NANRY, H Georgia Power Co 7/9/04/19, App

7903060316 Forwards LER 79-021/03L-0
NANRY, H Georgia Power Co 7/9/04/24 App

--7903060316 LER 79-021/03L-0 on 790306 during steady state operation, "HPI isolation trip logic A initiated" alarm received, closing inboard isolation valves 021-F002 Caused by high valve temp in HPI rack. Rept received
GREENE, T V Georgia Power Co 7/9/04/24 App

7903060473 Forwards LER 79-021/03L-2
NANRY, H Georgia Power Co 7/9/04/30 App

--7903060473 LER 79-021/03L-2 on 790306 during steady state power operation, redisturbance water observed bubbling from ground near diesel generator bldg. Caused by torn open line. Line closed immediately.
ROSEN, M H Georgia Power Co 7/9/04/30, App.

7903080220 Forwards LER 79-025/03L-0
NANRY, H Georgia Power Co 7/9/04/20, App.

--7903060526 LER 79-025/03L-0 on 790427 during steady state power operation, HODS analyzer pumps were inoperative Caused by incomplete HWP-18-3633 procedure Procedure will be revised by 7/9/01
BASKLEY, B X Georgia Power Co 7/9/04/27 App

7903050519 Forwards LER 79-026/03L-0
NANRY, H Georgia Power Co 7/9/05/07 App

--7903050520 LER 79-026/03L-0 on 790427 while performing procedure HWP-18-3111, valves 021-F008A & 021-F008B closed too fast Caused by knobler adjustments on 1818 Following report of corrective action will be sent
NLS, E T Georgia Power Co 7/9/05/07 App

7903050543 Forwards LER 79-027/03L-0
NANRY, H Georgia Power Co 7/9/05/07 App

--7903050549 LER 79-027/03L-0 on 790427 Initial tests of various Type C low level radiation test containment isolation valves proved unacceptable during local leak rate testing Caused by scratches on valve seat from valve closing on debris
GREENE, T V Georgia Power Co 7/9/05/07 App

7903050571 Forwards LER 79-028/03L-0
NANRY, H Georgia Power Co 7/9/05/18 App

--7903050603 LER 79-028/03L-0 on 790428 both doors of airlock R100 were opened simultaneously Caused by personnel error Glass installed to cover emergency override pushbuttons of both airlock doors
GREENE, T V Georgia Power Co 7/9/05/18 App

--7903050627 Forwards LER 79-028/03L-0
NANRY, H Georgia Power Co 7/9/05/17 App

--7903050630 LER 79-029/03L-0 on 790305 five containment isolation valves did not meet acceptance criteria during initial tests Cause under investigation Corrective action will be performed to allow satisfactory leakage rate for valves
GREENE, T V Georgia Power Co 7/9/05/17 App

--7903050644 Forwards LER 79-029/03L-0
NANRY, H Georgia Power Co 7/9/05/17 App

--7903050646 LER 79-029/03L-0 on 790305 door interlock defeated & both bldg airlock doors were open at same time Caused by personnel error Personnel uninstructed & engineering design is being reevaluated
BASKLEY, B X Georgia Power Co 7/9/05/17 App

--7903050646 Forwards LER 79-031/03L-0
NANRY, H Georgia Power Co 7/9/05/21 App

--7903050674 LER 79-031/03L-0 on 790306 main steam line liquid trap switch 021-M016 opened at 200F Caused by setpoint drifts
Switch rechecked & functionally tested
NLS, E T Georgia Power Co 7/9/05/21 App

--7903060683 Forwards LER 79-033/03L-0
NANRY, H Georgia Power Co 7/9/05/17, App

--7903060688 LER 79-033/03L-0 on 790306 air operation on 021-F018A & C were improperly installed Caused by insufficient installation info Rept procedure revised to ensure proper installation
GREENE, T V Georgia Power Co 7/9/05/17, App

DOCKET

A. Appl

7903090616 Responds to 790309 memo re policy on sending procedural meetings to public
BENTON, H R Office of Nuclear Reactor Regulation 7/9/04/04 App.

--7903090617 Requests NRC view on whether procedural meetings between NRC & utility representatives should be open to public
BRADFORD, P A Office of Nuclear Reactor Regulation 7/9/03/05, App

7903040516 Summary of 790301 meeting of Hurl II owners group in San Jose CA re interconnect plant program tests.
ANDERSON, C J. Containment Systems Branch 7/9/04/13 100pp.

DOCKETED ITEMS

7905030258 Summary of 790410 meeting w/Cincinnati Gas & Electric Co.
Long Island Lighting Co & Commonwealth Edison Co re
vibratory loads & equipment qualification Presentation mch
encl
PRLTIER, I A Light Water Reactors Branch 1 79/04/19 5pp

7905030300 Notification of 790315-17 meeting w/Cincinnati Gas &
Electric Co., Long Island Lighting Co., Commonwealth Edison Co &
E O in San Jose, CA re audit ASME equipment for seismic &
other dynamic qualification Presentation mch
encl
PRLTIER, I A Light Water Reactors Branch 1 79/04/23 3pp

7905040318 Responses to 790223 1st Reevaluation of plans of plants &
NEDS Seismic Category 1 equipment for Region Southern plans
for reevaluation program
HOWARD, J P Long Island Lighting Co 79/03/01 3pp

7905050500 Forwards list of SE Seismic Category 3 equipment for
seismic qualification review list identify equipment
required for safe shutdown & includes brief list of plant
sign designators
HOWARD, J P Long Island Lighting Co 79/03/04 37pp

7905050500 Forwards summary of EOR Nuclear, Inc. resolution/documentation
of show planning error which existed in version of
PDR, piping analysis computer program from Jan-Dec 1994
Review & recommendations included all work through Dec 1970
PARKER, F L EOR Nuclear, Inc 79/05/21 2pp

--7905050563 Forwards EOR Nuclear, Inc. list of BWR & piping systems which
could have been impacted by deficient computer program
of EOR no record of recommendations for Cooper piping systems
STEPHENS, R W General Electric Co. Nuclear Energy Products Div
79/05/25 8pp

P Security, medical, emergency & fire protection plans

7905050946 Requests copy of QAO report re insufficient state & local
emergency evacuation plans & NBC responses to plan
GARDNER, R Cammer & Shapiro 79/04/03 1p

Q Adjudicatory correspondence

7905040234 First set of interrogatories & notice to produce submitted
by County of Suffolk, NY re still Certificate of Sec encl
LIME, C Suffolk County, NY 79/03/28 5pp

7905050503 Response to request for info re possible shutdown of
facility due to possible design deficiencies noted by
computer model design computer model in question not used
for facilities
HOFELING, R N Branch 4 79/04/23 2pp

7905050916 Denies licensing of plant
GARDNER, R Affiliation Unknown 79/04/03 2pp

7905050503 Directs recipient to QAO Re High PWR-18-110 requested in
790403 3rd QAO response to be being prepared & will be provided
when available
HOFELING, R N Branch 4 79/04/13 1p

7905050507 Response to Suffolk County's 790320 discovery requests
contained in Apps A & B of first set of interrogatories &
notice to produce Affidavit of SA Nuclear, Interrogatory
Documentation & Certificate of Sec encl
MATTHERS, P C Long Island Lighting Co 79/04/17 3pp

7905040918 Requests details on allegation that EORs failed on site
different occasions
GARDNER, R Cammer & Shapiro 79/04/17 1p

7905050516 Forwards response to questions from 790420 meeting re utility's
first two sets of motions for summary disposition, exhibits
unsubmitted third set of summary disposition motions
Supporting documentation & affidavits encl
MATTHERS, P C Housen & Williams 79/04/27 3pp

R Utility Final Safety Analysis Report (FSAR) & amendments

7905040349 Forwards demand for FSAR application consisting of
Revision 1b to FSAR Affidavit encl
WYFFORD, A W Long Island Lighting Co 79/03/13 2pp

--7905040376 Amend SR to FSAR re combination design Overlaid drawings
encl
Long Island Lighting Co. 79/03/13 43pp

7905050210 Certificate of Sec of Revision 1a to FSAR
MORIN, J P Long Island Lighting Co. 79/03/22 1p

P Operating license stage documents & correspondence

7905050439 Unit will involve Code Case N-234 to ASME Section III which
allows use of ASME A200 Grade 5 & ASME A201 structural
bolting for welded attachments to ASME Section III Code Class
2 & 3 components This is supplemental 790327 1p
HOWARD, J P Long Island Lighting Co 79/04/25 1p

Q Inspection reports, SE Bulletins & correspondence

7905050516 Forwards IE Insp Notice 79-06: "Stress Analysis of
Barfly-Related Piping"
GILDER, E H Region 1, Philadelphia, Office of the Director
79/04/23 1p

7905040568 Forwards IE Insp Rept 50-352/79-03 on 790287-0202 No
noncompliance noted
GILDER, E H Region 1, Philadelphia, Reactor Construction &
Engineering Support Branch 79/03/23 2pp

--7905040672 IE Insp Rept 50-352/79-03 on 790287-0202 No noncompliance
noted Major areas inspected quality verification records for
reactor pressure vessel internal storage & installation &
licensee action on NRC findings
GILDER, E H REGION 1, Philadelphia, Office of the
Director HEDER, R W Region 1, Philadelphia, Reactor
Construction & Engineering Support Branch 79/03/22 3pp

7905040916 Response to SE Bulletin 79-05: "Pipe Support Base Plate
Designs Using Concrete Expansion Anchor Bolts" Forwards
and info re clarifying SDI upon items & conformity issues
HOWARD, J P Long Island Lighting Co 79/03/28 1p

7905050501 Forwards SE Bulletin 79-06: "Review of Operational Errors &
Misstatements Identified During TMI Incident"
GILDER, E H Region 1, Philadelphia, Office of the Director
79/04/11 1p

7905050516 Forwards SE Bulletin 79-06: "Seismic Stress Analysis of
Barfly-Related Piping" Licensee action required
GILDER, E H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040528 Forwards IE Bulletin 79-06: "Review of Operational Errors &
Misstatements Identified During TMI Incident"
GILDER, E H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905040509 Forwards IE Bulletin 79-06: "Events Relevant to Botini
Water Power Reactors Identified During TMI Incident"
GILDER, E H Region 1, Philadelphia, Office of the Director
79/04/14 1p

7905050707 Forwards IE Bulletin 79-06: "Failures of SR Type R-2
Circuit Breaker in Barfly-Related B" Licensee action
required
GILDER, E H Region 1, Philadelphia, Office of the Director
79/04/17 1p

7905050563 Forwards IE Bulletin 79-06: Review 1: "Review of
Operational Errors & Misstatements Identified During TMI
Incident"
GILDER, E H Region 1, Philadelphia, Office of the Director
79/04/18 1p

7905040537 Forwards revised procedures of pressuremap Insp program
HOWARD, J P Long Island Lighting Co 79/05/01 2pp

--7905040642 Automated ultrasonic examination procedures for reactor
vessel nozzle welds
Long Island Lighting Co 79/11/03 33pp

--7905040648 Revised ultrasonic examination procedures for reactor vessel
nozzle reinforced welds
Long Island Lighting Co 79/11/03 33pp

--7905040645 Automated ultrasonic examination procedures for reactor
vessel welds
Long Island Lighting Co 79/11/03 28pp

--7905040654 Ultrasonic examination procedures for piping butt welds &
longitudinal welds
Long Island Lighting Co. 79/09/01 33pp

DOCKETED ITEMS

139

DOCKET NO-329 DIABLO SANBORN NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905200474 Forwards replacement pages for Amends 1 & 4 to CPFR-28 & CPFR-29
GILZ, J F Light Water Reactors Branch 1 79/03/28 10pp

7905200578 Extends coast completion dates to 790630 for Unit 1 & 900229
for Unit 2
GILZ, J F Light Water Reactors Branch 1 79/04/13 6pp

7905200602 FR notice ordering extension of coast completion dates to 790630 for Unit 1 & 900229 for Unit 2
GILZ, J F Division of Project Management 79/04/13 2pp

7905200602 Forwards 41,000 fee to extend CP-18 response to NRC 790410
1st Requests acknowledgment
CHANE, P A Pacific Gas & Electric Co 79/04/27 2pp

7905201172 Forwards addl info on containment electrical penetrations
in response to NRC questions
CHANE, P A Pacific Gas & Electric Co 79/05/17 2pp

7905201187 Forwards info on bolted connections in liner supports in
response to NRC 790229 1st
CHANE, P A Pacific Gas & Electric Co 79/05/18 9pp

7905200631 Forwards application to extend completion date for CPFR-29
to 790630
CHANE, P A Pacific Gas & Electric Co 79/05/28 1p

7905200634 Application to extend completion date for CPFR-29 to 790630
CHANE, P A Pacific Gas & Electric Co 79/05/28 1p

F Securing, medical, emergency & fire protection plans

7905190054 Forwards modified physical security plan plan withheld
for security 7905
CHANE, P A Pacific Gas & Electric Co 79/05/28 1p

G Adjudicatory correspondence

7905200164 Request by intervenors Scenic Shoreline Preservation
Conference, San Luis Obispo Mothers for Peace, Ecology Action
Club, SA Silver & JJ Foster for Safe Filling of proposed
findings of fact & conclusions of law w/ certificate of Dec
FLEISCHMAN, D B Fleischman, D B 79/03/28 8pp

7905200174 Proposed Findings of fact & conclusions of law by
Intervenor Scenic Shoreline Preservation Conference, San
Luis Obispo Mothers for Peace, Ecology Action Club, SA Silver
& JJ Foster
FLEISCHMAN, D B Fleischman, D B PHILLIPS, J R KRISTOVICH, E
Center for Law in the Public Interest 79/03/28 40pp

7905200558 Informs of inability to submit proposed findings of fact on
adequacy of plant security systems denied access to evidence &
accuse of tampering on security plan Certificate of Dec encl
BACCHINI, M A San Luis Obispo Mothers for Peace 79/03/29 3pp

7905200569 Group of 12 letters protesting opening of facility
MAYERS, IB, H N UNLDR, S Affiliation Unknown 79/03/29 10pp

79052001018 Forwards request for Board notification re nonseafly-grade
equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/02 31pp

79052010154 Board notification, staff assessment re nonseafly-grade
equipment to mitigate transients
WARRALL, D B Assistant Director For Light Water Reactors
79/03/29 2pp

79052010198 Board notification recent issue on nonseafly-grade
equipment to mitigate transients How info is required.
TEEDBOD, R L Assistant Director For Reactor Safety 79/03/14 3pp

79052040356 Requests info on facility & earthquake Unhappy w/ member
power
GARCIA, D Affiliation Unknown 79/04/04 1p

79052040379 Requests that facility not be allowed to operate.
HARRIS, W J HARRIS, S Affiliation Unknown 79/03/20 1p

7905200044 Motion of extension of time until 790410 to file proposed
findings of fact & conclusions of law Certificate of Dec
encl
KATCHEM, E G Branch 3 79/04/04 4pp

7905200114 Grants NRC 790404 motion for extension until 790410 to which
to file findings of fact
ROMERS, E G Atomic Safety and Licensing Board Panel 79/04/08 1p

7905201004 Errata sheet to joint intervenors' proposed findings of fact
& conclusions of law Certificate of Dec encl
FLEISCHMAN, D B Fleischman, D B PHILLIPS, J R KRISTOVICH, E
Center for Law in the Public Interest 79/04/08 7pp

7905200320 Response to 790326 1st re status of facility licensing
Evaluating record in processing closed 790326 and pleading
scheduled to be filed by 790410 Practice date for initial
decision cannot be made
VORSE, J E Atomic Safety and Licensing Board Panel 79/04/06 1p

7905200323 Forwards 790313 1st from Relat Use New for Resources &
Employment, expressing concern about licensing of facility
Requests info on status of licensing process
ROMERS, E G House of Reps 79/03/28 2pp

7905204006 Rehealed to joint intervenors' 790325 proposed findings of
fact & conclusions of law Certificate of Dec encl
CHANE, P A Pacific Gas & Electric Co 79/04/09 20pp

79052040358 Errata to 790325 proposed findings of fact & conclusions of
law
CHANE, P A Pacific Gas & Electric Co 79/04/09 2pp

7905200137 Initial decision authorizing Director of Div of Nuclear
Reactor Regulation to make such addl findings on contested
matters as may be necessary to issue full-term DL
Certificate of Dec encl
TOUMTELLOTTE, J J KATCHEM, E G Branch 4 KATCHEM, E G
Regulations Division 79/04/10 10pp

7905200470 Requests that rebuttal to joint intervenors' proposed
findings of fact be amended to ref ASL 790329 order
CHANE, P A Pacific Gas & Electric Co 79/04/11 1p

7905200370 Forwards corrected pages to NRC 790410 proposed findings,
changing words "Initial Decision" to "Conclusions of Law"
TOUMTELLOTTE, J J Branch 4 79/04/12 3pp

7905200726 Response to 790316 & 790321 1st re requesting denial of DL
ASL will render issue moot to be included in docket file
of proceeding
ENELHARDT, T F Deputy Executive Legal Director 79/04/17 1p

7905200918 Forwards resolution adopted on 790416 Resolution requests
deferral of action on license application pending
determination that safety systems are adequate to ensure public
safety
HICKEL, H C Santa Barbara County, CA 79/04/18 1p

7905200602 Resolution of Board of Supervisors of Santa Barbara County,
CA urging NRC to defer final action on license application
until facility safety systems are adequate to ensure public
safety
MAYERS, IB Santa Barbara County, CA 79/04/18 1p

79052001018 Response to encl 1st re opening operation of facility because
of proximity to active earthquake fault & concern for
disposal of high level radioactive waste Materials being
considered by ASL
BENTON, S R Division of Project Management 79/04/30 3pp

79052040314 Requests denial w/o prejudice of joint intervenors' motion
to withhold issuance of DL Certificate of Dec encl
TOUMTELLOTTE, J J Branch 4 79/05/02 2pp

7905200607 Response in opposition to joint intervenors' request to
withhold issuance of DL Motion is untimely in whole form &
poorly based
ROMERS, E G Pacific Gas & Electric Co, GORDON, C Bnell &
Widener 79/04/24 4pp

7905200716 Act receipt of 790325 & 790404 1st re application to
operation of facility due to proximity to Hoag's Fault
Facility designed to withstand seismic event of 7.5 ASL is
preparing decision re licensing based on 790318 hearing.
BENTON, S R Office of Nuclear Reactor Regulation 79/05/14 9pp

DOCKETED ITEMS

7903200014 Expresses opposition to operation of facility due to possibility to impact health
MATERNAUSE, E Affiliation Unknown 79/04/26 1p

7903200020 Expresses opposition to operation of facility due to possibility to impact health
MATERNAUSE, E Affiliation Unknown 79/04/26 1p

G. General correspondence

7903200030 Requests immediate halt to work of facility
ANDREWS, H. House of Rep. 79/04/32 1p

7903200055 Notification of change of address for ED Criswellbaugh & B
Howard 10 1922 Hamilton Ave Suite B San Jose, CA 95128
COOPER, R. J. Real Technical Associates 79/04/25 1p

7903200071 Requests suspension of OL until necessary safety needs are implemented
BROWN, S. California State of 79/05/04 2pp

7903200085 Response to 790320 for re commitment concerns re granting of license to facility. Specific event of P 3 magnitude can be witnessed & quality of control is controlled by 790320 G0 program
GOSWAMI, L. V. Office of the Executive Director for Operations 79/05/06 2pp

H. Financial information

7903200018 Forwards "Annual Financial Rep 1978"
CRANE, P. A. Pacific Gas & Electric Co 79/03/23 1p

7903200024 "Annual Financial Rep 1978"
CRANE, P. A. Pacific Gas & Electric Co 79/03/24 40pp

7903200030 Forwards "Estimated Internal Fund Generation for CTR" & "Annual Financial Rep 1978"
CRANE, P. A. Pacific Gas & Electric Co 79/03/24 3pp

7903200039 "Annual Financial Rep 1978"
CRANE, P. A. Pacific Gas & Electric Co 79/03/23 30pp

I. Insurance & indemnity information

7903140012 Forwards Amend 4 to Indemnity Agreement 8-75 per 10CRF140 changes re increase in liability insurance from \$10 million to \$100 million effective 790312 Supporting documentation sent
BALTSMAN, J. Astronaut & Indemnity Group 79/05/01 4pp

7903140045 Forwards Amend executed Amendments 2) & 4 to Indemnity Agreement 8-75 & 9-75 respectively
CRANE, P. A. Pacific Gas & Electric Co 79/05/08 3pp

J. Advisory Committee on Reactor Safeguards reports & correspondence

7903100020 Response to request for written report after cancellations of ACRS 790301 stating re possibility of problem of instrument failure before staff report sent
CRACKER, L. P. Division of Project Management 79/03/20 5pp

K. Operating license stage documents & correspondence

7903200044 Response to NRC 790314 request for add info re containment purge valves. Forwards report of CRACOM program. Co calculates containment purge valve closing date calculated with data
CRANE, P. A. Pacific Gas & Electric Co 79/04/13 45pp

L. Inspection reports, DC Bulletin & correspondence

7903200046 Forwards 1E Insp Repts 80-278/79-05 & 80-283/79-03 re noncompliance noted
BROWN, H. E. Region 3, San Francisco, PWR Facility & Materials Safety Branch 79/03/19 2pp

7903200046 1E Insp Repts 80-278/79-05 & 80-283/79-03 re noncompliance noted. Major areas inspected including: in emergency planning, radioactive protection, staffing, respirators, protection, radioactive waste use & disposal. See California Annual Report, NRC, H. E. Region 3, San Francisco, Office of the Director. BROWN, H. E. Region 3, San Francisco, PWR Facility & Materials Safety Branch, 79/03/19 2pp

7903200047 Forwards 1E Insp Repts 80-278/79-05 & 80-283/79-03 re noncompliance noted. Major areas inspected including: in emergency planning, radioactive protection, staffing, respirators, protection, radioactive waste use & disposal. See California Annual Report, NRC, H. E. Region 3, San Francisco, Office of the Director. BROWN, H. E. Region 3, San Francisco, PWR Facility & Materials Safety Branch, 79/03/19 2pp

7903200048 1E Insp Repts 80-278/79-05 & 80-283/79-03 re noncompliance noted. Major areas inspected including: in emergency planning, radioactive protection, staffing, respirators, protection, radioactive waste use & disposal. See California Annual Report, NRC, H. E. Region 3, San Francisco, Office of the Director. BROWN, H. E. Region 3, San Francisco, PWR Facility & Materials Safety Branch, 79/03/19 2pp

7903200057 Forwards 1E Info Notice 79-04, "Wireless Analysis of Safety-Related Piping"
ENGLISH, R. H. Region 4, Dallas, Office of the Director 79/03/14 1p

7903200061 Forwards 1E Info Notice 79-07, "Review of Redwood Test"
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/03/26 1p

7903100023 Forwards 1E Bulletin 79-064, "Review of Operational Events & Management Identified During THE Incident"
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/14 1p

7903100024 Forwards 1E Bulletin 79-065, "Review of Operational Events & Management Identified During THE Incident"
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/14 1p

7903100029 Forwards 1E Bulletin 79-07, "Definite Stress Analysis of Safety-Related Piping - License action required"
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/14 1p

7903100031 Forwards 1E Bulletin 79-09, "Features of OR Age 2 & Circuit Breaker in Safety-Related Sys." license action required
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/17 1p

7903200064 Forwards 1E Bulletin 79-066, "Nuclear Incident at T-2-Bu-1"
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/21 1p

M. Reportable occurrences, LERs & related correspondence

7903110023 State notification breakdown reducing water storage and design efficiency
SCHEIDT, J. Hearings Division, 79/03/29 20pp

7903100060 Forwards 80-79-671
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/06 1p

7903100127 Forwards 80-79-678
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/11 1p

7903200023 Forwards 80-79-675
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/12 1p

7903100145 Forwards 80-79-677
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/13 1p

7903200045 Forwards 80-79-676
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/14 1p

7903200027 Forwards 80-79-676A,
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/20 1p

7903100423 Forwards 80-79-678
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/21 1p

7903100444 Forwards 80-79-676 & 40
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/22 1p

DOCKETED ITEMS

135

790302027 Forwards PNO-79-67AF
ENGLISH, M. H. Region 5, San Francisco, Office of the Director
79/04/25 1p

790302028 Forwards PNO-79-63AD
ENGLISH, M. H. Region 5, San Francisco, Office of the Director
79/04/26 1p

790302030 Forwards PNO-79-67AH
ENGLISH, M. H. Region 5, San Francisco, Office of the Director
79/04/27 1p

790307007 Forwards PNO-79-67AL per MEC 790401 ltr transmitting DE
Bulletin 79-05
ENGLISH, M. H. Region 5, San Francisco, Office of the Director,
79/03/01 1p

790309030 Submitte followup reply to 790404 notification of RO. During
progress of routine weld repairs on pipe rupture restraints,
cracking discovered in immediate vicinity of rupture. Full
range will be submitted
CRAMP, P. A. Pacific Gas & Electric Co 79/05/03 3pp

790310072 Forwards PNO-79-67AH
ENGLISH, M. H. Region 5, San Francisco, Office of the Director
79/05/07 1p

790324061 Ack receipt of 790303 ltr providing preliminary report re
cracking found in pipe rupture restraints
ENGLISH, M. H. Region 5, San Francisco, Office of the Director
79/05/16 1p

--790324070 Discusses situation reported to IE on 790404 re cracking
in pipe rupture restraints. Details program of investigation
based on crack severity will be forwarded
CRAMP, P. A. Pacific Gas & Electric Co 79/05/03 3pp

T. Hearing transcripts on non-antitrust matters

790303044 Corrections to transcripts from Dec 1970 & Jan 1979
Hearings Certificate of Doc. ent
HOBBS, J. C. + FORBES, H. J. CRAMP, P. A. Pacific Gas & Electric Co
79/04/04 20pp

790324023 Requests info re C. H. Hinkle 790305 ltr of concerns about
granting of license to child
LAWRENCE, J. R. House of Reps 79/03/20 1p

DOCKET 80-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

1. Insurance & indemnity information

790324099 Forwards Endorsement 33 to MARIU Policy HP-60
GRAHAM, W. E. Carolina Power & Light Co 79/04/25 3pp

790324067 Forwards Endorsement 33 to RELIA Policy HP-218
GRAHAM, W. E. Carolina Power & Light Co 79/04/25 2pp

790307077 Confirms increased liability limit to \$124,000,000 for
policies HP-22, 43, 76, 83, 106, 111, 142, 146, 151, 161, 164, 170,
173, 174, 179, 180, 182, 185, 186, 187, 188, 189, 192, 192, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
WATTHROGHT, J. American Nuclear Insurers 79/03/01 1p

790307082 Confirms increase in liability limit to \$36,000,000 for
policies HP-22, 43, 76, 83, 106, 111, 142, 146, 151, 161, 164, 170,
173, 174, 179, 180, 182, 185, 186, 187, 188, 189, 192, 192, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
ROBERTO, R. M. Mutual Atlantic Energy Liability Underwriters 79/05/03 1p

790314056 Forwards Amend 9 to Indemnity Agreement B-71 per 100FR140
changes re increase in liability insurance from \$440 million
to \$160 million, effective 790301 Supporting documentation
MCCI
BALTIMAN, J. A. Indemnity & Insurance Group 79/03/01 4pp

790317023 Forwards Amend 9 to Indemnity Agreement B-42 & B-71
reflecting increase in primary liability insurance provided
by AMI/RELIA
BARRETT, C. D. Douglas & Barham 79/03/11 3pp

P. Operating license stage documents & correspondence

790303030 Submitte exceptions & corrections to operations & program
for AME code for instrumentation & electrical equipment &
mechanical equipment & age for count phase
UTLEY, E. E. Carolina Power & Light Co 79/04/23 3pp

790303058 Responds to 790312 request for termination of leveling
portion of 790410 Phase 1 "Test Program for System
Monitoring - Approval request to terminate program
DPPOLITO, T. A. Operating Reactors Branch 79/04/25 3pp

790304024 Requests Tech Spec change re trip feature, annunciator
circuit to minimize operator confusion & stop valve
UTLEY, E. E. Carolina Power & Light Co 79/04/27 30pp

790308043 Submitte schedule for implementing suggested offgas age in
response to 790312 ltr Clarify feasible data for sampling
and testing & construction of age availability in 851031
UTLEY, E. E. Carolina Power & Light Co 79/05/01 1p

790308047 Responds to 790319 ltr re containment purging during normal
plant operation Should UOCC occur during normal
operation of ECCO age would not be affected Supporting info
ent
UTLEY, E. E. Carolina Power & Light Co 79/05/01 4pp

790309046 Provides results of GE analysis of prompt recirculation pump
trip for Cycle 3 operation MEC should be able to license
Cycle 3 operation until adequate recirculation pump trip
will be tested during facility startup
UTLEY, E. E. Carolina Power & Light Co 79/05/01 1p

790310070 Responds to MEC 790312 ltr re schedule for implementing
suggested offgas age. New hydrogen recombiners installed on
Frank and Rita will be operable by 851031
UTLEY, E. E. Carolina Power & Light Co 79/05/01 1p

790324063 Forwards airtight map & photo attachments to child 790129
reply on main dam core branch features. MFC drawings
FLORIO, G. D. Carolina Power & Light Co 79/05/06 3pp

790309020 Forwards summary of DOE Nuclear-Int resolution/Documentation
of allow flexibility error which existed in versions of
PIER, piping analysis computer program from Jan-Oct 1969
Review & reanalysis included All work through Dec 1970
ROBERT, F. L. DOE Nuclear, Inc. 79/05/01 2pp

--790303060 Forwards DOE Nuclear, Inc. list of BLM & piping age which
could have been impacted by deficient computer program
GE has no record of reanalysis for Copper piping age
HOBBS, J. C. + FORBES, H. J. CRAMP, P. A. Pacific Gas & Electric Co
79/01/24 10pp

790303070 Confirms & formalizes 790301 verbal commitment re seismic
concerns & ltr of re-evaluated piping. Comments
statements re reanalysis of circulation loops
UTLEY, E. E. Carolina Power & Light Co 79/03/02 3pp

Q. Inspection reports, IE Bulletins & correspondence

790310465 Forwards IE Insp Repts 80-324/79-05 & 80-325/79-05 on
790128-06 No noncompliance noted
LEWIS, R. C. Region 5, Atlanta: Reactor Operations Nuclear Support
Branch 79/03/14 2pp

--790303040 IE Insp Repts 80-325/79-05 & 80-324/79-05 on 790128-06. No
noncompliance noted. Major areas inspected radiological
airborne monitoring program, environment monitoring station &
data analytical sensitivity & control measures
ROBERT, F. L. Region 5, Atlanta: Reactor Operations Nuclear
Support Branch 79/03/09 3pp

790310158 Forwards SE Info Notice 79-06, "Breath Analysis of
Hazard-Related Piping" Region 5, Atlanta, Office of the Director
O'REILLY, J. P. 79/03/23 3pp

790303074 Forwards IE Info Notice 79-07, "Structure of Redundant Tanks"
O'REILLY, J. P. Region 5, Atlanta, Office of the Director
79/03/24 2pp

790305099 Forwards IE Info Notice 79-08, "Interconnection of
Contaminated Age W/Off Air Age Used as Source of Breathing
Air"
O'REILLY, J. P. Region 5, Atlanta, Office of the Director
79/03/26 2pp.

790310146 Forwards IE Info Notice 79-09, "Bill of Radiologically
Contaminated Rein"
O'REILLY, J. P. Region 5, Atlanta, Office of the Director,
79/03/30 3pp.

790304061 Forwards IE Insp Repts 80-324/79-10 & 80-325/79-10 on
790307-07 No noncompliance noted.
ROBERT, F. L. Region 5, Atlanta, Office of the Director, 79/04/06
2pp

DOCKETED ITEMS

136

- 7705200405 IE Insp Repts 50-324/79-10 & 50-325/79-10 on 770520-07 No
noncompliance noted Power areas inspected (interior only)
procedures & logs data & evaluation & special
attribution Insp of Reactor Support Branch 7/9/81/05
BAMN, H. J. Region 2, Atlanta, Office of the Director 7/9/81/05
App
- 7705100241 Response to IE Bulletin 79-00 No welded pipe from Thompson
Heating & Engineering is used or planned for use
VILK, E. E. Carolina Power & Light Co. 7/9/81/12 1p
- 7705200209 Act receipt of 770502 ltr informing MRC of steps taken to
correct violations noted in IE Insp Rept 50-324/79-07 &
50-325/79-07
Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 7/9/81/12 1p
- 7705200223 Response to MRC 770509 ltr re violations noted in IE Insp
Rept 50-324/79-07 & 50-325/79-07 CP corrective actions
& individuals have been commended on performing data reviews &
on corrective actions
BAMN, H. J. Carolina Power & Light Co. 7/9/81/02 2pp
- 7705200229 Forwarded IE Insp Repts 50-324/79-07 & 50-325/79-07 on
7705-0202 & notice of violation
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 7/9/81/09 2pp
- 7705200237 Notice of violation from ltr re 770130-0202
& Region 2, Atlanta, Office of the Director 7/9/81/09 1p
- 7705200243 IE Insp Repts 50-324/79-07 & 50-325/79-07 on 770520-0202
noncompliance noted state time for valve PGM was above
max time required by Tech Specs Three Independent Review
failed on nine points
VILK, E. E. - MERRITT, R. H. Region 2, Atlanta, Office of the
Director BAMN, H. J. Region 2, Atlanta, Reactor Operations
Nuclear Support Branch 7/9/81/09 2pp
- 7705200463 Forwarded IE Bulletin 79-040, "Review of Operational Errors &
Key Missions Identified During TMI Incident"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
7/9/81/4 2pp
- 7705200468 Forwarded IE Bulletin 79-00, "Atomic Stress Analysis of
Safety-Related Piping - Licensee action required"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
7/9/81/4 1p
- 7705100496 Forwarded IE Bulletin 79-04, "Events Relevant to SRM
Identified During TMI Incident - Licensee action required"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
7/9/81/4 2pp
- 7705200541 Forwarded IE Bulletin 79-00, "Failure of GE Type A-8
Circuit Breaker to Safely-Related Sps - Licensee action
required"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
7/9/81/17 2pp
- 7705200573 Forwarded IE Bulletin 79-04, Revision 1, "Review of
Operational Errors & Key Missions Identified During TMI
Incident"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
7/9/81/10 2pp
- 7705100517 Forwarded restate paragraph from 770200 ltr submitted as
revision to SR program in response to IE Insp Repts
50-324/79-02 & 50-325/79-07 Paragraph discusses radiation
survey/measuring instruments
VILK, E. E. Carolina Power & Light Co. 7/9/81/04 2pp
- 7705200592 Response to IE Bulletin 79-00, "Atomic Stress Analysis of
Safety-Related Piping - MRC messages all remaining
safety-related piping as well as MRC all those specified
criteria is acceptable w/transporting documentation"
VILK, E. E. Carolina Power & Light Co. 7/9/81/24 2pp
- 7705200609 Response to IE Bulletin 79-01 Search of plant documentation
indicates no valves using check valves wider than 3-1/2
inches are used at facility
VILK, E. E. Carolina Power & Light Co. 7/9/81/06 1p
- 7705201048 Response to 770204 response to IE Bulletin 79-07 re
reanalysis of computer program used for safety-related
piping AEC program verified & has been performed by
trained MRC-approved personnel data
VILK, E. E. Carolina Power & Light Co. 7/9/81/18 2pp
- 7705200944 Forwarded response to 770514 request for addl info re safety
analysis of safety-related piping Reanalysis with a 770524
BAMN, H. J. Carolina Power & Light Co. 7/9/81/21 2pp
- B Per-logic operating reports & related correspondence
- 7705100341 Forwarded monthly operating report for Apr 1979
BAMN, H. J. Carolina Power & Light Co. 7/9/81/29 1p
- 7705100420 Monthly operating report for Apr 1979
MILLER, E. Carolina Power & Light Co. 7/9/81/31 10pp
- B Releasable correspondence: LHM & related correspondence
- 7705200345 Forwarded LHM 79-017/03L-0
BAMN, H. J. Carolina Power & Light Co. 7/9/81/30 1p
- 7705200347 LHM 79-017/03L-0 on 770404 RIR pages 2B & 2D would not
be failed to meet Tech Spec. Trip time caused by activation
time on installed switch being too slow Alternative
switching methods under evaluation
TOLLISON, A. C. Carolina Power & Light Co. 7/9/81/30 3pp
- 7705200400 Forwarded LHM 79-018/03L-0
BAMN, H. J. Carolina Power & Light Co. 7/9/81/07 1p
- 7705200408 LHM 79-018/03L-0 on 770404 pressure switch 2-616-PB-172
failed to meet Tech Spec. Trip time caused by activation
time on installed switch being too slow Alternative
switching methods under evaluation
TOLLISON, A. C. Carolina Power & Light Co. 7/9/81/07 1p
- 7705200409 Forwarded LHM 79-019/03L-0
BAMN, H. J. Carolina Power & Light Co. 7/9/81/07 1p
- 7705200421 LHM 79-019/03L-0 on 770405 electrical open circuit Ap-4 in
12 power lead to fan motor caused by junction box splice
between motor & controller
TOLLISON, A. C. Carolina Power & Light Co. 7/9/81/07 1p
- 7705200423 Bulletin 14-day radiological environ event reph Radiactive
waste was shipped on 770522 w/irradiation levels exceeding
ISO incident to be reviewed & health physics radiactive
shipment procedures revised
BAMN, H. J. Carolina Power & Light Co. 7/9/81/16 2pp
- 7705200426 Forwarded LHM 79-020/03L-0
BAMN, H. J. Carolina Power & Light Co. 7/9/81/18 1p
- 7705200441 LHM 79-020/03L-0 on 770421 while performing standby zero
control, failed valve test, failed valve lifted at 1-250 lb
Caused by retaining strap. Retaining strap tested
satisfactorily & returned to svc
TOLLISON, A. C. Carolina Power & Light Co. 7/9/81/18 1p
- 7705200404 Forwarded LHM 79-021/03L-0
BAMN, H. J. Carolina Power & Light Co. 7/9/81/24 1p
- 7705200500 LHM 79-022/03L-0 on 770422 12 shutdown failed inspection
failed to test up No apparent cause observed. Eight used
valves when used & eight others replaced Remaining
three shutdowns failed to bleed two valves one replaced
TOLLISON, A. C. Carolina Power & Light Co. 7/9/81/24 2pp
- 7705200501 Forwarded LHM 79-021/03L-0
BAMN, H. J. Carolina Power & Light Co. 7/9/81/25 1p
- 7705200577 LHM 79-021/03L-0 on 770425 during leak, five Bergen Paines
shutdown failed caused by low fluid level in seal failure
Shutdowns results & returned to svc
TOLLISON, A. C. Carolina Power & Light Co. 7/9/81/25 2pp
- 7705200579 Forwarded LHM 79-022/03L-0
BAMN, H. J. Carolina Power & Light Co. 7/9/81/25 1p
- 7705200589 LHM 79-022/03L-0 on 770425 while in cold shutdown, rear
completion of refueling outage, water chemistry test West
limits exceeded Caused by excessive condensate coil leakage
causing partial withdrawal from tank
TOLLISON, A. C. Carolina Power & Light Co. 7/9/81/25 2pp
- 7705200587 Forwarded LHM 79-023/03L-0
BAMN, H. J. Carolina Power & Light Co. 7/9/81/26 1p

DOCKETED ITEMS

137

--790309097 LER 79-032/031-0 on 790428, while performing visual insp of inaccessible areas. Grinnell snubbers failed. Caused by low fluid level. All snubbers disassembled, inspected & rebuilt.
TOL,LSB;A C Carolina Power & Light Co 79/03/29 1p

66667 90-028 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

J Insurance & Indemnity Information
79/03/29 1p

790304079 Forwards Endorsement 08 to NRC Policy 79-03

SWAN, H E Carolina Power & Light Co 79/04/03 2pp

790304087 Forwards Endorsement 09 to NRC Policy 79-03

SWAN, H E Carolina Power & Light Co 79/04/03 2pp

790305097 Confirms increased liability limit to \$104,000,000 for
policy No. 1-25, 43, 76-52, 100, 111, 140, 154, 161, 164, 170,
174, 176, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
SNT/RS/DB/1 J American Nuclear Insurance 79/05/01 1p

790310091 Forwards Amend 9 to Indemnity Agreement 8-71 per 105/8140
request. Increase in liability insurance from \$100 million
to \$400 million effective 7/9/81 Supporting documentation
enc.
SNT/RS/DB/1 J American Nuclear Insurance 79/05/01 1p

790310093 Forwards Amend 9 to Indemnity Agreement 8-71

reflecting increase in primary liability insurance provided by
ANIL/RS/DB/1 J American Nuclear Insurance 79/05/01 1p

8. Operating license stage documents & correspondence

790309193 Submits exceptions & corrections to operations QA program
re ANSI codes for instrumentation & electrical equipment &
mechanical equipment & use for control plans
ULFV, L & Carolina Power & Light Co 79/04/23 3pp

790309026 Notification of 790428 meeting w/ULFV & GE in Bethesda, MD to
resolve questions on proposed recirculation pump trip
feature for end-of-cycle metal enhancement
HAGSBA, J H Operating Reactors Branch 3 79/04/23 1p

790310100 Responds to 790312 request for termination of leveling
portion of 790310 Phase 1 "RSP" Program for Seismic
Monitoring - Approves request to terminate program
ULFV, L & A Operating Reactors Branch 3 79/04/23 2pp

790304024 Requests Tech Spec change re trip feature, annunciation
clarity to minimize operator confusion & alarm valve
ULFV, E E Carolina Power & Light Co 79/04/27 1pp

790310022 Notification of 790420 meeting w/ULFV & GE in Bethesda, MD
to resolve questions on proposed recirculation pump trip
feature for end-of-cycle metal enhancement
HAGSBA, J H Operating Reactors Branch 3 79/04/30 1p

790305042 Submits schedule for implementing augmented offgas sys on
response to 790312 1st Earliest feasible date for completing
modification & demonstration of sys operability is 8/81
ULFV, E E Carolina Power & Light Co 79/05/01 1p

790309041 Responds to 790319 1st re containment purging during normal
plant operation. Should LDA occur during operations,
operation of EGS sys would not be affected. Supporting info
enc.
ULFV, E E Carolina Power & Light Co 79/05/01 4pp

790310274 Responds to NRC 790319 1st re schedule for implementing
augmented offgas sys. New hydrogen recombiners installed on
front end sys will be operable by 8/1/81
ULFV, E E Carolina Power & Light Co 79/05/01 1p

790306049 Forwards overlaid maps & photo attachments to 790312
req on main dome core branch features. M/Fs drawings
FLDSD, W B Carolina Power & Light Co 79/05/01 3pp

790306020 Forwards summary of ESB Nuclear, Inc resolution/documentation
of allow flexibility error which existed in versions of
PDRS piping analysis program. From Jan-Oct 79
Review & reanalysis included all work through Dec 1979
PDRS, P L ESB Nuclear, Inc 79/05/01 4pp

--790305025 Forwards ESB Nuclear, Inc list of SRRs & piping sys which
could have been impacted by deficient computer program
SE has no record of reanalysis for Cooper piping sys
BUPH/MS, P M General Electric Co, Nuclear Energy Products Div
79/04/24 1pp

790305025 Confirms & formalizes 790320 verbal commitment re seismic
comparison & insp of safety-related piping documents
statements re analysis of circulation loops
ULFV, E E Carolina Power & Light Co 79/05/02 2pp

Q Inspection reports, IE Sublines & correspondence

790301045 Forwards IE Insp Rpts 30-324/79-03 & 30-325/79-08 on
790132-24 Re noncompliance noted
LMBH, H C Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/03/14 2pp

--790301046 IE Insp Rpts 30-325/79-05 & 30-324/79-05 on 790132-24 Re
noncompliance noted. Major areas inspected: radiological
monitoring monitoring program, monitor monitoring station &
data, analog sensitivity & control measures
PDRS, H H Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/09 2pp

790301048 Forwards IE Info Notice 79-04, "Stress Analysis of
Safety-Related Piping"
D'NEELY, J P Region 2, Atlanta, Office of the Director
79/03/23 2pp

790303024 Forwards IE Info Notice 79-07, "Capture of Radiactive Tanks"
D'NEELY, J P Region 2, Atlanta, Office of the Director
79/03/26 2pp

790301045 Forwards IE Info Notice 79-08, "Interconnection of
Containment Sys w/Off Air Sys Used on Source of Breaching
Air"
D'NEELY, J P Region 2, Atlanta, Office of the Director
79/03/26 2pp

790301046 Forwards IE Info Notice 79-09, "Shift of Radioactively
Contaminated Resin"
D'NEELY, J P Region 2, Atlanta, Office of the Director
79/03/26 2pp

790304044 Forwards IE Insp Rpts 30-324/79-10 & 30-325/79-10 on
790304-07 Re noncompliance noted
HAGSBA, J H Region 2, Atlanta, Office of the Director 79/04/06
2pp

--790304045 IE Insp Rpts 30-324/79-10 & 30-325/79-10 on 790304-07 Re
noncompliance noted. Major areas inspected: inactive insp
program procedures & insp data & evaluation & spatial
ultrasonic insp of recirculation loop inlet safeguards
LMBH, J J Region 2, Atlanta, Office of the Director 79/04/06
2pp

790310024 Responds to IE Bulletin 79-09 Re welded pipe from Youngstown
Holding & Engineering is used or planned for use
ULFV, E E Carolina Power & Light Co 79/04/13 1p

790303020 Ack receipt of 790402 1st informing NRC of steps taken to
correct violations noted in IE Insp Rpts 30-324/79-07 &
30-325/79-07
LMBH, J J Region 2, Atlanta, Reactor Operations Nuclear Support
Branch 79/04/12 1p

--790303020 Responds to NRC 790309 1st re violations noted in IE Insp
Rpts 30-324/79-07 & 30-325/79-07. Corrective actions
individuals have been consulted on performing defect reviews &
on corrective actions
FLDS, B J Carolina Power & Light Co 79/04/06 2pp

--790303020 Forwards IE Insp Rpts 30-324/79-07 & 30-325/79-07 on
790132-0022 & notice of violation
LMBH, H C Region 2, Atlanta, Reactor Operations Nuclear
Support Branch 79/03/09 2pp

--790303020 Notice of violation from Insp on 790132-0022
& 30-325/79-07
Region 2, Atlanta, Office of the Director 79/03/09 1p

DOCKETED ITEMS

- 7903200243 IE Insp Reps 30-084/79-07 & 30-023/79-07 on 790319-0200
Noncompliance noted stroke lines for valve POMS was above
was time-sequenced by Tech Reps Three independent review
failed to note position
Region 2: Atlanta, Office of the
Director, S&S/C E Region 2: Atlanta, Reactor Operations
Nuclear Support Branch 7/9/04/04 App
- 7903200163 Forwards IE Bulletin 79-05B, "Review of Operational Errors &
Key Missions Identified During TME Incident"
O'REILLY, J P Region 2: Atlanta, Office of the Director
7/9/04/14 App
- 7903200288 Forwards IE Bulletin 79-07, "Self-Stress Analysis of
Safety-Related Piping - Licensee action required"
O'REILLY, J P Region 2: Atlanta, Office of the Director
7/9/04/14 App
- 7903200476 Forwards IE Bulletin 79-08, "Events Relevant to S&S
Identified During TME Incident"
Region 2: Atlanta, Office of the Director
O'REILLY, J P 7/9/04/14 App
- 7903200344 Forwards IE Bulletin 79-09, "Evaluation of SE Type AM-2
Circuit Breaker in Safety-Related Sys - Licensee action
required"
O'REILLY, J P Region 2: Atlanta, Office of the Director
7/9/04/14 App
- 7903200273 Forwards IE Bulletin 79-06A, Revision 1, "Review of
Operational Errors & Key Missions Identified During TME
Incident"
O'REILLY, J P Region 2: Atlanta, Office of the Director
7/9/04/18 App
- 7903200517 Forwards contained paragraph from 790300 11p, submitted as
revision to QA program, in response to IE Insp 30-084/79-07 &
30-023/79-07 Paragraph discusses radiation
survey/measuring instruments
UTLEY, E E Carolina Power & Light Co 7/9/04/20 App
- 7903200192 Response to IE Bulletin 79-07, "Dynamic Stress Analysis of
Safety-Related Piping - Will redesign all remaining
unsatisfactory piping as soon as S&S act. that specified
criteria is acceptable. Misreporting documentation"
UTLEY, E E Carolina Power & Light Co 7/9/04/24 App
- 7903200289 Response to IE Bulletin 79-08 Search of plant documentation
indicates no Valve used check valves w/diameter of 3-10
inches are used at facility
UTLEY, E E Carolina Power & Light Co 7/9/04/30 App
- 7903200165 Supplement 790436 response to IE Bulletin 79-07 re
reanalysis of computer program used for safety-related
piping. Additional computer verification has been performed by
Homing S&S-approved benchmark cases
UTLEY, E E Carolina Power & Light Co 7/9/05/10 App
- 7903200344 Forwards response to 790314 request for addl info re seismic
analysis of safety-related piping. Supplemental skill's 790436
& 790314 responses to IE Bulletin 79-07
FURR, B J Carolina Power & Light Co 7/9/05/01 App.
- B. Periodic operating reports & related correspondence**
- "a monthly operating rep for Apr 1979."
"a Rep & Light Co 7/9/05/09 App
- req for Apr 1979
Light Co 7/9/05/09 App
- related correspondence ---
- 7903200084 Forwards LER 79-010/02L-0 W/o encl
FURR, B J Carolina Power & Light Co 7/9/05/04 App
- 7903200018 LER 79-010/02L-0 on 790404 several Tech Spec items not
performed at proper intervals. Caused by oversight in
procedures. Periodic testing procedures revised.
TOLLISON, A C Carolina Power & Light Co 7/9/05/04 App
- 7903200321 Forwards LER 79-020/02L-0
FURR, B J Carolina Power & Light Co 7/9/05/07 App.
- 7903200324 LER 79-020/02L-0 on 790408 during containment isolation
valve leak test rate leak isolation valves did not shut & leak
had pressure. Caused by valve bushing wear. Bushings
replaced.
TOLLISON, A C Carolina Power & Light Co 7/9/05/07 App
- 7903200048 Forwards LER 79-010/02L-0
FURR, B J Carolina Power & Light Co 7/9/05/07 App
- 7903200049 LER 79-010/02L-0 on 790417 during leak of drive protease
sys isolation valves for makeup water treatment area
operator sys were shut caused by isolation valves being
isolated due to extensive use of fire protection sys
TOLLISON, A C Carolina Power & Light Co 7/9/05/07 App
- 7903200423 Forwards LER 79-010/02L-0
FURR, B J Carolina Power & Light Co 7/9/05/07 App
- 7903200539 LER 79-010/02L-0 on 790419 while performing normal surp
of dryup operator discovered 1-0AM/V10 isolation valve
would not shut caused by pneumatic flow restrictor in
circuit being closed, preventing valve from closing
TOLLISON, A C Carolina Power & Light Co 7/9/05/09 App
- 7903200304 Forwards LER 79-010/02L-0
FURR, B J Carolina Power & Light Co 7/9/05/09 App
- 7903200518 LER 79-010/02L-0 on 790414 main steam relief valve open
SD 10 psi & immediately resulted resulting reactor scram due
to high flow spike on intermediate range monitors
TOLLISON, A C Carolina Power & Light Co 7/9/05/09 App
- 7903200412 Submits 14-day radiological environ event rep reselection
water was shipped on 790505 irradiation levels exceeding
ETB incident to be reviewed & health physics radonics
shipment procedures revised
BARNES, H R Carolina Power & Light Co 7/9/05/10 App
- 7903200342 Forwards LER 79-030/02L-1
BARNES, H R Carolina Power & Light Co 7/9/05/10 App
- 7903200343 LER 79-030/02L-1 on 790512 while performing evap water leak
comps test high vibration levels discovered. Caused by
restriction bushing seized due to stretching of shaft. New layer
installed
TOLLISON, A C Carolina Power & Light Co 7/9/05/10 App
- 7903200331 Forwards LER 79-010/02L-1
BARNES, H R Carolina Power & Light Co 7/9/05/10 App
- 7903200349 LER 79-010/02L-1 on 790508 Bergen-Peterson scrubber
001-1AB01 failed to shut up cause undetermined whether
disconnected & now again installed
TOLLISON, A C Carolina Power & Light Co 7/9/05/10 App
- 7903200347 Forwards LER 79-010/02L-1
BARNES, H R Carolina Power & Light Co 7/9/05/10 App
- 7903200373 LER 79-010/02L-1 on 790504 while performing HPCI system
response test, HPCI turbine failed response assembly
Caused by misalignment of parameters on governor assembly
assembly realigned
TOLLISON, A C Carolina Power & Light Co 7/9/05/10 App
- 7903200420 Forwards LER 79-020/02L-0
FURR, B J Carolina Power & Light Co 7/9/05/21 App
- 7903200437 LER 79-020/02L-0 on 790420 1-0AC-1203 dryup/L hydrogen
system monitor went abnormally low reading caused by fused
level switch for condensate pot preventing moisture buildup
from draining.
TOLLISON, A C Carolina Power & Light Co 7/9/05/21 App
- 7903200413 Forwards LER 79-010/02L-0
BARNES, H R Carolina Power & Light Co 7/9/05/21 App
- 7903200419 LER 79-010/02L-0 on 790417 while auxiliary operator was
sampling clearance on HMB pump 3A & 3C control operator
noticed pump was still energized. Caused by clearance
locking Unit 1 instead of Unit 2. Clearance was corrected
TOLLISON, A C Carolina Power & Light Co 7/9/05/21 App
- 7903200425 Forwards LER 79-010/02L-0
BARNES, H R Carolina Power & Light Co 7/9/05/21 App
- 7903200429 LER 79-010/02L-0 on 790428 no indication at notch 34 for
control rod 34-27 Caused by short in switch for notch 34
wire insulated & switch returned to work
TOLLISON, A C Carolina Power & Light Co 7/9/05/24 App
- 7903200512 Forwards LER 79-020/02L-0
BARNES, H R Carolina Power & Light Co 7/9/05/25 App

DOCKETED ITEMS

139

79050300518 LER 79-023/00L-2 on 790429 control rod 10-07 did not have indication as notch caused by electrical problem in prototypic inlet piping probe located in drywell Problem will be corrected at next outage when spew is accessible TOLLESON, A.C. Carolina Power & Light Co 79/05/25 1p

DOCKET 50-036 UNIV. OF CALIFORNIA AT RIVERSIDE REACTOR

J Insurance & indemnity information

79051600231 Forwards Amend 3 to Indemnity Agreement E-03 per 10CFR140 changes re liability increased from \$100 million to \$150 million effective 7/9/01 Supporting documentation was MALTRIN, J. Antitrust & Indemnity Group 79/05/01 8pp

DOCKET 50-037 BEAUVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

79050300682 Response to 790412 ltr requesting facility be responsible for monitoring discharges Monitoring to be placed by TOL & required by NRC ltr is being referred to NRC for more specific responses WAPLEMAN, C H. Environmental Protection Agency 79/04/26 1p

DOCKET 50-037 BEAUVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

79050400300 Forwards description of filters to remove air discharged from auxiliary sump changes implemented pursuant to 740703-01 GL hearings HILLMAN, J E. Tennessee Valley Authority 79/04/30 4pp

79050700354 Requests mod of stake verification of Nabl Pollution Discharge Elimination Sys permit 790026450 re construction of W. K. ROGERS, D O. Tennessee Valley Authority 79/05/01 2pp

79050100346 Submits Amend 61 to Application consisting of revisions to certain chapters, responses & revised responses to NRC questions further documentation to items already transmitted & FBR text changes W's sent GILLESPIE, J E. Tennessee Valley Authority 79/05/24 1p

E NRC Safety Evaluation Report (SER), reply & correspondence

79051000056 Forwards TVA's responses to five SER outstanding confirmatory items Responses will be incorporated into Amend 61 of FBR GILLESPIE, J E. Tennessee Valley Authority 79/05/08 4pp

79052300317 Forwards comments from review of Mar 1979 SER apparent discrepancies between SER content & info provided to NRC supporting license application GILLESPIE, J E. Tennessee Valley Authority 79/05/17 8pp

F Security, medical, emergency & fire protection plans

79051900441 Forwards comments which should be incorporated into modified amended security plan Comments withheld (ref 10CFR2 7901) VANDER, B A. Light Meter Reactors Branch 4 79/04/27 2pp

79050700426 Forwards revisions to physical security plan Revisions withheld (ref 10CFR2 7901) GILLESPIE, J E. Tennessee Valley Authority 79/05/08 1p

79050900041 Submits requested info on radiological emergency plan. Changes state plan consistent w/ NRC responses to NRC questions on Watts Bar Nuclear Plant. Will forward final response by 790413 GILLESPIE, J E. Tennessee Valley Authority 79/05/07 18pp

J Insurance & indemnity information

79050100257 Forwards AMI Secondary Financial Protection Binder E8-66 00000, R H. Marsh & McLennan; M H H Nuclear Consultants; Inc. 5/19 79/04/25 6pp

79050700497 Confirms increased liability limit to \$124,000,000 for policies WP-1, 25, 45, 70, 75, 105, 111, 140, 144, 151, 161, 164, 170, 173, 174, 176, 178, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 199, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, 216, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

79050700502 Confirms increase in liability limit to \$24,000,000 for policies WP-25, 26, 29, 30, 35, 44, 45, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87, 88, 90, 91, 92, 93, 94, 95 & 96 ROBERTS, D M. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

79051600230 Forwards Amend 3 to Indemnity Agreement E-02 per 10CFR140 changes re liability increased from \$100 million to \$150 million effective 7/9/01 Supporting documentation was MALTRIN, J. Antitrust & Indemnity Group 79/05/01 8pp

K Utility Final Safety Analysis Report (FSAR) & amendments

7905060009 Amend 61 to FSAR Tennessee Valley Authority 79/05/25 200pp

79050300335 Forwards nonnegotiating version of FSAR table 07 A0-1, as revised by Amend 61 GILLESPIE, J E. Tennessee Valley Authority 79/05/25 3pp

P Operating license stage documents & correspondence

79050300490 Discusses 790313 letters w/ Bero of Westinghouse re incorrect weights for Vela Model C580 A-inch check valves used in safety injection sys SCHENCK, A C. Operating Reactors Branch 1 79/05/02 1p

O Inspection reports, DE Bulletins & correspondence

79050200439 Forwards DE Insap Repts 50-027/79-13 & 50-028/79-08 as 790502-09 No noncompliances noted HOFFMAN, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/08 2pp

79050300442 IE Insap Repts 50-027/79-13 & 50-028/79-08 as 790502-09 No noncompliances noted Major areas inspected auxiliary sump, control station, storage & housekeeping of electrical panels & review of instrumentation records WATKINS, D M. Region 2, Atlanta, Office of the Director, Reactor Construction & Engineering Support Branch 79/03/07 3pp

79050300510 Forwards IE Insap Repts 50-027/79-14 & 50-028/79-04 as 790502-13 No noncompliances noted WATKINS, D M. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/14 2pp

79050300544 IE Insap Repts 50-027/79-14 & 50-028/79-04 as 790502-13 No noncompliances noted Major areas inspected aux control, auxiliary monitoring data, analytical sensitivity for radiological samples & QC measures PERCY, W M. Region 2, Atlanta, Fuel Facility & Materials Safety Branch WATKINS, D M. Region 2, Atlanta, Office of the Director 79/03/13 2pp

79052400212 Forwards IE Insap Repts 50-027/79-11 & 50-028/79-04 as 790502-07 No noncompliances noted HOFFMAN, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/20 2pp

79050400337 IE Insap Repts 50-027/79-11 & 50-028/79-04 as 790502-07 No noncompliances noted Major areas inspected licensee action as previous insap findings & review qualification of safety-related equipment GILLESPIE, J E. Region 2, Atlanta, Office of the Director, Reactor Construction & Engineering Support Branch 79/03/14 2pp

79050100211 Forwards IE Info Notice 79-06, "Brexit Analysis of Safety-Related Piping" GILLESPIE, J E. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905010113 Forwards IE Info Notice 79-06, "Subcommittee of Contaminated Sys w/for Air Sys Used as Source of Breathing Air" GILLESPIE, J E. Region 2, Atlanta, Office of the Director 79/03/28 2pp

7905010260 Forwards IE Info Notice 79-09, "Upshot of Radioactivity Contaminated Basin" GILLESPIE, J E. Region 2, Atlanta, Office of the Director 79/02/20 2pp

DOCKETED ITEMS

7903200403 Forwarded DE Inps Rept 79-327/79-16 re 790321-0216 No nonconformance noted
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch
79/04/04 App

7903200404 DE Inps Rept 79-327/79-16 re 790321-0216 No nonconformance noted
Major areas inspected startup test procedures: steam testing, fuel handling equipment testing & review of Jordan analysis procedures
WRIGHT, J. J., SAGUD, R. C. Region 2, Atlanta, Office of the Director, WASHINGTON, D. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch
79/04/03 App

7903200328 Forwarded IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'NEILL, J. P. Region 2, Atlanta, Office of the Director
79/04/14 App

7903200323 Forwarded IE Bulletin 79-06, "Review of Operational Errors & System Misalignments Identified During TMI Incident."
O'NEILL, J. P. Region 2, Atlanta, Office of the Director
79/04/14 App

790310360 Forwarded IE Bulletin 79-06, "Events Relevant to Boiling Water Reactor Systems Identified During TMI Incident."
O'NEILL, J. P. Region 2, Atlanta, Office of the Director
79/04/14 App

7903200324 Forwarded IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'NEILL, J. P. Region 2, Atlanta, Office of the Director,
79/04/16 App

7903200319 Forwarded IE Bulletin 79-09, "Failures of 3E Type 40-2 Circuit Breaker in Safety-Related Sys." Licensee action required
O'NEILL, J. P. Region 2, Atlanta, Office of the Director
79/04/17 App

7903200419 Forwarded IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & System Misalignments Identified During TMI Incident."
O'NEILL, J. P. Region 2, Atlanta, Office of the Director
79/04/18 App

7903200323 Submits supplemental response to IE Bulletin 79-07 Original response submitted 790120. Provides add info located from manufacturer & describes plans to area of electrical penetrations
GILLESLAND, J. E. Tennessee Valley Authority
79/04/27 App

790310072 Responds to IE Bulletin 79-06A & 79-06A, Revision 1 re review of operational errors during TMI. Pressurizer level bistables in combined safety injection logic circuits will remain tripped except during injection logic circuits will proceed
GILLESLAND, J. E. Tennessee Valley Authority
79/05/07 App

7903200362 Forwarded Revision 7 to "Preventive Baseline Inp & Inservice Inp Program For TMI" incorporating responses to Batt Engineering Branch 790200 questions
GILLESLAND, J. E. Tennessee Valley Authority
79/05/08 83pp

----- TMI & related correspondence -----

deficiency rept re vibration in

authority 79/03/29 App
during preoperational pipe
scurried near
vibration of RHM flow
g shielded.
89 App

----- RHM deficiency rept re RHM pump 1A natural frequency
GILLESLAND, J. E. Tennessee Valley Authority
79/03/27 App

7903100407 Final deficiency rept forced vibration test showed RHM pump 1A natural frequency does not meet design requirements. RHE 1A was identified, resulting in changed flexure loads on pump & initial pipe supports to meet the support loads.
Tennessee Valley Authority
79/03/27 App

790310446 Forwarded Final deficiency rept re safety injection sys accumulator level transmitter lines.
GILLESLAND, J. E. Tennessee Valley Authority
79/05/08 App

790310443 Final deficiency rept use of Class C instead of Class B safety injection sys accumulator level transmitter lines. Final rept values to change. Nonaccepting prediction: nonaccepting Category 1 piping will be replaced.
Tennessee Valley Authority
79/05/08 App

7903100336 Forwarded final deficiency rept re overheating of bearings motor-driven auxiliary feedwater pumps.
GILLESLAND, J. E. Tennessee Valley Authority
79/04/09 App

7903100303 Final deficiency rept, during initial operation, bearings motor-driven auxiliary feedwater pumps were overheating. Caused by design error: Supercoil-Ram presently modifying pumps.
Tennessee Valley Authority
79/04/09 App

7903104046 Forwarded final deficiency rept re incorrect analysis of essential raw cooling water sys piping near total temp ramps.
GILLESLAND, J. E. Tennessee Valley Authority
79/04/18 App

7903104073 First interim deficiency rept essential raw cooling water sys piping in auxiliary bldg Piping not analyzed for full thermal range defined in APRC code. Analysis in progress.
Tennessee Valley Authority
79/04/18 App

7903104038 Forwarded deficiency rept re incorrect weight of swing check valves.
GILLESLAND, J. E. Tennessee Valley Authority
79/04/19 App

7903104064 Deficiency rept weight of swing check valves w/o Vels Engineering Co was incorrect. On Order drawing 790700 Weight shown was 325 lbs should have been 450 lbs Piping containing valves being analyzed.
Tennessee Valley Authority
79/04/19 App

7903104045 Forwarded First interim deficiency rept re overtrussed penetrations in containment shell.
GILLESLAND, J. E. Tennessee Valley Authority
79/04/19 App

7903104050 First interim rept deficient design of four penetrations in inert gas containment system. Computer analysis of piping supports revised & info sent to contractor for analysis.
Tennessee Valley Authority
79/04/19 App

7903040362 Forwarded final deficiency rept re diesel generator using Westwater failures reported 790120. All overtrussed diodes replaced & technicians closely monitored.
GILLESLAND, J. E. Tennessee Valley Authority
79/04/20 App

7903200333 Forwarded final rept re installation of improper cells in auxiliary feedwater & emergency gas treatment sys.
GILLESLAND, J. E. Tennessee Valley Authority
79/05/01 App

7903200326 Final deficiency rept during preoperational testing 40-2 instances were found where improper cells were installed in control circuit. Design drawing altered & correct cells procured.
GILLESLAND, J. E. Tennessee Valley Authority
79/05/01 App

7903100191 Forwarded final rept of deficiency initially reported 7904: re fire hazard analysis.
GILLESLAND, J. E. Tennessee Valley Authority
79/05/04 App

7903100595 Deficiency rept, vapor barrier is combustible & combustible fire load not considered in fire hazard analysis. Reels will be covered w/1/2-inch thick stainless steel plate in Units 1 & 2.
Tennessee Valley Authority
79/05/04 App

7903100597 Provides second interim rept of 790320 deficiency re vibration in RHM piping. Variable spring supports added to valve operators & new pipe support installed. Vibration problems resolved.
GILLESLAND, J. E. Tennessee Valley Authority
79/05/08 App

7903100523 Provides final deficiency rept on control logic bistables failing to be undetectable position on loss of control power M/E unit.
GILLESLAND, J. E. Tennessee Valley Authority
79/05/10 App

7903200362 Forwarded final deficiency rept on potential excessive water hammer forces in main feedwater sys.
GILLESLAND, J. E. Tennessee Valley Authority
79/05/16 App

7903200369 Final deficiency rept: potential excessive water hammer forces in main feedwater sys. Procedures implemented at design stage to prevent recurrence.
Tennessee Valley Authority
79/05/16 App

7903200445 Forwarded final deficiency rept on incorrect thermal analysis of piping.
GILLESLAND, J. E. Tennessee Valley Authority
79/05/17 App

DOCKETED ITEMS

143

D Administrative Correspondence

- 7905230208 Forwards 100R08 SR01 report re spray painting supports
01888, H. E. Isahn, Lincoln & Beale 79/03/23 1p
- 7905230204 Forwards Final evaluation of items discussed in 790508 memo re BSM-designed nuclear plants Requests add info re forwarding to licensing boards
0088, E. C. S. Division of Reactor Operations Inspections 79/03/28 10pp
- 7905160143 Forwards Board Notification 79-10 re reactor inspector
conferences re BSM plants Certificate of Div encl
0088, E. C. S. Division of Reactor Operations Inspections 79/03/29 14pp
- 7905160108 Board notification reactor inspector concerns re BSM plants
W0624, J. O. S. Assistant Director for Light Water Reactors
79/03/28 2pp
- 7905160201 Forwards re Meeting-to-Thompson memo for Board
notification info
1104P09, S. Office of 1 & R Executive Officer for Operations
Support 79/03/29 1p
- 7905160209 Inform that preliminary evaluation of item 3 contained in
790328 memo will be reviewed in light of the transient Addl
info may cause change in previous assessment
0088, E. C. S. Division of Reactor Operations Inspections
79/03/29 1p.
- 7905240493 Notice of appearance on behalf of NSC
0488, V. S. C. Operations & Administrative Division 79/03/30 1p
- 7905250436 Response to 790104 order by all intervenors except Dow
Chemical Co Urges thorough examination of still's conduct.
Certificate of Div encl
01888, H. E. Isahn, Lincoln & Beale 79/03/30 20pp
- 7905230208 NRC response to ASLR 790104 order requesting addl info from
parties. Designates portions of prior record for
consideration. Provides names of persons having relevant
info Certificate of Div encl
01888, E. C. S. Division of Reactor Operations Inspections
79/03/30 9pp
- 7905160112 Board notification nuclear incident at THE. Recommends boards
on cases involving BSM reactors be provided w/IE Bulletin
79-05 & 79-07 & ASLR, C. B. K. P. Q. & H.
W0624, J. O. S. Assistant Director for Light Water Reactors
79/04/03 2pp
- 7905230143 Revises description of testing log for special preheating
conference order
01888, H. E. Isahn, Lincoln & Beale 79/04/03 2pp
- 7905240340 Forwards Inform rept re discrepancies discovered in Inboard
terminal boxes of electrical generation assemblies.
01888, H. E. Isahn, Lincoln & Beale 79/04/03 1p
- 7905290100 Notice of preheating conference to begin on 790501 in
Washington
01888, H. E. Isahn, Lincoln & Beale 79/04/03 1p
- 7905180240 Responds 790503 action by ASLR for summary disposition re
Part 2 of ASLR 790503 order re remedied issues Motion re
preheating since no preheating conference has yet been held
Certificate of Div encl
01888, H. E. Isahn, Lincoln & Beale 79/04/19 3pp
- 7905180223 Memo & order ALAB-041 denies 790404 action by intervenors to
postpone & relocate 790503 preheating conference Allows ASLR
to reconsider 790404 order
01888, H. E. Isahn, Lincoln & Beale 79/04/27 2pp
- 7905240885 Denies intervenors 790404 motion to reschedule 790503
preheating conference or change location of hearing
01888, H. E. Isahn, Lincoln & Beale 79/04/27 2pp
- 7905240581 Motion by intervenors to schedule 790503 preheating
conference at change location of hearing
01888, H. E. Isahn, Lincoln & Beale 79/04/24 2pp
- 7905240589 Urges postponement of 790503 preheating conference due to
inability of intervenors to counsel to attend
01888, H. E. Isahn, Lincoln & Beale 79/04/24 2pp

H General correspondence

- 7905050207 Forwards Certificate of Div of Amend 62 (Revision 20 to
F002) to application for CP & D.
0088, E. C. S. Division of Reactor Operations Inspections 79/05/02 2pp
- 7905050497 Confirms increased liability limit to \$124,000,000 for
policyholders NP-1, 23, 42, 76, 82, 102, 111, 140, 146, 151, 164, 170,
172, 174, 176, 178, 180, 182, 184, 186, 188, 190, 192, 194, 196,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 216, 218, 219, 220, 222,
224, 226, 228, 230, 232, 234, 236, 238, 240, 242, 244, 246, 248, 250, 252, 254, 256, 258, 260, 262, 264, 266, 268, 270, 272, 274, 276, 278, 280, 282, 284, 286, 288, 290, 292, 294, 296, 298, 300, 302, 304, 306, 308, 310, 312, 314, 316, 318, 320, 322, 324, 326, 328, 330, 332, 334, 336, 338, 340, 342, 344, 346, 348, 350, 352, 354, 356, 358, 360, 362, 364, 366, 368, 370, 372, 374, 376, 378, 380, 382, 384, 386, 388, 390, 392, 394, 396, 398, 400, 402, 404, 406, 408, 410, 412, 414, 416, 418, 420, 422, 424, 426, 428, 430, 432, 434, 436, 438, 440, 442, 444, 446, 448, 450, 452, 454, 456, 458, 460, 462, 464, 466, 468, 470, 472, 474, 476, 478, 480, 482, 484, 486, 488, 490, 492, 494, 496, 498, 500, 502, 504, 506, 508, 510, 512, 514, 516, 518, 520, 522, 524, 526, 528, 530, 532, 534, 536, 538, 540, 542, 544, 546, 548, 550, 552, 554, 556, 558, 560, 562, 564, 566, 568, 570, 572, 574, 576, 578, 580, 582, 584, 586, 588, 590, 592, 594, 596, 598, 600, 602, 604, 606, 608, 610, 612, 614, 616, 618, 620, 622, 624, 626, 628, 630, 632, 634, 636, 638, 640, 642, 644, 646, 648, 650, 652, 654, 656, 658, 660, 662, 664, 666, 668, 670, 672, 674, 676, 678, 680, 682, 684, 686, 688, 690, 692, 694, 696, 698, 700, 702, 704, 706, 708, 710, 712, 714, 716, 718, 720, 722, 724, 726, 728, 730, 732, 734, 736, 738, 740, 742, 744, 746, 748, 750, 752, 754, 756, 758, 760, 762, 764, 766, 768, 770, 772, 774, 776, 778, 780, 782, 784, 786, 788, 790, 792, 794, 796, 798, 800, 802, 804, 806, 808, 810, 812, 814, 816, 818, 820, 822, 824, 826, 828, 830, 832, 834, 836, 838, 840, 842, 844, 846, 848, 850, 852, 854, 856, 858, 860, 862, 864, 866, 868, 870, 872, 874, 876, 878, 880, 882, 884, 886, 888, 890, 892, 894, 896, 898, 900, 902, 904, 906, 908, 910, 912, 914, 916, 918, 920, 922, 924, 926, 928, 930, 932, 934, 936, 938, 940, 942, 944, 946, 948, 950, 952, 954, 956, 958, 960, 962, 964, 966, 968, 970, 972, 974, 976, 978, 980, 982, 984, 986, 988, 990, 992, 994, 996, 998, 1000, 1002, 1004, 1006, 1008, 1010, 1012, 1014, 1016, 1018, 1020, 1022, 1024, 1026, 1028, 1030, 1032, 1034, 1036, 1038, 1040, 1042, 1044, 1046, 1048, 1050, 1052, 1054, 1056, 1058, 1060, 1062, 1064, 1066, 1068, 1070, 1072, 1074, 1076, 1078, 1080, 1082, 1084, 1086, 1088, 1090, 1092, 1094, 1096, 1098, 1100, 1102, 1104, 1106, 1108, 1110, 1112, 1114, 1116, 1118, 1120, 1122, 1124, 1126, 1128, 1130, 1132, 1134, 1136, 1138, 1140, 1142, 1144, 1146, 1148, 1150, 1152, 1154, 1156, 1158, 1160, 1162, 1164, 1166, 1168, 1170, 1172, 1174, 1176, 1178, 1180, 1182, 1184, 1186, 1188, 1190, 1192, 1194, 1196, 1198, 1200, 1202, 1204, 1206, 1208, 1210, 1212, 1214, 1216, 1218, 1220, 1222, 1224, 1226, 1228, 1230, 1232, 1234, 1236, 1238, 1240, 1242, 1244, 1246, 1248, 1250, 1252, 1254, 1256, 1258, 1260, 1262, 1264, 1266, 1268, 1270, 1272, 1274, 1276, 1278, 1280, 1282, 1284, 1286, 1288, 1290, 1292, 1294, 1296, 1298, 1300, 1302, 1304, 1306, 1308, 1310, 1312, 1314, 1316, 1318, 1320, 1322, 1324, 1326, 1328, 1330, 1332, 1334, 1336, 1338, 1340, 1342, 1344, 1346, 1348, 1350, 1352, 1354, 1356, 1358, 1360, 1362, 1364, 1366, 1368, 1370, 1372, 1374, 1376, 1378, 1380, 1382, 1384, 1386, 1388, 1390, 1392, 1394, 1396, 1398, 1400, 1402, 1404, 1406, 1408, 1410, 1412, 1414, 1416, 1418, 1420, 1422, 1424, 1426, 1428, 1430, 1432, 1434, 1436, 1438, 1440, 1442, 1444, 1446, 1448, 1450, 1452, 1454, 1456, 1458, 1460, 1462, 1464, 1466, 1468, 1470, 1472, 1474, 1476, 1478, 1480, 1482, 1484, 1486, 1488, 1490, 1492, 1494, 1496, 1498, 1500, 1502, 1504, 1506, 1508, 1510, 1512, 1514, 1516, 1518, 1520, 1522, 1524, 1526, 1528, 1530, 1532, 1534, 1536, 1538, 1540, 1542, 1544, 1546, 1548, 1550, 1552, 1554, 1556, 1558, 1560, 1562, 1564, 1566, 1568, 1570, 1572, 1574, 1576, 1578, 1580, 1582, 1584, 1586, 1588, 1590, 1592, 1594, 1596, 1598, 1600, 1602, 1604, 1606, 1608, 1610, 1612, 1614, 1616, 1618, 1620, 1622, 1624, 1626, 1628, 1630, 1632, 1634, 1636, 1638, 1640, 1642, 1644, 1646, 1648, 1650, 1652, 1654, 1656, 1658, 1660, 1662, 1664, 1666, 1668, 1670, 1672, 1674, 1676, 1678, 1680, 1682, 1684, 1686, 1688, 1690, 1692, 1694, 1696, 1698, 1700, 1702, 1704, 1706, 1708, 1710, 1712, 1714, 1716, 1718, 1720, 1722, 1724, 1726, 1728, 1730, 1732, 1734, 1736, 1738, 1740, 1742, 1744, 1746, 1748, 1750, 1752, 1754, 1756, 1758, 1760, 1762, 1764, 1766, 1768, 1770, 1772, 1774, 1776, 1778, 1780, 1782, 1784, 1786, 1788, 1790, 1792, 1794, 1796, 1798, 1800, 1802, 1804, 1806, 1808, 1810, 1812, 1814, 1816, 1818, 1820, 1822, 1824, 1826, 1828, 1830, 1832, 1834, 1836, 1838, 1840, 1842, 1844, 1846, 1848, 1850, 1852, 1854, 1856, 1858, 1860, 1862, 1864, 1866, 1868, 1870, 1872, 1874, 1876, 1878, 1880, 1882, 1884, 1886, 1888, 1890, 1892, 1894, 1896, 1898, 1900, 1902, 1904, 1906, 1908, 1910, 1912, 1914, 1916, 1918, 1920, 1922, 1924, 1926, 1928, 1930, 1932, 1934, 1936, 1938, 1940, 1942, 1944, 1946, 1948, 1950, 1952, 1954, 1956, 1958, 1960, 1962, 1964, 1966, 1968, 1970, 1972, 1974, 1976, 1978, 1980, 1982, 1984, 1986, 1988, 1990, 1992, 1994, 1996, 1998, 2000, 2002, 2004, 2006, 2008, 2010, 2012, 2014, 2016, 2018, 2020, 2022, 2024, 2026, 2028, 2030, 2032, 2034, 2036, 2038, 2040, 2042, 2044, 2046, 2048, 2050, 2052, 2054, 2056, 2058, 2060, 2062, 2064, 2066, 2068, 2070, 2072, 2074, 2076, 2078, 2080, 2082, 2084, 2086, 2088, 2090, 2092, 2094, 2096, 2098, 2100, 2102, 2104, 2106, 2108, 2110, 2112, 2114, 2116, 2118, 2120, 2122, 2124, 2126, 2128, 2130, 2132, 2134, 2136, 2138, 2140, 2142, 2144, 2146, 2148, 2150, 2152, 2154, 2156, 2158, 2160, 2162, 2164, 2166, 2168, 2170, 2172, 2174, 2176, 2178, 2180, 2182, 2184, 2186, 2188, 2190, 2192, 2194, 2196, 2198, 2200, 2202, 2204, 2206, 2208, 2210, 2212, 2214, 2216, 2218, 2220, 2222, 2224, 2226, 2228, 2230, 2232, 2234, 2236, 2238, 2240, 2242, 2244, 2246, 2248, 2250, 2252, 2254, 2256, 2258, 2260, 2262, 2264, 2266, 2268, 2270, 2272, 2274, 2276, 2278, 2280, 2282, 2284, 2286, 2288, 2290, 2292, 2294, 2296, 2298, 2300, 2302, 2304, 2306, 2308, 2310, 2312, 2314, 2316, 2318, 2320, 2322, 2324, 2326, 2328, 2330, 2332, 2334, 2336, 2338, 2340, 2342, 2344, 2346, 2348, 2350, 2352, 2354, 2356, 2358, 2360, 2362, 2364, 2366, 2368, 2370, 2372, 2374, 2376, 2378, 2380, 2382, 2384, 2386, 2388, 2390, 2392, 2394, 2396, 2398, 2400, 2402, 2404, 2406, 2408, 2410, 2412, 2414, 2416, 2418, 2420, 2422, 2424, 2426, 2428, 2430, 2432, 2434, 2436, 2438, 2440, 2442, 2444, 2446, 2448, 2450, 2452, 2454, 2456, 2458, 2460, 2462, 2464, 2466, 2468, 2470, 2472, 2474, 2476, 2478, 2480, 2482, 2484, 2486, 2488, 2490, 2492, 2494, 2496, 2498, 2500, 2502, 2504, 2506, 2508, 2510, 2512, 2514, 2516, 2518, 2520, 2522, 2524, 2526, 2528, 2530, 2532, 2534, 2536, 2538, 2540, 2542, 2544, 2546, 2548, 2550, 2552, 2554, 2556, 2558, 2560, 2562, 2564, 2566, 2568, 2570, 2572, 2574, 2576, 2578, 2580, 2582, 2584, 2586, 2588, 2590, 2592, 2594, 2596, 2598, 2600, 2602, 2604, 2606, 2608, 2610, 2612, 2614, 2616, 2618, 2620, 2622, 2624, 2626, 2628, 2630, 2632, 2634, 2636, 2638, 2640, 2642, 2644, 2646, 2648, 2650, 2652, 2654, 2656, 2658, 2660, 2662, 2664, 2666, 2668, 2670, 2672, 2674, 2676, 2678, 2680, 2682, 2684, 2686, 2688, 2690, 2692, 2694, 2696, 2698, 2700, 2702, 2704, 2706, 2708, 2710, 2712, 2714, 2716, 2718, 2720, 2722, 2724, 2726, 2728, 2730, 2732, 2734, 2736, 2738, 2740, 2742, 2744, 2746, 2748, 2750, 2752, 2754, 2756, 2758, 2760, 2762, 2764, 2766, 2768, 2770, 2772, 2774, 2776, 2778, 2780, 2782, 2784, 2786, 2788, 2790, 2792, 2794, 2796, 2798, 2800, 2802, 2804, 2806, 2808, 2810, 2812, 2814, 2816, 2818, 2820, 2822, 2824, 2826, 2828, 2830, 2832, 2834, 2836, 2838, 2840, 2842, 2844, 2846, 2848, 2850, 2852, 2854, 2856, 2858, 2860, 2862, 2864, 2866, 2868, 2870, 2872, 2874, 2876, 2878, 2880, 2882, 2884, 2886, 2888, 2890, 2892, 2894, 2896, 2898, 2900, 2902, 2904, 2906, 2908, 2910, 2912, 2914, 2916, 2918, 2920, 2922, 2924, 2926, 2928, 2930, 2932, 2934, 2936, 2938, 2940, 2942, 2944, 2946, 2948, 2950, 2952, 2954, 2956, 2958, 2960, 2962, 2964, 2966, 2968, 2970, 2972, 2974, 2976, 2978, 2980, 2982, 2984, 2986, 2988, 2990, 2992, 2994, 2996, 2998, 3000, 3002, 3004, 3006, 3008, 3010, 3012, 3014, 3016, 3018, 3020, 3022, 3024, 3026, 3028, 3030, 3032, 3034, 3036, 3038, 3040, 3042, 3044, 3046, 3048, 3050, 3052, 3054, 3056, 3058, 3060, 3062, 3064, 3066, 3068, 3070, 3072, 3074, 3076, 3078, 3080, 3082, 3084, 3086, 3088, 3090, 3092, 3094, 3096, 3098, 3100, 3102, 3104, 3106, 3108, 3110, 3112, 3114, 3116, 3118, 3120, 3122, 3124, 3126, 3128, 3130, 3132, 3134, 3136, 3138, 3140, 3142, 3144, 3146, 3148, 3150, 3152, 3154, 3156, 3158, 3160, 3162, 3164, 3166, 3168, 3170, 3172, 3174, 3176, 3178, 3180, 3182, 3184, 3186, 3188, 3190, 3192, 3194, 3196, 3198, 3200, 3202, 3204, 3206, 3208, 3210, 3212, 3214, 3216, 3218, 3220, 3222, 3224, 3226, 3228, 3230, 3232, 3234, 3236, 3238, 3240, 3242, 3244, 3246, 3248, 3250, 3252, 3254, 3256, 3258, 3260, 3262, 3264, 3266, 3268, 3270, 3272, 3274, 3276, 3278, 3280, 3282, 3284, 3286, 3288, 3290, 3292, 3294, 3296, 3298, 3300, 3302, 3304, 3306, 3308, 3310, 3312, 3314, 3316, 3318, 3320, 3322, 3324, 3326, 3328, 3330, 3332, 3334, 3336, 3338, 3340, 3342, 3344, 3346, 3348, 3350, 3352, 3354, 3356, 3358, 3360, 3362, 3364, 3366, 3368, 3370, 3372, 3374, 3376, 3378, 3380, 3382, 3384, 3386, 3388, 3390, 3392, 3394, 3396, 3398, 3400, 3402, 3404, 3406, 3408, 3410, 3412, 3414, 3416, 3418, 3420, 3422, 3424, 3426, 3428, 3430, 3432, 3434, 3436, 3438, 3440, 3442, 3444, 3446, 3448, 3450, 3452, 3454, 3456, 3458, 3460, 3462, 3464, 3466, 3468, 3470, 3472, 3474, 3476, 3478, 3480, 3482, 3484, 3486, 3488, 3490, 3492, 3494, 3496, 3498, 3500, 3502, 3504, 3506, 3508, 3510, 3512, 3514, 3516, 3518, 3520, 3522, 3524, 3526, 3528, 3530, 3532, 3534, 3536, 3538, 3540, 3542, 3544, 3546, 3548, 3550, 3552, 3554, 3556, 3558, 3560, 3562, 3564, 3566, 3568, 3570, 3572, 3574, 3576, 3578, 3580, 3582, 3584, 3586, 3588, 3590, 3592, 3594, 3596, 3598, 3600, 3602, 3604, 3606, 3608, 3610, 3612, 3614, 3616, 3618, 3620, 3622, 3624, 3626, 3628, 3630, 3632, 3634, 3636, 3638, 3640, 3642, 3644, 3646, 3648, 3650, 3652, 3654, 3656, 3658, 3660, 3662, 3664, 3666, 3668, 3670, 3672, 3674, 3676, 3678, 3680, 3682, 3684, 3686, 3688, 3690, 3692, 3694, 3696, 3698, 3700, 3702, 3704, 3706, 3708, 3710, 3712, 3714, 3716, 3718, 3720, 3722, 3724, 3726, 3728, 3730, 3732, 3734, 3736, 3738, 3740, 3742, 3744, 3746, 3748, 3750, 3752, 3754, 3756, 3758, 3760, 3762, 3764, 3766, 3768, 3770, 3772, 3774, 3776, 3778, 3780, 3782, 3784, 3786, 3788, 3790, 3792, 3794, 3796, 3798, 3800, 3802, 3804, 3806, 3808, 3810, 3812, 3814, 3816, 3818

DOCKETED ITEMS

7903040304 Forwarded IC Bulletin 79-064, "Review of Operational Errors & Out Misalignments Identified During THE Incident"
NEPFLER, J D Region 3, Chicago, Office of the Director 79/04/14
1p

7903040303 Forwarded IC Bulletin 79-066, "Review of Operational Errors & Out Misalignments Identified During THE Incident"
NEPFLER, J D Region 3, Chicago, Office of the Director 79/04/14
1p

7903040404 Forwarded IC Bulletin 79-07, "Seismic Stress Analysis of Reactor-Related Piping" Licensee action required
NEPFLER, J D Region 3, Chicago, Office of the Director 79/04/14
1p

7903040404 Forwarded IC Bulletin 79-06, "Events Relevant to Belling Water Reactor Reactors Identified During THE Incident"
NEPFLER, J D Region 3, Chicago, Office of the Director 79/04/14
1p

7903040307 Forwarded IC Info Notice 79-10, "Nonconforming Pipe Support Brackets"
NEPFLER, J D Region 3, Chicago, Office of the Director 79/04/14
1p

7903030219 Forwarded IC Bulletin 79-09, "Failures of DE Type AN-C Circuit Breaker in Safety-Related Sys" Licensee action required
NEPFLER, J D Region 3, Chicago, Office of the Director 79/04/17
1p

7903030404 Forwarded IC Bulletin 79-086, "Nuclear Incident at THE-Boggy"
NEPFLER, J D Region 3, Chicago, Office of the Director 79/04/21
1p

B Periodic operating reports & related correspondence

7903030478 Forwarded nonconformance report for Mar 1979
HOMELL, R H Consumers Power Co 79/03/23 100pp

B Reportable occurrences, LERs & related correspondence

7903040320 Ack receipt of 790309 final report re air filtering units. Review will be finished upon completion of corrective action.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/23 1p

7903040344 Ack receipt of 790320 report re electrical penetration assembly final report will be reviewed upon receipt.
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/05 1p

7903140317 Forwarded nonconformance report for Mar 1979, consisting of: Bechtel nonconformance reports, Bechtel nonconformance log, Bechtel quality audit findings, Bechtel quality action requests, BSM reports of nonconformity & unit tests.
HOMELL, R H Consumers Power Co 79/04/26 400pp

7903070903 Final deficiency report reactor bldg spray anchor discrepancy. Local pig witnesses may potentially exceed ASME Section III stiff assemblies at points. Existing procedural methods are adequate.
* Consumers Power Co 79/04/27 4pp

7903090308 Provide interim deficiency report on actions to resolve settlement of diesel generator foundations & bldg.
HOMELL, R H Consumers Power Co 79/04/30 2pp

7903090304 Interim Deficiency Report 5, settlement of diesel generator foundations & bldg caused by insufficient compaction in area. Fill re material Category 5 structures. Lists status & corrective actions. W62 overused drawings.
* Consumers Power Co 79/04/16 10pp

7903030327 Final report re reactor bldg spray piping supports. Analysis has verified adequacy of support design & ASME Section III Code allowable stresses. Bechtel met corrective action report NCR-22 and.
HOMELL, R H Consumers Power Co 79/05/01 7pp

7903030322 Forwarded interim report on status of component qualification. Local documentation re review Forwarded Bechtel "Qualification Test Status Report." Interim BSM report will be reviewed. Another report will be sent by 790704.
HOMELL, R H Consumers Power Co 79/05/04 2pp

7903060304 Interim report on seismic & environ component qualification. Forwarded "Qualification Test Status Report." Revision 7, dtd 79/04/04.
HOMELL, R H 2 Bechtel Power Corp (subs of Bechtel Corp) 79/04/20 35pp

7903030312 Forwarded final report re discrepancies discovered in inboard terminal bases.
HOMELL, R Consumers Power Co 79/03/23 7pp

7903030326 Final deficiency report re 790323 defects discovered in penetration assemblies in inboard terminal bases, possibly caused by type of termination log used. Log of terminations collected.
* Consumers Power Co 79/03/23 5pp

T Hearing transcripts on non-utility matters

7903140504 Transcript of 790321 prehearing conference in Bethesda, MD. 79 50,030-50,171.
MILLER, R E - LEBRON, LEEDS Atomic Safety and Licensing Board Panel 79/05/01 17pp

DOCKET 30-330 MIDLAND PLANT, UNIT 3

A Application/construction stage documents & correspondence

7903200413 Notification of 790309 meeting with B in Bethesda, MD to discuss status of safety & environmental review schedule. Date changed from 790403.
HARRIS, D H Light Water Reactors Branch 4 79/03/23 3pp

7903240442 Response to NRC 790312 ltr. Discusses analysis of cooling lake impact on local traffic due to icing & fogging.
NRC requires 79/04/01 monitoring program. Describes relevant studies.
CARSON, J H Argonne National Laboratory 79/04/23 3pp

7903103360 Indicates state will withhold Section 401(c)(1) of certification of facilities until CDE is approved by NE.
Environ Review Board
WARRICK, A Michigan, State of 79/05/17 2pp

7903200304 Response to NRC 790311 ltr. Forwarded "Investigation of Thermal Plume in Shallow River-Hydrothermal Model Studies, Cooling Pond Shutdown Discharge" & "Midland Power Plant Cooling Pond Operation Study".
HOMELL, R H Consumers Power Co 79/05/01 1p

7903200328 "Investigation of Thermal Plume in Shallow River, Hydrothermal Model Studies-Cooling Pond Shutdown Discharge," prepared by Alcoa Research Lab for facility.
REBERG, J C - MURPHY, R D Consumers Power Co 45-79/0324M 79/04/30 7pp

7903200303 "Midland Plant Cooling Pond Operation Study," prepared by Bechtel.
LICO, C P - PAPAIOANIS, C N Consumers Power Co 45-79/0324M 79/03/01 6pp

C Utility Environmental Report (ER), amendments & correspondence

7903030328 Forwarded Amend 64 to CP & DL.
HOMELL, R H Consumers Power Co 79/04/30 1p

7903030302 Amend 64 to CP & DL, consisting of revised pages for Revision 8 to environ report.
HOMELL, R H Consumers Power Co 79/04/30 4pp

7903110307 Forwarded affidavit of distribution of environ report. DL, signed Amend 64, Revision 8.
HARRIS, D H Consumers Power Co 79/05/07 4pp

D Adjudicatory correspondence

7903030328 Forwarded 1027030, BSM reports re spray piping supports.
HARRIS, D H Idaho, Lincoln & Seale 79/03/23 1p

7903040314 Forwarded final evaluation of issues discussed in 790309 and re BSM-designed nuclear plants. Requests add info be forwarded to licensing board.
HOMER, N C Division of Reactor Operations Inspections 79/03/28 10pp

7905160163 Forward Board Notification 79-10 re reactor inspector concerns re BSM plants Certificate of Div and
OINTEL J P Hearings Division 79/03/27 1pp

--7905160165 Board notification reactor inspector concerns re BSM plants
WASALLO D B Assistant Director for Light Water Reactors
79/03/03 2pp

--7905160201 Forward two Hensley-to-Thompson memo for Board
notification info
THOMPSON D Office of 1 & Executive Officer for Operations
Support 79/03/29 1p

7905200209 Inform that preliminary evaluation of item 3 contained in
790328 memo will be reviewed in light of TMI transient Add
info may cause change in previous assessment
HENSEL D C Division of Reactor Operations Inspections
79/03/29 1p

7905200493 Notice of appearance on behalf of NRC
DANIEL D C Operations & Administrative Division 79/03/30 1p

7905200498 Response to 790104 order by all intervenors accept Dow
Chemical Co Urges thorough examination of utility's conduct
Certificate of Div and
FLINKE P Cherry R H Cherry, Flynn & Kamber 79/03/30 20pp

7905200500 NRC response to AEBL 790104 order requesting add info from
parties Designates parties of prior record for
consideration Provides names of persons having relevant
info Certificate of Div and
BLINDEMAN J J NEFFLER J D Branch 4 DANIEL D C Operations &
Administrative Division 79/03/30 9pp

7905200512 Board notification nuclear incident at THE Bismarcks boards
on cases involving BSM reactor re provided w/IE Bulletin
79-20 & 79-07 & AEA-B.C.D.E.F.G.H & I
WASALLO D B Assistant Director for Light Water Reactors
79/04/03 2pp

7905200513 Replies description of cooling sys for special preheating
conference order
OINTEL J P Inham, Lincoln & Seale 79/04/03 2pp

7905200545 Forward interim rept re discrepancies discovered in inboard
terminal boxes of electrical penetration assemblies
OINTEL J P Inham, Lincoln & Seale 79/04/03 1p

7905200548 Notice of preheating conference to begin on 790501 in
Bethesda MD
HENSEL D C Atomic Safety and Licensing Board Panel 79/04/03 1p

7905150045 Oppose 790326 motion by util for summary disposition re
Part 2 of AEBL 790104 order re resumed issues Motion is
premature since no preheating conference has yet been held
Certificate of Div and
BLINDEMAN J J Branch 4 79/04/19 2pp

7905150023 Memo & order ALAD-541 Denies 790404 motion by intervenors to
postpone & relocate 790501 preheating conference ALAD-541
to reschedule 790407 order
OINTEL J P Atomic Safety and Licensing Appeal Panel 79/04/27 2pp

7905200635 Denies intervenors 790404 motion to reschedule 790501
preheating conference or change location of hearing
HENSEL D C Atomic Safety and Licensing Board Panel 79/04/27 2pp

--7905200691 Notice by intervenors to schedule 790501 preheating
conference & change location of hearing
FLINKE P Cherry R H Cherry, Flynn & Kamber 79/04/24 2pp

--7905200697 Urges postponement of 790501 preheating conference due to
availability of intervenors' counsel to attend
FLINKE P Cherry R H Cherry, Flynn & Kamber 79/04/24 2pp

M General correspondence

7905090207 Forward Certificate of Div of Amend 62 (Revision 20 to
FBR) to Application for CP & OL
BAGGS J L L Consumers Power Co 79/03/02 2pp

J Insurance & indemnity information

7905070747 Confirms increased liability limit to \$100,000,000 for
policy M-1-25-40-76-62-100-111-140-146-151-161-164-170-
173-176-179-180-185-186-187-188-189-190-192-193-194-195-
197-198-200-201-204-206-207-208-210-212-214-215 & others
MATTIACCHIONI J American Nuclear Insurers 79/03/21 1p

M Utility Final Safety Analysis Report (FSAR) & amendments

7905200209 Forward Amend 62 to application for CP & OL which
constitutes Revision 20 to FSAR Certificate of Div & revised
add to substantial ref disburse and
HENSEL D B Consumers Power Co 79/04/26 2pp

--7905030311 Revision 20 to FBR
Consumers Power Co 79/04/26 20pp

M Antitrust correspondence

7905200322 Requests antitrust info for add antitrust participants to
assess processing of amend or transfer of license
TOLBERT D A Antitrust & Indemnity Group 79/04/23 2pp

O Inspection reports, IE Bulletins & correspondence

7905200146 Forward IE Insp Repts 50-329/79-20 & 50-330/79-20 on
79011-12, 18-20, 790104-05, 09-11, 30-32, 0302 & 0308
NEFFLER J D Region 3, Chicago, Office of the Director 79/03/22 2pp

--7905200172 IE Insp Repts 50-329/79-20 & 50-330/79-20 on 790121-13,
18-20, 790104-05, 09-11, 30-32, 0302 & 0308 No noncompliance
noted Major areas inspected diesel generator bldg
foundations & structural workmanship of bldg
FIORELLI D Region 3, Chicago, Reactor Construction &
Engineering Support Branch HENSEL D C HENSEL D W Region 3,
Chicago, Office of the Director 79/03/19 2pp

7905200194 Forward IE Info Notice 79-04, "Stress Analysis of
Safety-Related Piping"
NEFFLER J D Region 3, Chicago, Office of the Director 79/03/23 1p

7905200209 Forward IE Info Notice 79-07, "Rupture of Reducers Tanks"
NEFFLER J D Region 3, Chicago, Office of the Director 79/03/26 1p

7905200209 Forward IE Insp Repts 50-329/79-04 & 50-330/79-04 on
790207 No noncompliance noted
FIORELLI D Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/03/29 2pp

--7905200276 IE Insp Repts 50-329/79-04 & 50-330/79-04 on 790207 No
noncompliance noted Major areas inspected project status,
concrete re recent developments onsite & upcoming inspection
activity
COON R J HENSEL D W Region 3, Chicago, Office of the
Director NEFFLER J D Region 3, Chicago, Reactor Construction &
Engineering Support Branch 79/03/27 2pp

7905200724 Forward IE Insp Repts 50-327/79-04 & 50-330/79-04 on
790328-29 No noncompliance noted
FIORELLI D Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/04/09 2pp

--7905200734 IE Insp Repts 50-329/79-04 & 50-330/79-04 on 790328-29 No
noncompliance noted Major areas inspected following
79070202 Social rept re workmanship of diesel generator bldg
& plant area fill
HENSEL D W Region 3, Chicago, Office of the
Director 79/04/04 2pp

7905300222 Forward IE Bulletin 79-04, "Review of Operational Errors &
Rpt Misalignments Identified During TMI Incident."
NEFFLER J D Region 3, Chicago, Office of the Director 79/04/11 1p

7905300283 Forward IE Bulletin 79-04, "Review of Operational Errors &
Rpt Misalignments Identified During TMI Incident."
NEFFLER J D Region 3, Chicago, Office of the Director 79/04/14 1p

7905400321 Forward IE Bulletin 79-04, "Review of Operational Errors &
Rpt Misalignments Identified During TMI Incident."
NEFFLER J D Region 3, Chicago, Office of the Director 79/04/14 1p

7905400483 Forward IE Bulletin 79-07, "Seismic Stress Analysis of
Safety-Related Piping" License action required
NEFFLER J D Region 3, Chicago, Office of the Director 79/04/14 1p

7905400546 Forward IE Bulletin 79-08, "Events Relevant to Boiling
Water Power Reactor Identified During TMI Incident."
NEFFLER J D Region 3, Chicago, Office of the Director 79/04/14 1p

DOCKETED ITEMS

7905010387 Forward 3E Info Notice 79-10, "Nonconforming Pipe Support Brackets"
 REPUBLIC J O Region 3, Chicago, Office of the Director 79/04/16
 1p

7905030319 Forward 1E Bulletin 79-06, "Patterns of 3E Type AM-2 Circuit Breaker in Safety-Related Systems - Licensee action required"
 REPUBLIC J O Region 3, Chicago, Office of the Director 79/04/17
 1p

7905050404 Forward 1E Bulletin 79-05B, "Nuclear Incident at TMI-2"
 REPUBLIC J O Region 3, Chicago, Office of the Director 79/04/21
 1p

R Periodic operating reports and related correspondence

7905020478 Forward 2E performance reports for Apr 1979
 HOBELL E H Consumers Power Co 79/03/25 100pp

S Reportable occurrences, LERs and related correspondence

7905020330 Act receipt of 790309 final report re air filtering units. Review will be finished upon completion of corrective action.
 FIDELL L O Region 3, Chicago, Reactor Construction and Engineering Support Branch 79/03/23 1p

7905040449 Act receipt of 790330 report re electrical penetration assembly final report will be returned upon receipt.
 FIDELL L O Region 3, Chicago, Reactor Construction and Engineering Support Branch 79/04/05 1p

7905050319 Forward 2E performance reports for Mar 1979, consisting of Reactor nonconformance reports, Reactor performance logs, Reactor quality audit findings, Reactor quality action requests, and parts of nonconformance and still reports.
 HOBELL E H Consumers Power Co 79/04/20 40pp

7905070501 Final deficiency report reactor bldg spray another fireproofing local pipe streamer may potentially exceed ASME Section III (C) allowable at joints. Existing procedural methods are adequate.
 Consumers Power Co 79/04/27 4pp

7905090602 Provides interim deficiency report 30 actions to resolve settlement of diesel generator foundations & bldg.
 HOBELL E H Consumers Power Co 79/04/30 2pp

7905090504 Interim Deficiency Report 30 settlement of diesel generator foundations & bldg. Caused by insufficient compaction in area. Will re seismic Category I structures. Lists status & corrective actions. 4022 reviewed drawings.
 Consumers Power Co 79/04/16 10pp

7905030327 Final report re reactor bldg spray piping supports. Analysis has verified adequacy of support design & ASME Section III. Code allowable stresses. Reactor agit corrective action report (RCAR 32) encl.
 HOBELL E H Consumers Power Co 79/05/01 3pp

7905080262 Forward interim report on status of component qualification test documentation re review. Forwarded Section "Qualification Test Status Report" - Similar test report will be reviewed. Another report will be sent by 7/9/79.
 HOBELL E H Consumers Power Co 79/05/04 2pp

7905080308 Interim report on seismic & structural component qualification. Forwarding "Qualification Test Status Report" - Revision 3, encl. 79/04/26.
 BALTZMAN R 2 Reactor Power Core (encl. of Reactor Core) 79/04/26 3pp

7905060282 Forward final report re discrepancies discovered in inboard terminal boxes.
 HOBELL E H Consumers Power Co 79/05/20 3pp

7905030304 Final deficiency report re 790203 defects discovered in penetration assemblies in inboard terminal boxes. Possible causes by type of termination (eg used, loop of terminations conducted).
 Consumers Power Co 79/05/23 4pp

T Hearing transcripts on non-withdrawn matters

7905140544 Transcription of 790501 prehearing conference in Bethesda, MD. Re 20,000-50,171.
 HALL J H E, LORRY, LEBER Atomic Safety and Licensing Board Panel 79/05/01 17pp

DOCKET 80-335 BURKE ARNOLD KEMERY CENTER

F Security, medical, emergency & fire protection plans

7905040491 Forward modified physical security plan with withdrawal of 10CFR 7701.
 LILU Iowa Electric Light & Power Co 79/04/30 1p

7905050336 Inform that fire hazard analysis report will be submitted by 790510. See to add analysis required by engineering staff & consultants.
 LILU Iowa Electric Light & Power Co 79/05/02 1p

7905080465 Advices of delay in security mod proposed due to labor disagreement & supplier's delay in mfg of critical computer components.
 LILU Iowa Electric Light & Power Co 79/05/04 1p

7905030447 Discusses schedule delays re plant security program. Local electrical union contract will expire on 790601 & union stoppage may delay.
 LILU Iowa Electric Light & Power Co 79/05/10 1p

G Regulatory correspondence

7905030507 Forward request to institute proceeding to suspend technical Assent 9 to License DPF-49. Also forwards pertinent FR notice.
 CENTON R R Office of Nuclear Reactor Regulation 79/04/12 2pp

7905100312 Request for suspension of technical Assent 9 to License DPF-49.
 HANSEN J E Citizens United for Responsible Energy 79/03/20 2pp

7905050303 Act receipt of request to institute proceeding to suspend Assent 9 to License DPF-49. Request is presently under consideration. Relevant FR notice & petitioner's request for action encl.
 CENTON R R Office of Nuclear Reactor Regulation 79/04/12 2pp

7905050307 Notice of request to suspend Assent 9 to License DPF-49.
 CENTON R R Office of Nuclear Reactor Regulation 79/04/12 1p

7905020447 Notification that Citizens for Responsible Energy filed petition seeking proceedings to suspend Assent 9 to License DPF-49.
 HANSEN J E Office of Nuclear Reactor Regulation 79/04/12 1p

7905100315 FR notice of request to suspend technical Assent 9 to License DPF-49.
 HANSEN J E Office of Nuclear Reactor Regulation 79/04/12 1p

7905020301 Request for action to institute proceeding to suspend Assent 9 to License DPF-49 re handling of BOP.
 HANSEN J E Citizens United for Responsible Energy 79/03/20 2pp

J Insurance & indemnity information

7905050497 Confirm increased liability limit to \$124,000,000 for policies NF-1, 25, 42, 74, 82, 100, 111, 140, 146, 161, 164, 170, 173, 174, 176, 179, 180, 182, 185, 186, 187, 189, 190, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
 SMITHSONIAN U American Nuclear Insurers 79/05/01 1p

7905050392 Confirm increase in liability limit to \$124,000,000 for policies NF-26, 28, 38, 39, 44, 46, 47, 49, 50, 51, 53, 54, 58, 59, 57, 58, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95, & others.
 HANSEN J E American Nuclear Insurers 79/05/01 1p

7905140523 Forward Assent & to Informing Agreement 3-66 per 10CFR140 complete increase from \$10 million to \$100 million. effective 790501. Supporting documentation encl.
 BALTIMORE J Antitrust & Indemnity Group 79/05/01 8pp

P Operating license change documents & correspondence

7905070176 Forward Assent 50 to License DPF-49, security plan evaluation withdrawal re 10CFR 7701 & notice of issuance & availability.
 FIDELL L O Operating Reactors Branch 2, 79/04/19 3pp

7905040419 Assent 20 to License DPF-49, incorporating security plan with license effective on 790523.
 FIDELL L O Operating Reactors Branch 2, 79/04/19 2pp

DOCKETED ITEMS

147

- 7905040201 Notice of Insurance and Availability of Amend 30 to License
DNR-59
INPEL-170-A-1 Operating Reactors Branch 3 79/03/19 App
- 7905050409 Informal delay until 790430 of App 3 Tech Dept submittal
originally scheduled for 790430 Consultant assigned on the
project
LJUL Iowa Electric Light & Power Co 79/03/02 1p
- 7905050502 Forwards bar-short schedule showing time periods for
installation of specific plant made as part of Mark I
containment long-term program installation currently
scheduled for Feb 1981 referring outage
LJUL Iowa Electric Light & Power Co 79/03/17 App
- B Inspection reports: EC Dullations & correspondence
- 7905050605 Forwards IE Insp Rept 30-331/79-07 on 790229-0301 No
noncompliance noted
HETBHMW-1 F Region 3, Chicago: Reactor Operations Nuclear
Support Branch 79/03/22 App
- 7905050619 IE Insp Rept 30-331/79-07 on 790229-0301 No noncompliance
noted Major areas inspected fire protection/prevention
program & review of Tech Dept surveillance requirements
for fire protection equipment
WRIGHT, J C Region 3, Chicago: Reactor Operations Nuclear
Support Branch, LITTLE, W B Region 3, Chicago: Office of the
Director 79/03/16 App
- 7905050626 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/03/29
1p
- 7905050632 Forwards IE Insp Rept 30-331/79-06 on 790229-06 & notice of
violations
SWAB, A B Region 3, Chicago: Fuel Facility & Materials Safety
Branch 79/03/23 App
- 7905050642 Notice of violation from Insp on 790307-09
Region 3, Chicago: Fuel Facility & Materials Safety Branch
79/03/28 1p
- 7905050646 IE Insp Rept 30-331/79-06 on 790307-09 Noncompliance noted
failure to submit QA program description for shipping
packages as required.
WRIGHT, J C Region 3, Chicago: Office of the
Director, FINCH, W L Region 3, Chicago: Fuel Facility &
Materials Safety Branch 79/03/23 App
- 7905060031 Forwards IE Info Notice 79-07, "Rupture of Reducible Valve"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/03/26
1p
- 7905060034 Forwards IE Insp Rept 30-331/79-10 on 790304-07 & 0301-22
FIORELLI, G Region 3, Chicago: Reactor Construction & Engineering
Support Branch 79/03/27 App
- 7905060041 IE Insp Rept 30-331/79-10 on 790304-07 & 0301-02 Major areas
inspected ultrasonic baseline test results for welds
involved in recirculation inlet piping model &
recirculation inlet nozzle NRE lead pipe
WRIGHT, J C, LITTLE, W B, & DANIELSON, D H Region 3, Chicago:
Office of the Director 79/03/23 App
- 7905100126 Forwards IE Insp Rept 30-331/79-09 on 790127-31, 0205-06,
11-12 & 23 & notice of violation
HETBHMW-1 B Region 3, Chicago: Reactor Operations Nuclear
Support Branch 79/03/27 App
- 7905100127 Notice of violation from Insp on 790127-31, 0205-06, 11-12 &
23
Region 3, Chicago: Office of the Director 79/03/28 1p
- 7905100128 IE Insp Rept 30-331/79-09 on 790127-31 & 0205-06, 11-12 & 23
Noncompliance noted failure to adhere to welding procedures
JACKSON, J M, & WALKER, R D Region 3, Chicago: Office of the
Director, & DANIELSON, D H Region 3, Chicago: Reactor Operations
Nuclear Support Branch 79/03/23 App
- 7905100129 Forwards IE Insp Rept 30-331/79-09 on 790108-12, 17-19, 24 &
29-31 & notice of violation
HEPFLER, J G Region 3, Chicago: Office of the Director 79/03/27
App
- 7905100429 Notice of violation from Insp on 790108-12, 17-19, 24 & 29-31
Region 3, Chicago: Office of the Director 79/03/27 1p
- 7905100430 IE Insp Rept 30-331/79-09 on 790108-12, 17-19, 24 & 29-31
Noncompliance noted nonperformance repts improperly
resolved & documented
WRIGHT, J C, & HEFLER, J G Region 3, Chicago: Office of the
Director, & DANIELSON, D H Region 3, Chicago: Reactor
Construction & Engineering Support Branch 79/03/23 App
- 7905050507 Forwards IE Info Notice 79-08, "Interconnection of
Containment Gas W/Bo Air Rep Used as Source of Breathing
Air"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/03/28
1p
- 7905050508 Forwards IE Info Notice 79-09, "Spill of Radioactively
Contaminated Basin"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/03/28
1p
- 7905050509 Forwards replacement pages for IE Insp repts documents
Revision reflects addition of Insp dates 790212-13,
790215-21 & 790228-29, which were not previously included
FIORELLI, G Region 3, Chicago: Reactor Operations Nuclear Support
Branch 79/04/06 1p
- 7905050510 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Bay Misalignments Identified During THE Incident"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/04/11
1p
- 7905050508 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Bay Misalignments Identified During THE Incident"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/04/14
1p
- 7905050509 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Bay Misalignments Identified During THE Incident"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/04/14
1p
- 7905050423 Forwards IE Bulletin 79-07, "Dynamic Stress Analysis of
Safety-Related Piping" License action required
HEPFLER, J G Region 3, Chicago: Office of the Director 79/04/14
1p
- 7905040560 Forwards IE Bulletin 79-08, "Events Relevant to Boiling
Water Pool Reactors Identified During THE Incident"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/04/14,
1p
- 7905100330 Responds to IE Bulletin 79-03 re pipe off by Youngstown
welding & Engineering Co Pipe is nuclear used not planned
for use in any subcriticalized system facilities
LJUL Iowa Electric Light & Power Co 79/04/16 1p
- 7905050527 Forwards IE Bulletin 79-09, "Failures of IE Type AN-2
Circuit Breaker in Safety-Related Bay" License action
required.
HEPFLER, J G Region 3, Chicago: Office of the Director 79/04/17
1p
- 7905050509 Forwards IE Bulletin 79-08B, "Nuclear Incident at
T-1000"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/04/21
1p
- 7905050527 Responds to IE Bulletin 79-07 No methods specified in
bulletin have been used Responses from NRE supplier &
AEC steel
LJUL Iowa Electric Light & Power Co 79/04/24 App
- 7905100107 App receipt of 790412 for Informing NRC of steps taken to
correct violations noted in IE Insp conducted on 790307-09
SWAB, A B Region 3, Chicago: Fuel Facility & Materials Safety
Branch 79/04/25 App
- 7905101042 Responds to NRC for re violation noted in IE Insp conducted on
790307-09 Corrective actions QA program will be
documented by 790421
LJUL Iowa Electric Light & Power Co 79/04/13 App
- 7905050513 Responds to IE Bulletin 79-06, Items 1-10 re THE effect on
Belle Response to then it will be sent before 790515
WALLACE, J A Iowa Electric Light & Power Co 79/04/27 18pp
- 7905040908 Forwards IE Circular 79-07, "Unsuspected Speed Increase of
Reactor Recirculation Motor Generator Set Resulted in
Reactor Power Increase"
HEPFLER, J G Region 3, Chicago: Office of the Director 79/05/02
1p

DOCKETED ITEMS

R Periodic operating reports & related correspondence

7905010280 Forwards monthly operating report for Apr 1979
HARRISON, E. L. Iowa Electric Light & Power Co. 79/05/04 1p

--7905010284 Monthly operating report for Apr 1979
VAN SICKEL, J. Iowa Electric Light & Power Co. 79/05/14 7p

R Reportable occurrences, LDRs & related correspondence

7905030351 Forwards LER 79-008/03L-0
HARRISON, E. L. Iowa Electric Light & Power Co. 79/04/25 1p

--7905030323 LER 79-008/03L-0 on 790326 pin hole leak discovered in reactor water cleanup gas pipe caused by linear indication in unit attributed to disintegrating stress corrosion cracking. Rib-joint & pipe on both ends replaced
VAN SICKEL, J. Iowa Electric Light & Power Co. 79/04/25 1p

7905040363 Forwards LER 79-014/03L-0
HARRISON, E. L. Iowa Electric Light & Power Co. 79/05/08 1p

--7905040349 LER 79-014/03L-0 on 790408 containment purge inlet valve CV 430A & burst pressure relief valve CV 430B not sealing properly due to tee ring seal not being preassembled. Caused by actuator valve linkage being out of adjustment
VAN SICKEL, J. Iowa Electric Light & Power Co. 79/05/08 1p

7905040386 Forwards LER 79-024/03L-0
HARRISON, E. L. Iowa Electric Light & Power Co. 79/05/08 1p

--7905040387 LER 79-024/03L-0 on 790408 drain sump discharge valve CV 3104 stuck caused by corrosion in valve operator cylinder. Use lubricated & design review will be initiated to determine if oiling device can be installed
VAN SICKEL, J. Iowa Electric Light & Power Co. 79/05/08 2pp

7905050182 Forwards LER 79-014/03L-0
HARRISON, E. L. Iowa Electric Light & Power Co. 79/05/10 1p

--7905050191 LER 79-014/03L-0 on 790424 main exhaust radiation monitors RTH 7600A & 7600B tripped at out-of-range setpoints caused by instrument drive monitors oxidizer
VAN SICKEL, J. Iowa Electric Light & Power Co. 79/05/10 1p

DOCKET 90-300 BARNHILL REPROCESSING PLANT

Q Inspection reports, IE Bulletins & correspondence

7905030782 Inform of deferral of corrective actions discussed in IE Supp. 79-030/77-02 re ballcock seat angle valves future facility operation uncertain due to NRC 770202 order terminating licensing proceedings
BAKTER, R. C. Allied General Nuclear Services 79/05/14 1p

7905050182 Forwards IE Info Notice 79-04, "Interconnection of Compressed Gas Airline Air Use as Source of Breathing Air"
C-MELLIN, J. P. Region 8, Atlanta, Office of the Director 79/05/20 1p

DOCKET 90-300 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

7905040367 Forwards add responses to draft safety evaluation of fire protection program. Discusses diesel fire room sprigler and sprigler detector testing, piping penetration seal certification & flame retardant coating
EARLY, P. J. Power Authority State of New York 79/05/09 5pp

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NY-1, 25, 40, 75, 100, 111, 140, 146, 150, 151, 154, 170, 171, 174, 175, 176, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, & others.
SMITH, G. H. American Nuclear Insurers 79/05/01 1p

7905070589 Confirms increase in liability limit to \$34,000,000 for policies NY-20, 21, 22, 23, 24, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100.
ROBERTS, R. H. Mutual Atomic Energy Liability Underwriters 79/05/09 1p

7905040312 Forwards Annual 7 to Indemnity Agreement R-43, per 100P44C changeover liability insurance increase from \$100 million to \$100 million effective 790501 Supporting documentation and BALTIMORE, J. Andrius & Jendry Group 79/05/01 8pp

7905010170 Forwards Enforcement 31 to NADU Policy 79-77 3200.F.H. Power Authority State of New York 79/05/07 1p

7905020087 Forwards Annual 7 to Indemnity Agreement R-43, in response to 790501 request
CLARK, P. R. Power Authority State of New York 79/05/16 3pp

P. Operating license stage documents & correspondence

7905030377 Assigns responsibility for prompt meeting notification re 790512 show cause order
STELLER, P. Division of Operating Reactors 79/05/24 3pp

7905010044 Responds to 790514 for Apologies for difficulty in obtaining info re space shutdown. Clarifies role of Region 1 re state notification
GRUBBS, H. H. Region 1, Philadelphia, Office of the Director 79/04/12 2pp

7905040318 Forwards status report re 790427 "Plan for Verification of Dynamic Analysis Codes"
JACOBS, E. H. Stone & Webster Engineering Corp. 79/04/27 2pp

7905040205 Responds to 790514 for info requested re shutdown radiation as found in GE Nuclear Energy Sys. Div. report, "Radiation Measurements at J.A. Fitzpatrick Nuclear Power Plant"
EARLY, P. J. Power Authority State of New York 79/04/30 1p

7905050365 Forwards list of piping analyzed during original design of plant using SHOCK II computer code
EARLY, P. J. Power Authority State of New York 79/04/30 7pp

7905050315 Proposes 790504 technical meeting w/NRC to discuss utility stress management & to show attempt in reasonable
EARLY, P. J. Power Authority State of New York 79/05/03 1p

7905050312 Forwards application for amendment to GL
EARLY, P. J. Power Authority State of New York 79/05/02 2pp

--7905050177 Application for amendment to GL changing Tech Spec to add limiting condition for operating & surveillance requirements & revising administrative controls for radiological effluents
EARLY, P. J. Power Authority State of New York 79/05/07 1p

--7905050183 Proposed Tech Spec changes re radiological effluents & monitoring
P. Power Authority State of New York 79/04/30 43pp

7905040229 Forwards proprietary documents requested during 790501-01 special insp.
BARNHILL, J. A. Stone & Webster Engineering Corp. 79/05/06 1p

--7905040245 Requests withholding Technical Guideline ENRD-02-0 & Technical Rep. ENRD-012 draft ICDP, 7901 Affidavit and
BARNHILL, J. A. Stone & Webster Engineering Corp. 79/05/04 10p

7905040302 Confirms 790504 between WMT Russell re computer desk associated w/SHOCK II program
BARNHILL, J. A. Stone & Webster Engineering Corp. 79/05/09 1p

7905050115 Forwards SHOCK II computer program listing, Superseded exhibit of 790406 Program listing withheld draft
100P72, 7901
BARNHILL, J. A. Stone & Webster Engineering Corp. 79/05/14 1p

7905070713 Ask receipt of 790515 & 21 31 re spent fuel racks. Request extension of response time until 790529 Start of new spent fuel rack installation scheduled for 790705 Request approval by 790515
EARLY, P. J. Power Authority State of New York 79/05/15 1p

7905070529 Numerical procedures & calculational techniques used in reanalysis of piping gas designed w/SHOCK II computer program. Reanalysis will reflect 790512 order to show cause
BARNHILL, J. A. Stone & Webster Engineering Corp. 79/05/10 4pp

Q. Inspection reports, IE Bulletins & correspondence

7905010127 Forwards IE Info Notice 79-04, "Stress Analysis of Reactor-Related Piping"
GRUBBS, H. H. Region 1, Philadelphia, Office of the Director 79/04/30 1p

DOCKETED ITEMS

149

7905010040 Forwards SE Info Notice 79-08, "Interconnection of Contaminated Bqs w/DCV Air Bqs Used as Source of Breathing Air"
GRIER, B. H. Region I, Philadelphia. Office of the Director
79/03/28 1p

7905010084 Forwards to IE Bulletin 79-03 Welded pipe was not used at Facility
LEONARD, J. D. Power Authority State of New York 79/03/29 1p

7905010310 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Bqs"
GRIER, B. H. Region I, Philadelphia. Office of the Director
79/03/30, 2pp

7905010368 Responds to IE Bulletin 79-04, "Deterioration of Steam Components - Replacement of Components during Outage dependent upon plant startup-in view of pipe stress problems Replacement within seven years of packaging date"
LEONARD, J. D. Power Authority State of New York 79/04/04 2pp

7905010372 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bqs Misalignments Identified During TMO Incident"
GRIER, B. H. Region I, Philadelphia. Office of the Director
79/04/11 1p

7905010384 Requests add info to complete inventory testing program Info needed includes pump, valve, core spray, reactor core isolation cooling system, reactor water cleanup system, steam area, and chilled water
IPFOLD, T. A. Operating Reactors Branch 3 79/04/12 2pp

7905010392 Forwards IE Bulletin 79-09, "Seismic Stress Analysis of Safety-Related Piping - Licensee action required"
GRIER, B. H. Region I, Philadelphia. Office of the Director
79/04/14 1p

7905040074 Forwards IE Bulletin 79-06, "Review of Operational Errors & Bqs Misalignments Identified During TMO Incident"
GRIER, B. H. Region I, Philadelphia. Office of the Director
79/04/14, 1p

7905040249 Forwards IE Bulletin 79-05, "Events Relevant to Boiling Water Reactor Identified During TMO Incident"
Licensee action required
GRIER, B. H. Region I, Philadelphia. Office of the Director
79/04/14 1p

7905040290 Responds to IE Bulletin 79-05, "Seismic Stress Analysis of Safety-Related Piping - A/E currently testing seismic stress on a safety-related piping. Results will be reported per show cause order issued 790511"
LEONARD, J. D. Power Authority State of New York 79/04/16 1p

7905050053 Forwards IE Bulletin 79-09, "Failures of OE Type AN-2 Circuit Breaker in Safety-Related Bqs - Licensee action required"
GRIER, B. H. Region I, Philadelphia. Office of the Director
79/04/17 1p

7905050296 Forwards IE Bulletin 79-06, Revision 1, "Review of Operational Errors & Bqs Misalignments Identified During TMO Incident"
GRIER, B. H. Region I, Philadelphia. Office of the Director
79/04/18 1p

7905050394 Responds to IE Bulletin 79-08, "Hq personnel reviewed procedures in operations desk which could jeopardize & lead under abnormal conditions. Containment isolation & initiation design reviewed"
LEONARD, J. D. Power Authority State of New York 79/05/23 2pp

7905100452 Inform that response to 790412 inquiry re inventory testing program was provided at 790425-26 meeting w/HQ & BQC. Revised program based on meeting resolutions will be submitted.
EARLY, P. J. Power Authority State of New York 79/05/08 1p

7905100430 Supplements 790425 response to IE Bulletin 79-08 re TMO incident implications for BQs. Amend being developed to correct instrumentation tables in Tech Spec identified in bulletin. Unnecessary non-safety-related discrepancies
EARLY, P. J. Power Authority State of New York 79/05/09 2pp

B. Periodic operating reports & related correspondence

7905010343 Submits weekly status report of BW piping reanalysis, as of 790420
EARLY, P. J. Power Authority State of New York 79/05/01 2pp

7905100254 Forwards weekly operating report for Apr 1979.
LEONARD, J. D. Power Authority State of New York 79/05/06, 1p

7905100256 Monthly operating report for Apr 1979
DUPLET, E. Power Authority State of New York 79/05/01 2pp

7905240697 Forwards weekly status report of BW piping reanalysis, as of 790515
EARLY, P. J. Power Authority State of New York 79/05/18 1p

C. Repeatable occurrences, LERs & related correspondence

7905010449 Forwards LER 79-022/04L-0
LEONARD, J. D. Power Authority State of New York 79/04/24 1p

7905010503 LER 79-022/04L-0 on 790409 monitor 17-06-558 did not activate local & remote high alarm as required by surveillance test P-RT-13 caused by drift in trip setpoint Pulse height discriminator adjusted
CHILDS, M. V. Power Authority State of New York 79/04/24 2pp

7905010528 Forwards LER 79-021/03L-0
LEONARD, J. D. Power Authority State of New York 79/04/24 1p

7905010503 LER 79-021/03L-0 on 790327 auxiliary power lost while in cold shutdown Emergency stop water gas started automatically Caused by loose wire in controller of motor operated valves Correction required
CHILDS, M. V. Power Authority State of New York 79/04/24 2pp

7905010478 Forwards LER 79-023/04L-0
LEONARD, J. D. Power Authority State of New York 79/05/07 1p

7905010477 LER 79-023/04L-0 on 790411 MPEI turbine disconnected for internal trip-requiring disassembly of piping for fixed fire suppression system contrary to Tech Spec Will remain disabled until 790515 when reassembly is complete
CHILDS, M. V. Power Authority State of New York 79/05/09 2pp

7905010441 Forwards LER 79-024/03L-0
LEONARD, J. D. Power Authority State of New York 79/05/24 1p

7905030416 LER 79-024/03L-0 on 790426 emergency stop water pump B could not be demonstrated to produce min shutdown level of 120 psig Caused by manual water Tech Spec amend to reduce shutoff head requirement under consideration
CHILDS, M. V. Power Authority State of New York 79/05/24 2pp

7905030356 Forwards LER 79-017/03L-1
LEONARD, J. D. Power Authority State of New York 79/05/24 1p

7905030314 LER 79-017/03L-1 on 790320 while surveillance test P-RT-345 was being conducted, station gas breakdown gas & in valve Q 12C-100-14 would not open Caused by failure of auxiliary controller in valve motor controller Contractor replaced
CHILDS, M. V. Power Authority State of New York 79/05/24 2pp

7905030322 Forwards LER 79-025/03L-0
LEONARD, J. D. Power Authority State of New York 79/05/24 1p

7905030327 LER 79-025/03L-0 on 790426 while conducting surveillance test P-RT-704A-section valve did not appear to be opening fully. Damaged gaskets may have been causing sluggish operation of valve Gasket replaced
CHILDS, M. V. Power Authority State of New York 79/05/24 2pp

DOCKET 20-034 REANER VALLEY POWER STATION, UNIT 1

a. Adjudicatory correspondence

7905010038 Reactor plant shutdown because of threat of accident as severe as rupture to reactor vessel
SEAWARD, G. R. Application Number 79/04/12 2pp

J. Insurance & indemnity information

7905070447 Confirms increased liability limit to \$124,000,000 for policies AP-1, 23, 43, 76, 83, 103, 111, 140, 146, 151, 161, 164, 170, 173, 174, 176, 179, 180, 186, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 204-007, 209, 210, 212, 214, 215, & others.
BUNTWISCH, J. American Nuclear Insurers 79/05/01 1p

7905070389 Confirms increase in liability limit to \$24,000,000 for policies AP-23, 25, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 79, 80, 84, 87, 88, 91, 91-02, 93, 94, 95 & 96.
ROBERTS, G. R. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

DOCKETED ITEMS

7905160199 Forwards Amend 5 to Indemnity Agreement B-73, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

P. Operating license stage documents & correspondence

7905080347 Assigns responsibility for prompt meeting notification re 790313 show cause orders.
STELLON, V. Division of Operating Reactors. 79/03/29. 3pp.

7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys.
SCHWENGER, A. Operating Reactors Branch 1. 79/04/02. 1p.

7905290723 Summary of 790329-30 meeting w/util & S&W in Boston, MA re progress to date & early analysis of pipe stresses in safety-related sys.
WIGGINTON, D. Operating Reactors Branch 1. 79/04/10. 3pp.

7905090066 Submits engineering info re pipe stress reanalysis. Oversized diagrams available in Central Files only.
DUNN, C.N. Duquesne Light Co. 79/04/19. 2pp.

7905040615 Forwards status rept on 790427 "Plan for Verification of Dynamic Analysis Codes."
JACOBS, S.B. Stone & Webster Engineering Corp. 79/04/27. 2pp.

7905080370 Forwards response to Questions 362.1, 362.2 & 362.3 of NRC 790109 ltr. Also forwards soil analysis of turbine bldg & northern yard area, dtd 790430, in response to Question 362.4.
WOOLEVER, E.J. Duquesne Light Co. 79/05/02. 600pp.

7905110011 Responds to NRC 780913 ltr. Forwards reanalysis of effects of major LOCA. Requests permission to remove present administrative limit of 2.31 & to restore existing Tech Spec limit of 2.32.
DUNN, C.N. Duquesne Light Co. 79/05/07. 75pp.

7905110070 Forwards addl info re new steam line break protection sys. in response to informal questions during review.
DUNN, C.N. Duquesne Light Co. 79/05/07. 10pp.

7905140239 Forwards proprietary documents requested during 790501-04 special insp.
ERLEWINE, J.A. Stone & Webster Engineering Corp. 79/05/08. 1p.

--7905140245 Requests withholding Technical Guideline EMTG-22-0 & Technical Rept EMTR-612 (ref 10CFR2.790). Affidavit encl.
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/04. 10pp.

7905140382 Confirms 790504 telcon w/WT Russell re computer deck associated w/SHOCK O program.
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/09. 1p.

7905160335 Notifies of review completion of computer deck. SHOCK O program still unrecovered. Piping sys conservatively designed & will perform intended function.
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/11. 1p.

7905210111 Forwards SHOCK 1 computer program listing. Supersedes submittal of 790406. Program listing withheld (ref 10CFR2.790).
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/14. 1p.

7905220081 Requests amend to OL changing ETS to eliminate aquatic monitoring except for fish impingement. W/proposed ETS App B to License DPR-66 & special study on aquatic monitoring reduction.
DUNN, C.N. Duquesne Light Co. 79/05/15. 225pp.

7905220093 Forwards proposed amend to OL consisting of revised versions of previously submitted Offsite Dose Calculation Manual & "Process Control Program."
DUNN, C.N. Duquesne Light Co. 79/05/15. 2pp.

--7905220099 Offsite Dose Calculation Manual.
* Duquesne Light Co. 79/05/01. 131pp.

--7905220104 "Process Control Program."
* Duquesne Light Co. 79/05/01. 31pp.

7905240583 Discusses monitoring capabilities of reactor incore thermocouples. Fifty operable thermocouples may be defective or have insecure head connectors.
CAREY, J.J. Duquesne Light Co. 79/05/16. 2pp.

7905290335 Summarizes procedures & calculational techniques used in reanalysis of piping sys designed w/SHOCK II computer program. Reanalysis will satisfy 790313 order to show cause.
KENNEDY, W.J. Stone & Webster Engineering Corp. 79/05/18. 6pp.

Q. Inspection reports, IE Bulletins & correspondence

7905010105 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905010042 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/28. 1p.

7905010297 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/30. 1p.

7905290123 Forwards IE Insp Rept 50-334/79-06 on 790227-0302. No noncompliance noted.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/03. 2pp.

--7905290126 IE Insp Rept 50-334/79-06 on 790227-0302. No noncompliance noted. Major areas inspected: previously identified unresolved items & sequence of events re recent high river water level.
MARKOWSKI, R. Region 1, Philadelphia, Office of the Director. KISTER, H.B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/28. 6pp.

7905290154 Forwards IE Insp Rept 50-334/79-07 on 790315-16. No noncompliance noted.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/10. 2pp.

--7905290157 IE Insp Rept 50-334/79-07 on 790315-16. No noncompliance noted. Major areas inspected: compliance w/790313 order to show cause.
BECKMAN, D.A. Region 1, Philadelphia, Office of the Director. KEIMIG, R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/14. 3pp.

7905020039 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

7905140322 Informs that pipe type described in IE Bulletin 79-03 has not been used in safety-related sys.
DUNN, C.N. Duquesne Light Co. 79/04/11. 1p.

7905020346 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040018 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040198 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905030060 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905010643 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

7905250461 Responds to IE Bulletin 79-07 re analysis of safety-related piping. Currently reanalyzing piping, per NRC 790313 order to show cause.
DUNN, C.N. Duquesne Light Co. 79/04/23. 1p.

DOCKETED ITEMS

151

7905070373 Forwards proposed "Inservice Insp Program" for 20-month period starting 790301. Program prepared per NRC 780110 request. Encl available in Central Files.
DUNN, C. N. Duquesne Light Co. 79/05/02. 1p.

R. Periodic operating reports & related correspondence

7905010491 Forwards "1978 Annual Environ Rept. Radiological," Vol 2.
DUNN, C. N. Duquesne Light Co. 79/04/24. 1p.

--7905010493 "1978 Annual Environ Rept. Radiological," Vol 2.
* Duquesne Light Co. 79/04/24. 120pp.

7905010532 Forwards national pollution discharge elimination sys monthly discharge monitoring rept for Mar 1979.
MOORE, G. W. Duquesne Light Co. 79/04/27. 3pp.

--7905010537 National pollution discharge elimination sys monthly discharge monitoring rept for Mar 1979.
MOORE, G. W. Duquesne Light Co. 79/04/27. 12pp.

7905030342 Forwards Nov 1978 "Reactor Containment Integrated Leak Rate Test Rept."
NUNN, C. N. Duquesne Light Co. 79/04/30. 1p.

--7905030344 "Reactor Containment Integrated Leak Rate Test Rept."
* Duquesne Light Co. 78/11/30. 83pp.

7905140300 Forwards monthly operating rept for Apr 1979.
DUNN, C. N. Duquesne Light Co. 79/05/04. 1p.

--7905140302 Monthly operating rept for Apr 1979.
TIMKO, D. R. Duquesne Light Co. 79/05/02. 4pp.

S. Reportable occurrences, LERs & related correspondence

7905310384 RO 79-8/01P on 790329: notified by vendor of potential for single dropped control rod to lead to calculated DNB ratios lower than reported to NRC in safety analysis. Caused by inconsistency between control settings used & those assumed.
WERLING, J. A. Duquesne Light Co. 79/03/30. 2pp.

7905080460 Forwards LER 79-010/01T-0.
WERLING, J. A. Duquesne Light Co. 79/04/30. 2pp.

--7905080468 LER 79-010/01T-0 on 790416: GE notified util of potential for failure of inside recirculation spray pump motor. Analysis indicates problem may occur when all bearing part tolerances & bearing housings are at extreme end of spectrum.
WERLING, J. A. Duquesne Light Co. 79/04/30. 2pp.

7905080545 Forwards LER 79-011/04T-0.
WERLING, J. A. Duquesne Light Co. 79/05/02. 2pp.

--7905080551 LER 79-011/04T-0 on 790430: tritium activity in quarterly composite of grab samples collected in OH River exceeded ETS limits. Caused by tritium discharge during normal plant operation.
WERLING, T. A. Duquesne Light Co. 79/05/02. 1p.

7905150531 Forwards LER 79-012/04T-0.
WERLING, J. A. Duquesne Light Co. 79/05/10. 2pp.

--7905150536 LER 79-012/04T-0 on 790430: gross beta in monthly composite grab samples from OH River exceeded ETS reporting level. Caused by naturally occurring radioactivity in sediments.
WERLING, J. A. Duquesne Light Co. 79/05/10. 1p.

7905240568 Submits special rept on diesel driven fire pump removed from svc on 790416 when intake bay was drained for maint. Motor-driven pump remained operable. Diesel pump returned to svc on 790503.
WERLING, J. A. Duquesne Light Co. 79/05/14. 2pp.

DOCKET 50-335 ST. LUCIE PLANT, UNIT 1

G. Adjudicatory correspondence

7905150125 Forwards NRC rept "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie."
SOHINKI, S. M. Branch 3. 79/04/11. 1p.

--7905150130 "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie."
MCTIERNAN, T. J. Office of Inspector & Auditor. 78/06/30. 85pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
GUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905160198 Forwards Amend 5 to Indemnity Agreement B-76, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

7905100309 Forwards Endorsement 31 to NELIA Policy NF-227.
FIELDER, J. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div. 79/05/04. 2pp.

7905100311 Forwards Endorsement 32 to NELIA Policy NF-227.
FIELDER, J. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div. 79/05/04. 2pp.

7905250397 Forwards executed Amend 5 to Indemnity Agreement B-76, increasing coverage to \$160 million.
UHRIG, R. E. Florida Power & Light Co. 79/05/21. 3pp.

M. Antitrust correspondence

7905150234 Motion by FL Cities seeking antitrust hearing. Renews request to argue position re review & consolidation of antitrust issue. Certificate of Svc encl.
JABLON, R. A. Spiegel & McDiarmid. 79/03/28. 2pp.

7905150729 Forwards motion for consolidated hearings on behalf of FL Cities.
JABLON, R. A. Spiegel & McDiarmid. 79/04/02. 1p.

--7905150733 Motion for consolidated hearings by FL Cities. Certificate of Svc encl.
JABLON, R. A. Spiegel & McDiarmid. 79/04/02. 4pp.

7905230622 Responds to 790328 & 790402 motions filed by FL Cities to initiate antitrust hearing, in response to NRC 780727 order. Certificate of Svc encl.
DEWEY, L., CHANANIA, F. D., EVANS, D. J. Anti-Trust Division. 79/04/17. 5pp.

P. Operating license stage documents & correspondence

7905070231 Forwards Amend 31 to License DPR-67, safety evaluation & notice of issuance & availability.
REID, R. W. Operating Reactors Branch 4. 79/04/05. 2pp.

--7905070236 Amend 31 to License DPR-67, modifying Tech Specs to allow replacement of selected safety-related hydraulic snubbers w/mechanical snubbers & to revise snubber surveillance requirements.
REID, R. W. Operating Reactors Branch 4. 79/04/05. 15pp.

--7905070277 Safety evaluation supporting Amend 31 to License DPR-67.
* Office of Nuclear Reactor Regulation. 79/04/05. 3pp.

--7905070299 Notice of issuance & availability of Amend 31 to License DPR-67.
REID, R. W. Operating Reactors Branch 4. 79/04/05. 2pp.

7905150798 Notifies of adequacy of licensee's sys for insuring feeding is maintained full of water at all times. Suggests auxiliary feedwater flow be actuated automatically to obtain time lapse of less than one minute.
LAINAS, G. Plant Systems Branch. 79/04/13. 2pp.

DOCKETED ITEMS

7905130278 Requests addl info re review of proposed pump & valve test program submitted by 770916 & 780908 ltrs. Encl 1 identifies info needed on certain check valves.
REID, R.W. Operating Reactors Branch 4. 79/04/20. 5pp.

7905250263 Forwards safety evaluations re fuel handling accident inside containment.
REID, R.W. Operating Reactors Branch 4. 79/04/27. 2pp.

--7905250275 Safety evaluation re fuel handling accident inside containment. Reveals fuel handling accident w/one or two assemblies would provide doses within 10CFR100 guideline values.
* Office of Nuclear Reactor Regulation. 79/04/27. 4pp.

7905040585 Forwards addl info for Cycle 3 reload application re anticipated burnup for clad collapse for each fuel batch, combining of fuel pin powers & augmentation factors & investigation of control elements assembly sticking.
UGRIG, R.E. Florida Power & Light Co. 79/04/30. 12pp.

7905070410 Provides status of verification program for technique of measuring resistance temp detectors time constants.
UGRIG, R.E. Florida Power & Light Co. 79/05/01. 2pp.

7905140310 Reviews impact of using NRC fission gas release enhancement factors on results of Cycle 3 safety analyses. Application of factors does not adversely affect Cycle 3 results of 790222.
UGRIG, R.E. Florida Power & Light Co. 79/05/08. 1p.

7905210121 Forwards startup testing info as suppl to Cycle 3 reload safety evaluation.
UGRIG, R.E. Florida Power & Light Co. 79/05/10. 2pp.

7905220027 Forwards response to questions re reload safety evaluation.
UGRIG, R.E. Florida Power & Light Co. 79/05/18. 13pp.

7905310214 Forwards responses to questions re reload safety evaluation.
UGRIG, R.E. Florida Power & Light Co. 79/05/22. 10pp.

7905300014 Forwards responses to reload safety evaluation questions.
UGRIG, R.E. Florida Power & Light Co. 79/05/23. 6pp.

7905310305 Submits info in response to NRC request. Zero power physics tests after reload performed according to procedures. Review criteria will be established. Evaluation of difference in individual assemblies power to be sent in two weeks.
UGRIG, R.E. Florida Power & Light Co. 79/05/25. 2pp.

7905310309 Confirms 790324 discussion during which util agreed to limit containment purging in operational Modes 1 & 2 to 90-h/year.
UGRIG, R.E. Florida Power & Light Co. 79/05/25. 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010195 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905030310 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905010104 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.

7905010358 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.

7905240045 Ack receipt of IE Insp Rept 50-335/79-04 on 790207-09. No proprietary info.
UGRIG, R.E. Florida Power & Light Co. 79/04/10. 1p.

--7905240054 Forwards IE Insp Rept 50-335/79-04 on 790207-09. No noncompliance noted.
KENNA, W.B. Region 2, Atlanta, Safeguards Branch. 79/03/12. 2pp.

--7905240069 IE Insp Rept 50-335/79-04 on 790207-09. No noncompliance noted. Major areas inspected: facility organization & operation, measurement & controls, shipping & receiving, storage & internal control, inventory & records.
TODD, G.A., CLAY, E.L. Region 2, Atlanta, Office of the Director.
WILLIAMS, G.H. Region 2, Atlanta, Safeguards Branch. 79/03/08. 4pp.

7905020127 Forwards IE Bulletin 79-06, "Review of Operational Error¹ Sys Misalignments Identified During TMI Incident." Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/11. 1p.

7905040141 Forwards IE Bulletin 79-06B, "Review of Operational Error¹ Sys Misalignments Identified During TMI Incident." Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040308 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905040404 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905030164 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp.

7905020465 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905240169 Responds to IE Bulletin 79-07 re seismic analysis of safety-related piping. No such computer codes used.
UGRIG, R.E. Florida Power & Light Co. 79/04/26. 3pp.

7905290150 Ack receipt of 790403 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-335/79-01.
O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/05/01. 1p.

--7905290159 Responds to NRC 790308 ltr re violations noted in IE Insp Rept 50-335/79-01. Corrective actions: calibr info sheet 039 corrected & appropriate personnel instructed on correct method of making changes.
UGRIG, R.E. Florida Power & Light Co. 79/04/03. 3pp.

--7905290167 Forwards IE Insp Rept 50-335/79-01 on 790109-12 & notice of violation.
LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/08. 2pp.

--7905290170 Notice of violation from insp on 790109-12.
* Region 2, Atlanta, Office of the Director. 79/03/07. 1p.

--7905290174 IE Insp Rept 50-335/79-01 on 790109-12. Noncompliance not failure to review calibr procedures.
WEBSTER, E.H., MOSSITT, B.R., CANTRELL, F.S. Region 2, Atlanta, Office of the Director. 79/03/07. 13pp.

S. Reportable occurrences, LERs & related correspondence

7905150241 Forwards LER 79-009/03L-0.
SCHLMIDT, A.D. Florida Power & Light Co. 79/04/04. 1p.

--7905150249 LER 79-009/03L-0 on 790305: control element assembly 2 wq not withdraw fully from misalignment to check control element assembly position alarms. Caused by faulty upper electric limit reed switch. Switch will be replaced.
JAMES, D.K. Florida Power & Light Co. 79/04/04. 1p.

7905090062 Forwards LER 79-013/03L-0.
SCHLMIDT, A.D. Florida Power & Light Co. 79/04/30. 1p.

--7905090064 LER 79-013/03L-0 on 790331: during surveillance testing of diesel generator, solenoid-operated fill valve for engine mounted fuel oil tank failed to open, causing tank level to drop below limit. Caused by burnt contacts in relay.
SCHOPPMAN, M.A. Florida Power & Light Co. 79/04/30. 1p.

7905220091 Forwards LER 79-014/03L-0.
SCHLMIDT, A.D. Florida Power & Light Co. 79/05/09. 1p.

--7905220098 LER 79-014/03L-0 on 790409: notified by vendor that crankshaft coupling for cooling fans used on diesels failed in other applications. Couplings replaced w/couplings of improved design, under directions from diesel vendor.
SCHOPPMAN, M.A. Florida Power & Light Co. 79/05/09. 1p.

DOCKETED ITEMS

153

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

7905290073 Forwards response to NRC verbal questions re fire protection. Engineering & design of most mods in progress.
COUNCIL, W.G. Northeast Utilities. 79/05/18. 16pp.

J. Insurance & indemnity information

7905140422 Forwards Amend 14 to Indemnity Agreement B-39 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905190075 Forwards executed Amend 14 to Indemnity Agreement B-39.
O'CONNOR, L.A. Northeast Utilities. 79/05/15. 4pp.

P. Operating license stage documents & correspondence

7905070332 Forwards Amend 50 to License DPR-65, safety evaluation & notice of issuance & availability.
REID, R.W. Operating Reactors Branch 4. 79/03/23. 2pp.

--7905070337 Amend 50 to License DPR-65, incorporating low temp overpressure protection sys requirements.
REID, R.W. Operating Reactors Branch 4. 79/03/23. 20pp.

--7905070347 Safety evaluation supporting Amend 50 to License DPR-65.
* Office of Nuclear Reactor Regulation. 79/03/23. 17pp.

--7905070351 Notice of issuance & availability of Amend 50 to License DPR-65.
REID, R.W. Operating Reactors Branch 4. 79/03/23. 2pp.

7905240253 Forwards draft safety evaluation re proposed neutron shield design to reduce radiation level outside containment. Load analysis to be completed 800101.
LAINAS, G. Plant Systems Branch. 79/04/17. 7pp.

7905290007 Forwards Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, EIA & notice of issuance & negative declaration.
ZIEHMANN, D.L. Operating Reactors Branch 2. 79/04/24. 3pp.

--7905290012 Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, revising ETS to provide more flexibility in sampling schedules & collection for aquatic monitoring & reflecting improved & modified program objectives.
ZIEHMANN, D.L. Operating Reactors Branch 2. 79/04/24. 13pp.

--7905290016 EIA supporting Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively.
* Office of Nuclear Reactor Regulation. 79/04/24. 11pp.

--7905290019 Notice of issuance of Amends 60 & 51 to Licenses DPR-21 & DPR-65, respectively, & negative declaration.
ZIEHMANN, D.L. Operating Reactors Branch 2. 79/04/24. 2pp.

7905040135 Responds to NRC 780419 request for insulation resistance tests. Forwards electrical penetration testing evaluation. Modified conductor configuration is acceptable for Cycle 3 operation.
COUNCIL, W.G. Northeast Utilities. 79/04/26. 8pp.

7905070359 Forwards proposed revision to Tech Specs to allow unlimited containment purges. Revisions deal w/containment isolation valves.
COUNCIL, W.G. Northeast Utilities. 79/04/27. 16pp.

7905080406 Forwards responses to request for addl info re Cycle 3 safety analysis. Nonproprietary rept encl. Proprietary version withheld (ref 10CFR2.790).
COUNCIL, W.G. Northeast Utilities. 79/05/03. 17pp.

7905100320 Discusses addl info re control element assembly guide tube insp. Fuel assemblies suitable for continued use during Cycle 3 operation.
COUNCIL, W.G. Northeast Utilities. 79/05/07. 2pp.

7905160262 Notifies that stem-mounted limit switches on valves SI-614, SI-624, SI-634 & SI-644 will not be replaced; valves do not perform safety-related function.
COUNCIL, W.G., SWITZER, D.C. Northeast Utilities. 79/05/08. 2pp.

7905160376 Discusses results of six tasks which utilized ADLPIPE computer program for reanalysis of piping sys. Mods involved minor changes to small portions of existing sys.
COUNCIL, W.G., SWITZER, D.C. Northeast Utilities. 79/05/11. 3pp.

7905300645 Informs of forthcoming detailed reply to 790507 ltr re CT nuclear power plants. Plants will not start up until all post-TMI items & requirements are implemented & confirmed.
HENDRIE, J.M. Commission. 79/05/11. 1p.

--7905300647 Requests assurance that action required by IE info notices & bulletins have been implemented before CT plants return to operation. Also requests info on other anticipated NRC actions or anticipated problems.
GRASSO, E. Connecticut, State of. 79/05/07. 2pp.

7905220116 Forwards addl info re performance of control element assembly guide tube sleeves, in response to 790512 ltr.
COUNCIL, W.G. Northeast Utilities. 79/05/17. 6pp.

7905300009 Comments on need for repairing or replacing aerated radwaste evaporator. Replacement not warranted, based on discharge criteria, actual plant releases & ALARA considerations.
COUNCIL, W.G. Northeast Utilities. 79/05/21. 2pp.

7905310183 Forwards proprietary & nonproprietary versions of "Sleeved CEA Guide Tube Eddy Current Test Results." Proprietary version withheld (ref 10CFR2.790). W/affidavit re withholding.
COUNCIL, W.G. Northeast Utilities. 79/05/23. 6pp.

--7905310189 "Sleeved CEA Guide Tube Eddy Current Test Results."
* Northeast Utilities. CEN-108(N)-NP. 79/05/02. 6pp.

G. Inspection reports, IE Bulletins & correspondence

7905240692 Forwards IE Insp Repts 50-245/78-42 & 50-336/78-39 on 781208-790105. No noncompliance noted.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/21. 2pp.

--7905240704 IE Insp Repts 50-245/78-42 & 50-336/78-39 on 781208-790105. No noncompliance noted. Major areas inspected: Unit 1 reactor, turbine & radwaste bldgs; Unit 2 auxiliary & turbine bldgs, condensate polishing facility & radiation protection.
SHEDLOSKEY, J.T. Region 1, Philadelphia, Office of the Director.
MCCABE, E.C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/20. 13pp.

7905010121 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905010053 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/28. 1p.

7905010304 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/30. 2pp.

7905290160 Forwards IE Insp Rept 50-336/79-04 on 790220-23. No noncompliance noted.
BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/04/10. 2pp.

--7905290166 IE Insp Rept 50-336/79-04 on 790220-23. No noncompliance noted. Major areas inspected: administrative controls of facility procedures & safety related calibr.
ZIMMERMAN, R.P., BAUNACK, W.H. Region 1, Philadelphia, Office of the Director.
KISTER, H.B. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/27. 16pp.

7905020061 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

7905020300 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

DOCKETED ITEMS

7905040049 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/04/14 1p

7905040214 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/04/14 1p

7905030077 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/04/17 1p

7905020284 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director.
79/04/18 1p

7905040053 Discusses guide tube insp program. Pull tests performed on 354 sleeves. Evaluation of data indicates sleeves are functioning as expected.
COUNCIL, W.G. Northeast Utilities. 79/04/26 2pp.

79050300261 Provides info in response to NRC request re impact of mods & reanalyses on high energy pipe break. Topic discussed in util 790511 response to IE Bulletin 79-07.
COUNCIL, W.G. Northeast Utilities. 79/05/23 2pp.

R. Periodic operating reports & related correspondence

7905150502 Forwards monthly operating rept for Apr 1979.
OPEKA, J.F. Northeast Utilities. 79/05/09 1p.

--7905150505 Monthly operating rept for Apr 1979.
HOWLETT, G.H. Northeast Utilities. 79/05/02 5pp.

S. Reportable occurrences, LERs & related correspondence

7905140067 PNO-79-91: vapor binding of shutdown cooling sys pump on 790314. Suction restored; no radioactive matl released to environ.
KILINGER, C., NOLAN, F., BRYAN, S.E. Office of Inspection & Enforcement. 79/04/23 1p.

7905080456 Forwards LER 78-022/03X-1.
OPEKA, J.F. Northeast Utilities. 79/04/30 1p.

--7905080461 LER 78-022/03X-1 on 780906: loss of efficiency noted in methyl iodide removal sys for encl bldg A filtration sys train. Caused by normal degradation through use.
MCCANN, W.J. Northeast Utilities. 79/04/30 1p.

7905300452 Forwards LER 79-011/03L-0.
OPEKA, J.F. Northeast Utilities. 79/05/18 1p.

--7905300457 LER 79-011/03L-0 on 790514: one electrical penetration & several boundary valves had leakage. Caused by inadvertent omission of pre-repair leak rate measurement for some valves. Test procedures to be revised.
STRATHMAN, R.A. Northeast Utilities. 79/05/18 3pp.

7905290221 RD 79-12/1P: inoperable linear power range channels. Caused by open connections between channels A & D detector cables. Connections repaired.
OPEKA, J.F. Northeast Utilities. 79/05/22 1p.

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

G. Adjudicatory correspondence

7905030262 Petition for formal intervenor status on turbine missile issue. If denied, requests permission to present evidence & cross-examine as amicus curiae. Certificate of Svc encl.
WEISS, E.R. Sheldon, Harmon & Roisman. 79/03/14 9pp.

7905030207 Agreement via stipulation of contentions, including withdrawal of previous contentions. Notice of appearance of RJ Goddard on behalf of NRC & Certificate of Svc encl.
DOUGHERTY, J.B. Potomac Alliance. GOLDBERG, S.C. Regulations Division. CHRISTMAN, J. Virginia Electric & Power Co. 79/03/23 10pp.

--7905030209 Agreement via stipulation of contentions, including withdrawal of previous contentions.
KRODT, I. Citizens Energy Forum. GOLDBERG, S.C. Branch 2.
CHRISTMAN, J. Virginia Electric & Power Co. 79/03/23 7pp.

7905030258 Answer by util in opposition to UCS 790314 petition to intervene. Claims untimeliness, intervention during appellate stage & lack of standing. Certificate of Svc encl.
RINACA, J.M. Hunton & Williams. 79/03/29 22pp.

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
SCINTO, J.F. Hearings Division. 79/04/02 31pp.

--7905010156 Board notification: staff assessment re nonsafety-grade equipment to mitigate transients.
VASSALLO, D.B. Assistant Director for Light Water Reactors.
79/03/29 2pp.

--7905010198 Board notification: recent issue on nonsafety-grade equipment to mitigate transients. More info is required.
TEDESCO, R.L. Assistant Director for Reactor Safety. 79/03/16 3pp.

7905230668 Notifies that recent info may affect licensing of high density spent fuel storage racks. Svc water temp & component cooling water temp will exceed values in FSAR.
CHRISTMAN, J.N. Hunton & Williams. 79/04/04 2pp.

7905240135 ALAB-536, denying UCS 790314 petition to intervene or participate in hearing as amicus curiae.
DUFLD, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/05 8pp.

7905240487 Directs parties to submit responsive prepared testimony re pumphouse settlement & turbine missile issues before 790531. Evidentiary hearing to be held during week of 790618. Lists procedures for informal discovery process.
DUFLD, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/09 4pp.

7905100137 Forwards EIA re proposed increase of storage capacity of spent fuel pool.
GOLDBERG, S.C. Branch 2. 79/04/10 1p.

--7905100140 EIA supporting proposed increase in storage capacity of spent fuel pool.
* Office of Nuclear Reactor Regulation. 79/04/02 32pp.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Svc encl.
SCINTO, J.F. Hearings Division. 79/04/11 45pp.

7905140319 Response to 790404 brief of Philadelphia Electric Co, PSE&O & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl.
KEPPORD, C.R. Citizens for Safe Environment. 79/04/11 8pp.

7905241006 Corrects info submitted on 790334 re deficiency in Westinghouse ECCS evaluation model. Model reanalysis indicates North Anna 1 & 2 still in compliance w/10CFR50.46.
SWANSON, D.T. Branch 1. 79/04/13 1p.

7905240255 Requests extension of time to 790504 in which to prepare testimony. Granted by ASLAB on 790420. Certificate of Svc encl.
SWANSON, D.T. Branch 1. 79/04/20 5pp.

7905230655 Grants interventions of Citizens Energy Forum & Potomac Alliance. Provides for hearing & designates contentions of intervenors.
DEALE, V.B. Atomic Safety and Licensing Board Panel. 79/04/21 4pp.

7905030330 Affidavit of Svc for applicant's Amend 66 in proceeding.
NEIL, R.M. Virginia, State of. 79/04/25 2pp.

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLD, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/25 13pp.

7905240814 Forwards second copy of util's testimony re probability of generating turbine missiles & turbine overspeed protection sys. W/o encl.
CHRISTMAN, J.N. Hunton & Williams. 79/04/30 2pp.

DOCKETED ITEMS

155

7905240455 Ack receipt of 790405 ltr requesting NRC to revoke OLs. Ltr is currently under consideration. Forwards FR notice re Allen 790405 ltr.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/04. 1p.

--7905240461 FR notice re J Allen 790405 request for revocation of OLs.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/04. 2pp.

7905240510 Extends time for NRC review of ALAB-536 until 790511.
CHILK, S. J. Office of the Secretary of the Commission. 79/05/04. 1p.

7905240571 Following 790626 prehearing conference, hearing shall commence re application by util for OL amend to increase spent fuel pool storage capacity, per 790423 order granting intervention.
DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/05/04. 5pp.

7905310033 Forwards J Allen 790405 ltr requesting NRC revoke facility OLs & FR notice of revocation request. W/790330 ltr to ASLAB re Westinghouse ECCS deficiency.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/05/04. 3pp.

7905250233 Request to amend petition to intervene by adding contention re svc water cooling sys. Notice of appearance of GM Gilman on behalf of intervenors. Certificate of Svc & supporting documentation encl.
DOUGHERTY, J. B., GILMAN, G. Potomac Alliance. 79/05/09. 11pp.

I. Financial information

7905020439 Discusses SEC 790321 ltr & registration statement. Util will file another statement which NRC will be able to review.
DROMERICK, A. W. Light Water Reactors Branch 3. 79/04/09. 1p.

--7905020466 Forwards SEC 790316 registration statement filed by util. Requests comments by 790330; util wishes statement to become effective by 790402.
MORIN, H. F. Securities & Exchange Commission. 79/03/21. 60pp.

J. Insurance & indemnity information

7905110107 Amend to Endorsement 51 to NELIA Policy NF-186. Constitutes Endorsement 54.
* Nuclear Energy Liability Insurance Association. 79/04/27. 1p.

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905110090 Endorsements 16, 30, 36 & 47 to NELIA Policy NF-186.
BARDES, C. R. Nuclear Energy Liability Insurance Association. 79/05/01. 1p.

7905140523 Forwards Amend 5 to Indemnity Agreement B-80 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905240342 Forwards executed Amend 5 to Indemnity Agreement B-80.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/21. 2pp.

7905300334 Forwards Endorsements 17, 20 & 21 to NELIA Policy NF-240.
KELLEY, P. J. Johnson & Higgins Insurance. 79/05/23. 4pp.

D. Advisory Committee on Reactor Safeguards reports & correspondence

7905100325 Responds to request for written rept after cancellation of ACRS 790331 meeting re possibility of problem w/instrument guide tubes Staff rept encl.
CROCKER, L. P. Division of Project Management. 79/03/30. 5pp.

P. Operating license stage documents & correspondence

7905020490 Discusses 790315 telcon w/R Sero of Westinghouse re incorrect weights for Velan Model C658 6-inch check valves used in safety injection sys.
SCHWENGER, A. Operating Reactors Branch 1. 79/04/02. 1p.

7905070087 Forwards EIA re expansion of spent fuel storage pool.
REGAN, W. H. Environmental Projects Branch 2. 79/04/06. 1p.

--7905070090 EIA re proposed increase in storage capacity of spent fuel pool.
* Environmental Projects Branch 2. 79/04/02. 32pp.

7905090304 Informs of completion of review of 781226 revised plant staff organization. Revisions acceptable if addl level is added & if appointment of alternates is clarified.
PARR, O. D. Light Water Reactors Branch 4. 79/04/09. 5pp.

7905020358 Ack receipt of 790409 ltr re reorganization. Modified requirements for personnel qualifications will be incorporated into FSAR in upcoming amend.
STALLINGS, C. M. Virginia Electric & Power Co. 79/04/27. 1p.

7905040126 Responds to AW Dromerick request re elevation marker readings located on svc water piping at svc water pumphouse.
BROWN, S. C. Virginia Electric & Power Co. 79/05/01. 1p.

7905240407 Submits 790903 elevations of three settlement markers at svc water pumphouse.
BROWN, S. C. Virginia Electric & Power Co. 79/05/01. 1p.

7905100317 Forwards drawings of stainless steel pressure-balanced expansion joints for svc water piping at svc water pumphouse, in response to AW Dromerick request. Oversized drawings encl.
BROWN, S. C. Virginia Electric & Power Co. 79/05/03. 1p.

7905080428 Notifies of plans to test Unit 2 auxiliary svc water pump 2-swp-4 on monthly bases, as outlined in inservice testing program submitted on 790131. Will test 1-swp-4 before OL is issued for Unit 2. Piping mod presently unnecessary.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/04. 1p.

7905080443 Supplements 790308 rept "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation." Spent fuel pool temp will exceed 110 F FSAR limit. Lists methods to meet limits. Fuel rack license application & FSAR will be amended.
BROWN, S. C. Virginia Electric & Power Co. 79/05/04. 1p.

7905080506 Lists completed Tech Specs testing requirements which should be deleted from list of tests requiring deferral for amend to OL.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/04. 1p.

7905190062 Forwards fee for issuance of Amend 10 to License NPF-4.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/07. 1p.

7905150270 Forwards replacement pages to 780501 application to amend License NPF-4 to expand spent fuel storage capacity.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/11. 10pp.

7905210176 Forwards suppl to proposed Tech Spec Change 12 re increasing amount of allowable settlement for svc water pumphouse.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17. 23pp.

7905230536 Suppl to proposed Tech Spec Change 12, "Settlement of Class I Structures," increasing amount of allowable settlement for svc waterpump house. Forwards revised Tech Spec, marked-up original & discussion of change.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17. 23pp.

7905230022 Forwards response to NRC 790503 evaluation & request for addl info re "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation."
BROWN, S. C. Virginia Electric & Power Co. 79/05/18. 8pp.

7905290375 Responds to AW Dromerick 790503 questions re containment depressurization, net positive suction head, analyses & effects of increased calculated svc water temps on design of charging pump coolers.
BROWN, S. C. Virginia Electric & Power Co. 79/05/23. 14pp.

G. Inspection reports, IE Bulletins & correspondence

7905010255 Forwards IE Insp Repts 50-338-79-01 & 50-339-79-01 on 790102-0202 & notice of violation.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/16. 2pp.

--7905010264 Notice of violation from insp on 790102-0202.
* Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14. 1p.

DOCKETED ITEMS

- 7905010275 IE Insp Repts 50-338/79-01 & 50-339/79-01 on 790102-0202. Noncompliance noted: failure to document approval of change to test procedure. KIDD, N. S., CANTRELL, F. S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14. 19pp.
- 7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.
- 7905090129 Forwards IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25 & notice of violation. LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.
- 7905090132 Notice of violation from insp on 790122-25. * Region 2, Atlanta, Office of the Director. 79/03/13. 1p.
- 7905090135 IE Insp Repts 50-338/79-04 & 50-339/79-04 on 790122-25. Noncompliance noted: failure to identify Tech Spec-listed snubbers prior to removal for testing. DYER, J. A., JOHNSON, A. H. Region 2, Atlanta, Office of the Director. MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/13. 8pp.
- 7905030319 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.
- 7905010123 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.
- 7905010369 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.
- 7905080534 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/11. 1p.
- 7905040254 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.
- 7905040271 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.
- 7905040448 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.
- sends to IE Bulletin 79-03, "Longitudinal Weld Defects in pipe 304 Stainless Steel Pipe Spools Mfg by King & Engineering Co." North Anna 1 uses no Surry 1 & 2 records are still under review. Virginia Electric & Power Co. 79/04/16. 2pp.
- re IE Bulletin 79-09, "Failures of OE Type AK-2 in Safety-Related Sys." Licensee action required. Region 2, Atlanta, Office of the Director.
- re IE Bulletin 79-06A, Revision 1, "Review of Errors & Sys Misalignments Identified During TMI Incident." Region 2, Atlanta, Office of the Director.
- receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-338/79-03. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/04/18. 1p.
- ponds to NRC 790320 ltr re violation noted in IE Insp Rept 50-338/79-03. Corrective actions: health physics technician training w/inadequate experience used in responsible position. JENKINS, G. R. Region 2, Atlanta, Office of the Director. GIBSON, A. F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/19. 3pp.
- ponds to IE Bulletin 79-07 re seismic analysis of safety-related piping. No computer codes identified using methods described. SPENCER, W. C. Virginia Electric & Power Co. 79/04/24. 10pp.
- 7905240181 Responds to IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Review committee was established & detailed review of TMI incident has been completed. STALLINGS, C. M. Virginia Electric & Power Co. 79/04/26. 9pp.
- 7905290119 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16. SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/05/01. 1p.
- 7905290125 Responds to NRC 790316 ltr re violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16. Corrective actions: applicable emergency plan implementing procedures put into action. STALLINGS, C. M. Virginia Electric & Power Co. 79/04/10. 3pp.
- 7905290130 Forwards IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302 & notice of violation. SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16. 2pp.
- 7905290138 Notice of violation from insp on 790228-0302. * Region 2, Atlanta, Office of the Director. 79/03/16. 1p.
- 7905290142 IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302. Noncompliance noted: release of radioactivity to unrestricted area. ZAVADOSKI, R. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16. 5pp.
- 7905300734 Ack receipt of IE Insp Rept 50-338/79-13 on 790305-15. No proprietary info. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/01. 1p.
- 7905300023 Forwards IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted. KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/05/02. 2pp.
- 7905300026 IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted. Major areas inspected: security plan, protected area barriers, vital area barriers & access controls. Details withheld (ref 10CFR.790). HENNESSEY, R. J. Region 2, Atlanta, Office of the Director. TOBIN, W. J. Region 2, Atlanta, Safeguards Branch. 79/05/02. 1p.
- 7905240481 Confirms 790426 response to IE Bulletin 79-06A re actions taken on Unit 1. All commitments for Unit 1 will apply to Unit 2. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/03. 1p.
- 7905300706 Forwards response to IE Bulletin 79-04. Velan swing check valves of three & six inches installed in chemical vol 1 & control & safety injection sys. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/03. 4pp.
- 7905210275 Responds to IE Bulletin 79-06A, Revision 1. Provides requested info on design changes re containment sump pump trip valve actuation & safety injection logic. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17. 2pp.
- 7905290032 Responds to IE Bulletin 79-09. OE Type AK-2 circuit breakers not in use or planned for use. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/23. 1p.
- 7905300018 Responds to IE Bulletin 79-10. Forwards requalification training program statistics. STALLINGS, C. M. Virginia Electric & Power Co. 79/05/24. 5pp.

DOCKETED ITEMS

157

R. Periodic operating reports & related correspondence

7905190191 Forwards monthly operating rept for Apr 1979.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/19. 1p.

--7905190193 Monthly operating rept for Apr 1979.
MADISON, W.R. Virginia Electric & Power Co. 79/05/08. 4pp.

S. Reportable occurrences, LERs & related correspondence

7905110203 Board notification: Seabrook refueling water storage tank design deficiency.
SCINTO, J. Hearings Division. 79/03/29. 30pp.

7905140401 Responds to 790411 notification of defect in computer program allowing vital area access by unauthorized personnel. Security personnel deployed to prevent recurrence.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/12. 2pp.

7905230631 Forwards addl info re significant potential safety hazard reported on 790421. Software program failure caused degraded mode, allowing unrestricted access to any cardholder. Vital entrances guarded while sys restored.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/23. 2pp.

7905020245 Forwards LER 79-047/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/26. 1p.

--7905020248 LER 79-047/01T-0 on 790412: during reanalysis of regenerative heat exchanger, nozzle loading by vendor discovered loads exceed vendor umbrella loading, caused by miscalculation of nozzle loading during initial analysis.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/04/26. 2pp.

7905020474 Forwards LER 79-043/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/26. 1p.

--7905020484 LER 79-043/01T-0 on 790411: manufacturer determined generic problem exists w/ lower radial bearings of recirculation spray sys motors. Bearing failure could result. Installed bearings tested.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/04/24. 3pp.

7905020391 Forwards LERs 79-029/03L-0 & 79-042/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/04/27. 1p.

--7905020396 LER 79-029/03L-0 on 790330: component cooling was lost to reactor coolant pump during steady state operation at 97% power. Caused by burned out air solenoid coil. Coil replaced.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/04/24. 2pp.

--7905020403 LER 79-042/03L-0 on 790330: auxiliary feedwater pump 1-FW-P-2 turbine governor/trip valve tripped closed at 40% power. Caused by overspeed trip signal from auxiliary feedwater pump turbine. Further testing performed.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/04/24. 2pp.

7905040626 Significant deficiency rept on 790425. Computer program would not correctly operate sys, allowing unauthorized person access to vital area. Computer program currently being revised.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/01. 2pp.

7905070530 Forwards LER 79-052/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/03. 1p.

--7905070533 LER 79-052/01T-0 on 790419: util informed by S&W of potential problem w/ seismic pipe stress analysis on safety injection piping. Caused by error in computer program input for design of pipe supports. Program corrected & mods made.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/02. 2pp.

7905070656 Forwards LERs 79-045/03L-0 & 79-046/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/03. 1p.

--7905070659 LER 79-045/03L-0 on 790404: level transmitter found out of calibr. Caused by instrument drift. Transmitter recalibr.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/02. 3pp.

--7905070662 LER 79-046/03L-0 on 790408: during cold shutdown, changing pumps 1A & 1B were tagged out w/o racking in alternate feeder breaker for pump 1C. Caused by personnel error. Pump 1C alternate feeder breaker racked in.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/02. 2pp.

7905080444 Forwards LERs 79-056/01T-0 & 79-057/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/04. 1p.

--7905080447 LER 79-056/01T-0 on 790421: 12 expansion joints on svc water side of component cooling heat exchangers were deflected greater than alignment allowances. Caused by failure to install correct number of tie-rods on expansion joints.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/04. 2pp.

--7905080449 LER 79-057/01T-0 on 790424: transfer bus & feeder cables not capable of continually carrying full load current for certain conditions. Caused by improper sizing of equipment. Final solution being analyzed.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/04. 3pp.

7905110142 Forwards LERs 79-034/03L-0 & 79-051/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/07. 1p.

--7905110147 LER 79-034/03L-0 on 790410: snubber 1-RC-HSS-85 had empty reservoir & declared inoperable. Caused by improperly seated O ring resulting in leak. Snubber replaced.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/04. 1p.

--7905110152 LER 79-051/03L-0 on 790416: RHR isolation valve MOV-1701 failed to close automatically in response to trip signal. Caused by misaligned limit switch contact in valve "close" circuitry. Contact realigned & valve retested satisfactorily.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/04. 2pp.

7905160432 Forwards LERs 79-048/03L-0, 79-049/03L-0, 79-050/03L-0 & 79-055/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/11. 1p.

--7905160437 LER 79-048/03L-0 on 790412: foreign substance found on valve seat & valve disc during repair on MOV-RS-100B. Caused by substance being left on seat by repair crew.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/11. 3pp.

--7905160444 LER 79-049/03L-0 on 790412: recalibr of steam generator 1B revealed nonconservative drift. Caused by instrument drift. Recalibr for level channel corrected problem.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/11. 2pp.

--7905160454 LER 79-050/03L-0 on 790412: recalibr on containment pressure channel P-LM-100A revealed nonconservative instrument drift. Caused by excessive drift of power supply in instrument.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/11. 2pCp./.

--7905160458 LER 79-055/03L-0 on 790401: during Mode 3 operation, three rod position indicators read high while rods were actually at 0 steps. Caused by electrical drift in indicator circuitry. Recalibr solved problem.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/11. 2pp.

7905210258 Forwards LER 79-062/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/17. 1p.

--7905210260 LER 79-062/01T-0 on 790503: temporary iron corner braces discovered on exhaust ducting of diesel generator cooling fans. Caused by braces left in place after ducting fabrication. Braces removed.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/17. 2pp.

7905220287 Forwards LER 79-053/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/18. 1p.

--7905220296 LER 79-053/03L-0 on 790419: while performing penetration leak testing, 20 valves discovered to have leakage exceeding allowable limits. Caused by deterioration of valve seats. Valves reworked.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/18. 2pp.

7905230060 Forwards LER 79-065/01T-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/21. 1p.

--7905230071 LER 79-065/01T-0 on 790507: informed by A/E that solenoid valves in sample sys did not meet proper environ qualifications. Caused by use of valves which were not environmentally qualified.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/21. 2pp.

7905300401 Forwards LERs 79-061/03L-0, 79-072/03L-0 & 79-058/03L-0.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/25. 1p.

--7905300404 LER 79-061/03L-0 on 790430: temp indicator TI-RS-100A on casing cooling tank read out of specs at greater than 50 F. Caused by slipping belt on mechanical refrigerator unit.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/28. 2pp.

DOCKETED ITEMS

--7905300408 LER 79-072/03L-O on 790514: main steam trip valve TV-MS-111B would not fully shut. Caused by deteriorated internal gasket. Gasket replaced.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/28. 2pp.

--7905300412 LER 79-058/03L-O on 790430: safety injection valve MOV-1865B failed to open. Caused by dried packing around valve stem. Valve manually opened & broken free from closed position.
CARTWRIGHT, W.R. Virginia Electric & Power Co. 79/05/28. 2pp.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905290296 Requests NRC reconsider its 3-month moratorium on issuance of new OL because of large addl costs of replacement power.
RAGONE, S. Virginia Electric & Power Co. 79/05/22. 2pp.

7905070087 Forwards EIA re expansion of spent fuel storage pool.
REGAN, W.H. Environmental Projects Branch 2. 79/04/06. 1p.

--7905070090 EIA re proposed increase in storage capacity of spent fuel pool.
* Environmental Projects Branch 2. 79/04/02. 32pp.

7905040126 Responds to AW Dromerick request re elevation marker readings located on svc water piping at svc water pumphouse.
BROWN, S.C. Virginia Electric & Power Co. 79/05/01. 1p.

7905240407 Submits 790903 elevations of three settlement markers at svc water pumphouse.
BROWN, S.C. Virginia Electric & Power Co. 79/05/01. 1p.

7905100317 Forwards drawings of stainless steel pressure-balanced expansion joints for svc water piping at svc water pumphouse, in response to AW Dromerick request. Oversized drawings encl.
BROWN, S.C. Virginia Electric & Power Co. 79/05/03. 1p.

7905080428 Notifies of plans to test Unit 2 auxiliary svc water pump 2-sw-p-4 on monthly bases, as outlined in inservice testing program submitted on 790131. Will test 1-sw-p-4 before OL is issued for Unit 2. Piping mod presently unnecessary.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/04. 1p.

7905080443 Supplements 790308 rept "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation." Spent fuel pool temp will exceed 110 F FSAR limit. Lists methods to meet limits. Fuel rack license application & FSAR will be amended.
BROWN, S.C. Virginia Electric & Power Co. 79/05/04. 1p.

7905190062 Forwards fee for issuance of Amend 10 to License NPF-4.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/07. 1p.

7905150270 Forwards replacement pages to 780501 application to amend License NPF-4 to expand spent fuel storage capacity.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/11. 10pp.

7905210176 Forwards suppl to proposed Tech Spec Change 12 re increasing amount of allowable settlement for svc water pumphouse.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/17. 23pp.

7905230536 Suppl to proposed Tech Spec Change 12, "Settlement of Class I Structures," increasing amount of allowable settlement for svc waterpump house. Forwards revised Tech Spec, marked-up original & discussion of change.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/17. 23pp.

7905230022 Forwards response to NRC 790503 evaluation & request for addl info re "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation."
BROWN, S.C. Virginia Electric & Power Co. 79/05/18. 8pp.

7905290375 Responds to AW Dromerick 790503 questions re containment depressurization, net positive suction head analyses & effects of increased calculated svc water temps on design of charging pump coolers.
BROWN, S.C. Virginia Electric & Power Co. 79/05/23. 14pp.

7905080441 Forwards corrections to Table A.5.1 & other matl in 790410 ltr from CM Stallings re startup physics testing program, description of input error in original computer code calculation & steps taken to preclude recurrence.
STALLINGS, C.M. Virginia Electric & Power Co. 79/05/02. 20pp.

G. Adjudicatory correspondence

7905030262 Petition for formal intervenor status on turbine missile issue. If denied, requests permission to present evidence & cross-examine as amicus curiae. Certificate of Svc encl.
WEISS, E.R. Sheldon, Harmon & Roisman. 79/03/14. 9pp.

7905030207 Agreement via stipulation of contentions, including withdrawal of previous contentions. Notice of appearance of RJ Goddard on behalf of NRC & Certificate of Svc encl.
DOUGHERTY, J.B. Potomac Alliance. GOLDBERG, S.C. Regulations Division. CHRISTMAN, J. Virginia Electric & Power Co. 79/03/23. 10pp.

--7905030209 Agreement via stipulation of contentions, including withdrawal of previous contentions.
KRODT, I. Citizens Energy Forum. GOLDBERG, S.C. Branch 2. CHRISTMAN, J. Virginia Electric & Power Co. 79/03/23. 7pp.

7905030258 Answer by util in opposition to UCS 790314 petition to intervene. Claims untimeliness; intervention during appellate stage & lack of standing. Certificate of Svc encl.
RINACA, J.M. Hunton & Williams. 79/03/29. 22pp.

7905010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
SCINTO, J.F. Hearings Division. 79/04/02. 31pp.

--7905010156 Board notification: staff assessment re nonsafety-grade equipment to mitigate transients.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/03/29. 2pp.

--7905010198 Board notification: recent issue on nonsafety-grade equipment to mitigate transients. More info is required.
TEDESCO, R.L. Assistant Director for Reactor Safety. 79/03/16. 3pp.

7905230668 Notifies that recent info may affect licensing of high density spent fuel storage racks. Svc water temp & component cooling water temp will exceed values in FSAR.
CHRISTMAN, J.N. Hunton & Williams. 79/04/04. 2pp.

7905240135 ALAB-536, denying UCS 790314 petition to intervene or participate in hearing as amicus curiae.
DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/05. 8pp.

7905240487 Directs parties to submit responsive prepared testimony re pumphouse settlement & turbine missile issues before 790531. Evidentiary hearing to be held during week of 790618. Lists procedures for informal discovery process.
DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/09. 4pp.

7905100137 Forwards EIA re proposed increase of storage capacity of spent fuel pool.
GOLDBERG, S.C. Branch 2. 79/04/10. 1p.

--7905100140 EIA supporting proposed increase in storage capacity of spent fuel pool.
* Office of Nuclear Reactor Regulation. 79/04/02. 32pp.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Svc encl.
SCINTO, J.F. Hearings Division. 79/04/11. 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co/PSE&G Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl.
KEPFORD, C.R. Citizens for Safe Environment. 79/04/11. 8pp.

7905241006 Corrects info submitted on 790334 re deficiency in Westinghouse ECCS evaluation model. Model reanalysis indicates North Anna 1 & 2 still in compliance w/10CFR50.46.
SWANSON, D.T. Branch 1. 79/04/13. 1p.

7905240255 Requests extension of time to 790504 in which to prepare testimony. Granted by ASLAB on 790420. Certificate of Svc encl.
SWANSON, D.T. Branch 1. 79/04/20. 5pp.

7905030330 Affidavit of Svc for applicant's Amend 66 in proceeding NEIL, R.M. Virginia, State of. 79/04/25. 2pp.

DOCKETED ITEMS

159

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
BUFLO, M. E. Atomic Safety and Licensing Appeal Panel. 79/04/25. 12pp

7905240814 Forwards second copy of util's testimony re probability of generating turbine missiles & turbine overspeed protection sys. w/o encl.
CHRISTMAN, J. N. Hunton & Williams. 79/04/30. 2pp.

7905240510 Extends time for NRC review of ALAB-536 until 790511.
CHILK, S. J. Office of the Secretary of the Commission. 79/05/04. 1p.

7905240571 Following 790626 prehearing conference, hearing shall commence re application by util for OL amend to increase spent fuel pool storage capacity, per 790423 order granting intervention.
DEALE, V. B. Atomic Safety and Licensing Board Panel. 79/05/04. 5pp.

7905250233 Request to amend petition to intervene by adding contention re svc water cooling sys. Notice of appearance of GM Gilman on behalf of intervenors. Certificate of Svc & supporting documentation encl.
DOUGHERTY, J. B., GILMAN, G. Potomac Alliance. 79/05/09. 11pp.

I. Financial information

7905020459 Discusses SEC 790321 ltr & registration statement. Util will file another statement which NRC will be able to review.
DROMERICK, A. W. Light Water Reactors Branch 3. 79/04/09. 1p.

--7905020466 Forwards SEC 790316 registration statement filed by util. Requests comments by 790330; util wishes statement to become effective by 790402.
MORIN, H. F. Securities & Exchange Commission. 79/03/21. 60pp.

J. Insurance & indemnity information

7905110107 Amend to Endorsement 51 to NELIA Policy NF-186. Constitutes Endorsement 34.
* Nuclear Energy Liability Insurance Association. 79/04/27. 1p.

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905110090 Endorsements 16, 30, 36 & 47 to NELIA Policy NF-186.
BARDES, C. R. Nuclear Energy Liability Insurance Association. 79/05/01. 1p.

7905140523 Forwards Amend 5 to Indemnity Agreement B-80 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905240342 Forwards executed Amend 5 to Indemnity Agreement B-80.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/21. 2pp.

7905300334 Forwards Endorsements 17, 20 & 21 to NELIA Policy NF-240.
KELLEY, P. J. Johnson & Higgins Insurance. 79/05/23. 4pp.

K. Inspection reports, IE Bulletins & correspondence

7905010235 Forwards IE Insp Repts 50-338-79-01 & 50-339-79-01 on 790102-0202 & notice of violation.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/16. 2pp.

--7905010264 Notice of violation from insp on 790102-0202.
* Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14. 1p.

--7905010275 IE Insp Repts 50-338-79-01 & 50-339-79-01 on 790102-0202. Noncompliance noted: failure to document approval of change to test procedure.
KIDDS, N. B., CANTRELL, F. S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14. 19pp.

7905230129 Forwards IE Insp Rept 50-339-79-12 on 790215-16. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/20. 2pp.

--7905230169 IE Insp Rept 50-339-79-12 on 790215-16. No noncompliance noted. Major areas inspected: 10CFR50.55(e) & 10CFR21 items.
MCFARLAND, C. R. Region 2, Atlanta, Office of the Director.
HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/19. 4pp.

7905090051 Forwards IE Insp Rept 50-339-79-11 on 790129-0202. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/21. 2pp.

--7905090056 IE Insp Rept 50-339-79-11 on 790129-0202. No noncompliance noted. Major areas inspected: procedures & activities necessary to implement operational GA program.
JENKINS, H. D., McDONALD, J. A. Region 2, Atlanta, Office of the Director.
KELLOGG, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/19. 30pp.

7905010224 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905020458 Forwards IE Insp Rept 50-339-79-13 on 790212-15. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.

--7905020471 IE Insp Rept 50-339-79-13 on 790212-15. No noncompliance noted. Major areas inspected: comparison of as-built plant to FSAR description.
SKOLDS, J. L. Region 2, Atlanta, Office of the Director.
CANTRELL, F. S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/12. 3pp.

7905090129 Forwards IE Insp Repts 50-338-79-04 & 50-339-79-04 on 790122-25 & notice of violation.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.

--7905090132 Notice of violation from insp on 790122-25.
* Region 2, Atlanta, Office of the Director. 79/03/13. 1p.

--7905090135 IE Insp Repts 50-338-79-04 & 50-339-79-04 on 790122-25. Noncompliance noted: failure to identify Tech Spec-listed snubbers prior to removal for testing.
DYER, J. A., JOHNSON, A. H. Region 2, Atlanta, Office of the Director.
MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/13. 8pp.

7905030319 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905010123 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.

7905010369 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.

7905240530 Forwards IE Insp Rept 50-339-79-18 on 790314-0316. No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/05. 2pp.

--7905240534 IE Insp Rept 50-339-79-18 on 790314-16. No noncompliance noted. Major areas inspected: startup procedures reviewed & pre-operational test witnessed.
BURNETT, P. T., DYER, J. A. Region 2, Atlanta, Office of the Director.
MARTIN, R. D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/04. 5pp.

7905020133 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/11. 1p.

7905040254 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

DOCKETED ITEMS

- 7905040271 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 1p.
- 7905040448 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 1p.
- 7905010317 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/16 2pp.
- 7905030191 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/17 2pp.
- 7905020502 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/18 2pp.
- 7905240783 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." No S&W computer codes were identified which used methods described in bulletin.
SPENCER, W. C. Virginia Electric & Power Co. 79/04/25 2pp.
- 7905290119 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/05/01 1p.
- 7905290125 Responds to NRC 790316 ltr re violations noted in IE Insp Repts 50-338/79-11 & 50-339/79-16. Corrective actions: applicable emergency plan implementing procedures put into action.
STALLINGS, C. M. Virginia Electric & Power Co. 79/04/10 3pp.
- 7905290130 Forwards IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302 & notice of violation.
SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16 2pp.
- 7905290138 Notice of violation from insp on 790228-0302.
* Region 2, Atlanta, Office of the Director. 79/03/16 1p.
- 7905290142 IE Insp Repts 50-338/79-11 & 50-339/79-16 on 790228-0302. Noncompliance noted: release of radioactivity to unrestricted area.
ZAVADOSKI, R. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 79/03/16 5pp.
- 7905300023 Forwards IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted.
KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 79/05/02 2pp.
- 7905300026 IE Insp Repts 50-338/79-12 & 50-339/79-19 on 790416-20. No noncompliance noted. Major areas inspected: security plan, protected area barriers, vital area barriers & access controls. Details withheld (ref 10CFR 7901).
HENNESSEY, R. J. Region 2, Atlanta, Office of the Director.
TOBIN, W. J. Region 2, Atlanta, Safeguards Branch. 79/05/02 1p.
- 7905240481 Confirms 790426 response to IE Bulletin 79-06A re actions taken on Unit 1. All commitments for Unit 1 will apply to Unit 2.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/03 1p.
- 7905210275 Responds to IE Bulletin 79-06A, Revision 1. Provides requested info on design changes containment sump pump trip valve actuation & safety injection logic.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/17 2pp.
- 7905290032 Responds to IE Bulletin 79-09, GE Type AK-2 circuit breakers not in use or planned for use.
STALLINGS, C. M. Virginia Electric & Power Co. 79/05/23 1p.
- S. Reportable occurrences, LERs & related correspondence**
- 7905100070 Provides info re overweight check valves used in safety injection sys. Error could result in pipes being overstressed during design basis test. Pipes being re-evaluated.
BROWN, S. C. Virginia Electric & Power Co. 79/03/26 2pp.
- 7905100076 Submits info re valve limit switch actuating arms flexing each time valve operates. Actuating arms being reworked.
BROWN, S. C. Virginia Electric & Power Co. 79/03/26 2pp.
- 7905100055 Submits info re cracked splinter plate in reactor coolant sys. Weldment samples of splinter plate/weld metal/pipe boss transition being analyzed.
BROWN, S. C. Virginia Electric & Power Co. 79/03/27 3pp.
- 7905110203 Board notification: Seabrook refueling water storage tank design deficiency.
SCINTO, J. Hearings Division. 79/03/29 30pp.
- 7905230235 Submits addl info to 790329 rept re failure of reversing motor starter supplied by Klockner-Moeller Corp. Discusses corrective actions re checkout procedure for discovering failures prior to startup.
* Virginia Electric & Power Co. 79/04/03 2pp.
- 7905290529 Submits final rept on valve malfunction. All actuating arms on valve limit switch replaced & tested satisfactorily. New arms will provide reliable valve position information.
BROWN, S. C. Virginia Electric & Power Co. 79/04/19 2pp.
- 7905070404 Rubber expansion joints in svc water piping found to be beyond misalignment tolerance acceptable to manufacturer. Svc water piping realigned & all expansion joints replaced.
BROWN, S. C. Virginia Electric & Power Co. 79/05/02 2pp.
- 7905080511 Submits final rept re deficiency in analysis of DNBR following single rod drop. Proposes to assure that all dropped rods will result in reactor trip via negative rate trip function.
BROWN, S. C. Virginia Electric & Power Co. 79/05/03 1p.
- 7905080434 Follows up 790406 & 11 repts re failure of inside recirculation spray pump motor. Mods & tests in progress.
BROWN, S. C. Virginia Electric & Power Co. 79/05/04 1p.
- 7905080452 Final rept re cracked flow splitter plate on reactor coolant loop piping. Cracks are characteristic of high cycle fatigue, which was probably caused by fluid flow-induced resonance in splitter plates.
BROWN, S. C. Virginia Electric & Power Co. 79/05/04 2pp.
- 7905090297 Notifies of completion of evaluation of cracks in loops C & A flow splitter plates. Cracks are characteristic of high cycle fatigue.
BROWN, S. C. Virginia Electric & Power Co. 79/05/04 2pp.
- 7905110214 Submits final 10CFR 50.55(e) rept re overweight check valves in safety injection sys. New loads for nozzles, where pipes affected by overweight valves connect to reactor coolant loop piping, are acceptable.
BROWN, S. C. Virginia Electric & Power Co. 79/05/08 1p.
- 7905160418 Discusses pipe stress analysis deficiency for pipes passing through main steam valve house (MSVH). Analyses completed using appropriate MSVH seismic structural response. Revised nozzle loads on quench spray pumps sent to vendor.
BROWN, S. C. Virginia Electric & Power Co. 79/05/10 2pp.
- 7905220344 Provides final rept re potential deficiency in regenerative heat exchanger support. Installation of bolt-on mod complete.
BROWN, S. C. Virginia Electric & Power Co. 79/05/17 1p.
- 7905290404 Forwards revised one-line diagram showing changes to alleviate potential overload situation of electrical sys which supply offsite power for startup & emergency loads.
BROWN, S. C. Virginia Electric & Power Co. 79/05/23 3pp.
- 7905300017 Reportable occurrence on 790521: weight of three 12-inch motor operated valves greater than that used by S&W in their original pipe stress analysis. Reanalysis of pipe stresses & support loads underway.
BROWN, S. C. Virginia Electric & Power Co. 79/05/24 2pp.
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2**
- A. Application/construction stage documents & correspondence**
- 7905150630 Notifies of cancellation of 790424 meeting w/util in Bethesda, MD to discuss OL review.
KINTNER, L. L. Light Water Reactors Branch 1. 79/03/08 2pp.
- 7905140251 Notifies of pending two-phase environ impact study at cooling water intake structure. Phase I will begin when plant begins drawing up water from Lake Erie. Phase II will commence when commercial operation begins.
TURNER, W. G. Michigan, State of. 79/05/03 2pp.

DOCKETED ITEMS

161

7905310083 Requests addl info to complete review of FSAR. Requests FSAR be amended by 790615 to comply w/requirements
STOLZ, J. F. Light Water Reactors Branch 1 79/05/07. 4pp.

F. Security, medical, emergency & fire protection plans

7905290528 Forwards request for addl info re security plan as result of review of OL application Request withheld (ref 10CFR 790)
STOLZ, J. F. Light Water Reactors Branch 1 79/04/13 2pp.

G. Adjudicatory correspondence

7905300025 Applicants' interrogatories submitted to Citizens for Employment & Energy Certificate of Svc encl
VOIGHT, H. H. LeBoeuf, Lamb, Leiby & MacRae 79/03/27 9pp

H. General correspondence

7905160443 Forwards Certificate of Svc indicating avc of Amend 22 to amended & substituted application for licenses to appropriate parties
METERS, B. R. Detroit Edison Co. 79/05/04 3pp

I. Financial information

7905040007 Forwards 1978 Annual Repts of each of three co-owners Encl available in Central Files only
THOMAS, E. B. 79/04/24 1p

G. Inspection reports, II Bulletins & correspondence

7905010253 Forwards II Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/23 1p

7905230302 Forwards II Insp Rept 50 341/79 06 on 790306-09 No noncompliance noted
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/21 2pp

--7905230308 II Insp Rept 50 341/79 06 on 790306-09 No noncompliance noted Major areas inspected QA/QC program, preservice insp work activities & nondestructive examination repts
WARD, K. D., DANIELSON, D. H. Region 3, Chicago, Office of the Director 79/03/23 2pp

7905040030 Forwards II Info Notice 79-07, "Rupture of Radwaste Tanks"
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/26 1p

7905150410 Forwards II Insp Rept 50 341/79 05 on 790306-09 & notice of violation
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/27 2pp

--7905150413 Notice of violation from insp on 790506-09
* Region 3, Chicago, Office of the Director 79/03/27 2pp

--7905150419 IE Insp Rept 50 341/79 05 on 790306-09 Noncompliance noted density test was not performed & procedures re nonconforming backfill were not followed
HUGHES, J., BARRETT, P. A. Region 3, Chicago, Office of the Director HAYES, D. W. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/22 11pp

7905030029 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/11 1p

7905010586 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040387 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040460 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" Licensee action required
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040556 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905010415 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/16. 1p.

7905030224 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/17. 1p.

7905080492 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/21. 1p.

7905240898 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/05/02. 1p

G Reportable occurrences, LERs & related correspondence

7905080024 Ack receipt of 790322 interim report, per 10CFR50.55(e), re handling damage to core spray pump motor.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/04. 1p.

7905090351 Forwards final status rept EF2-46,047 of 790419 deficiency rept on "Torax Ring Beam Weld Indications."
FAHRNER, W. J. Detroit Edison Co. 79/05/01. 2pp.

--7905090355 Deficiency rept: defects in toe of ring beam attachment weld. Cracks caused hydrogen cracking, characterized by intergranular fracture of coarse grained HAZ. Corrected by grinding & new welding procedures.
* Detroit Edison Co. 79/04/19. 3pp.

DOCKET 50-344 TROJAN NUCLEAR PLANT, UNIT 1

G. Adjudicatory correspondence

7905250260 Submits contentions for Phase 2 of mod proceedings. Certificate of Svc & notice of change of address encl.
BELL, N. Affiliation Unknown. 79/02/26. 7pp.

7905250279 Contentions of E Rosolie & Coalition for Safe Power re seismic capacity, cost/benefit analysis & insp procedures. Certificate of Svc encl.
ROSOLIE, E. Coalition for Safe Power. 79/02/26. 5pp.

7905030158 Response to 790130 contentions of N Bell, Consolidated Intervenor, E Rosolie & Coalition for Safe Power. Notice of appearance of AV Carr on behalf of Portland General Electric Co & Certificate of Svc encl.
JOHNSON, R. W. Portland General Electric Co. AXELRAD, M., CARR, A. V. Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/16. 59pp.

7905250273 Responds to 790305 interrogatories re adequacy of plant staff review, radioactive isotopes, core meltdown & QA programs. Certificate of Svc encl.
ROSOLIE, E. Coalition for Safe Power. 79/03/19. 5pp.

7905150722 Motion for order to compel E Rosolie & Coalition for Safe Power to respond fully to util's 790305 interrogatories.
JOHNSON, R. W. Portland General Electric Co. AXELRAD, M., CARR, A. V. Lowenstein, Newman, Reis, Axelrad & Toll. 79/03/23. 27pp.

7905100067 Affirms ASLB 781221 denial of appeal by Coalition for Safe Power & Consolidated Intervenor re interim operation issue.
DUFLD, M. E. Atomic Safety and Licensing Appeal Panel. 79/03/27. 7pp.

7905100208 Position on contentions of Consolidated Intervenor & E Rosolie on behalf of Coalition for Safe Power, dtd 790226. Certificate of Svc encl.
GRAY, J. R. Branch 1. 79/03/27. 46pp.

7905070147 Informs of corrected address for Columbia Environ Council.
GRAY, J. R. Branch 1. 79/04/02. 1p.

DOCKETED ITEMS

7905250030 Offers no objection to intervenor State of OR motion for extension of time in which to file petition for review of 790321 ASLAB decision, ALAB-531.
GRAY, J.R. Branch 1. 79/04/05. 1p.

7905140033 Notifies parties that time for filing petitions for ALAB-531 review is extended until 790417. Time for NRC review is extended until 790430.
CHILK, S.J. Office of the Secretary of the Commission. 79/04/06. 1p.

7905250148 Requests answers to Contentions 1 & 18 of NRC 790309 interrogatories by 790416 & identification of any addl security concerns.
GRAY, J.R. Branch 1. 79/04/09. 1p.

7905150811 Forwards info re PWRs. Discusses NUREG-0409, "Iodine Behavior in PWR Sys Following Postulated Steam Generator Tube Rupture Accident."
GRAY, J.R. Branch 1. 79/04/10. 7pp.

7905250357 Petitions for review of 790321 ALAB-531 decision by ASLAB. Commission must ack strong possibility that each commercial reactor may become a de facto waste storage facility.
GARRETT, S.M. Coalition for Safe Power. 79/04/10. 7pp.

7905230550 Supplemental response to 790305 interrogatories from util. Certificate of Svc encl.
ROSOLIE, E. Coalition for Safe Power. 79/04/13. 7pp.

7905230546 Response to 790309 interrogatories from NRC. Certificate of Svc encl.
ROSOLIE, E. Coalition for Safe Power. 79/04/17. 6pp.

7905300104 Licensees' response to 790402 request of PA Public Util Commission for hearing & petition to intervene re 790313 show cause order. Urges NRC to hold ruling in abeyance.
CHURCHILL, B.W. Shaw, Pittman, Potts, & Trowbridge. 79/04/17. 4pp.

7905290042 Forwards revised pp 1 & 3 of util's answer opposing review of intervenor Garrett's 790410 petition.
HASTINGS, W. Portland General Electric Co. 79/04/23. 3pp.

7905230661 Orders extension until 790503 to review ALAB-534, dtd 790324.
CHILK, S.J. Office of the Secretary of the Commission. 79/04/24. 1p.

7905240948 Forwards list of requests for design charges re rept on design mods for control bldg. Certificate of Svc encl.
JOHNSON, R.W. Portland General Electric Co. 79/04/24. 6pp.

7905240224 Opposes 790411 motion by SM Garrett & Coalition for Safe Power for NRC review of ASLAB 790321 order re storage pool mod. Certificate of Svc encl.
GRAY, J.R. Branch 1. 79/04/26. 12pp.

mits info re work & workers involved in control bldg used in 790420 response to intervenors in proceeding. Requests analysis.
Portland General Electric Co. 79/05/02. 1p.

nual Financial Rept 1978" from Portland General ter & Electric Board & Pacific Power & General Electric Co. 79/05/17. 1p.

1978."
79/03/31. 36pp.

in Eugene Water & Electric

SEC.
35pp.

503 extension of ltr of
&
79/05/25. 3pp.

--7905300429 Discusses financial obligations under agreement w/Eugene Water & Electric Board re retrospective premiums under Price-Anderson Act.
HITTLE, L.G. Energy, Dept. of. 79/05/21. 2pp.

J. Insurance & indemnity information

7905020388 Forwards Endorsement 30 to MAELU Policy MF-86.
WILSON, F.R. Portland General Electric Co. 79/04/23. 2p.

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905160187 Forwards Amend 4 to Indemnity Agreement B-78, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

7905220078 Forwards Endorsements 37 & 38 to ANI Policy NF-225, increasing limit of liability & establishing premium for increase, respectively.
WILSON, R.F. Portland General Electric Co. 79/05/16. 3pp.

P. Operating license stage documents & correspondence

7905020478 Forwards response to NRC 790126 comments on "Containment Structure Tendon Surveillance - One Year Surveillance," prepared by Bechtel Corp. Comments have been applied to third-year program now underway.
GOODWIN, C. Portland General Electric Co. 79/04/25. 38pp.

7905030361 Responds to DOE 790411 ltr. Unable to provide supplemental info by 790430. Response dependent upon preparation & approval of Offsite Dose Calculation Manual. Response will be ready by 790531.
GOODWIN, C. Portland General Electric Co. 79/04/27. 1p.

7905080431 Submits info re facility design, in response to J Holman 790418 request.
WITHERS, D.B. Portland General Electric Co. 79/04/30. 4pp.

7905040520 Forwards License Change Application 52. Certificate of Svc & \$4,000 Class III encl.
BROEHL, D.J. Portland General Electric Co. 79/05/01. 2pp.

--7905040523 License Change Application 52 to License NPF-1.W/Tech Spec changes.
Portland General Electric Co. 79/05/01. 13pp.

7905150387 Forwards responses to 790508 & 790510 requests for info re pressurizer code safety valves, main feedwater sys & containment isolation valve functionality. Info needed for meeting on 790512.
BROEHL, D.J. Portland General Electric Co. 79/05/11. 4pp.

7905230492 Notifies that Offsite Dose Calculation Manual & process control program require further review & will be submitted by 790630, instead of 790515.
GOODWIN, C. Portland General Electric Co. 79/05/15. 1p.

7905230407 Forwards response to NRC 790509 request for info re feedwater sys.
GOODWIN, C. Portland General Electric Co. 79/05/18. 4pp.

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PISOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970.
PORTER, F.L. EDS Nuclear, Inc. 79/05/21. 9pp.

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program. OE has no record of reanalysis for Cooper piping sys.
STEPHENS, P.W. General Electric Co., Nuclear Energy Products Div. 79/01/24. 18pp.

G. Inspection reports, IE Bulletins & correspondence

7905010289 Forwards IE Info Notice 79-06, "Stress Analysis of Safety Related Piping"
ENGELKEN, R. H. Region 5, Dallas, Office of the Director. 79/03/23. 1p.

7905290078 Requests extension until 790715 for response to IE Bulletin 78-12, 78-12A & 78-12B
GOODWIN, C. Portland General Electric Co. 79/03/23. 1p.

7905040086 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/03/26. 1p.

7905040362 Forwards IE Insp Rept 50-1447/79-05 on 790226-0302 No noncompliance noted
BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/03/27. 2pp.

--7905040366 IE Insp Rept 50-1447/79-05 on 790226-0302 No noncompliance noted Major areas inspected: environ monitoring, radiation protection, spent fuel pool rack installation & followup on Part 21 rept
DAIRD, J. B., NORTON, H. Region 5, San Francisco, Office of the Director. BOOK, H. E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/03/27. 11pp.

7905010218 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Gas w/low Air Sys Used as Source of Breathing Air"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/03/28. 1p.

7905010420 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/03/30. 1p.

7905010027 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During IMI Incident" licensee action required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040477 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During IMI Incident"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040416 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During IMI Incident"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905070102 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" licensee action required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905030293 Forwards IE Bulletin 79-09, "Failures of GI Type AK-2 Circuit Breaker in Safety Related Sys" licensee action required
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/17. 1p.

7905080369 Forwards IE Bulletin 79-05B, "Nuclear Incident at TH1-Suppl"
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

7905130812 Responds to IE Bulletin 79-07 Details computer programs used in seismic stress analysis of safety related piping
GOODWIN, C. Portland General Electric Co. 79/04/23. 1p.

7905240908 Responds to IE Bulletin 79-06A re IMI-2 event Describes actions taken
GOODWIN, C. Portland General Electric Co. 79/04/24. 15pp.

R. Periodic operating reports & related correspondence

7905110167 Forwards monthly operating rept for Apr 1979
WITHERS, B. D. Portland General Electric Co. 79/05/04. 1p.

--7905110169 Monthly operating rept for Apr 1979
BAIR, G. G. Portland General Electric Co. 79/05/04. 4pp.

B. Reportable occurrences, LERs & related correspondence

7905150062 Forwards PNO-79-67L.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/06. 1p.

7905150168 Forwards PNO-79-67R.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/11. 1p.

7905040125 Forwards PNO-79-67S.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/12. 1p.

7905150142 Forwards PNO-79-67T.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/13. 1p.

7905030030 Forwards PNO-79-67U.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905020529 Forwards PNO-79-67AA.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/20. 1p.

7905040449 Forwards LER 79-002/03L-0.
WITHERS, B. D. Portland General Electric Co. 79/04/20. 3pp.

--7905040458 LER 79-002/03L-0 on 790322: automatic isolation feature of control room emergency ventilation sys on high chlorine & high radiation not verified during two 18-month periods. Caused by personnel error.
PERRY, J. C. Portland General Electric Co. 79/04/19. 1p.

7905010422 Forwards PNO-79-67AB.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

7905010445 Forwards PNO-79-67AC & AD.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/23. 1p.

7905010458 Forwards PNO-79-67AE.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/24. 1p.

7905090039 Forwards PNO-79-67AF.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/25. 1p.

7905090054 Forwards PNO-79-67AG.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/26. 1p.

7905090116 Forwards PNO-79-67AH.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/27. 1p.

7905100267 Forwards LER 79-003/01T-0.
WITHERS, B. D. Portland General Electric Co. 79/04/27. 1p.

--7905100270 LER 79-003/01T-0 on 790414: CV-2256 & CV-2276 valves failed to respond to manually initiated closing signal during periodic surveillance testing. Caused by valve packing binding stem. Packing adjusted.
PERRY, J. C. Portland General Electric Co. 79/04/27. 3pp.

7905070028 Forwards PNO-79-67AI, AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/30. 1p.

7905070010 Forwards PNO-79-67AL per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/05/01. 1p.

7905310053 Forwards PNO-79-67AM.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/05/07. 1p.

DOCKETED ITEMS

7905170238 Forwards LER 79-004/03L-0.
WITHERS, B. D. Portland General Electric Co. 79/05/10. 1p.

--7905170247 LER 79-004/03L-0 on 790411: 1-h surveillance test of emergency diesel generator not performed as required by Tech Specs. Caused by personnel error. Personnel reinstructed.
PERRY, J. C. Portland General Electric Co. 79/05/10. 3pp.

7905220289 Forwards LER 79-005/03L-0.
WITHERS, B. D. Portland General Electric Co. 79/05/14. 2pp.

--7905220293 LER 79-005/03L-0 on 790414: feedwater isolation valve failed following reactor trip. Backup valve closed properly so feedwater line was isolated. Caused by failure of hydraulic fitting.
PERRY, J. C. Portland General Electric Co. 79/05/14. 1p.

7905220311 Forwards LER 79-006/03L-0.
WITHERS, B. D. Portland General Electric Co. 79/05/15. 1p.

--7905220316 LER 79-006/03L-0 on 790415: leak discovered in auxiliary feedwater pump fuel line fitting. Caused by vibration. Fitting replaced. Fuel line design will be modified.
PERRY, J. C. Portland General Electric Co. 79/05/15. 2pp.

7905310350 RO: util cannot assure containment ventilation sys supply valves will remain leak tight following postulated LOCA while ventilating containment. Analysis shows damage to sys may result.
WITHERS, B. D. Portland General Electric Co. 79/05/21. 1p.

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

G. Adjudicatory correspondence

7905070239 Requests denial of J. Doherty's 790404 motion for postponement of 790418 prehearing conference. Combustible gas control issue was not dropped from case.
NEWMAN, J. R. Lowenstein, Neuman, Reis, Arvid & Toll. 79/04/06. 3pp.

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
GUATTROCHINI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905160231 Forwards Amend 4 to Indemnity Agreement B-79, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

7905140361 Forwards Endorsements 28 & 29 to NELIA Policy NF-236.
LLOYD, R. D. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div. 79/05/07. 3pp.

7905300418 Forwards executed Amend 4 to Indemnity Agreement B-79.
ROE, L. E. Toledo Edison Co. 79/05/25. 3pp.

P. Operating license stage documents & correspondence

7905240933 Confirms 790401 discussions. Will notify NRC prior to resuming operations. Postpones meeting scheduled for 790404.
KEPPLER, J. G. Region 3, Chicago, Office of the Director. 79/04/02. 1p.

7905240129 Ack receipt of 790116 ltr providing info re coolant sys flow data & total pressure drops. Review requires Class III fee.
DIOGS, R. M. License Fee Management Branch. 79/04/24. 1p.

7905240662 Expresses appreciation for 790305 ltr providing util views on NRC activities. Describes development of STS & radiological effluent Tech Specs.
BOYD, R. S. Division of Project Management. 79/05/01. 5pp.

--7905240671 Requests evaluation of NRC Tech Spec requirements, which util believes are often counterproductive and unnecessary.
ROE, L. E. Toledo Edison Co. 79/03/05. 3pp.

7905080416 As result of commitments contained in 790427 ltr, details addl actions to be taken prior to startup. In order to meet requirements, will initiate mod to provide control room verification of auxiliary feedwater flow to steam generator.
ROE, L. E. Toledo Edison Co. 79/05/04. 2pp.

7905090353 Forwards response to G. Vissing 790226 request for addl info re spent fuel pool capacity mod, to finalize environ assessment.
ROE, L. E. Toledo Edison Co. 79/05/04. 3pp.

7905150402 Forwards Chapters 1, 2, 8-10, 12 & 13, revised by Suppl 4 of initial startup rept. W/instructions for insertion.
GRANT, J. S. Toledo Edison Co. 79/05/09. 2pp.

--7905150405 Initial startup rept, Suppl 4, revising Chapters 1, 2, 8-10, 12 & 13. Covers testing completed 790106-0405.
* Toledo Edison Co. 79/05/09. 80pp.

7905190031 Forwards interim anticipatory reactor trip sys design (Drawing SK-E-409, Revision 1). Oversized drawing available in Central Files.
ROE, L. E. Toledo Edison Co. 79/05/11. 1p.

7905240586 In response to NRC 790424 ltr, forwards Class III amend fee.
ROE, L. E. Toledo Edison Co. 79/05/15. 1p.

7905220095 Forwards Offsite Dose Calculation Manual, to aid review of radiological ETS, submitted 790316.
ROE, L. E. Toledo Edison Co. 79/05/18. 67pp.

7905240403 Forwards addl info re auxiliary feedwater turbine dynamic brake installation, dual level setpoints for auxiliary feedwater controls & actuation signals, pressurizer level indication & water source & cross-connect requirements.
ROE, L. E. Toledo Edison Co. 79/05/19. 7pp.

7905290419 Forwards "Evaluation of Transient Behavior & Small Reactor Coolant Sys Breaks in 177 Fuel Assembly Plant, 790516," Vol 3, Revision 1.
ROE, L. E. Toledo Edison Co. 79/05/22. 1p.

--7905290422 "Evaluation of Transient Behavior & Small Reactor Coolant Sys Breaks in 177 Fuel Assembly Plant, 790516," Vol 3, Revision 1.
* Toledo Edison Co. 79/05/19. 66pp.

7905310450 Forwards info re auxiliary feedwater flow indicators, surveillance test/maint mode procedures & valve alignment requirements.
ROE, L. E. Toledo Edison Co. 79/05/22. 3pp.

7905300483 Forwards info requested at NRC 790508 meeting. Info includes overall reliability of auxiliary feedwater sys w/regard to operating history & design improvements.
ROE, L. E. Toledo Edison Co. 79/05/23. 16pp.

7905310375 Submits matrix to cross-reference station procedures w/operating procedure mods re NRC 790317 order & RN Reid 790518 ltr.
ROE, L. E. Toledo Edison Co. 79/05/23. 4pp.

G. Inspection reports, IE Bulletins & correspondence

7905100357 Notice of deviation from insp on 771116-18 & 30 & 1201-02.
* Region 3, Chicago, Reactor Operations Nuclear Support Branch. 77/12/16. 1p.

--7905100362 IE Insp Rept 50-346/77-34 on 771116-18 & 30 & 1201-02. No noncompliance noted. Major areas inspected: surveillance testing & investigation & followup associated w/loss of offsite power on 771129.
TAMBLING, T. M., KNOV, R. C. Region 3, Chicago, Office of the Director. 77/12/16. 7pp.

7905110097 Ack receipt of 771214 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-346/77-32.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/01/13. 1p.

--7905110099 Responds to NRC 771122 ltr re violation noted in IE Insp Rept 50-346/77-32. Corrective actions: Administrative Procedure AD 1823.00 revised & supervisors reinstructed re importance of filling out log sheets.
GRANT, J. S. Toledo Edison Co. 77/12/14. 2pp.

DOCKETED ITEMS

165

--7905110100 Forwards IE Insp Rept 50-346/77-32 on 770926-30, 1005-07, 18-21 & 27.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch 77/11/22 2pp

--7905110108 Notice of violation from insp on 770926-30, 1005-07, 18-21 & 27.
* Region 3, Chicago, Office of the Director 77/11/18 1p

--7905110111 IE Insp Rept 50-346/77-32 on 770926-30, 1005-07, 18-21 & 27. Noncompliance noted failure to properly implement procedure for jumper-lifted wire.
TAMBLING, I. N., HARTSHORN, L. L., KNOPF, R. C. Region 3, Chicago, Office of the Director 77/11/10 19pp

7905110089 Ack receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/77-32.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch 78/07/12 1p

--7905110091 Responds to NRC 790430 ltr re violations noted in IE Insp. Rept 50-346/77-32. Corrective actions test deficiency documented on 790417 & proper review & changes to dropped rod control test obtained on 790615.
GRANT, J. S. Toledo Edison Co. 79/07/10 1p

--7905110092 Forwards IE Insp Rept 50-346/77-32 on 771206-08 & 790306-08 & notice of violation.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/20 3pp

--7905110093 Notice of violation from insp on 771206-08 & 790306-08.
* Region 3, Chicago, Office of the Director 79/04/19 1p

--7905110094 IE Insp Rept 50-346/77-32 on 771206-08 & 790306-08. Noncompliance noted failure to perform rod drop testing at 40% power & failure to file test deficiency report.
CRESWELL, J. S. Region 3, Chicago, Office of the Director
LITTLE, W. S. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/19 12pp

7905010267 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/20 1p

7905040053 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/26 1p

7905010176 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Gas w/50% Air Gas Used as Source of Breathing Air".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/28 1p

7905010413 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/03/30 1p

7905030053 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/11 1p

7905010604 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040427 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040591 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident".
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905070174 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping". Licensee action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905240097 Responds to IE Bulletin 79-03 re defects in pipes mfg by Youngstown Welding & Engineering Co. Ultrasonic exam of containment spray sys piping revealed some defects, which are being evaluated.
GRANT, J. S. Toledo Edison Co. 79/04/16 3pp

7905250198 Forwards revision to 790411 response to IE Bulletin 79-05/ re auxiliary feedwater trains.
GRANT, J. S. Toledo Edison Co. 79/04/16 2pp.

7905030245 Forwards IE Bulletin 79-09, "Failures of OE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/17 1p.

7905080509 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl." Licensee action required.
KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/04/21 1p.

7905150113 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/79-05.
HEISHMAN, R. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/25 1p.

--7905150121 Responds to NRC 790314 ltr re violations noted in IE Insp Rept 50-346/79-05. Corrective actions: reemphasized importance of review of surveillance test data & personnel instructed on proper work method re safety-related equipment.
GRANT, J. S. Toledo Edison Co. 79/04/03 2pp.

7905100354 Forwards IE Insp Rept 50-346/77-34 on 771116-18 & 30 & 1201-02. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch 77/12/16 3pp.

R. Periodic operating reports & related correspondence

7905140233 Forwards monthly operating rept for Apr 1979.
MURRAY, T. D. Toledo Edison Co. 79/05/08 1p.

--7905140235 Monthly operating rept for Apr 1979.
CABA, E. C. Toledo Edison Co. 79/05/08 6pp.

S. Reportable occurrences, LERs & related correspondence

7905100375 PNO-77-171 as of 770926 no radioactive releases occurred at Davis-Besse 1, as result of loss of coolant pressure due to failure of pressurizer power operated relief valve.
KLINGER, D., NOLAN, F., SNIJEK, J. H. Office of Inspection & Enforcement 77/09/26 1p.

--7905100378 Reviews available info re reactor coolant sys depressurization event at Davis-Besse 2. No current indication of fuel damage or other serious problems at plant.
MCDERMOTT, R. J. Quality Assurance Branch 77/10/06 2pp.

--7905100380 LER NP-32-77-16(Suppl) on 770924: depressurization of primary sys from normal operating pressure occurred, resulting in steam formation.
MURRAY, T. D. Toledo Edison Co. 77/11/14 60pp.

7905100341 Forwards LER 77-096/03L-0.
MURRAY, T. D. Toledo Edison Co. 77/12/16 2pp.

--7905100345 LER 77-096/03L-0 on 771129: diesel generator 1-1 started, but failed to supply power during temporary loss of power. Caused by diesel tripping on overspeed due to governor setting. Switches reset & diesel generator declared operable.
BEYER, B. Toledo Edison Co. 77/12/16 3pp.

7905020266 Notifies of reportable event on 790413: certain starters for essential motors had overload heaters installed which were smaller than capacity specified on relay data sheets, causing possible overload heater burnout. Heater being replaced.
MURRAY, T. D. Toledo Edison Co. 79/04/16 1p.

7905100286 RO on 790423: unplanned reactivity insertion of more than 0.3% occurred. Caused by valve MU39 leaking demineralized water. Procedure mod rewritten to prevent valve leakage & increase sampling frequency.
MURRAY, T. D. Toledo Edison Co. 79/04/23 1p.

7905020303 Forwards LER 79-046/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/04/25 1p.

--7905020330 LER 79-046/03L-0 on 790330: diesel generator declared inoperable after loud, unusual noises & placed in action statement. Caused by bearing failure in turbocharger. Turbocharger replaced.
HARTIGAN, J. P. Toledo Edison Co. 79/04/25 3pp.

7905020418 Forwards LER 79-047/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/04/25 1p.

DOCKETED ITEMS

- 7905020438 LER 79-047/03L-0 on 790329: on 790331 makeup pump 1-1 taken out of svc for maint due to increased vibration & decreased pump performance. Caused by failure of first stage impeller which cut large groove in shaft.
HARTIGAN, J. P. Toledo Edison Co. 79/04/25. 3pp.
- 7905020488 Forwards LER 79-045/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/04/25. 1p.
- 7905020500 LER 79-045/03L-0 ON 790330: borated water storage tank low level trip setpoint in Safety Features Actuation Sys Channel II discovered out of tolerance. Caused by instrument drift & analog amplifier. Analog amplifier recalibrated.
NELSON, J. M. Toledo Edison Co. 79/04/25. 3pp.
- 7905020427 Forwards LER 79-048/01T-0.
MURRAY, T. D. Toledo Edison Co. 79/04/26. 1p.
- 7905020443 LER 79-048/01T-0 on 790413: starters for essential motors had overload heaters installed which were smaller than capacity specified. Caused by error in initial installation due to procedural inadequacy. Check of overload heaters conducted.
MURRAY, T. D. Toledo Edison Co. 79/04/26. 3pp.
- 7905040129 Forwards LER 79-049/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/04/26. 1p.
- 7905040132 LER 79-049/03L-0 on 790331: during surveillance testing half of steam safety valves discovered to be out of design setpoint range. Caused by changing ambient conditions. Valves adjusted & retested.
BROWN, R. A. Toledo Edison Co. 79/04/27. 3pp.
- 7905090269 Forwards LER 79-050/01T-0.
MURRAY, T. D. Toledo Edison Co. 79/05/04. 1p.
- 7905090273 LER 79-050/01T-0 on 790423: boron concentration dropped lower than anticipated final value, resulting in unplanned reactivity insertion. Caused by mechanical personnel & procedural error. Valve being repaired.
BROWN, D. H. Toledo Edison Co. 79/05/04. 3pp.
- 7905150455 Forwards LER 79-051/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/05/09. 1p.
- 7905150456 LER 79-051/03L-0 on 790410: fire alarm point F-056 sounded when no fire existed. Caused by lack of proper control room annunciation & procedure control. Procedure mods being prepared & installation of annunciator investigated.
LINGENFELTER, J. Toledo Edison Co. 79/05/09. 3pp.
- 7905160404 Forwards LER 79-052/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/05/11. 1p.
- 7905160409 LER 79-052/03L-0 on 790416: piece of duct tape found blocking inlet to containment pressure sampling line, rendering instruments inoperable. Tape removed.
NELSON, J. M. Toledo Edison Co. 79/05/11. 2pp.
- 7905220124 Forwards LER 79-035/03L-1.
MURRAY, T. D. Toledo Edison Co. 79/05/15. 1p.
- 7905220125 LER 79-035/03L-1 on 790228: reactor coolant pump 1-1-2 tripped, resulting in reactor runback to 74%. Caused by loosening of inservice filter cover during maint. Cover retightened & add'l nameplates being made.
ROHRER, E. Toledo Edison Co. 79/05/27. 3pp.
- 7905220096 Forwards LER 79-033/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/05/16. 1p.
- 7905220101 LER 79-053/03L-0 on 790417: while in Mode 5, position indication for control rod 3 became erratic. Caused by defective connection in penetration butt splice. Butt splice reconnected. Tests will be made when in Mode 3.
NAYLOR, R. W. Toledo Edison Co. 79/05/16. 2pp.
- 7905220117 Forwards LER 79-054/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/05/16. 1p.
- 7905220121 LER 79-054/03L-0 on 790409: control room isolation damper HV53118 stuck open during surveillance test. Caused by corrosion of bushing in damper shaft. Damper removed & returned to manufacturer for reconditioning.
RUDOLPH, J. J. Toledo Edison Co. 79/05/16. 2pp.
- 7905230371 Forwards review of 770924 event re depressurization of primary sys. Similarities to 790328 incident at TMI-2 noted.
ROE, L. E. Toledo Edison Co. 79/05/18. 3pp.
- 7905250134 Forwards LER 79-055/03L-0.
MURRAY, T. D. Toledo Edison Co. 79/05/18. 1p.
- 7905250142 LER 79-055/03L-0 on 790423: low reactor coolant pressure block bistable BA103 did not reset automatically on increasing surveillance test signal. Caused by sticking of relay K-4. Relay replaced.
NELSON, J. M. Toledo Edison Co. 79/05/18. 2pp.
- DOCKET 50-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7905140357 Notifies of potential reportable inconsistency in calculated DNB ratios, as reported to util by Westinghouse.
HAIRSTON, W. G. Alabama Power Co. 79/03/30. 2pp.
- F. Security, medical, emergency & fire protection plans
- 7905070631 Forwards check to replace check sent 790323 w/safeguards security contingency plan.
CLAYTON, F. L. Alabama Power Co. 79/05/01. 2pp.
- I. Financial information
- 7905150391 Forwards "Annual Financial Rept 1978," unaudited financial statements for quarter ending 790331 & cash flow projections for 1979.
BOWDEN, T. J. Alabama Power Co. 79/05/10. 7pp.
- 7905150395 "Annual Financial Rept 1978."
* Alabama Power Co. 78/12/31. 47pp.
- J. Insurance & indemnity information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
GUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.
- 7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.
- 7905160224 Forwards Amend 4 to Indemnity Agreement B-81, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.
- 7905100304 Forwards Endorsement 23 to NELIA Policy NF-238.
DUCK, J. R. Marsh & McLendon, M & M Nuclear Consultants, Inc. Div. 79/05/04. 2pp.
- 7905150357 Forwards signed Amend 4 to Indemnity Agreement B-81.
BARTON, A. R. Alabama Power Co. 79/05/11. 2pp.
- 7905160396 Forwards Endorsement 24 to ANI Policy NF-238.
DUCK, J. R. Marsh & McLendon, M & M Nuclear Consultants, Inc. Div. 79/05/11. 2pp.
- 7905300468 Forwards Endorsement 25 to ANI Policy NF-238.
DUCK, J. R. Marsh & McLendon, M & M Nuclear Consultants, Inc. Div. 79/05/25. 2pp.
- M. Antitrust correspondence
- 7905100196 AL Electric Cooperative's Response to applicant's "Memo re Impact of Public Regulatory Policies Act of 1978." Certificate of Svc & supporting documentation encl.
BOSKEY, B., MACGUINEA, D. B. Volpe, Boskey & Lyons. 79/03/28. 23pp.

7905100217 Response of Municipal Electric Util Association of AL to applicant's memo re impact of Public Util Regulatory Policies Act of 1978. Certificate of Svc encl. GOLDBERG, R. Goldberg, Fieldman & Letham, P.C. HJELMFELT, D.C. Affiliation Unknown. 79/03/28. 10pp.

7905240978 Notice of appearance of DJ Evans on behalf of NRC. Certificate of Svc encl. EVANS, D.J. Anti-Trust Division. 79/03/28. 3pp.

7905100269 Reply memo re impact of "Public Util Regulatory Policies Act of 1978" on proceeding. Act neither changes legal status of case nor impacts on decisions of liability. Certificate of Svc encl. AXELRAD, J.A. Regulations Division. EVANS, D.J. Anti-Trust Division. 79/03/29. 12pp.

7905240985 Responds to applicant's memo re impact of Public Util Regulatory Policies Act of 1978. Certificate of Svc & supporting documentation encl. WHITLER, J.D. Justice, Dept. of. 79/03/29. 22pp.

P. Operating license stage documents & correspondence

7905090079 Forwards Amend 11 to License NPF-2, safety evaluation & notice of issuance & availability. SCHWENCER, A. Operating Reactors Branch 1. 79/04/13. 3pp.

--7905090080 Amend 11 to License DPR-26, maintaining & implementing all provisions of approved fire protection plan. * Operating Reactors Branch 1. 79/04/13. 2pp.

--7905090083 Safety evaluation supporting Amend 11 to License DPR-26. * Office of Nuclear Reactor Regulation. 79/02/12. 30pp.

--7905090084 Notice of issuance & availability of Amend 11 to License DPR-26. SCHWENCER, A. Operating Reactors Branch 1. 79/04/13. 2pp.

7905020242 Forwards proposed amends to Tech Specs for Unit 1 incorporating radiological effluent Tech Specs into App A & proposed draft radiological effluent Tech Specs for Unit 2. Proposed draft App B Tech Specs encl. CLAYTON, F.L. Alabama Power Co. 79/04/16. 190pp.

7905040267 Ack receipt of 790104 application & 790321 supplementary filing. Requests payment of Class III fee. MILLER, W.D. License Fee Management Branch. 79/04/16. 2pp.

7905170266 Forwards proposed Tech Specs revision modifying safety injection logic by deleting coincident low pressurizer pressure/level logic actuation. CLAYTON, F.L. Alabama Power Co. 79/05/11. 10pp.

7905230414 Requests informal facility info re TMI incident be withheld from public disclosure unless util conducts proprietary review. CLAYTON, F.L. Alabama Power Co. 79/05/16. 2pp.

7905310376 Submits addl info re pressurizer pressure safety injection logic, in ref to 790523 telcon w/E Reeves & T Dunning. Pressurizer pressure transmitters 444, 445, 456 & 457 have control or protection functions. CLAYTON, F.L. Alabama Power Co. 79/05/23. 2pp.

7905010161 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905230777 Informs of delay in responding to IE Bulletin 78-12, 78-12A & 78-12B re weld mats used for each reactor vessel primary boundary ferritic weldment. Westinghouse is unable to provide needed data until 791031. CLAYTON, F.L. Alabama Power Co. 79/03/23. 1p.

7905030290 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905010093 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.

7905010339 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.

7905240514 Forwards IE Insp Rept 50-348/79-10 on 790313-0316 & 21-23. No noncompliance noted. MURPHY, C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/04. 2pp.

--7905240518 IE Insp Rept 50-348/79-10 on 790313-0316 & 21-23. No noncompliance noted. Major areas inspected: inservice insp, welding & nondestructive examination. CROWLEY, B.R. Region 2, Atlanta, Office of the Director. CONLON, T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/04. 7pp.

7905240523 Forwards IE Insp Rept 50-348/79-12 on 790306-0309. No noncompliance noted. LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/04. 2pp.

--7905240527 IE Insp Rept 50-348/79-12 on 790306-09. No noncompliance noted. Major areas inspected: LERS, Part 21 repts, open items, operations review & independent insp. HARDIN, A.K. Region 2, Atlanta, Office of the Director. CANTRELL, F.S. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/03. 6pp.

7905020124 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/11. 1p.

7905100279 Requests extension of time until 790512 to respond to IE Bulletin 79-03, "Longitudinal Weld Defects in Pipe Spools Mfg by Youngstown Welding & Engineering Co." CLAYTON, F.L. Alabama Power Co. 79/04/11. 1p.

7905150568 Confirms 790412 telcon to AK Hardin re IE Bulletin 79-02. Test program was initiated; enough failures found in anchor bolt installations to justify expansion of test scope. Further details will come in 14-day followup. HAIRSTON, W.G. Alabama Power Co. 79/04/12. 1p.

7905040148 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040298 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040322 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905030137 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp.

7905020370 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905240443 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Methods specified by Item 1 have never been used. Therefore, specific concerns are not applicable to facility. CLAYTON, F.L. Alabama Power Co. 79/04/24. 3pp.

7905300710 Forwards response to IE Bulletins 79-06A & 79-06, Revision 1. Training program for personnel w/operational duties is being developed; actions required by operating procedures re transients & accidents have been reviewed. CLAYTON, F.L. Alabama Power Co. 79/04/24. 21pp.

7905300554 Responds to IE Bulletin 79-03. No SA-312 or other welded pipe mfg by Youngstown Welding & Engineering has been received on site or will be used in future. CLAYTON, F.L. Alabama Power Co. 79/04/26. 1p.

7905090075 Forwards "Inservice Testing Program for Class 1, 2 & 3 Pumps & Valves." Encl available in Central Files. CLAYTON, F.L. Alabama Power Co. 79/05/01. 2pp.

DOCKETED ITEMS

7905250036 Responds to IE Bulletin 79-04 "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." One discrepancy found between weights specified in bulletin & actual weight of valve.
CLAYTON, F. L. Alabama Power Co. 79/05/01. 2pp.

R. Periodic operating reports & related correspondence

7905230361 Forwards monthly operating rept for Apr 1979.
CLAYTON, F. L. Alabama Power Co. 79/05/15. 2pp.

--7905230362 Monthly operating rept for Apr 1979.
HAIRSTON, W. G. Alabama Power Co. 79/05/01. 3pp.

S. Reportable occurrences, LERs & related correspondence

7905140368 Confirms 790328 telcon re LER 79-015/01T-0. While performing inservice insp on 790327, five linear surface indications discovered on ECCS line. Currently evaluating nondestructive examination on similar components.
HAIRSTON, W. G. Alabama Power Co. 79/03/28. 1p.

7905020247 Forwards LER 79-021/01T-0.
CLAYTON, F. L. Alabama Power Co. 79/04/26. 1p.

--7905020249 LER 79-021/01T-0 on 790412: in response to IE Bulletin 79-02, program initiated to randomly test anchor bolts installed in Seismic Category 1, safety-related, 2.5-inch grater piping sys. Statistical sample too small. Program expanded.
HAIRSTON, W. G. Alabama Power Co. 79/04/26. 3pp.

7905110242 Forwards LER 79-018/03L-0.
CLAYTON, F. L. Alabama Power Co. 79/05/07. 1p.

--7905110247 LER 79-018/03L-0 on 790409: discovered outer personnel air lock door not operating properly. Caused by inadequate procedural controls. Fuel handling procedures revised to verify that both air lock doors are closed.
* Alabama Power Co. 79/05/07. 3pp.

7905140306 Forwards LER 79-021/01T-1.
CLAYTON, F. L. Alabama Power Co. 79/05/08. 1p.

--7905140311 LER 79-021/01T-1 on 790412: statistical sampling of anchor bolt reliability not sufficient to provide high probability of greater than 95% reliability. Program expanded to include 100% testing.
HAIRSTON, W. G. Alabama Power Co. 79/05/08. 4pp.

7905160403 Forwards LERs 79-020/03L-0 & 79-015/01T-0.
CLAYTON, F. L. Alabama Power Co. 79/05/10. 1p.

--7905160414 LER 79-020/03L-0 on 790411: alarm received on BIJ sequencer. Sequencer found in test, rendering IC dc inoperable & violating min requirement for one dc sst. Caused by faulty key switch breaking internal parts. Switch replaced.
* Alabama Power Co. 79/05/11. 1p.

--7905160407 LER 79-015/01T-1 on 790327: linear surface indications found on 2-inch ECCS line to Loop 1 cold leg, Loop 2 cold leg & Loop 3 hot leg. Probably caused during piping mfg. Affected part of Loop 1 replaced. Loop 2 & 3 indications ground out.
* Alabama Power Co. 79/05/10. 3pp.

7905300500 Forwards LER 79-019/03L-0.
CLAYTON, F. L. Alabama Power Co. 79/05/22. 1p.

--7905300504 LER 79-019/03L-0 on 790420: chemical analysis of reactor coolant revealed overconcentrations of chloride & fluoride. Cause undetermined. Engineering evaluation in progress.
HAIRSTON, W. G. Alabama Power Co. 79/05/22. 1p.

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C. J. Containment Systems Branch. 79/04/13. 150pp.

G. Adjudicatory correspondence

7905210058 Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel.
ROMANO, F. R. Affiliation Unknown. 79/04/12. 5pp.

H. General correspondence

7905230711 Requests const review of facility. Expresses concern re insufficient supply of water near plant for cooling reactor.
BUONANNO, N. A. Affiliation Unknown. 79/04/02. 1p.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010134 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ORIER, B. H. Region 1, Philadelphia. Office of the Director. 79/03/23. 1p.

7905020077 Forwards IE Bulletin 79-06, "Review of Operational Errors: Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia. Office of the Director. 79/04/11. 1p.

7905020372 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
ORIER, B. H. Region 1, Philadelphia. Office of the Director. 79/04/14. 1p.

7905040083 Forwards IE Bulletin 79-06B, "Review of Operational Errors: Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia. Office of the Director. 79/04/14. 1p.

7905040264 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia. Office of the Director. 79/04/14. 1p.

7905030086 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ORIER, B. H. Region 1, Philadelphia. Office of the Director. 79/04/17. 1p.

7905020305 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ORIER, B. H. Region 1, Philadelphia. Office of the Director. 79/04/18. 1p.

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905210058 Requests plant shutdown because of threat of accident as severe as rupture to reactor vessel.
ROMANO, F. R. Affiliation Unknown. 79/04/12. 5pp.

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C. J. Containment Systems Branch. 79/04/13. 150pp.

H. General correspondence

7905230711 Requests const review of facility. Expresses concern re insufficient supply of water near plant for cooling reactor.
BUONANNO, N. A. Affiliation Unknown. 79/04/02. 1p.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

DOCKETED ITEMS

169

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

H. General correspondence

7905070450 Ack receipt of 790216 resolution opposing storage of high level radioactive wastes in township. Objections should be made at ASLB hearing. Expansion of storage pools is unlikely. No independent facilities are planned.
DENTON, H.R. Office of Nuclear Reactor Regulation. 79/03/29. 5pp.

G. Inspection reports, IE Bulletins & correspondence

7905010134 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905140291 Responds to 790312 ltr re resolution adopted on 790216 by Township of Lower Alloways Creek, NJ. Resolution opposes storage of high level wastes. Forwards NRC response.
GOSSICK, L.V. Office of the Executive Director for Operations. 79/04/11. 1p.

7905020077 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

I. Financial information

7905070647 Forwards "Annual Financial Rept, 1978" for Public Svc Electric & Gas Co. Atlantic City Electric Co. Delmarva Power & Light Co & Philadelphia Electric Co.
FRYLING, R. Public Service Electric & Gas Co. of New Jersey. 79/04/30. 162pp.

7905020372 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

J. Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905040083 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905040264 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010140 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

7905030086 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905020100 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/11. 1p.

7905020305 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

7905020369 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905070552 Submits revised schedule re response to NRC's position on NUREG-0313, "Technical Rept on Matl Selection & Processing Guidelines for BWR Coolant Pressure Boundary Piping." Response will be submitted no later than Sept 1979.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 79/04/23. 1p.

7905040093 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

O. Adjudicatory correspondence

7905230512 Util response to briefs opposing de minimus approach of Perkins proceeding. Licensees in Peach Bottom & Hope Creek proceedings conted approach is valid; no need to consider health effects further. W/Certificate of Svc.
CONNER, T.B. Conner, Moore & Corber. 79/04/04. 30pp.

7905040282 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/14. 1p.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Svc encl.
SCINTO, J.F. Hearings Division. 79/04/11. 45pp.

7905030101 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905140519 Response to 790404 brief of Philadelphia Electric Co, PSE&G & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl.
KEPFORD, C.R. Citizens for Safe Environment. 79/04/11. 8pp.

7905020322 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B.H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905140332 Notifies of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLD, M.E. Atomic Safety and Licensing Appeal Panel. 79/04/25. 13pp.

7905070552 Submits revised schedule re response to NRC's position on NUREG-0313, "Technical Rept on Matl Selection & Processing Guidelines for BWR Coolant Pressure Boundary Piping." Response will be submitted no later than Sept 1979.
MITTL, R.L. Public Service Electric & Gas Co. of New Jersey. 79/04/23. 1p.

7905240585 Memo & order ALAB-546. Denies applicants' petition for reconsideration of ALAB-540, which consolidates applicants re radon issue.
DUFLD, M.E. Atomic Safety and Licensing Appeal Panel. 79/05/08. 3pp.

DOCKETED ITEMS

G. Adjudicatory correspondence

7905230512 Util response to brief opposing de minimus approach of Perkins proceeding. Licensees in Peach Bottom & Hope Creek proceedings contend approach is valid; no need to consider health effects further. W/Certificate of Svc.
CONNEX, T. B. Conner, Moore & Corber. 79/04/04. 30pp.

7905110418 Response to ALAB-509 re radon emissions & de minimus theory from Perkins record. Certificate of Svc encl.
SCINTO, J. F. Hearings Division. 79/04/11. 45pp.

7905140519 Response to 790404 brief of Philadelphia Electric Co. PSE&G & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Svc encl.
KEPFORD, C. R. Citizens for Safe Environment. 79/04/11. 8pp.

7905140332 Notices of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
DUFLD, M. E. Atomic Safety and Licensing Appeal Panel. 79/04/25. 13pp.

7905240565 Memo & order ALAB-546. Denies applicants' petition for reconsideration of ALAB-540, which consolidates applicants re radon issue.
DUFLD, M. E. Atomic Safety and Licensing Appeal Panel. 79/05/08. 3pp.

H. General correspondence

7905070450 Ack receipt of 790216 resolution opposing storage of high level radioactive wastes in township. Objections should be made at ASLB hearing. Expansion of storage pools is unlikely. No independent facilities are planned.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/03/29. 5pp.

7905140291 Resonds to 790312 ltr re resolution adopted on 790216 by Township of Lower Alloways Creek, NJ. Resolution opposes storage of high level wastes. Forwards NRC response.
GOSSICK, L. V. Office of the Executive Director for Operations. 79/04/11. 1p.

I. Financial information

7905070647 Forwards "Annual Financial Rept. 1978" for Public Svc Electric & Gas Co. Atlantic City Electric Co. Delmarva Power & Light Co & Philadelphia Electric Co.
FRYLING, R. Public Service Electric & Gas Co. of New Jersey. 79/04/30. 162pp.

J. Insurance & indemnity information

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010140 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/03/23. 1p.

Forwards IE Bulletin 79-06, "Review of Operational Errors & Incidents Identified During TMI Incident."
Region 1, Philadelphia, Office of the Director.

ismic Stress Analysis of
required.
of the Director.

ational Errors &
tor.

7905030101 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Svs." Licensee action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/17. 1p.

7905020322 Forwards IE Bulletin 79-06A. Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B. H. Region 1, Philadelphia, Office of the Director. 79/04/18. 1p.

DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C. J. Containment Systems Branch. 79/04/13. 150pp.

7905100258 Summary of 790410 meeting w/Cincinnati Gas & Electric Co. Long Island Lighting Co & Commonwealth Edison Co re vibratory loads & equipment qualification. Presentation matl encl.
PELTIER, I. A. Light Water Reactors Branch 1. 79/04/19. 15pp.

7905230558 Notification of 790515-17 meeting w/Cincinnati Gas & Electric Co. Long Island Lighting Co. Commonwealth Edison Co & GE in San Jose, CA to audit NSSS equipment for seismic & other dynamic qualification.
PELTIER, I. A. Light Water Reactors Branch 1. 79/04/23. 3pp.

7905020451 Response to 790223 ltr requesting plans & schedule for re-qualification of equipment for seismic & hydrodynamic loads. All Category I equipment has been evaluated as qualified.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/04/26. 3pp.

7905080439 Forwards requested info re seismic Category I equipment, scenario for accomplishing cold shutdown & Sargent & Lundy Balance of Plant equipment for Category I.
BORGMANN, E. A. Cincinnati Gas & Electric Co. 79/05/04. 49pp.

E. NRC Safety Evaluation Report (SER), suppl & correspondence

7905010659 Summary of 790328 meeting w/util re status of implementation of SER issues.
PELTIER, I. A. Light Water Reactors Branch 1. 79/04/12. 7pp.

F. Security, medical, emergency & fire protection plans

7905240572 Summarizes progress in fire protection review. Because redundant electrical divisions are in same fire area, they are suby to identical fire exposure. Fire ratings must be verified prior to OL issuance.
STOLZ, J. F. Light Water Reactors Branch 1. 79/04/19. 3pp.

7905140156 Forwards intervenor Miami Valley Power Project's 790223 answers to util's second set of interrogatories. Questions application of lead plant Mark II acceptance criteria.
KOSIK, L. S. Kosik, L. S. 79/02/21. 1p.

7905140157 Motion by intervenor Miami Valley Power Project to applicant's motion to dismiss. Certificate of Svc encl.
KOSIK, L. S. Kosik, L. S. 79/02/22. 2pp.

7905140369 Answer by intervenor Miami Valley Power Project to applicant's second set of interrogatories. Supporting documentation & Certificate of Svc encl.
KOSIK, L. S. Kosik, L. S. 79/02/22. 8pp.

7905150131 Discusses answers to Cincinnati Gas & Electric Co's interrogatories. Propounds third set of interrogatories to obtain specific responses to second set of questions.
WETTERHAHN, M. J. Conner, Moore & Corber. 79/03/05. 2pp.

7905150133 Applicants' third set of interrogatories to Miami Valley Power Project. Certificate of Svc encl.
WETTERHAHN, M. J. Conner, Moore & Corber. 79/03/05. 6pp.

7905010223 Requests to know if NRC has funds available for use by intervenors to obtain expert witnesses in licensing hearings.
KOSIK, L. S. Kosik, L. S. 79/03/07. 1p.

DOCKETED ITEMS

171

- 7905150144 Interrogatories of intervenor D Fankhauser submitted to applicant. Certificate of Svc encl.
WOLIVER, J.D. Woliver, J.D. 79/03/08. 5pp.
- 7905290171 Opposes D Fankhauser response to 790306 proposed timetable of events. Certificate of Svc encl.
CONNER, T.B., WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/08. 3pp.
- 7905290176 Motion to order answering of fourth set of interrogatories directed to Miami Valley Power Project. Certificate of Svc encl.
CONNER, T.B., WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/08. 3pp.
- 7905290180 Serves fourth set of interrogatories on Miami Valley Power Project. Certificate of Svc encl.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/08. 4pp.
- 7905290464 Submits supplementary answers to applicant's second set of interrogatories. Affidavit encl.
KOSIK, L.S., Kosik, L.S. RIGBERG, S. Miami Valley Power Project. 79/03/13. 6pp.
- 7905290468 Memo in opposition to applicant's motion to require response to fourth set of interrogatories.
RIGBERG, S. Miami Valley Power Project. 79/03/13. 4pp.
- 7905290520 Response to proposed prehearing conference schedule. Schedule reflects impatience rather than sound judgment. Certificate of Svc encl.
RIGBERG, S. Miami Valley Power Project. 79/03/13. 5pp.
- 7905150151 Opposition by applicant to Miami Valley Power Project 790307 motion to admit addl contentions & to extend time for discovery. Project does not satisfy requirements of 10CFR2.715. Certificate of Svc encl.
CONNER, T.B., WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/19. 9pp.
- 7905100210 Responds to intervenor Miami Valley Power Project's set of interrogatories. Affidavit & Certificate of Svc encl.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/03/21. 45pp.
- 7905300062 Forwards applicant's objections to Miami Valley Power Project first set of interrogatories & motion for protective order.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/21. 1p.
- 7905300067 Applicant's objections to certain of Miami Valley Power Project's first set of interrogatories & motion for protective order. Certificate of Svc encl.
WETTERHAHN, M.J., CONNER, T.B. Conner, Moore & Corber. 79/03/21. 6pp.
- 7905010215 NRC is not legally obligated to financially assist intervenors.
SHAPAR, H.K. Office of the Executive Legal Director. 79/03/22. 2pp.
- 7905240412 Ack receipt of 790307 ltr. Informs that US Court of Appeals held that agencies cannot fund participants in proceedings w/o special grant of authority from Congress. NRC will not fund participants in rulemaking proceedings.
SHAPAR, H.K. Office of the Executive Legal Director. 79/03/22. 1pp.
- 7905080379 Opposes applicant's 790308 motion to require response by intervenor Miami Valley Power Project to interrogatories submitted by applicant. Certificate of Svc encl.
BARTH, C.A. Branch 3. 79/03/26. 7pp.
- 7905100222 Responds to interrogatories served by intervenor D Fankhauser upon applicant. Certificate of Svc encl.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/03/27. 23pp.
- 7905170301 Forwards applicant's objections to intervenor Fankhauser's interrogatories & motion for protective order.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/03/27. 1p.
- 7905170303 Applicant's objections to intervenor D Fankhauser's interrogatories & motion for protective order. Three interrogatories exceed scope of proceeding. Certificate of Svc encl.
WATTERHAHN, M.J. Conner, Moore & Corber. 79/03/27. 6pp.
- 7905300091 NRC opposition to Miami Valley Power Project's motion to admit two addl contentions re adequacy of cable trays & control rods. Recommends denial of motion according to 10CFR2.714(a)&(b). Certificate of Svc encl.
BARTH, C.A. Branch 3. 79/03/27. 3pp.
- 7905150757 Response in support of admission of addl contentions & extension of time for discovery. Certificate of Svc encl.
RIGBERG, S., MCDONALD, T. Miami Valley Power Project. 79/04/02. 13pp.
- 7905020334 NRC expects to issue suppl to SER prior to end of May.
BARTH, C.A. Branch 3. 79/04/04. 1p.
- 7905220075 Forwards summary of "Rept to Commission--Inquiry into an Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Serving St Lucie."
BARTH, C.A. Branch 3. 79/04/04. 2pp.
- 7905220084 Discusses inquiries into charges of possible NRC employee misconduct by restricting investigations of power grid disturbances. Available evidence does not support such allegations.
MCTIERNAN, T.J. Office of Inspector & Auditor. 78/06/26. 5pp.
- 7905080341 NRC has recently discovered document possibly relevant to issue of sabotage of spent fuel. Info is classified & may never be published in final form. NRC assessment of info will follow as soon as available.
BARTH, C.A. Branch 3. 79/04/05. 2pp.
- 7905100169 Memo by Cincinnati Gas & Electric in support of 771031 motion for summary judgment re certain admitted contentions. Affidavits of KL Rooney, JR Schott & QC Ficke encl.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/04/06. 66pp.
- 7905140083 Response to second set of interrogatories submitted by intervenor Miami Valley Power Project. Certificate of Svc encl.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/04/06. 24pp.
- 7905250117 Objections by util to portions of intervenor Miami Valley Power Project's 790319 second set of interrogatories. Also seeks protective order.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/04/06. 3pp.
- 7905250123 Request by util that Miami Valley Power Project be dismissed as party for violations of discovery rules, or in the alternative, that util be granted extension of time to file motion of summary judgment re project's contentions.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/04/06. 4pp.
- 7905300690 Notification of new schedule, including new dates for prehearing conference.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/04/06. 4pp.
- 7905250208 Notice of prehearing conference on 790521-23, to be held per ASLB 790406 order.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/04/09. 2pp.
- 7905150227 Motion to delay OL hearings & to extend time for discovery re Contention 13. Certificate of Svc encl.
KOSIK, L.S. Miami Valley Power Project. 79/04/16. 6pp.
- 7905240506 Forwards request for ASLAB decisions from C Richards & summary of NRC 790327 meeting w/util to discuss fire protection.
BARTH, C.A. Branch 3. 79/04/16. 5pp.
- 7905240515 Requests copies of ALAB-444 & ALAB-462 be sent to aid in research re use & availability of U fuel.
RICHARDS, C. Affiliation Unknown. 79/04/10. 1p.
- 7905150218 Motion by intervenor D Fankhauser to reopen discovery & for continuance of hearing, pending NRC review of TMI-2 incident. Certificate of Svc encl.
WOLIVER, J.D. Woliver, J.D. 79/04/17. 4pp.
- 7905150212 Opposes util's motion to dismiss intervenor Miami Valley Power Project as party. Does not oppose util's alternative request for extension of time. Certificate of Svc encl.
KOSIK, L.S. Miami Valley Power Project. 79/04/18. 4pp.
- 7905150221 Third set of interrogatories to applicant. Certificate of Svc encl.
KOSIK, L.S. Miami Valley Power Project. 79/04/20. 11pp.
- 7905240092 Requests joint appearance for A Shapiro & EJ Torchia at ASLB hearings in Moscow, OH on 790522 & Cincinnati, OH on 790523. Requests notification of meeting schedule.
TORCHIA, E.J. Affiliation Unknown. 79/04/20. 1p.

DOCKETED ITEMS

7905240104 Complains that date of 790423 is unrealistic; objections & protective order were filed after receipt of discovery motions.
KOSIK, L.S. Kosik, L. S. 79/04/20. 1p.

7905310093 Fifth set of interrogatories submitted by util to Miami Valley Power Project. Certificate of Svc encl.
WETTERHAHN, M.J. Conner, Moore & Corber. 79/04/20. 7pp.

7905290036 Grants extension until 790502 for NRC to respond to util's 790406 motion for summary disposition.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/05/01. 2pp.

7905150284 Orders one-day extension until 790502 for City of Cincinnati to respond to util's 790406 motion for summary disposition.
BECHHOEFER, C. Atomic Safety and Licensing Board Panel. 79/05/02. 1p.

7905300749 Requests opportunity to present limited statement at 790523 prehearing conference in Moscow, OH.
ZITT, K.L. Affiliation Unknown. 79/05/04. 1p.

H. General correspondence

7905300284 Requests deletion of PH Forster of Dayton Power & Light Co from svc list & replacement w/SG Smith.
FLYNN, J.D. Cincinnati Gas & Electric Co. 79/05/25. 1p.

J. Insurance & indemnity information

7905160272 Forwards Amend 2 to Indemnity Agreement B-85, per 10CFR140 changes, re increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

7905110148 Forwards Indemnity Agreement B-85 & Amend 1.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/05/04. 15pp.

K. Utility Final Safety Analysis Report (FSAR) & amendments

7905290449 Forwards Amend 92 to application, consisting of Revision 57 to FSAR.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/04/30. 2pp.

---7905290456 Amend 92 to application, FSAR Revision 57. Submitted in response to second round questions.
* Cincinnati Gas & Electric Co. 79/04/30. 400pp.

7905160434 Forwards Certificate of Svc of Amend 92, in form of Revision 57 to FSAR.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/05/10. 2pp.

G. Inspection reports, IE Bulletins & correspondence

7905010242 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/03/23. 1p.

7905030372 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/03/26. 1p.

7905240719 Forwards IE Insp Rept 50-358/79-08 on 790305-06. No noncompliance noted.
HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/03/27. 2pp.

---7905240729 IE Insp Rept 50-358/79-08 on 790305-06. No noncompliance noted. Major areas inspected: operational QA program & station staffing.
HARPSTER, T.L., MENNING, J.E., WERNICK, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/03/15. 2pp.

7905150529 Forwards IE Insp Rept 50-358/79-10 on 790319-20. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/03/29. 2pp.

---7905150535 IE Insp Rept 50-358/79-10 on 790319-20. No noncompliance noted. Major areas inspected: review of procedures, work activities & quality records for hangers, snubbers & restraints design.
YIN, L.T., NAIDUK, R. Region 3, Chicago, Office of the Director.
DANIELSON, D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/03/28. 5pp.

7905290699 Forwards IE Insp Rept 50-358/79-09 on 790321-23. No noncompliance noted.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/09. 2pp.

---7905290720 IE Insp Rept 50-358/79-09 on 790321-23. No noncompliance noted. Major areas inspected: followup of previously identified noncompliance & unresolved matters & review of electrical & instrumentation activities in progress.
VANDEL, T.E., HUGHES, J., KNOP, R.C. Region 3, Chicago, Office of the Director. 79/04/06. 8pp.

7905030017 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/11. 1p.

7905010574 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040351 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040452 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040534 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905010400 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/16. 1p.

7905030215 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/17. 1p.

7905040368 Responds to 781017 phone call re Sargent & Lundy control of stress rept documentation. NRC review discloses weakness in control of outdated procedures & will be pursued until open item is adequately resolved. W/o encl.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/19. 1p.

7905080397 Forwards IE Bulletin 79-03B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/21. 1p.

7905140107 Ack receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/79-07.
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/25. 1p.

---7905140111 Responds to NRC 790305 ltr re violations noted in IE Insp Rept 50-358/79-07. Corrective actions: approved calibr procedure implemented & uncontrolled rods & stubs removed.
BORGMANN, E.A. Cincinnati Gas & Electric Co. 79/04/11. 3pp.

7905240887 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/05/02. 1p.

B. Reportable occurrences, LERs & related correspondence

7905070009 Ack receipt of 790313 final rept re control rod interference, per 10CFR50.55(e).
FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/04. 1p.

DOCKETED ITEMS

173

DOCKET 50-360 BATTELLE MEMORIAL INST. CRITICAL FACILITY

J. Insurance & indemnity information

7905160233 Forwards Amend 7 to Indemnity Agreement B-58, per 10CFR140 changes, re liability insurance increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl. SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 5pp.

7905300523 Forwards Amend 7 to Indemnity Agreement B-58. FRANSEN, C. D. Battelle Memorial Institute, Pacific Northwest Laboratory. 79/05/24. 2pp.

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905010553 Comments on "Cultural Resource Mgt Repts for San Onofre-to-Mission-to-Encino 230 kV Transmission Lines & Mapping & Data Recovery Program for Site W-1527." Repts are suitable as baseline studies. Identifies questions for clarification. MELLON, K. California, State of. 79/03/20. 2pp.

7905230589 Notification of 790426 meeting w/util in Bethesda, MD to discuss fuel design & analysis. ROOD, H. Light Water Reactors Branch 2. 79/04/19. 3pp.

7905290411 Notification of 790504 meeting w/util in Bethesda, MD to discuss San Onofre geology. ROOD, H. Light Water Reactors Branch 2. 79/05/02. 3pp.

7905210160 Forwards equipment seismic qualification summary info, in response to NRC 790111 request in preparation for site visit. Drawings available in Central Files only. BASKIN, K. P. Southern California Edison Co. 79/05/16. 700pp.

I. Financial information

7905150400 Forwards "Annual Financial Rept 1978" for Southern CA Edison Co & San Diego Gas & Electric Co. DRAKE, J. H. Southern California Edison Co. 79/05/08. 1p.

--7905150404 "Annual Financial Rept 1978." * Southern California Edison Co. 79/02/15. 31pp.

--7905150406 "Annual Financial Rept 1978." * San Diego Gas & Electric Co. 79/02/20. 43pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others. GUATTROCHMI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

M. Antitrust correspondence

7905310373 Submits request for addl info to complete antitrust review of OL application. TOALSTON, A. L. Antitrust & Indemnity Group. 79/05/11. 3pp.

Q. Inspection reports, IE Bulletins & correspondence

7905010292 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." ENGELKEN, R. H. Region 4, Dallas, Office of the Director. 79/03/23. 1p.

7905010025 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040512 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040619 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905070104 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905030296 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/17. 1p.

7905080371 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl." ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

S. Reportable occurrences, LERs & related correspondence

7905150064 Forwards PNO-79-67L. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/06. 1p.

7905150170 Forwards PNO-79-67R. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/11. 1p.

7905040128 Forwards PNO-79-67S. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/12. 1p.

7905150145 Forwards PNO-79-67T. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/13. 1p.

7905030024 Forwards PNO-79-67U. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905020532 Forwards PNO-79-67AA. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/20. 1p.

7905010434 Forwards PNO-79-67AB. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

7905010449 Forwards PNO-79-67AC & AD. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/23. 1p.

7905010462 Forwards PNO-79-67AE. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/24. 1p.

7905090041 Forwards PNO-79-67AF. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/25. 1p.

7905090057 Forwards PNO-79-67AG. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/26. 1p.

7905310012 Ack receipt of 790406 interim rept on Taylor Forge pipe defects pursuant to 10CFR50.55(e). ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/26. 1p.

7905090119 Forwards PNO-79-67AH. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/27. 1p.

7905070031 Forwards PNO-79-67AI, AJ & AK, per NRC 790401 ltr transmitting IE Bulletin 79-05. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/30. 1p.

7905070012 Forwards PNO-79-67AL, per NRC 790401 ltr transmitting IE Bulletin 79-05. ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/05/01. 1p.

DOCKETED ITEMS

7905090277 Provides followup on 790108 final rept on reportable condition re fillet weld design. Revised drawings for remaining 78 pipe support assemblies will be issued for const use by 790904.
MOORE, J. B. Southern California Edison Co. 79/05/02. 1p.

7905310044 Forwards PNO-79-67AM.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/05/07. 1p.

7905300265 Forwards interim rept of Marine Review Committee re ECCS.
WONG, S. California, State of. 79/05/15. 1p.

--7905300270 "Interim Rept of Marine Review Committee to CA Coastal Commission, Part I: General Summary of Findings, Predictions & Recommendations Concerning Cooling Sys."
CONNELL, J. H., MECHALAS, B. J., MIHURSKY, J. A. California, State of. 79/05/12. 22pp.

--7905300277 "Interim Rept of Marine Review Committee to CA Coastal Commission, Part II: App of Technical Evidence in Support of General Summary."
CONNELL, J. H., MECHALAS, B. J., MIHURSKY, J. A. California, State of. 79/05/12. 197pp.

7905310423 Forwards final deficiency rept, "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators," identified in 790419 ltr.
MOORE, J. B. Southern California Edison Co. 79/05/18. 1p.

--7905310426 Final deficiency rept: "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators."
Appropriate drawing changes will be issued for design changes by 790715. Fifteen actuators will require rework.
* Southern California Edison Co. 79/05/18. 3pp.

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

A. Application/construction stage documents & correspondence

7905010553 Comments on "Cultural Resource Mgt Repts for San Onofre-to-Mission-to-Encino 230 kV Transmission Lines & Mapping & Data Recovery Program for Site W-1527." Repts are suitable as baseline studies. Identifies questions for clarification.
MELLON, K. California, State of. 79/03/20. 2pp.

7905230589 Notification of 790426 meeting w/util in Bethesda, MD to discuss fuel design & analysis.
ROOD, H. Light Water Reactors Branch 2. 79/04/19. 3pp.

7905290411 Notification of 790504 meeting w/util in Bethesda, MD to discuss San Onofre geology.
ROOD, H. Light Water Reactors Branch 2. 79/05/02. 3pp.

7905210160 Forwards equipment seismic qualification summary info. in response to NRC 790111 request in preparation for site visit. Drawings available in Central Files only.
BASKIN, K. P. Southern California Edison Co. 79/05/16. 700pp.

I. Financial information

7905150400 Forwards "Annual Financial Rept 1978" for Southern CA Edison Co & San Diego Gas & Electric Co.
DRAKE, J. H. Southern California Edison Co. 79/05/08. 1p.

--7905150404 "Annual Financial Rept 1978."
* Southern California Edison Co. 79/02/15. 31pp.

--7905150406 "Annual Financial Rept 1978."
* San Diego Gas & Electric Co. 79/02/20. 43pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
GUATTROCHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

M. Antitrust correspondence

7905310373 Submits request for addl info to complete antitrust review of OL application.
TOALSTON, A. L. Antitrust & Indemnity Group. 79/05/11. 3pp.

G. Inspection reports, IE Bulletins & correspondence

7905010292 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
ENGELKEN, R. H. Region 4, Dallas, Office of the Director. 79/03/23.

7905010020 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040512 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905040619 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905070104 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905030296 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/17. 1p.

7905080371 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

S. Reportable occurrences, LERs & related correspondence

7905150064 Forwards PNO-79-67L.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/06. 1p.

7905150170 Forwards PNO-79-67R.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/11. 1p.

7905040128 Forwards PNO-79-67S.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/12. 1p.

7905150145 Forwards PNO-79-67T.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/13. 1p.

7905030024 Forwards PNO-79-67U.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/14. 1p.

7905020532 Forwards PNO-79-67AA.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/20. 1p.

7905010434 Forwards PNO-79-67AB.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/21. 1p.

7905010449 Forwards PNO-79-67AC & AD.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/23. 1p.

7905010462 Forwards PNO-79-67AE.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/24. 1p.

7905090041 Forwards PNO-79-67AF.
ENGELKEN, R. H. Region 5, San Francisco, Office of the Director. 79/04/25. 1p.

DOCKETED ITEMS

175

7905090057 Forwards PNO-79-67AG.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/26. 1p.

7905310012 Ack receipt of 790406 interim rept on Taylor Forge pipe defects pursuant to 10CFR50.55(a).
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/26. 1p.

7905090119 Forwards PNO-79-67AH.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/27. 1p.

7905070031 Forwards PNO-79-67AI, AJ & AK, per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/04/30. 1p.

7905070012 Forwards PNO-79-67AL, per NRC 790401 ltr transmitting IE Bulletin 79-05.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/05/01. 1p.

7905090277 Provides followup on 790108 final rept on reportable condition re fillet weld design. Revised drawings for remaining 78 pipe support assemblies will be issued for const use by 790904.
MOORE, J. B. Southern California Edison Co. 79/05/02. 1p.

7905310044 Forwards PNO-79-67AM.
ENGELKEN, R. H. Region 3, San Francisco, Office of the Director.
79/05/07. 1p.

7905300265 Forwards interim rept of Marine Review Committee re ECCB.
MONO, B. California, State of. 79/05/15. 1p.

--7905300270 "Interim Rept of Marine Review Committee to CA Coastal Commission, Part I: General Summary of Findings, Predictions & Recommendations Concerning Cooling Sys."
CONNELL, J. H., MECHALAB, B. J., MIHURSKY, J. A. California, State of.
79/05/12. 22pp.

--7905300277 "Interim Rept of Marine Review Committee to CA Coastal Commission, Part II: App of Technical Evidence in Support of General Summary."
CONNELL, J. H., MECHALAB, B. J., MIHURSKY, J. A. California, State of.
79/05/12. 197pp.

7905310423 Forwards final deficiency rept: "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators."
Identified in 790419 ltr.
MOORE, J. B. Southern California Edison Co. 79/05/18. 1p.

--7905310426 Final deficiency rept: "Undersized Safety-Related Heating, Ventilating & Air Conditioning Damper Actuators."
Appropriate drawing changes will be issued for design changes by 790715. Fifteen actuators will require rework.
* Southern California Edison Co. 79/05/18. 3pp.

DOCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905070466 Forwards "Design Info, Submittal 2, Structural Reorientation," w/current design features reflecting new licensing concerns of post-CP period.
FINFROCK, J. R. Jersey Central Power & Light Co. 79/03/05. 2pp.

--7905070470 "Design Info, Submittal 2, Structural Reorientation."
FINFROCK, J. R. Jersey Central Power & Light Co. 79/02/23. 54pp.

7905150287 Forwards 790307 ltr from S. Rush, of Sea Alliance of Ocean County, NJ, for placement in docket file.
ABRAHAM, K. Region 1, Philadelphia, Office of the Director.
79/03/20. 1p.

--7905150293 Requests that planned salt water cooling tower not be built because of disastrous effects on natural beauty of area.
RUSH, S. Sea Alliance of Ocean County. 79/03/07. 1p.

--7905150298 Responds to 790307 ltr objecting to proposed cooling tower. Ltr forwarded to NRC headquarters.
ABRAHAM, K. Region 1, Philadelphia, Office of the Director.
79/03/20. 1p.

H. General correspondence

7905090144 Ack receipt of 790206 ltr requesting list of publications re nuclear-powered electric generating facilities & related issues. List of repts re cooling towers, transmission lines & socioeconomic impacts encl.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/04/04. 3pp.

7905040343 Ack receipt of encl 790202 ltr to President Carter expressing concern over proposed facility. Describes environ review process. Const is about 9% complete.
DENTON, H. R. Office of Nuclear Reactor Regulation. 79/04/13. 4pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHINI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

G. Inspection reports, IE Bulletins & correspondence

7905010112 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/03/23. 1p.

7905240679 Forwards IE Insp Rept 50-363/79-03 on 790306-07. No noncompliance noted.
CARLSON, R. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/03/23. 2pp.

--7905240684 IE Insp Rept 50-363/79-03 on 790306-07. No noncompliance noted. Major areas inspected: containment concrete placement activities & associated quality records.
CERNE, A. C. Region 1, Philadelphia, Office of the Director.
MCQUAGHY, R. W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 79/03/22. 3pp.

7905020045 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/11. 1p.

7905020393 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14. 1p.

7905040020 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14. 1p.

7905040204 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/14. 1p.

7905030065 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/17. 1p.

7905010650 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
GRIER, B. H. Region 1, Philadelphia, Office of the Director.
79/04/18. 1p.

DOCKETED ITEMS

176

DOCKET 50-364 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7905140357 Notifies of potential reportable inconsistency in calculated DNS ratios, as reported to util by Westinghouse.
HAIRSTON, W. G. Alabama Power Co. 79/03/30. 2pp.

7905240109 Notifies of 790531 expiration of Certificate of Compliance 5364 for Model NPI-67-0442 Renewal must be requested.
MACDONALD, C. E. Transportation Branch. 79/04/12. 1p.

7905020242 Forwards proposed amends to Tech Specs for Unit 1 incorporating radiological effluent Tech Specs into App A & proposed draft radiological effluent Tech Specs for Unit 2. Proposed draft App B Tech Specs encl.
CLAYTON, F. L. Alabama Power Co. 79/04/16. 190pp.

7905230414 Requests informal facility info re TMI incident be withheld from public disclosure unless util conducts proprietary review
CLAYTON, F. L. Alabama Power Co. 79/05/16. 2pp.

F. Security, medical, emergency & fire protection plans

7905070631 Forwards check to replace check sent 790323 w/safeguards security contingency plan.
CLAYTON, F. L. Alabama Power Co. 79/05/01. 2pp.

I. Financial information

7905150391 Forwards "Annual Financial Rept 1978," unaudited financial statements for quarter ending 790331 & cash flow projections for 1979.
BOWDEN, T. J. Alabama Power Co. 79/05/10. 7pp.

--7905150395 "Annual Financial Rept 1978."
* Alabama Power Co. 78/12/31. 47pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 25, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
GUATTROCHINI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
D. M. Mutual Atomic Energy Liability Underwriters. 79/05/01.

Forwards Endorsement 23 to NELIA Policy NF-238.
March & McLendon, M & M Nuclear Consultants, Inc. Div.

sent 24 to ANI Policy NF-238.
Nuclear Consultants, Inc. Div.

by NF-238.
Nuclear Consultants, Inc. Div.

to applicant's "Memo re
1978."
encl.
ions. 79/03/28. 23pp.

Association of AL to
ulatory
HJELMFIELT, D. C.

behalf of NRC.
3pp.

Regulatory Policies Act
gal status of
rtificate of
J. Anti-Trust

7905240985 Responds to applicant's memo re impact of Public Util Regulatory Policies Act of 1978. Certificate of Svc & supporting documentation encl.
WHITLER, J. D. Justice, Dept. of. 79/03/29. 22pp.

G. Inspection reports, IE Bulletins & correspondence

7905010161 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905030290 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905100279 Requests extension of time until 790512 to respond to IE Bulletin 79-03, "Longitudinal Weld Defects in Pipe Spools Mfg by Youngstown Welding & Engineering Co."
CLAYTON, F. L. Alabama Power Co. 79/04/11. 1p.

7905150568 Confirms 790412 telcon to AK Hardin re IE Bulletin 79-02. Test program was initiated; enough failures found in anchor bolt installations to justify expansion of test scope. Further details will come in 14-day followup.
HAIRSTON, W. G. Alabama Power Co. 79/04/12. 1p.

7905040148 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040298 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040322 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905010331 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905030137 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp.

7905020365 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905240443 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Methods specified by Item 1 have never been used. Therefore, specific concerns are not applicable to facility.
CLAYTON, F. L. Alabama Power Co. 79/04/24. 3pp.

7905300710 Forwards response to IE Bulletins 79-06A & 79-06, Revision 1. Training program for personnel w/operational duties is being developed; actions required by operating procedures re transients & accidents have been reviewed.
CLAYTON, F. L. Alabama Power Co. 79/04/24. 21pp.

7905300554 Responds to IE Bulletin 79-03, No SA-312 or other welded pipe mfg by Youngstown Welding & Engineering has been received on site or will be used in future.
CLAYTON, F. L. Alabama Power Co. 79/04/26. 1p.

DOCKET 50-366 EDWIN I. HATCH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

7905150089 Responds to 790302 ltr reporting reasons for delays on implementing 10CFR73.55 requirements & describing compensatory measures provided to meet these requirements. Measures are acceptable.
IPPOLITO, T. A. Operating Reactors Branch 3. 79/04/18. 2pp.

I. Financial information

7905080497 Forwards "Annual Financial Rept 1978."
VASQUEZ, R. O. Metropolitan Electric Authority of Georgia. 79/05/02. 1p.

DOCKETED ITEMS

177

--7905080508 "Annual Financial Rept 1978."
* Metropolitan Electric Authority of Georgia. 78/12/31. 24pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 29, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others. QUATTROCHINI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies NF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

7905080427 Forwards Amend 10 to Indemnity Agreement B-69. WHITMER, C.F. Georgia Power Co. 79/05/01. 3pp.

7905140493 Forwards Amend 11 to Indemnity Agreement B-69 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl. SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905080430 Forwards Endorsement 49 to NELIA Policy NF-215. FIEDLER, J. Marsh & McLennan, M & M Nuclear Consultants, Inc. Div. 79/05/03. 2pp.

P. Operating license stage documents & correspondence

7905090183 Forwards Amend 7 to License NPF-5 & notice of issuance & availability. IPPOLITO, T.A. Operating Reactors Branch 3. 79/04/03. 3pp.

--7905090186 Amend 7 to License NPF-5, changing Tech Spec deadline for initial startup rept. IPPOLITO, T.A. Operating Reactors Branch 3. 79/04/03. 5pp.

--7905090189 Notice of issuance & availability of Amend 7 to License NPF-5. IPPOLITO, T.A. Operating Reactors Branch 3. 79/04/03. 2pp.

7905070669 Responds to 790319 ltr questioning license amend fee requirement for 781221 application. Fees paid are justified. MILLER, W.O. License Fee Management Branch. 79/04/05. 1p.

7905170234 Forwards schedule for implementation & resolution of Mark I containment long-term program. Only vent header deflectors are necessary as major mod for conformance to long-term program acceptance criteria. WHITMER, C.F. Georgia Power Co. 79/05/14. 4pp.

7905290184 Forwards changes to Unit 2 Tech Specs re reactor protection sys instrumentation, isolation actuation instrumentation & bases for applicability spec per 790201 request. WHITMER, C.F. Georgia Power Co. 79/05/22. 9pp.

G. Inspection reports, IE Bulletins & correspondence

7905010200 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/23. 2pp.

7905020489 Forwards IE Insp Repts 50-321/79-09 & 50-366/79-11 on 790210-0302. No noncompliance noted. LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 2pp.

--7905020497 IE Insp Repts 50-321/79-09 & 50-366/79-11 on 790210-0302. No noncompliance noted. Major areas inspected: Unit 1 plant operations, Unit 2 startup testing, Tech Specs compliance, reportable occurrences & Unit 2 transient test witnessing. ROGERS, R.F. Region 2, Atlanta, Office of the Director. DANCE, H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/23. 4pp.

7905030312 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/26. 2pp.

7905010107 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as Source of Breathing Air." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/28. 2pp.

7905010360 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/03/30. 2pp.

7905250098 Requests page 6 of IE Insp Repts 50-321/79-06 & 50-366/79-07 be replaced w/encl corrected page. MILLER, J.H. Georgia Power Co. 79/04/04. 2pp.

--7905250105 Forwards IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16. No noncompliance noted. LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/21. 2pp.

--7905250110 IE Insp Repts 50-321/79-06 & 50-366/79-07 on 790214-16. No noncompliance noted. Major areas inspected: plant operations, followup of unresolved items, LERs & test witnessing. DANCE, H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. HINCKLEY, D.G. Region 2, Atlanta, Office of the Director. 79/03/21. 8pp.

7905040216 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 2pp.

7905040304 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/14. 1p.

7905100244 Responds to IE Bulletin 79-03. No evidence of Youngstown Welding & Engineering seam welded ASME SA-312 Type 304 stainless steel piping is being used in safety-related sys. ASME SA-358 Type 304 spool is used. STAFFA, R.W. Georgia Power Co. 79/04/16. 1p.

7905030165 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/17. 2pp.

7905020467 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 79/04/18. 2pp.

7905290029 Responds to IE Bulletin 79-08. Addresses events relevant to BWRs identified during TMI incident. Response to Item 11 will be forwarded in 30 days. WIDNER, W.A. Georgia Power Co. 79/04/25. 15pp.

7905300309 Responds to IE Bulletin 79-04. Review of design records indicates there are no 3/4 or 6-inch diameter Velan swing check valves used at facility. STAFFA, R.W. Georgia Power Co. 79/05/02. 1p.

7905290035 Forwards revised responses to IE Bulletin 79-08, "Events Relevant to BWRs Identified During TMI Incident." Replaces previous 790425 submittal (mentioned as 790415 in present ltr). Includes response to Item 11. WIDNER, W.A. Georgia Power Co. 79/05/09. 16pp.

R. Periodic operating reports & related correspondence

7905150344 Forwards monthly operating rept for Apr 1979. HANRY, M. Georgia Power Co. 79/05/09. 1p.

--7905150348 Monthly operating rept for Apr 1979. STANCLIL, R. Georgia Power Co. 79/05/01. 11pp.

S. Reportable occurrences, LERs & related correspondence

7905140316 Notifies that LERs 50-366/1979-27 & 50-321/1979-16 have been voided. They were later determined to be not reportable. HANRY, M. Georgia Power Co. 79/03/13. 1p.

7905010469 Forwards LERs 79-025/01X-1 & 79-025/01T-0. HANRY, M. Georgia Power Co. 79/04/19. 1p.

DOCKETED ITEMS

--7905010470 LER 79-025/01X-1 on 790223: torus insp revealed several upper clevis pins of torus vent header support columns displaced. Caused by vibration of vent header causing roll pins to be sheared. Design changes issued.
GREENE, T.V. Georgia Power Co. 79/04/17. 2pp.

7905070639 Forwards LER 79-031/03L-0.
MANRY, M. Georgia Power Co. 79/05/01. 2pp.

--7905070646 LER 79-031/03L-0 on 781129: quick start test failed. Sys declared inoperable. Quick start surveillance procedure rewritten & personnel re-instructed.
BAXLEY, S.X. Georgia Power Co. 79/05/01. 2pp.

7905150465 Forwards LER 79-030/03L-0.
MANRY, M. Georgia Power Co. 79/05/04. 1p.

--7905150467 LER 79-030/03L-0 on 790418: during surveillance on water level instrument 2B21-N024A, limit switch failed to actuate, tripping recirculation pump A on low level. Caused by fouled switch contacts. Contacts cleaned.
NIX, R.T. Georgia Power Co. 79/05/04. 1p.

7905300683 Forwards LER 79-033/03L-0.
MANRY, M. Georgia Power Co. 79/05/17. 1p.

--7905300688 LER 79-033/03L-0 on 790508: air operators on 2B21-F018A & C were improperly installed. Caused by insufficient installation info. Maint procedures revised to assure proper installation.
GREENE, T.V. Georgia Power Co. 79/05/17. 2pp.

DOCKET 50-367 BAILLY GENERATING STATION

A. Application/construction stage documents & correspondence

7905020400 Forwards NUREG-0531, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability. W/o encl.
VASSALLO, D.B. Assistant Director for Light Water Reactors. 79/03/23. 2pp.

7905040316 Summary of 790321 meeting of Mark II owners group in San Jose, CA re intermediate plant program tasks.
ANDERSON, C.J. Containment Systems Branch. 79/04/13. 150pp.

G. Adjudicatory correspondence

7905240223 Requests that NRC grant hearing on Northern IN Public Svc 790207 petition for extension of CP. Certificate of Svc encl.
ANDREWS, W.; OLSZANSKI, S.M. Affiliation Unknown. 79/03/27. 3pp.

G. Inspection reports, IE Bulletins & correspondence

7905010258 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/03/23. 1p.

7905040041 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/03/26. 1p.

7905030036 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/11. 1p.

7905010593 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040398 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905040568 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905070164 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14. 1p.

7905010429 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/16. 1p.

7905030232 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/17. 1p.

7905080502 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/04/21. 1p.

7905240907 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEPPLER, J.G. Region 3, Chicago, Office of the Director. 79/05/02. 1p.

R. Periodic operating reports & related correspondence

7905010534 Forwards well charts for 790404-790411, well levels, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, & water meter readings for 790411.
BOHN, R.J. Northern Indiana Public Service Co. 79/04/23. 33pp.

7905140308 Forwards well charts for 790411-18, well levels for 790412, 13, 17 & 18, Bailly wells w/o recorders for 790418, pond levels for 790418, pneumatic pressure transducers for 790418 & water meter readings for 790418.
BOHN, R.J. Northern Indiana Public Service Co. 79/04/27. 17pp.

7905110306 Forwards 790418-25 well charts, 790419-25 well levels, 790425 Bailly wells w/o recorders, 790425 pond levels, 790425 pneumatic pressure transducers, 790425 water meter readings & 790201-0316 rainfall at Flint Lake pump station.
BOHN, R.J. Northern Indiana Public Service Co. 79/05/04. 19pp.

7905220207 Forwards well charts for 790425-790502, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers, water meter reading & USOS wells, all for 790502.
BOHN, R.J. Northern Indiana Public Service Co. 79/05/11. 16pp.

7905210277 Forwards "Winter 1979 Quarterly Rept" on ecological monitoring program.
SHORB, E.M. Northern Indiana Public Service Co. 79/05/15. 1p.

--7905210280 "Winter 1979 Quarterly Rept" on ecological monitoring program for Jan-Mar 1979.
* Northern Indiana Public Service Co. 79/04/30. 126pp.

7905300329 Forwards well charts for 790502-09, Bailly wells w/o recorders, pond levels, pneumatic pressure transducers & water meter readings for 790509.
BOHN, R.J. Northern Indiana Public Service Co. 79/05/18. 31pp.

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

H. General correspondence

7905240955 Responds to 790412 ltr to JM Hendrie re nuclear power plant near Russellville, AR. Outlines steps for license review. Forwards "Transportation of Nuclear Fuel & Waste" & "Disposal of Radioactive Waste." W/o encl.
DEYOUNG, R.C. Division of Site Safety & Environmental Analysis. 79/05/07. 2pp.

--7905240965 Expresses concern re nuclear plants at Russellville, AR. Requests public investigation re safety of facility. Forwards policy statement of Arkansas for Safe Energy.
BERKY, J.A. Affiliation Unknown. 79/04/12. 2pp.

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 23, 43, 76, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUATTROCHHI, J. American Nuclear Insurers. 79/05/01. 1p.

7905070582 Confirms increase in liability limit to \$36,000,000 for policies MF-22, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

DOCKETED ITEMS

179

7905140489 Forwards Amend 8 to Indemnity Agreement B-65 per 10CFR140 changes, re increase in liability insurance from \$140 million to \$160 million, effective 790501. Supporting documentation encl.
SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 6pp.

7905190167 Forwards executed Amend 8 to Indemnity Agreement B-65.
TRIMBLE, D. C. Arkansas Power & Light Co. 79/05/10. 3pp.

P. Operating license stage documents & correspondence

7905070491 Responds to 771205 request. Forwards addl info re fracture toughness & potential for lamellar tearing of steam generator & reactor coolant pump support matl. Oversized encl available in Central Files only.
WILLIAMS, D. H. Arkansas Power & Light Co. 78/12/19. 8pp.

7905230840 Requests verification to assure adequacy of onsite distribution of power from offsite circuits. Also requests review of electric power sys to determine if potential exists for violation of General Design Criteria 17.
VASSALLO, D. B. Assistant Director for Light Water Reactors. 79/05/02. 8pp.

7905250210 Summary of 790425 meeting w/C-E re natural circulation capability for C-E plants.
THADANI, A. C. Reactor Systems Branch. 79/05/02. 43pp.

7905250049 Forwards Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability.
STOLZ, J. F. Light Water Reactors Branch 1. REID, R. W. Operating Reactors Branch 4. 79/05/03. 2pp.

--7905250055 Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively, modifying App A & B Tech Specs re mgt organization.
REID, R. W. Operating Reactors Branch 4. 79/05/03. 14pp.

--7905250058 Safety evaluation supporting Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively.
* Operating Reactors Branch 4. 79/05/03. 2pp.

--7905250065 Notice of issuance & availability of Amends 42 & 11 to Licenses DPR-51 & NPF-6, respectively.
REID, R. W. Operating Reactors Branch 4. 79/05/03. 2pp.

7905230087 Forwards summary of 790501 meeting w/C-E re natural circulation conditions in C-E operating reactors.
THADANI, A. C. Reactor Systems Branch. 79/05/09. 1p.

7905170265 Forwards proposed radiological Tech Specs changes & Class III amend fee.
CAVANAUGH, W. Arkansas Power & Light Co. 79/05/10. 2pp.

--7905170267 Proposed radiological Tech Spec changes covering engineered safety feature response time, physics tests liquid & gaseous radwaste treatment sys.
* Arkansas Power & Light Co. 79/05/10. 56pp.

7905300002 Forwards amend to 790417 ltr proposing change to Tech Spec 3.7.1. Seeks to include addl fire barriers in request for temporary relief. Plant can be operated w/o fire dampers in ventilation ducts.
CAVANAUGH, W. Arkansas Power & Light Co. 79/05/18. 4pp.

7905300208 Forwards summary of EDS Nuclear, Inc resolution/documentation of elbow flexibility error which existed in versions of PIGOL piping analysis computer program from Jan-Oct 1969. Review & reanalysis included all work through Dec 1970.
PORTER, F. L. EDS Nuclear, Inc. 79/05/21. 9pp.

--7905300263 Forwards EDS Nuclear, Inc list of BWRs & piping sys which could have been impacted by deficient computer program. GE has no record of reanalysis for Cooper piping sys.
STEPHENS, P. H. General Electric Co., Nuclear Energy Products Div. 79/01/24. 18pp.

G. Inspection reports, IE Bulletins & correspondence

7905010385 Forwards IE Insp Repts 50-313/79-02 & 50-368/79-02 on 790115-0211 & notice of violation.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/03/01. 2pp.

--7905010391 Notice of violation from insp on 790115-0211.
* Region 4, Dallas, Office of the Director. 79/03/01. 1p.

--7905010395 IE Insp Repts 50-313/79-02 & 50-368/79-02 on 790115-0211. Noncompliance noted: failure to prepare weekly rept of overdue maint.
WESTERMAN, T. F. Region 4, Dallas, Reactor Operations Nuclear Support Branch. BOYTER, N. C. Region 4, Dallas, Office of the Director. MADSEN, G. L. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/03/01. 15pp.

7905150079 Forwards IE Circular 79-04, "Loose Locking Nut on Limitorque Valve Operators."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/16. 1p.

7905310387 Responds to IE Bulletin 78-12, "Atypical Weld Matl in Reactor Pressure Vessels." Records search initiated & final rept expected from GE by 790813.
RUETER, D. A. Arkansas Power & Light Co. 79/03/16. 1p.

7905010448 Forwards IE Bulletin 78-128, "Atypical Weld Matl in Reactor Pressure Vessel Welds."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/19. 1p.

7905020441 Forwards IE Circular 79-05, "Moisture Leakage in Stranded Wire Conductors."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/20. 1p.

7905020277 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/23. 1p.

7905020419 Forwards IE Info Notice 79-07, "Rupture of Radwaste Tanks."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/26. 1p.

7905020436 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/Svc Air Sys Used as the Source of Breathing Air."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/28. 1p.

7905140152 Forwards IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp." Licensee action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/30. 1p.

7905150045 Forwards IE Info Notice 79-09, "Spill of Radioactively Contaminated Resin."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/30. 1p.

7905020325 Responds to 790228 ltr & forwards procedures re obtaining emergency relief from Tech Specs.
MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 79/04/05. 2pp.

--7905020343 Clarifies response to 781214 notice of violation. Quorum meetings will be held to review items in Safety Review Committee's purview. Voices concern re ability to obtain emergency Tech Spec mods in absence of quorum.
RUETER, D. A. Arkansas Power & Light Co. 79/02/28. 2pp.

7905140088 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident." Licensee action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/11. 1p.

7905040606 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905070043 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905090096 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI."
SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/16. 1p.

DOCKETED ITEMS

7905030048 Forwards IE Bulletin 79-08, "Failures of SE Type AM-2 Circuit Breaker in Safety-Related Rys." Licensee action required
 807917, K V Region 4, Dallas, Office of the Director 79/04/17.
 1p

7905030340 Forwards IE Bulletin 79-08, "Nuclear Incident at TWH-Suppl." Applicant ADR recommendations and list of IE Bulletins issued in last 12 months wcl
 807917, K V Region 4, Dallas, Office of the Director 79/04/21
 1p

7905030444 Responds to IE Bulletin 79-07 re seismic stress analysis Computer codes specified on Item 1 not used in analysis of safety-related piping
 790503, D C Arkansas Power & Light Co 79/04/24 App

7905100307 Forwards page 12a omitted from original responses to IE Bulletin 79-06B
 790510, D C Arkansas Power & Light Co 79/04/28 1p

---7905100603 Forwards responses to IE Bulletin 79-06B re preliminary chronology of EMD-2 to further increase margin of safety design change is being evaluated for Items in Category III & IV
 790510, D C Arkansas Power & Light Co 79/04/24 19pp

B Periodic operating reports & related correspondence

7905030490 Forwards "Semiannual Environ Monitoring Rpt" for Jul-Dec 1978
 790510, D C Arkansas Power & Light Co 79/04/20 1p

---7905030494 "Semiannual Environ Monitoring Rpt" for Jul-Dec 1978
 * Arkansas Power & Light Co 79/04/20 330pp

7905100307 Forwards monthly operating report for Apr 1979 extracted copy of monthly operating report for Mar 1979 & LER 79-04/04/92-3
 790510, D C Arkansas Power & Light Co 79/05/10 App

---7905100307 Monthly operating report for Apr 1979
 790510, D C Arkansas Power & Light Co 79/05/09 App

---7905100307 LER 79-04/04/92-3 on 790510 diesel generator 1 failed to achieve rated voltage & speed caused by blown fuse in starting circuit for one of two air-charging solenoids LER submitted per Tech Spec 4 B 1.3
 790510, D C Arkansas Power & Light Co 79/05/02 1p

B Repeatable occurrences, LERs & related correspondence

7905040106 Forwards PWD-79-035
 790504, D C Region 4, Dallas, Reactor Operations Nuclear Support 79/04/12 1p

"once again if unusual sequence of events 10 voltage resulting from noise connected causing stress to 1000lb/in sq here 79/05/12 App

790510, D C Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/12 1p

7905030589 Forwards PWD-79-070, V & M
 790510, D C Region 4, Dallas, Office of the Director 79/04/16 1p

7905030538 Forwards PWD-79-076 & V
 790510, D C Region 4, Dallas, Office of the Director 79/04/10 1p

7905100324 Forwards PWD-79-072
 790510, D C Region 4, Dallas, Office of the Director 79/04/24 1p

7905100267 Forwards PWD-79-074A, AB, & AB
 790510, D C Region 4, Dallas, Office of the Director 79/04/26 1p

7905030588 Forwards PWD-79-074E
 790510, D C Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/28 1p

7905100306 Forwards PWD-79-074F, AB, AB, & AB re nuclear incident at TWH
 790510, D C Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/10 1p

7905100372 Forwards LERs 79-025/03L-0, 79-027/03L-0 & 79-028/03L-0
 790510, D C Arkansas Power & Light Co 79/05/01 2pp

---7905100372 LER 79-025/03L-0 on 790503 during review of heating, ventilation & air conditioning installation 22 fire dampers discovered not installed as required caused by installation of fire which established dampers to be installed
 790510, D C Arkansas Power & Light Co 79/05/01 1p

---7905100372 LER 79-027/03L-0 on 790503 high pressure safety injection reactor relief valve 299V-5112 body leaked caused not required Pressure setting verified cap & gaskets across gaskets replaced & 299V-5112 valve returned to svc
 790510, D C Arkansas Power & Light Co 79/05/01 1p

---7905100372 LER 79-028/03L-0 on 790403 emergency feedwater pump 2978 removed from svc caused by leaking leak pump shaft repaired & returned to svc
 790510, D C Arkansas Power & Light Co 79/05/01 1p

7905030490 Forwards PWD-79-074K & AL
 790510, D C Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/05/12 1p

7905100372 Forwards LERs 79-025/03L-0, 79-027/03L-0 & 79-028/03L-0
 790510, D C Arkansas Power & Light Co 79/05/01 1p

---7905100372 LER 79-025/03L-0 on 790415 during Node 2 operation condensate storage tank A dropped below tank level min of 90L caused by inability of makeup plants to produce condensate in next high demand during blowdown testing
 790510, D C Arkansas Power & Light Co 79/05/09 1p

---7905100372 LER 79-027/03L-0 on 790421 while investigating ground problem in battery bank 2555, inverter 2-1/22 switched to alternate source caused by dc supply opening while attempting to locate 2555 ground. Supply reestablished
 790510, D C Arkansas Power & Light Co 79/05/03 1p

---7905100372 LER 79-028/03L-0 on 790510 DCV-1007-2 failed to operate free control valve rendering pump 2 PPA feed to steam generator 2548 inoperable caused by solid white valve actuating 2 CV-1007-2 & valve in closed command
 790510, D C Arkansas Power & Light Co 79/05/12 1p

7905030588 Forwards LER 79-031/03L-0 & 79-032/03L-0
 790510, D C Arkansas Power & Light Co 79/05/17 1p

---7905030588 LER 79-031/03L-0 on 790510 leak found on charging pump A suction pipe at 2-inch coupling to 299V-0254. Caused by vibration leak located in heat affected area of 2-inch universal pipe section replaced
 790510, D C Arkansas Power & Light Co 79/05/17 1p

---7905030588 LER 79-032/03L-0 on 790510 excessive vibration found in 3 emergency diesel engine caused by failure of forward half of upper main bearings due to poor lubrication main bearings caps replaced by rebuilding
 790510, D C Arkansas Power & Light Co 79/05/17 1p

7905030589 Forwards LER 79-033/03L-0
 790510, D C Arkansas Power & Light Co 79/05/28 1p

---7905030589 LER 79-033/03L-0 on 790510 condensate tank discovered at reactor coolant pump 299V-5112 seal cavity pressure sensing line for 299V-5112. Cause undetermined. Affected portion of schedule 80 pipe replaced w/160 pipe
 790510, D C Arkansas Power & Light Co 79/05/28 1p

DOCKET 80-04W WILLIAM B. HUGHES NUCLEAR STATION UNIT 1

A Application/construction stage documents & correspondence

7905030490 Forwards of delay in submitting add'l info re status of outstanding review matters & evaluation of performance of plant design w/MS requirements
 790510, D C Duke Power Co. 79/04/30 1p

DOCKETED ITEMS

181

0. Adjudicatory correspondence

7903010115 Forwards request for Board notification re non-safety-grade equipment to mitigate transients
RCINTD/J F Hearings Division 79/04/02 3pp.

--7903010150 Board notification staff assessment re non-safety-grade equipment to mitigate transients
W000044/D B Assistant Director for Light Water Reactors 79/02/27 3pp

--7903010150 Board notification Request letter on non-safety-grade equipment to mitigate transients RMC info is required
TE000000/N L Assistant Director for Reactor Safety 79/03/16 0pp.

7903020056 Denies motion to reopen safety phases of licensing procedures as sought by Carolina Energy Study Group in 790129 petition & approved by NRC & Duke Power Co 790325 answers.
LA2D/R H Atomic Safety & Licensing Board Panel 79/04/10 14pp

7903030056 Orders issuance of CL to applicant; conditions upon procedural & factual conditions Orders stay of present initial decision until further order after issuance of appeal to NRC re any unresolved generic safety issues
L000000/E A, L000000/C H, LA2D/R H Atomic Safety and Licensing Board Panel. 79/04/18 122pp.

J. Insurance & Indemnity Information

7903050280 Confirms increase in liability limit to \$25,000,000 for policies 79-02-26, 29, 30, 34, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96
R000000/B M Nuclear Atomic Energy Liability Underwriters 79/03/05 0pp

79030140320 Forwards Amend 2 to Indemnity Agreement S-82 per 10CFR40 changes re increase in liability insurance from \$140 million to \$150 million effective 790301 Supporting documentation.
encl
BA12DWH/J Antitrust & Indemnity Group 79/03/01 4pp

0. Inspection reports, IE Bulletins & correspondence

7903030070 Informs that responses to IE Bulletin 79-12 & 79-12A is being prepared by Westinghouse info being gathered from C-E & Westinghouse reactor vessel manufacturers Util's responses will be provided by 791021.
F000000/B O Duke Power Co 79/03/16 1p

7903040177 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY/J P Region 2, Atlanta, Office of the Director. 79/03/23 2pp

7903030037 Forwards IE Info Notice 79-07, "Repairs of Reactor Tanks"
O'REILLY/J P Region 2, Atlanta, Office of the Director 79/03/26 2pp

7903010098 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Dry W/Buc Air Bys Used as Source of Breathing Air."
O'REILLY/J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7903010290 Forwards IE Info Notice 79-09, "Repair of Radioactively Contaminated Resin"
O'REILLY/J P Region 2, Atlanta, Office of the Director 79/03/30 2pp

7903020408 Ack receipt of IE Insp Rept 30-049/79-13 on 790303-03, No proprietary info
F000000/B O Duke Power Co. 79/04/09 1p.

--7903020412 Forwards IE Insp Rept 30-049/79-13 on 790303-03 No non-compliance noted.
LEWIS/R G Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/03/14 2pp

--7903020423 IE Insp Rept 30-049/79-13 on 790303-03, No non-compliance noted. Major areas inspected verification of preoperational test procedures & followup of previous enforcement actions
COTTELL/M T, OYER/J A Region 2, Atlanta, Office of the Director. CANTRELL/F S Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/15 7pp

7903020205 Ack receipt of 790411 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 30-049/79-11 Gaseous monitor info proprietary
MURPHY/C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/11 2pp

--7903020201 Responds to NRC 790304 ltr re violation noted in IE Insp Rept 30-049/79-11 Corrective actions burnt cable was result of molten metal falling on cable after welding
F000000/B O Duke Power Co 79/04/11 1p

--7903020224 Forwards IE Insp Rept 30-049/79-11 on 790303-03 & notice of violation
MURPHY/C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/28 2pp

--7903020209 Notice of violation from Insp on 790303-03
Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/27 1p.

--7903020208 IE Insp Rept 30-049/79-11 on 790303-03 Non-compliance noted safety-related cable had 1-inch diameter burn hole
MURPHY/C E, BRANT/J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/27 4pp

7903020700 Ack receipt of IE Insp Rept 30-049/79-17 on 790303-03 No proprietary info
F000000/B O Duke Power Co 79/04/13 1p

--7903020707 Forwards IE Insp Rept 30-049/79-17 on 790303-03 No non-compliance noted
LEWIS/R G Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/26 2pp

--7903020717 IE Insp Rept 30-049/79-17 on 790303-03 No non-compliance noted Major areas inspected but functional testing activities & followup on unresolved items
COTTELL/M T, COTTELL/M T Region 2, Atlanta, Office of the Director 79/03/22 4pp

7903040174 Forwards IE Bulletin 79-040, "Review of Operational Errors & Bys Missings Identified During TH1 Incident"
O'REILLY/J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7903040201 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TH1 Incident"
O'REILLY/J P Region 2, Atlanta, Office of the Director 79/04/14 1p

7903010335 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
O'REILLY/J P Region 2, Atlanta, Office of the Director 79/04/16 2pp

7903030145 Forwards IE Bulletin 79-09, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Bys" Licensee action required
O'REILLY/J P Region 2, Atlanta, Office of the Director 79/04/17 2pp

7903020440 Forwards IE Bulletin 79-04A, Revision 1, "Review of Operational Errors & Bys Missings Identified During TH1 Incident"
O'REILLY/J P 79/04/10 3p

7903040424 Ack
F000000/B O

7903020173 W
790423 ltr
30-049/79-1
LEWIS/R G
Branch 79

B. Regulatory

7903010203 B
design def
RCINTD/J F

7903020204 P
F000000/B O

DOCKETED ITEMS

--790510202 Deficiency report 60-389/370-79-01 on 790412 during test of pressureless power operated relief valves-one valve stuck in partially open position caused by valve plug binding in valve bonnet recess area Configuration will be revised
* Duke Power Co 79/04/12 3pp

DOCKET 30-370 WILLIAM B. MOORE NUCLEAR STATION UNIT 2

A Application/construction stage documents & correspondence

7905070401 Inform of delay in submitting add info re status of outstanding review matters & evaluation of conformance of plant design w/NSC requirements
PARKER, L D Duke Power Co 79/04/30 1p

B Adjudicatory correspondence

7905010118 Forward request for Board notification re non-safety-grade equipment to mitigate transients
SCINTO, J F Hearings Division 79/04/22 3pp

--7905010156 Board notification staff assessment re non-safety-grade equipment to mitigate transients
VAGHALL, S E Assistant Director for Light Water Reactors 79/03/29 2pp

--7905010196 Board notification recent issue on non-safety-grade equipment to mitigate transients More info is requested
TODD, M L Assistant Director for Reactor Safety 79/03/26 2pp

7905060506 Denies motion to reopen safety phases of licensing procedures as sought by Service Review Study Group 58
7905128 petition & opened by NSC & Duke Power Co 790520
comment
LADD, R M Atomic Safety and Licensing Board Panel 79/04/10 14pp

7905010156 Orders issuance of OL to applicant contingent upon procedural & factual conditions Order stay of present initial decision until further order after issuance of reply to NSC re any unresolved generic safety issues
LAWRENCE, S A HARRIS, C H LADD, R M Atomic Safety and Licensing Board Panel 79/04/18 122pp

J Insurance & indemnity information

7905070202 Confirm increase in liability limit to \$35,000,000 for policies 79-25, 26, 27, 28, 29, 44, 45, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, S M Mutual Atomic Energy Liability Underwriters 79/03/01 1p

7905140308 Forward Amend 2 to indemnity agreement 5-03 per 10258140 changes re increase in liability insurance from \$140 million to \$140 million effective 790501 Supporting documentation and
GALTMAN, J Antitrust & Indemnity Group 79/05/04 4pp

K Inspection reports, IE Bulletins & correspondence

* Refer to IE Bulletin 79-12 & 79-12A is phone info being gathered from C-8
* manufacturers until a response
1000
P Co 79/03/16 1p

* Notice 79-06, "Stress Analysis of
* Atlanta, Office of the Director,

* Notice 79-07, "Explosion of Sediment Tanks"
* Atlanta, Office of the Director

* 79-04A, "Review of Operational Errors and
* During TMI Incident"
* Atlanta, Office of the Director

* 79-08, "Events Related to Boiling
* During TMI Incident"
* Atlanta, Office of the Director,

7905010202 Forward IE Info Notice 79-10, "Nonconforming Pipe Support
* Atlanta, Office of the Director
79/04/16 2pp

7905030146 Forward IE Bulletin 79-09, "Failure of GE Type AB-2
Circuit Breaker in Safety-Related System" Licensee action
required
DRELLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

7905050477 Forward IE Bulletin 79-06A, Revision 1, "Review of
Operational Errors & Events Documented Identified During TMI
Incident"
DRELLY, J P Region 2, Atlanta, Office of the Director
79/04/16 2pp

D Reportable occurrences, LHRs & related correspondence

7905100203 Board notification Westbrook refueling water storage tank
design deficiencies
SCINTO, J Hearings Division 79/03/25 30pp

7905100204 Forward Significant Deficiency Report 60-389-070/79-01
PARKER, L D Duke Power Co 79/04/12 1p

--7905100242 Deficiency report 60-389/370-79-01 on 790412 during test of
pressureless power operated relief valves-one valve stuck in
partially open position caused by valve plug binding in
valve bonnet recess area Configuration will be revised
* Duke Power Co 79/04/12 2pp

DOCKET 30-370 LAGARDE COUNTY STATION UNIT 1

A Application/construction stage documents & correspondence

7905040316 Summary of 790321 meeting of H&I owners group in San
Jose, CA re intermediate plant program issue
ANDERSON, C J Containment Systems Branch 79/04/20 180pp

7905040248 Request add info re soil-structure interaction effect
based on elastic half-space model & finite element model
PARKER, L D Light Water Reactors Branch 5 79/04/16 4pp

7905100208 Summary of 790418 meeting w/Cincinnati Gas & Electric Co,
Long Island Lighting Co & Commonwealth Edison Co re
visitation needs & equipment qualification Presentation mail
and
FELTNER, J A Light Water Reactors Branch 1 79/04/19 15pp

7905020500 Notification of 790315-17 meeting w/Cincinnati Gas &
Electric Co, Long Island Lighting Co, Commonwealth Edison Co
& SE in San Jose, CA to audit NRCB equipment for seismic &
other dynamic qualification
FELTNER, J A Light Water Reactors Branch 1 79/04/23 3pp

7905070700 Summary review of equipment qualification for
static & hydrodynamic loads in response to RB Req'd to E Line
790522 1st Reporting info and
DOL, CERN, L O Commonwealth Edison Co 79/04/25 44pp

7905040482 Notice of intention to develop safety analysis using
existing computer codes. Requests add info.
SELBY, C M Commonwealth Edison Co 79/04/26 1p

7905060204 Clarify status of acquisition of transmission line rights-
of-way Necessary property has been acquired for first of two
x-ns. Final offers have been made to acquire remaining
parcels.
DELBONO, L O Commonwealth Edison Co 79/05/02 1p

7905070021 Notification of 790311 meeting w/ULI in Bethesda, MD re
division open items on containment sys
ROBERTS, A Light Water Reactors Branch 2 79/05/02 3pp

7905140202 Forward IE EPA request to be removed from distribution list
for F&H & amendments effective as of Amend 46
DELBONO, L O Commonwealth Edison Co 79/05/07 3pp

7905060600 Application to use ADRS Code Case 9-240 to exempt certain
piping from hydrodynamic testing
DELBONO, L O Commonwealth Edison Co 79/05/01 2pp

DOCKETED ITEMS

883

7903010045 Informs NRC of erosion in portions of makeup and blowdown water pipelines corridor Plan submitted by Soil Conservation Service will be completed.
BROOK, C. Commonwealth Edison Co. 7/9/83/23 App.

F. Electricity, Medical, emergency & fire protection plans

7903010023 Forwards Revision 4 to physical security plan Plan withheld (see 7903010023)
REED, C. Commonwealth Edison Co. 7/9/83/17 App.

J. Insurance & indemnity information

79030100163 Endorsement 99 to RWEL Policy NF-02
OFBAY, F. Nuclear Energy Liability Insurance Association. 7/9/83/27 App.

79030100497 Confirms increased liability limit to \$124,000,000 for policies NF-1-25, 40, 76, 83, 109, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 183, 187, 188, 189, 190, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 218, & others.
QUANTRODINI, J. American Nuclear Insurance. 7/9/83/01 App.

79030100498 Confirms increase in liability limit to \$40,000,000 for policies NF-1-25, 29, 30, 34, 40, 44, 47, 49, 50, 51, 52, 53, 54, 55, 57, 59, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 80A, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 94, 95 & 96.
REYNOLDS, D. H. Mutual Atomic Energy Liability Underwriters. 7/9/83/01 App.

79030100344 Forwards Amend 1 to Indemnity Agreement 3-86 per SOCFR-143 changes re increase in liability insurance from \$150 million to \$150 million effective 7/9/83. Supporting documentation encl.
BARTMAN, J. Ashbrook & Indemnity Group. 7/9/83/01 App.

N. Utility Final Safety Analysis Report (FSAR) & amendments

79030100162 Forwards Amend 45 to FSAR which responds to 34 second round questions.
REED, C. Commonwealth Edison Co. 7/9/83/25 App.

79030100300 Amend 45 to FSAR Overlaid charts available in General Plant.
REED, C. Commonwealth Edison Co. 7/9/83/25 App.

79030101083 Forwards affidavit for distribution of Amend 45 to FSAR.
DELGROSS, L. O. Commonwealth Edison Co. 7/9/83/04 App.

O. Inspection reports, IE Bulletins & correspondence

79030100304 Forwards IE Insp Rept 50-373/79-11 & 50-374/79-08 on 7903010023 & notice of violation.
PIGARELL, J. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 7/9/83/19 App.

79030100304 Notice of violation from Insp on 7903010023 & 79030100304.
Region 3, Chicago, Office of the Director. 7/9/83/14 App.

79030100307 IE Insp Rept 50-373/79-11 & 50-374/79-08 on 7903010023. Noncompliance noted: failure to maintain min bend radius for cables & failure to take measure to ensure that max cable bend tensions were not exceeded.
BARTLEY, P. A. & HETTLER, J. F. Region 3, Chicago, Office of the Director. 7/9/83/14 App.

79030100309 Forwards IE Insp Rept 50-373/79-04 on 79030100301 & 79030100304 & notice of violation.
HETTLER, J. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 7/9/83/19 App.

79030100309 Notice of violation from Insp on 79030100301 & 79030100304.
Region 3, Chicago, Office of the Director. 7/9/83/14 App.

79030100307 IE Insp Rept 50-373/79-04 on 79030100301 & 79030100304. Noncompliance noted: failure to comply w/10CFR50 App D, Sections 5 & 14.
MAHER, P. A. & DETTMER, R. H. Region 3, Chicago, Office of the Director. 7/9/83/19 App.

79030100483 Forwards response to IE Bulletin 79-12 & 79-13A: "Asplical Weld Metal in Reactor Pressure Vessel"
REED, C. Commonwealth Edison Co. 7/9/83/22 App.

79030100334 Forwards IE Info Notice 79-04: "Stress Analysis of Safety-Related Piping"
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/22 App.

79030100370 Forwards IE Info Notice 79-07: "Rupture of Radwaste Tanks."
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/26 App.

79030100313 Forwards IE Bulletin 79-04: "Review of Operational Errors & Noncompliance Identified During The Incident"
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/11 App.

79030100313 Forwards IE Insp Rept 50-373/79-14 on 790402-03 Noncompliance noted.
PIGARELL, J. G. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 7/9/83/11 App.

79030100313 IE Insp Rept 50-373/79-14 on 790402-03 Noncompliance noted. Major areas inspected: preventive insp work activities & nondestructive examination data review.
WARD, M. S. & DANIELSON, S. H. Region 3, Chicago, Office of the Director. 7/9/83/10 App.

79030100313 Forwards IE Bulletin 79-04A: "Review of Operational Errors & Noncompliance Identified During The Incident"
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/14 App.

79030100334 Forwards IE Bulletin 79-04B: "Review of Operational Errors & Noncompliance Identified During The Incident"
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/14 App.

79030100334 Forwards IE Bulletin 79-08: "Events Related to Rolling Water Pump Station Identified During The Incident"
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/14 App.

79030100380 Forwards IE Info Notice 79-10: "Nonconforming Pipe Support Struts"
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/14 App.

79030100380 Forwards IE Bulletin 79-09: "Failures of 8K Type A4-2 Circuit Breaker in Safety-Related Bays - Licensee action required"
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/17 App.

79030100412 Forwards IE Bulletin 79-03B: "Nuclear Incident at TH1-Suppl 1"
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/21 App.

79030100412 IE Bulletin 79-03B: "Nuclear Incident at TH1-Suppl 1"
Region 3, Chicago, Office of the Director. 7/9/83/21 App.

79030100412 ACRB recommendations re 79030100412. Suggests high priority to be placed on development of safety research & behavior of LWR during abnormal transients.
ACRB - Advisory Committee on Reactor Safeguards. 7/9/83/17 App.

79030100420 Forwards ACRB recommendations re TH1 incident presented on 7/9/83.
FRANK, R. F. ACRB - Advisory Committee on Reactor Safeguards. 7/9/83/17 App.

79030100422 In response to NRC 790418, licensee will 790417 ACRB recommendations apply to all PWRs, but were not intended to require immediate changes. Plant also should be made after study of effects on overall safety. TSC excluded.
CARSON, H. E. ACRB - Advisory Committee on Reactor Safeguards. 7/9/83/20 App.

79030100423 Forwards response to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping. Response indicates analysis of in-transect combination has little effect on pipe strength & equipment support loads.
REED, C. Commonwealth Edison Co. 7/9/83/24 App.

79030100488 Forwards IE Circular 79-07: "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted In Reactor Power Increase."
REFFLER, J. G. Region 3, Chicago, Office of the Director. 7/9/83/02 App.

8. Reportable incidents, LARs & related correspondence

79030100488 Notification that all upper skirt Type 1202 hangers which were galvanized prior to welding are only to be used without Type 1202 hangers.
DELORME, L. O. Commonwealth Edison Co. 7/9/83/23 App.

DOCKETED ITEMS

DOCKET NO. 50-204 LABALLE COUNTY STATIS. UNIT 2

A. Application/construction stage documents & correspondence

790504031 Summary of 790321 meeting of Mark II users group in San Jose, CA re interconnect plant program back
 JONES, C. J. Containment System Branch 79/04/13 12pp.

790504040 Requests add info re soil-structure interaction effect based on elastic half-space model & finite element model
 PARRIS, C. Light Water Reactors Branch 3 79/05/16 4pp

790504050 Summary of 790410 meeting w/ Cincinnati Gas & Electric Co., Long Island Lighting Co. & Commonwealth Edison Co. re vibratory loads & equipment qualification Presentation mail
 FELTHER, A. Light Water Reactors Branch 1 79/05/17 13pp

790504058 Notification of 790413-17 meeting w/ Cincinnati Gas & Electric Co., Long Island Lighting Co., Commonwealth Edison Co. & GE in San Jose, CA to audit NRC equipment for seismic & other dynamic qualifications
 FELTHER, A. Light Water Reactors Branch 1 79/05/23 3pp.

790507023 Summary reevaluation of equipment qualification for seismic & hydrodynamic loads, in response to RB Supp to G Lee
 790522 (re Supporting Info and)
 DELCORRAL, L. O. Commonwealth Edison Co. 79/04/25 4pp

790509082 Notices of intention to develop safety analysis using existing computer codes Request add info
 DELCORRAL, L. O. Commonwealth Edison Co. 79/05/26 1p

790509070 Clarifies status of acquisition of transmission line rights-of-way. Necessary property has been acquired for first of two size final offers have been made to acquire remaining parcels
 DELCORRAL, L. O. Commonwealth Edison Co. 79/05/23 1p.

790529002 Notification of 790511 meeting w/ staff in Bethesda, MD to discuss open items on containment test
 DOUBSHIRE, A. Light Water Reactors Branch 3 79/05/03 2pp

790540032 Forwarded IC EPA request to be removed from distribution list for FGR & accident effective on April 48
 DELCORRAL, L. O. Commonwealth Edison Co. 79/05/09 0pp

790520002 Application to use AWC Code Case K-240 to exempt certain piping from hydrostatic testing
 DELCORRAL, L. O. Commonwealth Edison Co. 79/03/23 3pp

790510041 Defers ABC of erosion on portions of makeup & blowdown water pipeline corridor. Plan submitted by Mail Conservation Soc will be implemented
 REDUCO, Commonwealth Edison Co. 79/05/20 2pp

F. Security: medical, emergency & fire protection plans

790510023 Forwarded Revision 4 to physical security plan. Plan withheld (ref 10CFR 7901)
 REDUCO, Commonwealth Edison Co. 79/04/17 1p

G. Insurance & indemnity information

790510014 Endorsement 99 to MARU Policy HP-52
 SERRA, T. Nuclear Energy Liability Insurance Association 79/03/27 1p

790507047 Confirms increased liability limit to \$124,000,000 for policies HP-1, 25, 43, 36, 83, 100, 111, 140, 144, 181, 161, 164, 170, 173, 174, 175, 176, 180, 181, 182, 183, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 205, 207, 208, 210, 213, 214, 215 & others
 QUATROCHI, J. American Nuclear Insurers. 79/05/01 1p.

790507082 Confirms increase in liability limit to \$34,000,000 for policies HP-22, 23, 24, 35, 39, 44, 45, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96.
 REDUCO, T. M. Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

790540044 Forwarded Amend 1 to Indemnity Agreement 9-58 per 10CFR 140 changes increase in liability insurance from \$140 million to \$140 million effective 790501 Reporting documentation and
 SMLTERR, J. Arbitrator & Indemnity Group 79/05/01. App.

H. Safety Final Safety Analysis Report (FSAR) & amendments

790503032 Forwarded Amend 45 to FSAR which responds to 24 second new questions
 REDUCO, Commonwealth Edison Co. 79/04/20 1p

790503032 Amend 45 to FSAR Overview charts available in Central Files
 Commonwealth Edison Co. 79/04/25 24pp

790510035 Forwarded Affidavit for distribution of Amend 45 to FSAR
 DELCORRAL, L. O. Commonwealth Edison Co. 79/05/04 3pp

I. Inspection reports, IE Bulletins & correspondence

790500004 Forwarded IE Inspect 50-323/79-11 & 50-374/79-00 on

790501-02 & notice of violation
 PIERRELLI, J. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/13 2pp

790503041 Notice of violation from Inspect 790221-23.
 Region 3, Chicago, Office of the Director 79/05/14 2pp

790503004 IE Inspect 50-372/79-11 & 50-374/79-00 on 790221-23 Noncompliance noted. Failure to maintain air based radon for cables & failure to take measures to assure that net cable pull tensions were not exceeded
 SERRA, T. A. HEIDLER, J. W. S. S. Region 3, Chicago, Office of the Director 79/05/14 4pp

790503041 Forwarded response to IE Bulletin 79-12 & 79-12b. "Atypical Weld Rats in Reactor Pressure Vessel Weld"
 REDUCO, Commonwealth Edison Co. 79/03/22 10pp

790510026 Forwarded IE Info Notice 79-04. "Stress Analysis of Safety-Related Piping"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/03/23 1p.

790503030 Forwarded IE Info Notice 79-07. "Failure of Rodent Traps"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/03/23 1p.

790503033 Forwarded IE Bulletin 79-05. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

790503034 Forwarded IE Bulletin 79-06. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

790504034 Forwarded IE Bulletin 79-08. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

790504034 Forwarded IE Bulletin 79-08. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

790504034 Forwarded IE Bulletin 79-08. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

790504034 Forwarded IE Bulletin 79-08. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

790504034 Forwarded IE Bulletin 79-08. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

790504034 Forwarded IE Bulletin 79-08. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

790504034 Forwarded IE Bulletin 79-08. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

790504034 Forwarded IE Bulletin 79-08. "Review of Operational Errors & Misalignments Identified During TMI Incident"
 KOFFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p

DOCKETED ITEMS

--PROPOSED TO ACRS recommendations re 790022 incident at TRF, suggest
priority be placed on development of safety research on
behavior of LWRs during anomalous transients.
o ACRS - Advisory Committee on Reactor Safeguards 79/04/07
o

--P055040301 Forwarded ACRB recommendations re TMS incident, presented on 7/20/17.
FRANJE, R F ACRB - Advisory Committee on Reactor Safeguards
7/20/17/10 is.

--7905040025 in response to NRC 790408 ltr. states all 790417 ACRR recommendations apply to all PWRs, but were not intended to require immediate changes. Plant made should be made after study of effects on overall safety. TMI included CARBONEL M 1 ACRR = Advisory Committee on Reactor Safeguards 79/04/00 Doc

7408244633 Forward responses to IE Bulletin 74-07 requesting info re seismic analysis of safety-related piping. Reanalysis indicates method of (intramural) combination has little effect on pipe stresses & equipment support loads.
 REED-C Commonwealth Edison Co. 75/04/24 4pp.

7703140480 Forwards IE Circular 79-07. "Unsuspected Speed Increase of
Reactor Recirculation Water Generator Not Resulted in
Reactor Power Increase"
KOPPLER, J D Sagien D. Chicago: Office of the Director 79/05/02
1a.

§ Reportable occurrences, LREs & related correspondence

7903304035 Notifies that all super strut Type 1202 hangers which were salvaged prior to welding are now to same defect reported in 790409 1tr Complete work will be performed on Type 1202 hangers
DCL/EDP/CE-LD Commonwealth Edison Co 79/03/20. See

ROCKET 80-875 NUCLEAR EXAMINATION REACTOR

© 2004 Blackwell Publishing Ltd, *Journal of Internal Medicine* 255: 103–110

7908160320 Forwards Amend 15 to Indemnity Agreement B-12 per IDCR140
changes re increases from \$140 million to \$160 million.
effective 790301 Supporting documentation encl
SALTIRAG J. Arbitrator & Indemnity Group 79/05/01 Spp

* Periodic operating reports & related correspondence

950030910 Forwards "L-65 Reactor, Annual Operations for 1978" &
"Energy Sys Group Environ Monitoring & Facility Effluent
Annual Rep, 1978"
BRINDE, C. J. H. Rockwell International Corp 79/05/04 Is.

~7908080510 "L-05 Reactor Annual Operations for 1970"
 DAWKINS V.A. Reactor International Corp 79/02/08. 2pg.

--7405000017 "Energy Sys Group Environ Monitoring & Facility Effluent
Annual Rep, 1978"
MOORE, J D. Rockwell International Corp. E00-74-7 74/04/00
22a

ROCKET RD-376 NORTH COAST MAC PLANT

Abstract

790310013 Forwards "Site Safety Evaluation Rpt" for early site review of Isola site in Puerto Rico 584 is suitable for plant provided 0.45 g seismic design level is used & outstanding items in rpt are resolved.
NDORLE, V A. Assistant Director for Environmental Projects.
79/04/27. 1p.

--790510016 "Bite Safety Evaluation Rept" re determination of suitability of isolate site for eventual cresh of plant by Puerto Rican Water Resources Authority.
Office of Nuclear Reactor Regulation. HUR03-0041 79/04/03.
4 Dec.

FOUO/NOFORN Forwards site safety evaluation rept review by ACSS.
W/o Atchl.
GALLAGHER, J.L. Environmental Projects Branch 1 79/04/87 289

--905150132 Notice of availability of site safety evaluation report for
facility
SMALLARD-S.L. Environmental Projects Branch 1 79/04/27 Rps.

© Adjudicatory competence.

7906246759 Forwards status report of 790430 on developments in Puerto Rico concerning facility application
 AXELRAD, H. Louenstein, Newman, Reitz, Axelrad & Tall 20/06/79 14

--790840970 Status rept by Puerto Rico Water Resources Authority re
Pending applications of 790435 Electric Power Sys will
issue rept by 14th Reg Certificate of Rec smth.
ANLEARD, H Lewenstein-Hausman-Reis, Anleard & Tall 79/04/30 3p

DOCKET 26-282 WATERFORD GENERATING STATION, UNIT 2

A. Haidichaidou et al. / *Journal of Macroeconomics* 32 (2010) 103–115

792508486 Forwards NUREG-0531, "Investigation & Evaluation of Bypass Generation Cracking in Piping of LWR Plants" & notice of issuance & availability. M/o encl
UNCLASSIFIED Assistant Director Per Light Water Reactors
79/02/02. Qsa

7905140516 Forwarded summary of major milestones re OL application
safety review Review of schedule concludes 810920 is
available date for issuance of OL
8070.8 8 Division of Project Management 79/08/18 Gen

790100112 Requests and info re complete review of PSAR Complete
responses should be provided by 790720 in order to maintain
review schedule
BMR:RL Light Water Reactors Branch 4 79/04/26 Y600

C. Utility Environmental Report (UER), appendices & correspondence.

7905250000 Forward request for add info to complete environ review
 Addenda should consist of sequentially numbered revisions
 to environ rpt
 BALLARD, R L Environmental Projects Branch 1 79/05/02 29u

D. Adjudicators correspondence

7938290000 Cancellation of LA Consumers League Amends original petition
Affidavit of L. Samuel & Certificate of Notary
SRVING L M Louisiana Consumer's League, Inc 79/04/04 Doc

7935970151 Contention of Save Our Wetlands, Inc & Oystershell Alliance.
Inc. Amended original petition Affidavits of N Haskell & J
King & Certificate of Dvc seal
PORTANTA, L. Fontana, L. JORDAN, L. L. Gillespie & Jones 79/04/11
14pp

7905250040 Notices of appearance on behalf of LA Power & Light Co
Certificate of Inc and
TROWER/DOR-Q F ; YUSPEH-A.R. (Shaw, Pittman, Petts, & Frowbridge
79/04/03 App

79052206037 Notice of appearance on behalf of LA Power & Light Co
Certificate of Evt encl.
STEVENSON-D-4 M. Moore & Lennox 79/04/17 3pg

793229049 Suppl to petition to intervene. Success WRC positions re
contentions of Save Our Wetlands, Inc & Dymersheim Alliance.
Inc certificate of Rev and
McGOWEN H.J. Branch 1. 28/04/28. 2000.

790029004: Discusses 790426 prehearing conference interveners' Contentions 2,3,4 & 6 were admitted NRC will file submission re Contentions 5 & 7 by 790001.
NRC, D. J. Abner Sattelo and Lisaanne Reed Esal. 7905/09 2

E. Essential information

7906070166 Forward registration statement filed by LA Power & Light Co
on 7/9/02 4/0 encl.
8/9/02 4/0 Securities & Exchange Commission 7906070166

7925110260 Forwards "Annual Financial Rept 1970 "
AMERILL, D L. Louisiana Power & Light Co. 79/04/20. 1a

--7903030262 "Annual Financial Rpt 1978"
 * Louisiana Power & Light Co 79/03/09 19xx

B. Utility Final Safety Analysis Report (USAR) & append

7905170228 Forwards Amend 3 to FEAR
ADMITL, D.L. Louisiana Power & Light Co. 79/05/10 Rec

DOCKETED ITEMS

--7508170201 Amdt 3 to FRAM
AMMUL-01, Louisiana Power & Light Co 29/08/10 800w

7905260399 Certificate of Bvz Per Amend 3 to P&L
of Louisiana Power & Light Co. 79/05/83. 1c

② Inspection reports, IE Bulletins & correspondence

7903010276 Forwards SE Info Notice 79-06, "Stress Analysis of
Gefely-Related Piping"
GEFFRIT, R W Region 4, Dallas, Office of the Director 79/03/20
1a

790559541 Forwards IE Insp Rept 50-082/79-03 on 790226-0099 & notice
of violation
SIDELW C Region 4 Dallas Reactor Construction & Engineering
Support Branch 79/03/28 Doc

==7808190544 Notice of violation from Insp on 790226-0304
* Region 4, Dallas, Office of the Director 79/03/27 Rev

--7908130555 IE Insp Sept 88-002/77-03 on 790024-0004 Noncompliance
noted improper mounting of Glass IE 4150 volt switchgear &
failure to follow approved drawings
STEWART, C. GILBERT, L. D. MARTIN, E. Region 4- Dallas- Office
of the Director 29/03/87 20

PROLOGUE: Foreword DE Bulletin 79-03A. "Nuclear Incident at
the - Suppl."
SECRET, R. V. Region 4, Dallas, Office of the Director,
to

7903040496 Forwarded IE Bulletin 79-048, "Review of Operational Errors &
Sgs Misalignments Identified During TMI Incident"
SEYFERT, R. V. Region 4, Dallas, Office of the Director 79/04/14
to

790040619 Forwarded IE Bulletin 79-06. "Events Relevant to Seiling
Major Power Reactors Identified During TMI Incident"
SEVREIT-K V. Region 4. Dallas. Office of the Director 79/04/14
1a

7908070066 Forwarded IE Bulletin T9-07. "Seismic Stress Analysis of Safety-Related Piping" - Licensee action required.
BRYFRET.K.V Region 4: Dallas Office of the Director 79/04/86
1a

79CDD10425 Forward: RE info Notice 79-10, "Nonconforming Pipe Supports
Struts"
SEVRET-K V Region 4- Dallas, Office of the Director 79/04/50
1a

7906090101 Forward: supp: to IE Bulletin 79-05A, "Hacienda Incident at
THI."
REVIEWIT:K W. Region 4- Dallas: Office of the Director 79/04/38
1a.

770303074 Forwards IC Bulletin 79-09, "Failures of GE Type AA-2 Circuit Breaker in Safety-Related Sys - Licensee action required."
NEWELL, R. M. Senior R. Dallas, Office of the Director. 28/04/79

B. Replicable differences; LCRs & related correspondence

PHO000134 Forwarded PHO-79-67H, I, J & K.
SEYFERT, K V Region 4, Dallas, Office of the Director 79/04/DA
1P.

7906000113 Forwards PHO-39-43L, R. H. & P.
SEIDLE, M. C. Region 4; Dallas, Reactor Construction & Engineering
Support Branch 79/04/128 10

• **Reader Construction & Engineering**

Faculty of Construction & Engineering

Water Conservation & Reclamation

various dimensions of the relationship

7903000066 Forwards FWD-79-67U & V
BRIDLE, M C. Region 4, Dallas. Reactor Construction & Engineering
Research Branch. 79/04/1A. 4P

74080000280 Forward: PAC-74-ATM
MIDDLEMAN Region 4, Dallas, Reactor Construction & Engineering
Support Branch 74/04/57 to

7905620524 Forwards FND-79-67AA
BIDDLE, M C. Region 4, Dallas. Reactor Construction & Engineering
Research Report. 78-15-6235. 10

7503000311 Forwards FMD-79-67NS.AC & AD
DETLE-M C Region 4, Dallas, Reactor Construction & Engineering
Research Branch 75106/03 1c

7903040379 Forwards FMD-79-67AE.
 #215LEW C Region 4, Dallas, Reactor Construction & Engineering
 Manager, Reactor 790403040379

7702670188 Forwards PMD-79-57AP & AD
BRIDLE, M C Region 4, Dallas, Research Construction & Engineering
Geosynth Research, TX/08/07, 1a

7905010222 Forwards FNG-79-5786.A5 & A4 1
MIDDLEBURY College Region 4: Sales, Reaction Construction & Engineering
Research Branch 7905010222 to

7903240374 Forwards FWD-79-6788, 6 AL
BRIDLE-W C. Region 8: Dallas, Reaction Construction & Engineering
Daguerre Branch 78/03505 6a

7908180264 Forward Significant Efficiency Rept 81 re switchgear
Greater position switch operator defect
ADWHL-01, Inspection Report & Sign Off, 79081810, 14

--990505233 Significant Deficiency Rest 11 switchgear breaker position switch operator defect Switch may become bent due to interference w/circuit breaker New switch operator designed to be more rigid & protected by guide

BRANTY,P.A. SANDFORTH,B. COTTELL,D.J. Louisiana Power & Light Co. 79/03/88

7709130408 Forwards Interim Rept 12 no significant const deficiency
ASWD.L.S.C. Louisiana Power & Light Co 79/09/10 00

==7909180465 Interim Rept 12 of significant const deficiency on 790406
McJannet Corp notified Elanco Mvcs, Inc that page fittings
bearing 164 identification 98739 were sub; to math failures.
All installed fittings identified & tested
GRONON, J., KUSHNER, R J., COSTELLO, J Louisiana Power & Light Co
79/05/18 Sys

--Y403135417 Summarizes 790409 discussion w/RC Housely Rehow cracking identified in lot M571V Recall program initiated Six albums from defective lot found at facility. After testing, defective fittings will be replaced

T. Hearing transcripts on noncontingent matters

790594666 Transcript of 790426 hearing in New Orleans, LA. Pp. 1-111
WOLF, B. JORDAN, M.; FORDMAN, H. Atomic Safety and Licensing Board
Panel. 790426. 132pp.

DOCKET NO-007 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

A. Application/construction class documents & correspondence

790304031a Summary of 790225i meeting of Mark II experts group in G
Jesse CA re intermediate plant program tasks.
ANDREWS, C J. Containment Systems Branch. 29/04/79 150w

7905000224 Notification of 790505-04 meeting w/utill at Gasquetenne
site in RA to discuss const schedule. Agenda encl
MINER.B Links Meter Research Branch 2 791006/10 400.

9903260006 Informs of possible six month delay in DL review schedule
from WHI
HEARD, J. 11400 Huber, Spokane, Spokan 5, 99205-000, Sp.

790509G346 Notices of plans to replace reactor pressure vessel recirculation nozzle end- and thermal sleeves. Mid sized & increasing reliability & protection against intergranular stress corrosion cracking
CURTIS, H.W. Pennsylvania Power & Light Co. 79/05/04 2p

7905090363 Forwards affidavit of svu for Amend 9 to OL application
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/05/07 2pp

7905100300 Discusses 781103 deficiency report re BSE sgs standing diesel generator safety. Items to be evaluated & results transmitted by 790525. 79051003 report
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/05/11 2pp

7905240074 Like EPA-approved herbicides used along transmission lines to replace suspended herbicide 2,4,5-T
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/05/21 1p

F. Security, medical, emergency & fire protection plans

7905180794 Forwards request for add info re physical security plan to complete review of OL application Reel withheld
(ref 100P82.790)
PERRY-G.D. Light Water Reactors Branch 3 79/04/13 2pp

G. Adjudicatory correspondence

7905290186 Investigation completed re allegations made at 790120 prehearing conference by MR. Cress. Investigation did not substantiate allegations.
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/03/29 1p

7905240081 Daily transcript of hearings will be loaned to intervenors whenever possible as aid in preparation of case
CUTRIS-H.W. Branch 3 79/04/10 2pp

7905240025 Requests info re procedure to make limited appearance at hearing
RECHTVE-E Affiliation Unknown 79/04/15 1p

K. Utility Final Safety Analysis Report (FSAR) & amendments

7905050242 Forwards Amend 9 to application for OL submitted as Revision 7 to FSAR
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/04/03 124pp

7905180224 Forwards Amend 10 to OL application containing Revision 8 to FSAR Amend withheld (ref 100P82.790)
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/05/15 2pp

L. Inspection reports, IE Bulletins & correspondence

7905100428 Forwards IE Insp Rept 30-387/79-07 on 790222 Re noncompliance noted
CARLSON-R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/19 2pp

7905100430 IE Insp Rept 30-387/79-07 on 790222 Re noncompliance noted
Major areas inspected power generator control complex & areas containing electrical/instrumentation equipment
Installations
MOLTAU-P.B. Region 1, Philadelphia, Office of the Director
EDMISTER-S.D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/16 2pp

7905100434 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping."
CARLSON-R.T. Region 1, Philadelphia, Office of the Director 79/03/23 1p

7905040140 Ack receipt of 790519 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-387/79-02
CARLSON-R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/06 1p

7905040146 Responds to NRC 790220 ltr re violations noted in IE Insp Rept 30-387/79-02. Corrective action plan transmitted with corrective and/or corrective structural steel numbers for are strikes
BAROLA-R. Pennsylvania Power & Light Co. 79/02/19 2pp

7905040149 Forwards IE Insp Rept 30-387/79-02 on 790130-0202 & notice of violations.
CARLSON-R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/02/20 2pp

7905040153 Notice of violation from Insp on 790130-0202
Region 1, Philadelphia, Office of the Director. 79/02/20 1p

7905050405 IE Insp Rept 30-387/79-02 on 790130-0202 Noncompliance noted
Failure to control structural steel are strikes
MCNEARY-T.R. & PABAND-A.R. Region 1, Philadelphia, Office of the Director
TRIPP-L. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/02/16 2pp

7905030083 Forwards IE Bulletin 79-04, "Review of Operational Errors & System Malfunctions Identified During TMI Incident"
08105.8.H Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905030402 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping"
08105.8.H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040091 Forwards IE Bulletin 79-08, "Review of Operational Errors & System Malfunctions Identified During TMI Incident"
08105.8.H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040097 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Reactors Identified During TMI Incident"
08105.8.H Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030093 Forwards IE Bulletin 79-09, "Failures of DE Type A-2 Circuit Breaker in Safety-Related Bays"
08105.8.H Region 1, Philadelphia, Office of the Director 79/04/17 1p

7905030094 Forwards IE Bulletin 79-04, Revision 1, "Review of Operational Errors & System Malfunctions Identified During TMI Incident"
08105.8.H Region 1, Philadelphia, Office of the Director 79/04/10 1p

R. Periodic operating reports & related correspondence

7905040094 Forwards annual environ rept, "Bound Level Measurements Near Plant Site Corral 1978" prepared by Bolt Beranek & Newman Inc.
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/05/01 1p

7905040094 "Bound Level Measurements Near Plant Site Corral 1978," annual environ rept, cont'd data progress rept prepared by Bolt Beranek & Newman Inc.
BARBER-J.D. & MOORE-E.F. Pennsylvania Power & Light Co. 79/05/01 23pp

S. Reportable occurrences, LESs & related correspondence

7905030129 Ack receipt of 790303 interim deficiency report re J-WH solenoid valves.
CARLSON-R.T. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/10 1p

7905030149 Confirms info re potentially reportable deficiency in circle seal Model J-458 solenoid valves ineffective diodes
Valves have been removed from installed locations & are in package warehouse awaiting return to vendor
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/05/23 2pp

7905040149 Forwards corrected page 1 of PLR-352 which includes missing date of 790303
BAROLA-R. Pennsylvania Power & Light Co. 79/05/11 2pp

7905050401 Updates deficiency report re Circle Seal Model J-458 solenoid valves. Defective valves presently controlled per Benthall procedure. Final rept to be submitted by 790505.
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/05/22 2pp

DOCKET 30-388 SUSQUEHANNA NUCLEAR ELECTRIC STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905040216 Summary of 790222 meeting of Part II items presented in San Jose, CA re information plant program tests
ANDERSON-C.J. Containment Systems Branch 79/04/13 150pp

7905050224 Notification of 790518 meeting w/with Susquehanna
San Jose, CA re discuss cost schedule agenda encl
MILNER-R. Light Water Reactors Branch 3 79/04/14 1p

7905040226 Inform of possible six month delay in OL review schedule from NRC.
MILNER-R. Light Water Reactors Branch 3 79/05/03 2pp

7905050064 Notices of plans to replace reactor pressure vessel
with 18 18 to discuss cost schedule agenda encl
Increasing reliability & protection against intergranular stress corrosion cracking.
CUTRIS-H.W. Pennsylvania Power & Light Co. 79/05/04 2pp

79031903265 Forwards affidavit of svc for Amend 9 to DL application
CURTIS, H. W. Pennsylvania Power & Light Co. 79/05/07. 2pp

7903110300 Discusses 7901103 deficiency report re BSE sys standby diesel
generator safety impact to be evaluated & results
transmitted by 790323 N7901103 report
CURTIS, H. W. Pennsylvania Power & Light Co. 79/05/11. 2pp

7903240504 Lists EPA-approved herbicides used along transmission lines
to regulate vegetation herbicide S-4-S-T
CURTIS, H. W. Pennsylvania Power & Light Co. 79/05/21. 1p

F. Security, medical, emergency & fire protection plans

7903190394 Forwards request for AME info re physical security plan to
complete review of DL application S-4-S-T
ref 10CFR2 7901
PARKER, D. Light Water Reactors Branch 3 79/04/13. 2pp

G. Regulatory correspondence

7903230104 Investigation completed re allegations made at 790106
prehearing conference by Mr. Greay. Investigation did not
substantiate allegations
CURTIS, H. W. Pennsylvania Power & Light Co. 79/03/29. 1p

7903240301 Daily transcript of hearings will be loaned to interviewers
wherever possible as aid in preparation of case
CUTCHIN, J. H. Branch 3 79/04/10. 2pp

7903240425 Requests info re procedure to make limited appearance at
hearing
MENEZES, E. Affiliation Unknown 79/04/15. 1p

H. Utility Final Safety Analysis Report (FSAR) & amendments

7903030340 Forwards Amend 9 to application for DL submitted as Revision
7 to FSAR
CURTIS, H. W. Pennsylvania Power & Light Co. 79/04/03. 12pp

7903190324 Forwards Amend 10 to DL application containing Revision 8 to
FSAR Amend withdrawn (ref 10CFR2 7901)
CURTIS, H. W. Pennsylvania Power & Light Co. 79/05/11. 2pp

I. Inspection reports, IE Bulletins & correspondence

7903060104 Forwards IE Bulletin 79-04, "Stress Analysis of
Safety-Related Piping"
ORLEN, S. H. Region 1, Philadelphia, Office of the Director
79/03/22. 1p

7903090905 Forwards IE Bulletin 79-04, "Review of Operational Errors &
Sys Missions Identified During TH1 Incident"
ORLEN, S. H. Region 1, Philadelphia, Office of the Director
79/04/11. 1p

7903030402 Forwards IE Bulletin 79-07, "Relistic Stress Analysis of
Safety-Related Piping - Licensee action required"
ORLEN, S. H. Region 1, Philadelphia, Office of the Director
79/04/14. 1p

7903040401 Forwards IE Bulletin 79-04B, "Review of Operational Errors &
Sys Missions Identified During TH1 Incident"
ORLEN, S. H. Region 1, Philadelphia, Office of the Director
79/04/14. 1p

7903040304 Forwards IE Bulletin 79-06, "Events Relevant to Bolting
Major Power Reactors Identified During TH1 Incident"
ORLEN, S. H. Region 1, Philadelphia, Office of the Director
79/04/14. 1p

7903230300 Forwards IE Bulletin 79-06, "Failures of GE Type AM-2
Circuit Breaker in Safety-Related Sys - Licensee action
required"
ORLEN, S. H. Region 1, Philadelphia, Office of the Director
79/04/17. 1p

7903030314 Forwards IE Bulletin 79-04B, Revision 1, "Review of
Operational Errors & Sys Missions Identified During TH1
Incident"
ORLEN, S. H. Region 1, Philadelphia, Office of the Director
79/04/18. 1p

R. Periodic operating reports & related correspondence

7903040504 Forwards annual environ report, "Ground Level Measurements Near
Plant Site Genl 1978" prepared by
Bolt Beranek & Newman
Inc.
CURTIS, H. W. Pennsylvania Power & Light Co. 79/05/01. 1p

---7903040304 "Ground Level Measurements Near Plant Site Coast 1978,"
annual environ report not progress report prepared by
Bolt Beranek & Newman Inc.
BARNES, J. D. & MOORE, E. F. Pennsylvania Power & Light Co. 79/03/21
2pp

S. Reportable occurrences, LLRs & related correspondence

7903160424 Forwards corrected page 1 of ALA-302 which includes missing
date of 790307
BARTON, H. C. Pennsylvania Power & Light Co. 79/05/11. 2pp.

7903250401 Updates deficiency report re Circle Seal Model J-670 solenoid
valves. Defective valves presently controlled per Bachel
procedure. Final report to be submitted by 790701
CURTIS, H. W. Pennsylvania Power & Light Co. 79/05/22. 2pp.

DOCKET NO-399 ST. LUCIE PLANT, UNIT 2

G. Administrative correspondence

7903240307 Response by still to 790301 ALAS memo & order re
release rates, concentrations & health effects Certificate
of Svc and
BARNES, J. D. & MOORE, E. F. Pennsylvania Power & Light Co. 79/04/30. 2pp

7903100402 Notifies new info re fuel blockage model for 20C8 is
presently being evaluated. Review will be forwarded upon
completion
PATON, H. D. Branch 4 79/04/11. 1p

7903110416 Response to ALAS-307 re radon emissions & de minimus theory
from Perkins received Certificate of Svc and
SCHEIDT, J. H. Hearings Division 79/04/11. 8pp

7903140519 Response to 790404 brief of Philadelphia Electric Co. PB040 &
Atlantic City (AC) Electric Co. re de minimus theory.
Certificate of Svc and
KOPF, S. L. C. Citizens for Safe Environment 79/04/11. 8pp.

7903190125 Forwards AME report "Inquiry into Allegation of Employee
Misconduct by Restricting Investigation to Determine
Reliability of Power Grid Serving St. Lucie"
SCHEIDT, J. H. Branch 3 79/04/11. 1p

---7903150130 "Inquiry into Allegation of Employee Misconduct by
Restricting Investigation to Determine Reliability
of Power Grid Serving St. Lucie."
METSINGER, T. J. Office of Inspector & Auditor. 78/04/30. 88pp

7903100126 Notifies continuance will be needed for preparation of info
re ALAS-307 vital witness is currently assigned to TH1-2,
but can return 790501. Present estimate for submittal date
is 790615 or later
TOMMELT, STE. J. Branch 4. 79/04/12. 2pp

7903100309 Forwards action for reconsideration of 790405 ALAS-307 or
scheduling of prehearing conference. Explains & expresses
Basis of ALAS decision re manner of proceeding in captioned matter
REIS, H. F. Lewinstein, Neuman, Reiss, Aschard & Toll 79/04/14. 2pp

---7903100511 Moves for reconsideration of 790405 ALAS-307 or scheduling
prehearing conference. Refers to accompanying memo containing
justification Certificate of Svc and
REIS, H. F. Lewinstein, Neuman, Reiss, Aschard & Toll. 79/04/19. 2pp

---7903100511 Supports 790405 motion for reconsideration of ALAS-307 or
scheduling prehearing conference. Certificate of Svc and
REIS, H. F. Lewinstein, Neuman, Reiss, Aschard & Toll. 79/04/19. 2pp

7903240514 Forwards Draft Reg Guide 1,XXX, "Lightning Protection for
Maritime Power Plants - A/E and
PATON, H. D. Branch 4. 79/04/17. 1p.

DOCKETED ITEMS

189

7903290209 Motion by intervenors for initiation of discovery procedures & submission of interrogatories to still re utility electrical grid stability & emergency power vs Certificate of Rvc and
HODGEN, R. H. Hodder, R. H. 79/04/17 5pp

7903290003 Notices that taken to AMLAG from RH Hodder, counsel for ALAG-937
HODGEN, R. H. Atomic Safety and Licensing Appeal Panel 79/04/18 5pp

7903290070 Requests denial of intervenors' 790417 motion to permit discovery Certificate of Rvc and
COLL, M. A. Stast, Hector & Davis 79/04/10 5pp

7903400332 Notice of consolidation of five intervenor groups re radon detection issue Parties have until 790325 to which to file for summary disposition
HODGEN, R. H. Atomic Safety and Licensing Appeal Panel 79/04/25 12pp

7903290005 Extends until 790517 time for Commission review of portion of ALAG-937 re steam generator tubes
CHILL, B. J. Office of the Secretary of the Commission 79/03/08 1p

J Insurance and Liability Information

7903290497 CasFire's Increased Liability limit to \$124,000,000 for policies No. 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, G. H. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7903290392 Confirms increase in liability limit to \$26,000,000 for policies No. 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, G. H. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

7903290309 Forwards Endorsement 31 to NELA Policy No. 227
FISHER, J. Marsh & McLennan, H & Nuclear Consultants, Inc. Div 79/05/04 5pp

7903290311 Forwards Endorsement 32 to NELA Policy No. 227
FISHER, J. Marsh & McLennan, H & Nuclear Consultants, Inc. Div 79/05/04 5pp

K Antitrust correspondence

7903400332 Forwards add info re licensing preparation W/O encl
KORNO, G. J. Anti-Trust Division 79/03/27 1p

7903290102 Supplemental discovery rulings as result of parties' memo responding to 790309 memo and order Parties may negotiate and of prehearing schedule First Intervenor report re progress of discovery will be due 790301
SHEP, T. M. Atomic Safety and Licensing Board Panel 79/03/28 12pp

7903290322 Responds to 790328 & 790402 motions filed by PL Cities to initiate evidentiary hearing in response to JSC 790327 order Certificate of Rvc and
GOMEZ, L. Anti-Trust Division 79/04/17 5pp

7903400353 Joint action of still & PL Cities for suspension of discovery procedures to permit settlement discussions to be pursued Certificate of Rvc and
JAMES, R. A., SUTMAN, D., Seigel & Macdonald BROWNIGHT, J. A. Luenstein-Hadden, Bels, Austad & Toll 79/04/25 5pp

7903290794 Grants 790420 joint motion by Applicant & PL Cities seeking delay in discovery until 790801
SMITH, T. M. Atomic Safety and Licensing Board Panel 79/04/22 1p

L Inspection reports, IE Bulletins & correspondence

7903290352 Forwards IE Insp Rpt 80-289/79-02 as 790321-0002 No noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/13 2pp

7903290356 IE Insp Rpt 80-289/79-02 as 790321-0002 No noncompliance noted, Major areas inspected: concrete procedures, specs & records & concrete placement & backfill operations
JONES, J. L. & SEVANT, J. G. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/13 4pp

7903290355 Forwards IE Insp Rpt 80-289/79-02 as 790321-0002 No noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/13 2pp

7903290355 IE Insp Rpt 80-289/79-02 as 790321-0002 No noncompliance noted, Major areas inspected: reactor vessel internals procedures, work observation & quality records, equipment storage, & QA records storage
AND, J. P., DRYGAL, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/13 3pp

7903290357 Forwards IE Insp Rpt 80-289/79-04 as 790327-0002 No noncompliance noted
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/21 2pp

7903290355 IE Insp Rpt 80-289/79-04 as 790327-0002 No noncompliance noted, Major areas inspected: concrete lab-inlets structure, concrete placement, weld repair to containment vessel & site SA work
WRIGHT, R. M., GOUZE, H. J. Region 2, Atlanta, Office of the Director
HODGEN, R. H. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/20 5pp

7903290355 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7903290355 Forwards IE Info Notice 79-07, "Reactors of Redwood Tanks"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/26 5pp

7903290355 Forwards IE Bulletin 79-08, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 5pp

7903400303 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping" - Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7903290404 Forwards IE Bulletin 79-08, "Events Relevant to Refilling Major Reactors Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7903290355 Forwards IE Info Notice 79-10, "Nucleonating Pipe Support Brackets"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/18 2pp

7903290364 Forwards IE Bulletin 79-09, "Failures of SR Type AN-2 Circuit Breaker in Safety-Related Sys" - Licensee action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17 5pp

7903290404 Forwards IE Bulletin 79-08, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/18 5pp

M Reportable occurrences, LERs & related correspondence

7903290303 Board notification: Westbrook refueling water storage tank design deficiency
SEINF, J. Hearings Division 79/03/29 10pp

DOCKET 80-390 MATRIN BAR NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7903290325 Notification of 790500-02 meeting w/utl in Spring City, TN re review status of plant used in order to make independent estimate of fuel loading data
STANLEY, C. R. Light Water Reactors Branch 4. 79/04/25 2pp

7903400348 Revises completion dates specified in CPs as extended to July 1990 for Unit 1 & Mar 1991 for Unit 2 Factors
KULLAND, J. K. Tennessee Valley Authority 79/04/27 5pp

7903290325 Approval of Refuel 205 as another unit requiring surveillance interval no more stringent than that required for shutdowns prepared equipped shutdowns.
DILLON, A. J. Tennessee Valley Authority 79/05/04 25pp

DOCKETED ITEMS

7700200038 Responds to NRC questions re plant containment sump. Forwards "NRCN Calculations for RMI & Containment Spray Pump Operating in Recirculation Mode" & "Model Study of Plant RMI Sump" to
GILLESAND, J E Tennessee Valley Authority 79/02/22 1p

7700200039 "NRCN Calculations for RMI & Containment Spray Pump Operating in Recirculation Mode" App 1979
Tennessee Valley Authority 79/04/04 5pp

7700200039 "Model Study of RMI Sump"
FALIN, J G Tennessee Valley Authority 79/03/31 2pp

J Insurance & Indemnity Information

7700200047 Carriers increased liability limit to \$24,000,000 for policies NP-1,23,43,74,83,100,111,140,146,181,181,184,191,193,174,179,180,182,183,185,187,188,189,190,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215 & others
GUTHRIE, J L American Nuclear Insurance 79/03/01 1p

7700200050 Carriers increased liability limit to \$24,000,000 for policies NP-22,24,29,30,39,46,47,48,49,50,51,52,53,54,55,56,57,58,59,61,64,66,67,68,69,70,71,72,74,76,77,79,80,86,87,88,90,91,92,93,94,95 & 96
ROBERTS, J M Michael Atomic Energy Liability Underwriters 79/05/01 1p

7700200052 Forwards IE Insp Rpt 80-290/79-03 & 80-391/79-03 on 770127-0223, Re noncompliance noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/22 2pp

7700200053 IE Insp Rpt 80-890/79-03 & 80-391/79-03 on 770129-0223 Re noncompliance noted. Major areas inspected: welding of pressurizer spray pipe, RMI piping, containment spray piping & work on reactor internals
COCHRAN, B J Region 2, Chicago, Office of the Director
HDSOT, A R Region 2, Chicago, Reactor Construction & Engineering Support Branch 79/03/01 7pp

7700200054 Forwards IE Info Notice 79-06, "Gross Analysis of Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7700200055 Forwards IE Info Notice 79-06, "Interconnection of Contaminated Dry Air/Wet Air Eqs Used as Source of Breathing Air"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp

7700200056 Forwards IE Info Notice 79-06, "Spill of Radioactively Contaminated Resin"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/30 2pp

7700200058 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" - license action required
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/14 2pp

7700200059 Forwards IE Bulletin 79-08, "Review of Operational Errors & Eqs Misalignments Identified During TDE Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director, 79/04/14 3pp

1 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Reactors Identified During TDE Incident"
J P Region 2, Atlanta, Office of the Director 1p

79-05 "Nonconforming Pipe Support

Office of the Director

Letter of OE Type AK-2

"License Action

As Director

7700200059 Forwards IE Bulletin 79-08, Revision 1, "Review of Operational Errors & Eqs Misalignments Identified During TDE Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/08 3pp

7700200064 Forwards Revisions 2 & 3 to Preservice Baseline & Service Insp Program 81-4, 4, 1, 1
GILLESAND, J E Tennessee Valley Authority 79/04/24, 1p

7700200067 "Surveillance Instruction 81-4, 4, 1, 1, Preservice Insp & Service Insp Program"
GILLESAND, J E Tennessee Valley Authority 79/02/28 2pp

7700200069 Submits supplemental responses to IE Bulletin 79-07. Original responses submitted 700120. Provides add'l info received from manufacturer & describes plans in area of electrical penetrations
GILLESAND, J E Tennessee Valley Authority 79/04/27 3pp

B. Reportable occurrences, LERs & related correspondence

7700200070 Forwards First interim deficiency rpt re defective Phillips self-drill concrete anchors
GILLESAND, J E Tennessee Valley Authority 79/04/10 1p

7700200071 First interim deficiency rpt re defective Phillips self-drill concrete anchors. Deficiency reported by manufacturer STE Phillips On-Site Serv. Search initiated to locate all anchors supplied in defective lot
Tennessee Valley Authority 79/04/10 1p

7700200072 Forwards First interim rpt re incorrect analysis of piping spr over relief snap range
GILLESAND, J E Tennessee Valley Authority 79/04/19 1p

7700200073 First interim rpt re incorrect analysis of piping spr over operating temp range. UII is reanalyzing stressing of all eqs subj to temp relief ambient.
Tennessee Valley Authority 79/04/19 1p

7700200081 Fourth interim rpt of status of review of possible unacceptable pressurizer relief & safety line blowdown events. Next rpt to be submitted by 770051. Awaiting Westinghouse review of nozzle loads
GILLESAND, J E Tennessee Valley Authority 79/04/23 1p

7700200082 Forwards final rpt on deficiency re omitted heating & ventilating ductwork hangers
GILLESAND, J E Tennessee Valley Authority 79/04/23, 1p

7700200083 Final rpt re omitted heating & ventilating ductwork hangers. Finding to provide seismic Category I integrity. Design drawings being reviewed. Required add'l hangers will be added
Tennessee Valley Authority 79/04/23 1p

7700200084 Forwards final deficiency rpt re diesel generator relay tachometer failures reported 700520. All overhauled diesel replaced & tachometers closely monitored.
GILLESAND, J E Tennessee Valley Authority 79/04/30 3pp

7700200085 Forwards First interim deficiency rpt re QA program implementation breakdown
GILLESAND, J E Tennessee Valley Authority 79/05/04, 1p

7700200086 First interim deficiency rpt on 770004 QA program breakdown re structural integrity of high density spent fuel storage racks. Objective documentary evidence will be obtained from supplier.
Tennessee Valley Authority 79/05/04, 2pp

7700200087 Forwards final deficiency rpt re failure of power operated relief valves to meet frequency requirements
GILLESAND, J E Tennessee Valley Authority 79/05/08, 1p

7700200088 First interim deficiency rpt re power operated relief valves. GILLESAND do not meet frequency requirements. Westinghouse is developing math model to consider valve frequency which will be incorporated in piping analysis.
Tennessee Valley Authority 79/05/08 1p

7700200089 Forwards final deficiency rpt re failure of control loop hysteresis.
GILLESAND, J E Tennessee Valley Authority 79/05/10, 1p

7700200090 Final deficiency rpt re control loop hysteresis. Fall in unacceptable position on loss of control power caused by error in wiring of bistable. Bistable wiring corrected so that bistable will fall upon on loss of power.
Tennessee Valley Authority 79/05/08, 1p

7700200091 Provides second interim rpt re deficiency in twellie anodes. Capacitors now being design allowances. Testing of stud anchors still in progress. Next rpt to be submitted by 770004
GILLESAND, J E Tennessee Valley Authority 79/05/17 1p

DOCKETED ITEMS

191

DOCKET 80-291 MATTS BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7903010020 Forward 790301-02 meeting w/Unit 1 in Spring City, TN to review status of plant cost to order to make independent estimate of fuel loading data.
BRIAN, C. R. Light Water Reactors Branch 4 79/04/28 App.

7903040348 Requests completion dates specified in CPs be extended to Jul 1980 for Unit 1 & Mar 1981 for Unit 2. Factors contributing to delays include: 1. Lack of condenser subelements & installation of large cable tray supports.
GILLILAND, J. E. Tennessee Valley Authority 79/04/27 App.

7903010020 Approval of Tefzel 200 as another mat requiring surveillance (interim) on more stringent than that required for ethylene propylene (EPR) gaskets.
GILLILAND, J. E. Tennessee Valley Authority 79/05/04 App.

7903020070 Response to NRC questions re plant containment sump. Forward "NPH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode" & "Model Study of Plant RHR Sump".
GILLILAND, J. E. Tennessee Valley Authority 79/05/23, 1p

7903020070 "NPH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode." App. 2/79
* Tennessee Valley Authority 79/04/30 App.

7903030070 "Model Study of RHR Sump"
Patt, T. D. Tennessee Valley Authority 10/08-1-05-101 79/02/31 App.

J Insurance & indemnity information

7903070497 Confirms increased liability limit to \$104,000,000 for policies #79-1, 28, 43, 76, 103, 100, 111, 145, 146, 181, 161, 164, 170, 173, 174, 175, 179, 180, 182, 185, 186, 187, 189, 190, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 211, 214, 215, & others.
DUNN, B. H. J. American Nuclear Insurers, 79/03/01, 1p

7903070502 Confirms increase in liability limit to \$36,000,000 for policies #79-20, 26, 29, 35, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 61, 64, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, & 86.
DUNN, B. H. J. American Nuclear Insurers, 79/03/01, 1p

G Inspection reports, IE Bulletins & correspondence

7903030020 Forward IE Insp Rept 80-290/79-03 & 80-291/79-03 on 790303-0203 re noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/22, App.

7903030020 IE Insp Rept 80-290/79-03 & 80-291/79-03 on 790303-0203 re noncompliance noted. Major areas inspected: welding of steamgenerator spray pipe, RHR piping, containment spray piping & work on reactor internals.
GOSCHMAN, C. J. Region 2, Chicago, Office of the Director.
WARD, A. R. Region 2, Chicago, Reactor Construction & Engineering Support Branch, 79/03/23, 7p.

7903010021 Forward IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping".
GILLILAND, J. E. Region 2, Atlanta, Office of the Director, 79/03/23, App.

7903030070 Receipt of 790402 IE Informing NRC of steps taken to correct violations noted in IE Insp Rept 80-291/79-04.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/04/18, App.

7903030070 Forward IE Insp Rept 80-291/79-04 on 790303-0203 & notice of violation.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/03/07, App.

7903030020 Notice of violation from Insp on 790303-0203
* Region 2, Atlanta, Office of the Director, 79/03/08, 1p.

7903030021 IE Insp Rept 80-291/79-04 on 790303-0203 Noncompliance noted. Failure to follow reactor vessel internal procedures.
MURPHY, C. E. Region 2, Atlanta, Office of the Director. BRIAN, C. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/03/08, App.

7903030020 Forward IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping". Licensee action required.
GILLILAND, J. E. Region 2, Atlanta, Office of the Director, 79/04/14, App.

7903040320 Forward IE Bulletin 79-04B, "Review of Operational Errors & Pipe Misalignments Identified During TMI Incident".
GILLILAND, J. E. Region 2, Atlanta, Office of the Director, 79/04/14, App.

7903010335 Forward IE Bulletin 79-03, "Events Relevant to Boiling Water Reactor Identification During TMI Incident".
GILLILAND, J. E. Region 2, Atlanta, Office of the Director, 79/04/14, 1p.

7903030341 Forward IE Info Notice 79-10, "Nonconforming Pipe Support".
GILLILAND, J. E. Region 2, Atlanta, Office of the Director, 79/04/10, 1p.

7903020070 Forward IE Bulletin 79-03, "Failures of 6E Type AA-2 Circuit Breaker in Safety-Related Area". Licensee action required.
GILLILAND, J. E. Region 2, Atlanta, Office of the Director, 79/04/17, App.

7903020070 Forward IE Bulletin 79-04A, Revision 1, "Review of Operational Errors & Pipe Misalignments Identified During TMI Incident".
GILLILAND, J. E. Region 2, Atlanta, Office of the Director, 79/04/18, App.

7903030341 Forward Revisions 2 & 3 to Preserve Baseline & Interservice Insp Program R1-4 LO 1.
GILLILAND, J. E. Tennessee Valley Authority, 79/04/24, 1p.

7903030341 "Surveillance Inspection, R1-4, & 10.1, Preserve Baseline & Interservice Insp Program".
GILLILAND, J. E. Tennessee Valley Authority, 79/04/28, 3pp.

7903030320 Submit supplemental response to IE Bulletin 79-07 Original response submitted 790302 Provides add'l info received from manufacturer & describes plans in area of electrical penetrations.
GILLILAND, J. E. Tennessee Valley Authority, 79/04/27, App.

B Reportable occurrences, LERs & related correspondence

7903040490 Forward First interim deficiency rept re defective Phillips self-drill concrete anchors.
GILLILAND, J. E. Tennessee Valley Authority, 79/04/18, 1p.

7903040491 First interim deficiency rept defective Phillips self-drill concrete anchors. Deficiency reported by manufacturer. ITT Phillips Drill Div. Search initiated to locate all anchors supplied in defective lot.
GILLILAND, J. E. Tennessee Valley Authority, 79/04/18, 1p.

7903040320 Forward first interim rept re incorrect analysis of piping eye over total temp 7903.
GILLILAND, J. E. Tennessee Valley Authority, 79/04/19, 1p.

7903040324 First interim rept (incorrect analysis of piping eye over operating temp range. Unit is maintaining straining of all supports to temp below ambient.
* Tennessee Valley Authority, 79/04/19, 1p.

7903030481 Fourth interim rept unacceptable penetration re analysis. Next rept to be submitted. Pending review of data.
GILLILAND, J. E. Tennessee Valley Authority, 79/04/19, 1p.

7903030510 Forward final rept re ventilating ductwork hangers.
GILLILAND, J. E. Tennessee Valley Authority, 79/04/19, 1p.

7903030519 Final rept re civil hangers failing to provide design drawings being reworked.
* Tennessee Valley Authority, 79/04/19, 1p.

7903030532 Forward final rept re containment failure. Repertory re: containment failure. Containment failure. Containment failure.
GILLILAND, J. E. Tennessee Valley Authority, 79/04/19, 1p.

DOCKETED ITEMS

790510028 Forwards first interim deficiency rept re OH program implementation breakdown
OILFIELD, J. E. Tennessee Valley Authority 79/05/04 1p

---790510028 First interim deficiency rept on 790504 OH program breakdown re structural integrity of high density spent fuel storage racks Objective documentary evidence will be obtained from supplier
* Tennessee Valley Authority 79/05/04 2pp

7905160317 Forwards first deficiency rept re failure of power operated relief valves to meet frequency requirements
OILFIELD, J. E. Tennessee Valley Authority 79/05/08 1p

---7905160317 First interim deficiency rept power operated relief valves (3146880) do not meet frequency requirements Meetinghouse is developing math model to consider valve frequency, which will be incorporated in piping analysis
* Tennessee Valley Authority 79/05/08 1p

7905190317 Forwards final deficiency rept re failure of control loop bistables
OILFIELD, J. E. Tennessee Valley Authority 79/05/10 1p

---7905190317 Final deficiency rept control loop bistables fail in undesirable position as loss of control power. Caused by error in wiring of bistable Bistable using serrated as that bistable will fail open as loss of power
* Tennessee Valley Authority 79/05/10 1p

7905200301 Provides second interim rept re deficiency in female anchor capacities lower than design allowable testing of steel anchors still in progress Next rept to be submitted by 790504
OILFIELD, J. E. Tennessee Valley Authority 79/05/17 1p

DOCKET 80-294 CALIFORNIA WHITE POLYTECH COLLEGE RE3 REACTOR

J Insurance & indemnity information

7905260343 Forwards Amendment 6-B, per 100FR140 changes re liability insurance increases from \$140 million to \$140 million effective 790501 Supporting documentation and
SALTMAN, J. Antitrust & Indemnity Group 79/05/01 3pp

7905190400 Forwards Amendment 7 to Indemnity Agreement E-88, PATTERSON, K. P. California Polytech State Univ 79/05/08 2pp

DOCKET 80-295 VIRROL E SUMNER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7905200414 Forwards NRC-0301, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability R/S and
WHELAN, D. S. Assistant Director for Light Water Reactors, 79/05/20 2pp

7905260430 Summary of 790327 meeting w/Util. Gilbert Associates, Inc. & Meetinghouse in Bethesda, MD re second round requests for info on Reaction 7 & 8 at RAB
TISBETH, D. L. Light Water Reactors Branch 2 79/04/27 7pp

7905300452 Forwards Technical Rept 79-0, "Full-Scale 1978 Reinforcing Near Plant" & Technical Rept 79-1, "Seismic Activity Near Plant for Jan-Mar 1979"
CRANDALL, M. South Carolina Electric & Gas Co. 79/05/28 1p

---7905300454 Technical rept 79-0, "Oct-Dec 1978 Seismicity Near Plant,"
* South Carolina Electric & Gas Co 79/05/01 60pp

---7905300780 Technical rept 79-1, "Seismic Activity Near Plant, Jan-Mar 1979,"
TALAMANI, P. South Carolina, Univ. of 79/05/01 20pp

F Security, medical, emergency & fire protection plans

7905300486 Notification of 790430-080-03 meeting w/Util. Gilbert/Communities Coalition & Gilbert/Outpost in Fairfield County, SC to visit meteorological monitoring installations & review fire protection program
TISBETH, D. L. Light Water Reactors Branch 2 79/04/11 3pp

G Adjudicatory correspondence

7905260343 Business Information & Bureau's Contentious Ad & Adjudicatory 790503 action for summary disposition
LUNDGREN, O. A. HODGES, P. F. SMITH, J. M. Atomic Safety and Licensing Board Panel 79/04/08 16pp

J Insurance & indemnity information

7905160317 Forwards Amendment 6-B, per 100FR140 changes re liability insurance increases from \$140 million to \$140 million effective 790501 Supporting documentation and
SALTMAN, J. Antitrust & Indemnity Group 79/05/01 3pp

H Antitrust correspondence

7905200314 Motion by BC Electric & Gas to strike Central Electric & Gas 790322 brief on, in alternative, for leave to file reply, Certificate of Doc and
CONNER, T. B., HADLER, R. H. Conner, Moore & Corbin 79/03/23 3pp

7905200346 Opposition to 790322 BC Electric & Gas motion to strike Reply right to answer as due process of law or as matter of right from BC move for summary disposition in two 790322 pleadings Certificate of Doc and
BRAND, R. E., WALL, E. K. Central Electric Power Cooperative, Inc 79/03/27 3pp

7905140337 Response of BC Electric & Gas Co. in opposition to Central Electric Power Cooperative, Inc reply brief. Upon denial of right from BC move for summary disposition in two 790322 pleadings Certificate of Doc & supporting documentation and
CONNER, T. B., HADLER, R. H. Conner, Moore & Corbin 79/04/19 15pp

7905190318 Response to reply brief of Central Electric Power Cooperative, Inc. should deny petition. Certificate of Doc and
CHAMBERLAIN, P. O. Anti-Trust Division 79/04/24 7pp

7905260343 Forwards corrected page to NRC 790319 response to amended petition of Central Electric Power Cooperative, Inc. to amend
CHAMBERLAIN, P. O. Anti-Trust Division 79/04/24 3pp

G Inspection reports, IC Bulletin & correspondence

7905200466 Forwards IC Insp Rept 80-295/79-07 on 790227-0301 No noncompliance noted.
LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/16 2pp

---7905200467 IC Insp Rept 80-295/79-07 on 790227-0301 No noncompliance noted. Major areas inspected: 1) interview, prearranged test procedures review & plant tour.
DONAT, T. J., WATKINS, D. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/02/16 2pp

7905010209 Forwards IC Info Notice 79-04, "Stress Analysis of Safety-Related Piping"
WILLIAMS, J. P. Region 2, Atlanta, Office of the Director 79/03/29 1pp

7905030317 Forwards IC Info Notice 79-07, "Failure of Redundant Tanks,"
WILLIAMS, J. P. Region 2, Atlanta, Office of the Director 79/03/28 1p

7905260464 Forwards IC Insp Rept 80-295/79-08 on 790312-18 No noncompliance noted.
HOPKIN, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/08 2pp

---7905260466 IC Insp Rept 80-295/79-08 on 790312-18 No noncompliance noted. Major areas inspected: 1) license action on previous Insp findings; 2) inspection & circulars; 3) contract activities & implementation of 100FR140
BURNETTE, T. E. Region 2, Atlanta, Office of the Director, 79/04/08 2pp

7905090420 Ack receipt of IC Insp Rept 80-295/79-04 on 790212-14 No noncompliance noted.
JENSEN, K. E. South Carolina Electric & Gas Co. 79/04/21 1p

---7905090424 Forwards IC Insp Rept 80-295/79-04 on 790212-14, No noncompliance noted.
HOPKIN, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/22 2pp

DOCKETED ITEMS

183

--790504046 IE Insp Rept 50-095/79-06 on 790320-14 No noncompliance noted. Major areas inspected: Class A & B storage containment; pretraining; RA/RC controls; quality records & cost status. LAMAR, J. D. Region 2, Atlanta, Office of the Director. 79/04/11 C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/03/22 App.

790520050 Response to IE Bulletin 79-04 "Incorrect Weights for Baling Check Valves Hfg by Velox Engineering Corp." No 3, 4 or 4-inch valves are installed or scheduled to be installed. GREGG, E. H. South Carolina Electric & Gas Co. 79/04/11 Ip.

7905030100 Forwarded IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14 Ip.

7905040223 Forwarded IE Bulletin 79-08, "Review of Operational Errors & Byg Missalignments Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14 App.

7905040424 Forwarded IE Bulletin 79-08, "Events Relevant to Belling Nuclear Power Reactors Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/14 Ip.

7905040374 Forwarded IE Info Notice 79-10, "Housekeeping Pipe Support Devices." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/16 Ip.

7905030149 Forwarded IE Bulletin 79-06, "Failures of OE Type AN-2 Circuit Breaker in Safety-Related Sys." Licensee action required. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/17 App.

7905020423 Forwarded IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Byg Missalignments Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18 App.

7905030475 Forwarded IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Byg Missalignments Identified During TMI Incident." O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/18 App.

7905030105 Ack receipt of IE Insp Rept 50-095/79-09 on 790320-20 No noncompliance noted. JOHNSON, M. C. South Carolina Electric & Gas Co. 79/04/23 Ip.

--7905030102 Forwarded IE Insp Rept 50-095/79-09 on 790320-20 No noncompliance noted. HUMPHRY, C. E. Region 2, Atlanta, Office of the Director. 79/04/09 App.

--7905030117 IE Insp Rept 50-095/79-09 on 790320-20 No noncompliance noted. Major areas inspected: instrumentation of QA procedures; work activities; quality records; electrical cables & terminations work. O'BRYEN, T. D. Region 2, Atlanta, Office of the Director. 79/04/04 App.

B. Reportable occurrences, LERs & related correspondence

7905108107 Informs that injection pumps have been removed from engines returned to factory inspected per newly established criteria returned to site & reinstalled engines. All injection pumps in good condition. MCHENRY, J. H. Cell Industries, Inc. 79/03/23, Ip.

7905030480 Interim rept updating status of previously identified items re full penetration butt weld splices in electrical support members. JOHNSON, M. C. South Carolina Electric & Gas Co. 79/04/23 App.

DOCKET 50-096 UNIV. OF VIRGINIA CAVANIS REACTOR

A. Application/construction stage documents & correspondence

7905030319 "Air Products & Chemicals, Inc. Past LSW Reactor Test Summary." Washington Public Power Supply System. APC-79-8. 78/07/31 175pp.

7905040216 Summary of 790321 meeting of Mark II users group in San Jose, CA re intermediate plant program tests. JOHNSON, M. C. Containment Systems Branch. 79/04/13 150pp.

7905100407 Notification of 790419 meeting w/UTM in Bethesda, MD to discuss Chapter 7 of FRM. LYNN, H. D. Light Water Reactors Branch. 79/04/13 App.

7905100506 Repts on geological studies' status. Generic rept expected in Fall 1979. Response meeting to discuss plans for submitting rept of studies as well as mechanism for identification & review of studies in Hartford area. ROSENBERG, D. L. Washington Public Power Supply System. 79/04/27 App.

7905040411 Forwarded NRC positions on WPPSS-34-006, "Operational QA Program Description." Response to positions should be submitted by 790505 as amend to original rept. HARRIS, M. P. Quality Assurance Branch. 79/03/01 App.

7905100323 Forwarded utility responses to round one, set four questions from Accident Analysis Branch (Emergency Planning) re QA application. ROSENBERG, D. L. Washington Public Power Supply System. 79/05/07 App.

--7905100237 Responses by utility to round one, set four questions from Accident Analysis Branch (Emergency Planning) re QA application. Washington Public Power Supply System. 79/05/04 63pp.

7905100117 Prepares course of action to facilitate round two review. Outlines most efficient utilization of manpower & resources at NRC, utility & contractors. Requests NRC to provide generic concerns for similarly-designed plants. ROSENBERG, D. L. Washington Public Power Supply System. 79/05/11 App.

7905200327 Forwarded utility responses to round one, set three questions from Accident Analysis Branch. Responses will be incorporated into FRM. ROSENBERG, D. L. Washington Public Power Supply System. 79/05/14 87pp.

F. Security, medical, emergency & fire protection plans

7905200345 Forwarded request for addl info re physical security plan in complete review of application for DL Encl withheld info. 100FR2 7901. VANDE, A. B. Light Water Reactors Branch. 79/04/03 App.

7905030550 Forwarded preliminary fire protection questions prior to site visit. BARRER, R. D. Open-Source Association, Inc. 79/03/02 20pp.

7905040401 Forwarded safeguards contingency plan. Plan withheld info. 100FR2 7901. ROSENBERG, D. L. Washington Public Power Supply System. 79/05/03 App.

H. General correspondence

7905030449 Forwarded affidavit & Certificate of Use for Amend 3 to FRM. ROSENBERG, D. L. Washington Public Power Supply System. 79/03/01 App.

G. Inspection reports, IE Bulletins & correspondence

7905030294 Forwarded IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping." Region 4, Dallas, Office of the Director. 79/03/20 1p.

7905030450 Forwarded "Preservice Insp Program Plan, Vols 1 & 2." ROSENBERG, D. L. Washington Public Power Supply System. 79/03/28 App.

--7905030456 "Preservice Insp Program Plan, Vols 1 & 2." Washington Public Power Supply System. 79/03/08, 1200pp.

DOCKET 50-096 UNIV. OF VIRGINIA CAVANIS REACTOR

G. Inspection reports, IE Bulletins & correspondence

7905030294 Forwarded IE Bulletin 79-05, 79-06A & 79-06 re nuclear incident at TMI. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/04/12, Ip.

DOCKETED ITEMS

7903010015 Forwards IE Bulletin 79-046, "Review of Operational Errors & Key Misalignments Identified During TMI Incident"
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7903040015 Forwards IE Bulletin 79-046, "Review of Operational Errors & Key Misalignments Identified During TMI Incident"
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7903040029 Forwards IE Bulletin 79-046, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7903050010 Forwards IE Bulletin 79-07, "Dynamic Stress Analysis of Safety-Related Piping - Licensee action required"
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7903030020 Forwards IE Bulletin 79-09, "Failures of GE Type AA-2 Circuit Breaker in Safety-Related Bays - Licensee action required"
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/17 1p

7903050030 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-2"
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/21 1p

7903010029 Response to NRC 790417 ltr re violations noted in IE ltr on 790327-02B, 0201-02 & 14-1A Corrective actions/process
Instrument pipe & other parts of reactor vessel nozzle were beyond
REHOBOTH, S. L. Washington Public Power Supply System 79/05/10, app

B Reportable occurrences, LRs & related correspondence

7903010047 Forwards PWD-79-47L
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p

7903010013 Forwards PWD-79-43R
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/11 1p

7903040024 Forwards PWD-79-47B
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/12 1p

Forwards PWD-79-43T,
H Region 3, San Francisco, Office of the Director,
1p

1-79-43U,
on 3, San Francisco, Office of the Director.

of the Director,

is Director

factor.

deficiency

VS4/23,

recher

recher

recher,

7903010021 Forwards PWD-79-43AH
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/27, 1p

7903010034 Forwards PWD-79-07AL, AL & AN per NRC 790401 ltr transmitting IE Bulletin 79-05
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/30 1p

7903050049 Forwards reft on deficient basic inflow valves used in standby gas treatment sys.
REHOBOTH, S. L. Washington Public Power Supply System 79/04/30 1p

7903050033 Reft on possible failure of basic inflow valves w/interlock motor & manual operation valve may become inoperable due to vibration. All 19 valves are being repaired per manufacturer's recommendation.
Washington Public Power Supply System 79/04/30 1p

7903070010 Forwards PWD-79-47AL, per NRC 790401 ltr transmitting IE Bulletin 79-05
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/03/01 1p

7903010037 Forwards PWD-79-47AH
ENGLERMAN, R. H. Region 3, San Francisco, Office of the Director
79/04/07, 1p

DOCKET 30-400 SHARON HARRIS NUCLEAR POWER PLANT, UNIT 1
A Application/Construction Stage documents & correspondence

7903040049 Notification of 790305 meeting w/uttl in Bethesda, MD to discuss preparation of environ. rep.
MADON, S. E. Environmental Projects Branch 2 79/04/27, 1p

7903050043 Forwards oversized maps & photo attachments to still 791129 reft on main dam core trench features w/o drawings
FLORES, S. D. Carolina Power & Light Co 79/05/08 3pp

7903030040 Inform of design change notices re structure content of backfill against Category I structures & of central core unit for main & auxiliary dam & separating dike removal
if problem will be documented in 3046
HODGFIELD, M. A. Carolina Power & Light Co 79/03/09 2pp

7903030030 Response to Region 12 790304 request for criteria used to approve previously placed backfill.
HODGFIELD, M. A. Carolina Power & Light Co 79/03/10 3pp.

G Adjudicatory correspondence

7903050040 Response to intervenors Conservation Council of NC & Wake Environ. Inc 790304 motion to remand to ASD for further hearings before petition to reopen record Certificate of Env. eval
BARTH, C. A. Branch 3 79/03/16, app.

7903050040 Response to 790305 request of Radio Alliance & W. Eastman re 790313 ALAD-BB affirming 790310 order denying order of petitions filed by intervenors Supporting Documentation & Certificate of Env. eval.
TODMAN, DORE, F. Shaw, Pittman, Pethe, & Troubridge. 79/03/20, 11pp

7903030029 NRC motion to accept exhibits into evidence re mgt capability of applicant to construct & operate proposed facility Certificate of Env. eval.
BARTH, C. A. Branch 3 79/03/20, App

7903050018 Forwards request for Board notification re nonseafely-grade equipment to mitigate transients.
BENNETT, J. F. Hearings Division. 79/04/02 31pp

7903050016 Board notification staff assessment re nonseafely-grade equipment to mitigate transients.
WARRALL, D. O. B. Assistant Director for Light Water Reactors 79/03/29, 3pp.

7903050016 Board notification recent letter on nonseafely-grade equipment to mitigate transients.
TERRELL, R. L. Assistant Director for Reactor Safety. 79/03/16 3pp.

7903050030 Applicant has no objection to NRC 790330 action to accept late evidence exhibits 12, 13, 14, 15, 19 & 20 from recent proceedings. Certificate of Env. eval.
TODMAN, DORE, F. Shaw, Pittman, Pethe, & Troubridge. 79/04/04, 3pp

DOCKETED ITEMS

195

- 7903200093 Forwarded 790119 Press Release 79-19 re issuance of NRC positive statement on Reactor Safety Study; the review by Lewis panel & WASH-1400 see survey
BARTHC.C.A Branch 3 79/04/04 1p.
- 7903200216 Informing ARLS of review of seal security info re sabotage of spent nuclear fuel Forwarded transmittal memo NRC assessment of significance of info to be forwarded when available
BARTHC.C.A Branch 3 79/04/05 2pp
- 7903200443 Forwarded draft memo discussing aspects of accumulator delivery identified in NRC studies of SCOD performance characteristcs NRC does not consider issue relevant to proceeding
BARTHC.C.A Branch 3 79/04/05 3pp
- 7903240703 Forwarded memo re behavior of rodine during postulated steam generator tube rupture accidents
BARTHC.C.A Branch 3 79/04/05 1p
- 7903030152 Forwarded NRC 790211 survey re use of WASH-1400 in licensing process
BARTHC.C.A Branch 3 79/04/10 9pp
- 7903104918 Response to ALAB-SOR re radon emissions & de minimus theory from Perkins record Certificate of Woc mail
SCINTO.J.F Hearings Division 79/04/11 4pp.
- 7903140849 Response to 790404 brief of Philadelphia Electric Co. PECO & Atlantic City Gas Electric Co re de minimus theory Certificate of Woc mail.
NEPFSO.C.N Citizens For Safe Environment 79/04/11 2pp.
- 7903150342 Forwarded 790335 motion All requested exhibits mentioned in motion were submitted during Raleigh, NC hearing, which respondent attended & so on
REILB.S.J Branch 3 79/04/13 1p
- 7903160221 Forwarded applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Woc mail
TSCBHS1505.C.P Shaw, Pittman, Patton & Treubridge 79/04/17 2pp
- 7903140228 Lists corrections to be made in transcripts of evidentiary hearing conducted on 790327-0332 & 790336-08 in Raleigh, NC
O'REILLY.J.P Shaw, Pittman, Patton & Treubridge 79/04/17 2pp
- 7903140261 Prepared findings of fact & conclusions of law in form of supplementary initial decision (CP). List of exhibits mail
TSCBHS1505.C.P. O'REILLY.J.P Shaw, Pittman, Patton & Treubridge 79/04/17 2pp
- 7903200709 Cites evident error in prepared findings of fact of Carolina Power & Light Co concerning statement allowed by Nuke Alliance or other parties Request more participation be allowed
EGLERMAN.W. Nuke Alliance 79/04/21 1p
- 7903140332 Notification of cancellation of five intervenor groups re radon emissions issue. Parties have until 790329 in which to file for summary disposition
DUPLE.N.E Atomic Safety and Licensing Appeal Panel 79/04/25 1pp.
- 7903404801 Comments on ARLS findings re still operating record suggests Board condition facility due in light of still operating problems.
EGLERMAN.W. Affiliation Unknown. 79/04/27 2pp.
- 7903230148 Summary of 790324 Affirmation 79-10 in Washington, DC re NRC-A-79-25 motion to reopen hearings in Sherron Harris proceeding & NRC-A-79-10A, Kennel FGA Appeal 79-A-20.
CHILK.S.J. Office of the Secretaries of the Commission. 79/03/04 1p.
- 7903200362 Inform parties of possibility of taking official notice re test for viscosity. Objections to ARLS procedure must be filed within ten days. Supporting documentation & Certificate of Woc mail.
BARTHC.C.A Atomic Safety and Licensing Board Panel 79/05/10 2pp.
- 7903201640 Forwarded IE Info Notice 79-04. "Stress Analysis of Safety-Related Piping."
O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/03/23 2pp.
- 7903200324 Forwarded IE Info Notice 79-07. "Rupture of Reducible Tee." O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 79/03/26 2pp.
- 7903040343 Forwarded IE Bulletin 79-04B. "Review of Operational Errors & Re-Examination Identified During TMI Incident."
O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/14 2pp
- 7903040381 Forwarded IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping - Licensee action required."
O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7903040329 Forwarded IE Bulletin 79-08. "Nuclear Reliance to Seismic Water Pumps Reactors Identified During TMI Incident."
O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/14 1p
- 7903010244 Forwarded IE Info Notice 79-10. "Nonconforming Pipe Support Struts."
O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7903010244 Forwarded IE Info Notice 79-10. "Nonconforming Pipe Support Struts."
O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7903010244 Forwarded IE Bulletin 79-09. "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Sys - Licensee action required."
O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/17 2pp
- 7903030225 Act receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-403/79-02, 30-401/79-03, 30-408/79-01 & 30-405/79-07.
HUBBARD.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 1p
- 7903030330 Response to NRC 790227 ltr re violations noted in IE Insp Repts 30-403/79-02, 30-401/79-03, 30-408/79-01 & 30-405/79-07.
Connective actions appropriate personnel instructed in correct close-out procedures
HUBBARD.C.E Carolina Power & Light Co 79/04/06 2pp
- 7903020773 Forwarded IE Bulletin 79-04A. Revision 1. "Review of Operational Errors & Re-Examination Identified During TMI Incident."
O'REILLY.J.P Region 2, Atlanta, Office of the Director 79/04/18 2pp
- 7903030330 Act receipt of IE Insp Repts 30-403/79-02, 30-401/79-03, 30-408/79-01 & 30-405/79-07.
HUBBARD.C.E Carolina Power & Light Co 79/04/26 2pp
- 7903030337 Forwarded IE Insp Repts 30-403/79-02, 30-401/79-03, 30-408/79-01 & 30-405/79-07.
HUBBARD.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/18 2pp
- 7903030300 IE Insp Repts 30-403/79-02, 30-401/79-03, 30-408/79-01 & 30-405/79-07.
HUBBARD.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/18 2pp
- R Periodic operating reports & related correspondence
- 7903030475 Forwarded "Seismic Monitoring Program." R
7903030425
HUBBARD.C.E Carolina Power & Light Co 79/03
- 7903030480 "Seismic Monitoring Program." R
HUBBARD.C.E Carolina Power & Light Co 79/03/26 2pp.
- B. Reportable occurrences, LRs & related correspondence
- 7903040410 Inform that during 790327 site audit - inspectors notified of potential reportable the containment water proofing membrane leakage has not yet determined. Final decision by 790328.
CHILK.S.J. Carolina Power & Light Co. 79/03
- 7903100203 Board notification Reactor refusing design deficiency
SCINTO.J.F Hearings Division 79/03/29 2pp

DOCKETED ITEMS

DOCKET 90-401 SHAWNEE NUCLEAR REACTOR PLANT, UNIT 2

A Application/Construction stage documents & correspondence

790304089 Notification of 790306 meeting w/UEI in Bethesda, MD to discuss presentation of revision 7903
BAMM, B. Environmental Projects Branch 3 79/04/27 1p

790306040 Forwarded covered maps & photo attachments to airtel 781129
reg re main dom core vessel Features, NC. OCHOLUP
PLEU, S. Carolina Power & Light Co 79/02/08 5pp

790306040 Inform of design change notices re auxiliary contents of
safety against Category 3 structures & of control core
vessel for main & auxiliary doms separating 444 Resolution
condition will be documented in 7903
790306040 Carolina Power & Light Co 79/03/09 5pp

790306080 Response to Region II 790304 request for criteria used to
approve previously placed battery
790306080 Carolina Power & Light Co 79/04/18 7pp

O Affidavitary correspondence

790306080 Response to Intervenor's Conservation Council of NC & Wake
County, Inc. 790306 motion to remove to ALE for further
reviewing w/ur petition to remove record Certificate of Gov
encl
BAMM, C. A. Branch 3 79/03/16 4pp

790306080 Response to 790303 request of Atomic Alliance & W. Carolina re
790303 ALAD-526 affirming 790303 order denying series of
petitions filed by intervenor Supporting documentation & Certificate of Gov encl
790306080 C. P. Shaw, Pittman, Patte, & Treadwell 79/05/21 1pp

790306080 NRC motion to accept exhibits into evidence re mgt
capability of applicant to own & operate proposed
facility Certificate of Gov encl
BAMM, C. A. Branch 3 79/03/30 4pp

790306080 Forward request for Board notification re non-safety-grade
equipment to mitigate transients
SCINTO, J. F. Hearings Division 79/04/03 31pp

790306080 Board notification staff assessment re non-safety-grade
equipment to mitigate transients
VAMM, S. B. Assistant Director for Light Water Reactors,
79/02/09 5pp

790306080 Board notification recent focus on non-safety-grade
equipment to mitigate transients
VAMM, S. B. Assistant Director for Reactor Safety 79/03/16 5pp

790306080 Applicant has no objection to NRC 790303 motion to accept
into evidence Exhibit 12, 13, 14, 15, 16 & 20 from recent
proceedings. Certificate of Gov encl
790306080 C. P. Shaw, Pittman, Patte, & Treadwell 79/04/04 2pp

790306080 Forward 790303 Press Release 79-18 re issuance of NRC
policy statement on Reactor Safety Study, its review by Lewis
panel & AMRI-1400 use surveys
BAMM, C. A. Branch 3 79/04/04 1p

790306080 Inform ALE of review of nati security info re sabotage of
spent nuclear fuel Forwarded transmittal memo, NRC assessment of
significance of info to be forwarded when available
BAMM, C. A. Branch 3 79/04/02 2pp

790306080 Forward draft memo discussing aspects of accumulator
delivery identified in NRC studies of ECCS performance
characteristics NRC does not consider issue relevant to
proceeding
BAMM, C. A. Branch 3 79/04/02 1pp

790306080 Forward memo re behavior of iodine during postulated steam
generator tube rupture accident
BAMM, C. A. Branch 3 79/04/03 1p

790306080 Forward NRC 781121 survey re use of AMRI-1400 in licensing
process
BAMM, C. A. Branch 3 79/04/04 5pp

790306080 Response to ALAD-509 re radon emissions & de minimis theory
from Perkins record Certificate of Gov encl
SCINTO, J. F. Hearings Division 79/04/21 4pp

790306080 Response to 790304 Order of Philadelphia Electric Co, H&W &
Atlantic City, N&D Electric Co re de minimis radon
Certificate of Gov encl
MEPHR, C. E. Sullivan for Safe Environment 79/04/18 8pp

790306080 Forward 790303 motion ALE requested exhibits mentioned
in motion were submitted during Raleigh, NC hearing, which
requester attended w/o encl
MEPHR, C. E. Sullivan 79/04/13 1p

790306080 Forward applicant's transcript corrections & Applicant's
proposed findings of fact & conclusions of law in the form
of supplemental initial decision Certificate of Gov encl
MEPHR, C. E. Sullivan, Pittman, Patte, & Treadwell 79/04/17 3pp

790306080 Little corrections to be made in transcripts of evidentiary
hearing conducted on 790307-0300 & 790308-0300
O'REILLY, J. H. Shaw, Pittman, Patte, & Treadwell 79/04/17 2pp

790306080 Proposed findings of fact & conclusions of law in form of
supplemental initial decision (CPI) List of exhibits encl
790306080 C. P. Shaw, Pittman, Patte, & Treadwell
79/04/17 54pp

790306080 Notice of invalidation of flow intervener group re radon
emissions issue Parties have until 790605 in which to file
for summary disposition
BAMM, C. A. Atomic Safety and Licensing Appeal Panel 79/04/25 17pp

790306080 Comments on ALE findings re still operating reactor Suggests
S&W consider facility OK in light of still operating
problems
790306080 Affiliation Unknown 79/04/27 2pp

790306080 Summary of 790306 Affirmation Denial 79-10 in Washington, DC
re 790306-A-79-20 motion to keep hearing in Shawnee
proceeding & 790307-164, 164a, 164b, 164c, 164d, 164e, 164f, 164g, 164h, 164i, 164j, 164k, 164l, 164m, 164n, 164o, 164p, 164q, 164r, 164s, 164t, 164u, 164v, 164w, 164x, 164y, 164z, 164aa, 164ab, 164ac, 164ad, 164ae, 164af, 164ag, 164ah, 164ai, 164aj, 164ak, 164al, 164am, 164an, 164ao, 164ap, 164aq, 164ar, 164as, 164at, 164au, 164av, 164aw, 164ax, 164ay, 164az, 164ba, 164bb, 164bc, 164bd, 164be, 164bf, 164bg, 164bh, 164bi, 164bj, 164bk, 164bl, 164bm, 164bn, 164bo, 164bp, 164bq, 164br, 164bs, 164bt, 164bu, 164bv, 164bw, 164bx, 164by, 164bz, 164ca, 164cb, 164cc, 164cd, 164ce, 164cf, 164cg, 164ch, 164ci, 164cj, 164ck, 164cl, 164cm, 164cn, 164co, 164cp, 164cq, 164cr, 164cs, 164ct, 164cu, 164cv, 164cw, 164cx, 164cy, 164cz, 164da, 164db, 164dc, 164dd, 164de, 164df, 164dg, 164dh, 164di, 164dj, 164dk, 164dl, 164dm, 164dn, 164do, 164dp, 164dq, 164dr, 164ds, 164dt, 164du, 164dv, 164dw, 164dx, 164dy, 164dz, 164ea, 164eb, 164ec, 164ed, 164ee, 164ef, 164eg, 164eh, 164ei, 164ej, 164ek, 164el, 164em, 164en, 164eo, 164ep, 164eq, 164er, 164es, 164et, 164eu, 164ev, 164ew, 164ex, 164ey, 164ez, 164fa, 164fb, 164fc, 164fd, 164fe, 164ff, 164fg, 164fh, 164fi, 164fj, 164fk, 164fl, 164fm, 164fn, 164fo, 164fp, 164fq, 164fr, 164fs, 164ft, 164fu, 164fv, 164fw, 164fx, 164fy, 164fz, 164ga, 164gb, 164gc, 164gd, 164ge, 164gf, 164gg, 164gh, 164gi, 164gj, 164gk, 164gl, 164gm, 164gn, 164go, 164gp, 164gq, 164gr, 164gs, 164gt, 164gu, 164gv, 164gw, 164gx, 164gy, 164gz, 164ha, 164hb, 164hc, 164hd, 164he, 164hf, 164hg, 164hi, 164hj, 164hk, 164hl, 164hm, 164hn, 164ho, 164hp, 164hq, 164hr, 164hs, 164ht, 164hu, 164hv, 164hw, 164hx, 164hy, 164hz, 164ia, 164ib, 164ic, 164id, 164ie, 164if, 164ig, 164ih, 164ii, 164ij, 164ik, 164il, 164im, 164in, 164io, 164ip, 164iq, 164ir, 164is, 164it, 164iu, 164iv, 164iw, 164ix, 164iy, 164iz, 164ja, 164jb, 164jc, 164jd, 164je, 164jf, 164jg, 164jh, 164ji, 164jj, 164jk, 164jl, 164jm, 164jn, 164jo, 164jp, 164jq, 164jr, 164js, 164jt, 164ju, 164jv, 164jw, 164jx, 164jy, 164jz, 164ka, 164kb, 164kc, 164kd, 164ke, 164kf, 164kg, 164kh, 164ki, 164kj, 164kk, 164kl, 164km, 164kn, 164ko, 164kp, 164kq, 164kr, 164ks, 164kt, 164ku, 164kv, 164kw, 164kx, 164ky, 164kz, 164la, 164lb, 164lc, 164ld, 164le, 164lf, 164lg, 164lh, 164li, 164lj, 164lk, 164ll, 164lm, 164ln, 164lo, 164lp, 164lq, 164lr, 164ls, 164lt, 164lu, 164lv, 164lw, 164lx, 164ly, 164lz, 164ma, 164mb, 164mc, 164md, 164me, 164mf, 164mg, 164mh, 164mi, 164mj, 164mk, 164ml, 164mm, 164mn, 164mo, 164mp, 164mq, 164mr, 164ms, 164mt, 164mu, 164mv, 164mw, 164mx, 164my, 164mz, 164na, 164nb, 164nc, 164nd, 164ne, 164nf, 164ng, 164nh, 164ni, 164nj, 164nk, 164nl, 164nm, 164nn, 164no, 164np, 164nq, 164nr, 164ns, 164nt, 164nu, 164nv, 164nw, 164nx, 164ny, 164nz, 164oa, 164ob, 164oc, 164od, 164oe, 164of, 164og, 164oh, 164oi, 164oj, 164ok, 164ol, 164om, 164on, 164oo, 164op, 164oq, 164or, 164os, 164ot, 164ou, 164ov, 164ow, 164ox, 164oy, 164oz, 164pa, 164pb, 164pc, 164pd, 164pe, 164pf, 164pg, 164ph, 164pi, 164pj, 164pk, 164pl, 164pm, 164pn, 164po, 164pp, 164pq, 164pr, 164ps, 164pt, 164pu, 164pv, 164pw, 164px, 164py, 164pz, 164qa, 164qb, 164qc, 164qd, 164qe, 164qf, 164qg, 164qh, 164qi, 164qj, 164qk, 164ql, 164qm, 164qn, 164qo, 164qp, 164qq, 164qr, 164qs, 164qt, 164qu, 164qv, 164qw, 164qx, 164qy, 164qz, 164ra, 164rb, 164rc, 164rd, 164re, 164rf, 164rg, 164rh, 164ri, 164rj, 164rk, 164rl, 164rm, 164rn, 164ro, 164rp, 164rq, 164rr, 164rs, 164rt, 164ru, 164rv, 164rw, 164rx, 164ry, 164rz, 164sa, 164sb, 164sc, 164sd, 164se, 164sf, 164sg, 164sh, 164si, 164sj, 164sk, 164sl, 164sm, 164sn, 164so, 164sp, 164sq, 164sr, 164ss, 164st, 164su, 164sv, 164sw, 164sx, 164sy, 164sz, 164ta, 164tb, 164tc, 164td, 164te, 164tf, 164tg, 164th, 164ti, 164tj, 164tk, 164tl, 164tm, 164tn, 164to, 164tp, 164tq, 164tr, 164ts, 164tt, 164tu, 164tv, 164tw, 164tx, 164ty, 164tz, 164ua, 164ub, 164uc, 164ud, 164ue, 164uf, 164ug, 164uh, 164ui, 164uj, 164uk, 164ul, 164um, 164un, 164uo, 164up, 164uq, 164ur, 164us, 164ut, 164uu, 164uv, 164uw, 164ux, 164uy, 164uz, 164va, 164vb, 164vc, 164vd, 164ve, 164vf, 164vg, 164vh, 164vi, 164vj, 164vk, 164vl, 164vm, 164vn, 164vo, 164vp, 164vq, 164vr, 164vs, 164vt, 164vu, 164vv, 164vw, 164vx, 164vy, 164vz, 164wa, 164wb, 164wc, 164wd, 164we, 164wf, 164wg, 164wh, 164wi, 164wj, 164wk, 164wl, 164wm, 164wn, 164wo, 164wp, 164wq, 164wr, 164ws, 164wt, 164wu, 164wv, 164ww, 164wx, 164wy, 164wz, 164xa, 164xb, 164xc, 164xd, 164xe, 164xf, 164xg, 164xh, 164xi, 164xj, 164xk, 164xl, 164xm, 164xn, 164xo, 164xp, 164xq, 164xr, 164xs, 164xt, 164xu, 164xv, 164xw, 164xx, 164xy, 164xz, 164ya, 164yb, 164yc, 164yd, 164ye, 164yf, 164yg, 164yh, 164yi, 164yj, 164yk, 164yl, 164ym, 164yn, 164yo, 164yp, 164yq, 164yr, 164ys, 164yt, 164yu, 164yv, 164yw, 164yx, 164yy, 164yz, 164za, 164zb, 164zc, 164zd, 164ze, 164zf, 164zg, 164zh, 164zi, 164zj, 164zk, 164zl, 164zm, 164zn, 164zo, 164zp, 164zq, 164zr, 164zs, 164zt, 164zu, 164zv, 164zw, 164zx, 164zy, 164zz

B Inspection reports, DE Bulletin and correspondence

790306080 Forwarded IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/23 2pp

790306080 Forwarded IE Info Notice 79-07, "Response of Redwood Tanks"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/26 2pp

790306080 Forwarded IE Bulletin 79-08, "Review of Operational Errors &
Site Missions Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 2pp

790306080 Forwarded IE Bulletin 79-09, "Seismic Stress Analysis of
Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 1p

790306080 Forwarded IE Bulletin 79-09, "Seismic Response to Boiling
Water Reactor Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 1p

790306080 Forwarded IE Info Notice 79-10, "Non-safety-Related Pipe Support
Buckling"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 2pp

790306080 Forwarded IE Bulletin 79-09, "Failures of 8E Type A-2
Circuit Breaker in Safety-Related Sys." License action
required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/17 1p

790306080 Act receipt of 790406 1st Informing NRC of steps taken to
correct violations noted in IE Insp Reps 80-400/79-05
30-101/79-05-20-002/79-05-1 & 30-102/79-05-20
MEPHR, C. E. Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/04/17 2p

DOCKETED ITEMS

197

7906000073 Forwards IE Bulletin 79-044-Revision 1, "Review of Operational Errors & Opa Misalignments Identified During THE Incident -"
O'NEILL, J. P. Region 2: Atlanta, Office of the Director
7/9/04/18 App

7906200015 Ask Receipt of IE Insp Repts 50-400/79-04-50-401/79-04-50-402/79-05-50-403/79-05-790402-05. No proprietary info
HARRIS, P. N. Carolina Power & Light Co. 7/9/04/26 App

--7905200017 Forwards IE Insp Repts 50-400/79-04-50-401/79-04-50-402/79-05-50-403/79-05-790402-05. No noncompliance noted
HARRIS, P. N. Region 2: Atlanta, Reactor Construction & Engineering Support Branch 7/9/04/19 App

--7905200020 IE Insp Repts 50-400/79-04-50-401/79-04-50-402/79-05-50-403/79-05-790402-05. No noncompliance noted. Major areas inspected project status, cost estimate review & license action on previous line findings
HARRIS, P. N. Region 2: Atlanta, Office of the Director
HARRIS, P. N. Region 2: Atlanta, Reactor Construction & Engineering Support Branch 7/9/04/19 App

R Periodic operating reports & related correspondence

7905000475 Forwards "Seismic Monitoring Program, First Data Rept."
790430-790331
HARRIS, P. N. A. Carolina Power & Light Co. 7/9/04/03 App

--7905000480 "Seismic Monitoring Program, First Data Rept." 790430-790331
HARRIS, P. N. A. Carolina Power & Light Co. 7/9/04/03 App

B Reportable occurrences, LERs & related correspondence

7905140419 Informs that during 790102 site audit of const activities, inspectors notified of potential reportable item re containment water proofing nearshore leakage. Reportability not yet determined. Final decision by 790301
HARRIS, P. N. A. Carolina Power & Light Co. 7/9/01/22 App

7905110002 Board notification Reactor refueling water storage tank design deficiency
HARRIS, P. N. A. Carolina Power & Light Co. 7/9/03/28 App

DOCKET 03-402 RE-ENTRY HARRIS NUCLEAR POWER PLANT, UNIT 3
A Application/construction stage documents & correspondence

7905240429 Notification of 790506 meeting w/uttl in Bethesda, MD to discuss preparation of environ rept
HARRIS, P. N. A. Environmental Projects Branch 2 7/9/04/27 App

7905000482 Forwards overlaid maps & photo attachments to Unit 790129 rept on main dam core trench features. M/s drawings
HARRIS, P. N. A. Carolina Power & Light Co. 7/9/03/08 App

7905050016 Informs of design change notices re selective content of 790121 applicant Category 1 structures & of reactor core melt for main & auxiliary dam & separating dike. Revision of problem will be documented in PRA
HARRIS, P. N. A. Carolina Power & Light Co. 7/9/05/09 App

7905200030 Response to Region II 790304 request for criteria used to approve previously placed backfill
HARRIS, P. N. A. Carolina Power & Light Co. 7/9/05/16 App

B Adjudicatory correspondence

7905200036 Response to Intervenor's Conservation Council of NC & Wake Environ. Inc 790304 motion to remand to ABL for further hearings w/ re petition to reopen record. Certificate of Evt
HARRIS, P. N. A. Branch 3 7/9/03/16 App

7905300480 Responds to 790310 request of Nuclear Alliance & W Edmonson re 790210 ALAB-826 affirming 790310 order denying series of petitions filed by Intervenor. Supporting Documentation & Certificate of Evt encl.
HARRIS, P. N. A. Branch 3 7/9/03/21 App

7905200029 NRC motion to accept exhibits into evidence re mgt capability of applicant to carry & operate proposed facility. Certificate of Evt encl.
HARRIS, P. N. A. Branch 3 7/9/03/20 App

--7905200030 Responds to NRC 790327 ltr re violations noted in IE Insp Repts 50-400/79-04-50-401/79-04-50-402/79-05-50-403/79-05-790402-05. Corrective actions appropriate personnel instructed in document signout procedures
HARRIS, P. N. Carolina Power & Light Co. 7/9/04/06 App

7905010115 Forwards request for Board notification re non-safety-grade equipment to mitigate transients
HARRIS, P. N. A. Hearings Division 7/9/04/02 App

--7905010155 Board notification staff assessment re non-safety-grade equipment to mitigate transients
HARRIS, P. N. A. Assistant Director for Light Water Reactors 7/9/03/29 App

--7905010190 Board notification recent issue on non-safety-grade equipment to mitigate transients. More info is required
HARRIS, P. N. A. Assistant Director for Reactor Safety 7/9/03/16 App

7905000029 Applicant has no objection to NRC 790330 motion to accept into evidence Exhibits 12, 13, 14, 15, 16 & 20 from recent proceedings. Certificate of Evt encl.
HARRIS, P. N. A. Branch 3 7/9/04/04 App

7905200019 Forwards 790419 Press Release 79-19 re issuance of NRC policy statement on Reactor Safety Study. Its review by Louis Daniel & MARR-1000 are ongoing.
HARRIS, P. N. A. Branch 3 7/9/04/04 App

7905050016 Informs ABL of review of cell security info re sabotage of spent nuclear fuel. Forwards transmittal memo NRC assessment of significance of info to be forwarded when available
HARRIS, P. N. A. Branch 3 7/9/04/05 App

7905020043 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of BOCB performance characteristics. NRC does not consider issue relevant to proceeding
HARRIS, P. N. A. Branch 3 7/9/04/06 App

7905040003 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents
HARRIS, P. N. A. Branch 3 7/9/04/05 App

7905000132 Forwards NRC 790312 survey re use of MARR-1400 in licensing process
HARRIS, P. N. A. Branch 3 7/9/04/10 App

7905110418 Response to ALAB-826 re radon emissions & de minimus theory from Purkin record Certificate of Evt encl.
HARRIS, P. N. A. Hearings Division 7/9/04/11 App

7905140019 Response to 790404 brief of Philadelphia Electric Co. REED & Atlantic City (NJ) Electric Co re de minimus theory. Certificate of Evt encl.
HARRIS, P. N. A. Citizens for Safe Environment 7/9/04/11 App

7905100043 Forwards 790330 motion All requested exhibits mentioned in motion were submitted during Raleigh, NC hearings, which respondent attended w/ encl.
HARRIS, P. N. A. Branch 3 7/9/04/13 App

7905140021 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision. Certificate of Evt encl.
HARRIS, P. N. A. Branch 3 7/9/04/13 App

--7905140021
hearing
O'NEILL,
7/9/04/17

7905140031
supplies
HARRIS,
7/9/04/17

7905140032
motions
for summary
judgment
HARRIS,
7/9/04/17

7905200021
C Board case
proceedings
HARRIS,
7/9/04/17

DOCKETED ITEMS

790502008 Summary of 790502 Affirmation Session 79-10 In Washington DC re NRC's 79-10-20 motion to reopen hearings in Sherron Harris proceeding & NRCV-79-10A-Nuclear PSIA Appeal 78-8-20
GHEIL, J. Office of the Secretary of the Commission 79/03/04
1p

790502052 Inform parties of possibility of taking official notice re test of viscosity. Objections to ASLR procedure must be filed within ten days Supporting documentation & Certificate of Doc. sent.
GHEIL, M. Atomic Safety and Licensing Board Panel 79/03/05 2pp

0 Inspection reports, IE Bulletins & correspondence

790503018 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
GHEIL, J. P. Region 2, Atlanta, Office of the Director 79/03/23 3pp

790503024 Forwards IE Info Notice 79-07, "Structure of Redundant Tanks."
GHEIL, J. P. Region 2, Atlanta, Office of the Director 79/03/26 3pp

790504018 Forwards IE Bulletin 79-08, "Review of Operational Errors & Key Misalignments Identified During DM Incident"
GHEIL, J. P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

790504024 Forwards IE Bulletin 79-09, "Seismic Stress Analysis of Safety-Related Piping" License action required
GHEIL, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

790504032 Forwards IE Bulletin 79-09, "Events Relevant to Entitled Water Pump Reactors Identified During DM Incident"
GHEIL, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

790504034 Forwards IE Info Notice 79-10, "Noninterfering Pipe Support Straps"
GHEIL, J. P. Region 2, Atlanta, Office of the Director 79/04/14 3pp

790505014 Forwards IE Bulletin 79-09, "Failure of DE Type AA-2 Circuit Breaker In Safety-Related Bus" License action required
GHEIL, J. P. Region 2, Atlanta, Office of the Director 79/04/17 1p

790506035 Act receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-403/79-01 & 50-403/79-02
50-403/79-02 50-403/79-01 50-403/79-01
HARRIS, C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 1p

790506035 Responses to NRC 790507 ltr re violations noted in IE Insp Repts 50-403/79-02 50-403/79-01 50-403/79-01
Corrective actions appropriate personnel involved in document close-out procedures
HARRIS, C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 1p

790506037 Forwards IE Bulletin 79-08A Revision 1, "Review of Operational Errors & Key Misalignments Identified During DM Incident"
GHEIL, J. P. Region 2, Atlanta, Office of the Director 79/04/18 3pp

790506065 Act receipt of IE Insp Repts 50-403/79-06 50-403/79-06 50-403/79-05 & 50-403/79-05 on 790403-05 No noncompliance info.
HARRIS, C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 3pp

790506067 Forwards IE Insp Repts 50-403/79-06 50-403/79-06 50-403/79-05 & 50-403/79-05 on 790403-05 No noncompliance noted
HARRIS, C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 3pp

790506068 IE Insp Repts 50-403/79-06 50-403/79-06 50-403/79-05 & 50-403/79-05 on 790403-05 No noncompliance noted Major areas inspected, project status, correct contract review & license action on previous Insp findings.
HARRIS, C. Region 2, Atlanta, Office of the Director.
HARRIS, A. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 3pp

B. Periodic operating reports & related correspondence

7905070470 Forwards "Seismic Monitoring Program, First Data Rept."
790507-790501.
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/09 1p

7905070480 "Seismic Monitoring Program, First Data Rept." 790507-790501
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/09 1p

C. Reportable occurrences, LERs & related correspondence

790510019 Inform that during 791027 site audit of containment activities, inspectors notified of potential reportable item re containment water proofing membrane leakage. Reliability not yet determined. Final decision by 791201
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/11/22 1p

790511052 Board notification Rebarbed rebarbed water storage tank design deficiency
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/29 3pp

DOCKET 30-403 SHERRON HARRIS NUCLEAR POWER PLANT, UNIT 4

A. Application/construction stage documents & correspondence

790504059 Notification of 790503 meeting w/UTL in Bethesda, MD to discuss preparation of various rept
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/27 1p

790504063 Forwards forwarded assn & photo attachments to unit 791017 rept on main dome core breach features. No drawings
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/06 3pp

790505040 Inform of design change notices re moisture content of backfill against Category 1 structures & of central core melt for main & auxiliary duct & separating duct. Resolution of problem will be documented in PSAR.
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/09 3pp

790505050 Response to Region II 790504 request for criteria used to approve previously placed backfill
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 7pp

D. Regulatory correspondence

790505056 Response to Interagency Conservation Council of NC & Nels. Counties. Ltr 790526 motion to amend to ASLR for further hearings w/er protection to reopen record Certificate of Doc. sent.
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 3pp

790505060 Response to 790513 request of Nucleo Alliance V M Edelman re 790513 ALAD-326 decision affirming 790510 order denying access of petition filed by Interagency Conservation Council of NC & Nels. Counties. Ltr 790513 motion to amend to ASLR for further hearings w/er protection to reopen record Certificate of Doc. sent.
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 3pp

790505062 NRC motion to accept exhibits late evidence re apt capability of applicant to comb & separate proposed facility Certificate of Doc. sent.
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 3pp

790505063 Forwards request for Board notification re non-safety-grade equipment to mitigate transients
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 3pp

790505064 Board notification re non-safety-grade equipment to mitigate transients
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 3pp

790505065 Board notification re non-safety-grade equipment to mitigate transients. More info is required.
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 3pp

790505066 Applicant has no objection to NRC 790506 motion to accept late evidence Exhibits 52, 13, 14, 15, 16 & 20 from recent proceedings Certificate of Doc. sent.
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 3pp

790505067 Forwards 790514 Press Release 79-10 re issuance of ASLR petition on Reactor Safety Study, its review by Lewis & Clark & ASLR-1400 law survey.
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 3pp

790505068 Inform ASLR of review of radiological info re subsept of spent nuclear fuel. Forwards. Inform ASLR of ASLR assessment of significance of info to be forwarded when available
GHEIL, J. P. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/10 3pp

7905000442 Forwards draft memo discussing aspects of accumulator delivery identified in NRC studies of ECCS performance characteristics. NRC does not consider issues relevant to proceeding.
SANTOLIC, C. A. Branch 3 79/04/05 5pp

7905000703 Forwards memo re behavior of Indian during postulated steam generator tube rupture accidents.
SANTOLIC, C. A. Branch 3 79/04/05 1p

7905000932 Forwards 701211 NRC survey re use of WASH-1400 in licensing process.
SANTOLIC, C. A. Branch 3 79/04/10 90pp

7905010418 Response to ALAB-509 re radon emissions & de minimus theory from Parties record Certificate of Etc and
BOINTE, J. P. Hearings Division 79/04/11 45pp

7905040517 Response to 790424 Brief of Philadelphia Electric Co-FOEA & Atlantic City 1110 Electric Co re de minimus theory Certificate of Etc and
REDFORD, R. Citizens for Safe Environment 79/04/11 8pp

7905010902 Forwards 790330 motion all requested exhibits mentioned in motion were submitted during Raleigh, NC hearing, which respondent attended W/A and
REIB, E. J. Branch 3 79/04/13 1p

7905040521 Forwards applicant's transcript corrections & applicant's proposed findings of fact & conclusions of law in the form of supplemental initial decision Certificate of Etc and
WENSHAM, D. P. Shaw, Pittman, Potts, & Trowbridge 79/04/17 1p

7905040523 Lists corrections to be made in transcripts of evidentiary hearing conducted on 790227-0302 & 790208-03 in Raleigh, NC.
O'REILLY, J. P. Shaw, Pittman, Potts, & Trowbridge 79/04/17 3pp

7905040531 Proposed findings of fact & conclusion of law in form of supplemental initial decision (CFI) List of exhibits and
WENSHAM, D. P. Shaw, Pittman, Potts, & Trowbridge 79/04/17 84pp

7905020509 Cites evident error in proposed findings of fact of Carolina Power & Light Co counsel no statement allowed by Nucleus Alliance or other parties Requests more participation be allowed
KORLEMAN, M. Nucleus Alliance 79/04/21 1p

7905040532 Notifies of consolidation of five intervenor groups re radon emissions from Parties have until 790503 in which to file for summary disposition
CUMPLIO, R. E. Atomic Safety and Licensing Appeal Panel 79/04/23 13pp

7905040531 Comments on ASL findings re still operating record Supports board condition facility due in light of still operating problems
KORLEMAN, M. Affiliation Unknown 79/04/27 3pp

7905020510 Summary of 790502 Affirmation Session 79-10 in Washington, DC re DECY-A-79-20 motion to reopen hearings in Sharon Harris proceeding & DECY-79-10a, Kranich FOIA Appeal 79-A-20
CHILM, R. J. Office of the Secretary of this Commission 79/05/04 1p

7905020512 Informs parties of possibility of taking official notice re test for viscosity objections to ASL procedure must be filed within 10 days. Supporting documentation & Certificate Etc and
SHETTS, C. H. Atomic Safety and Licensing Board Panel 79/05/10 5pp

0 Inspection reports, IE Bulletins & correspondence

7905010148 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/23 2pp

7905030284 Forwards IE Info Notice 79-07, "Rupture of Reducible Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/26 5pp

7905040142 Forwards IE Bulletin 79-08, "Review of Operational Errors & Realignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 8pp

7905040201 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." License action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7905040329 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Reactor Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

790501024 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/19 2pp

7905030341 Forwards IE Bulletin 79-05, "Failures of DE Type AM-2 Circuit Breaker in Safety-Related Systems - Licensee action required."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17 1p

7905030325 Act receipt of 790426 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-400/79-04, 30-401/79-04, 30-402/79-04, & 30-403/79-04.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 1p

7905030330 Response to NRC 790327 ltr re violations noted in IE Insp Repts 30-400/79-04, 30-401/79-04, 30-402/79-04, & 30-403/79-04.
CORRECTIVE actions appropriate personnel instructed in document close-out procedures.
HOLME, P. H. Carolina Power & Light Co 79/04/04 5pp

7905030370 Forwards IE Bulletin 79-04a, Revision 1, "Review of Operational Errors & Realignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/10 2pp

7905020313 Act receipt of IE Insp Repts 30-400/79-04, 30-401/79-04, 30-402/79-04, & 30-403/79-04 on 790408-03. No proprietary info
HOLME, P. H. Carolina Power & Light Co 79/04/26 2pp

7905020317 Forwards IE Insp Repts 30-400/79-04, 30-401/79-04, 30-402/79-04, & 30-403/79-04 on 790408-03. No proprietary info
HOLME, P. H. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/19 2pp

7905020320 IE Insp Repts 30-400/79-04, 30-401/79-04, 30-402/79-04, & 30-403/79-04 on 790408-03. No noncompliance noted. Major items inspected project status, cost contract review & license action on previous Insp findings.
BRADLEY, D. B. Region 2, Atlanta, Office of the Director 79/04/19 3pp

7905020320 IE Insp Repts 30-400/79-04, 30-401/79-04, 30-402/79-04, & 30-403/79-04 on 790408-03. No noncompliance noted. Major items inspected project status, cost contract review & license action on previous Insp findings.
BRADLEY, D. B. Region 2, Atlanta, Office of the Director 79/04/19 3pp

B. Periodic operating reports & related correspondence

7905070475 Forwards "Seismic Monitoring Program, First Data Rept."
790436-790321
HOLME, P. H. Carolina Power & Light Co 79/04/30 1p

7905070480 "Seismic Monitoring Program, First Data Rept." 790330-790331.
HOLME, P. H. Carolina Power & Light Co 79/04/30 8pp

B. Reportable occurrences, LMRs & related correspondence

7905100114 Informs that 790407 acts audit of const activities. Inspections notified of potential reportable items re containment water proofing membrane leakage. Reportability not yet determined. Final decision by 790201.
CHANDLER, R. J. Carolina Power & Light Co 79/11/22 1p

7905100203 Heard notification/Rebarwork refueling water storage tank design deficiency
BOINTE, J. P. Hearings Division 79/03/29 30pp

DOCKET 79-044 NORTH ANNA POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

7905030385 Forwards info re calculating flow at various locations in reactor vessel. Flow values provided at core edge at inside radius of reactor vessel & at outside radius of reactor vessel.
HOLME, R. L. Belcor & Wilcox Co 79/03/03 3pp

7905100277 Advises that still position is not in accordance w/Reg Guide 1.1, "Hot Positive Section Head for ECCS & Containment Heat Removal Bay Pumps."
HOLME, R. L. Virginia Electric & Power Co 79/05/05 1p

DOCKETED ITEMS

7905020501 Defines unit's nonconforming position on Reg Guide 1.80.
Concrete Placement in Category I Structures -
BROWN, C. Virginia Electric & Power Co 7/9/05/17 2pp

I Financial information

7905020409 Forwards REC 790221 1tr & registration statement Will will file another statement which REC will be able to review
ROSENCRANK, M Light Meter Reactors Branch 2. 7/9/04/09 1p

7905020446 Forwards REC 790334 registration statement filed by which Requests comments by 790333/0111 which statement to become effective by 790402
MORIN, H. F. Securities & Exchange Commission 7/9/03/21 60pp

J Insurance & indemnity information

7905101507 Amend to Endorsement S1 to NELA Policy NP-186 Constitutes Endorsement S1
Nuclear Energy Liability Insurance Association 7/9/04/27 1p

7905020497 Confirms increased liability limit to \$124,000,000 for policies NP-1-25, 43, 78, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 176, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215 & others.
GANTTSS00011-J American Nuclear Insurers 7/9/05/01 1p

7905020492 Confirms increase in liability limit to \$26,000,000 for policies NP-20, 28, 29, 38, 39, 44, 46, 47, 49, 55, 56, 58, 59, 64, 65, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROSENCRANK, M. Mutual Atomic Energy Liability Underwriters 7/9/05/01 1p

7905101509 Endorsements 16, 20, 26 & 47 to NELA Policy NP-186
BARNES, C. R. Nuclear Energy Liability Insurance Association 7/9/05/01 1p

7905020504 Forwards Endorsements 17, 20 & 21 to NELA Policy NP-246
HOLLEY, F. J. Johnson & Higgins Insurance 7/9/05/02 4pp

G Inspection reports, IE Bulletins & correspondence

7905101524 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/02/23 2pp

7905020519 Forwards IE Info Notice 79-07, "Review of Radiactive Tanks"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/02/06 2pp

7905020103 Forwards IE Bulletin 79-06, "Review of Operational Errors & Age Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/11 1p

7905020254 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Age Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/14 2pp

7905020273 Forwards IE Bulletin 79-07, "Heimlich Stress Analysis of Safety-Related Piping" - License action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/14 1p

7906040440 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/14 1p

7906020317 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/16 2pp

7905020181 Forwards IE Bulletin 79-06, "Failures of SG Type AG-2 Circuit Breaker in Safety-Related Bay" - License action required.
BARNES, C. R. Region 2, Atlanta, Office of the Director 7/9/04/17 2pp

7905020502 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Age Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/18 2pp

DOCKET 30-405 NORTH ANNA POWER STATION, UNIT 4

A Applications/construction stage documents & correspondence

7905020393 Forwards info re calculating Flux at various locations on reactor vessel. Flux values provided at core edge at inside radius of reactor vessel & at outside radius of reactor vessel.
MORIN, H. L. Babcock & Wilcox Co 7/9/03/03 2pp

7905102077 Advises that unit position is not in accordance with Guide 1.1, "New Positive Section Head for SCSS & Containment Head Removal Bay Pumps"
BROWN, C. Virginia Electric & Power Co 7/9/05/08 1p

7905020511 Defines unit's nonconforming position on Reg Guide 1.80.
Concrete Placement in Category I Structures -
BROWN, C. Virginia Electric & Power Co 7/9/05/01 2pp

I Financial information

7905020409 Forwards REC 790221 1tr & registration statement Will will file another statement which REC will be able to review
ROSENCRANK, M Light Meter Reactors Branch 2. 7/9/04/09 1p

7905020446 Forwards 790334 REC registration statement Requests comments by 790335, as still wishes statement to become effective by 790402
MORIN, H. F. Securities & Exchange Commission 7/9/03/21 60pp

J Insurance & indemnity information

7905101507 Amend to Endorsement S1 to NELA Policy NP-186 Constitutes Endorsement S1
Nuclear Energy Liability Insurance Association 7/9/04/27 1p

7905020497 Confirms increased liability limit to \$124,000,000 for policies NP-1-25, 43, 78, 83, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 176, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215 & others.
GANTTSS00011-J American Nuclear Insurers 7/9/05/01 1p

7905020492 Confirms increase in liability limit to \$26,000,000 for policies NP-20, 28, 29, 38, 39, 44, 46, 47, 49, 55, 56, 58, 59, 64, 65, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
ROSENCRANK, M. Mutual Atomic Energy Liability Underwriters 7/9/05/01 1p

7905020504 Forwards Endorsements 17, 20&21 to NELA Policy NP-246
HOLLEY, F. J. Johnson & Higgins Insurance 7/9/05/02 4pp

7905101509 Endorsements 16, 20, 26 & 47 to NELA Policy NP-186
BARNES, C. R. Nuclear Energy Liability Insurance Association 7/9/05/01 1p

G Inspection reports, IE Bulletins & correspondence

7905101524 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/02/23 2pp

7905020519 Forwards IE Info Notice 79-07, "Review of Radiactive Tanks"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/02/06 2pp

7905020103 Forwards IE Bulletin 79-06, "Review of Operational Errors & Age Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/11 1p

7906040440 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Age Misalignments Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/14 2pp

7905020273 Forwards IE Bulletin 79-07, "Heimlich Stress Analysis of Safety-Related Piping" - License action required
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/14 1p

7906040440 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident"
O'REILLY, J. P. Region 2, Atlanta, Office of the Director 7/9/04/14 1p

DOCKETED ITEMS

201

7905010317 Forwarded IE Info Notice 79-10, "Nonconforming Pipe Support
Struts"
O'NEILL, J P Region 2, Atlanta, Office of the Director
79/05-1A 200

790800132 Forwards draft evaluation of systematic evaluation program
Topic 1W-6 A Requests review & response within 30 days
2208000, D L Operating Reactors Branch 2 79/04/17 Pgs

770503049; Forwarded IE Bulletin 77-05. "Failures of OE Type AK-2
Circuit Breaker in Safety-Related Sys " Licensee action
required
G'NEILL, J P Region 2, Atlanta: Office of the Director
77/04/17 309

22EHAN, D I Operating Reactors Branch 2 79/04/19 6pp

7405020000 Forwarded DE Bulletin 77-055, Revision 1, "Review Operational Errors & Sys Misalignments Identified During Incident"
@REELLY, J P Region 2, Atlanta; Office of the Director
77/04/18 200

7900063373 Forwards "Structural Analysis Design Rept For LACBR
Replacement Peripheral Shroud"
LINCOR, Gainland Power Cooperative 79/04/00 Doc

==7909040375 "Structural Analysis Design Rept For LACBR Replacement
Peripheral Shield"
ORNL-4000-A, HILDEB, VANCE A H Nuclear Energy Service, Inc
78/11/17 60pp

DOCKET NO. 454, TURNER V. IHRF, RESEARCH REACTOR

Insurance & indemnity information

7905140204 Forwards Amend 5 to Indemnity Agreement E-87, per 10CFR40 changes: re increase from \$140 million to \$160 million, effective 790501. Supporting documentation encl.

7700800043 Responds to NRC 770008 Dir re ATWS requirements & recirculation pump trip design. ATWS procedures added to operating manual; operator training accomplished & recirculation pump trip design effort is in progress. LINCOLN, C. DuPont Power Generation. 27/04/2002. 2pp

7903240675 Amend 5 to Indemnity Agreement E-57 increasing amount
of coverage to \$160,000,000
SALTMAN, J Antitrust & Indemnity Group * Taskforce Inst
79/05/15 lp

7905160425 Edwards "Cycle B Fuel Performance & Finalized Refueling Plan for Cycle B." Apr 1970 Includes responses to NRC 790424 request for addl info re rad withdrawal error & other transient analyses
CANDOR-C, Dairfield Power Cooperative, 790505JTW, 21pg

==7905160427 "Cycle B Fuel Performance & Finalized Reducing Plan for
Cycle A," Apr 1979
BAPFTV, B & Delivered Power Cooperative BUCKP Nuclear Energy
Services, Inc 79/04/20 23pg

© Immigration experts, IE Bulletin & correspondence

7900070102 Forwards IE Bulletin 79-05, 79-05A & 79-06 re nuclear
incident at THE
ORRISVILLE, Pa Region 2, Atlanta, Office of the Director
79/0-6/13 1a

7900220304 Request to amend to License BPR-45, changing Tech Specs re
inservice insp program, which is in conflict w/1974 edition
of AGNE Section XI Supporting documentation will
be submitted. E. Bainland, Power Conservator, 79/08/01, Am

DOCIDET NO-807 UNIV OF UTAH RESEARCH REACTOR

2. Insurance & indemnity information

7905000004 Forwards Amend IO to Indemnity Agreement E-31, reflecting change in GDPB140, increasing primary layer of liability from \$140 million to \$160 million, effective 790500
Supporting documentation encl
RSLT2MMJ Antitrust & Indemnity Group 79/05/00 App.

7400290386 Act receipt of HRS 750430 ltr re Cagle & fuel performance
Applies for award to provisional GL Submits proposed Tech
Spec change
LINDER, F Saitryland Power Cooperative 79/03/23 App

7903140286: Amend ID to Indemnity Agreement E-35
BALTIMORE, Md Antitrust & Indemnity Group 79/03/07 1p

790308012 Submits application to amend provisional License EPR-45 by proposing changes to Tech Specs re off gas activity W/resp to AEC 790322 query re verification of core configuration for Cycle 4 operation
LINES: 0, Rejoined Power Generation 79/03/22, Age

7903000014 Requests amend to provisional DL. Proposes changes re
isolation of forced circulation loops & increase of
operational condition for reactor vessel water level safety
LSMIS
LSNDS-F Gairland Power Cooperative 79/05/20 App.

DOCKET NO-409 LA CORDRE BOILING WATER REACTOR

d. Insurance & indemnity information

7903160157 Forwards Asset 5 to Indemnity Agreement B-62, per 10CFR140 changes: liability insurance increase from \$140 million to \$160 million, effective 790301. Supporting documentation encl. SAL/THAN.J. Antibiot & Indemnity Group. 79/05/01 Sp.

760090173 Forward: DE Inap Rpt 54-404774-03 on 790221-23 Re
sanctions/force related
HEISHMAN, R F Region 3, Chicago, Reactor Operations Mgr
Success Search 79/05/22 Doc

7905080175 EE Insp Rept 80-404/79-03 on 790201-23 Re noncompliance noted Major areas inspected core thermal power evaluation, control rod scan line test, comparison of calculated power shape w/incore monitor & determination of shutdown margin CHOW, E.T., STROTHER, J.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch CERNOWELL, J.S. Region 3, Chicago, Office of the Director 79/03/14 4aa

7905110303 Forwards Amend 5 to Indemnity Agreement E-42.
LINDBER, P. Sube Power Co 79/05/07 Doc

790031033? Forwards Endorsements SI & SR to AMT Policy WP-217
OSVINE, R P. Cleveland Power Cooperative 79/09/22 3pg

B. Operating license cases documents & correspondence

79080000332 Forwards draft rept "Review of Liquefaction Potential: L&L
near Genoa, Versen Coast, NJ"
RICH, R., KATARA, J. M. Dames & Moore 79/03/12 1p

7903010201 Forwards IE info Notice 79-06: "Stress Analysis of Safety-Related Piping"
KEPLER, J G Region 3, Chicago, Office of the Director 79/03/23
is

790304185 Requests immediate action re implementation of ICGFR73 50 as
result of 790312-44 Insp & 790321 meeting. Anticipated
action withheld (ref ICGFR74 740)
KORNER, J.G. Section 3, Chicago, Office of the Director 79/03/23

7905060174 Notification of 790426 meeting w/utl in Bethesda, MD to discuss LACBWR Cycle 5 fuel performance & reload Cycle 5
ZIEGLER, D L. Operating Reactors Branch 2 79/04/19. 1p

7903040027 Forwards IE Info Notice 79-07, "Rupture of Reducible Tanks"
KOPPLER, J D Region 3, Chicago, Office of the Director 79/03/26

7909100304 Notification of 790426 meeting w/ell in Silver Spring, MD to discuss Cycle 5 fuel performance & reload Cycle 6. Meeting notes, raw data.
METHNORS, J. B. Operating Reactors Branch 2 79/04/18 is

7508010665 Forwards IR Info Notice 79-06, "Interconnection of Contaminated Sys w/ Dvt Air Sys Used as Source of Breathing Air"
 KAPPLER, J G Region 5, Chicago, Office of the Director 79/03/29
 1c

7708230377 Requests info on HPCS discharge line for systematic
evaluation program review. Requests response within 15 days
DISTANCE L. Operating Reactors Branch 2 77/04/18 App

- 7905000274 Forwards IE Info Notice 79-09, "Hull of Radioactively Contaminated Basin".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/03/30
LINDBER, F. Dairland Power Cooperative 79/04/10 1p
- 7905070036 Response to IE Bulletin 79-04 No chest valves manufactured by Hens Engineering Corp are in use at facility.
LINDBER, F. Dairland Power Cooperative 79/04/10 1p
- 7905000028 Forwards IE Bulletin 79-06, "Review of Operational Errors & Site Missalignments Identified During TMI Incident".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/11 1p
- 7905010025 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Site Missalignments Identified During TMI Incident".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040084 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Site Missalignments Identified During TMI Incident".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040443 Forwards IE Bulletin 79-07, "Reactive Stress Analysis of Safety-Related Piping - Licensee action required".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/14 1p
- 7905040583 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/14 1p
- 7905030220 Forwards IE Bulletin 79-09, "Failures of GE Type AB-2 Circuit Breaker in Safety-Related Bay - Licensee action required".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/17 1p
- 7905060490 Forwards IE Bulletin 79-09B, "Nuclear Incident at TMI-Regd".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/04/21 1p
- 7905040016 Requests extension until 790503 to respond to IE Bulletin 79-09 re TMI effects on Radiation Level.
LINDBER, F. Dairland Power Cooperative 79/04/27 1p
- 7905040496 Response to IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/02 1p
- 7905040896 Forwards IE Bulletin 79-07, "Unexplained Rapid Increase of Reactor Recirculation Nuclear Operator Not Assessed in Reactor Power Increase".
NEPFLER, J. O. Region 3, Chicago, Office of the Director 79/05/02 1p
- 7905020417 Response to IE Bulletin 79-07, Forwards info re seismic stress analysis of safety-related piping.
LINDBER, F. Dairland Power Cooperative 79/05/03 10pp.
- 7905050082 Forwards "Radioactive Effluent Regt & Environ Monitoring Regt" for 1978.
LINDBER, F. Dairland Power Cooperative 79/04/20 1p.
- 7905060036 "Radioactive Effluent Regt & Environ Monitoring Regt" for 1979.
Dairland Power Cooperative 79/05/01 3pp
- 7905100231 Forwards monthly operating rept for Apr 1979.
LINDBER, F. Dairland Power Cooperative 79/05/08 1p.
- 7905100234 Monthly operating rept for Apr 1979.
PAWORTH, L. Dairland Power Cooperative 79/05/07 10pp.
- R. Applicable occurrences, LDBs & related correspondence
- 7905020038 Notification of 790410 RD 79-04: Fuel assembly 2-13 contains fuel rod with degraded cladding.
LINDBER, F. Dairland Power Cooperative 79/04/10 1p
- 7905010004 Forwards LDBs 79-005/017-0 & 79-006/017-0.
LINDBER, F. Dairland Power Cooperative 79/04/10 7pp
- 7905010030 LER 79-005/017-0 on 790403, during refueling, inspection of irradiated fuel assembly 2-13 revealed abnormal degradation in stainless steel fuel cladding of fuel rods caused by pellet/clad interaction. Assembly will not be reused.
PAWORTH, L. Dairland Power Cooperative 79/04/19 1p
- 7905010030 LER 79-006/017-0 on 790410 during refueling, inspection of irradiated fuel assembly 2-13 revealed abnormal degradation in stainless steel fuel cladding of fuel rods caused by pellet/clad interaction. Assembly will not be reused.
PAWORTH, L. Dairland Power Cooperative 79/04/19 1p.
- 7905020043 RD 79-07 on 790403, abnormal degradation discovered in primary reactor containment during type B & C surveillance. Leakage valve testing. Electrical penetration tests performed.
LINDBER, F. Dairland Power Cooperative 79/04/20 2pp
- 7905020517 Forwards LER 79-007/017-0.
LINDBER, F. Dairland Power Cooperative 79/05/09 4pp.
- 7905030033 RD 79-07/017-0 on 790403 electrical penetration tests 3 & 4 did not meet Type B test criteria during periodic leakage rate testing. Cause by individual during periodic penetration tests. Penetration replaced & sealing compound applied.
PAWORTH, L. Dairland Power Cooperative 79/05/09 1p
- 7905020494 Forwards LER 79-008/017-1.
LINDBER, F. Dairland Power Cooperative 79/05/09 1p.
- 7905030407 LER 79-008/017-1 on 790405 during refueling, inspection of irradiated fuel assembly 2-13 revealed abnormal degradation in fuel cladding of fuel rods caused by pellet/clad interaction. Inspection of fuel rods during stress corrosion.
SHIMMURA, E. Dairland Power Cooperative 79/04/19 1p
- DOCKET 80-410 NINE HOLE POINT NUCLEAR STATION, UNIT 2
- A. Applicable construction stage documents & correspondence
- 7905040284 Summary of 790321 meeting of Mark II course group in New York, CA re intermediate plant program tests.
ANDERSON, C. J. Combined Systems Branch 79/04/13 10pp
- J. Insurance & Indemnity Information
- 7905070497 Confirms increased liability limit to \$124,000,000 for policies NP-1, 25, 43, 76, 82, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 183, 184, 187, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
SMITH, T. H. American Nuclear Insurers 79/05/01 1p
- 7905070502 Confirms increase in liability limit to \$34,500,000 for policies NP-1, 25, 43, 76, 82, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 178, 179, 180, 182, 183, 184, 187, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
SMITH, T. H. Mutual Atomic Energy Liability Underwriters 79/05/01 1p
- B. Inspection reports: IE Bulletins & correspondence
- 7905010125 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping".
GRIDER, R. H. Region 1, Philadelphia, Office of the Director 79/03/23 1p
- 7905050071 Forwards IE Bulletin 79-04, "Review of Operational Errors & Site Missalignments Identified During TMI Incident".
GRIDER, R. H. Region 1, Philadelphia, Office of the Director 79/04/11 1p
- 7905050029 Forwards IE Bulletin 79-07, "Reactive Stress Analysis of Safety-Related Piping - Licensee action required".
GRIDER, R. H. Region 1, Philadelphia, Office of the Director 79/04/16 1p.
- 7905040068 Forwards IE Bulletin 79-08B, "Review of Operational Errors & Site Missalignments Identified During TMI Incident".
GRIDER, R. H. Region 1, Philadelphia, Office of the Director 79/04/14 1p
- 7905040235 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident".
GRIDER, R. H. Region 1, Philadelphia, Office of the Director 79/04/14 1p.

DOCKETED ITEMS

203

7905030001 Forwards IE Bulletin 79-05, "Failures of GE Type AR-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
 REGION 1: Philadelphia, Office of the Director
 7/9/84/17 1p

7905030099 Forwards IE Bulletin 79-06, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
 REGION 1: Philadelphia, Office of the Director.
 7/9/84/18 1p

DOCKET 50-413 SEAWAY VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

7905030088 Request plant shutdown because of threat of accident as severe as rupture to reactor vessel.
 BOMBARDIER Affiliation Unknown 7/9/84/12 5pp.

D Adversatory correspondence

7905030067 Forwards CP amend request for extension of expiration date to 8/1/85.
 BUNN, C.N. Duquesne Light Co 7/9/83/09 3pp

7905030069 Application for amend of CPFR-100 to extend completion date to 8/1/85.
 BUNN, C.N. Duquesne Light Co 7/9/83/09 4pp

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies #P-25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, & 96.
 GANTT/CHS/II, J American Nuclear Insurance 7/9/83/01 1p.

7905070502 Confirms increase in liability limit to \$24,000,000 for policies #P-25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, & 96.
 ROBERTS, D.R. Mutual Atomic Energy Liability Underwriters, 7/9/83/01 1p.

D Inspection reports: IE Bulletin & correspondence

7905040106 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping."
 REGION 1: Philadelphia, Office of the Director.
 7/9/83/23 1p.

7905030043 Forwards IE Bulletin 79-04, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
 REGION 1: Philadelphia, Office of the Director
 7/9/84/11 1p.

7905030038 Forwards IE Bulletin 79-07, "Heliose Stress Analysis of Safety-Related Piping." Licensee action required.
 REGION 1: Philadelphia, Office of the Director.
 7/9/84/14 1p.

7905040034 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
 REGION 1: Philadelphia, Office of the Director.
 7/9/84/14 1p.

7905040060 Forwards IE Bulletin 79-08, "Events Relevant to Sealing Water Pumps Reactors Identified During TMI Incident."
 REGION 1: Philadelphia, Office of the Director
 7/9/84/14 1p.

7905030043 Forwards IE Bulletin 79-06, "Failures of GE Type AR-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
 REGION 1: Philadelphia, Office of the Director
 7/9/84/17 1p.

7905030043 Forwards IE Bulletin 79-06, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
 REGION 1: Philadelphia, Office of the Director.
 7/9/84/18 1p.

E Reportable occurrences, LERs & related correspondence

7905030080 Informa that injection pumps have been removed from engines inspected per newly established criteria & reinstalled on engines. All injection pumps in good condition.
 HERRIN, J.H. Cold Industries, Inc. 7/9/83/25 1p.

7905030044 Forwards 790329 Initial interim report on Significant Deficiency 79-01 re Birgham-Williams Co stop work directive. Possibility of significant deficiency reported on 790330 Final report to be issued by 7/9/84.
 MOOREHEAD, C. Duquesne Light Co 7/9/84/25 1p

7905030051 Interim report on Significant Deficiency 79-01 re Birgham-Williams Co stop work directive for pump spray, reconstruction spray & auxiliary feedwater pump spray. SA problem & corrective action.
 Duquesne Light Co 7/9/84/25 2pp

DOCKET 50-413 CATANHA NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

7905030049 Ack receipt of 790221 letter forwarding AD application. Acceptance review to determine compliance with ADs.
 WELLS, D.A. Light Water Reactors Branch 4, 7/9/84/25 3pp.

7905070100 Forwards info in response to request for approval of flexible hoses in control of Class 71 & 111 piping.
 SMILL, C. Duke Power Co 7/9/83/18 5pp.

7905070101 Documentation of Compliance of Metal Bellows Corp Part 74864 to Requirements of ASME Section III N D3647 for Use in Class 71 & Class 111 Piping.
 Duke Power Co. 7/9/83/26 1pp

7905070102 Documentation of Compliance of Metal Bellows Corp Part 74864 to Requirements of ASME Section III N D3647 for Use in Class 71 & Class 111 Piping.
 Duke Power Co. 7/9/83/26 1pp

7905070104 Documentation of Compliance of Metal Bellows Corp Part 74864 to Requirements of ASME Section III N D3647 for Use in Class 71 & Class 111 Piping.
 Duke Power Co. 7/9/83/26 1pp.

7905070104 "Design Rept for House Assembly Flexible Metal," prepared by Metal Bellows Corp for ASME Section III & Pressure Vessel Code Section III N D3647 for Use in Class 71 & 111.
 Duke Power Co. 7/9/83/23 30pp.

J Insurance & indemnity information

7905070497 Confirms increased liability limit to \$124,000,000 for policies #P-25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, & 96.
 GANTT/CHS/II, J American Nuclear Insurance, 7/9/83/01 1p.

7905070502 Confirms increase in liability limit to \$24,000,000 for policies #P-25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, & 96.
 ROBERTS, D.R. Mutual Atomic Energy Liability Underwriters, 7/9/83/01 1p.

D Inspection reports: IE Bulletin & correspondence

7905010103 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
 REGION 2: Atlanta, Office of the Director.
 7/9/83/23 2pp

7905030051 Forwards IE Info Notice 79-07, "Rupture of Radw O'SHELLY, J.P. Region 2: Atlanta, Office of the Director
 7/9/83/26 2pp.

7905040060 Forwards IE Bulletin 79-08, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
 O'SHELLY, J.P. Region 2: Atlanta, Office of the Director.
 7/9/84/14 2pp.

7905040034 Forwards IE Bulletin 79-06, "Heliose Stress Analysis of Safety-Related Piping."
 REGION 2: Atlanta, Office of the Director
 7/9/84/14 2pp.

7905040060 Forwards IE Bulletin 79-08, "Events Relevant to 8 Meter Power Reactors Identified During TMI Incident."
 O'SHELLY, J.P. Region 2: Atlanta, Office of the Director
 7/9/84/14 1p.

7905010236 Forwards IE Info Notice 79-10, "Hot-Confining Pipe Stubs."
 REGION 2: Atlanta, Office of the Director
 7/9/84/14 1p.

DOCKETED ITEMS

7905030150 Forwards IE Bulletin 79-06, "Failures of GE Type A6-2 Circuit Breaker in Safety-Related Sys - Licensee action required."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/17 App

7905030450 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/18 App

7905040162 Act receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 79-013/79-04 & 79-014/79-04.
MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/30 App

--7905140167 Response to NRC 790302 ltr re violations noted in IE Insp Repts 79-013/79-04 & 79-014/79-04. Corrective actions used identifications of both malis & tags were corrected. Piping stored correctly.
SALL, L. C. Duke Power Co. 79/04/19 App

DOCKET 79-414 CATAWBA NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905050103 Forwards info in response to request for approval of discharge tubes in vent of Class II & III piping.
SALL, L. C. Duke Power Co. 79/05/10 App

--7905170101 "Documentation of Compliance of Metal Bellows Comp Part 790402 to Requirements of ASME Section III N 3349 for Use in Class II & Class III Piping."
Duke Power Co. 79/05/20 App

--7905170103 "Documentation of Compliance of Metal Bellows Comp Part 790402 to Requirements of ASME Section III N 3349 for Use in Class II & Class III Piping."
Duke Power Co. 79/05/20 App

--7905170104 "Documentation of Compliance of Metal Bellows Comp Part 790402 to Requirements of ASME Section III N 3349 for Use in Class II & Class III Piping."
Duke Power Co. 79/05/20 App

--7905170106 "Design Rept for House Assembly, Flexible Metal," prepared by Metal Bellows Corp. per ASME Section III N 3349 for Use in Class II & Class III Piping.
Duke Power Co. 79/05/23 App

7901050439 Act receipt of 790301 ltr forwarding Q. application. Acceptance review to determine completeness has begun.
WAGS, B. A. Light Water Reactors Branch 4. 79/04/23 App

J. Insurance & Indemnity Information

7905070497 Confirms increased liability limit to \$125,000,000 for policies AP-125,42,76,82,100,111,140,146,191,141,146,170,175,176,177,180,182,182,186,187,188,189,192,193,194,195,197,199,200,201,204,205,207,208,210,212,214,215, & others.
SALL, L. C. American Nuclear Insurers. 79/05/01 App

7905070502 Confirms increase in liability limit to \$25,000,000 for policies NP-25,38,39,42,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,78,79,80,86,87,88,90,91,92,93,94,95, & 96.
WAGS, B. A. Nuclear Assets Energy Liability Underwriters. 79/05/01 App

G. Inspection reports, IE Bulletins & correspondence

7905010183 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/03/09 App

7905030201 Forwards IE Info Notice 79-07, "Repture of Radiactive Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/03/26 App

7905040162 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 App

7905040266 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 App

7905040266 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 App

7905050206 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/18 App

7905050303 Forwards IE Bulletin 79-06, "Failures of GE Type A6-2 Circuit Breaker in Safety-Related Sys - Licensee action required."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/17 App

7905050453 Forwards IE Bulletin 79-06A, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/18 App

7905140162 Act receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 79-013/79-04 & 79-014/79-04.
MURPHY, C E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/30 App

--7905140167 Response to NRC 790302 ltr re violations noted in IE Insp Repts 79-013/79-04 & 79-014/79-04. Corrective actions used identifications on both malis & tags were corrected. Piping stored correctly.
SALL, L. C. Duke Power Co. 79/04/19 App

DOCKET 79-416 GRAND DULF NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7901050436 Forwards first round request for addl info re age analysis for PWRB rebus.
O'REILLY, J. P. Light Water Reactors Branch 1. 79/04/25 App

B. General correspondence

7905050450 Forwards affidavit of wtr re distribution of Amend 20ppr sent to NRC 790407 ltr.
SALL, L. C. Mississippi Power & Light Co. 79/04/30 App

K. Utility Final Safety Analysis Report (FSAR) & amendments

7905060439 Forwards Amend 30 to FSAR & schedule for completing outstanding first round questions.
STANLEY, M. L. Mississippi Power & Light Co. 79/05/25 App

--7905060441 Amend 30 to FSAR Copies of plant area drainage drawing, equipment test plans & response spectra curves available in Central Files.
Duke Power & Light Co. 79/05/25, 2000pp

L. Inspection reports, IE Bulletins & correspondence

7905010204 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/03/23 App

7905030214 Forwards IE Info Notice 79-07, "Repture of Radiactive Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/03/26 App

7905040266 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 App

7905040312 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director.
79/04/14 App

DOCKETED ITEMS

205

790304030 Forwards IE Bulletin 79-08, "Events Related to Sealing Water Pump Reactors Identified During TMI Incident".
Region 2, Atlanta, Office of the Director
79/04/14, 1p

790303071 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets".
Region 2, Atlanta, Office of the Director
79/04/14, 1p

790303017 Forwards IE Bulletin 79-06, "Failures of GE Type AN-2 Circuit Breaker in Safety-Related Bays". Licensee action required.
Region 2, Atlanta, Office of the Director
79/04/17, 2pp

790302472 Forwards IE Bulletin 79-06a, Revision 1, "Review of Operational Errors & Bys Missalignments Identified During TMI Incident".
Region 2, Atlanta, Office of the Director.
79/04/14, 2pp

790309001 Ack receipt of IE Insp Repts 90-416/79-01 & 90-417/79-01 on 79/03/25. No proprietary info.
79/04/18, 1p

790304035 Responds to HRC 7903032 ltr re violations noted in IE Insp Repts 90-416/79-01 & 90-417/79-02. Corrective actions: Backfill quality action request issued on welding electrodes found in drywell area & supervisors instructed in rec control duties.
79/04/23, 2pp

5 Reportable occurrences, LSRs & related correspondence

790303039 Forwards Final deficiency rept for weld separation on strut leg bearing mesh.
79/03/22, 1p

790304030 Final rept on potentially Reportable Deficiency 79/03 investigation by Backfill revealed factory weld separation on Unisolated Part P1005 mesh. All post welds accept one lot, most required safety factors unacceptable lot isolated.
79/03/22, 1p

790303055 Interim rept on potentially reportable deficiency re circuit separation discrepancies in power generation control complexes. Final rept will be submitted by 79/06/20.
79/03/23, 1p

790304034 Inform of potential Reportable Deficiency 79/03 improper drawings supplied by GE. Reportability is being determined. Final rept will be issued by 79/03/27.
79/03/27, 1p

790303033 Inform of possible defective wall shipment purchased from Tube Turns & shipped to Backfill Power. Manufacturer's recall notice encl.
79/04/04, 1p

790304031 Inform that deficiency reported on 790320 re failure of solid state trip devices was caused by inadequate or incomplete older joints on printed circuit boards. Boards returned to vendor for analysis.
79/04/23, 1p

790304033 Interim Rept 1 for potentially reportable Deficiency 79-07 re circuit separation discrepancies. Final rept will be submitted by 79/06/20.
79/04/23, 1p

DOCKET 90-417 GRAND GULF NUCLEAR STATION UNIT 2

A. Application/construction stage documents & correspondence

790304031 Forwards Final round request for steel lido re sig analysis.
79/04 review.
79/04/25, 4pp

H General correspondence

790304030 Forwards affidavit of svc re distribution of Amend 29 per sent to HRC 7903027 ltr.
79/04/30, 2pp

K Utility Final Safety Analysis Report (FSAR) & amendments

790304039 Forwards Amend 30 to FSAR & schedule for completing outstanding Final round questions.
79/05/25, 4pp

790303044, Amend 30 to FSAR. Copies of plant area drainage drawing, equipment test plans & response spectra curves available in Central Files.
79/03/23, 2000pp

G Inspection reports, IE Bulletins & correspondence

790301004 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping".
Region 2, Atlanta, Office of the Director
79/03/22, 2pp

790303014 Forwards IE Info Notice 79-03, "Sealing of Refueling Tanks".
Region 2, Atlanta, Office of the Director
79/03/26, 1p

790304033 Forwards IE Bulletin 79-08a, "Review of Operational Errors & Bys Missalignments Identified During TMI Incident".
Region 2, Atlanta, Office of the Director
79/04/14, 1p

790304032 Forwards IE Bulletin 79-07, "Mechanic Stress Analysis of Safety-Related Piping". Licensee action required.
Region 2, Atlanta, Office of the Director
79/04/14, 1p

790304030 Forwards IE Bulletin 79-08, "Events Related to Sealing Water Pump Reactors Identified During TMI Incident".
Region 2, Atlanta, Office of the Director
79/04/14, 1p

790301071 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets".
Region 2, Atlanta, Office of the Director
79/04/14, 1p

790303017 Forwards IE Bulletin 79-06, "Failures of GE Type AN-2 Circuit Breaker in Safety-Related Bays". Licensee action required.
Region 2, Atlanta, Office of the Director
79/04/17, 2pp

790302472 Forwards IE Bulletin 79-06a, Revision 1, "Review of Operational Errors & Bys Missalignments Identified During TMI Incident".
Region 2, Atlanta, Office of the Director
79/04/18, 2pp

790309001 Ack receipt of IE Insp Repts 90-416/79-01 & 90-417/79-01 on 79/03/25. No proprietary info.
79/04/18, 1p

790304035 Responds to HRC 7903032 ltr re violations noted in IE Insp Repts 90-416/79-01 & 90-417/79-02. Corrective actions: Backfill quality action request issued on welding electrodes found in drywell area & supervisors instructed in rec control duties.
79/04/23, 2pp

6 Reportable occurrences, LSRs & related correspondence

790303039 Forwards Final deficiency rept for weld separation on strut leg bearing mesh.
79/03/22, 1p

790304030 Final rept on potentially Reportable Deficiency 79/03 investigation by Backfill revealed factory weld separation on Unisolated Part P1005 mesh. All post welds accept one lot, most required safety factors unacceptable lot isolated.
79/03/22, 1p

790303055 Interim rept on potentially reportable deficiency re circuit separation discrepancies in power generation control complexes. Final rept will be submitted by 79/06/20.
79/03/23, 1p

790304034 Inform of potential Reportable Deficiency 79/03 improper drawings supplied by GE. Reportability is being determined. Final rept will be issued by 79/03/27.
79/03/27, 1p

790303033 Inform of possible defective wall shipment purchased from Tube Turns & shipped to Backfill Power. Manufacturer's recall notice encl.
79/04/04, 1p

790304031 Inform that deficiency reported on 790320 re failure of solid state trip devices was caused by inadequate or incomplete older joints on printed circuit boards. Boards returned to vendor for analysis.
79/04/23, 1p

7905040031 Interior Dept 1 for potentially reportable Deficiency 79-07 re circuit separation design/analysis. Final report will be submitted by 790505
 MCSA/STC/J.P. Miscellaneous Power & Light Co. H. 79/04/23. 1p.

DOCKET 50-424 HELLTOWN NUCLEAR POWER STATION, UNIT 2

A. Application/inspection stage documents & correspondence

7905050437 Forward draft application for extension of OPR-113 to New 1985
 FOSTER, E.R. Northwest Utilities. 79/05/09. 3pp

J. Insurance & indemnity information

7905050442 Forward Amend 14 to Indemnity Agreement 8-09 per 195PR140 changes re increase in liability insurance from \$400 million to \$100 million effective 790501. Supporting documentation and
 SALTZMAN, J. Antitrust & Indemnity Group. 79/05/01. 4pp

7905050455 Forward executed Amend 14 to Indemnity Agreement 8-09
 O'CONNOR, A. Northwest Utilities. 79/05/15. 4pp.

B. Inspection reports, IE Bulletins & correspondence

7905050181 Forward IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
 ORTIZ, E.H. Region 3, Philadelphia. Office of the Director. 79/05/23. 1p.

7905050202 Forward IE Info Notice 79-08, "Interconnection of Contaminated Dye w/DCR Air Dye Used as Source of Breathing Air."
 ORTIZ, E.H. Region 3, Philadelphia. Office of the Director. 79/05/28. 1p.

7905050354 Forward IE Info Notice 79-09, "Mill of Radioactively Contaminated Basin."
 ORTIZ, E.H. Region 3, Philadelphia. Office of the Director. 79/05/30. 2pp.

7905050364 Forward IE Bulletin 79-36, "Review of Operational Errors & Site Misalignments Identified During TMI Incident."
 ORTIZ, E.H. Region 3, Philadelphia. Office of the Director. 79/04/11. 1p.

7905050390 Forward IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping." Licensee action required.
 ORTIZ, E.H. Region 3, Philadelphia. Office of the Director. 79/04/14. 1p.

7905050399 Forward IE Bulletin 79-06, "Review of Operational Errors & Site Misalignments Identified During TMI Incident."
 ORTIZ, E.H. Region 3, Philadelphia. Office of the Director. 79/04/14. 1p.

7905050414 Forward IE Bulletin 79-08, "Events Relevant to Sealing Water Pump Reactor Identified During TMI Incident."
 ORTIZ, E.H. Region 3, Philadelphia. Office of the Director. 79/04/14. 1p.

7905050577 Forward IE Bulletin 79-09, "Failures of QC Type AM-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
 ORTIZ, E.H. Region 3, Philadelphia. Office of the Director. 79/04/17. 1p.

7905050584 Forward IE Bulletin 79-06, Revision 1, "Review of Operational Errors & Site Misalignments Identified During TMI Incident."
 ORTIZ, E.H. Region 3, Philadelphia. Office of the Director. 79/04/18. 1p.

B. Reportable occurrences, LERs & related correspondence

7905050599 Refuse of completion of analysis of injection pump failures. Failures were result of surface irregularities on barrel after plunger-incorrect seal. Air new pump Pump removed from facility.
 MCINTYRE, J.M. Colt Industries Inc. 79/05/22. 1p.

DOCKET 50-424 ALVIN W. MOFFLE NUCLEAR PLANT, UNIT 1

A. Application/inspection stage documents & correspondence

7905050241 Inform that spare multipot discharge diffuser will be installed. Discharge in cost spare versus 38-day compressive strength concrete referenced in PSAR Section D B Requests prompt concurrence.
 DUNHAM, R.D. Georgia Power Co. 79/04/23. 2pp

7905050249 Rebuttal clarification of use of 91-day compressive strength concrete specified in cost spare versus 38-day compressive strength concrete referenced in PSAR Section D B Requests prompt concurrence.
 DUNHAM, R.D. Georgia Power Co. 79/05/11. 3pp

Q. Adjudication correspondence

7905050405 Denies 790501 request by Georgians Against Nuclear Power to suspend CP.
 SOTO, R.B. Office of Nuclear Reactor Regulation. 79/04/13. 3pp

7905050405 Forward denial of suspension of facility CP. Supporting documentation and.
 SEXTON, H.R. Office of Nuclear Reactor Regulation. 79/04/13. 1pp

7905050421 Director's denial of 105PR 206 request.
 SOTO, R.B. Office of Nuclear Reactor Regulation. 79/04/13. 3pp

79050504219 Analysis of need for facility.
 Division of Site Safety & Environmental Analysis. 79/04/13. 3pp.

79050504227 Responds to SM Fossil 790207 request Forward suit as Georgians Against Nuclear Energy request to suspend facility CP.
 MEYER, C.F. Georgia Power Co. 79/12/19. 12pp

79050504222 TX FIRD's action for admission of 790501 model Contribution 1.
 BOETT, J.H. Texas Public Interest Research Group. 79/05/22. 3pp

7905050492 Denies 790501 request of Georgians Against Nuclear Power to suspend CP issued to SH Power Co. & to hold hearings re alleged new evidence.
 SOTO, R.B. Division of Project Management. 79/04/13. 2pp

7905050505 Forward 790415 letter denying Georgians Against Nuclear Energy request to suspend CP. Also Forward PR notice of denial.
 DENTON, H.R. Office of Nuclear Reactor Regulation. 79/04/19. 3pp.

7905050518 Orders extension of time for NRC to review GAs of Nuclear Reactor Regulation 790405 denial of request for enforcement action.
 CHILDS, R.J. Office of the Secretary of the Commission. 79/04/06. 1p.

L. Financial information

7905050497 Forward "Annual Financial Report 1978."
 SMOULDER, R.C. Metropolitan Electric Authority of Georgia. 79/05/02. 1p.

7905050508 "Annual Financial Report 1978."
 Metropolitan Electric Authority of Georgia. 79/12/31. 21pp

J. Insurance & indemnity information

7905050497 Confirms increased liability limit to \$124,000,000 for policies NF-25, 23, 42, 76, 63, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 176, 179, 180, 186, 188, 189, 190, 191, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215 & where.
 SMITH, TROGHE, J. American Nuclear Insurers. 79/05/01. 1p.

7905050582 Confirms increase in liability limit to \$34,000,000 for policies NF-25, 23, 42, 76, 63, 100, 111, 140, 146, 151, 161, 164, 170, 173, 174, 176, 179, 180, 186, 188, 189, 190, 191, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215 & where.
 ROBERTS, E.H. Mutual Atomic Energy Liability Underwriters. 79/05/01. 1p.

DOCKETED ITEMS

207

Q Inspection reports, IE Bulletins & correspondence

7903010200 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/23 2pp

7903040012 IE Info Notice 79-07, "Bursture of Radwaste Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/26 2pp

7903040016 Forwards IE Bulletin 79-08, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 2pp

7903040034 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 1p

7903040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 1p

7903010206 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 1p

7903030018 Forwards IE Bulletin 79-09, "Failures of SE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/17 2pp

7903030467 Forwards IE Bulletin 79-06, Revision 1, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/10 2pp

7903240489 Ack receipt of IE Insp Rpts 80-424/79-05 & 80-425/79-05 on 790325-29. No proprietary info.
BRYAN, R. W. Georgia Power Co. 79/03/03 1p

--7903240500 Forwards IE Insp Rpts 80-424/79-05 & 80-425/79-05 on 790325-29. No noncompliance noted.
MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/10 2pp

--7903240505 IE Insp Rpts 80-424/79-05 & 80-425/79-05 on 790325-29. No noncompliance noted. Major areas inspected: control station, concrete procedures & space, concrete placement & records & action on previously identified items.
HARRIS, J. D. Region 2, Atlanta, Office of the Director
BRYAN, R. W. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/04/10. App.

DOCKEY 80-428 ALVIN W. VOTILE NUCLEAR PLANT, UNIT 2
A Application/Construction file documents & correspondence

7903030041 Inform that spare multipoint discharge diffuser will not be installed. Evaluation at other operating plants indicates no need for addl diffuser.
KORNFELDER, W. Georgia Power Co. 79/04/25 2pp

7903230036 Submit the classification of use of 20-day compressive strength concrete tested in test spot versus 28-day compressive strength concrete referenced in PSAR Section 3.8. Requests prompt concurrence.
KORNFELDER, W. Georgia Power Co. 79/05/31 2pp.

Q Adjudicating correspondence

7903150080 Denies TMI031 request by Georgians Against Nuclear Power to suspend CP.
BOYD, R. B. Office of Nuclear Reactor Regulation. 79/04/13 2pp.

7903040001 Forwards denial of suspension of facility CP. Supporting documentation encl.
DOCKEN, H. R. Office of Nuclear Reactor Regulation. 79/04/13 1pp.

--7903040011 Director's denial of 10CFR2.306 request.
BOYD, R. B. Office of Nuclear Reactor Regulation. 79/04/13 2pp.

--7903040019 Analysis of need for facility
& Division of Site Safety & Environmental Analysis 79/04/13 2pp.

--7903040027 Responds to Mr Friedrich TMI207 request. Forwards mail on Georgians Against Nuclear Energy request to suspend facility CP.
MITHEN, C. P. Georgia Power Co. 79/12/19 12pp.

--7903040032 TX PWR's notice for acceleration of TMI031 addl Contention 1.
SCOTT, J. H. Texas Public Interest Research Group 79/03/22 2pp.

7903030092 Denies TMI031 request of Georgians Against Nuclear Power to suspend CP issued to GA Power Co & to hold hearings re alleged new evidence.
BOYD, R. B. Division of Project Management. 79/04/13 2pp.

7903150075 Forwards 790413 ltr denying Georgians Against Nuclear Energy request to suspend CP. Also forwards PR notice of denial.
DOCKEN, H. R. Office of Nuclear Reactor Regulation. 79/04/14 2pp.

7903240018 Reopens extension of time for NRC to review 3rd of Nuclear Reactor Regulation 790403 denial of request for enforcement action.
CHILKA, J. Office of the Secretary of the Commission 79/04/30 1p

I. Financial Information

7903030497 Forwards "Annual Financial Rpt 1978."
WASSER, R. G. Metropolitan Electric Authority of Georgia. 79/03/02 1p.

--7903030508 "Annual Financial Rpt 1978."
Metropolitan Electric Authority of Georgia 79/12/35 24pp.

J. Insurance & Indemnity Information

7903240497 Confirms increased liability limit to \$25,000,000 for policies W-1, 25, 43, 76, 82, 100, 131, 140, 144, 181, 141, 144, 170, 173, 174, 178, 179, 186, 188, 189, 190, 199, 192, 193, 194, 199, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215 & others.
MANTRESCHE, L. American Nuclear Insurers. 79/02/01 1p.

7903240362 Confirms increase in liability limit to \$25,000,000 for policies W-25, 26, 29, 28, 30, 44, 46, 47, 48, 50, 51, 52, 53, 54, 55, 56, 57, 58, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87, 88, 90, 91, 92, 93, 94, 95 & 96.
KORNFELDER, W. Mutual Atomic Energy Liability Underwriters. 79/05/01 1p.

Q Inspection reports, IE Bulletins & correspondence

7903010200 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/23 2pp.

7903030012 Forwards IE Info Notice 79-07, "Bursture of Radwaste Tanks."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/03/26 2pp

7903040016 Forwards IE Bulletin 79-08, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 2pp

7903040034 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 1p.

7903040413 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During TMI Incident."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 1p.

7903010206 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets."
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/16 1p.

7903240489 Forwards IE Bulletin 79-09, "Failures of SE Type AK-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
O'REILLY, J. P. Region 2, Atlanta, Office of the Director
79/04/17 2pp.

DOCKETED ITEMS

7903020467 Forwards IE Bulletin 79-044, Revision 1, "Review of Operational Errors & Key Misalignments Identified During TMS Studies"
 6/23/79, J. P. Region 2, Atlanta, Office of the Director,
 79/04/18, 2pp

7903020468 Ask receipt of IE Insp Repts 80-424/79-03 & 80-425/79-08 on 79/03/29 Re proprietary info
 STAFF, R. H. Georgia Power Co 79/03/03 1p

7903020500 Forwards IE Insp Repts 80-424/79-03 & 80-425/79-08 on 79/03/29 Re nonproprietary info
 MAURIN, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/04/10 2pp

7903020509 IE Insp Repts 80-424/79-03 & 80-425/79-08 on 79/03/29 Re noncompliance noted major areas inspected cont status concrete preparations & spalls, concrete placement & records & action on previously identified items
 HARRIS, J. R. Region 2, Atlanta, Office of the Director
 BRINK, J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 79/04/10 4pp

DOCKET 80-424 ALVIN W. VOOLIE NUCLEAR PLANT, UNIT 3

I Financial Information

7903020487 Forwards "Annual Financial Rept 1978"
 790302, R. D. Metropolitan Electric Authority of Georgia 79/03/02 1p

7903020500 "Annual Financial Rept 1978"
 * Metropolitan Electric Authority of Georgia 30/12/20 24pp

DOCKET 80-427 ALVIN W. VOOLIE NUCLEAR PLANT, UNIT 4

I Financial Information

7903020487 Forwards "Annual Financial Rept 1978"
 790302, R. D. Metropolitan Electric Authority of Georgia 79/03/02 1p

7903020500 "Annual Financial Rept 1978"
 * Metropolitan Electric Authority of Georgia 79/12/21 24pp

DOCKET 80-430 ARCO, UNIT 1

T. Hearing transcripts on non-ARCO/ARCO matters

7903040086 Statement of C. Haisle, President, Atomic Industrial Forum, Inc before Subcommittee on Nuclear Regulation of Senate Committee on Environment & Public Works
 WARRNE, C. Atomic Industrial Forum 79/04/23 3pp

DOCKET 80-433 UC-BAYTA BARBARA RESEARCH REACTOR

J Insurance & indemnity information

7903040019 Forwards Amend 4 to indemnity Agreement E-28, per 100R0140
 Company re liability insurance increases from \$140 million to \$140 million effective 79/03/31 Supporting documentation sent
 BALTZMAN, J. Antitrust & Indemnity Group 79/03/01, 3pp

O-827 FLOATING NUCLEAR PLANT

re correspondence above documents & correspondence

80-0331: "Investigation & Evaluation of Stress in Piping of LWR Flasks" & notice of site site eval.
 Ask Director Per Light Water Reactors.

chemical staff be informed that longer holdup re should be required be avoid
 24 weeks & 40%
 Resources Defense Council 79/04/09, 1p

review of RPS Rept 7870-RP-1A451, Buckling
 ing Nuclear Plant," draft Revision B
 Application of Criteria to Design of
 #11,
 of Nuclear Reactor Regulation, 79/04/17, 1p

7903030034 Requests repts "Buckling Criteria & Application of Criteria to Design of Steel Containment Shell" & "Review of ORE Rept 7870-RP-1A451"
 RESOURCES DEFENSE COUNCIL 79/03/31 1p

7903030042 "Review of RPS Rept 7870-RP-1A451, Buckling Criteria & Application of Criteria to Preliminary Design of Steel Containment Shell for Floating Nuclear Power Plant."
 Revision 8 (790301)
 * International Structural Engineers, Inc. NRC-03-77-101
 79/03/31 20pp

7903030091 "Buckling Criteria & Application of Criteria to Design of Steel Containment Shell"
 HARRIS, J. P., BELOUS, P., WISNIEWSKI, J. V. International Structural Engineers, Inc. NRC-03-77-101 79/03/31 104pp

7903030109 Identification of 790303-08 meetings w/Harrison-Walker Refractories ORE & NRC consultant to discuss Harrison-Walker's experience w/magnesium oxide refractories & ORE's floating nuclear plant core sale
 BIRSEL, R. A. Light Water Reactors Branch 2 79/04/20 4pp

7903030339 Forwards list of items to be addressed by Harrison & Walker Refractories & ORE at 79/03/27-08 meeting in Jacksonville, FL
 BIRSEL, R. A. Aerospace Corp 79/04/26 3pp

7903040103 Forwards Amend 27 to plant design repts re cancellation of P&ID & contract, incorporation of refractory data & recommendations of NRC consultant re containment shell buckling analysis
 HARRIS, J. P. Offshore Power Systems (subs. of Westinghouse Electric Corp.) 79/04/20 121pp

7903040112 Discusses current activities of product assurance organization review & approval of drawings & space books to obtain mfg license & customers as soon as possible
 to approve drawings & specifications
 HARRIS, J. P. Offshore Power Systems (subs. of Westinghouse Electric Corp.) 79/03/11 2pp

7903040123 Forwards errors sheet to correct errors in Amend 27 to 790400 plant design repts
 HARRIS, J. P. Offshore Power Systems (subs. of Westinghouse Electric Corp.) 79/03/14, 2pp

7903040428 Forwards "Buckling Criteria & Application of Criteria to Preliminary Design of Steel Containment Shell for Floating Nuclear Power Plant," Revision 8
 HARRIS, J. P. Offshore Power Systems (subs. of Westinghouse Electric Corp.) 79/03/23, 1p

7903040498 "Buckling Criteria & Application of Criteria to Preliminary Design of Steel Containment Shell for Floating Nuclear Plant," Revision 8
 * Offshore Power Systems (subs. of Westinghouse Electric Corp.) 7870-RP-1A451 79/03/31, 335pp

G. Affidavits correspondence

7903030323 Withdrawal of mfg facts which are not in dispute. Applicant not able to build mfg plants by 1985. Statement filed in opposition to NRC statement of mfg facts
 HARRIS, J. P. Offshore Power Systems (subs. of Westinghouse Electric Corp.) 79/03/08 7pp

7903030270 Identification of evidence for 790400 hearing, submitted in response to ASLR 790302 order. Professional qualifications of Dr. Paulin asked
 COHMAN, R. L., COUSHARTY, T. H., KERNICK, J. R. Offshore Power Systems (subs. of Westinghouse Electric Corp.) 79/03/23 4pp

7903030177 Response to ASLR 790313 ltr re applicant's plans for convergence of reactor pressure vessel to site. Applicant will not channelize either Satara River or San Bernard River. Willing to begin responding to discovery actions.
 COPLAND, J. D., Baker & Smith, 79/03/27, 2pp

7903040113 Forwards request for Board notification re nonaffidavits correspondence re mitigate lawsuits.
 SCOTTO, J. F. Hearings Division, 79/04/02, 2pp

DOCKETED ITEMS

209

--7903010104 Board notification staff Assessment re non-safety-grade equipment to mitigate transients
WOLFE,B.D. & Assistant Director For Light Water Reactors
79/03/29 2pp

--7903010104 Board notification request issue on non-safety-grade equipment to mitigate transients More info is required
TEDBORG,F.L. Assistant Director For Reactor Safety 79/03/18 2pp

7903010204 Discusses effects of TSC on hearing schedules lists questions to be answered at 790404 hearing
REID,R.J. Branch 3 79/04/02 2pp

--7903010404 Lists questions to be answered at 790404 hearing re liquid pathologies generic study and TSC
HOLFE,B. Atomic Safety and Licensing Board Panel 79/03/29 2pp

7903010104 Replies to applicant & NRC opposition to motion for summary disposition Opposes applicant motion for summary disposition
RODRIGUEZ,N. Natural Resources Defense Council 79/04/04 10pp

--7903010204 Statement of mail facts in dispute to applicant motion for summary disposition Supporting affidavit & resume of TS Cochran encl
RODRIGUEZ,N. Natural Resources Defense Council 79/04/04 10pp

7903010204 No comment on proposed schedule submitted by applicant if all proposed findings of fact & conclusions of law re NRC contention are filed after completion of Board action & hearings on remission.
RODRIGUEZ,N. Natural Resources Defense Council 1 79/04/09 2pp

7903010120 Forwards NRC rep "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Servicing St. Louis"
SCHINABEL,H. Branch 3 79/04/11 1p

--7903010120 "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Servicing St. Louis"
MCTIGHERMAN,T.J. Office of Inspector & Auditor 79/04/30 20pp

7903010307 Ack receipt of 790411 3p transmitting report of investigation in connection w/ St. Louis Locks Proceeding Requested Board be relieved of any relevance to proceeding.
HOLFE,B.J. Atomic Safety and Licensing Board Panel 79/04/12 1p

7903010123 Informa that written responses to ASL 790329 3p are being delayed NRC staff originally assigned to work on response are presently involved at TH-2
GOLDMAN,D.M. Branch 3 79/04/17 1p

H General correspondence

7903010302 Expresses concern about safety of floating nuclear power plants, due to unpredictability of weather & seismic conditions
TOOMER,J.L. Affiliation Unknown. 79/04/08 1p

G Inspection reports: IE Bulletins & correspondence

7903010104 Forwards IE Info Notice 79-05, "Stress Analysis of Safety-Related Piping."
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/03/23 1p

7903010203 Forwards IE Info Notice 79-07, "Regulation of Redesign Tests."
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/03/24 1p

7903010104 Forwards IE Bulletin 79-07, "Dynamic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/04/14 1p

7903010104 Forwards IE Bulletin 79-08, "Review of Operational Errors & Bye Misalignments Identified During TH-2 Incident."
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/04/14 1p

7903010104 Forwards IE Bulletin 79-08, "Events Relevant to Bollinger Water Power Reactor Identified During TH-2 Incident."
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/04/14 1p

7903010104 Forwards IE Bulletin 79-09, "Failures of GE Type AN-2 Circuit Breakers in Safety-Related Bye." Licensee action required.
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/04/17 1p

7903010203 Forwards IE Bulletin 79-08, "Review of Operational Errors & Bye Misalignments Identified During TH-2 Incident."
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/04/18 1p

H Reportable occurrences, LERs & related correspondence

7903010203 Board notification breakdown refueling water storage tank design deficiency
RODRIGUEZ,N. Hearings Division. 79/03/29 20pp

DOCKET 50-408 BELLISPOKE NUCLEAR PLANT, UNIT 1

A Application/controversy stage documents & correspondence

7903010204 Notifies that radiological safety review schedule has been rescheduled & revised New schedule encl
PARR,D.D. Light Water Reactors Branch 3 79/04/30 2pp

7903010104 Forwards request for info re initial test program
PARR,D.D. Light Water Reactors Branch 3 79/03/01 10pp

7903010204 Approval of Terset 205 as smelter plant requiring surveillance interval no more stringent than that required for industrial processes equipped withers
GILLESPIE,J.E. Tennessee Valley Authority 79/05/04 21pp

J Insurance & indemnity information

7903010104 Confirms increased liability limit to \$124,000,000 for policies 79-01, 29, 43, 74, 102, 103, 11, 143, 144, 151, 152, 154, 170, 172, 174, 175, 176, 180, 182, 183, 184, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
WOLFE,B.D. American Nuclear Insurers 79/05/01 1p

7903010104 Confirms increase in liability limit to \$124,000,000 for policies 79-02, 20, 27, 30, 31, 44, 45, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 61, 64, 65, 67, 68, 69, 70, 71, 72, 74, 75, 77, 79, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96
WOLFE,B.D. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

G Inspection reports: IE Bulletins & correspondence

7903010104 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/03/23 2pp

7903010203 Forwards IE Bulletin 79-07, "Dynamic Stress Analysis of Safety-Related Piping." Licensee action required.
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/04/14 2pp

7903010203 Forwards IE Bulletin 79-08, "Review of Operational Errors & Bye Misalignments Identified During TH-2 Incident."
O'REILLY,J.P. Region 2: Atlanta, Office of the Director. 79/04/14 2pp

7903010203

Water Po
O'REILLY,J.P.
79/04/14

7903010204

Stress &
O'REILLY,J.P.
79/04/14

7903010205

Circuit
require
O'REILLY,J.P.
79/04/14

7903010207

General
Incident
O'REILLY,J.P.
79/04/14

DOCKETED ITEMS

7905020293 Submits supplemental response to SE Bulletin 79-07. Original response submitted 7/9/82. Provides add info received from manufacturer & describes plans in area of electrical penetrations.
GILLESAND, J. E Tennessee Valley Authority 7/9/82/27 Spp

B. Reportable occurrences, LERs & related correspondence

7905020548 Forwards second interim report of tensile anchor capacities lower than design allowable.
GILLESAND, J. E Tennessee Valley Authority 7/9/82/17 Ip

7905020557 Second interim report tensile anchor capacities lower than assumed in design allowable. Testing of steel anchors still in progress. Final results expected 7/30/82.
* Tennessee Valley Authority 7/9/82/17 Ip

DOCKET 50-439V BULLFOUNT NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7905020576 Notifies that radiological safety review schedule has been accelerated & revised. New schedule as follows:
PARR, D. D Light Water Reactors Branch 3 7/9/82/20 Spp

7905020641 Forwards request for info re initial test program.
PARR, D. D Light Water Reactors Branch 3 7/9/82/01 Tapp

7905020625 Approval of Refuel 200 as another unit requiring surveillance interval to meet stringent test schedule for auxiliary systems equipped equipment.
GILLESAND, J. E Tennessee Valley Authority 7/9/82/04 Spp

J. Insurance & indemnity information

7905020597 Confirms increased liability limit to \$25,000,000 for policies MP-1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000.

D. Inspection reports, IE Bulletins & correspondence

7905020611 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/23 Spp

7905020638 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020637 Forwards IE Bulletin 79-08, "Review of Operational Errors & By Missalignments Identified During TMI Incident."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020635 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020641 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/18 Spp

7905020617 Forwards IE Bulletin 79-09, "Failures of OE Type AW-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/17 Spp

7905020649 Forwards IE Bulletin 79-08, Revision 1, "Review of Operational Errors & By Missalignments Identified During TMI Incident."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020649 Submits supplemental response to IE Bulletin 79-07. Original response submitted 7/9/82. Provides add info received from manufacturer & describes plans in area of electrical penetrations.
GILLESAND, J. E Tennessee Valley Authority 7/9/82/27 Spp

B. Reportable occurrences, LERs & related correspondence

7905020548 Forwards second interim report of tensile anchor capacities lower than design allowable.
GILLESAND, J. E Tennessee Valley Authority 7/9/82/17 Ip

7905020557 Second interim report tensile anchor capacities lower than assumed in design allowable. Testing of steel anchors still in progress. Final results expected 7/30/82.
* Tennessee Valley Authority 7/9/82/17 Ip

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7905020644 Forwards HANCO-0001, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability M-01 and M-02.
* REFFLER, J. G. Assistant Director for Light Water Reactors 7/9/82/22 Spp

D. Inspection reports, IE Bulletins & correspondence

7905020646 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/23 Spp

7905020638 Forwards IE Info Notice 79-07, "Stress Analysis of Safety-Related Piping."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/23 Spp

7905020637 Forwards IE Bulletin 79-08, "Review of Operational Errors & By Missalignments Identified During TMI Incident."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020635 Forwards IE Bulletin 79-08, "Review of Operational Errors & By Missalignments Identified During TMI Incident."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020638 Forwards IE Bulletin 79-08, "Review of Operational Errors & By Missalignments Identified During TMI Incident."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020635 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactors Identified During TMI Incident."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020637 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020635 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/18 Spp

7905020617 Forwards IE Bulletin 79-09, "Failures of OE Type AW-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/17 Spp

7905020649 Forwards IE Bulletin 79-08, "Nuclear Incident at TMI-2."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

7905020649 Forwards IE Bulletin 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
* REFFLER, J. G. Region 3, Chicago, Office of the Director 7/9/82/14 Spp

DOCKETED ITEMS

211

DOCKET 80-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A. Application/construction stage documents & correspondence

7905040244 Forwards MUREG-8501, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability WFO encl.
VARNHULST, S. Assistant Director for Light Water Reactors
79/03/22 2pg

B. Inspection reports, IE Bulletin & correspondence

7905040245 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping." Region 3, Chicago, Office of the Director 79/03/23, 1p

7905040241 Forwards IE Info Notice 79-07, "Rupture of Reducers Tank." Region 3, Chicago, Office of the Director 79/03/26 1p

7905040249 Forwards IE Bulletin 79-04, "Review of Operational Errors & System Missalignments Identified During TMI Incident." Region 3, Chicago, Office of the Director 79/04/15 1p.

7905040250 Forwards IE Bulletin 79-04, "Review of Operational Errors & System Missalignments Identified During TMI Incident." Region 3, Chicago, Office of the Director 79/04/14 1p.

7905040252 Forwards IE Bulletin 79-04, "Review of Operational Errors & System Missalignments Identified During TMI Incident." Region 3, Chicago, Office of the Director. 79/04/14, 1p

7905040257 Forwards IE Bulletin 79-08, "Events Related to Boiling Water Reactor Identified During TMI Incident." Region 3, Chicago, Office of the Director. 79/04/14, 1p.

7905040259 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." License action required.
KEFFLER, J.G. Region 3, Chicago, Office of the Director. 79/04/14 1p.

7905040296 Forwards IE Info Notice 79-16, "Nonconforming Pipe Support Struts." Region 3, Chicago, Office of the Director 79/04/16 1p.

7905050207 Forwards IE Bulletin 79-05, "Failure of OE Type AN-2 Circuit Breaker in Safety-Related Sys." License action required.
KEFFLER, J.G. Region 3, Chicago, Office of the Director. 79/04/17, 1p.

7905050400 Forwards IE Bulletin 79-05, "Nuclear Incident at TMI-2." Region 3, Chicago, Office of the Director. 79/04/21, 1p.

7905040889 Forwards IE Circular 79-07, "Unsuspected Speed Increase of Reactor Recirculation Motor Operator Not Detected in Reactor Power Increase." Region 3, Chicago, Office of the Director. 79/05/02 1p.

DOCKET 80-442 BEAR CREEK NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905050779 Refers questions by Beacourt Anti-Pollution League re financing plan proposed in Public Use Co 790321 & 790427 files.
BACOUR, R.A. O'Neill, Secaucus, Spelman. 79/05/04. 4pg.

7905170245 Forwards Amend 40 to License application, Certificate of Work, annual fee & supporting documentation encl.
KEFFLER, J.A. Reps & Gray. 79/05/16, 1p.

7905170281 Appointment of agent & signature of applicant.
CLARK, J.V. Green Mountain Power Corp. 79/04/30. 2pg.

7905170283 Forwards Amend 40 to 790320 license application, request for partial transfer of ownership to CPP-138 & CPP-136 & supporting financial info of owners.
HERRILL, E.N. Green Mountain Power Corp. 79/05/14. 31pgs.

F. Security, medical, emergency & fire protection plans

7905040345 Forwards Ofc of Nuclear Reactor Regulation 790329 memo to Commissioners re results of fire protection research test
NRC will provide all generic board notifications in all proceedings involving facilities
BROWNER, L. Branch 3 79/04/05. 2pg

G. Adjudicatory correspondence

7905040353 Forwards request for order to show cause why CP should not be suspended or revoked. NRC position on not reviewing consequences of Class 4 facility accident should be reviewed in light of DEC-79-037.
BACOUR, R.A. O'Neill, Secaucus, Spelman 79/03/12 2pg

7905040359 Requests order to show cause why CP should not be suspended or revoked for lack of financial qualifications of lead applicant & other participating companies Certificate of Rev encl
BACOUR, R.A. O'Neill, Secaucus, Spelman 79/03/12 7pg

7905040368 Requests to Beacourt Anti-Pollution League request for order to show cause why CP should not be suspended or revoked.
Cells for investigation into utility's financial qualifications Certificate of Rev encl
BART, L. Nassau County, State of 79/03/26. 3pg

7905040413 Forwards 790312 order to show cause & request for order to show cause
BACOUR, R.A. Office of Nuclear Reactor Regulation 79/03/26. 2pg

7905040416 Forwards request for order to show cause why CP should not be suspended or revoked
BACOUR, R.A. O'Neill, Secaucus, Spelman 79/03/12 1p

7905040422 Request for order to show cause why CP for proposed nuclear power plants should not be suspended or revoked.
BACOUR, R.A. O'Neill, Secaucus, Spelman 79/03/12 2pg

7905040430 Request for order to show cause, filed by Beacourt Anti-Pollution League.
BART, L. Office of Nuclear Reactor Regulation 79/03/12 1p.

7905050334 Requests NRC immediately stop consent until design changes are made.
WEINHOOLD, E.H. Application Unknown. 79/04/01. 3pg

7905100418 Responses to ALAT-009 re radon emissions & de minimus theory from Parties record, Certificate of Rev encl
BART, L. Hearings Division. 79/04/11. 4pgs.

7905140514 Responses to 790404 brief of Philadelphia Electric Co. PEG&M & Atlantic City (N.J.) Electric Co re de minimus theory.
Certificate of Rev encl.
KEFFLER, J.G. Citizens for Safe Environment. 79/04/11. 8pg.

7905140521 Urges quick conclusion to seismic issue for facilities in light of closing of five nuclear plants
LEWIS, R. Beacourt Anti-Pollution League. 79/04/18. 1p.

7905290370 Opposes EN Weinhold 790401 request for seismic design changes & for halt in consent until implementation of such changes. EN Weinhold should be permitted to file brief unless curative.
BROWNER, L. Branch 3 79/04/23. 7pg.

7905140302 Notification of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 in which to file for summary disposition.
BART, L. R.E. Atomic Safety and Licensing Appeal Panel. 79/04/23. 13pg.

I. Financial information

7905040777 Requests to NRC 790319 request for add info re design, analysis & fabrication for proposed mod of shoring reactor cavity annular seal plate during operation. Info will be provided by 790721.
MALHOTRA, H.C. Sacramento Municipal Utility District. 79/04/26. 5pg.

7905100447 Forwards until 790426 preliminary prospectus offering 1,000,000 shares of preferred stock at \$25 par value.
HITBOM, J.A. Reps & Gray 79/04/27. 2pg.

7905100449 Forwards 790315 final prospectus re sinking fund stock, 11,345 dividend series.
HITBOM, J.A. Reps & Gray. 79/05/16. 50pg.

DOCKETED ITEMS

G. Inspection reports, IE Bulletins & correspondence

7903010143 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
08128, S.H. Region I, Philadelphia, Office of the Director.
79/03/23 1p

7903020049 Forwards IE Bulletin 79-06, "Review of Operational Errors & Key Misalignments Identified During TMI Incident"
08128, S.H. Region I, Philadelphia, Office of the Director.
79/04/11 1p

7903020244 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping" - Licensee action required.
08128, S.H. Region I, Philadelphia, Office of the Director.
79/04/14 1p

7903040102 Forwards IE Bulletin 79-08, "Review of Operational Errors & Key Misalignments Identified During TMI Incident"
08128, S.H. Region I, Philadelphia, Office of the Director.
79/04/14 1p

7903040284 Forwards IE Bulletin 79-08, "Events Relevant to Selling Water Power Reactors Identified During TMI Incident"
08128, S.H. Region I, Philadelphia, Office of the Director.
79/04/14 1p

7903050093 Forwards IE Bulletin 79-09, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Bays" - Licensee action required.
08128, S.H. Region I, Philadelphia, Office of the Director.
79/04/17 1p

7903050324 Forwards IE Bulletin 79-09, Revision 1, "Review of Operational Errors & Key Misalignments Identified During TMI Incident"
08128, S.H. Region I, Philadelphia, Office of the Director.
79/04/18 1p

7903050392 Responds to IE Bulletin 79-09, GE type AM-2 circuit breakers not planned for use.
08128, S.H. Public Service Co. of New Hampshire 79/04/23 1p

DOCKET 30-464 BEAVERHOLZ NUCLEAR STATION, UNIT 2

7903010447 Forwards until 790306 preliminary prospectus, offering 1,000,000 shares of preferred stock at \$25 par value.
RITSMER, J.A. Rogers & Gray 79/04/23 5pp

A. Application/construction stage documents & correspondence

7903030398 Replies questions by Seacoast Anti-Pollution League re financing plan proposed in Public Use Co 790301 & 790407.
08128, S.H. Region I, Philadelphia, Office of the Director.
79/05/04 4pp

790110240 Forwards Amend 40 to license application, Certificate of Gov. amend fee & supporting documentation etc.
RITSMER, J.A. Rogers & Gray 79/05/16 1p

7903030351 Appointment of agent & signature of applicant.
CLARK, J.V. Green Mountain Power Corp 79/04/32 2pp

7903030353 Forwards Amend 40 to 790302 license application, request for partial transfer of ownership of CPPS-125 & CPPS-136 & supporting financial info of owners.
NEBRILL, D.N. Green Mountain Power Corp. 79/05/14 20pp

F. Security, medical, emergency & fire protection plans

7903020343 Forwards Ofc of Nuclear Reactor Regulation 790229 memo to Commissioners re results of fire protection research test.
Will provide all generic board notifications in all proceedings involving facilities.
RITSMER, J.A. Rogers & Gray 79/04/08 2pp

G. Regulatory correspondence

7903010323 Forwards request for order to show cause why CP should not be suspended or revoked, NRC position on not reviewing consequences of Cleveland facility accident should be reconsidered in light of OGCY-79-137.
RACUM, S.A. O'Neill, Becker, Spielman 79/03/12 2pp

7903030422 Responds order to show cause why CP should not be suspended or revoked for lack of financial qualifications of feed applicant & other participating companies Certificate of Gov. amend.
RACUM, S.A. O'Neill, Becker, Spielman 79/03/12 2pp

7903070324 Responds to Seacoast Anti-Pollution League request for order to show cause why CP should not be suspended or revoked.
Call for investigation into utility's financial qualifications Certificate of Gov. amend.
SURT, L. Massachusetts, State of 79/05/26 8pp

7903020416 Forwards 790312 order to show cause & request for order to show cause.
SEITZ, R.A. Office of Nuclear Reactor Regulation 79/03/29 2pp

7903020456 Forwards request for order to show cause why CP should not be suspended or revoked.
RACUM, S.A. O'Neill, Becker, Spielman 79/03/12 1p

7903050422 Request for order to show cause why CP for proposed nuclear power plants should not be suspended or revoked.
RACUM, S.A. O'Neill, Becker, Spielman 79/03/12 2pp

7903050430 Request for order to show cause, filed by Seacoast Anti-pollution League.
SEITZ, R.A. Office of Nuclear Reactor Regulation 79/03/12 1p

7903030334 Requests NRC immediately stop work until design change is made.
WEINER, S.H. Affiliation Unknown 79/04/01 3pp

7903010416 Response to ALAD-509 re radon emissions & de minimis theory from Perkins report, Certificate of Gov. amend.
SCHULTZ, J.F. Hearings Division 79/04/11 4pp

7903040519 Response to 790404 brief of Philadelphia Electric Co. re radon & Atlantic City, OGCY Electric Co. re de minimis theory.
Certificate of Gov. amend.
NEFFORD, C.S. Citizens for Safe Environment 79/04/11 3pp

7903040521 Urges NRC conclusion to seismic stress for facilities in light of closing of five nuclear plants.
LEWIS, E. Seacoast Anti-Pollution League 79/04/18 1p

7903050323 Opposes GE Model 60 790401 request for seismic design changes & for halt in work until implementation of such changes. GE Model 60 should be permitted to file brief unless waived.
SEITSMER, J.A. Rogers & Gray 79/04/23 3pp

7903040522 Notices of consolidation of five intervenor groups re radon emissions issue. Perkins have until 790329 in which to file for summary disposition.
SEITSMER, J.A. Atlantic Safety and Licensing Appeal Panel 79/04/23 13pp

E. Financial information

7903050477 Responds to NRC 790319 request for add'l info re design analysis & fabrication for proposed and of starting reactor cavity annular seal plate during operation. Info will be provided by 790731.
SMITH, E.M. Sacramento Municipal Utility District 79/04/26 1pp

7903010129 Forwards 790315 final prospectus re selling fund stock 11,245 dividend shares.
RITSMER, J.A. Rogers & Gray 79/05/16 33pp

B. Inspection reports, IE Bulletins & correspondence

7903010143 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
08128, S.H. Region I, Philadelphia, Office of the Director.
79/03/23 1p

7903020103 Forwards IE Bulletin 79-06, "Review of Operational Errors & Key Misalignments Identified During TMI Incident"
08128, S.H. Region I, Philadelphia, Office of the Director.
79/04/11 1p

- 7905030088 Motion on progress made in Mar 1979 in completing discovery, submitted per AELS 790421 under Certificate of Evc and
HARRIS, J.L. / BERGER, H.S. / CLARK, R.H. Justice, Dept of 79/03/26
7pp
- 7905030179 Describes discovery activities of Public Utility Board of Brownsville, TX for Mar 1979 Certificate of Evc and
FOSTER, M.B. Spiegel & McDaniel. 79/04/03 App
- 7905030206 Request by TX Util Generating Co for NRC to discontinue Central Power & Light South West Corp as intervenors in alternative, issue concerning discovery or imposing of collateral estoppel.
KROTT, J.B. Debevoise & Lishman. 79/04/03 App
- 7905030242 Request by TX Util Generating Co for order barring Central Power & Light from seeking relief incidentally w/ district court decision for favorable decision re summary disposition
KROTT, J.B. Debevoise & Lishman. 79/04/03 App
- 7905030259 Motion by TX Util Generating Co re notice & authorities supporting motion to discontinue Central Power & Light South West Corp as intervenors or for summary disposition
KROTT, J.B. Debevoise & Lishman. 79/04/03 App
- 7905100228 Response to second set of interrogatories & requests for production of documents directed to SOU by Houston Lighting & Power. Qualifications of expert witnesses: MC Scott & OTC Taylor & Certificate of Evc and
HARRIS, J.L. / BERGER, H.S. / CLARK, R.H. Justice, Dept of 79/04/03
25pp
- 7905100228 Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power. Qualifications of expert witnesses: MC Scott & OTC Taylor & Certificate of Evc and
HARRIS, J.L. / BERGER, H.S. / CLARK, R.H. Justice, Dept of 79/04/03
25pp
- 7905100275 Response to first set of interrogatories & request for production of documents submitted by TX Util Generating Co Certificate of Evc and
HARRIS, J.L. Justice, Dept of 79/04/03 11pp
- 7905100284 Request by Central Power & Light that AEL issue protective order re interrogatories & request for production of documents from Houston Lighting & Power. Certificate of Evc and
BTAM, D.B. Isham, Lincoln & Seale. 79/04/03 7pp
- 7905100273 Response to TX Util Generating Co's objections to & motion for protective orders & motion to compel further answers to interrogatories & request for production of documents
BLUME, R.S. Anti-Trust Division. 79/04/04 36pp
- 7905100415 Motion by Public Utility Board of Brownsville, TX to compel further production of documents from South TX Electric Cooperative & Medina Electric Cooperative Supporting documentation & Certificate of Evc and
FOSTER, M.B. Spiegel & McDaniel. 79/04/03. 17pp
- 7905100538 Request by Central Power & Light for extension of time to respond to 790503 responses by Houston Lighting & Power & TX Util Generating Co to former's interrogatories & document requests. Certificate of Evc and
BTAM, D.B. Isham, Lincoln & Seale. 79/04/03. App
- 7905100580 Motion that responses to motions for summary disposition filed by Houston Lighting & Power & TX Util Generating Co be governed by 10CFR2.79013. Certificate of Evc and
LEERY, R.P. Anti-Trust Division. 79/04/06. 3pp
- 7905100479 Motion by Houston Lighting & Power for protective order re public disclosure of info requested by Public Utility Board of Brownsville, TX. Certificate of Evc and
BARNETT, C.W. Baker & Smith. 79/04/06. 3pp
- 7905030793 Status of discovery & production during Mar 1979. Certificate of Evc and
DAKOWSKI, R.C. Austin. TX. 79/04/06. 3pp
- 7905100442 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utility Board of Brownsville, TX.
MILLER, H.E. Atomic Safety and Licensing Board Panel. 79/04/07. 3pp
- 7905030488 Motion re on discovery for Mar 1979. Discovery requests were initially indicated not received. Certificate of Evc and
JOHNS, D.F. Austin, Dept. Hauer & Field. 79/04/09. 3pp
- 7905030481 Answer by Houston Power & Lighting to NRC 790323 responses to civil motion for protective order. Motion to compel further answers to interrogatories & NRC request for production of documents. Certificate of Evc and
BARNETT, C.W. Baker & Smith. 79/04/11. 12pp
- 7905030280 Foreman's review page 20-1 attached to Central Power & Light Co's answers & objections to Houston Lighting & Power Co's first set of written interrogatories to Central Power & Light Co Certificate of Evc and
BTAM, D.B. Isham, Lincoln & Seale. 79/04/12. 4pp
- 7905030232 Advice to discover requests have been initiated or received by Texas Electric Cooperative, Inc. Certificate of Evc and
BARNETT, C.W. Northcutt & Egan. 79/04/12. 4pp
- 7905100463 Grants motion for extension of time for parties to respond to discovery requests
MILLER, H.E. Atomic Safety and Licensing Board Panel. 79/04/12. 3pp
- 7905030488 South TX Electric Cooperative, Inc. & Medina Electric Cooperative, Inc.'s opposition to Public Utility Board of Brownsville, TX 790323 motion for further responses to interrogatories. Certificate of Evc and
MILLER, H.E. Atomic Safety and Licensing Board Panel. 79/04/12. 3pp
- 7905040067 Advice that during Mar 1979 NRC filed motions to compel against Houston Lighting & Power & TX Util Generating Co NRC is preparing responses to TX Util's first & Houston's second set of interrogatories.
LEERY, R.P. Anti-Trust Division. 79/04/13. 3pp
- 7905050129 Ack receipt of response to Mar 1979 motion to compel & evaluation in progress
LEERY, R.P. Anti-Trust Division. 79/04/13. 3pp
- 7905100426 Request by Public Utility Board of Brownsville, TX for extension of time to answer first set of interrogatories & requests for production of documents from Central Power & Light & Houston Lighting & Power. Certificate of Evc and
MCDANIEL, R.C. Spiegel & McDaniel. 79/04/16. 7pp
- 7905100481 Corrects revised page 20-1 of Central Power & Light Co answers & objections in 790402 proceeding from "expenditure" to "expenditure" & "expenditure" to "expenditure" other than other than "expenditure" & "expenditure" of Evc and
BTAM, D.B. Isham, Lincoln & Seale. 79/04/17. 4pp
- 7905100780 Directs TX Util Generating Co (790203) to produce documents & full responses to 790113 interrogatories. Denies 790203's order for protective order.
MILLER, H.E. Atomic Safety and Licensing Board Panel. 79/04/18. 2pp
- 7905030424 Response by skill re Central Power & Light's 790323 objections & 790503 motion for protective order re util's first set of interrogatories. Includes motion to compel answers, motion of appearance & Certificate of Evc and
BARNETT, C.W. Baker & Smith. 79/04/19. 11pp
- 7905030537 Grants extension of time to answer interrogatories by Public Utility Board of Brownsville, TX in response to 790416 motion
MILLER, H.E. Atomic Safety and Licensing Board Panel. 79/04/19. 3pp
- 7905100158 Motion by Central Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted by 790228 Supporting documentation & Certificate of Evc and
BTAM, D.B. Isham, Lincoln & Seale. 79/04/20. 25pp
- 7905100152 Motion by Central Power & Light to compel TX Util Generating Co to answer first set of interrogatories submitted 790228.
BTAM, D.B. Isham, Lincoln & Seale. 79/04/20. 12pp
- 7905100271 Answer by Central Power & Light & Central & South West Corp seeking continuance of NRC witness reviews, w/o party sworn on grounds of no prejudice of collateral estoppel. Supporting documentation & Certificate of Evc and
MILLER, H.E. / MILLER, H.E. / BTAM, D.B. Isham, Lincoln & Seale. 79/04/20. 11pp

DOCKETED ITEMS

215

7905010086 Opened City of Austin's 790329 letter & 790403 motions for full or partial summary judgment filed by Houston Lighting & Power & TX Utilities Generating Co. Denial of certification & interlocutory appeals M/Certificate of the LORRY, R. B. Anti-Trust Division 79/04/23 2pp.

7905010051 Response of Public Utility Board of Brownsville, TX opposing Houston Lighting & Power motion for summary decision & City of Austin brief in support of re-judicate Supporting documentation & Certificate of the anti- M/Certificate of the LORRY, R. B. Anti-Trust Division 79/04/23 2pp.

7905020444 NRC answer to motions of Gulf States Util for protective order & order setting conditions for compliance w/790228 subpoena. Util should produce documents as requested Certificate of the anti- M/Certificate of the LORRY, R. B. Anti-Trust Division 79/04/24 1pp

6. Disposition reports, DE Bulletins & correspondence

7905040194 Response to DE Bulletin 79-01. No action to be taken at this time. GARY, R. J. Texas Utilities Generating Co 79/02/19 2pp

7905030761 Details actions taken in response to DE Bulletin 79-067 survey prepared by Westinghouse indicates none of Seller-Summer Type M relays w/cool air in use in safety-related equipment. GARY, R. J. Texas Utilities Generating Co 79/02/19 2pp

7905070191 Forwards info meeting re: 790212 meeting w/DE & local public officials in Oremburg, TX to discuss assignment of resident inspector. DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/02 2pp.

7905070307 Summary of 790212 info meeting w/local officials of Oremburg, TX re assignment of resident inspector, lines of communication, facility status & community concerns. TAYLOR, R. B., WEINER, C. E., CHODURA, W. A. Region 4, Dallas, Office of the Director 79/03/02 3pp

7905010330 Forwards IE Insp Rpts 30-445/79-03 & 30-446/79-03 on 790202-20 Notice of violation already forwarded w/MRC 790220 3pp. DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/14 2pp

7905010370 IE Insp Rpts 30-445/79-03 & 30-446/79-03 on 790202-20 Noncompliance noted failure to follow concrete placement procedures. TAYLOR, R. B. Region 4, Dallas, Office of the Director 79/03/15 2pp

7905010281 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping." DE Bulletin, M. C. Region 4, Dallas, Office of the Director 79/03/23 1p.

7905050054 Forwards IE Insp Rpts 30-445/79-03 & 30-446/79-03 on 790202-20 IE & 13. No noncompliance noted. DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/25 2pp

7905010261 IE Insp Rpts 30-445/79-03 & 30-446/79-03 on 790202-20 IE & 13. No noncompliance noted. Major areas inspected correct activities. ROEMER, A. S. Region 4, Dallas, Reactor Construction & Engineering Support Branch. BARRETT, J., MILLER, H. L. C. Region 4, Dallas, Office of the Director 79/03/25 2pp.

7905010444 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI - Suppl." DE Bulletin, M. C. Region 4, Dallas, Office of the Director 79/04/05 1p.

7905040504 Forwards IE Bulletin 79-05B, "Review of Operational Errors & Key Missions Identified During TMI Incident." DE Bulletin, M. C. Region 4, Dallas, Office of the Director 79/04/14 1p.

7905040429 Forwards IE Bulletin 79-08, "Events Relevant to Belling Water Power Reactor Identified During TMI Incident." DE Bulletin, M. C. Region 4, Dallas, Office of the Director 79/04/14 1p

7905070080 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required. DE Bulletin, M. C. Region 4, Dallas, Office of the Director 79/04/14 1p.

7905010440 Forwards IE Info Notice 79-10, "Housekeeping Plan Support Study." DE Bulletin, M. C. Region 4, Dallas, Office of the Director 79/04/14 1p

7905010108 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI." DE Bulletin, M. C. Region 4, Dallas, Office of the Director 79/04/16 1p

7905030283 Forwards IE Bulletin 79-09, "Failures of DE Type AN-6 Circuit Breaker in Safety-Related Sys." Licensee action required. DE Bulletin, M. C. Region 4, Dallas, Office of the Director 79/04/17 1p

7905050420 Ack receipt of 790320 & 0420 line informing NRC of steps taken to correct violations noted in IE Insp Rpts 30-445/79-04 & 30-446/79-04. DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

7905050448 Response to NRC 790320 re re violations noted in IE Insp Rpts 30-445/79-04 & 30-446/79-04. Corrective actions implemented. Record for ventilation fan action received. GARY, R. J. Texas Utilities Generating Co 79/04/12 2pp

8. Reportable occurrences, LBNs & related correspondence

7905000140 Forwards PHO-79-67A, L. J. & R. DE Bulletin, M. C. Region 4, Dallas, Office of the Director 79/04/06 1p

7905030263 Forwards PHO-79-67A, L. J. & R. DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09 1p

7905030107 Forwards PHO-79-67A DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/10 1p

7905030194 Forwards PHO-79-67A & 79-77 DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 1p

7905030124 Forwards PHO-79-67A DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 1p

7905030201 Forwards PHO-79-67A DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 1p

7905030076 Forwards PHO-79-67A & V. DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p

7905030204 Forwards PHO-79-67A DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p

7905030214 Forwards PHO-79-67A DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p

7905030208 Forwards PHO-79-67A, AC & AD. DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p

7905040580 Forwards PHO-79-67A, DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

7905070193 Forwards PHO-79-67A & AD DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/27 1p

7905010230 Forwards PHO-79-67A, AC & AD DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30 1p

7905040299 Forwards PHO-79-67A & AL DE Bulletin, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/04 1p

770521618 Continues potentially RO re reactor vessel head weld metal defects originally reported in 7705200 telcon. Investigative continuing.
GARY, E. J. Texas Utilities Generating Co. 7/19/84. 1p

DOCKET 50-446 CORNACIO PEAR STEAM ELECTRIC STA., UNIT 2

A Applications/interim stage documents & correspondence

770520300 Summary of 770520-022 meeting w/ TX Util. Generating Co. Rees & Best, Gibbs & Hill & TX Util. Div. Inc. in San Jose, TX re testing schedule, cost progress & gathering of info to permit independent estimate of Peak loading date.
BUNELL, S. B. Light Water Reactors Branch 2. 7/19/84. 8pp

770520285 Forwarded answers qualification plans for over sized steel available in Central Files.
GARY, E. J. Texas Utilities Generating Co. 7/19/84. 2pp.

770520263 Inform that response to 770456 request for add second round info will be submitted by Jul 1979
w. Texas Utilities Generating Co. 7/19/84. 2p

770514284 Forwarded initial responses to SA Branch round one questions 10422 7-8422 200 which will be retransmitted to HRC as PRMR Amend 5
GARY, E. J. Texas Utilities Co. 7/19/84. 125pp

770514282 Forwarded "Chlorine Minimization Plan" submitted by ARI Requests comment by 7704061.
ELLIOTT, R. B. Environmental Protection Agency. 7/19/84. 1p

770514284 Forwarded "Chlorine Minimization Plan" Requests comment within 40 days
PIRAN, L. F. Texas Utilities Generating Co. 7/19/84. 1p

770514226 "Chlorine Minimization Plan"
RICE, J. B. Texas Utilities Generating Co. 7/19/84. 10pp

B Adjudicators correspondence

770520228 Answer to Citizens for Sound Energy 770520 petition to intervene re application for SL Davis denial as author of right & discretion Notice of appearance of HG Response on behalf of Utility Certificate of Div encl.
REYNOLDS, N. S., BEVERIDGE, J. B. Beaveridge & Lieberman. 7/19/84. 12pp

770520221 Answer to Citizens for Fair Utility Regulation 770520 petition to intervene re application for SL Davis denial as author of right & discretion Certificate of Div encl.
REYNOLDS, N. S., BEVERIDGE, J. B. Beaveridge & Lieberman. 7/19/84. 11pp.

770520271 Answer to Citizens for Sound Energy 770520 petition to intervene re application for SL Davis denial as author of right & discretion Certificate of Div encl.
CHAMBERLIN, J. Branch 1. 7/19/84. 9pp

770520154 Request for hearing & first amended petition to intervene by TX Association for Community Organizations. Affidavits of T Thompson, M. Martin, R. Bishop, C. Bishop, M. Ward & D. Wood & Certificate of Div encl.
BARNETT, M., SMITH, J. H., GARY, E. J. West Texas Legal Services. 7/19/84. 27pp.

770520115 Request by joint intervenors that time for filing of objections & final prehearing conference be continued. Notice of appearance of OR Gay on behalf of intervenors; request of set of documents & Certificate of Div encl.
GARY, E. J. West Texas Legal Services. 7/19/84. 13pp.

770520247 Confirms scheduled 770417 meeting & requests draft of proposed conferees.
CHAMBERLIN, J. Branch 1. 7/19/84. 5p

770520283 Orders conference on 770520 to consider petition to intervene
BARNETT, M. Atomic Safety and Licensing Board Panel. 7/19/84. 09p.

770510212 Answer by applicant in opposition to 770520 first amended petition to intervene & request for hearing filed by TX Association of Community Organizations for Reform New & West TX Legal Div. Certificate of Div encl.
REYNOLDS, N. S., BEVERIDGE, J. B. Beaveridge & Lieberman. 7/19/84. 14pp

770520065 Connects ARL 770429 order re location of 770520 prehearing conference.
BARNETT, M. Atomic Safety and Licensing Board Panel. 7/19/84. 17p

770520055 Reconsiders granting joint petition to intervene from TX Association of Community Organizations for Reform New & West TX Legal Div. encl. re clarification of interest & authorization Certificate of Div encl.
CHAMBERLIN, J. Branch 1. 7/19/84. 12pp

770520347 Applicant's response to 770456 motion for continuance filed by Association of Community Organizations for Reform New & West TX Legal Div. Certificate of Div encl.
REYNOLDS, N. S., BEVERIDGE, J. B. Beaveridge & Lieberman. 7/19/84. 23p

770520429 Motion to suppress certificate of Div encl.
ELLIOTT, R. B. Citizens Association for Sound Energy. 7/19/84. 07p

I Financial information

7705202154 Forwarded financial information supporting Amend 1 to CFFS-126 & CFFS-127
BALTIMORE, J. Arbitration & Mediation Group. 7/19/84. 13p

M Affidavit correspondence

770510245 Forwarded TX Util. Co. & subsidiaries' answer to HRC initial interrogatories & requests for production of documents. Reserves rights to file objections & protective order before 770520 Certificate of Div encl.
ELLIOTT, R. B., VERAN, F. Veran, Forsythe & Wampels. 7/19/84. 01p.

770520232 Denies 770517 motion by Public Utility Board of Brownsville, TX seeking subpoena until 770520 & 770403, in which is compel full response to Board's interrogatories.
REYNOLDS, N. S., BEVERIDGE, J. B. Atomic Safety and Licensing Board Panel. 7/19/84. 1p

770520427 Notifies that location of deposition of LC Pealer of Heneside Co has been changed from Holiday Inn, Austin, TX to Butler, Simon, Rice, Cook & Nepp law office in Houston, TX.
RYAN, T. G., Isham, Lincoln & Seale. 7/19/84. 02p.

770520440 Order protecting confidentiality of info sought by Houston Lighting & Power from Central Power & Light, West TX Util. Public Div. of OR & Southwestern Electric Power Co.
ELLIOTT, R. B. Atomic Safety and Licensing Board Panel. 7/19/84. 02p

770521020 Response by still to second set of interrogatories & request for production of documents submitted to Central Power & Light. Also moves for protective order Certificate of Div encl.
BARNETT, M. Baker & Scott. 7/19/84. 02pp.

770520240 Advises that deposition of Edward Guerra, Air Products & Chemical Co. Allentown, PA, originally scheduled for 770403, has been changed to 770419 at site of Air Products & Chemical Co.
RYAN, T. G., Isham, Lincoln & Seale. 7/19/84. 01p

770520245 RL Wright, AD Cyphers & L. Pealer were deposed during Mar. Central Power & Light filed answers & objections to Houston Lighting & Power Co. first set of written interrogatories.
RYAN, T. G., Isham, Lincoln & Seale. 7/19/84. 03p

770520058 Rept on progress made in Mar 1979 in completing discovery submitted per ARL 770521 order. Certificate of Div encl.
HARRIS, J. L., REEDER, M. O., CLARK, R. H. Justice, Dept. of. 7/19/84. 03p

770520317 Describes discovery activities of Public Utility Board of Brownsville, TX for Mar 1979. Certificate of Div encl.
FOSTER, M. H. Spiegel & McDermid. 7/19/84. 03p

770520226 Request by TX Util. Generating Co. for HRC to disallow Central Power & Light South West Corp. as intervenors. In alternative, seeks summary disposition of invoking of collateral subpoena Certificate of Div encl.
REYNOLDS, N. S., BEVERIDGE, J. B. Beaveridge & Lieberman. 7/19/84. 03p

770520242 Request by TX Util. Generating Co. for order barring Central Power & Light South West Corp. as intervenors. In alternative, seeks summary disposition of invoking of collateral subpoena Certificate of Div encl.
REYNOLDS, N. S., BEVERIDGE, J. B. Beaveridge & Lieberman. 7/19/84. 03p

770520240 Revises by TX Util. Generating Co. re status & authorization supporting motion to disallow Central Power & Light South West Corp. as intervenors or for summary disposition.
REYNOLDS, N. S., BEVERIDGE, J. B. Beaveridge & Lieberman. 7/19/84. 03p

7905100288 Response to second set of interrogatories & requests for production of documents directed to SOU by Houston Lighting & Power. Qualifications of expert witnesses re Scott & OTC Taylor & Certificate of Div encl.
HARRIS, J. L., HERRER, H. P., CLARK, R. H. Justice, Dept. of 79/04/03 54pp

7905100289 Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power. Qualifications of expert witnesses re Scott & OTC Taylor & Certificate of Div encl.
HARRIS, J. L., HERRER, H. P., CLARK, R. H. Justice, Dept. of 79/04/03 55pp

7905200341 Request by Central Power & Light that ABLN issue protective order re interrogatories & request for production of documents from Houston Lighting & Power. Certificate of Div encl.
BUTLER, D. H. Inham, Lincoln & Beale 79/04/03 7pp

7905100323 Response to TX Utility Generating Co's objections to & motion for protective order & motion to compel further answers to interrogatories & request for production of documents.
Certificate of Div encl.
BLUM, M. B. Anti-Trust Division 79/04/04 54pp

7905100315 Motion by Public Utility Board of Brownsville, TX to compel further production of documents from South TX Electric Cooperative & Madine Electric Cooperative. Supporting documentation & Certificate of Div encl.
FOSTER, H. R. Spigal & McDiarmid 79/04/05 17pp

7905140326 Request by Central Power & Light for extension of time to respond to 7905200341 responses by Houston Lighting & Power & TX Utility Generating Co to former's interrogatories & document requests. Certificate of Div encl.
STAN, D Inham, Lincoln & Beale 79/04/05 4pp

7905100336 Motion that respondent be motions for summary disposition filed by Houston Lighting & Power & TX Utility Generating Co be governed by 105792 79041 Certificate of Div encl.
LARRY, R. P. Anti-Trust Division 79/04/06 5pp

7905200406 Motion by Houston Lighting & Power for protective order re public disclosure of info requested by Public Utility Board of Brownsville, TX. Certificate of Div encl.
BARNETT, E. M., Baker & Butts, BURNING, J. A. Lauenstein, Neuman, Reis, Asinof & Toll 79/04/06 9pp

7905200350 Motion of discovery & production during Mar 1979 Certificate of Div encl.
BALDWIN, R. C. Austin, Tex. 79/04/06 3pp

7905100412 Applies restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utility Board of Brownsville, TX.
HALL, R. H. E. Atomic Safety and Licensing Board Panel 79/04/09 5pp

7905200408 Motion re discovery for Mar 1979. Discovery requests were neither initiated nor resolved. Certificate of Div encl.
JOHN, D. F. Attn: Comp. Hauer & Feld 79/04/09 3pp

7905200368 Answer by Houston Power & Lighting to NRC 790523 response to utility motion for protective order. NRC motion to compel further answers to interrogatories & NRC request for production of documents. Certificate of Div encl.
BARNETT, E. M., Baker & Butts, BURNING, J. A. Lauenstein, Neuman, Reis, Asinof & Toll 79/04/11 10pp

7905200340 Forwards revised page 20-1 attached to Central Power & Light Co's answers & objections to Houston Lighting & Power Co's first set of written interrogatories to Central Power & Light Co. Certificate of Div encl.
STAN, D. H. Inham, Lincoln & Beale 79/04/12 4pp

7905240323 Advice no discovery requests have been initiated or received by Tex. Electric Cooperative. Certificate of Div encl.
BURNING, J. A. Northwest City 79/04/12 4pp

7905100343 Grants motions for attention of time for parties to respond to discovery requests.
HALL, R. H. E. Atomic Safety and Licensing Board Panel 79/04/13 5pp

7905200440 South TX Electric Cooperative, Inc. & Madine Electric Cooperative, Inc.'s opposition to Public Utility Board of Brownsville, TX 790423 motion for further responses to interrogatories. Certificate of Div encl.
HURTELL, R. Madine, Lachy & Kilgore, JOHN, D. F. Attn: Comp. Hauer & Feld 79/04/13 11pp

7905200467 Advice that during Mar 1979 NRC filed motions to compel against Houston Lighting & Power & TX Utility Generating Co. NRC is preparing responses to TX Utility's first & Houston's second set of interrogatories.
LARRY, R. P. Anti-Trust Division 79/04/13 1p

7905200429 Ack receipt of response to Mar 1979 motion to compel & evaluation in progress.
LARRY, R. P. Anti-Trust Division 79/04/13 1p

7905140326 Request by Public Utility Board of Brownsville, TX for extension of time to answer first set of interrogatories & requests for production of documents from Central Power & Light & Houston Lighting & Power. Certificate of Div encl.
HARRIS, J. L. Spigal & McDiarmid 79/04/16 7pp

7905200424 Corrects revised page 20-1 of Central Power & Light Co answers & objections to 790523 motion for summary disposition other than expenditures to expenditures other than advertising. Certificate of Div encl.
STAN, D. H. Inham, Lincoln & Beale 79/04/17 4pp

7905100380 Orders TX Utility Generating Co (TUGSC) to produce documents or make full responses to 790513 interrogatories. Series 790523 order for protective order.
HALL, R. H. E. Atomic Safety and Licensing Board Panel 79/04/18 5pp

7905200424 Response by utility to Central Power & Light's 790523 objections & 790523 motion for protective order re utility's first set of interrogatories. Includes motion to compel answers. Certificate of Div encl.
BARNETT, E. M., Baker & Butts, BURNING, J. A. Lauenstein, Neuman, Reis, Asinof & Toll 79/04/19 48pp

7905200477 Grants extension of time to answer interrogatories by Public Utility Board of Brownsville, TX in response to 790516 motion.
HALL, R. H. E. Atomic Safety and Licensing Board Panel 79/04/19 1p

7905100318 Motion by Central Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted.
Supporting documentation & Certificate of Div encl.
STAN, D Inham, Lincoln & Beale 79/04/20 20pp

7905100323 Motion by Central Power & Light to compel TX Utility Generating Co to answer first set of interrogatories submitted 790523.
STAN, D Inham, Lincoln & Beale 79/04/20 10pp

7905200271 Answer by Central Power & Light & Central & South West Corp seeking continuance of NRC anti-trust review. NRC partly based on grounds of new judicial collateral estoppel. Supporting documentation & Certificate of Div encl.
FOSTER, H. R., MILLER, M. L., STAN, D. H. Inham, Lincoln & Beale 79/04/20 112pp

7905100316 Opposes City of Austin's 790329 brief & 790403 motions for full or partial summary judgment filed by Houston Lighting & Power & TX Utility Generating Co. Beale denial of certification & intervenors' appeals. Certificate of Div encl.
LARRY, R. P., BLUM, M. B. Anti-Trust Division 79/04/23 24pp

7905140315 Response of Public Utility Board of Brownsville, TX opposing Houston Lighting & Power motion for summary decision & City of Austin brief in support of new judicial collateral estoppel. Certificate of Div encl.
HARRIS, J. L., BALDWIN, R. C., FOSTER, H. R. Spigal & McDiarmid 79/04/23 8pp

7905200466 NRC answer re motions of Gulf States Utility for protective order & order setting conditions for compliance w/790523 subpoenas. Utility should produce documents as requested. Certificate of Div encl.
BLUM, M. B. Anti-Trust Division 79/05/04 14pp

0 Inspection Reports, IE Bulletins & correspondence

7905200416 Response to IE Bulletin 79-01 No action to be taken at this time.
GARY, R. J. Texas Utilities Generating Co 79/05/19 5pp

7905200741 Details actions taken in response to IE Bulletin 79-047. States that no corrective action is indicated none of safety-related equipment.
GARY, R. J. Texas Utilities Generating Co 79/05/19 5pp

7905200416 Forwards info meeting re 790513 meeting w/IE & local public officials in Granbury, TX to discuss status of resident inspector.
BEILE, W. C. Regis & Geller, Necker Construction & Engineering Report Branch 79/05/02 5pp

DOCKETED ITEMS

7905070209 Summary of 790213 info meeting w/local officials of
Orlando, FL re assignment of resident inspectors, lines of
communication, facility status & community concerns
WATSON, R. D. MCNEIL, C. J. CHISHOLM, R. A. Region 4, Dallas, Office
of the Director 79/03/02 3pp

7905030345 Forwarded IE Insp Rpts 80-445/79-03 & 80-446/79-03 on
790320-28, notice of violation already forwarded w/REC 790320
ltr.
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/03/04 2pp

7905030370 IE Insp Rpts 80-445/79-02 & 80-446/79-03 on 790320-28
Noncompliance noted Failure to follow concrete placement
procedures
WATSON, R. D. Region 4, Dallas, Office of the Director 79/03/13
3pp

7905030381 Forwarded IE Info Notice 79-04, "Stress Analysis of
Safety-Related Piping"
SEIDLE, M. C. Region 4, Dallas, Office of the Director 79/03/23,
1p

7905030384 Forwarded IE Insp Rpts 80-445/79-07 & 80-446/79-07 on
790320-12 & 13, No noncompliance noted
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/03/23 2pp

7905030381 IE Insp Rpts 80-445/79-07 & 80-446/79-07 on 790320-12 & 13,
No noncompliance noted Major area Unacceptable const
activities
SEIDLE, M. C. Region 4, Dallas, Reactor Construction &
Engineering Support Branch BRANCH 3: CLERK, R. L. Region 4,
Dallas, Office of the Director 79/03/23 3pp

7905030444 Forwarded IE Bulletin 79-05A, "Nuclear Incident at
TMI - Part 1"
SEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/05
1p

7905040501 Forwarded IE Bulletin 79-06B, "Review of Operational Errors &
Age Misalignments Identified During TMI Incident"
SEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/14
1p

7905040529 Forwarded IE Bulletin 79-09, "Events Relevant to Rolling
Major Power Reactors Identified During TMI Incident"
SEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/14
1p

7905070380 Forwarded IE Bulletin 79-07, "Stress Analysis of
Safety-Related Piping." Licensee action required
SEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/14
1p

7905010442 Forwarded IE Info Notice 79-10, "Nonconforming Pipe Support
Struts."
SEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/14
1p

7905040518 Forwarded suppl to IE Bulletin 79-05A, "Nuclear Incident at
TMI"
SEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/14
1p

7905030283 Forwarded IE Bulletin 79-09, "Failures of GE Type M-2
Circuit Breaker in Safety-Related Sys." Licensee action
required
SEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/17
1p

7905020421 Ack receipt of 790320 & 2412 ltr informing NRC of steps
taken to correct violations noted in IE Insp Rpt
80-445/79-04 & 80-446/79-04.
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/26 1p

7905020648 Response to NRC 790320 ltr re violations noted in IE Insp
Rpts 80-445/79-04 & 80-446/79-04. Corrective actions
equipment repair record for ventilation fan motor
revised.
WATSON, R. D. Texas Utilities Generating Co 79/04/12 3pp

B. Reportable occurrences, LERs & related correspondence

7905030140 Forwarded PNO-79-470, I, J & K.
SEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/06,
1p

7905030080 Forwarded PNO-79-470, M, N & P.
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/09 1p

7905030107 Forwarded PNO-79-470
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/10 1p

7905030151 Forwarded PNO-79-470 & 79-77
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/11 1p

7905030124 Forwarded PNO-79-470
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/12 1p

7905030201 Forwarded PNO-79-477
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/13 1p

7905030374 Forwarded PNO-79-470 & V.
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/14 1p

7905030384 Forwarded PNO-79-474
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/17 1p

7905030314 Forwarded PNO-79-474A
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/23 1p

7905030208 Forwarded PNO-79-470, AC & AG.
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/23 1p

7905040580 Forwarded PNO-79-474E
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/26 1p

7905070193 Forwarded PNO-79-474F & AG.
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/27 1p

7905010230 Forwarded PNO-79-474M, AI & AJ.
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/04/30 1p

7905040299 Forwarded PNO-79-474K & AL.
SEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering
Support Branch 79/05/04 1p

7905010192 Confirms potentially 80 re reactor vessel nozzle weld metal
detected originally reported in 790326 telcon. Investigation
continues.
OMRY, R. J. Texas Utilities Generating Co 79/05/14 1p

DOCKET 87N-50-447 SEBRAN-228

A. Application/construction stage documents & correspondence

7905020448 Response to 790321 ltr requesting June 1979 deadline for
detailed review of SEBRAN-228 NE preliminary design approval
extension. Due to manpower shortages, extension review will
not be conducted on schedule
SEIDLE, M. C. Office of Nuclear Reactor Regulation 79/04/16, 7pp

J. Insurance & indemnity information

7905070382 Confirms increase in liability limit to \$24,000,000 for
policyholders NF-20, 26, 29, 33, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 59, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87,
88, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D. H. Mutual Atomic Energy Liability Underwriters 79/05/01,
1p

DOCKET 80-448 DOUGLAS POINT NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905030374 Forwarded "Site Selection Study for Two 1,100 Megawatt
Nuclear Power Plants," prepared by Dames & Moore
CON, E. T. Polomac Electric Power Co. 79/05/07, 2pp

7905030374 "Site Selection Study for Two 1,100 Megawatt Nuclear Power
Plants,"
Polomac Electric Power Co. 79/05/01, 70pp

J. Insurance & indemnity information

7903010013 Endorsement 99 to NAEML Policy NF-92
GERAB, T. Nuclear Energy Liability Insurance Association 79/03/27
1p

7903070497 Confirms increased liability limit to \$224,000,000 for
policies NF-125, 43, 74, 82, 105, 111, 140, 146, 151, 140, 144, 170,
173, 174, 176, 179, 180, 182, 183, 185, 186, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUARTROCHI, J. American Nuclear Insurers 79/02/01 1p

7903070582 Confirms increase in liability limit to \$26,000,000 for
policies NF-22, 24, 26, 29, 30, 34, 44, 47, 49, 50, 51, 52, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/02/01
1p

7903070587 Forwards amend to application for CP & CL submitted as
Amend 20 to FEAR
REED, C. Commonwealth Edison Co 79/03/02 2pp

7903070574 Amend 20 to FEAR
* Commonwealth Edison Co 79/03/02 400pp

7903030281 Forwards affidavit of distribution for FEAR Amend 20
HAUGHTON, M. P. Commonwealth Edison Co 79/03/11 2pp

K. Inspection reports, IC Bulletins & correspondence

7903020421 Forwards response to IE Bulletin 79-12 & 79-12A, "Algal
Welds in Reactor Pressure Vessel Heads"
REED, C. Commonwealth Edison Co 79/03/02 10pp

7903010204 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/03/23
1p

7903030270 Forwards IE Info Notice 79-07, "Buckling of Reinforced Tanks"
KAPPLER, J. S. Region 3, Chicago, Office of the Director 79/03/26
1p

7903030603 Forwards IE Bulletin 79-04, "Review of Operational Errors &
Key Missions Identified During The Incident"
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/04/11
1p

7903010089 Forwards IE Bulletin 79-04A, "Review of Operational Errors &
Key Missions Identified During The Incident"
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/04/14
1p

7903040234 Forwards IE Bulletin 79-04B, "Review of Operational Errors &
Key Missions Identified During The Incident"
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/04/14
1p

7903040529 Forwards IE Bulletin 79-06, "Events Relevant to Belling
Hatch Reactor Identified During The Incident"
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/04/14
1p

7903010380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Brace"
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/04/14
1p

7903030204 Forwards IE Bulletin 79-09, "Failures of GE Type AR-2
Control Reactor In Safety-Related Pipe - Licensee action
required."
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/04/17
1p

7903040142 Forwards IE Bulletin 79-08B, "Nuclear Incident at
TRI-Nucl."
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/04/21
1p

7903040129 IE Bulletin 79-08B, "Nuclear Incident at TRI-Nucl."
Supporting documentation encl.
* Region 3, Chicago, Office of the Director 79/04/21 10pp

7903040170 ACES recommendations to 790302 incident at TRI. Suggests high
priority be placed on development of safety research on
behavior of LWRs during annular flow transients.
* ACES - Advisory Committee on Reactor Safeguards 79/04/17
2pp

7903040201 Forwards ACES recommendations re TRI incident presented to
790417
SALEBY, R. P. ACES - Advisory Committee on Reactor Safeguards
79/04/18 1p

7903040202 In response to NRC 790418 ltr. states all 790417 ACES
recommendations apply to all PWRs, but were not intended to
require immediate changes. Plant modifications should be made after
study of effects on overall safety. TRI excluded.
SALEBY, R. P. ACES - Advisory Committee on Reactor Safeguards
79/04/20 2pp

7903040203 Forwards response to IE Bulletin 79-07 requesting data re
static analysis of safety-related piping. Comments
indicate method of instrument combination has little effect
on pipe stresses & equipment support loads.
REED, C. Commonwealth Edison Co 79/04/24 4pp

DOCKET 30-455 BYRON STATION UNIT 2

A. Application/construction stage documents & correspondence

7903040402 Notifies of intention to develop safety analysis using
existing computer codes. Requests add info.
HOLMES, C. M. Commonwealth Edison Co 79/04/26 1p

B. Adjudicatory correspondence

7903050187 Grants petition to intervene to Defend Area Alliance to
Responsible Energy Initiatives Alliance for Envision & League
of Women Voters of Rockford. IL. Requests N. Hesterman's
petition for not satisfy "interest" requirements.
LUTON, E. Atomic Safety and Licensing Board Panel 79/03/23 3p

7903020244 Request by util that AELB schedule special rehearing
for 100R22 Trial Certificate of Decision
HARRIS, P. H. (Judge, Lincoln & Smith 79/04/18 2pp

7903040204 Response to 790411 ltr. re respondent's petition to intervene
in Facility OL proceeding. AELB issued order on 790320
holding that 3 nuclear PWRs had sufficiently demonstrated
standing to proceed.
GOSSELINK, V. Office of the Executive Director for Operations
79/03/08 2pp

J. Insurance & indemnity information

7903010013 Endorsement 99 to NAEML Policy NF-92
GERAB, T. Nuclear Energy Liability Insurance Association 79/03/27
1p

7903070497 Confirms increased liability limit to \$224,000,000 for
policies NF-125, 43, 74, 82, 105, 111, 140, 146, 151, 140, 144, 170,
173, 174, 176, 179, 180, 182, 183, 185, 186, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215 & others.
QUARTROCHI, J. American Nuclear Insurers 79/02/01 1p

7903070582 Confirms increase in liability limit to \$26,000,000 for
policies NF-22, 24, 26, 29, 30, 34, 44, 47, 49, 50, 51, 52, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/02/01
1p

K. Utility Final Safety Analysis Report (FSAR) & amendments

7903070587 Forwards amend to application for CP & CL submitted as
Amend 20 to FEAR
REED, C. Commonwealth Edison Co 79/03/02 2pp

7903070574 Amend 20 to FEAR
* Commonwealth Edison Co 79/03/02 400pp

7903030281 Forwards affidavit of distribution for FEAR Amend 20
HAUGHTON, M. P. Commonwealth Edison Co 79/03/11 2pp

L. Inspection reports, IE Bulletins & correspondence

7903020421 Forwards response to IE Bulletin 79-12 & 79-12A, "Algal
Welds in Reactor Pressure Vessel Heads."
REED, C. Commonwealth Edison Co 79/03/02 10pp

7903010204 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
KAPPLER, J. D. Region 3, Chicago, Office of the Director 79/03/23
1p

DOCKETED ITEMS

221

7903030970 Forwards IE Info Notice 79-07, "Rupture of Reactant Tanks"
KEPFLER, J.S. Region 3, Chicago, Office of the Director 79/03/26
lp

7903030013 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Ops Misalignments Identified During THE Incident"
KEPFLER, J.S. Region 3, Chicago, Office of the Director, 79/04/11
lp

7903030969 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Ops Misalignments Identified During THE Incident"
KEPFLER, J.S. Region 3, Chicago, Office of the Director, 79/04/14
lp

7903040236 Forwards IE Bulletin 79-08, "Review of Operational Errors &
Ops Misalignments Identified During THE Incident"
KEPFLER, J.S. Region 3, Chicago, Office of the Director 79/04/14
lp

7903040329 Forwards IE Bulletin 79-08, "Events Relevant to Selling
Water Pumps Reactors Identified During THE Incident"
KEPFLER, J.S. Region 3, Chicago, Office of the Director 79/04/14
lp

7903040300 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Structure"
KEPFLER, J.S. Region 3, Chicago, Office of the Director 79/04/18
lp

7903040306 Forwards IE Bulletin 79-09, "Failures of GE Type AK-2
Circuit Breaker in Safety-Related Sys." Licensee action
required
KEPFLER, J.S. Region 3, Chicago, Office of the Director 79/04/17
lp

7903040142 Forwards IE Bulletin 79-08, "Nuclear Incident at
THI-Boppel"
KEPFLER, J.S. Region 3, Chicago, Office of the Director, 79/04/21
lp

--7903040118 IE Bulletin 79-08, "Nuclear Incident at THI-Boppel"
Supporting documentation encl.
Region 3, Chicago, Office of the Director 79/04/21 13pp

--7903040170 ACRS recommendations re 790302 Incident at THI suggests high
priority be placed on development of safety research on
behavior of LWRs during accident transients
a ACRS - Advisory Committee on Reactor Safeguards. 79/04/17.
2pp

--7903040201 Forwards ACRS recommendations re THE Incident, presented on
7904/17.
KEPFLER, J.S. ACRS - Advisory Committee on Reactor Safeguards.
79/04/18 lp

--7903040202 IE response to NRC 790418 ltr, status all 790417 ACRS
recommendations apply to all PWRs but were not intended to
require immediate changes PWRs should be made after
study of effects on overall safety. The enclosed.
CARROLL, H.T. ACRS - Advisory Committee on Reactor Safeguards.
79/04/20. 2pp.

7903040623 Forwards response to IE Bulletin 79-07 requesting info re
seismic analysis of safety-related piping. Remarks
indicates method of instrumented combustion has little effect
on pipe stresses & equipment support loads.
KEPFLER, J.S. Region 3, Chicago, Office of the Director 79/04/24 App

DOCKET 50-456 UNANNOUNCED STATUS, UNIT 1

A Application/construction stage documents & correspondence

7903040482 Notifies of intention to develop safety analysis using
existing computer codes Requests add info
BOLDRIO, C.W. Commonwealth Edison Co. 79/04/26. lp.

7903050337 Discusses Penn. bunking program at Facility. Number of
pumps will be reduced as construction progresses to minimize
possibility of injury & prevent interference w/consent Special
pumps are available
KEPFLER, J.S. Commonwealth Edison Co. 79/06/14. 2pp

G. Adjudicatory correspondence

7903030032 Grants petition to intervene filed by B. Rosen on behalf of
Selling Alliance & S. Baker. Penn. Inc. Requests R. Newstrom's
petition to Intervene for failure to demonstrate standing.
LUTON, E. Atomic Safety and Licensing Board Panel 79/03/22. App.

7903050084 Request by utility that AES schedule special prehearing
conference per DOE's 79101. Certificate of NRC encl.
MURPHY, P.H. Inham, Lincoln & Neale 79/04/18 2pp

7903240024 Responses to 790418 ltr re consent petition to intervene
in Facility B. processing AES issued order on 790323
holding that S. Baker Penn. Inc. had sufficiently demonstrated
standing in proceeding
DOERFEL, L.V. Office of the Executive Director for Operations
79/05/01 2pp

J Insurance & indemnity information

7903050143 Endorsement 99 to NRC's Policy 99-02.
GEARAT Nuclear Energy Liability Insurance Association 79/03/27
lp

7903070497 Confirms increased liability limit to \$124,000,000 for
policies 99-1, 25-43, 76, 82, 100, 111, 140, 140, 161, 164, 170,
171, 174, 175, 176, 183, 185, 186, 187, 188, 189, 190, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 213, 214, 215 & others
QUARTROCHI, J. American Nuclear Insurers 79/05/01 lp

7903070588 Confirms increase in liability limit to \$20,000,000 for
policies 99-23, 26, 29, 30, 31, 44, 46, 47, 49, 50, 51, 52, 53, 54,
57, 58, 60, 61, 64, 65, 67, 68, 69, 70, 71, 72, 74, 76, 77, 79, 79, 80, 84, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTS, D. Mutual Atomic Energy Liability Underwriters 79/05/01
lp

K. Utility Final Safety Analysis Report (FSAR) & amendments

7903070507 Forwards amend to application for CP & CL submitted as
Amend 20 to FSRB
KEPFLER, J.S. Commonwealth Edison Co. 79/05/02 2pp

--7903070574 Amend 20 to FSRB.
Commonwealth Edison Co. 79/05/02. 43pp

7903100381 Forwards affidavit of distribution for FSRB Amend 20
NAUGHTON, W.P. Commonwealth Edison Co. 79/05/11. 2pp

L Inspection Reports IE Bulletin & correspondence

7903050421 Forwards response to IE Bulletin 79-12 & 79-12A, "Atypical
Nail Pen. in Reactor Pressure Vessel Welds."
KEPFLER, J.S. Commonwealth Edison Co. 79/03/22 10pp

7903010236 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping."
KEPFLER, J.S. Region 3, Chicago, Office of the Director 79/03/23
lp

7903030370 Forwards IE Info Notice 79-07, "Rupture of Reactant Tanks."
KEPFLER, J.S. Region 3, Chicago, Office of the Director, 79/03/26.
lp

7903240780 Forwards IE Insp Repts 30-456/79-04 & 30-457/79-04 on
790302-21 & 23 re noncompliance.
FICHELLI, G. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/05/15. 2pp

--79061
No
en
cl
encl
SI

7903053
By
KEPFLER, J.S.

7903051
By
KEPFLER, J.S.

7903054
By
KEPFLER, J.S.

DOCKETED ITEMS

7903040229 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Power Reactors Identified During THE Incident".
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/18 1p

7903040380 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets".
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/19 1p

7903040206 Forwards IE Bulletin 79-09, "Failure of GE Type AA-8 Circular Breaker in Safety-Related Bus" License action required.
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/17 1p

7903040142 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Bugel".
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/20 1p

--7903040256 IE Bulletin 79-05B, "Nuclear Incident at TMI-Bugel" Supporting documentation email.
Region 3, Chicago, Office of the Director. 79/04/21 12pp

--7903040170 ACRB recommendations re 790303B incident at TMI suggests high priority be placed on development of safety research on behavior of LWRs during anomalous transients.
ACRB - Advisory Committee on Reactor Safeguards. 79/04/17 2pp

--7903040205 Forwards ACRB recommendations re THE incident presented on 790417.
FRALBY, R. P. ACRB - Advisory Committee on Reactor Safeguards. 79/04/18 1p

--7903040221 In response to NRC 790418 ltr, states all 790417 ACRB recommendations apply to all PWRs, but were not intended to require immediate change. Plant needs should be made after study of effects on overall safety. TMI accident.
CONRAD, R. S. ACRB - Advisory Committee on Reactor Safeguards. 79/04/20 2pp

7903040433 Forwards responses to IE Bulletin 79-07 requesting info re recent analysis of safety-related piping. Analysis indicates method of intracode combination has little effect on pipe stresses & equipment support loads.
NEED, C. Commonwealth Edison Co. 79/04/28 4pp

DOCKET 30-457 BRAINARD STATION, UNIT 2

A. Application/construction stage documents & correspondence

7903030087 Forwards NUREG-0219, "Nuclear Security Personnel for Power Plants, Contact & Review Procedures for Security Training & Qualification Program." w/enc.
VARNALD, D. S. Assistant Director for Light Water Reactors. NUREG-0219. 79/09/23 4pp

7903040462 Notification of intention to develop safety analysis using existing computer codes. Requests add info.
BOLMIND, C. Commonwealth Edison Co. 79/04/25 1p

7903020037 Decreases fowell hunting program at facility. Number of passes will be reduced as cost progresses to minimize possibility of failure & prevent interference w/next. Special permits are available.
NEED, C. Commonwealth Edison Co. 79/05/14 3pp

B. Regulatory correspondence

7903030032 Grants petition to Intervene filed by SL Rosen on behalf of Boiling Alliance & B Weiner. Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Power Reactors Identified During THE Incident".
LUTCH, E. Atomic Safety & Licensing Board Panel. 79/03/22 4pp

7903030284 Request by UHL that ALE schedule special prehearing conference per 10CFR72.701(c). Certificate of Not avail.
MURPHY, P. M. John, Lincoln & Steele. 79/04/18 3pp

7903040434 Responds to 790418 ltr re constituent petition to Intervene in facility SL proceeding ALEB issued over on 790302B holding that B Weiner. Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Power Reactors Identified During THE Incident".
DOERFEL, L. V. Office of the Executive Director for Operations. 79/05/08 3pp

H. General correspondence

7903130458 Forwards 790329 ltr from constituent B Weiner re petition to Intervene in SL proceedings. Requests assistance in preparations for intervention.
O'BRIEN, G. M. House of Rep. 79/04/11 3pp

7903100143 Endorsement 99 to NAREL Policy 79-02.
OBRAN, P. Nuclear Energy Liability Insurance Association. 79/03/27 1p

7903070497 Confirms increased liability limit to \$104,000,000 for policies 79-1, 23, 43, 74, 83, 105, 111, 182, 146, 191, 168, 164, 173, 172, 174, 176, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 205, 207, 208, 210, 212, 214, 215, & others.
WATTS, R. C. American Nuclear Insurers. 79/03/01 1p

7903070382 Confirms increase in liability limit to \$34,000,000 for policies 79-22, 26, 29, 30, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 61, 64, 66, 67, 68, 69, 71, 72, 74, 75, 76, 77, 78, 79, 80, 82, 83, 84, 85, 86, 90, 91, 92, 93, 94, 95 & 96.
ROSENBERG, S. Mutual Atomic-Energy Liability Underwriters. 79/03/01 1p

I. Utility Final Safety Analysis Report (FSAR) & amendments

7903070357 Forwards amendment to application for CP & CL exhibited at Amend 20 to FSAR.
NEED, C. Commonwealth Edison Co. 79/05/02 3pp

--7903070374 Amend 20 to FSAR.
Commonwealth Edison Co. 79/05/02 430pp

7903100351 Forwards affidavit of distribution for FSAR Amend 20.
KNAUTH, C. W. Commonwealth Edison Co. 79/05/01 2pp

J. Inspection reports, IE Bulletins & correspondence

7903040241 Forwards response to IE Bulletin 79-12 & 79-10A: "Alphabet Mail sent to Reactor Pressure Vessel Nozzle".
NEED, C. Commonwealth Edison Co. 79/03/22 10pp

7903100204 Forwards IE Info Notice 79-03, "Stress Analysis of Safety-Related Piping".
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/03/29 1p

7903030070 Forwards IE Info Notice 79-07, "Review of Refueling Forks".
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/03/26 1p

7903040748 Forwards IE Insp Rpts 80-456/79-04 & 80-457/79-04 re 790320-21 & 22. No noncompliance.
FIORELLI, D. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/04/10 2pp

--7903040748 IE Insp Rpts 80-456/79-04 & 80-457/79-04 re 790320-21 & 22. No noncompliance noted. Major areas inspected: storage of MGB components & safety-related equipment; quality records for Class 2 & 3 equipment & automatic pipe welder operation.
EUB, C. R. DANIELSON, D. L. Region 3, Chicago, Office of the Director. 79/04/04 4pp

7903030415 Forwards IE Bulletin 79-06, "Review of Operational Errors & Sys Misalignments Identified During THE Incident".
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/16 1p

7903030549 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During THE Incident".
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/16 1p

7903040334 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During THE Incident".
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/16 1p

7903040329 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Power Reactors Identified During THE Incident".
HEFFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/16 1p

DOCKETED ITEMS

223

7905010385 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KOPFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/10. 1p.

7905010386 Forwards IE Bulletin 79-09, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
KOPFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/10. 1p.

7905010412 Forwards IE Bulletin 79-039, "Nuclear Incident at THU-Regpl."
KOPFLER, J. O. Region 3, Chicago, Office of the Director. 79/04/01. 1p.

--7905010418 IE Bulletin 79-098, "Nuclear Incident at THU-Regpl."
Supporting documentation sent.
Region 3, Chicago, Office of the Director. 79/04/21. 62p.

--7905010470 ACRS recommendations re 790328 incident at THU. Suggests high priority be placed on development of safety research on behavior of LMRs during anomalous transients.
ACRS - Advisory Committee on Reactor Safeguards. 79/04/17. 2p.

--7905010501 Forwards ACRS recommendations re THU incident presented on 790417.
PRALYER, R. ACRS - Advisory Committee on Reactor Safeguards. 79/04/18. 1p.

--7905010502 In response to NRC 790418 illustrates all 790417 ACRS recommendations apply to all PWRs, but were not intended to require immediate changes. Plans made should be made after study of effects on overall safety. THU excluded.
CARROLL, K. J. ACRS - Advisory Committee on Reactor Safeguards. 79/04/20. 2p.

7905010618 Forwards responses to IE Bulletin 79-07 requesting info re seismic analysis of safety-related piping. Reanalyses indicates method of intramural combination has little effect on pipe stresses & equipment support loads.
NRCED, G. Commonwealth Edison Co. 79/04/04. 4pp.

DOCKET 50-458 RIVER BEND STATION, UNIT 1
A. Application/Construction stage documents & correspondence

7905010637 Forwards NUREG-0801, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability.
VALLBO, D. B. Assistant Director for Light Water Reactors. 79/03/23. 2pp.

7905010638 Notices of reorganization of unit's Engineering & Safety Dept. JO Weiland has overall responsibility for River Bend project.
HMFHMBTG, L. L. Gulf States Utilities Co. 79/05/03. 1p.

7905010639 Advances of data from 790301 to 791201 in providing response to NRC concerns re use of austenitic stainless steel in PWR facilities. Presently examining recommendations of pipe crack study in NUREG-0801.
MELONIN, J. O. Gulf States Utilities Co. 79/05/20. 1p.

7905010677 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
SEIFRIT, K. V. Region 4, Dallas, Office of the Director. 79/03/23. 1p.

7905010438 Forwards IE Bulletin 79-05A, "Nuclear Incident at THU - Regpl."
SEIFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/05. 1p.

7905010489 Forwards IE Bulletin 79-046, "Review of Operational Errors & Bus Misassignments Identified During THU Incident."
SEIFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905010510 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Power Reactors Identified During THU Incident."
SEIFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905010505 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
SEIFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905010443 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
SEIFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905010509 Forwards reply to IE Bulletin 79-05A, "Nuclear Incident at THU."
SEIFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/14. 1p.

7905010527 Forwards IE Bulletin 79-09, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
SEIFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/17. 1p.

B. Reportable occurrences, LERs & related correspondence

7905010808 Confirms 790329 telcon concerning potential deficiency re support column sleeve welds wfg by Graver Energy Sys. Will submit interim report within 30 days.
HMFHMBTG, L. L. Gulf States Utilities Co. 79/05/30. 1p.

7905010521 Forwards PWD-79-676, I.J. & K.
SEIFRIT, K. V. Region 4, Dallas, Office of the Director. 79/04/04. 1p.

7905010587 Forwards PWD-79-671, M.N. & P.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/05. 1p.

7905010591 Forwards PWD-79-673.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/10. 1p.

7905010597 Forwards PWD-79-678 & 79-77.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/11. 1p.

7905010617 Forwards PWD-79-676.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/12. 1p.

7905010618 Forwards PWD-79-677.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/12. 1p.

7905010673 Forwards PWD-79-670 & V.
HMFHMBTG, L. L. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/16. 8p.

7905010628 Forwards PWD-79-674.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/17. 1p.

7905010628 Forwards PWD-79-674A.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/20. 1p.

7905010648 Forwards PWD-79-678A, AC & AD.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/23. 1p.

7905010654 Forwards PWD-79-678E.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/24. 1p.

7905010680 Forwards PWD-79-678F & AG.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/27. 1p.

7905010626 Forwards PWD-79-678H, AI & AJ.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/28. 1p.

7905010694 Forwards PWD-79-678K & AL.
SEIFRIT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/05/04. 1p.

DOCKETED ITEMS

DOCKET NO-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

7905004037 Forwards WMO-0031, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of licensee & availability
WMSALO, D. B. Assistant Director for Light Water Reactors
79/05/23 3p

7905004043 Notice of reorganization of still's Engineering & Const Dept. J. H. Melpert has overall responsibility for River Bend Project
MELPERT, J. H. Gulf States Utilities Co. 79/05/28 1p

7905004048 Advice of delay from 790601 to 791201 in providing response to MRC concerns re use of synthetic stainless steel in SAR facilities presently examining recommendations of pipe crack study in WMO-0031
WDSAWO, J. D. Gulf States Utilities Co. 79/05/22 1p

S Inspection reports, IE Bulletin & correspondence

7905004077 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
BEYRETT, K. V. Region 4, Dallas, Office of the Director 79/03/23 1p

7905004083 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI - Borel"
BEYRETT, K. V. Region 4, Dallas, Office of the Director 79/04/03 1p

7905004088 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
BEYRETT, K. V. Region 4, Dallas, Office of the Director 79/04/14 1p

7905004100 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
BEYRETT, K. V. Region 4, Dallas, Office of the Director 79/04/14 1p

7905004090 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping - Licensee action required."
BEYRETT, K. V. Region 4, Dallas, Office of the Director 79/04/14 1p

7905004094 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets"
BEYRETT, K. V. Region 4, Dallas, Office of the Director 79/04/16 1p

7905004098 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMI"
BEYRETT, K. V. Region 4, Dallas, Office of the Director 79/04/16 1p

7905004107 Forwards IE Bulletin 79-09, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Sys - Licensee action required."
BEYRETT, K. V. Region 4, Dallas, Office of the Director 79/04/17 1p

S Reportable occurrences, LERs & related correspondence

7905004036 Forwards PHO-79-07A, J & K
BEYRETT, K. V. Region 4, Dallas, Office of the Director 79/04/06 1p

7905004089 Forwards PHO-79-07L, M & P
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09 1p

7905004091 Forwards PHO-79-07B
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/10 1p

7905004093 Forwards PHO-79-07C & 79-77
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 1p

7905004097 Forwards PHO-79-07D
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 1p

7905004104 Forwards PHO-79-07E
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 1p

7905004090 Forwards PHO-79-07U & V
ENGLISH, R. H. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p

7905004096 Forwards PHO-79-07F
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 1p

7905004098 Forwards PHO-79-07G
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/20 1p

7905004099 Forwards PHO-79-07H, AC & AD
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p

7905004104 Forwards PHO-79-07I
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p

7905004100 Forwards PHO-79-07JF & AG
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p

7905004102 Forwards PHO-79-07K, AI & AJ
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30 1p

7905004104 Forwards PHO-79-07L & AL
BEYRETT, K. V. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/04 1p

DOCKET NO-460 WPPSS NUCLEAR PLANTS, UNIT 1

A Application/construction stage documents & correspondence

7905004065 Reply on geological studies" re: above Geologic rept. expected in Fall 1979. Requests meeting to discuss plans for submitting reply of studies, as well as mechanism for identification & review of studies in Hartford area.
RENDERSON, D. L. Washington Public Power Supply System 79/04/27 2p

7905004011 Forwards MRC position on WPPSS-04-004, "Operational OA Response Description." Response to position should be submitted by 790601 as annex to original rept.
HARRIS, P. Quality Assurance Branch 79/03/01 2p

7905004054 Requests MRC for visiting accessibility of scale model tests to line of equipment tests to activity completion in WPPSS-04
PRM Division & 77 re recirculation pump testing.
RENDERSON, D. L. Washington Public Power Supply System 79/03/13 1p

7905004094 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
ENGLISH, R. H. Region 4, Dallas, Office of the Director 79/03/23 1p

7905004092 Forwards IE Bulletin 79-05A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/14 1p

7905004094 Forwards IE Bulletin 79-05B, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident."
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/14 1p

7905004095 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Reactors Identified During TMI Incident"
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/14 1p

7905004100 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping - Licensee action required."
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/14 1p

7905004097 Forwards IE Bulletin 79-09, "Failures of GE Type AM-2 Circuit Breaker in Safety-Related Sys - Licensee action required."
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/17 1p

7905004097 Forwards IE Bulletin 79-09B, "Nuclear Incident at TMI-Borel."
ENGLISH, R. H. Region 3, San Francisco, Office of the Director 79/04/21 1p

DOCKETED ITEMS

226

790518069 Forwards RMD-79-67L
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/04 1p

790518070 Forwards RMD-79-67M
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/11 1p

790518071 Forwards RMD-79-67N
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/12 1p

790518072 Forwards RMD-79-67P
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/13 1p

790518073 Forwards RMD-79-67U
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/14 1p

790518074 Forwards RMD-79-67AA
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/20 1p

790518075 Forwards RMD-79-67AB
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/21 1p

790518076 Forwards RMD-79-67AC & AD
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/22 1p

790518077 Forwards RMD-79-67AE
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/24 1p

790518078 Forwards RMD-79-67AF
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/25 1p

790518079 Forwards RMD-79-67AG
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/26 1p

790518080 Forwards RMD-79-67AH
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/27 1p

790518081 Forwards RMD-79-67AI, AJ & AK per RMC 790401 ltr transmitting IE Bulletin 79-03
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/04/30 1p

790518082 Forwards RMD-79-67AL per RMC 790401 ltr transmitting IE Bulletin 79-03
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/05/01 1p

790518083 Forwards final deficiency report re loutdown cooler supports, per 790416 telegram
RSHAW,R.D. L. Washington Public Power Supply System. 79/05/07 1p.

790518084 Final deficiency report re loutdown cooler supports inadequate to support specified loads, caused by inadequate design by component manufacturer. Mail mounted brackets redesigned.
* Washington Public Power Supply System. 79/05/07 2pp.

790518085 Forwards RMD-79-67AM
ENGLER,R.H. Region 3, San Francisco, Office of the Director
79/05/07 1p.

790518086 Ack receipt of 790507 final deficiency report on loutdown cooler support design deficiencies.
ENGLER,R.H. Region 3, San Francisco, Office of the Director.
79/05/16 1p

DOCKET 80-441 CLETON POWER STATION, UNIT 1
A Application/construction stage documents & correspondence

790518087 Notification of proposed reactor pressure vessel and OE authorized to act as agent for performance of work which will be subcontracted to Reactor Controls, Inc. Work to begin 790517.
RSHAW,R.D. L. Illinois Power Co. 79/03/15 1p

790518088 Requests addl info re 790426 telcon concerning emission adds for operating nuclear power plants. seeks info re gamma release of U daughters & also for emission of radioactive products into cooling water.
RSHAW,R.D. Prairie Alliance. 79/04/26 2pp

G. Inspection reports, IE Bulletins & correspondence

790518089 Forwards IE Insp Rept 80-461/79-02 on 790506-08 Re containment. Rept
FIDELL,J.D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/22 2pp

790518090 IE Insp Rept 80-461/79-02 on 790506-08 Re noncompliance noted. Region areas inspected reactor coolant pressure boundary/safety-related piping & welding. QA manuals & procedures & work activities.
LISKE,V. Region 3, Chicago, Office of the Director
BARTLEMAN,D.H. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/19 2pp

790518091 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping."
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/03/23 1p

790518092 Forwards IE Info Notice 79-07, "Repture of Reducents Tests."
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/03/26 1p

790518093 Forwards IE Bulletin 79-08, "Review of Operational Errors & Gas Misalignments Identified During THE Incident."
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/04/11 1p

790518094 Forwards IE Bulletin 79-08A, "Review of Operational Errors & Gas Misalignments Identified During THE Incident."
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/04/14 1p

790518095 Forwards IE Bulletin 79-08B, "Review of Operational Errors & Gas Misalignments Identified During THE Incident."
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/04/14 1p

790518096 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping." Licensee action required.
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/04/14 1p

790518097 Forwards IE Bulletin 79-08, "Events Relevant to Sealing Motor Power Systems Identified During THE Incident."
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/04/14 1p

790518098 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/04/16 1p

790518099 Forwards IE Bulletin 79-09, "Failures of IE Type AM-2 Circuit Breaker in Safety-Related Systems." Licensee action required.
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/04/17 1p

790518100 Forwards IE Bulletin 79-09B, "Nuclear Incident at TH-3000."
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/04/21 1p

790518101 Forwards IE Circular 79-07, "Unsuspected Speed Increase of Reactor Recirculation Motor Generator Set Resulted in Reactor Power Increase."
KEFFLER,J.D. Region 3, Chicago, Office of the Director 79/03/02 1p.

G. Reportable occurrences, LERs & related correspondence

790518102 Ack receipt of 790507 final report re design mail platwork defects. Review will be completed during future insp.
FIDELL,J.D. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/23 1p.

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905040330 Requests add info re 790404 between concerning infusion site for operating nuclear power plants. Says info re general release of U daughter & beta for analysis of radioactive products into cooling water.
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/04/26 2pp

G. Inspection reports, IE Bulletin & correspondence

7905040327 Forwards IE Info Notice 79-06: "Stress Analysis of Safety-Related Piping."
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/03/20 1p

7905040328 Forwards IE Info Notice 79-07: "Nuclear of Radwaste Tanks."
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/03/26 1p

7905040323 Forwards IE Bulletin 79-06: "Review of Operational Errors & Site Missions Identified During DRI Incident."
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/04/11 1p

7905040300 Forwards IE Bulletin 79-06: "Review of Operational Errors & Site Missions Identified During DRI Incident."
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040294 Forwards IE Bulletin 79-06: "Review of Operational Errors & Site Missions Identified During DRI Incident."
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040409 Forwards IE Bulletin 79-07: "Stress Analysis of Safety-Related Piping." License action required.
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040264 Forwards IE Bulletin 79-06: "Events Relevant to Selling Water Power Reactors Identified During DRI Incident."
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/04/14 1p

7905040420 Forwards IE Info Notice 79-10: "Nonconforming Pipe Support Brackets."
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/04/16 1p

7905040328 Forwards IE Bulletin 79-09: "Failure of SC Tube AR-2 Circuit Breaker in Safety-Related Sys." License action required.
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/04/17 1p

7905040448 Forwards IE Bulletin 79-09: "Nuclear Incident at Trin-Trip."
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/04/21 1p

7905040456 Forwards IE Circular 79-07: "Unexpected Speed Increase of Reactor Recirculation Pump Generator Not Resulted in Reactor Power Increase."
REPLYER: J. S. Region 3, Chicago, Office of the Director 79/03/22 1p

DOCKET 50-462 FULTON GENERATING STATION, UNIT 1

B. Adjudicatory correspondence

7905040130 Updates 790302 ltr. advising IOGPR is available in Pittsburgh, PA Public Library.
REPLYER: J. S. Branch 1 79/04/09 1p

7905040114 Discusses notifications not previously supplied in hearings re nuclear power reactors, specifically Lewis Committee Report & interpretation of radionuclides in urban environs.
REPLYER: J. S. Branch 1 79/04/05 2pp

7905040117 Ack receipt of SW Zimmer memo re neutron exposure at commercial power reactors. Data does not imply lack of control by any licensee re neutron exposure nor does it indicate personnel neutron dosimetry problem exists at LWRs.
REPLYER: J. S. Division of Operating Reactors, VOL/HCS/R.H. Assistant Director for Site Analysis 79/03/06 2pp

7905040139 States that encl 790508 article by J. Anderson, "Neutron Radiation at Nuclear Plants" contains factual errors. No calculations have been made of neutron radiation inside nuclear plants. Forwards EO Case 790403 memo.
REPLYER: W.C. Commissioner 79/05/08 3pp

7905030246 Forwards info re behavior of turbine during postulated steam generator tube rupture accidents & aspects of accumulator delivery.
REPLYER: J. S. Branch 1 79/04/10 2pp

7905030091 Ack receipt of 790402 ltr & resolution opposing NRC early site suitability review. NRC will consider issues raised.
REPLYER: H.C. Division of Site Safety & Environmental Analysis 79/04/19 1p

7905030099 Forwards resolution opposing early site suitability review.
GALBREATH, P. Fulton Orange 856 79/04/02 2pp

H. General correspondence

7905030134 Responds to comments re opposition to facility location. NRC is required to conduct an early site review on site suitability issues selected by applicant & does not have initiative in this matter.
REPLYER: R.L. Environmental Projects Branch 1 79/04/03 1p

J. Insurance & indemnity information

7905070882 Confirms increase in liability limit to \$50,000,000 per policies. 79-05-26, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100.
REPLYER: H. Mutual Atomic Energy Liability Underwriters 79/05/01 1p

DOCKET 50-464 FULTON GENERATING STATION, UNIT 2

C. Adjudicatory correspondence

7905040130 Updates 790302 ltr. advising IOGPR is available in Pittsburgh, PA Public Library.
REPLYER: J. S. Branch 1 79/04/09 1p

7905040114 Discusses notifications not previously supplied in hearings re nuclear power reactors, specifically Lewis Committee Report & interpretation of radionuclides in urban environs.
REPLYER: J. S. Branch 1 79/04/10 2pp

7905040139 Ack receipt of SW Zimmer memo re neutron exposure at commercial power reactors. Data does not imply lack of control by any licensee re neutron exposure nor does it indicate personnel neutron dosimetry problem exists at LWRs.
REPLYER: J. S. Division of Operating Reactors, VOL/HCS/R.H. Assistant Director for Site Analysis 79/03/06 2pp

7905040139 States that encl 790508 article by J. Anderson, "Neutron Radiation at Nuclear Plants" contains factual errors. No calculations have been made of neutron radiation inside nuclear plants. Forwards EO Case 790403 memo.
REPLYER: W.C. Commissioner 79/05/08 3pp

7905030246 Forwards info re behavior of turbine during postulated steam generator tube rupture accidents & aspects of accumulator delivery.
REPLYER: J. S. Branch 1 79/04/10 2pp

7905030091 Ack receipt of 790402 ltr & resolution opposing NRC early site suitability review. NRC will consider issues raised.
REPLYER: H.C. Division of Site Safety & Environmental Analysis 79/04/19 1p

7905030099 Forwards resolution opposing early site suitability review.
GALBREATH, P. Fulton Orange 856 79/04/02 2pp

H. General correspondence

7905030134 Responds to comments re opposition to facility location. NRC is required to conduct an early site review on site suitability issues selected by applicant & does not have initiative in this matter.
REPLYER: R.L. Environmental Projects Branch 1 79/04/03 1p

DOCKETED ITEMS

227

J Insurance & indemnity information

7903030497 Confirm increased liability limit to \$100,000,000 for policies #7-22, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000.

7903030502 Confirm increase in liability limit to \$100,000,000 for policies #7-22, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000.

DOCKET 50-466 ALLEIGH CREEK NUCLEAR STATION UNIT 1

A Application/Obstruction Stage documents & correspondence

7903030378 Forwarded add info re reactor pressure vessel off-loading facility, in response to 7903030378 request.
MCQUEEN, W F Houston Lighting & Power Co. 79/03/17 App

7903030453 Responds to 790420 for & updates 790101 list of proposed & listed endangered species. Said species now listed as endangered in TX. Requests biological assessment within 180 days of listed species in plant construction area.
MCQUEEN, W F Interior, Dept. of Fish & Wildlife Service 79/03/22 App

E. NRC Safety Evaluation Report (SER), supply & correspondence

7903030549 Forwarded Suppl 2 to SER re application for OS, W&C encl.
WAGGON, B A Light Water Reactors Branch 4 79/04/29 App.

0 Adjudicatory correspondence

7903030501 Urges ARLB to modify 790302 order-grant JH Roberts's intervention petition & admit Contention 2 Certificate of Dvc encl.
BOKHINK, D H Branch 3 79/03/06 App.

7903030507 Request by Houston Lighting & Power that ARLB deny 790304 petition by JH Roberts & Amendment Contention for admission of previously abandoned contentions Certificate of Dvc encl.
CULP, R H, NEWMAN, J R, Lowenstein, Newman, Reis, Ansell & Telli, COPELAND, J G Baker & Bette 79/03/06 App

7903030513 Responds in application to TX PDR 790302 motion for admission of two contentions previously abandoned due to Class 7 accident prohibition based on NRC hearing. Certificate of Dvc encl.
BOKHINK, D H Branch 2 79/03/06 App

7903030503 Houston Lighting & Power's first set of interrogatories & request for production of documents for TX PDR Certificate of Dvc encl.
COPELAND, J G, Baker & Bette, NEWMAN, J R, CULP, R H, Lowenstein, Newman, Reis, Ansell & Telli, 79/03/15 App

7903030511 Request by Houston Lighting & Power that ARLB deny appeal of eight petitions for intervention filed in response to ARLB 790302 order. Certificate of Dvc encl.
NEWMAN, J R, REID, H F, CULP, R H, Lowenstein, Newman, Reis, Ansell & Telli, 79/03/15 App

7903030508 Request by Houston Lighting & Power that ARLB deny 790302 petition for directed certification filed by TX PDR. Petition does not meet criteria of 100FR2, 710(c). Certificate of Dvc encl.
NEWMAN, J R, REID, H F, CULP, R H, Lowenstein, Newman, Reis, Ansell & Telli, 79/03/15 App

7903030505 Requests ARLB deny 790302 petition of TX PDR for directed certification. Intervention review of question is not needed or proper. Certificate of Dvc encl.
WOODHEAD, C P Branch 3 79/03/19 App

7903030519 Request to file brief adverse curia Certificate of Dvc encl.
ROSMAN, A I, Natural Resources Defense Council, PARKER, D L, 100DE, D, Georgetown Univ. Law School, 79/03/19 App

7903030490 Brief adverse curia in support of appeal of Natl Lawyers Guild re intervention petition. ARLB denial of petition was contrary to Federal hearing requirements.
PARKER, D L, 100DE, D, Georgetown Univ. Law School, ROSMAN, A I, Natural Resources Defense Council, 79/03/19 App

7903030507 Answers first set of interrogatories & request for production of documents from Houston Lighting & Power Certificate of Dvc encl.
HENDERSTEIN, C Affiliation Unknown 79/03/26 App

7903030510 Motion for admission of C Hinderstein's Contention 2 Certificate of Dvc encl.
HENDERSTEIN, C Affiliation Unknown 79/03/26 App

7903030520 Houston Lighting & Power's response to TX PDR's first set of interrogatories. Certificate of Dvc encl.
COPELAND, J G, THORAK, C O Baker & Bette, NEWMAN, J R, Lowenstein, Newman, Reis, Ansell & Telli 79/03/26 App

7903030512 Response to first set of interrogatories submitted by Houston Lighting & Power Certificate of Dvc encl.
BOKHINK, D H Texas Public Interest Research Group 79/03/27 App

7903030517 First request for production of documents from Houston Lighting & Power Certificate of Dvc encl.
BOKHINK, D H Texas Public Interest Research Group 79/03/27 App

7903030518 Answers to interrogatories submitted to B McKeen by Houston Lighting & Power. Certificate of Dvc encl.
MCQUEEN, W F Affiliation Unknown, 79/03/28 App

7903030522 Request by Houston Lighting & Power Co for denial of 790304 motion by C Hinderstein & J McKeen for 1-month extension of time for discovery. Certificate of Dvc encl.
NEWMAN, J R, REID, H F, CULP, R H, Lowenstein, Newman, Reis, Ansell & Telli 79/03/28 App

7903030540 Second set of interrogatories & requests for production of documents submitted to Houston Lighting & Power. Certificate of Dvc encl.
HENDERSTEIN, C Affiliation Unknown 79/03/29 App

7903030520 Requests to make statement at

DOCKETED ITEMS

- 790310029 Motion to postpone Contention 2 & 3 re cost hearing license raised by Intervenor JH Schmeffler
SCOTT, J.R. Texas Public Interest Research Group 79/04/02 App.
- 790300004 Response by utility to first interrogatories submitted by G Hinderstein Certificate of Dvc encl
COPELAND, J.D., THORAD, C.D. Baker & Butts NEWMAN, J.R.
Lounsbury, Hummer, Reiss, Aronson & Tull 79/04/02 App.
- 790300007 Response interrogatories to TX PIRG Certificate of Dvc encl
SCHINKEL, E.H. Branch 3 79/04/02 App.
- 790301011 First set of interrogatories & request for production of documents submitted to Houston Lighting & Power Certificate of Dvc encl
WHITE, H., FAINTER, J.W., LOEWEN, R.H. Texas State of 79/04/02 App.
- 790301047 Response by utility to second set of interrogatories from TX PIRG Certificate of Dvc encl
COPELAND, J.D., THORAD, C.D. Baker & Butts NEWMAN, J.R.
Lounsbury, Hummer, Reiss, Aronson & Tull 79/04/02 App.
- 790301082 Motion to postpone 790419 prehearing conference until completion of inquiry re accident at TMI
SCOTT, J.R. Affiliation Unknown 79/04/02 App.
- 790301033 Supplemental contention re lack of strength of steel containment shell
DOHERTY, J.F. Affiliation Unknown 79/04/03 App.
- 790302014 Motion for admission of supplemental contention re strength of steel containment shell Intervenor asserts that petition is timely Certificate of Dvc encl
DOHERTY, J.F. Affiliation Unknown 79/04/03 App.
- 790303006 Applicant's response to TX PIRG's updated motion to postpone further practical steps except for discovery motion for denial of motion TX PIRG does not offer justification for delay Certificate of Dvc encl
COPELAND, J.D., THORAD, C.D. Baker & Butts NEWMAN, J.R.
Lounsbury, Hummer, Reiss, Aronson & Tull 79/04/03 App.
- 790301083 First request for production of documents to Houston Lighting & Power Co
SCHINKEL, E.H. Affiliation Unknown 79/04/03 App.
- 790302057 Notices of intention to make oral statement before ABLR on 790408
SCHINKEL, E.H. Affiliation Unknown 79/04/06 App.
- 790301088 First set of interrogatories & second set of requests for documents submitted to Houston Lighting & Power Certificate of Dvc encl
DOHERTY, J.F. Affiliation Unknown 79/04/09 App.
- 790303040 Response to first set of interrogatories from TX PIRG, Certificate of Dvc & supporting documentation encl
WHITE, H., FAINTER, J.W., LOEWEN, R.H. Texas State of 79/04/10 App.
- 790302029 Request appearance at 790416 prehearing conference in Houston, TX
BERGREN, J. Affiliation Unknown 79/04/10 App.
- 790303076 Request appearance at 790418 prehearing conference in Houston, TX
LEWIS, E.A. Affiliation Unknown 79/04/11 App.
- 790303074 Summary cost of facility.
BULLINGTON, G., POKHONOTON, C. Affiliation Unknown
ically, Express concern for public
rel. 79/04/19, App.
- inquiry into Allegation of Employee
violation to determine
ing St Louis - W/o encl.
04/11, App.
- issue on issues in controversy
Parties have 30 days to
Rescind due dates for
Atomic Safety and Licensing Board Panel.
- 790301025 Informs of opposition to Applicant's request for
reconsideration of ABLR order cancelling prehearing
conference. Order is maintainable in light of issuance of
ALAB-235
SCHINKEL, E.H. Branch 3 79/04/12 App.
- 790303057 Motion by utility for reconsideration of 790404 ALAB-235,
as reversed & remanded to ABLR for further consideration.
Revised creates significant uncertainty re ABLR procedures
Certificate of Dvc encl
NEWMAN, J.R., REID, H.P., CULP, R.H. Lounsbury, Hummer, Reiss, Aronson & Tull 79/04/12 App.
- 790303044 Forward info re procedures involved in making limited
aperture statements in response to 790408 request
SCHINKEL, E.H. Branch 3 79/04/13 App.
- 790303047 Submit contention re reactor safety. Believes PES is
totally inadequate
SCHINKEL, E.H. Affiliation Unknown 79/04/13 App.
- 790304020 Forward denial of suspension of facility OP Supporting
documentation encl
DOHERTY, J.F. Office of Nuclear Reactor Regulation 79/04/13 App.
- 790303011 Director's denial of 100P2B 204 request.
SCHINKEL, E.H. Office of Nuclear Reactor Regulation 79/04/13 App.
- 790304019 Analysis of need for facility.
Division of Site Safety & Environmental Analysis 79/04/13 App.
- 790304027 Response to RW Friedrich 790307 request Forwarded with
on Georgia Against Nuclear Energy request to suspend facility
OP
DOHERTY, J.F. Georgia Power Co. 79/12/19 App.
- 790304032 TX PIRG's motion for admission of 790305 addl Contention 1
SCOTT, J.R. Texas Public Interest Research Group, 79/03/02, App.
- 790302035 Expresses opposition to facility cancel Requests development
of alternate mode of energy
ANDRUS, H., HIGGINS, M., LUTZ, J.B. Affiliation Unknown 79/04/16 App.
- 790304026 Response to TX PIRG brief supporting admission of
reconsidered 12 re fire in wiring. Claims that
cable fires should be admitted as issue in controversy.
Certificate of Dvc encl
SCHINKEL, E.H. Branch 3 79/04/17 App.
- 790304019 Act receipt of mailman requesting copy of ALAB-235 which
was submitted when ABLR issued ruling on 790404.
SCHINKEL, E.H. Branch 3 79/04/18 App.
- 790302007 Admits TX PIRG Contention 12 as issue in controversy.
Discovery procedures shall begin immediately.
MOLFE, B.J. Atomic Safety and Licensing Board Panel, 79/04/19, App.
- 790303080 Answers to Houston Power & Lighting to third set of
interrogatories & request for production of documents from
Intervenor G Hinderstein, Certificate of Dvc encl
COPELAND, J.D., THORAD, C.D. Baker & Butts NEWMAN, J.R.
Lounsbury, Hummer, Reiss, Aronson & Tull 79/04/19, App.
- 790303001 Requests by Houston Power & Lighting for denial of MRC
790416 motion for clarification of ALAB-235. Also requests
that those matters be treated in ruling as still a motion for
reconsideration. Certificate of Dvc encl
NEWMAN, J.R., REID, H.P., CULP, R.H. Lounsbury, Hummer, Reiss, Aronson & Tull 79/04/20 App.
- 790304043 Answers by Houston Lighting & Power Co to first set of
interrogatories & request for production of documents from
Intervenor G Hinderstein, Certificate of Dvc encl.
COPELAND, J.D., THORAD, C.D. Baker & Butts 79/04/20 App.
- 790304043 Notices that ABLR orders of 790304, 790412 & 790416 have not
yet been received causing delay in response to ABLR
order to perfect contentions by 30 days from date of
receipt. Requests placement on dvc list.
DOHERTY, J.F. Affiliation Unknown 79/04/23, App.
- 790304028 Supports admission of JF Doherty 790405 supplemental
contention re strength of steel containment shells.
Certificate of Dvc encl.
SCHINKEL, E.H. Branch 3 79/04/23, App.

DOCKETED ITEMS

229

7905290203 Answers by Houston Lighting & Power to direct act of interjurisdictional request for production of documents submitted by State of TX Affidavit & Certificate of Due and

7905290247 Moves for extension of time in which to submit contention Response info and

DOCKET 80-467 ALLENB CREEK NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905290208 Forwards add info re reactor pressure vessel off-loading facility in response to 790528 request

7905290453 Response to 790426 ltr & updates 771049 list of proposed & endangered species bald eagles now listed as endangered in TX Response biological assessment within 180 days of listed species in plant census area

6. Adjudicatory correspondence

7905290500 Response to first act of interjurisdictional from TX PSD Certificate of Due & supporting documentation and

7905290720 Requests appearance at 790418 prehearing conference in Houston, TX

7905290706 Requests appearance at 790418 prehearing conference in Houston, TX

7905290744 Prehearing conf of facility

7905290793 Opposes const of facility Expresses concern for public safety in event of mishap

DOCKET 80-471 PILGRIM NUCLEAR POWER STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905290744 Forwards ltr requested in 790450 discussion re execution of Cape Cod summer population

7905290430 Forwards response to NRC inquiries re need for power & cost of Onager delay in operation Response based on NRC lead forecast, starting point not extended to be appropriate by unit

7905290947 Forwards response to question re comparison of projected population densities in PWR & 1978 update to 1974 site selection study.

7905290951 Forwards ltr re NRC lead growth renee pertaining to savings associated w/installing facility in 1985 vs 1988 & commission of annual carrying charges.

D. NRC Drafts/Final Environmental Statements, supp & correspondence

7905290181 Forwards comments received to date on draft suppl to FES. Requests review & response by 790418, ltr and

7905290411 Comments by Commonwealth of MA on draft suppl to FES.

7905290470 Comments on draft suppl to FES recapitulation should be given to cumulative impacts of siting two plants adjacent to each other

7905290501 Forwards responses to comments submitted by Commonwealth of MA re draft suppl to FES Certificate of Due and

6. Adjudicatory correspondence

7905290544 Forwards supp. "Parameters Bearing on Decision to Limit Siting Efforts to Given Geographical Area," & "Siting Study for Long-Term Power Generating Capacity Expansion," in response to NRC 790457 ltr re alternate siting

7905290519 Forwards request for Board notification re non-safety-grade equipment to mitigate transients

7905290516 Board notification staff assessment re non-safety-grade equipment to mitigate transients

7905290518 Board notification recent issues on non-safety-grade equipment to mitigate transients

7905290701 Forwards notification of NRC evaluation of new info re flow blockage model for ECCB to determine design

7905290943 Opposes 790307 resumption of evidentiary hearings on alternative site

7905290938 Second motion to supplemental hearing record re need for power issue & to defer current hearing schedule

7905290955 Files memo on applicability & effect of 790714 Perkins partial initial decision re serious consequences of U cycle

7905290929 Ask rescat of motion to resume evidentiary hearings

7905290937 Evidentiary hearings shall resume 790524 in Plymouth, MA & continue on 790525 & 29-06-85

7905290938 Memo by staff re applicability & effect of Perkins partial initial decision on proceedings

7905290944 Supple ltr re is of LEAD-4

7905290944

7905290944

7905290944

7905290944

7905290944

7905290944

7905290944

7905290944

7905290944

7905290944

7905290626 Forwards most recent long-range energy & demand forecasts of Utah & New England Power Pool in response to Board's 790509 order. Certificate of Due mail.
BUTLER, J. R. Boston Edison Co. 79/05/15. App

7905290630 "Long-Range Forecast of Electric Power Needs & Requirements: Annual Suppl. 1-2." 1979-1988. Vols. 1 & 2.
LORD, J. H. Boston Edison Co. 79/04/31. 300pp

7905290637 "New England Load & Capacity Repch." 1978-1989
BUTLER, J. R. Boston Edison Co. 79/04/01. 35pp

7905290640 "New England Long-Range Forecast of Electric Power Needs & Requirements." 1978-1989
BUTLER, J. R. Boston Edison Co. 79/03/03. 31pp

7905290642 "Rep of New England Power Pool Load Forecasting Task Force on Model-Based Forecast of New England Electric Energy & Peak Load." 1979-1989
Boston Edison Co. 79/02/01. 30pp

7905290645 "Parameters Bearing on Decision to Limit Biting Efforts to Given Geographic Area"
Boston Edison Co. 78/04/13. 30pp

7905290647 "Biting Study For Long-Term Power Generating Capacity Expansion: 1979-2006." Vols. A & B & C
FRALL, T. F. Boston Edison Co. 79/02/15. 400pp

3. Financial Information

7905290613 Forwards response to NRC request for info to complete financial specification review
BUTLER, J. R. Boston Edison Co. 79/02/02. App.

4. Insurance & Indemnity Information

7905290677 Confirms increased liability limit to \$25,000,000 for policies NF-25, 43, 76, 80, 100, 111, 160, 164, 170, 173, 174, 176, 178, 180, 182, 183, 184, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUARTROCHI, J. American Nuclear Insurers. 79/03/01. 1p

7905290682 Confirms increase in liability limit to \$25,000,000 for policies NF-25, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 82, 87, 88, 90, 91, 92, 93, 94, 95, & 96
RISDORF, D. M. Mutual Atomic Energy Liability Underwriters. 79/03/01. 1p

5. Reportable occurrences, LERs & related correspondence

7905100203 Board notification Westbrook regarding water storage tank design deficiency
BUTLER, J. R. Boston Edison Co. 79/03/29. 30pp

DOCKET 89-478 FIDELITY NUCLEAR POWER STATION, UNIT 3

A. Application/construction stage documents & correspondence

7905100277 Forwards response to question re completion of projected population densities in FEMA & 1978 update to 1974 site selection study.
BUTLER, J. R. Boston Edison Co. 79/05/10. 14pp

DOCKET 89-478 ATLANTIC GENERATING STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905100443 Forwards PR notice re withdrawal of application to construct & operate generating station.
BALLARD, R. L. Environmental Projects Branch 1. 79/04/22. 1p

DOCKET 89-478 ATLANTIC GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

7905100443 Forwards PR notice re withdrawal of application to construct & operate generating station.
BALLARD, R. L. Environmental Projects Branch 1. 79/04/22. 1p

DOCKET 89-478 WOLF CREEK GENERATING STATION

A. Application/construction stage documents & correspondence

7905290634 Forwards NUREG-0531. "Investigation & Analysis of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability. N/A encl.
VANDAL, G. D. Assistant Director for Light Water Reactors. 79/03/28. 3pp

7905290721 Notification of 790513 meeting w/30 Gas & Electric Co & Bechtel in Burlington, KS to discuss concrete strength of existing base mat.
LIGOTTA, C. A. Light Water Reactors Branch 3. 79/04/24. 1p

7905290801 Forwards summary of concrete problems. In response to 790512 request.
GOSSELINK, L. V. Office of the Executive Director for Operations. 79/05/25. App

7905290814 Forwards test rept of 28-day base mat cylinder Reactor 106 base mat concrete is uniform & of high quality w/length exceeding specified design value of 5,000 psi.
KOEHLER, G. L. Kansas Gas & Electric Co. 79/06/03. 1p

7905290816 "Reactor Base mat Concrete Testing of 28-Day Cylinder Specimens"
KOEHLER, G. L. Portland Cement Association. 79/04/27. 20pp

7905100811 Forwards "Reanalysis of Wolf Creek Reactor 106 Base Mat" per NRC 790506 request
GOSSELINK, L. V. Kansas Gas & Electric Co. 79/05/10. 3pp

7905110014 "Reanalysis of Wolf Creek Reactor 106 Base Mat"
Kansas Gas & Electric Co. 79/05/08. 40pp

6. Administrative correspondence

7905290401 Forwards SAND77-1921, "Transport of Radionuclides in Urban Environments Working Draft document." DOE-79-01-016 78044 & DOE-79-01-016 78109 re impact of working draft.
Assessment on regulatory policy M/A encl.
LEWIS, E. M. Branch 2. 79/05/20. 2pp

7905290412 Discusses 10r re subpages of spent nuclear fuel being separately forwarded to ARLS.
LEWIS, E. M. Branch 2. 79/04/02. 3pp

7905100418 Response to ALAB-107 re radon emissions & de minimus theory.
Forwards recent Certificate of Compliance.
KIMBLE, J. F. Hearings Division. 79/04/11. 40pp

7905290519 Response to 790504 brief of Philadelphia Electric Co. 790514 & Electric City 201 Electric Co. re de minimus theory.
Certificate of Due mail.
RISDORF, D. M. Citizens for Safe Environment. 79/04/11. 3pp

7905100511 Response to 790524 re requesting hearing for possible sale of 175 interest in certain nuclear electric cooperatives.
GOSSELINK, L. V. Deputy Executive Legal Director. 79/04/16. 3pp

7905100532 Notice of consolidation of five intervenor groups re radon emissions issue. Parties have until 790523 to which to file for summary disposition.
BUTLER, J. R. Atomic Safety and Licensing Appeal Panel. 79/04/25. 10pp

7905290639 Response to encl 791029 maligner re problems encountered w/ reactor base mat in cost of facility. NRC staff action is being taken to resolve these problems. Response by DOE is unnecessary.
FREEDBERG, A. J. Energy Dept. of. 79/01/28. 1p

7905100645 Comments on shoddy work being done on reactor base mat.
GOSSELINK, L. V. Affiliation Unknown. 79/05/25. 2pp

7905290636 Response to 791029 maligner re "shoddy work being done on reactor base mat" at facility. Although concrete apparently does not meet original design ultimate suitability yet to be determined w/summary of concrete test.
BUTLER, J. R. Office of Inspection & Enforcement. 79/04/27. 5pp

7905290670 Response to 790128 10r to JM Hendrix re facility corr. Evaluation of 10r is being considered. Forwards summary of concrete problems. 10r notice.
BUTLER, J. R. Office of Inspection & Enforcement. 79/04/27. 3pp

7. Insurance & Indemnity Information

7905290677 Confirms increased liability limit to \$25,000,000 for policies NF-25, 43, 76, 80, 100, 111, 160, 164, 170, 173, 174, 176, 178, 180, 182, 183, 184, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others.
QUARTROCHI, J. American Nuclear Insurers. 79/03/01. 1p

7905290682 Confirms increase in liability limit to \$25,000,000 for policies NF-25, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 82, 87, 88, 90, 91, 92, 93, 94, 95, & 96
RISDORF, D. M. Mutual Atomic Energy Liability Underwriters. 79/03/01. 1p

DOCKETED ITEMS

231

8. Inspection reports, IE Bulletin and correspondence

790503032 Forwards IE Insp Rept 80-482/79-03 on 790320-23, notice of violation & notice of deviation
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/14. Spp.

790503036 Notice of violation from Insp on 790320-23
* Region 4, Dallas, Office of the Director 79/03/12. Ip

790503038 Notice of deviation from Insp on 790320-23.
* Region 4, Dallas, Office of the Director. 79/03/12. Ip

790503032 IE Insp Rept 80-482/79-03 on 790320-23, Nonconformance noted failure to follow procedure to confer with Reg Repts 1, 15, CERNCO, C. M. & TWPA, J. L. Region 4, Dallas, Office of the Director
HMLA, R. E. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/03/12. Spp

790503030 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping"
BEIDLE, M. C. Region 4, Dallas, Office of the Director 79/03/23. Ip

790503049 Forwards IE Bulletin 79-08A, "Nuclear Incident at TMS - Suppl"
BEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/05. Ip

790504044 Forwards IE Bulletin 79-08B, "Review of Operational Errors & Key Missalignments Identified During TMS Incident"
BEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/14. Ip

790504047 Forwards IE Bulletin 79-08, "Events Relevant to Rolling Motor Power Reactors Identified During TMS Incident"
BEIDLE, M. C. Region 4, Dallas, Office of the Director. 79/04/14. Ip

790507062 Forwards IE Bulletin 79-07, "Dynamic Stress Analysis of Safety-Related Piping - Licensee action required"
BEIDLE, M. C. Region 4, Dallas, Office of the Director. 79/04/14. Ip

790503044 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
BEIDLE, M. C. Region 4, Dallas, Office of the Director. 79/04/26. Ip

7905050100 Forwards suppl to IE Bulletin 79-05A, "Nuclear Incident at TMS."
BEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/16. Ip

7905030673 Forwards IE Bulletin 79-09, "Failures of SE Type AW-R Circuit Breaker in Safety-Related Sys." Licensee action required.
BEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/17. Ip

7905030421 Series 790323 request for extension of time to respond to IE Bulletin 79-12, 79-12A & 79-12B, "Design review from reactor vessel manufacturer APA due by 790501; licensee responses by 790520."
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/23. Ip.

79050300426 Requests time extension to 791001 for responding to IE Bulletin 79-12, 79-12A & 79-12B.
WESBTER, G. L. Kansas Gas & Electric Co. 79/03/23. Spp.

7905020957 Clarifies current status of low concrete strength investigation at Facility; Relevant documents are available at LPH in Burlington, MO.
WESBTER, G. L. Division of Reactor Construction Inspection 79/02/02. App.

7905030958 Notification of 790315 public meeting with & Dechert in Burlington, MO to discuss concrete strength of base mat.
LUCIFER, C. A. Light Water Reactors Branch 3. 79/04/24. Spp.

8. Reportable occurrences, LERs and related correspondence

7905030104 Forwards PMD-79-67N, I, J, K, L.
BEIDLE, M. C. Region 4, Dallas, Office of the Director 79/04/05. Ip.

7905030097 Forwards PMD-79-67L, M, N & P
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09. Ip

7905030099 Forwards PMD-79-67S
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/10. Ip

7905030146 Forwards PMD-79-67E & 79-77
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11. Ip

7905030119 Forwards PMD-79-67G
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12. Ip

7905030193 Forwards PMD-79-67T
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13. Ip

7905030257 Forwards PMD-79-67U & V
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16. Ip

7905030248 Forwards PMD-79-67W
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17. Ip

7905030254 Forwards PMD-79-67X
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/20. Ip

7905030253 Forwards PMD-79-67Y, AC & AD
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23. Ip

7905040572 Forwards PMD-79-67AF
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26. Ip

7905030411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events under 790450 lit of notification and
PETERSON, A. Shupps-Standardized Nuclear Unit Power Plant System 79/04/28. Spp

7905030448 Confirms 7905021 action to N. Thornberg re reportable deficiency in safety analysis methodology for certain single dropped control rod events
ANDERSON, T. M. Westinghouse Electric Corp 79/03/30. Spp

7905070046 Forwards PMD-79-67AF & AD
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/27. Ip

7905030256 Forwards PMD-79-67AH, AI & AJ
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 79/04/30. Ip

7905070049 Forwards deficiency rept "Final Rept on Pressurizer Support Anchor Bolts" for SWAPS units
PETERSON, A. Shupps-Standardized Nuclear Unit Power Plant System. 79/05/01. Spp.

7905070050 "Final Rept on Pressurizer Support Anchor Bolts" for SWAPS units. Anchor bolts did not have adequate length to get full thread grip for the heavy base nuts. Design drawings revised.
WESBTER, G. L. Shupps-Standardized Nuclear Unit Power Plant System. 79/04/20. App.

7905040418 Forwards PMD-79-67AK & AL
BEIDLE, M. C. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/04. Ip

7905020326 Provides interim significant deficiency rept re essential sec water pump anchor bolts. Preliminary indications show sec anchor bolts are originally released for const may be adequate. Significant deficiency rept may be withdrawn.
WESBTER, G. L. Kansas Gas & Electric Co. 79/05/18. Ip.

DOCKET NEN-59-482 CALLOWAY PLANT, UNIT 1

0 Adjudicatory correspondence

79030160410 Requests consideration of forthcoming action to show cause setting order for review of portion of EIS which omitted ref to impact of transmission lines on migrating patterns
 OGDEN, R. B. Assistant, State of 79/03/10 1p

H General correspondence

7903020210 Responds to 790307 request re ltr from R Leaf Forwards "Summary of Progress of Calloway Plant" & "Reactor Licensing Process." Letter not enc.
 GOSBURN, L. V. Office of the Executive Director for Operations 79/03/20 2pp

7903020212 Requests responses to R Leaf ltr re inquiry re NRC involvement w/ ltr
 GOSBURN, L. V. Senate 79/03/07 1p

G Inspection reports, IE Bulletins & correspondence

7903010246 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/03/23 1p

7903040038 Forwards IE Info Notice 79-07, "Rupture of Reducers Tests."
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/03/26 1p

7903030038 Forwards IE Bulletin 79-06, "Review of Operational Errors & Misalignments Identified During TMI Incident."
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/04/11 1p

7903030510 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Misalignments Identified During TMI Incident."
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/04/14 1p

7903040420 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Misalignments Identified During TMI Incident."
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/04/14 1p

7903040414 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." License action required
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/04/14 1p

7903040595 Forwards IE Bulletin 79-08, "Events Relevant to Rolling Water Reactors Identified During TMI Incident."
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/04/14 1p

7903010400 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Details."
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/04/16 1p

7903030349 Forwards IE Bulletin 79-07, "Failures of SE Type AN-2 Circuit Breaker in Safety-Related Sys." License action required
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/04/17 1p

7903060512 Forwards IE Bulletin 79-08B, "Nuclear Incident at TMI-2."
 NEFFLER, J. S. Region 3, Chicago, Office of the Director 79/04/25 1p

B Reportable occurrences, LERs & related correspondence

7903010411 Withdraws initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events. Vendor 790410 ltr of notification enc.
 PETRIC, N. A. Stagg-Standardized Nuclear Unit Power Plant System 79/04/26 2pp

7903010418 Confirms 790328 action to 4 Thornbury re reportable deficiency in safety analysis methodology for certain single dropped control rod events.
 ANDERSON, T. H. Westinghouse Electric Corp 79/03/26 2pp

7903075649 Forwards deficiency report "Final Rpt on Pressurizer Support 'Anchor Bolts' for SWPPS Unit"
 PETRIC, N. A. Stagg-Standardized Nuclear Unit Power Plant System 79/03/01 2pp

7903070369 "Final Rpt on Pressurizer Support Anchor Bolts" for SWPPS Unit. Anchor bolts did not have adequate length to get full thread grip for two heavy hex nuts. Design drawings revised.
 MILLER, C. L. Stagg-Standardized Nuclear Unit Power Plant System 79/04/30 4pp

DOCKET ETH-59-404 TROHNS BROWNS PARK, UNIT 1

0 Adjudicatory correspondence

7903010133 Rana by ltr exhibiting that radon release date & concentration levels contained in Perkins decision are complete & accurate. Supports for radon decision approach of Perkins board.
 BLANK, E. L. TRAVISO-0242, N. Shaw, Pittman, Petts, & Townbridge 79/04/29 4pp

7903040799 Notice of appearance on behalf of Northern States Power Certificate of Doc. 401
 TRAVISO-0242, N. Shaw, Pittman, Petts, & Townbridge 79/04/01 2pp

7903010410 Response to ALAB-809 re radon emissions & de minimis theory from Perkins record Certificate of Doc. 401
 MCINTOSH, J. F. Hearings Division 79/04/11 4pp

7903010359 Response to 790404 brief of Philadelphia Electric Co. 790404 & Atlantic City (AC) Electric Co. re de minimis theory
 Certificate of Doc. 401
 RAPPERS, C. R. Citizens for Safe Environment 79/04/11 3p

7903040332 Notice of consolidation of five intervenor groups re radon emissions issue. Parties have until 7/03/28 in which to file for summary disposition.
 DULIN, R. E. Atomic Safety and Licensing Appeal Panel 79/04/28 12pp

J Insurance & indemnity information

7903070487 Confirms increased liability limit to \$124,000,000 per policies 99-1, 20-43, 74-83, 100-131, 140-186, 191, 191, 194, 195, 197, 174-176, 178, 180-182, 183, 184, 187, 189, 190, 192, 194, 195, 197, 199, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
 OUNTS, J. American Nuclear Insurers 79/03/04 1p

7903070502 Confirms increase in liability limit to \$24,000,000 per policies 99-20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

DOCKETED ITEMS

233

7905040587 Forwards IE Bulletin 79-06, "Events Relevant to Boiling Water Reactors Identified During THE Incident."
KAPLER, J. D. Region 3, Chicago, Office of the Director 79/04/14
1p

7905040449 Forwards IE Info Notice 79-10, "Nonconforming Pipe Report Strike"
KAPLER, J. D. Region 3, Chicago, Office of the Director 79/04/14
1p

7905030225 Forwards IE Bulletin 79-06, "Failures of GE Type AW-2 Circuit Breaker in Safety-Related Bays - Licensee action required"
KAPLER, J. D. Region 3, Chicago, Office of the Director 79/04/17
1p

7905030203 Forwards IE Bulletin 79-08, "Nuclear Incident at TMI-Bays 1"
KAPLER, J. D. Region 3, Chicago, Office of the Director 79/04/21
1p

B. Reportable occurrences, LERs & related correspondence

7905110202 Board notification Substool refueling water storage tank design deficiency
DEINICH, J. Hearings Division 79/03/29 30pp

7905030415 Nichevaux initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events, Vendor 790410 Ltr of notification and
PETERICH, M. A. Group-Standardized Nuclear Unit Power Plant System 79/04/24 3pp

--7905030410 Confirm 790308 taken in H Thomsburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events.
HENSEN, T. H. Hearings Division Electric Corp 79/03/30 2pp

7905070549 Forwards deficiency re: "Final Rept on Pressurizer Support Anchor Bolts" for GROUPS units
PETERICH, M. A. Group-Standardized Nuclear Unit Power Plant System 79/05/01 2pp

--7905070540 "Final Rept on Pressurizer Support Anchor Bolts" for GROUPS units. Anchor bolts did not have adequate length to get full thread grip for two bays but have design drawings revised
HENSEN, T. H. Group-Standardized Nuclear Unit Power Plant System 79/04/30 4pp

DOCKET 03N-50-000 STEELING POWER PROJECT NUCLEAR UNIT 1

A. Application/construction stage documents & correspondence

7905100393 Submit revised Attachment A, B & C to 790320 submitted
amending Tech Spec for chemical filter testing & iodine removal equipment operability
WILKENS, F. C. Rochester Gas & Electric Corp. 79/05/08 24pp

B. Adjudicatory correspondence

7905020497 Licensee's response to ALAB-509 Urges AELAB to conclude that intervenors have not substantiated any deficiencies of significance in Pertine record & that health effects re N-232 are de minimis & do not require further analysis
LAKIN, L. K. Leabow, Lamb, Leiby & MacKay 79/04/09 00pp

7905100492 Urges withdrawal of CP or renouncing of alternative sites issue re AELAB. Contents AELAB interpretation of "obviously superior" w/d. Certificate of Gov encl.
HENSEN, T. H. Ecology Action of Savage 79/04/09 10pp

7905030208 Orders extension, until 790411, for NRC to file mand. per
790320 order
CHILK, B. J. Office of the Secretary of the Commission 79/04/10 1p

7905100410 Response to ALAB-509 re radon emissions & de minimis theory from Pertine record Certificate of Gov encl.
SCHIND, J. F. Hearings Division 79/04/11 45pp

7905140819 Response to 790404 brief of Philadelphia Electric Co. REBOS & Atlantic City (NU) Electric Co. re de minimis theory
Certificate of Gov encl.
KAPFER, C. R. Citizens For Safe Environment 79/04/11 8pp

7905150748 Forwards NRC re: "Inquiry into Allegation of Employee Misconduct by Restricting Investigation to Determine Reliability of Power Grid Barring THE Incident" w/d encl.
SCHIND, J. F. Branch 3 79/04/11 1p

7905030208 NRC memo in response to NRC 790309 order Supports approval of both 790119 ALAB decision & Paratation of obviously better text as clear & substantiated
HENSEN, T. H. Branch 3 79/04/11 13pp

7905040195 Notice of appearance of H.H. Veit & H.F. McNamee on behalf of Rochester Gas & Electric Corp Certificate of Gov encl.
HENSEN, T. H. & HENSEN, T. H. Leabow, Lamb, Leiby & MacKay 79/04/23 4pp

7905130274 Licensee's reply brief to Ecology Action of Savage's 790409 agency brief NRC should disallow Action's petition for review as having been impermissibly granted Certificate of Gov encl.
HENSEN, T. H. & HENSEN, T. H. & LARSON, L. K. Leabow, Lamb, Leiby & MacKay 79/04/24 14pp

7905110203 Reply to initial brief re appeal of ALAB-509 Neither applicant nor NRC has made convincing argument for accepting AELAB interpretation of "obviously superior" Certificate of Gov encl.
HENSEN, T. H. Ecology Action of Savage 79/04/24 4pp

7905140222 Petition of consolidation of five intervenor groups re radon emissions issue Parties have until 790523 in which to file for summary disposition
SCHIND, J. F. Atomic Safety and Licensing Appeal Panel 79/04/25 13pp

1. Financial information

7905040208 Forwards "Annual Financial Rept 1979" for Rochester Gas & Electric Corp. Nuclear Unit 1 & Electric Co. Nichevaux Robert Power Corp. & Savage & Rockwell Units Repts available in Central Files only
HENSEN, T. H. Leabow, Lamb, Leiby & MacKay 79/05/02 1p

2. Insurance & indemnity information

7905070547 Confirm increased liability limit to \$124,000,000 per policies NF-25, 42, 70, 83, 100, 111, 140, 146, 151, 161, 144, 150, 170, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 194, 195, 197, 198, 200, 201, 204, 205, 207, 208, 210, 212, 214, 215, & others
QUARTZ, D. H. American Nuclear Insurers 79/05/01 1p

7905070540 Confirm increase in liability limit to \$24,000,000 per policies NF-25, 42, 70, 83, 100, 111, 140, 146, 151, 161, 144, 150, 170, 174, 176, 179, 180, 182, 183, 184, 187, 188, 189, 190, 194, 195, 197, 198, 200, 201, 204, 205, 207, 208, 210, 212, 214, 215, & others
QUARTZ, D. H. Mutual Atomic Group Liability Underwriters 79/05/01 1p

C. Inspection reports: IE Bulletin and correspondence

7905010148 Forwards IE Info Notice 79-05, "Stress Analysis of Safety-Related Piping"
GRUBB, B. H. Region 1, Philadelphia, Office of the Director 79/03/22 1p

7905020111 Forwards IF Bulletin 79-04, "Review of Operational Errors & Bay Misalignments Identified During THE Incident"
GRUBB, B. H. Region 1, Philadelphia, Office of the Director 79/04/11 1p

7905030200 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping"
GRUBB, B. H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040104 Forwards IE Bulletin 79-08, "Review of Operational Errors & Bay Misalignments Identified During THE Incident"
GRUBB, B. H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905040208 Forwards IE Bulletin 79-09, "Events Relevant to Boiling Water Reactors Identified During THE Incident"
GRUBB, B. H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905030110 Forwards IE Bulletin 79-04, "Failures of GE Type AW-2 Circuit Breaker in Safety-Related Bays - Licensee action required"
GRUBB, B. H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

7905020223 Forwards IE Bulletin 79-06A-Revision 1, "Review of Operational Errors & Bay Misalignments Identified During THE Incident"
GRUBB, B. H. Region 1, Philadelphia, Office of the Director 79/04/18 1p

DOCKETED ITEMS

B. Reportable occurrences, USRs & related correspondence

7903030413 Midstream initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events tender ltr of notification on 790610
encl
PETERICK, W.A. Shaggs-Standardized Nuclear Unit Power Plant System
79/04/26 3pp

--7903030418 Gaslines 790308 letter to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events
ANDERSON, T.H. Westinghouse Electric Corp 79/03/30 2pp

7905030449 Forwarded deficiencies re: "Final Rpt on Pressurizer Support Anchor Bolts" for SWAPS units
PETERICK, W.A. Shaggs-Standardized Nuclear Unit Power Plant System
79/05/01 2pp

--7905030455 "Final Rpt on Pressurizer Support Anchor Bolts" for SWAPS units Anchor bolts did not have adequate length to get full thread grip for low heavy hex nuts Design drawings revised
MILLER, C.L. Shaggs-Standardized Nuclear Unit Power Plant System
79/04/26 4pp

DOCKET 87H-30-68A Callaway Plant, Unit 2

A. Application/Construction Stage

B. Adjudicatory correspondence

7905030410 Requests consideration of rehearing motion to show cause setting order for review of portion of EIS which limited ref to impact of transmission lines on migrating patterns
CHATELAIN, D.B. Missouri, State of 79/05/10 1p

H. General correspondence

7905030510 Responds to 790307 request re ltr from D Leaf Forwarded "Summary of Progress of Callaway Plant" & "Reactor Licensing Process" Letter not encl
OSBORN, L.V. Office of the Executive Director for Operations
79/04/25 2pp

--7905030512 Requests response to R Leaf ltr if inquiry re NRC involvement w/issue
CHATELAIN, D.B. Missouri, State of 79/05/07 1p

C. Inspection reports, OE Bulletin & correspondence

7905030518 Forwarded 3E Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/22 1p

7905030528 Forwarded 3E Info Notice 79-07, " rupture of Reducible Tanks " & "Reactor Licensing Process"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/05/25 1p

7905030528 Forwarded 3E Bulletin 79-06, "Review of Operational Errors & Six Realignments Identified During TMI Incident,"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/04/11 1p

7905030510 Forwarded 3E Bulletin 79-06A, "Review of Operational Errors & Six Realignments Identified During TMI Incident"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905030528 Forwarded 3E Bulletin 79-06A, "Review of Operational Errors & Six Realignments Identified During TMI Incident"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/04/16 1p

7905030461 Forwarded 3E Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping," Licensee action required.
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905030528 Forwarded 3E Bulletin 79-08, "Events Relevant to Boiling Water Reactor Identified During TMI Incident"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/04/14 1p

7905030466 Forwarded 3E Info Notice 79-10, "Manufacturing Pipe Support Bolts"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/04/16 1p

7905030449 Forwarded 3E Bulletin 79-06, "Failure of 3E Type AB-2 Circuit Breaker in Safety-Related System" Licensee action required
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/04/17 1p

7905030512 Forwarded 3E Bulletin 79-08, "Nuclear Incident at TMI-Bepi"
KEFFLER, J.G. Region 3, Chicago, Office of the Director 79/04/25 1p

7905030418 Midstream initial notification of reportable deficiency in safety analysis methodology for certain single dropped control rod events tender ltr of notification on 790610
encl
PETERICK, W.A. Shaggs-Standardized Nuclear Unit Power Plant System
79/04/26 3pp

--7905030418 Gaslines 790308 letter to H Thornburg re reportable deficiency in safety analysis methodology for certain single dropped control rod events
ANDERSON, T.H. Westinghouse Electric Corp 79/03/30 2pp

7905030449 Forwarded deficiencies re: "Final Rpt on Pressurizer Support Anchor Bolts" for SWAPS units
PETERICK, W.A. Shaggs-Standardized Nuclear Unit Power Plant System
79/05/01 2pp

--7905030455 "Final Rpt on Pressurizer Support Anchor Bolts" for SWAPS units Anchor bolts did not have adequate length to get full thread grip for low heavy hex nuts Design drawings revised
MILLER, C.L. Shaggs-Standardized Nuclear Unit Power Plant System
79/04/26 4pp

DOCKET 87H-30-68B PERKINS NUCLEAR STATION, UNIT 1

B. Adjudicatory correspondence

7905030519 Applicant's reply to interveners' further supplemental proposed finding of fact & conclusions of law Certificate of Dec encl.
HOGAN, J.H. Duke Power Co 79/03/21 22pp.

7905030516 NRC opposes interveners' 790323 motion to reopen record to consider reactor safety sub-geology, seismology, foundation & hydrology. Documents motion be decided as lacking basis in law & fact Certificate of Dec encl.
BARTHE, C.A. Branch 3 79/03/26 2pp

7905030518 Forwarded request for Board notification re non-safety-grade equipment to mitigate transients
KEFFLER, J.G. Hearings Division 79/04/02 11pp

--7905030516 Board notification/staff assessment re non-safety-grade equipment to mitigate transients
WHEELER, D.B. Assistant Director for Light Water Reactors 79/03/29 2pp

--7905030518 Board notification/recent issue on non-safety-grade equipment to mitigate transients. More info is required.
THOMAS, R.L. Assistant Director for Reactor Safety 79/03/16 2pp

7905030520 Forwarded Violator 790222 memo re behavior of Jodine during postulated steam generator tube rupture accidents.
BARTHE, C.A. Branch 3 79/04/05 1p

7905030509 Forwarded memo discussing info re behavior of Jodine during postulated steam generator tube rupture accidents.
BARTHE, C.A. Branch 3 79/04/10 1p

7905030510 Responds to 790402 telegram re proposed Facilities Results of NRC analysis of TMI incident will be furnished when available.
YERK, F.R. Atomic Safety and Licensing Board Panel 79/04/17 1p

--7905030449 Forwarded proposed licensing of Facility be held up pending NRC assessment
HOGAN, J.H. Duke Power Co 79/04/02 1p

7905030475 Opposes interveners' 790323 motion to reopen record & offer insufficiently specific of critical decision on generic safety issue considerations Certificate of Dec encl.
HOGAN, J.H. Duke Power Co 79/04/16 2pp

7905030467 Requests temporary moratorium on licensing of nuclear plants in light of TMI incident
FORBES, L.L., HARRIS, P., BRECHER, J. Affiliation Unknown 79/04/20 4pp.

DOCKETED ITEMS

236

J Insurance & indemnity information

7903020497 Confirms increased liability limit to \$124,000,000 for policies 170-25, 43, 74, 83, 100, 111, 143, 144, 151, 161, 164, 170, 173, 174, 176, 179, 180, 185, 186, 187, 188, 189, 190, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
 QUATREBOEUF, J. American Nuclear Insurers 79/03/01 1p

7903070262 Confirms increase in liability limit to \$24,000,000 for policies 79-25, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 57, 59, 60, 61, 64, 66, 67, 69, 70, 71, 72, 74, 75, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
 ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/03/01 1p

K Inspection reports, IE Bulletin & correspondence

7903010183 Forwards IE Info Notice 79-56, "Stress Analysis of Safety-Related Piping"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/22 2pp.

7903030301 Forwards IE Info Notice 79-07, "Failure of Radwaste Tanks"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/25 2pp

7903040185 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Rys Misalignments Identified During TMI Incident"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp.

7903040246 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping - Licensee action required"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

7903040304 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Identified During TMI Incident"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p

7903010334 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/26 1p

7903030183 Forwards IE Bulletin 79-05, "Failures of OR Type AR-2 Circuit Breaker in Safety-Related Sys - Licensee action required"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17 1p

7903020493 Forwards IE Bulletin 79-04A, Revision 1, "Review of Operational Errors & Rys Misalignments Identified During TMI Incident"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/16 2pp

B Reportable occurrences, LDRs & related correspondence

7901102003 Board notification Breaker refusing water storage tank design deficiency.
 GUNTER, D. Hearings Division 79/03/29 3pp

DOCKET 87H-90-429 FORMER NUCLEAR STATION, UNIT 2

G Advisory correspondence

7903030099 Applicant's reply to intervenors' further supplemental proposed finding of fact & conclusions of law. Certificate of Rys mcl.
 HCDARRY, W. H. Duke Power Co 79/03/21 2pp.

7903030056 HRC opposes intervenors' 790121 action to reopen record to consider reactor safety study, policy, technology, foundation & engineering recommendations as limited as lacking basis in law & fact. Certificate of Rys mcl.
 BENTLEY, C. A. Branch 3, 79/03/25 2pp.

7903010115 Forwards request for Board notification re nonsafety-grade equipment to mitigate transients.
 HINTON, J. P. Hearings Division 79/04/02 3pp.

7903010156 Board notification staff assessment re nonsafety-grade equipment to mitigate transients.
 HENNING, D. B. Assistant Director for Light Water Reactors, 79/03/29 2pp.

7903010190 Board notification recent issue on nonsafety-grade equipment to mitigate transients. Rys info is required.
 TODESCO, R. L. Assistant Director for Reactor Safety 79/03/16 2pp

7903040305 Forwards Volker 790222 memo re behavior of iodine during postulated steam generator tube rupture accidents
 BARTH, C. A. Branch 3 79/04/05 1p

7903030099 Forwards memo discussing info re behavior of iodine during postulated steam generator tube rupture accidents
 BARTH, C. A. Branch 3 79/04/10 1p

7903020103 Responds to 790302 telegram re proposed facilities. Results of Rys analysis of TMI incident will be forwarded when available.
 YORKE, T. H. Atomic Safety and Licensing Board Panel 79/04/17 1p

7903030149 Requests proposed licensing of facility be held up, pending Rys assessment of TMI.
 HENNING, D. B. House of Rep 79/04/02 1p

7903030475 Opposes intervenors' 790305 motion to reopen record & defer indefinitely issuance of initial decision on generic safety issue considerations. Certificate of Rys mcl.
 HCDARRY, W. H. Duke Power Co 79/04/10 2pp

J Insurance & indemnity information

7903020497 Confirms increased liability limit to \$124,000,000 for policies 170-25, 43, 74, 83, 100, 111, 143, 144, 151, 161, 164, 170, 173, 174, 176, 179, 180, 185, 186, 187, 188, 189, 190, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others
 QUATREBOEUF, J. American Nuclear Insurers 79/03/01 1p

7903070262 Confirms increase in liability limit to \$24,000,000 for policies 79-25, 26, 29, 38, 39, 44, 46, 47, 49, 50, 51, 52, 53, 54, 55, 57, 59, 60, 61, 64, 66, 67, 69, 70, 71, 72, 74, 75, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96
 ROBERTS, D. M. Mutual Atomic Energy Liability Underwriters 79/03/01 1p

K Inspection reports, IE Bulletin & correspondence

7903010183 Forwards IE Info Notice 79-56, "Stress Analysis of Safety-Related Piping"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/22 2pp

7903030301 Forwards IE Info Notice 79-07, "Failure of Radwaste Tanks"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/03/25 2pp

7903040185 Forwards IE Bulletin 79-04B, "Review of Operational Errors & Rys Misalignments Identified During TMI Incident"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

7903040246 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping - Licensee action required"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 2pp

7903040304 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Identified During TMI Incident"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/14 1p.

7903010334 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Struts."
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 79/04/16 1p

7903030183 Forwards IE Bulletin 79-05, "Failures of OR Type AR-2 Circuit Breaker in Safety-Related Sys - Licensee action required."
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/17 1p.

7903020493 Forwards IE Bulletin 79-04A, Revision 1, "Review of Operational Errors & Rys Misalignments Identified During TMI Incident"
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 79/04/16 2pp

B. Reportable occurrences, LERs & related correspondence

7705110002 Board notification Handbook regarding water storage tank design deficiency
SCINTO, J. Hearings Division 77/03/29 30pp

DOCKET 01N-20-490 PERKINS NUCLEAR STATION, UNIT 2

B. Adjudicatory correspondence

7705200079 Applicant's reply to interveners' further supplemental proposed finding of fact & conclusions of law Certificate of Rev and
KOSMAN, J. M. Duke Power Co. 77/03/21. 32pp.

7705200056 NRC opposes interveners' 770126 motion to reopen record to consider reactor safety study, geology, seismology, foundation & hydrology Recommendations Motion by DENIED as lacking basis in law & fact Certificate of Rev and
BARTH, C. A. Branch 3. 77/03/25 3pp

7705200118 Forwards request for Board notification re non-safety-grade equipment to mitigate transients
SCINTO, J. P. Hearings Division 77/04/02 30pp

7705200156 Board notification staff assessment re non-safety-grade equipment to mitigate transients
VANDERKAM, D. B. Assistant Director for Light Water Reactors 77/03/29 2pp

7705200198 Board notification recent issue on non-safety-grade equipment to mitigate transients
BENNETT, S. L. Assistant Director for Reactor Safety 77/03/16 3pp

7705200435 Forwards Voltaire 770520 memo re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C. A. Branch 3 77/04/02 1p

7705200494 Forwards memo discussing info re behavior of iodine during postulated steam generator tube rupture accidents
BARTH, C. A. Branch 3 77/04/10 1p

7705200508 Response to 770402 telephone re proposed facilities. Results of NRC analysis of TMI incident will be forwarded when available
YORKE, T. H. Atomic Safety and Licensing Board Panel 77/04/17. 1p

7705200549 Requests proposed licensing of facility be held up, pending IRS assessment of TMI.
HOL, S. L. House of Rep. 77/04/02 1p

7705200647 Requests temporary moratorium on licensing of nuclear plants in light of TMI incident
HOL, S. L. House of Rep. 77/04/02. Affiliation Unknown 77/04/30. 4pp.

J. Insurance & indemnity information

7705200447 Confirms increased liability limit to \$524,000,000 for policies #7-1, 25, 43, 76, 83, 105, 111, 145, 146, 151, 152, 154, 170, 173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000, 1001, 1002, 1003, 1004, 1005, 1006, 1007, 1008, 1009, 1010, 1011, 1012, 1013, 1014, 1015, 1016, 1017, 1018, 1019, 1020, 1021, 1022, 1023, 1024, 1025, 1026, 1027, 1028, 1029, 1030, 1031, 1032, 1033, 1034, 1035, 1036, 1037, 1038, 1039, 1040, 1041, 1042, 1043, 1044, 1045, 1046, 1047, 1048, 1049, 1050, 1051, 1052, 1053, 1054, 1055, 1056, 1057, 1058, 1059, 1060, 1061, 1062, 1063, 1064, 1065, 1066, 1067, 1068, 1069, 1070, 1071, 1072, 1073, 1074, 1075, 1076, 1077, 1078, 1079, 1080, 1081, 1082, 1083, 1084, 1085, 1086, 1087, 1088, 1089, 1090, 1091, 1092, 1093, 1094, 1095, 1096, 1097, 1098, 1099, 1100, 1101, 1102, 1103, 1104, 1105, 1106, 1107, 1108, 1109, 1110, 1111, 1112, 1113, 1114, 1115, 1116, 1117, 1118, 1119, 1120, 1121, 1122, 1123, 1124, 1125, 1126, 1127, 1128, 1129, 1130, 1131, 1132, 1133, 1134, 1135, 1136, 1137, 1138, 1139, 1140, 1141, 1142, 1143, 1144, 1145, 1146, 1147, 1148, 1149, 1150, 1151, 1152, 1153, 1154, 1155, 1156, 1157, 1158, 1159, 1160, 1161, 1162, 1163, 1164, 1165, 1166, 1167, 1168, 1169, 1170, 1171, 1172, 1173, 1174, 1175, 1176, 1177, 1178, 1179, 1180, 1181, 1182, 1183, 1184, 1185, 1186, 1187, 1188, 1189, 1190, 1191, 1192, 1193, 1194, 1195, 1196, 1197, 1198, 1199, 1200, 1201, 1202, 1203, 1204, 1205, 1206, 1207, 1208, 1209, 1210, 1211, 1212, 1213, 1214, 1215, 1216, 1217, 1218, 1219, 1220, 1221, 1222, 1223, 1224, 1225, 1226, 1227, 1228, 1229, 1230, 1231, 1232, 1233, 1234, 1235, 1236, 1237, 1238, 1239, 1240, 1241, 1242, 1243, 1244, 1245, 1246, 1247, 1248, 1249, 1250, 1251, 1252, 1253, 1254, 1255, 1256, 1257, 1258, 1259, 1260, 1261, 1262, 1263, 1264, 1265, 1266, 1267, 1268, 1269, 1270, 1271, 1272, 1273, 1274, 1275, 1276, 1277, 1278, 1279, 1280, 1281, 1282, 1283, 1284, 1285, 1286, 1287, 1288, 1289, 1290, 1291, 1292, 1293, 1294, 1295, 1296, 1297, 1298, 1299, 1300, 1301, 1302, 1303, 1304, 1305, 1306, 1307, 1308, 1309, 1310, 1311, 1312, 1313, 1314, 1315, 1316, 1317, 1318, 1319, 1320, 1321, 1322, 1323, 1324, 1325, 1326, 1327, 1328, 1329, 1330, 1331, 1332, 1333, 1334, 1335, 1336, 1337, 1338, 1339, 1340, 1341, 1342, 1343, 1344, 1345, 1346, 1347, 1348, 1349, 1350, 1351, 1352, 1353, 1354, 1355, 1356, 1357, 1358, 1359, 1360, 1361, 1362, 1363, 1364, 1365, 1366, 1367, 1368, 1369, 1370, 1371, 1372, 1373, 1374, 1375, 1376, 1377, 1378, 1379, 1380, 1381, 1382, 1383, 1384, 1385, 1386, 1387, 1388, 1389, 1390, 1391, 1392, 1393, 1394, 1395, 1396, 1397, 1398, 1399, 1400, 1401, 1402, 1403, 1404, 1405, 1406, 1407, 1408, 1409, 1410, 1411, 1412, 1413, 1414, 1415, 1416, 1417, 1418, 1419, 1420, 1421, 1422, 1423, 1424, 1425, 1426, 1427, 1428, 1429, 1430, 1431, 1432, 1433, 1434, 1435, 1436, 1437, 1438, 1439, 1440, 1441, 1442, 1443, 1444, 1445, 1446, 1447, 1448, 1449, 1450, 1451, 1452, 1453, 1454, 1455, 1456, 1457, 1458, 1459, 1460, 1461, 1462, 1463, 1464, 1465, 1466, 1467, 1468, 1469, 1470, 1471, 1472, 1473, 1474, 1475, 1476, 1477, 1478, 1479, 1480, 1481, 1482, 1483, 1484, 1485, 1486, 1487, 1488, 1489, 1490, 1491, 1492, 1493, 1494, 1495, 1496, 1497, 1498, 1499, 1500, 1501, 1502, 1503, 1504, 1505, 1506, 1507, 1508, 1509, 1510, 1511, 1512, 1513, 1514, 1515, 1516, 1517, 1518, 1519, 1520, 1521, 1522, 1523, 1524, 1525, 1526, 1527, 1528, 1529, 1530, 1531, 1532, 1533, 1534, 1535, 1536, 1537, 1538, 1539, 1540, 1541, 1542, 1543, 1544, 1545, 1546, 1547, 1548, 1549, 1550, 1551, 1552, 1553, 1554, 1555, 1556, 1557, 1558, 1559, 1560, 1561, 1562, 1563, 1564, 1565, 1566, 1567, 1568, 1569, 1570, 1571, 1572, 1573, 1574, 1575, 1576, 1577, 1578, 1579, 1580, 1581, 1582, 1583, 1584, 1585, 1586, 1587, 1588, 1589, 1590, 1591, 1592, 1593, 1594, 1595, 1596, 1597, 1598, 1599, 1600, 1601, 1602, 1603, 1604, 1605, 1606, 1607, 1608, 1609, 1610, 1611, 1612, 1613, 1614, 1615, 1616, 1617, 1618, 1619, 1620, 1621, 1622, 1623, 1624, 1625, 1626, 1627, 1628, 1629, 1630, 1631, 1632, 1633, 1634, 1635, 1636, 1637, 1638, 1639, 1640, 1641, 1642, 1643, 1644, 1645, 1646, 1647, 1648, 1649, 1650, 1651, 1652, 1653, 1654, 1655, 1656, 1657, 1658, 1659, 1660, 1661, 1662, 1663, 1664, 1665, 1666, 1667, 1668, 1669, 1670, 1671, 1672, 1673, 1674, 1675, 1676, 1677, 1678, 1679, 1680, 1681, 1682, 1683, 1684, 1685, 1686, 1687, 1688, 1689, 1690, 1691, 1692, 1693, 1694, 1695, 1696, 1697, 1698, 1699, 1700, 1701, 1702, 1703, 1704, 1705, 1706, 1707, 1708, 1709, 1710, 1711, 1712, 1713, 1714, 1715, 1716, 1717, 1718, 1719, 1720, 1721, 1722, 1723, 1724, 1725, 1726, 1727, 1728, 1729, 1730, 1731, 1732, 1733, 1734, 1735, 1736, 1737, 1738, 1739, 1740, 1741, 1742, 1743, 1744, 1745, 1746, 1747, 1748, 1749, 1750, 1751, 1752, 1753, 1754, 1755, 1756, 1757, 1758, 1759, 1760, 1761, 1762, 1763, 1764, 1765, 1766, 1767, 1768, 1769, 1770, 1771, 1772, 1773, 1774, 1775, 1776, 1777, 1778, 1779, 1780, 1781, 1782, 1783, 1784, 1785, 1786, 1787, 1788, 1789, 1790, 1791, 1792, 1793, 1794, 1795, 1796, 1797, 1798, 1799, 1800, 1801, 1802, 1803, 1804, 1805, 1806, 1807, 1808, 1809, 1810, 1811, 1812, 1813, 1814, 1815, 1816, 1817, 1818, 1819, 1820, 1821, 1822, 1823, 1824, 1825, 1826, 1827, 1828, 1829, 1830, 1831, 1832, 1833, 1834, 1835, 1836, 1837, 1838, 1839, 1840, 1841, 1842, 1843, 1844, 1845, 1846, 1847, 1848, 1849, 1850, 1851, 1852, 1853, 1854, 1855, 1856, 1857, 1858, 1859, 1860, 1861, 1862, 1863, 1864, 1865, 1866, 1867, 1868, 1869, 1870, 1871, 1872, 1873, 1874, 1875, 1876, 1877, 1878, 1879, 1880, 1881, 1882, 1883, 1884, 1885, 1886, 1887, 1888, 1889, 1890, 1891, 1892, 1893, 1894, 1895, 1896, 1897, 1898, 1899, 1900, 1901, 1902, 1903, 1904, 1905, 1906, 1907, 1908, 1909, 1910, 1911, 1912, 1913, 1914, 1915, 1916, 1917, 1918, 1919, 1920, 1921, 1922, 1923, 1924, 1925, 1926, 1927, 1928, 1929, 1930, 1931, 1932, 1933, 1934, 1935, 1936, 1937, 1938, 1939, 1940, 1941, 1942, 1943, 1944, 1945, 1946, 1947, 1948, 1949, 1950, 1951, 1952, 1953, 1954, 1955, 1956, 1957, 1958, 1959, 1960, 1961, 1962, 1963, 1964, 1965, 1966, 1967, 1968, 1969, 1970, 1971, 1972, 1973, 1974, 1975, 1976, 1977, 1978, 1979, 1980, 1981, 1982, 1983, 1984, 1985, 1986, 1987, 1988, 1989, 1990, 1991, 1992, 1993, 1994, 1995, 1996, 1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 214

DOCKETED ITEMS

7705104085 Forwards IE Bulletin 79-08, "Review of Operational Errors & Rys Misalignments Identified During TMI Incident"
O'DRILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 App.

7705204063 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'DRILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 App.

7705204066 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required
O'DRILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 App.

7705204066 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Reactors Identified During TMI Incident"
O'DRILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 App.

7705204063 Forwards IE Bulletin 79-09, "Failures of GE Type AN-2 Circuit Breaker in Safety-Related Sys." Licensee action required
O'DRILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/17 App.

7705204063 Forwards IE Bulletin 79-08A, Revision 1, "Review of Operational Errors & Rys Misalignments Identified During TMI Incident"
O'DRILLY, J.P. Region 2, Atlanta, Office of the Director
79/04/14 App.

7705204060 Act receipt of IE Insp Repts 90-491/79-07, 90-492/79-07 & 90-493/79-07 on 7705200 & 23 No noncompliance info
SAL, L. C. Date Power Co. 79/04/25 App.

7705204063 Forwards IE Insp Repts 90-491/79-07, 90-492/79-07 & 90-493/79-07 on 7705200 & 23 No noncompliance info
SAL, L. C. Date Power Co. 79/04/25 App.

7705204063 IE Insp Repts 90-491/79-07, 90-492/79-07 & 90-493/79-07 on 7705200 & 23 No noncompliance info
SAL, L. C. Date Power Co. 79/04/25 App.

DOCKET 87H-50-493 CHESSBORO NUCLEAR STATION, UNIT 3

O. A. Judicial Review of Proceedings

7705204063 Forwards IE Repts name re accumulator characteristics identified during study of ECCS performance.
SAL, L. C. Branch 3 79/04/25 App.

7705204063 Forwards name re discussing problems experienced in competition w/pipe support base plate design.
SAL, L. C. Branch 3 79/04/25 App.

7705204060 Forwards 7705200 Board notification pipe support base plate design. Requests notification of decision as to whether licensing boards will be notified.
SAL, L. C. Branch 3 79/04/25 App.

7705204063 Forwards name re behavior of valve during pressurized steam generator tube rupture accidents.
SAL, L. C. Branch 3 79/04/25 App.

7705204063 Forwards name re shortage of spent fuel HGO assessment of significance of info will be forwarded to Board when available.
SAL, L. C. Branch 3 79/04/25 App.

7705204063 Response filed per ALAB-500, Part-time Licensing Board's use of de minimis theory regarding applicants & its compliance w/applicable law Certificate of Rev. encl.
SAL, L. C. Date Power Co. 79/04/25 App.

7705104063 Response to ALAB-500 re radon solutions & de minimis theory from Part-time radon Certificate of Rev. encl.
SAL, L. C. Date Power Co. 79/04/25 App.

7705104063 Response to 7705104 brief of Philadelphia Electric Co. (PECO) & Atlantic City (AC) Electric Co. re de minimis theory. Certificate of Rev. encl.
SAL, L. C. Date Power Co. 79/04/25 App.

7705104063 Response to ALAB-500 re radon solutions & de minimis theory from Part-time radon Certificate of Rev. encl.
SAL, L. C. Date Power Co. 79/04/25 App.

J. Insurance & Surety Information

7705204063 Confirms increases in liability limit to \$40,000,000 for policies 79-05, 79-06, 79-07, 79-08, 79-09, 79-10, 79-11, 79-12, 79-13, 79-14, 79-15, 79-16, 79-17, 79-18, 79-19, 79-20, 79-21, 79-22, 79-23, 79-24, 79-25, 79-26, 79-27, 79-28, 79-29, 79-30, 79-31, 79-32, 79-33, 79-34, 79-35, 79-36, 79-37, 79-38, 79-39, 79-40, 79-41, 79-42, 79-43, 79-44, 79-45, 79-46, 79-47, 79-48, 79-49, 79-50, 79-51, 79-52, 79-53, 79-54, 79-55, 79-56, 79-57, 79-58, 79-59, 79-60, 79-61, 79-62, 79-63, 79-64, 79-65, 79-66, 79-67, 79-68, 79-69, 79-70, 79-71, 79-72, 79-73, 79-74, 79-75, 79-76, 79-77, 79-78, 79-79, 79-80, 79-81, 79-82, 79-83, 79-84, 79-85, 79-86, 79-87, 79-88, 79-89, 79-90, 79-91, 79-92, 79-93, 79-94, 79-95, 79-96, 79-97, 79-98, 79-99, 79-100, 79-101, 79-102, 79-103, 79-104, 79-105, 79-106, 79-107, 79-108, 79-109, 79-110, 79-111, 79-112, 79-113, 79-114, 79-115, 79-116, 79-117, 79-118, 79-119, 79-120, 79-121, 79-122, 79-123, 79-124, 79-125, 79-126, 79-127, 79-128, 79-129, 79-130, 79-131, 79-132, 79-133, 79-134, 79-135, 79-136, 79-137, 79-138, 79-139, 79-140, 79-141, 79-142, 79-143, 79-144, 79-145, 79-146, 79-147, 79-148, 79-149, 79-150, 79-151, 79-152, 79-153, 79-154, 79-155, 79-156, 79-157, 79-158, 79-159, 79-160, 79-161, 79-162, 79-163, 79-164, 79-165, 79-166, 79-167, 79-168, 79-169, 79-170, 79-171, 79-172, 79-173, 79-174, 79-175, 79-176, 79-177, 79-178, 79-179, 79-180, 79-181, 79-182, 79-183, 79-184, 79-185, 79-186, 79-187, 79-188, 79-189, 79-190, 79-191, 79-192, 79-193, 79-194, 79-195, 79-196, 79-197, 79-198, 79-199, 79-200, 79-201, 79-202, 79-203, 79-204, 79-205, 79-206, 79-207, 79-208, 79-209, 79-210, 79-211, 79-212, 79-213, 79-214, 79-215, 79-216, 79-217, 79-218, 79-219, 79-220, 79-221, 79-222, 79-223, 79-224, 79-225, 79-226, 79-227, 79-228, 79-229, 79-230, 79-231, 79-232, 79-233, 79-234, 79-235, 79-236, 79-237, 79-238, 79-239, 79-240, 79-241, 79-242, 79-243, 79-244, 79-245, 79-246, 79-247, 79-248, 79-249, 79-250, 79-251, 79-252, 79-253, 79-254, 79-255, 79-256, 79-257, 79-258, 79-259, 79-260, 79-261, 79-262, 79-263, 79-264, 79-265, 79-266, 79-267, 79-268, 79-269, 79-270, 79-271, 79-272, 79-273, 79-274, 79-275, 79-276, 79-277, 79-278, 79-279, 79-280, 79-281, 79-282, 79-283, 79-284, 79-285, 79-286, 79-287, 79-288, 79-289, 79-290, 79-291, 79-292, 79-293, 79-294, 79-295, 79-296, 79-297, 79-298, 79-299, 79-300, 79-301, 79-302, 79-303, 79-304, 79-305, 79-306, 79-307, 79-308, 79-309, 79-310, 79-311, 79-312, 79-313, 79-314, 79-315, 79-316, 79-317, 79-318, 79-319, 79-320, 79-321, 79-322, 79-323, 79-324, 79-325, 79-326, 79-327, 79-328, 79-329, 79-330, 79-331, 79-332, 79-333, 79-334, 79-335, 79-336, 79-337, 79-338, 79-339, 79-340, 79-341, 79-342, 79-343, 79-344, 79-345, 79-346, 79-347, 79-348, 79-349, 79-350, 79-351, 79-352, 79-353, 79-354, 79-355, 79-356, 79-357, 79-358, 79-359, 79-360, 79-361, 79-362, 79-363, 79-364, 79-365, 79-366, 79-367, 79-368, 79-369, 79-370, 79-371, 79-372, 79-373, 79-374, 79-375, 79-376, 79-377, 79-378, 79-379, 79-380, 79-381, 79-382, 79-383, 79-384, 79-385, 79-386, 79-387, 79-388, 79-389, 79-390, 79-391, 79-392, 79-393, 79-394, 79-395, 79-396, 79-397, 79-398, 79-399, 79-400, 79-401, 79-402, 79-403, 79-404, 79-405, 79-406, 79-407, 79-408, 79-409, 79-410, 79-411, 79-412, 79-413, 79-414, 79-415, 79-416, 79-417, 79-418, 79-419, 79-420, 79-421, 79-422, 79-423, 79-424, 79-425, 79-426, 79-427, 79-428, 79-429, 79-430, 79-431, 79-432, 79-433, 79-434, 79-435, 79-436, 79-437, 79-438, 79-439, 79-440, 79-441, 79-442, 79-443, 79-444, 79-445, 79-446, 79-447, 79-448, 79-449, 79-450, 79-451, 79-452, 79-453, 79-454, 79-455, 79-456, 79-457, 79-458, 79-459, 79-460, 79-461, 79-462, 79-463, 79-464, 79-465, 79-466, 79-467, 79-468, 79-469, 79-470, 79-471, 79-472, 79-473, 79-474, 79-475, 79-476, 79-477, 79-478, 79-479, 79-480, 79-481, 79-482, 79-483, 79-484, 79-485, 79-486, 79-487, 79-488, 79-489, 79-490, 79-491, 79-492, 79-493, 79-494, 79-495, 79-496, 79-497, 79-498, 79-499, 79-500, 79-501, 79-502, 79-503, 79-504, 79-505, 79-506, 79-507, 79-508, 79-509, 79-510, 79-511, 79-512, 79-513, 79-514, 79-515, 79-516, 79-517, 79-518, 79-519, 79-520, 79-521, 79-522, 79-523, 79-524, 79-525, 79-526, 79-527, 79-528, 79-529, 79-530, 79-531, 79-532, 79-533, 79-534, 79-535, 79-536, 79-537, 79-538, 79-539, 79-540, 79-541, 79-542, 79-543, 79-544, 79-545, 79-546, 79-547, 79-548, 79-549, 79-550, 79-551, 79-552, 79-553, 79-554, 79-555, 79-556, 79-557, 79-558, 79-559, 79-560, 79-561, 79-562, 79-563, 79-564, 79-565, 79-566, 79-567, 79-568, 79-569, 79-570, 79-571, 79-572, 79-573, 79-574, 79-575, 79-576, 79-577, 79-578, 79-579, 79-580, 79-581, 79-582, 79-583, 79-584, 79-585, 79-586, 79-587, 79-588, 79-589, 79-590, 79-591, 79-592, 79-593, 79-594, 79-595, 79-596, 79-597, 79-598, 79-599, 79-600, 79-601, 79-602, 79-603, 79-604, 79-605, 79-606, 79-607, 79-608, 79-609, 79-610, 79-611, 79-612, 79-613, 79-614, 79-615, 79-616, 79-617, 79-618, 79-619, 79-620, 79-621, 79-622, 79-623, 79-624, 79-625, 79-626, 79-627, 79-628, 79-629, 79-630, 79-631, 79-632, 79-633, 79-634, 79-635, 79-636, 79-637, 79-638, 79-639, 79-640, 79-641, 79-642, 79-643, 79-644, 79-645, 79-646, 79-647, 79-648, 79-649, 79-650, 79-651, 79-652, 79-653, 79-654, 79-655, 79-656, 79-657, 79-658, 79-659, 79-660, 79-661, 79-662, 79-663, 79-664, 79-665, 79-666, 79-667, 79-668, 79-669, 79-670, 79-671, 79-672, 79-673, 79-674, 79-675, 79-676, 79-677, 79-678, 79-679, 79-680, 79-681, 79-682, 79-683, 79-684, 79-685, 79-686, 79-687, 79-688, 79-689, 79-690, 79-691, 79-692, 79-693, 79-694, 79-695, 79-696, 79-697, 79-698, 79-699, 79-700, 79-701, 79-702, 79-703, 79-704, 79-705, 79-706, 79-707, 79-708, 79-709, 79-710, 79-711, 79-712, 79-713, 79-714, 79-715, 79-716, 79-717, 79-718, 79-719, 79-720, 79-721, 79-722, 79-723, 79-724, 79-725, 79-726, 79-727, 79-728, 79-729, 79-730, 79-731, 79-732, 79-733, 79-734, 79-735, 79-736, 79-737, 79-738, 79-739, 79-740, 79-741, 79-742, 79-743, 79-744, 79-745, 79-746, 79-747, 79-748, 79-749, 79-750, 79-751, 79-752, 79-753, 79-754, 79-755, 79-756, 79-757, 79-758, 79-759, 79-760, 79-761, 79-762, 79-763, 79-764, 79-765, 79-766, 79-767, 79-768, 79-769, 79-770, 79-771, 79-772, 79-773, 79-774, 79-775, 79-776, 79-777, 79-778, 79-779, 79-780, 79-781, 79-782, 79-783, 79-784, 79-785, 79-786, 79-787, 79-788, 79-789, 79-790, 79-791, 79-792, 79-793, 79-794, 79-795, 79-796, 79-797, 79-798, 79-799, 79-800, 79-801, 79-802, 79-803, 79-804, 79-805, 79-806, 79-807, 79-808, 79-809, 79-810, 79-811, 79-812, 79-813, 79-814, 79-815, 79-816, 79-817, 79-818, 79-819, 79-820, 79-821, 79-822, 79-823, 79-824, 79-825, 79-826, 79-827, 79-828, 79-829, 79-830, 79-831, 79-832, 79-833, 79-834, 79-835, 79-836, 79-837, 79-838, 79-839, 79-840, 79-841, 79-842, 79-843, 79-844, 79-845, 79-846, 79-847, 79-848, 79-849, 79-850, 79-851, 79-852, 79-853, 79-854, 79-855, 79-856, 79-857, 79-858, 79-859, 79-860, 79-861, 79-862, 79-863, 79-864, 79-865, 79-866, 79-867, 79-868, 79-869, 79-870, 79-871, 79-872, 79-873, 79-874, 79-875, 79-876, 79-877, 79-878, 79-879, 79-880, 79-881, 79-882, 79-883, 79-884, 79-885, 79-886, 79-887, 79-888, 79-889, 79-890, 79-891, 79-892, 79-893, 79-894, 79-895, 79-896, 79-897, 79-898, 79-899, 79-900, 79-901, 79-902, 79-903, 79-904, 79-905, 79-906, 79-907, 79-908, 79-909, 79-910, 79-911, 79-912, 79-913, 79-914, 79-915, 79-916, 79-917, 79-918, 79-919, 79-920, 79-921, 79-922, 79-923, 79-924, 79-925, 79-926, 79-927, 79-928, 79-929, 79-930, 79-931, 79-932, 79-933, 79-934, 79-935, 79-936, 79-937, 79-938, 79-939, 79-940, 79-941, 79-942, 79-943, 79-944, 79-945, 79-946, 79-947, 79-948, 79-949, 79-950, 79-951, 79-952, 79-953, 79-954, 79-955, 79-956, 79-957, 79-958, 79-959, 79-960, 79-961, 79-962, 79-963, 79-964, 79-965, 79-966, 79-967, 79-968, 79-969, 79-970, 79-971, 79-972, 79-973, 79-974, 79-975, 79-976, 79-977, 79-978, 79-979, 79-980, 79-981, 79-982, 79-983, 79-984, 79-985, 79-986, 79-987, 79-988, 79-989, 79-990, 79-991, 79-992, 79-993, 79-994, 79-995, 79-996, 79-997, 79-998, 79-999, 79-1000, 79-1001, 79-1002, 79-1003, 79-1004, 79-1005, 79-1006, 79-1007, 79-1008, 79-1009, 79-1010, 79-1011, 79-1012, 79-1013, 79-1014, 79-1015, 79-1016, 79-1017, 79-1018, 79-1019, 79-1020, 79-1021, 79-1022, 79-1023, 79-1024, 79-1025, 79-1026, 79-1027, 79-1028, 79-1029, 79-1030, 79-1031, 79-1032, 79-1033, 79-1034, 79-1035, 79-1036, 79-1037, 79-1038, 79-1039, 79-1040, 79-1041, 79-1042, 79-1043, 79-1044, 79-1045, 79-1046, 79-1047, 79-1048, 79-1049, 79-1050, 79-1051, 79-1052, 79-1053, 79-1054, 79-1055, 79-1056, 79-1057, 79-1058, 79-1059, 79-1060, 79-1061, 79-1062, 79-1063, 79-1064, 79-1065, 79-1066, 79-1067, 79-1068, 79-1069, 79-1070, 79-1071, 79-1072, 79-1073, 79-1074, 79-1075, 79-1076, 79-1077, 79-1078, 79-1079, 79-1080, 79-1081, 79-1082, 79-1083, 79-1084, 79-1085, 79-1086, 79-1087, 79-1088, 79-1089, 79-1090, 79-1091, 79-1092, 79-1093, 79-1094, 79-1095, 79-1096, 79-1097, 79-1098, 79-1099, 79-1100, 79-1101, 79-1102, 79-1103, 79-1104, 79-1105, 79-1106, 79-1107, 79-1108, 79-1109, 79-1110, 79-1111, 79-1112, 79-1113, 79-1114, 79-1115, 79-1116, 79-1117, 79-1118, 79-1119, 79-1120, 79-1121, 79-1122, 79-1123, 79-1124, 79-1125, 79-1126, 79-1127, 79-1128, 79-1129, 79-1130, 79-1131, 79-1132, 79-1133, 79-1134, 79-1135, 79-1136, 79-1137, 79-1138, 79-1139, 79-1140, 79-1141, 79-1142, 79-1143, 79-1144, 79-1145, 79-1146, 79-1147, 79-1148, 79-1149, 79-1150, 79-1151, 79-1152, 79-1153, 79-1154, 79-1155, 79-1156, 79-1157, 79-1158, 79-1159, 79-1160, 79-1161, 79-1162, 79-1163, 79-1164, 79-1165, 79-1166, 79-1167, 79-1168, 79-1169, 79-1170, 79-1171, 79-1172, 79-1173, 79-1174, 79-1175, 79-1176, 79-1177, 79-1178, 79-1179, 79-1180, 79-1181, 79-1182, 79-1183, 79-1184, 79-1185, 79-1186, 79-1187, 79-1188, 79-1189, 79-1190, 79-1191, 79-1192, 79-1193, 79-1194, 79-1195, 79-1196, 79-1197, 79-1198, 79-1199, 79-1200, 79-1201, 79-1202, 79-1203, 79-1204, 79-1205, 79-1206, 79-1207, 79-1208, 79-1209, 79-1210, 79-1211, 79-1212, 79-1213, 79-1214, 79-1215, 79-1216, 79-1217, 79-1218, 79-1219, 79-1220, 79-1221, 79-1222, 79-1223, 79-1224, 79-1225, 79-1226, 79-1227, 79-1228, 79-1229, 79-1230, 79-1231, 79-1232, 79-1233, 79-1234, 79-1235, 79-1236, 79-1237, 79-1238, 79-1239, 79-1240, 79-1241, 79-1242, 79-1243, 79-1244, 79-1245, 79-1246, 79-1247, 79-1248, 79-1249, 79-1250, 79-1251, 79-1252, 79-1253, 79-1254, 79-1255, 79-1256, 79-1257, 79-1

DOCKETED ITEMS

239

7903040307 IE Soap Haps 56-495/79-03, 50-492/79-07 & 50-493/79-07 as 790302 & 23 Re noncompliance noted Major areas (suspended) procedures for erection of containment vessel structures & support/erector work & quality records
 DASH, G.B. Region 2, Atlanta, Office of the Director
 BRUNER, E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/04 App

DOCKET 57N-50-495 RUEDDAR-41

A. Application/Construction stage documents & correspondence

7903070404 Response to NRC 790304 for requesting add info re preliminary design approach. Forward (list of cross-reference documents as aid in review
 KENNEDY, M.J. Stone & Webster Engineering Corp 79/08/03 App

7903070402 Discontinue extension review re preliminary design approach. Requests assessment of 50495/790304-41 design compared to Category 1-IV items.
 MOYER, R. Division of Project Management 79/03/24 App

7903020202 Forwarded set of 50495/790304-41 through Amend 23 for preliminary design assessment per T CoC request & info committed to in 7903030303 for to SD Regd
 CULP, M. Stone & Webster Engineering Corp 79/03/14 App

DOCKET 57N-50-495 SOUTH TEXAS PROJECT, UNIT 1

A. Application/Construction stage documents & correspondence

7903030601 Requests add info in areas of mechanical engineering, structural engineering & age analysis, for review of PSM.
 PARR, G.B. Light Water Reactors Branch 3 79/04/13 App.

7903030303 Requests add info re metallurgy to complete review of PSM.
 PARR, G.B. Light Water Reactors Branch 3 79/04/20 App

7903040405 Notification of 790303 meeting w/utill in Bethesda, MD to discuss first round questions dealing w/utill
 LECTER, E. Light Water Reactors Branch 3 79/03/04 App

F. Return; medical, emergency & fire protection plans

7903030303 Forwarded Amend 1 to physical security plan Plan withheld (ref 19C92 790)
 TURNER, E.A. Houston Lighting & Power Co. 79/05/01 App.

G. Administrative correspondence

7903030306 Response to Citizens for Equitable Utility 790302 petition to intervene. Petition should be granted because standing is shown. Certificate of Div encl.
 KENNEDY, M.J. Branch 1, 79/03/02, 17pp

7903030307 Request by applicant that AELB issue add procedures prior to ruling on 790303 petition to Intervene from Citizens Concerned About Nuclear Power, Certificate of Div encl.
 KENNEDY, M.J., BRUNER, E., CULP, R.H. Leventhal-Human, Rais, Avelard & Telt. 79/03/14, App.

7903030601 NRC responses to Houston Lighting & Power 790304 motion for add procedures requested from Citizens Concerned About Nuclear Power. Request violates limitations stated in NRC Rules of Practice Certificate of Div encl.
 KENNEDY, M.J. Branch 1, 79/03/29, App.

7903030604 Response to applicant's motion to provide AELB w/790303 decision in Health Research Group vs Kennedy reproduced from "Legal Times of Washington." Certificate of Div encl.
 KENNEDY, M.J. Branch 1 79/04/04, App.

7903030308 Assignment of SD Gelman-Hank & HC Farrer to AELB for proceedings.
 DUFFLO, R.E. Atomic Safety and Licensing Appeal Panel. 79/04/17, App

7903030308 Notice of appeal by Houston Lighting & Power of 790302 order granting intervention to Citizens Concerned About Nuclear Power. Citizens for Equitable Utility & Austin Citizens for Electrical Energy Certificate of Div encl.
 KENNEDY, M.J., BRUNER, E., CULP, R.H. Leventhal-Human, Rais, Avelard & Telt. 79/04/17, App.

H. General correspondence

7903030307 FDIA request for "Prehearing Conference Order Ruling Upon Intervention Petitioner's" & "Part 2 Rules of Practice for Domestic Licensing Proceedings"
 KVAL, E.H. Citizens Concerned About Nuclear Power, Inc 79/04/10 App

7903010004 Response to FDIA request for "Prehearing Conference Order Ruling Upon Intervention Petitioner's," & "Part 2 Rules of Practice for Domestic Licensing Proceedings" & "Part 2 Rules of Practice for Domestic Licensing Proceedings" & "Part 2 Rules of Practice for Domestic Licensing Proceedings"
 FELTON, J.M. Division of Rules and Records 79/04/24 App

7903030303 Forwarded Amend 3 to PSM.
 TURNER, E.A. Houston Lighting & Power Co 79/03/04 App

7903030304 Amend 4 to PSM.
 Houston Lighting & Power Co 79/03/04 800pp

7903030306 Forwarded supplemental info to Amend 3 to PSM covering Const Procedures AOMAPCP-14 & 3A certification and test dtd 79/03/03
 TURNER, E.A. Houston Lighting & Power Co 79/03/09 78pp

M. Additional correspondence

7903030304 Forwarded TX Utility Co & subsidiaries' answer to NRC initial interrogatories & requests for production of documents. Reserves rights to file objections & protective order before 790303 Certificate of Div encl.
 BLICKER, P.H. Marsh, Forsythe & Shapell 79/03/01 App

7903030302 Grants 790307 motion by Public Utility Board of Brownsville, TX seeking automatic nullification of 790302 & 790405, in which to compel further responses by Board's interrogatories.
 KENNEDY, M.J. Atomic Safety and Licensing Board Panel 79/03/02 App

7903040307 Notification that location of deposition of LC Paster of Houston Co has been changed from Holiday Inn-Alvin, TX to another location. Paster & Regg law office in Houston, TX.
 KENNEDY, M.J. Susan, Lincoln & Beale 79/03/20 App

7903030408 Order protecting confidentiality of info sought by Houston Lighting & Power from Central Power & Light; West TX Utility. Public Div of DC & Southeastern Electric Power Co.
 MILLER, M.E. Atomic Safety and Licensing Board Panel 79/03/23 App.

7903030303 Response by utill to second set of interrogatories & request for production of documents submitted to Central Power & Light Also moves for protective order Certificate of Div encl.
 KENNEDY, M.J. Baker & Beale 79/03/08 27pp

7903070404 Advises that deposition of Edward Sherry, Air Products & Chemicals Co, Alvin, TX, originally scheduled for 790406, has been changed to 790317 at office of Air Products & Chemicals Co.
 KENNEDY, M.J. Susan, Lincoln & Beale 79/03/30 App.

7903070404 RE Wright, AD Coghlan & L Paster were deposed during Mar Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogatories.
 KENNEDY, M.J. Susan, Lincoln & Beale 79/03/30 App

7903030306 Rept on progress made in Mar 1979 in completing discovery submitted per AELB 790402 order Certificate of Div encl.
 KENNEDY, M.J., BRUNER, E., CULP, R.H. Justice, Dept. of 79/03/31 App.

7903030318 Describes discovery activities of Public Utility Board of Brownsville, TX for Mar 1979 Certificate of Div encl.
 KENNEDY, M.J. Dufflo & Hefner, 79/04/03 App.

7903290024 Request by TX Utils Generating Co for NRC to disallow Central Power & Light South West Corp as intervenor in alternative, except summary disposition or disposition of collateral estoppel Certificate of Nrc and
 AMSTUTZ, J. E. Debevoise & Lieberman 79/04/02 3pp

7903290042 Request by TX Utils Generating Co for order barring Central Power & Light from seeking relief from disallowance of collateral estoppel decision for favorable decision re summary disposition
 AMSTUTZ, J. E. Debevoise & Lieberman 79/04/02 3pp

7903290050 Memo by TX Utils Generating Co re points & authorities supporting motion to disallow Central Power & Light South West Corp as intervenor or for summary disposition
 AMSTUTZ, J. E. Debevoise & Lieberman 79/04/02 42pp

7903290058 Responses to second set of interrogatories & requests for production of documents directed to GCU by Houston Lighting & Power. Qualifications of expert witnesses NE Scott & OTC Taylor & Certificate of Nrc and
 HARRIS, J. L. KESNER, M. D. CLARK, R. H. Justice, Dept. of 79/04/03 23pp

7903290058 Responses to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power. Qualifications of expert witnesses NE Scott & OTC Taylor & Certificate of Nrc and
 HARRIS, J. L. KESNER, M. D. CLARK, R. H. Justice, Dept. of 79/04/03 23pp

7903290061 Request by Central Power & Light that NRC issue protective order re interrogatories & request for production of documents from Houston Lighting & Power Certificate of Nrc and
 STAN, D. M. Isham, Lincoln & Seale 79/04/03 7pp

7903290073 Response by TX Utils Generating Co's objections to a motion for protective orders & motion to compel further answers to interrogatories & request for production of documents Certificate of Nrc and
 CLARK, R. H. Anti-Trust Division 79/04/04 23pp

7903290084 Mar 1979 discovery progress report of City of San Antonio During last of 790329 documents made available by City were inspected by Public Utility Board of Brownsville-TX Certificate of Nrc and
 WOOD, J. C. Natthauer, Hovell, MacFarlane & Barratt 79/04/05 4pp

7903290088 Motion by Public Utility Board of Brownsville, TX to compel further production of documents from Central Power & Light Electric Cooperative & Medina Electric Cooperative. Supporting documentation & Certificate of Nrc and
 POISBIE, H. E. Spiegel & McDermid 79/04/05 17pp

7903290098 Request by Central Power & Light for extension of time to respond to 790329 responses by Houston Lighting & Power & TX Utils Generating Co to former's interrogatories & document requests Certificate of Nrc and
 STAN, D. M. Isham, Lincoln & Seale 79/04/05 4pp

7903290098 Motion that respondents to motions for summary disposition filed by Houston Lighting & Power & TX Utils Generating Co be governed by 505FRS 7904/04 Certificate of Nrc and
 LEBER, R. P. Anti-Trust Division 79/04/06 3pp

7903290100 Motion by Houston Lighting & Power for protective order re public disclosure of info requested by Public Utility Board of Brownsville-TX Certificate of Nrc and
 BARNETT, E. H. Baker & Smith BOUWHOUT, J. A. Lowenstein-Human, Reiss, Asinoff & Tull 79/04/06 7pp

7903290103 Status of discovery & production during Mar 1979 Certificate of Nrc and
 DALY, S. A. Austin, TX 79/04/06 3pp

7903290104 Apply restrictions on confidential documents to be produced by Houston Lighting & Power Co in response to request for production of documents by Public Utility Board of Brownsville-TX
 MILLER, H. E. Atomic Safety and Licensing Board Panel 79/04/07 3pp

7903290109 Status report on discovery for Mar 1979. Discovery requests were neither initiated nor received. Certificate of Nrc and
 JONES, P. P. Asin, Comp. Hauer & Field 79/04/09 2pp

7903290127 Motion by Gulf States Utils for further extension of time until 7904/09, in which to complete response to City of Brownsville's subpoena for production of documents. Certificate of Nrc and
 HARRIS, R. H. Connery, Moore & Corbett 79/04/09 4pp

7903290181 Answer by Houston Power & Lighting to NRC 790329 response to utility motion for protective order. NRC motion to compel further answers to interrogatories & NRC request for production of documents Certificate of Nrc and
 BARNETT, E. H. Baker & Smith BOUWHOUT, J. A. Lowenstein-Human, Reiss, Asinoff & Tull 79/04/11 12pp

7903290260 Forward revised page 20-1 attached to Central Power & Light Co's answers & objections to Houston Lighting & Power Co's first set of written questions to Central Power & Light Co Certificate of Nrc and
 STAN, D. M. Isham, Lincoln & Seale 79/04/12 4pp

7903290332 Advise re discovery requests have been initiated or received by Ter-Lu Electric Cooperative, Inc. Certificate of Nrc and
 BURCHETTE, W. H. Northcutt Elm 79/04/12 4pp

7903290348 Austin TX Electric Cooperative, Inc & Medina Electric Cooperative, Inc's opposition to Public Utility Board of Brownsville-TX 790405 motion for fuller responses to interrogatories Certificate of Nrc and
 HUNTER, H. McDermid, Luchridge & Kilgore JOHN, E. F. Asin, Comp. Hauer & Field 79/04/13 11pp

7903290367 Advise that during Mar 1979 NRC filed motions to compel against Houston Lighting & Power & TX Utils Generating Co. NRC is preparing responses to TX Utils' first & Houston's second set of interrogatories
 LEBER, R. P. Anti-Trust Division 79/04/13 1p

7903290379 AC receipt of response to Mar 1979 motion to compel & evaluation in progress
 LEBER, R. P. Anti-Trust Division 79/04/15 3p

7903290426 Request by Public Utility Board of Brownsville, TX for extension of time to answer first set of interrogatories & request for production of documents from Central Power & Light & Houston Lighting & Power Certificate of Nrc and
 McDONALD, R. C. Spiegel & McDermid 79/04/16 7pp

7903290441 Concrete revised page 20-1 of Central Power & Light Co answers & objections in 790412 proceeding from "expedient" other than "expedient" re "expedient" other than "expedient" advertising Certificate of Nrc and
 STAN, D. M. Isham, Lincoln & Seale 79/04/17 4pp

7903290580 Direct TX Utils Generating Co (790520) to produce documents or make full responses to 790519 interrogatories. Status 790520's answer for protective order
 MILLER, H. E. Atomic Safety and Licensing Board Panel 79/04/19 3p

7903290624 Response by NRC to Central Power & Light's 790329 objections & 790405 motion for protective order re utility's first set of interrogatories. Includes motion to compel answers. Motions of appearance & Certificate of Nrc and
 BARNETT, E. H. Baker & Smith BOUWHOUT, J. A. Lowenstein-Human, Reiss, Asinoff & Tull 79/04/19 13pp

7903290677 Grants extension of time to answer interrogatories by Public Utility Board of Brownsville, TX in response to 790519 motion
 MILLER, H. E. Atomic Safety and Licensing Board Panel 79/04/19 3p

7903290688 Motion by Central Power & Light to compel Houston Lighting & Power to answer second set of interrogatories submitted 790329 Supporting documentation & Certificate of Nrc and
 MILLER, H. E. Isham, Lincoln & Seale 79/04/20 20pp

7903290722 Motion by Central Power & Light to compel TX Utils Generating Co to answer first set of interrogatories submitted 790329
 STAN, D. M. Isham, Lincoln & Seale 79/04/20 10pp

7903290731 Answer by Central Power & Light & Central & South West Corp meeting conference of NRC activities review, which partly based on grounds of res judicata of collateral estoppel. Supporting documentation & Certificate of Nrc and
 POWELL, R. E. MILLER, H. E. STAN, D. M. Isham, Lincoln & Seale 79/04/20 13pp

7903290804 Oppose City of Austin's 790329 brief & 790403 motion for full or partial summary judgment filed by Houston Lighting & Power & TX Utils Generating Co. Basis denial of certification & intervenor's appeals M/Certificate of Nrc and
 LEBER, R. P. DALY, S. A. Anti-Trust Division 79/04/23 24pp

7903290835 Response of Public Utility Board of Brownsville, TX opposing Houston Lighting & Power's motion for summary decision & City of Austin brief in support of res judicata. Supporting documentation & Certificate of Nrc and
 McDONALD, R. C. JORDAN, R. C. POISBIE, H. E. Spiegel & McDermid 79/04/23 8pp

DOCKETED ITEMS

241

7903240248 Confirms 790424 action that will plans to file response to 790419 Notice By NRC for reconsideration of board order of 790416 compelling further action by until Certificate of NRC mail
FRANKLIN, W J Lewenstein, Neuman, Reiss, Asatrad & Tall 79/04/24 App

7903240249 Util's discovery progress report for Apr. 1979 Certificate of NRC mail
FRANKLIN, W J Lewenstein, Neuman, Reiss, Asatrad & Tall 79/03/02 App

7903250191 Requests until supply & update list of privileged documents
LEEDY, R P Anti-Tank Division 79/03/02 Ip

7903250446 NRC answer to motions of Gulf States Util's per protective order & order making conditions for compliance w/790226 subpoena. Util's should produce documents as requested Certificate of NRC mail.
BLUM, E A Anti-Tank Division 79/03/04 App

D Inspection Reports; IE Bulletin & correspondence

7903010378 Forwards IE Insp Repts 50-498/79-03 & 50-499/79-03 on 790221-23 & notice of violation.
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/02/14 App

7903010379 Notice of violation from Insp on 790221-23
Region 4, Dallas, Office of the Director 79/03/13 Ip

7903010382 IE Insp Repts 50-498/79-03 & 50-499/79-03 on 790221-23 Administrative noted failure to follow procedure for storage of mail
SEITZ, M C Region 4, Dallas, Office of the Director 79/03/13 App

7903010379 Forwards IE Insp Notice 79-04, "Stress Analysis of Safety-Related Piping"
SEITZ, M C Region 4, Dallas, Office of the Director 79/03/23 Ip

7903010437 Forwards IE Bulletin 79-05A, "Nuclear Incident at TMI - Suppl."
SEITZ, M C Region 4, Dallas, Office of the Director 79/04/05 Ip

7903010492 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Key Missions Identified During TMI Incident"
SEITZ, M C Region 4, Dallas, Office of the Director 79/04/14 Ip

7903040443 Forwards IE Bulletin 79-08, "Events Relating to Rolling Water Pump Reactors Identified During TMI Incident"
SEITZ, M C Region 4, Dallas, Office of the Director 79/04/14 Ip

7903070008 Forwards IE Bulletin 79-07, "Nuclear Stress Analysis of Safety-Related Piping." Licensee action required.
SEITZ, M C Region 4, Dallas, Office of the Director 79/04/14 Ip

7903010441 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets."
SEITZ, M C Region 4, Dallas, Office of the Director 79/04/14 Ip

7903090099 Forwards reply to IE Bulletin 79-08A, "Nuclear Incident at TMI."
SEITZ, M C Region 4, Dallas, Office of the Director 79/04/14 Ip

7903030271 Forwards IE Bulletin 79-09, "Failures of SC Type AB-2 Circuit Breakers in Safety-Related Bay." Licensee action required.
SEITZ, M C Region 4, Dallas, Office of the Director 79/04/17 Ip

7903240404 Ack receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-03 & 50-499/79-03
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 Ip

7903240405 Response to NRC 790314 ltr re violations noted in IE Insp Repts 50-498/79-03 & 50-499/79-03 corrective actions storage areas on site surveyed for stainless steel melt in contact w/ carbon steel
TUMBLE, E A Houston Lighting & Power Co. 79/04/03 App

G Reportable occurrences, LERs & related correspondence

7903230208 Forwards PNO-79-076, L & N
SEITZ, M C Region 4, Dallas, Office of the Director 79/04/06 Ip

7903230244 Forwards PNO-79-076, L & N
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09 Ip

7903230245 Forwards PNO-79-076
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/09 Ip

7903230343 Forwards PNO-79-076 & 79-77
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 Ip

7903230318 Forwards PNO-79-076
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 Ip

7903230349 Forwards PNO-79-077
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/13 Ip

7903230371 Forwards PNO-79-076 & V
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 Ip

7903230340 Forwards PNO-79-076
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 Ip

7903230314 Forwards PNO-79-076A
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 Ip

7903230305 Forwards PNO-79-076A, AC & AD
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 Ip

7903240391 Forwards PNO-79-076A
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 Ip

7903240392 PNO-79-076A summary of info re nuclear incident as of 790426. Describes plant & accident status
Office of Inspection & Enforcement 79/04/26 App

7903070183 Forwards PNO-79-076A & AD
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/27 Ip

7903010216 Forwards PNO-79-076A, AI & AJ
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/30 Ip

7903240380 Forwards PNO-79-076A & AL
SEITZ, M C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/04 Ip

DOCKET 8TH-50-499 80/04 TEXAS PROJECT, UNIT "

A. Applicant

7903030004 structure

PAR, G. J

7903230371

PAR, G. J

7903240404

structure

LICITRA

F. Secured

7903030303

Unit 50

TUMBLE

DOCKETED ITEMS

U. Adjudicatory correspondence

7905020286 Response to Citizens for Reliable and Safe Nuclear Power 790223 petition to intervene. Petition should be granted because standing is shown. Certificate of Soc encl
MCURBREN, H. J. Branch 1 79/02/12 17pp.

7905020179 Request by applicant that ARLS issue addl procedures prior to ruling on 7902029 petition to intervene. Petition Concerned About Nuclear Power Certificate of Soc encl
MCURBREN, H. J., REIS, H. F., CULP, R. H. Lounsbury, Houston, Texas, Austin & Tell 79/02/14 8pp

7905020381 NRC response to Houston Lighting & Power 790314 motion for addl procedures requested from Citizens Concerned About Nuclear Power. Request via written intervention. Certificate in NRC Rules of Practice Certificate of Soc encl
MCURBREN, H. J. Branch 1 79/03/29 3pp

7905020264 Response to applicant's motion to provide ARLS w/790119 decision in Health Research Group vs Kennedy. Reproduced from "Legal Times of Washington" Certificate of Soc encl
MCURBREN, H. J. Branch 1 79/04/02 3pp.

7905020218 Assignment of DR Galtman, JH Beck & MC Farrow to ARLS for proceeding
DUPLOE, E. Atomic Safety and Licensing Appeal Panel 79/04/17. 1p

7905020328 Notice of appeal by Houston Lighting & Power of 790402 order granting intervention to Citizens Concerned About Nuclear Power. Citizens for Reliable and Safe Nuclear Power for Economic Energy Certificate of Soc encl
MCURBREN, H. J., REIS, H. F., CULP, R. H. Lounsbury, Houston, Texas, Austin & Tell 79/04/17 3pp

7905020032 Reply by applicants to NRC 790402 motion for extension of time to file Citizens for Reliable and Safe Nuclear Power for continuance. Both motions are unnecessary & unreasonable. Certificate of Soc encl
MCURBREN, H. J., REIS, H. F., CULP, R. H. Lounsbury, Houston, Texas, Austin & Tell 79/04/27 3pp

H. General correspondence

7905010037 PSDA request for "Prehearing Conference Order Ruling Upon Intervention Petitions," & "Part 2 Rules of Practice For Domestic Licensing Proceedings."
RYAN, C. R. Citizens Concerned About Nuclear Power, Inc 79/04/10 1p

7905010024 Response to FOIA request for "Prehearing Conference Order Ruling Upon Intervention Petitions," & "Part 2 Rules of Practice For Domestic Licensing Proceedings." Records requested info. size encl
FELTONG, J. M. Division of Rules and Records 79/04/24 1p.

K. Utility Final Safety Analysis Report (FSAR) & amendments

7905020408 FSARs Amended 3 to FSNM,
TURNER, E. A. Houston Lighting & Power Co. 79/05/04 3pp

7905020409 Amended 3 to FSNM
& Houston Lighting & Power Co 79/05/04 20pp.

7905010224 FSARs supplemental info to Amended 3 to FSNM covering Const Procedure ACRM-PCP-14 & SA violation. Insu rpt dtd 790503
TURNER, E. A. Houston Lighting & Power Co 79/05/09 7pp

N. Arbitration correspondence

7905010318 Petitioners TX Utility Co & subsidiaries' answer to NRC Initial Intervention Petition & request for production of documents. Reserves rights to file objections & protective order before 790505. Certificate of Soc encl
MCURBREN, H. J., MORGAN, FORREY & SAMPSON 79/05/01 1p

7905020322 Grants 790317 motion by Public Utility Board of Brownsville, TX setting intervention until 790505 & 790405 in which the compel ruling responses to Board's intervention.
MCURBREN, H. J. Atomic Safety and Licensing Appeal Panel 79/05/22 1p

7905040127 Notifies that location of deposition of LC Paster of Houston Co has been changed from Building 100, Dallas TX to Dallas-Brown-Rice, C&S & Maple law offices in Houston, TX
RYAN, T. G. Idaho, Lincoln & Seale 79/05/22 3pp

7905020480 Order protecting confidentiality of info sought by Houston Lighting & Power from Central Power & Light, TX Utility. Public Use of OR & Boudinville Electric Power Co
MCURBREN, H. J. Atomic Safety and Licensing Appeal Panel 79/05/03 3pp

7905010020 Response by utility to second set of interrogatories & request for production of documents, submitted to Central Power & Light. Also moves for protective order. Certificate of Soc encl
BARNETT, E. W. Baker & Bette 79/03/28 20pp

7905070380 Advice that deposition of Edward Sherry, Air Products & Chemicals Co, will be held on 790419 at 9:00 a.m. in Houston, TX. 790426
RYAN, T. G. Idaho, Lincoln & Seale 79/05/03 1p

7905020405 HL, Hight, AD Oshers & L. Paster were deposed during Mar Central Power & Light filed answers & objections to Houston Lighting & Power Co first set of written interrogatories
RYAN, T. G. Idaho, Lincoln & Seale 79/03/20 3pp

7905020328 Report on progress made in Mar 1979 in completing discovery, submitted per ARLS 790402 order. Certificate of Soc encl
HARRIS, J. L. Justice, Dept of 79/05/31 7pp

7905030173 Describes discovery activities of Public Utility Board of Brownsville, TX for Mar 1979. Certificate of Soc encl
MCURBREN, H. J. Branch 1 79/04/02 3pp

7905020326 Request by TX Utility Generating Co for NRC to disallow Central Power & Light South West Corp as interveners in alternative, seeks summary disposition or striking of collateral interrogatories. Certificate of Soc encl
MCURBREN, H. J. Debevoise & Lieberman 79/04/03 3pp

7905050042 Request by TX Utility Generating Co for order barring Central Power & Light from seeking relief immediately w/ District Court decision for favorable decision re summary disposition
MCURBREN, H. J. Debevoise & Lieberman 79/04/03 3pp

7905050030 Reply by TX Utility Generating Co re points & authorities supporting motion to disallow Central Power & Light South West Corp as interveners or for summary disposition
MCURBREN, H. J. Debevoise & Lieberman 79/04/03 42pp

7905010020 Response to second set of interrogatories & requests for production of documents directed to Dept of Justice by Houston Lighting & Power. Qualifications of expert witnesses
MCURBREN, H. J. Justice, Dept of 79/04/03 33pp

7905040070 Response to first set of interrogatories & request for production of documents submitted by TX Utility Generating Co. Certificate of Soc encl
HARRIS, J. L. Justice, Dept of, 79/04/03 11pp.

7905020341 Request by Central Power & Light that ARLS issue protective order re interrogatories & request for production of documents from Houston Lighting & Power. Certificate of Soc encl
RYAN, T. G. Idaho, Lincoln & Seale 79/04/03 7pp

7905010029 Response to TX Utility Generating Co's objection to & motion for protective orders & motion to compel further answers to interrogatories & request for production of documents. Certificate of Soc encl.
KLING, R. E. Anti-Trust Division 79/04/04 33pp

7905020251 Mar 1979 discovery progress rpt of City of San Antonio. During visit of 790323, documents made available by City were inspected by Public Utility Board of Brownsville, TX. Certificate of Soc encl.
MCURBREN, H. J. Debevoise & Lieberman 79/04/05 4pp

7905040115 Motion by Public Utility Board of Brownsville, TX to compel further production of documents from South TX Electric Separative & Marine Electric Cooperative. Supporting documentation & Certificate of Soc encl.
MCURBREN, H. J. Branch 1 79/04/05 15pp.

7905040128 Request by Central Power & Light for extension of time to respond to 790328 responses by Houston Lighting & Power & TX Utility Generating Co to former's interrogatories. Documents requested. Certificate of Soc encl.
RYAN, T. G. Idaho, Lincoln & Seale 79/04/05 4pp.

DOCKETED ITEMS

7903010446 Forwards IE Info Notice 79-10: "Noninterfering Pipe Support Brims" - DEVPET, K.V. Region A, Dallas, Office of the Director 79/04/16 1p

7903020077 Forwards suppl to IE Bulletin 79-05A: "Nuclear Incident at TMI" - DEVPET, K.V. Region A, Dallas, Office of the Director 79/04/16 1p

7903030273 Forwards IE Bulletin 79-09: "Failures of SE Type AB-R Circuit Breaker in Safety-Related Ops" - Licensee action required. DEVPET, K.V. Region A, Dallas, Office of the Director 79/04/17 1p

7903040405 Act receipt of 790403 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 90-498/79-03 & 90-499/79-03. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

--7903050493 Response to NRC 790314 ltr re violations noted in IE Insp Repts 90-498/79-03 & 90-499/79-03 Corrective actions Licensee action on site surveyed for stainless steel melt in contact with hot steel TURNER, E.A. Houston Lighting & Power Co. 79/04/03 5pp

H Reportable occurrences, LERs & related correspondence

7903050338 Forwards FMD-79-426A, J & K. DEVPET, K.V. Region A, Dallas, Office of the Director 79/04/26 1p

7903050664 Forwards FMD-79-411, A, B & F. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/26 1p

7903050670 Forwards FMD-79-470. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p

7903050643 Forwards FMD-79-476 & 79-77. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p

7903050618 Forwards FMD-79-475. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/12 1p

7903050648 Forwards FMD-79-527. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/13 1p

7903050671 Forwards FMD-79-520 & V. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p

7903050646 Forwards FMD-79-571. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/16 1p

7903050656 Forwards FMD-79-676A. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/20 1p

7903050668 Forwards FMD-79-676A, J & A. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/23 1p

7903050681 Forwards FMD-79-676E. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/24 1p

--7903050406 FMD-79-676E, summary of info re nuclear incident at of 790404, Des Moines plant & activities status. Office of Inspection & Enforcement. 79/04/24. 5pp.

7903070105 Forwards FMD-79-676P & A. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/27 1p

7903010214 Forwards FMD-79-676M, J & A. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/04/28 1p

7903040388 Forwards FMD-79-676K & A. BEITEL, W.C. Region A, Dallas, Reactor Construction & Engineering Support Branch 79/05/04 1p

DOCKET 90-300 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2
g. Adjudicatory correspondence

7903040316 Forwards final evaluation of items discovered in 790303 area re BSA designated nuclear plant Requested info forwarded to licensing boards. HOLLEY, M.E. Division of Reactor Operations Inspections 79/03/28 10pp

7903040643 Forwards Board Notification 79-10 on reactor inspection progress re BSA plants Certificate of Evc mcl. BEITEL, J.F. Hearings Division 79/03/29 14pp

--7903040658 Board notification reactor inspection concerns re BSA plants. VARNALLO, B. Assistant Director for Light Water Reactors 79/03/26 5pp

--7903040651 Forwards two messages to Thompson memo for Board notification info. THOMPSON, D. Office of I & E Executive Officer for Operations Support 79/03/29 1p

--7903040659 Preliminary evaluation of item 3 contained in 790303 area will be reviewed in light of TMI transcripts. AGRI info may cause change in previous assessment. HOLLEY, M.E. Division of Reactor Operations Inspections 79/03/29 1p

7903040316 Reactor notification nuclear incident at TMI Recommends boards on cases involving BSA reactors be provided w/IE Bulletin 79-03. FMD-79-476 & 90-499/79-03 & 90-498/79-03. Assistant Director for Light Water Reactors 79/04/03 5pp

7903040316 Response to ALAB-509 re padon activities & de minimis theory. J. Van Perkins receive Certificate of Evc mcl. BEITEL, J.F. Hearings Division 79/04/11 43pp

7903040316 Response to 790404 ltr of Philadelphia Electric Co. BSA & Allstate City Hall Electric Co re de minimis theory. Certificate of Evc mcl. BEITEL, J.F. Citizens for Safe Environment 79/04/11 5pp

7903040302 Notices of consolidation of five intervenor groups re redef. evidence issue Parties have until 790223 in which to file for summary disposition. DUFFLE, R.E. Atomic Safety and Licensing Appeal Panel 79/04/02 43pp

J Insurance & indemnity information

7903070477 Confirms increased liability limit to \$24,000,000 for policies MF-1, 205-425, 79-03-100, 111, 140, 146, 151, 161, 164-170, 173, 174, 170, 176, 180-200, 180, 184-187, 188, 189, 190, 193, 194, 195, 197, 199, 200, 201, 204, 206-207, 200, 210, 212, 214, 215, & others. GUMFELD, C.H. J. American Nuclear Insurers. 79/08/01 1p

7903070502 Confirms increased liability limit to \$24,000,000 for policies MF-1, 205-425, 29, 30, 35-39, 44-46, 47, 49, 50, 51, 52, 53, 54, 58, 59, 60, 61, 64-66, 67-69, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 86, 87, 88, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, D.M. Mutual Atomic Energy Liability Underwriters. 79/05/04 1p

7903040361 Forwards Enforcement 28 & 29 to NRC 14 Policy MF-03. LLOYD, E.D. Harris & McLennan, N & K Nuclear Consultants, Inc. 79/05/07 3pp

g. Inspection reports, IE Bulletin & correspondence

7903050401 Forwards IE Insp Rept 90-300/79-01 & 90-301/79-01 on 790222 No noncompliance noted. FIORELLI, S. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/23 2pp

--7903050476 IE Insp Rept 90-300/79-01 & 90-301/79-01 on 790222 No noncompliance noted. Major area inspected: SA-003 progress in applicable area: drilling & grouting in progress & manpower requirements. JONES, C.C. & HAYES, D.W. NRC, E.C. Region 3, Chicago, Office of the Director. 79/03/18 1pp

H Reportable occurrences, LERs & related correspondence

7903050226 Notification of reportable event in 790414, certain starting for essential nuclear had overrated lockers installed which were smaller than capacity specified on relay data sheets, causing possible overload heater burnout. Heater being replaced. KASBERG, T.D. Toledo Edison Co. 79/04/16 1p

DOCKETED ITEMS

245

DOCKET 80-101 DAVID-BEEBE NUCLEAR POWER STATION, UNIT 1

A. Application/construction stage documents & correspondence

7705100142 Forwarded final evaluation of items discussed in 770508 memo re BSM developed nuclear plants Request add info be forwarded to Licensing Board.
HOLLEY, H. C. Division of Reactor Operations Inspections 79/03/28 15pp

7705100143 Forwarded Board Notification 79-10 on reactor inspection conducted re BSM plants Certificate of Div. and
BOHND, J. F. Hearings Division 79/03/29 14pp

7705100145 Board notification reactor inspection concerns re BSM plants
VANDERLIND, S. Assistant Director for Light Water Reactors 79/03/29 2pp

7705100146 Forwarded two Haseley-to-Thompson memo for Board
Notification info
THOMPSON, D. Office of I & E Executive Officer for Operations Support 79/03/29 1p

7705100149 Preliminary evaluation of item D contained in 770508 memo will be reviewed in light of the transient add'l info may cause change in previous assessment
HOLLEY, H. C. Division of Reactor Operations Inspections 79/03/29 1p

7705100152 Board notification nuclear incident at the BSM recommends board on cases involving BSM reactors be provided with Bulletin
79-03 & 79-04 & 874-B.C.D.E.P. & C
VANDERLIND, S. Assistant Director for Light Water Reactors 79/04/03 2pp

7705100153 Response to ALAB-20 re radon emissions & do minimum theory
from Pacific Power Certificate of Div. and
BOHND, J. F. Hearings Division 79/04/11 43pp

7705100159 Response to 770404 brief of Philadelphia Electric Co/PEPCO & Atlantic City Light Electric Co re do minimum theory.
Certificate of Div. and
HOLLEY, H. C. Citizens for Safe Environment 79/04/11 3pp

7705100160 Notice of consolidation of five intervenor groups re radon emissions issue Pacific have until 790529 to which to file
for summary disposition
OFFICE, R. C. Atomic Safety and Licensing Appeal Panel 79/04/25 13pp

J. Insurance & indemnity information

7705070497 Confirmed increased liability limit to \$124,000,000 for
policy No. 1-25-42-78-82, 125-111, 140-146, 151-161, 164-170,
170-174, 175-179, 180-189, 188-189, 187-188, 189, 190, 192, 194, 198,
197, 199, 200, 201, 204, 205, 207, 208, 210, 212, 214, 215, & others.
QUATTROCI, J. American Nuclear Insurers 79/03/01 1p

7705070498 Confirmed increase in liability limit to \$24,000,000 for
policy No. 22-26-29-39, 44-46, 47, 49, 50-51, 52-53, 54, 56, 59, 60,
61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 81, 82,
83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96.
HOLLEY, H. C. Mutual Atomic Energy Liability Underwriters 79/03/01 1p

7705100161 Forwarded Endorsements 28 & 29 to NELA Policy No. 236.
LLOYD, H. H. Marsh & McLennan, H & Nuclear Consultants, Inc. Div. 79/03/07 2pp

D. Inspection reports: IE Bulletins & correspondence

7705030461 Forwarded IE Insp. Report 80-100/79-01 & 80-101/79-01 on 770522
no correspondence noted
FROST, L. G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/23 2pp

7705050470 IE Insp. Report 80-100/79-01 & 80-101/79-01 on 770522. No
noncompliance noted Major areas inspected: QA/QC program in
applicable areas, drilling & grouting in progress & manpower
requirements.
JONES, E. E., HANSEN, D. E., MAND, R. G. Region 3, Chicago, Office of the Director 79/03/19 6pp

E. Regulatory correspondence, LERs & related correspondence

7705070466 Notice of reportable event on 770412, certain starters for
essential motors had overlaid heaters installed which were
smaller than capacity specified on relay data sheets, covering
possible overload heater burnout. Heaters being replaced
MURRAY, T. D. Toledo Edison Co 79/04/14 1p

DOCKET 87N-80-902 HAVEN NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7705100142 Requests info re State of HI Public Use Commission views on
siting of facility & effect of HI Electric Power Co
application for simple nuclear unit near Haven in Shastah
County, HI
DENTON, H. A. Commission 79/04/05 2pp

7705090141 Forwarded request for add'l info re outstanding alternate
sites
BALLARD, F. L. Environmental Projects Branch 1 79/04/19 3pp

7705050147 Forwarded add'l copies of results of geological investigations
re possible faulting under Lake Michigan, presence of
utility & BSM at 770507 meeting w/WMHC re evidence of
faulting indicated. 62 overlaid drawings in Central Files
BURSTEIN, H. Wisconsin Electric Power Co 79/03/20 36pp

7705100151 Submits add'l info re P&AB & site addendum in response to
770508 request identifies items requiring add'l time for
completion
BURSTEIN, H. Wisconsin Electric Power Co 79/04/10 33pp

B. Utility Preliminary Safety Analysis Report, amendments

7705100152 Forwarded Amend 2B to be inserted into P&AB site addendum
affidavit and
BURSTEIN, H. Wisconsin Electric Power Co 79/04/20 2pp

7705100151 Amend 2B to P&AB site addendum insertion instructions and
a Wisconsin Electric Power Co 79/04/20 103pp

C. Utility Environmental Report (IER), amendments & correspondence

7705100149 Forwarded "Amend 14 to Environ Rept." CP stage
BURSTEIN, H. Wisconsin Electric Power Co 79/04/10 33pp

7705100149 "Amend 14 to Environ Rept." CP stage w/overlaid drawings
a Wisconsin Electric Power Co 79/04/20 143pp

D. Application/construction stage documents & correspondence

7705070498 Requests explanation for denial of 770509 motion
Certificate of Div. and
HOLLEY, H. C. Safe Energy for New Haven 79/03/30 2pp

7705100147 Motion & brief in support of verification & analysis of data
submitted by BSM Certificate of Div. and
HOLLEY, H. C. Safe Energy for New Haven 79/03/30 2pp

7705070498 Denial of 770509 motion by Intervenor Safe Haven for
verification & analysis of computations & computer codes.
Intervenor is making inappropriate request beyond scope of
ARL.
CHARNOCK, S. M. Shaw, Pittman, Potts, & Taubridge 79/04/10 3pp

7705040288 Response in opposition to Intervenor Safe Haven 770520
motion for verification & analysis of all BSM computer
codes Intervenor does not cite sufficient facts or legal
authority. Certificate of Div. and
SOLDSBERG, G. C. Branch 2 79/04/17 3pp

K. General correspondence

7705070470 Forwarded affidavit of PF Libertas, attesting wvt of
minority wvt Amends 13 & 14 & P&AB Amend 2B.
BURSTEIN, H. Wisconsin Electric Power Co 79/03/02 10pp

J. Insurance & indemnity information

7705070497 Confirmed increased liability limit to \$124,000,000 for
policy No. 1-25-42-78-82, 125-111, 140-146, 151-161, 164-170,
170-174, 175-179, 180-189, 188-189, 187-188, 189, 190, 192, 194, 198,
197, 199, 200, 201, 204, 205, 207, 208, 210, 212, 214, 215, & others.
QUATTROCI, J. American Nuclear Insurers 79/03/01 1p

7705070498 Confirmed increase in liability limit to \$24,000,000 for
policy No. 22-26-29-39, 44-46, 47, 49, 50-51, 52-53, 54, 56, 59, 60,
61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 81, 82,
83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96.
HOLLEY, H. C. Mutual Atomic Energy Liability Underwriters 79/03/01 1p

DOCKETED ITEMS

P. Operating license change documents & correspondence

7905040285 Forwards chronology of FEAR amend re SA program in response to NRC 790502 request
BARKIN, R P Southern California Edison Co 79/04/27 3pp

BOCKET 8TH-30-300 KWHNU NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7905040282 Requests info re status of NE Public Use Commission views on siting of facility & effect of NE Electric Power Co application for single nuclear unit near Haven in Shastate County, CA
CROFTON, M R Commission 79/04/05 3pp

O Adjudicatory correspondence

7905070230 Requests explanation for dismissal of 780509 motion Certificate of Decision
HARRIS, M C Safe Energy for New Haven 79/03/30 2pp

7905010247 Motion & brief in support of verification & analysis of data supplied by NE Certificate of Decision
HARRIS, M C Safe Energy for New Haven 79/03/30 2pp

BOCKET 8TH-30-300 KWHNU NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

7905040279 Forwards Rept 4 to "Groundwater Drainage Sys. Analysis of Site Performance & Data to Date"
HARRIS, M C Washington Public Power Supply System 79/04/26 3pp

7905040288 Rept 4 to "Groundwater Drainage Sys. Analysis of Site Performance & Data to Date"
HARRIS, M C Washington Public Power Supply System 79/03/31 30pp

7905040411 Forwards NRC position on WPPSS-CA-004, "Operational SA Program Description." Response to position should be submitted by 790501 as amend to original report
HARRIS, M P Pacific Assurance Branch 79/05/05 3pp

7905010237 Notices that environ evaluation has been performed on West Layton Areas adverse impacts associated w/development activity. Development of area to begin in June 1979. Forwards internal memo & report re potential adverse impacts
HARRIS, M C Washington Public Power Supply System 79/05/07 3pp

I Financial information

7905090284 Forwards "Annual Financial Rept 1978" for Puget Sound Power & Light Co. Portland OR. Pacific Power & WPPSS
HARRIS, M C Washington Public Power Supply System 79/05/01 3pp

7905090283 "Annual Financial Rept 1978."
Puget Sound Power & Light Co. 78/12/01 44pp

7905090282 "Annual Financial Rept 1978."
Portland General Electric Co 79/03/31 40pp

7905040292 "Annual Financial Rept 1978."
Pacific Power Co. 78/12/31 30pp

7905090275 "Annual Financial Rept 1978."
Washington Public Power Supply System. 78/12/31 45pp

7905090280 "Annual Financial Rept 1978."
Washington Water Power Co. 78/12/31 30pp

O Inspection reports, IE Bulletins & correspondence

7905010294 Forwards IE Info Notice 79-06, "Review Analysis of Safety-Related Piping."
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/03/22 1p

7905010013 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Re Misalignments Identified During TMI Incident."
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/14 1p

7905040314 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Re Misalignments Identified During TMI Incident."
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/14 1p

7905040425 Forwards IE Bulletin 79-06C, "Events Relevant to Bellingham Water Reactor Identified During TMI Incident."
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/14 1p

7905070110 Forwards IE Bulletin 79-07, "Belmont Stress Analysis of Safety-Related Piping." Licensee action required
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/14 1p

7905050205 Forwards IE Bulletin 79-08, "Failures of GE Type A-2 Circuit Breaker in Safety-Related Sys." Licensee action required.
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/17 1p

7905060378 Forwards IE Bulletin 79-09B, "Nuclear Incident at TMI-Bugel."
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/21 1p

B Reportable occurrences, LERs & related correspondence

7905100347 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/06 1p

7905100373 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/11 1p

7905040134 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

7905100150 Forwards PNO-79-ATL
ENGELKEN, R H Region 3, San Francisco, Office of the Director. 79/04/12 1p

DOCKETED ITEMS

247

790318037 Forwards PWD-79-674H.
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/05/07 1p

DOCKET 87H-30-504 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

790304039 Forwards Suppl 4 to "Groundwater Drawings Sys. Analysis of
Sys Performance & Data to Date" *
RENNER, D. L. Washington Public Power Supply System 79/04/26
3pp

--790304038 Suppl 4 to "Groundwater Drawings Sys. Analysis of Sys
Performance & Data to Date" * Overhead drawings encl
* Washington Public Power Supply System 79/03/31. 10pp

790304041 Forwards NRC positions on WPPSS-0A-004, "Operational SA
Program Description" * Response to questions should be
submitted as amend to original rpt by 7/30/81.
HARRIS, H. P. Quality Assurance Branch 79/03/01 2pp

790306037 Notifies that environ evaluation has been performed on West
Laguna Avenue adverse impacts associated w/development
actively development of area to begin in June 1979 Forwards
internal memo & rpt re potential environ impacts
RODENSEN, S. L. Washington Public Power Supply System 79/03/07.
4pp

I Financial information

790309084 Forwards "Annual Financial Rpt 1978" for Puget Sound Power
& Light Co, Portland OR Pacific Power & Light Co
RENNER, D. L. Washington Public Power Supply System 79/03/01
2pp

--790309085 "Annual Financial Rpt 1978" *
* Puget Sound Power & Light Co 78/12/01 44pp

--790309086 "Annual Financial Rpt 1978" *
* Portland General Electric Co 79/03/01. 40pp

--790309087 "Annual Financial Rpt 1978" *
* Pacific Power Co 78/12/01. 32pp

--790309088 "Annual Financial Rpt 1978" *
* Washington Public Power Supply System 78/12/01 45pp.

--790309089 "Annual Financial Rpt 1978" *
* Washington Water Power Co 78/12/01 32pp

790310094 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
ENGLER, R. H. Region 4, Dallas, Office of the Director 79/03/23
1p

790310015 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident."
ENGLER, R. H. Region 5, San Francisco, Office of the Director
79/04/14. 1p

790304016 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Sys Misalignments Identified During TMI Incident."
ENGLER, R. H. Region 5, San Francisco, Office of the Director
79/04/14. 1p.

790304021 Forwards IE Bulletin 79-06, "Events Relevant to Rolling
Water Reactor Identified During TMI Incident."
ENGLER, R. H. Region 5, San Francisco, Office of the Director.
79/04/14. 1p

790307010 Forwards IE Bulletin 79-07, "Stress Analysis of
Safety-Related Piping" * License action required.
ENGLER, R. H. Region 5, San Francisco, Office of the Director
79/04/14. 1p.

790303005 Forwards IE Bulletin 79-07, "Failures of SE Type AM-2
Circuit Breaker in Safety-Related Sys" * License action
required.
ENGLER, R. H. Region 5, San Francisco, Office of the Director.
79/04/17. 1p.

790306007 Forwards IE Bulletin 79-07B, "Nuclear Incident at
TMI-2 Suppl." *
ENGLER, R. H. Region 5, San Francisco, Office of the Director.
79/04/21. 1p

B Reportable occurrences, LERs & related correspondence

790305009 Forwards PWD-79-67L
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/04 1p

790305013 Forwards PWD-79-67E
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/01. 1p

790305014 Forwards PWD-79-67B
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/02 1p

790305015 Forwards PWD-79-67T
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/03 1p

790305016 Forwards PWD-79-67U
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/04 1p

790305018 Forwards PWD-79-67AA
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/20 1p

790310429 Forwards PWD-79-67AB
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/21 1p.

790310430 Forwards PWD-79-67AC & AD
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/22 1p

790310440 Forwards PWD-79-67AE
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/24. 1p.

790309047 Forwards PWD-79-67AF
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/28 1p

790309059 Forwards PWD-79-67AG
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/28. 1p

790309012 Forwards PWD-79-67AH
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/27. 1p

790309034 Forwards PWD-79-67AJ, Ad & AE, per NRC 790401 ltr transmitt.
IE Bulletin 79-05.
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/28. 1p

790309018 Forwards PWD-79-67AL per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/03/01. 1p.

790310037 Forwards PWD-79-67AM.
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/05/07 1p

DOCKET 30-810 BLUM HILLS STATION, UNIT 1

D. Adjudicatory correspondence

790306043 Forwards 790702 memo discussing results of recently
conducted fire protection research test performed by UL as
part of NRC fire protection research program
WCCORP, G. P. Branch 3. 79/04/03. 1p

790304012 Evidentiary hearing re applicable? * re review
will begin 7/8/80.
HILLER, R. E. Atomic Safety and Licensing Board Panel. 79/04/04.
5pp

790303018 Requests permission to address with hearings.
DWAH, R. Sierra Club. 79/04/26. 1p.

DOCKETED ITEMS

T. Hearing transcripts on non-antitrust matters

7905050523 Transcript of 7905050 hearing in Jasper, TX Re 1-102
 MILLER, M. E.; LITTLE, L. M.; NORMAN, L. H. Atomic Safety and Licensing
 Board Panel 79/05/05 153pp

7905050520 Transcript of 7905050 hearing in Jasper, TX Re 123-289
 MILLER, M. E.; LITTLE, L. M.; NORMAN, L. H. Atomic Safety and Licensing
 Board Panel 79/05/05 167pp

DOCKET 50-511 BLUE HILLS STATION, UNIT 2

G. Antitrust correspondence

7905050523 Forwards 7905050 memo discussing results of recently
 completed fire protection research task performed by US, as
 part of NRC fire protection research program
 7905050523, C.F. Branch 3 79/05/05 1p

7905050522 Evidentiary hearing re application for early site review
 will begin 790505
 MILLER, M. E. Atomic Safety and Licensing Board Panel 79/04/26
 4pp

7905050519 Requests permission to address site hearings
 DWHB-E Sierra Club 79/04/26 1p

T. Hearing transcripts on non-antitrust matters

7905050523 Transcript of 7905050 hearing in Jasper, TX Re 1-102
 MILLER, M. E.; LITTLE, L. M.; NORMAN, L. H. Atomic Safety and Licensing
 Board Panel 79/05/05 153pp

7905050520 Transcript of 7905050 hearing in Jasper, TX Re 123-289
 MILLER, M. E.; LITTLE, L. M.; NORMAN, L. H. Atomic Safety and Licensing
 Board Panel 79/05/05 167pp

DOCKET 50-511 WPPSS NUCLEAR PROJECT, UNIT 4

A. Application/construction stage documents & correspondence

7905050524 Reply on geological studies' status. Summary report requested in
 Fall 1979. Requests meeting to discuss plans for submitting
 reports of studies, as well as mechanism for identification &
 review of studies. On Hanford area
 BERENSON, S. L. Washington Public Power Supply System 79/04/27
 2pp

7905050511 Forwards NRC positions on WPPSS-04-004, "Operational QA
 Program Description." Response to positions should be
 submitted as amend to original report by 790505.
 MAMERS, W. P. Quality Assurance Branch 79/05/01 2pp

7905050524 Requests NRC for stating acceptability of scale model tests in
 line of impact tests to satisfy commitment in WPPSS-04-004
 PWR Section 6.77 re recirculation pump testing.
 BERENSON, S. L. Washington Public Power Supply System, 79/05/25.
 1p

ion of review on
 ASLE
 re record.
 stem 79/04/07.

& de Minibus theory

P.

Electric Co. PMSB &
 074.

04/11 Epp.

refer groups re radio
 on to file

encl. 79/04/25.

S. Inspection reports, IE Bulletin & correspondence

7905050524 Forwards IE Info Notice 79-05, "On-site Analysis of
 Reactor-Related Piping."
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director 79/05/20
 1p

7905050519 Forwards IE Bulletin 79-048, "Review of Operational Errors &
 Six Missions Identified During TMI Incident."
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/14 1p

7905050516 Forwards IE Bulletin 79-048, "Review of Operational Errors &
 Six Missions Identified During TMI Incident."
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/14 1p

7905050525 Forwards IE Bulletin 79-05, "Events Relating to Belling
 Meter Power Switches Identified During TMI Incident."
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director,
 79/04/14 1p

7905050515 Forwards IE Bulletin 79-07, "Seismic Stress Analysis of
 Safety-Related Piping." Licenses action required
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/14 1p

7905050520 Forwards IE Bulletin 79-09, "Failures of GE Type A-2
 Circuit Breaker in Safety-Related Gps." Licenses action
 required
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/17 1p

7905050520 Forwards IE Bulletin 79-05B, "Nuclear Incident at
 TMI-2."
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/21 1p

B. Reportable occurrences, LERs & related correspondence

7905050524 Forwards PMSB-79-076.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/05 1p

7905050513 Forwards PMSB-79-076.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/11 1p

7905050519 Forwards PMSB-79-076.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director,
 79/04/12 1p

7905050510 Forwards PMSB-79-077.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/12 1p

7905050519 Forwards PMSB-79-076.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/14 1p

7905050526 Forwards PMSB-79-076.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/20 1p

7905050529 Forwards PMSB-79-076.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/21 1p

7905050520 Forwards PMSB-79-076 & AD.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/23 1p

7905050523 Forwards PMSB-79-076.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director,
 79/04/24 1p

7905050547 Forwards PMSB-79-076.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director,
 79/04/25 1p

7905050529 Forwards PMSB-79-076.
 ENGELSEN, R. H. Region 3, San Francisco, Office of the Director
 79/04/26 1p

DOCKETED ITEMS

700990121 Forwards #10-79-67001
DISTRIBUTION: R.H. Region 3, San Francisco; Office of the Director
70094027 1c

790870034 Forward: PHG-79-67A1.8J & AM per HRC 790801 ltr transmitting
to Bulletin 79-08
DIRECTIONS: H. H. Region 8, San Francisco, Office of the Director
79/08/790

79097306D Forwarded FMD-79-67AL per MRC 790401 for transmission to
Sullivan 79-09
SMOLKEN, R H Region 5- San Francisco; Office of the Director
79/05/04 1a.

705190067 Forwards final deficiency report re bid item senior support,
per 770416 balcon.
HENDERSON, D L. Washington Public Power Supply System 79/03/07
D.

--70031900649 Piping deficiency rept latdown cooler supports inadequate to support specified loads Caused by inadequate design by component manufacturer Hall mounted brackets redesigned at Washington Public Power Supply System 7/4/03/07 See

905380007 Forwarded FPO-79-6246
INGELKON, R H Region 5, San Francisco, Office of the Director
MAR 1979

705240637 Ack receipt of 790307 final deficiency rpt on ledson
color support design inadequacy.
DUELN24 R 01 Region 5- San Francisco. Office of the Director
7006/14. 1a

DOCKET NO. 80-014, ROEBLE ORIGINATOR NUCLEAR PLANT, UNIT 1

© Radiologicallibrary.com

W08060163 Forwards Beard Notification 79-10 re reenter Inspector
jancusa re BMA clients. Certificate of Enc and
SCINTQ:J P Hearings Division 79/03/29 1aaa

70501015D Forward request for Board notification re nonsafety-grade
equipment to mitigate transients
SCINTG.L.J. Hearings Division 79/04/02. 01pp

-7905050106 Heard validation staff assessment re necessary CT
 equipment to mitigate transients.
 WDBALLD, S. S Assistant Director for Light Water Reactors
 29/03/27 Sue

-7903010178 Delayed notification, recent issue on non-safety-grade equipment to mitigate spendants More info is required
TEHRANCO.R L. Assistant Director for Reactor Safety 7903010178
Dm.

7035601R Board notification, nuclear incident at TMS, recommends boards
on cases involving BWR reactors be provided w/IE Bulletin
70-05 & PMO-67 & 470, S.C.D.E.F.O & H.
WISALL, D.E. Assistant Director for Light Water Reactors
704000R Rec.

790524076Z Memo & order re 790620 conference to discuss scheduled status of state of DR proceeding & status of open items
YDWE-J.R. Atomic Safety and Licensing Board Panel 79/05/11 201

Financial Information

7400000470 "Annual Financial Rept 1970" from SEC
 a. Highland General Electric Co. 70/12/31 0001

4. Insurance & Indemnity Information

78082070497 Confirms increased liability limit to \$124,000,000 for policies NF-1, 20-42, 76, 83, 109, 111, 140, 146, 151, 161, 164, 170, 173, 174, 176, 179, 180, 182, 183, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 206, 207, 208, 210, 212, 214, 215, & others. QUARTERMASTER, J. American Nuclear Insuranc. 7/9/01/01 lg.

7805070889 Confirms increase in liability limit to \$34,000,000 for
policies 89-22, 26, 29, 36, 39, 44-46, 47-49, 50, 51, 52, 53, 54, 55, 56,
57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 76, 77, 78, 79, 80, 84, 87,
88, 90, 91, 92, 93, 94, 95 & 96
ROBERTO, D.M. Mutual Atomic Energy Liability Underwriters 77/05/85.
Sa.

© Advisory Committee on Teacher Salaries reports & correspondence

79051008-4 Forwards responses to 26 ACRS questions re plant application in response to HMC 771121 Ltr
WILLIAMS, J L. Portland General Electric Co 7/9/80 13p

P. Describing license state documents & correspondence

7906030361 Responds to DOE 79040111 Site Unable to provide supplemental info by 790430 Response dependent upon preparation & approval of Offsite Data Calculation Manual Response will be ready by 790501

B Reportable occurrences, LERs & res

790510209 Board notification Seabrook refueling water storage tank design deficiency
NCHTDL-J Seabrook Division 79/03/29 300a

DOSEY 80-015 PEGGLE SPRINGS NUCLEAR PLANT, UNIT 2

© Adjudicatory correspondence

7903140510 Forwarded Board Notification 79-02 as reactor Inspector
continued re BSW plants Certificate of Suit and
010000J.F. Marine Division 7903/29 1400

79000010415 Forwards request for Board notification re non-safety-grade equipment to mitigate transients
 subject: 10415 Newlines Division 79/004002 Dale

--7905010134 Heard notification staff assessment re necessary-prob
equipment to mitigate transients
UNRECORDED B Assistant Director for Light Water Reactors
79/03/29 Doc

7900020498 Board notification recent issue on non-safety-grade
equipment to mitigate transients More info is required
TEDDSCOM L Assistant Director for Reactor Safety 79/02/12

790516-0112 Based notification nuclear incident at TRI Reactors &
an cases involving BWR reactors be provided w/IE Bulletin
79-05 & PMD-67 & AT&A,C,E,E,F,G & H
9956ALLD D 9 Assistant Director for Light Water Reactors
79/04/COO 3ea

7906240762 Memo & order re 790620 conference to discuss schedule, status of state of OR proceeding & status of open items
VQBE: J R Atomic Safety and Licensing Board Panel 79/03/11 3pp

d. Insurance and Employment Information

790807D-497 Confirms increased liability limit to \$124,000,000 for
policy no. NW-55,43, 74-WS, 100, 111, 140, 144-151, 161, 164, 170,
173, 174, 178, 179, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195,
197, 198, 200, 201, 204, 206, 207, 208, 210, 213, 214, 215, & others
199-2030001. J. American Nuclear Insurance 79/05/01 1p

7903070592 Confirms increase in liability limit to \$35,000,000 for policies MF-22,24,29,35,39,44,46,47,49,50,51,52,53,54,55,56,57,58,60,61,64,66,67,68,69,70,71,72,74,76,77,79,80,84,87,88,90,91,92,93,94,95 & 96
ROBERTO, O M Mutual Atomic Energy Liability Underwriters 79/09/01
in.

D. Advisory Committee on Reactor Safeguards reports & correspondence

7900110014 Forward response to 26 ACES questions re plant application, in response to NRC 775023 ltr.
MILLBANK, J.L. Portland General Electric Co 77/11/90. 10pp

ii. Reservation license stage documents & correspondence

7906030361 Responds to DOE 790411 ltr Unkln to provide supplemental info by 780430 Response dependent upon preparation & approval of Offsite Dose Calculation Manual. Response will be ready by 790601
Rockland General Electric Co 79/04/27. Is

DOCKETED ITEMS

B Reportable occurrences, LERs & related correspondence

790510003 Board notification Reactor refueling water storage tank design deficiencies
BCHING, J. Hearings Division 79/03/29 30pp

DOCKET 87N-80-516 JAMESPORT NUCLEAR STATION, UNIT 1

C Adjudicatory correspondence

790501015 Forward request for Board notification re nonsafety-grade equipment to mitigate transients
BCHING, J. F. Hearings Division 79/04/02 31pp

--790501015 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
WABALLOO, S. Assistant Director for Light Water Reactors 79/03/29 2pp

--790501016 Board notification recent issue on nonsafety-grade equipment to mitigate transients. More info is required
TOMECED, R. L. Assistant Director for Reactor Safety 79/03/16 3pp

790501015 Applicants' brief opposing Suffolk County 790115 exceptions & 790226 supporting brief. Supporting documentation & Certificate of Gov. seal
REVELEY, M. T., WHITTENORE, Merton & Williams 79/04/02 30pp

790508093 Response to request for info re possible shutdown of facility due to possible design deficiencies caused by computer model design Computer model in question not used for facilities
MORTLAND, E. K. Branch 4 79/04/03 2pp

790504028 Operates Intervenor County of Suffolk brief in support of exceptions to ALE 791226 initial decision Certificate of Gov. seal
BORMESCH, S. H. Branch 4 79/04/12 27pp

790508010 Requests inclusion of NY Dept of Public Wgt on evc list for NY siting proceeding
BLAU, J. New York, State of 79/04/13 1p

D Inspection reports, IE Bulletin & correspondence

790501016 Forward IE Info Notice 79-06: "Stress Analysis of Safety-Related Piping"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/02/23 1p

790502021 Forward IE Bulletin 79-06: "Review of Operational Errors & Sys Misalignments Identified During THE Incident"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/11 1p

790502079 Forward IE Bulletin 79-07: "Radiation Stress Analysis of Safety-Related Piping - Licensee action required"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/16 1p

790504020 Forward IE Bulletin 79-08: "Review of Operational Errors & Sys Misalignments Identified During THE Incident"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/16 1p

790504028 Forward IE Bulletin 79-08: "Events Relevant to Boiling Water Power Reactors Identified During THE Incident"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

790503070 Forward IE Bulletin 79-09: "Failures of GE Type AA-2 Circuit Breaker in Safety-Related Sys - Licensee action required"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/17 1p

790502043 Forward IE Bulletin 79-08A/Revision 1: "Review of Operational Errors & Sys Misalignments Identified During THE Incident"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/18 1p

E Reportable occurrences, LERs & related correspondence

790510003 Board notification Reactor refueling water storage tank design deficiencies
BCHING, J. Hearings Division 79/03/29 30pp

DOCKET 87N-80-517 JAMESPORT NUCLEAR STATION, UNIT 2

G Adjudicatory correspondence

790501015 Forward request for Board notification re nonsafety-grade equipment to mitigate transients
BCHING, J. F. Hearings Division 79/04/02 31pp

--790501016 Board notification staff assessment re nonsafety-grade equipment to mitigate transients
WABALLOO, S. Assistant Director for Light Water Reactors 79/03/29 2pp

--790501016 Board notification recent issue on nonsafety-grade equipment to mitigate transients. More info is required
TOMECED, R. L. Assistant Director for Reactor Safety 79/03/16 3pp

790501015 Applicants' brief opposing Suffolk County 790115 exceptions & 790226 supporting brief. Supporting documentation & Certificate of Gov. seal
REVELEY, M. T., WHITTENORE, Merton & Williams 79/04/02 30pp

790508093 Response to request for info re possible shutdown of facility due to possible design deficiencies caused by computer model design Computer model in question not used for facilities
MORTLAND, E. K. Branch 4 79/04/03 2pp

790504028 Operates Intervenor County of Suffolk brief in support of exceptions to ALE 791226 initial decision Certificate of Gov. seal
BORMESCH, S. H. Branch 4 79/04/12 27pp

790508010 Requests inclusion of NY Dept of Public Wgt on evc list for NY siting proceeding
BLAU, J. New York, State of 79/04/13 1p

H Inspection reports, IE Bulletin & correspondence

790501016 Forward IE Info Notice 79-06: "Stress Analysis of Safety-Related Piping"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/02/23 1p

790502021 Forward IE Bulletin 79-06: "Review of Operational Errors & Sys Misalignments Identified During THE Incident"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/11 1p

790502079 Forward IE Bulletin 79-07: "Radiation Stress Analysis of Safety-Related Piping - Licensee action required"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/16 1p

790504028 Forward IE Bulletin 79-08: "Review of Operational Errors & Sys Misalignments Identified During THE Incident"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

790504020 Forward IE Bulletin 79-08: "Events Relevant to Boiling Water Power Reactors Identified During THE Incident"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/14 1p

790503070 Forward IE Bulletin 79-09: "Failures of GE Type AA-2 Circuit Breaker in Safety-Related Sys - Licensee action required"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/17 1p

790502043 Forward IE Bulletin 79-08A/Revision 1: "Review of Operational Errors & Sys Misalignments Identified During THE Incident"
OBER, S. H. Region 1, Philadelphia, Office of the Director 79/04/18 1p

I Reportable occurrences, LERs & related correspondence

790510003 Board notification Reactor refueling water storage tank design deficiencies
BCHING, J. Hearings Division 79/03/29 30pp

DOCKETED ITEMS

251

DOCKET RTH-95-010 HARTSVILLE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7905080341 Discusses steel position on leak testing, pressure & temp requirements of ACI Bids 318 & 349 for piping to be embedded in concrete. Revisions to P&AR re embedded piping will be implemented immediately.
GILLELAND, J.E. Tennessee Valley Authority 79/05/03 3pp

F. Security, medical, emergency & fire protection plans

7905060442 Forwards add response to 790506 meeting minutes re STRIDE fire protection analysis includes proposed design changes to fire protection app Requests early meeting to discuss responses
GILLELAND, J.E. Tennessee Valley Authority 79/05/03 3pp

G. Additional correspondence

7905060774 Requests adoption of de minimis theory of Pertine ABL Certificate of Guc encl.
BANDER, J. W. WALLACE, L. E. SUTTERMAN, A. H. Tennessee Valley Authority 79/04/06 11pp

7905100410 Response to ALAB-SOV re radon emissions & de minimis theory from Pertine record Certificate of Guc encl.
BANDER, J. F. Marriage Division 79/04/11 43pp

7905100519 Response to 790404 brief of Philadelphia Electric Co. P&AR & Atlantic City 1100 Electric Co re de minimis theory Certificate of Guc encl.
KEPPORD, C. R. Citizens for Safe Environment 79/04/11 3pp

7905140032 Notification of consolidation of five intervenor groups re radon emissions issue. Parties have until 790520 in which to file for summary disposition.
DUFFLO, M. E. Atomic Safety and Licensing Appeal Panel 79/04/20 13pp

J. Insurance & indemnity information

7905070477 Confirms increased liability limit to \$124,000,000 for policies 97-1, 98-2, 99-3, 100-4, 101-5, 102-6, 103-7, 104-8, 105-9, 106-10, 107-11, 108-12, 109-13, 110-14, 111-15, 112-16, 113-17, 114-18, 115-19, 116-20, 117-21, 118-22, 119-23, 120-24, 121-25, 122-26, 123-27, 124-28, 125-29, 126-30, 127-31, 128-32, 129-33, 130-34, 131-35, 132-36, 133-37, 134-38, 135-39, 136-40, 137-41, 138-42, 139-43, 140-44, 141-45, 142-46, 143-47, 144-48, 145-49, 146-50, 147-51, 148-52, 149-53, 150-54, 151-55, 152-56, 153-57, 154-58, 155-59, 156-60, 157-61, 158-62, 159-63, 160-64, 161-65, 162-66, 163-67, 164-68, 165-69, 166-70, 167-71, 168-72, 169-73, 170-74, 171-75, 172-76, 173-77, 174-78, 175-79, 176-80, 177-81, 178-82, 179-83, 180-84, 181-85, 182-86, 183-87, 184-88, 185-89, 186-90, 187-91, 188-92, 189-93, 190-94, 191-95, 192-96, 193-97, 194-98, 195-99, 196-100, 197-101, 198-102, 199-103, 200-104, 201-105, 202-106, 203-107, 204-108, 205-109, 206-110, 207-111, 208-112, 209-113, 210-114, 211-115, 212-116, 213-117, 214-118, 215-119, 216-120, 217-121, 218-122, 219-123, 220-124, 221-125, 222-126, 223-127, 224-128, 225-129, 226-130, 227-131, 228-132, 229-133, 230-134, 231-135, 232-136, 233-137, 234-138, 235-139, 236-140, 237-141, 238-142, 239-143, 240-144, 241-145, 242-146, 243-147, 244-148, 245-149, 246-150, 247-151, 248-152, 249-153, 250-154, 251-155, 252-156, 253-157, 254-158, 255-159, 256-160, 257-161, 258-162, 259-163, 260-164, 261-165, 262-166, 263-167, 264-168, 265-169, 266-170, 267-171, 268-172, 269-173, 270-174, 271-175, 272-176, 273-177, 274-178, 275-179, 276-180, 277-181, 278-182, 279-183, 280-184, 281-185, 282-186, 283-187, 284-188, 285-189, 286-190, 287-191, 288-192, 289-193, 290-194, 291-195, 292-196, 293-197, 294-198, 295-199, 296-200, 297-201, 298-202, 299-203, 300-204, 301-205, 302-206, 303-207, 304-208, 305-209, 306-210, 307-211, 308-212, 309-213, 310-214, 311-215, 312-216, 313-217, 314-218, 315-219, 316-220, 317-221, 318-222, 319-223, 320-224, 321-225, 322-226, 323-227, 324-228, 325-229, 326-230, 327-231, 328-232, 329-233, 330-234, 331-235, 332-236, 333-237, 334-238, 335-239, 336-240, 337-241, 338-242, 339-243, 340-244, 341-245, 342-246, 343-247, 344-248, 345-249, 346-250, 347-251, 348-252, 349-253, 350-254, 351-255, 352-256, 353-257, 354-258, 355-259, 356-260, 357-261, 358-262, 359-263, 360-264, 361-265, 362-266, 363-267, 364-268, 365-269, 366-270, 367-271, 368-272, 369-273, 370-274, 371-275, 372-276, 373-277, 374-278, 375-279, 376-280, 377-281, 378-282, 379-283, 380-284, 381-285, 382-286, 383-287, 384-288, 385-289, 386-290, 387-291, 388-292, 389-293, 390-294, 391-295, 392-296, 393-297, 394-298, 395-299, 396-300, 397-301, 398-302, 399-303, 400-304, 401-305, 402-306, 403-307, 404-308, 405-309, 406-310, 407-311, 408-312, 409-313, 410-314, 411-315, 412-316, 413-317, 414-318, 415-319, 416-320, 417-321, 418-322, 419-323, 420-324, 421-325, 422-326, 423-327, 424-328, 425-329, 426-330, 427-331, 428-332, 429-333, 430-334, 431-335, 432-336, 433-337, 434-338, 435-339, 436-340, 437-341, 438-342, 439-343, 440-344, 441-345, 442-346, 443-347, 444-348, 445-349, 446-350, 447-351, 448-352, 449-353, 450-354, 451-355, 452-356, 453-357, 454-358, 455-359, 456-360, 457-361, 458-362, 459-363, 460-364, 461-365, 462-366, 463-367, 464-368, 465-369, 466-370, 467-371, 468-372, 469-373, 470-374, 471-375, 472-376, 473-377, 474-378, 475-379, 476-380, 477-381, 478-382, 479-383, 480-384, 481-385, 482-386, 483-387, 484-388, 485-389, 486-390, 487-391, 488-392, 489-393, 490-394, 491-395, 492-396, 493-397, 494-398, 495-399, 496-400, 497-401, 498-402, 499-403, 500-404, 501-405, 502-406, 503-407, 504-408, 505-409, 506-410, 507-411, 508-412, 509-413, 510-414, 511-415, 512-416, 513-417, 514-418, 515-419, 516-420, 517-421, 518-422, 519-423, 520-424, 521-425, 522-426, 523-427, 524-428, 525-429, 526-430, 527-431, 528-432, 529-433, 530-434, 531-435, 532-436, 533-437, 534-438, 535-439, 536-440, 537-441, 538-442, 539-443, 540-444, 541-445, 542-446, 543-447, 544-448, 545-449, 546-450, 547-451, 548-452, 549-453, 550-454, 551-455, 552-456, 553-457, 554-458, 555-459, 556-460, 557-461, 558-462, 559-463, 560-464, 561-465, 562-466, 563-467, 564-468, 565-469, 566-470, 567-471, 568-472, 569-473, 570-474, 571-475, 572-476, 573-477, 574-478, 575-479, 576-480, 577-481, 578-482, 579-483, 580-484, 581-485, 582-486, 583-487, 584-488, 585-489, 586-490, 587-491, 588-492, 589-493, 590-494, 591-495, 592-496, 593-497, 594-498, 595-499, 596-500, 597-501, 598-502, 599-503, 600-504, 601-505, 602-506, 603-507, 604-508, 605-509, 606-510, 607-511, 608-512, 609-513, 610-514, 611-515, 612-516, 613-517, 614-518, 615-519, 616-520, 617-521, 618-522, 619-523, 620-524, 621-525, 622-526, 623-527, 624-528, 625-529, 626-530, 627-531, 628-532, 629-533, 630-534, 631-535, 632-536, 633-537, 634-538, 635-539, 636-540, 637-541, 638-542, 639-543, 640-544, 641-545, 642-546, 643-547, 644-548, 645-549, 646-550, 647-551, 648-552, 649-553, 650-554, 651-555, 652-556, 653-557, 654-558, 655-559, 656-560, 657-561, 658-562, 659-563, 660-564, 661-565, 662-566, 663-567, 664-568, 665-569, 666-570, 667-571, 668-572, 669-573, 670-574, 671-575, 672-576, 673-577, 674-578, 675-579, 676-580, 677-581, 678-582, 679-583, 680-584, 681-585, 682-586, 683-587, 684-588, 685-589, 686-590, 687-591, 688-592, 689-593, 690-594, 691-595, 692-596, 693-597, 694-598, 695-599, 696-600, 697-601, 698-602, 699-603, 700-604, 701-605, 702-606, 703-607, 704-608, 705-609, 706-610, 707-611, 708-612, 709-613, 710-614, 711-615, 712-616, 713-617, 714-618, 715-619, 716-620, 717-621, 718-622, 719-623, 720-624, 721-625, 722-626, 723-627, 724-628, 725-629, 726-630, 727-631, 728-632, 729-633, 730-634, 731-635, 732-636, 733-637, 734-638, 735-639, 736-640, 737-641, 738-642, 739-643, 740-644, 741-645, 742-646, 743-647, 744-648, 745-649, 746-650, 747-651, 748-652, 749-653, 750-654, 751-655, 752-656, 753-657, 754-658, 755-659, 756-660, 757-661, 758-662, 759-663, 760-664, 761-665, 762-666, 763-667, 764-668, 765-669, 766-670, 767-671, 768-672, 769-673, 770-674, 771-675, 772-676, 773-677, 774-678, 775-679, 776-680, 777-681, 778-682, 779-683, 780-684, 781-685, 782-686, 783-687, 784-688, 785-689, 786-690, 787-691, 788-692, 789-693, 790-694, 791-695, 792-696, 793-697, 794-698, 795-699, 796-700, 797-701, 798-702, 799-703, 800-704, 801-705, 802-706, 803-707, 804-708, 805-709, 806-710, 807-711, 808-712, 809-713, 810-714, 811-715, 812-716, 813-717, 814-718, 815-719, 816-720, 817-721, 818-722, 819-723, 820-724, 821-725, 822-726, 823-727, 824-728, 825-729, 826-730, 827-731, 828-732, 829-733, 830-734, 831-735, 832-736, 833-737, 834-738, 835-739, 836-740, 837-741, 838-742, 839-743, 840-744, 841-745, 842-746, 843-747, 844-748, 845-749, 846-750, 847-751, 848-752, 849-753, 850-754, 851-755, 852-756, 853-757, 854-758, 855-759, 856-760, 857-761, 858-762, 859-763, 860-764, 861-765, 862-766, 863-767, 864-768, 865-769, 866-770, 867-771, 868-772, 869-773, 870-774, 871-775, 872-776, 873-777, 874-778, 875-779, 876-780, 877-781, 878-782, 879-783, 880-784, 881-785, 882-786, 883-787, 884-788, 885-789, 886-790, 887-791, 888-792, 889-793, 890-794, 891-795, 892-796, 893-797, 894-798, 895-799, 896-800, 897-801, 898-802, 899-803, 900-804, 901-805, 902-806, 903-807, 904-808, 905-809, 906-810, 907-811, 908-812, 909-813, 910-814, 911-815, 912-816, 913-817, 914-818, 915-819, 916-820, 917-821, 918-822, 919-823, 920-824, 921-825, 922-826, 923-827, 924-828, 925-829, 926-830, 927-831, 928-832, 929-833, 930-834, 931-835, 932-836, 933-837, 934-838, 935-839, 936-840, 937-841, 938-842, 939-843, 940-844, 941-845, 942-846, 943-847, 944-848, 945-849, 946-850, 947-851, 948-852, 949-853, 950-854, 951-855, 952-856, 953-857, 954-858, 955-859, 956-860, 957-861, 958-862, 959-863, 960-864, 961-865, 962-866, 963-867, 964-868, 965-869, 966-870, 967-871, 968-872, 969-873, 970-874, 971-875, 972-876, 973-877, 974-878, 975-879, 976-880, 977-881, 978-882, 979-883, 980-884, 981-885, 982-886, 983-887, 984-888, 985-889, 986-890, 987-891, 988-892, 989-893, 990-894, 991-895, 992-896, 993-897, 994-898, 995-899, 996-900, 997-901, 998-902, 999-903, 1000-904, 1001-905, 1002-906, 1003-907, 1004-908, 1005-909, 1006-910, 1007-911, 1008-912, 1009-913, 1010-914, 1011-915, 1012-916, 1013-917, 1014-918, 1015-919, 1016-920, 1017-921, 1018-922, 1019-923, 1020-924, 1021-925, 1022-926, 1023-927, 1024-928, 1025-929, 1026-930, 1027-931, 1028-932, 1029-933, 1030-934, 1031-935, 1032-936, 1033-937, 1034-938, 1035-939, 1036-940, 1037-941, 1038-942, 1039-943, 1040-944, 1041-945, 1042-946, 1043-947, 1044-948, 1045-949, 1046-950, 1047-951, 1048-952, 1049-953, 1050-954, 1051-955, 1052-956, 1053-957, 1054-958, 1055-959, 1056-960, 1057-961, 1058-962, 1059-963, 1060-964, 1061-965, 1062-966, 1063-967, 1064-968, 1065-969, 1066-970, 1067-971, 1068-972, 1069-973, 1070-974, 1071-975, 1072-976, 1073-977, 1074-978, 1075-979, 1076-980, 1077-981, 1078-982, 1079-983, 1080-984, 1081-985, 1082-986, 1083-987, 1084-988, 1085-989, 1086-990, 1087-991, 1088-992, 1089-993, 1090-994, 1091-995, 1092-996, 1093-997, 1094-998, 1095-999, 1096-1000, 1097-1001, 1098-1002, 1099-1003, 1100-1004, 1101-1005, 1102-1006, 1103-1007, 1104-1008, 1105-1009, 1106-1010, 1107-1011, 1108-1012, 1109-1013, 1110-1014, 1111-1015, 1112-1016, 1113-1017, 1114-1018, 1115-1019, 1116-1020, 1117-1021, 1118-1022, 1119-1023, 1120-1024, 1121-1025, 1122-1026, 1123-1027, 1124-1028, 1125-1029, 1126-1030, 1127-1031, 1128-1032, 1129-1033, 1130-1034, 1131-1035, 1132-1036, 1133-1037, 1134-1038, 1135-1039, 1136-1040, 1137-1041, 1138-1042, 1139-1043, 1140-1044, 1141-1045, 1142-1046, 1143-1047, 1144-1048, 1145-1049, 1146-1050, 1147-1051, 1148-1052, 1149-1053, 1150-1054, 1151-1055, 1152-1056, 1153-1057, 1154-1058, 1155-1059, 1156-1060, 1157-1061, 1158-1062, 1159-1063, 1160-1064, 1161-1065, 1162-1066, 1163-1067, 1164-1068, 1165-1069, 1166-1070, 1167-1071, 1168-1072, 1169-1073, 1170-1074, 1171-1075, 1172-1076, 1173-1077, 1174-1078, 1175-1079, 1176-1080, 1177-1081, 1178-1082, 1179-1083, 1180-1084, 1181-1085, 1182-1086, 1183-1087, 1184-1088, 1185-1089, 1186-1090, 1187-1091, 1188-1092, 1189-1093, 1190-1094, 1191-1095, 1192-1096, 1193-1097, 1194-1098, 1195-1099, 1196-1100, 1197-1101, 1198-1102, 1199-1103, 1200-1104, 1201-1105, 1202-1106, 1203-1107, 1204-1108, 1205-1109, 1206-1110, 1207-1111, 1208-1112, 1209-1113, 1210-1114, 1211-1115, 1212-1116, 1213-1117, 1214-1118, 1215-1119, 1216-1120, 1217-1121, 1218-1122, 1219-1123, 1220-1124, 1221-1125, 1222-1126, 1223-1127, 1224-1128, 1225-1129, 1226-1130, 1227-1131, 1228-1132, 1229-1133, 1230-1134, 1231-1135, 1232-1136, 1233-1137, 1234-1138, 1235-1139, 1236-1140, 1237-1141, 1238-1142, 1239-1143, 1240-1144, 1241-1145, 1242-1146, 1243-1147, 1244-1148, 1245-1149, 1246-1150, 1247-1151, 1248-1152, 1249-1153, 1250-1154, 1251-1155, 1252-1156, 1253-1157, 1254-1158, 1255-1159, 1256-1160, 1257-1161, 1258-1162, 1259-1163, 1260-1164, 1261-1165, 1262-1166, 1263-1167, 1264-1168, 1265-1169, 1266-1170, 1267-1171, 1268-1172, 1269-1173, 1270-1174, 1271-1175, 1272-1176, 1273-1177, 1274-1178, 1275-1179, 1276-1180, 1277-1181, 1278-1182, 1279-1183, 1280-1184, 1281-1185, 1282-1186, 1283-1187, 1284-1188, 1285-1189, 1286-1190, 1287-1191, 1288-1192, 1289-1193, 1290-1194, 1291-1195, 1292-1196, 1293-1197, 1294-1198, 1295-1199, 1296-1200, 1297-1201, 1298-1202, 1299-1203, 1300-1204, 1301-1205, 1302-1206, 1303-1207, 1304-1208, 1305-1209, 1306-1210, 1307-1211, 1308-1212, 1309-1213, 1310-1214, 1311-1215, 1

DOCKETED ITEMS

F. Security, medical, emergency & fire protection plans

7903050662 Forwards addl response to 709506 meeting minutes re NRCSD Fire Security analysis Includes proposed design for fire protection sys Requests early meeting to discuss responses
GILLESAND, J.E. Tennessee Valley Authority 79/03/22 Up

G. Adjudicatory correspondence

7903040874 Requests adoption of de minimus theory of Perkins ABL Certificate of Rev. encl.
SWINDELL, H.W. - UNLACED, L.E. QUINTERMAN, A.H. Tennessee Valley Authority 79/04/06 Up

7903104110 Response to ALAB-509 re radon emissions & de minimus theory from Perkins second Certificate of Rev. encl.
SCINTO, J. Hearings Division 79/04/11 Up

7903140359 Response to 790406 brief of Philadelphia Electric Co. PERMA & Atlantic City (N) Electric Co re de minimus theory Certificate of Rev. encl.
KOPPEL, C.E. Citizens for Safe Environment 79/04/11 Up

7903140328 Request for consolidation of five intervenor groups re radon emissions issue Parties have until 790328 in which to file for summary disposition
DUFFIN, H.C. Atomic Safety and Licensing Appeal Panel 79/04/25 Up

J. Insurance & indemnity information

7903070497 Confirms increased liability limit to \$124,000,000 for policies PP-51,25,42,76,82,100,111,140,146,155,160,164,170-174,176,179,180,183,185,186,187,188,189,190,193,193,194,195,197,198,200,201,204,206,207,208,210,212,214,215,216,217,218,219,220,221,222,223,224,225,226,227,228,229,230,231,232,233,234,235,236,237,238,239,240,241,242,243,244,245,246,247,248,249,250,251,252,253,254,255,256,257,258,259,260,261,262,263,264,265,266,267,268,269,270,271,272,273,274,275,276,277,278,279,280,281,282,283,284,285,286,287,288,289,290,291,292,293,294,295,296,297,298,299,300,301,302,303,304,305,306,307,308,309,310,311,312,313,314,315,316,317,318,319,320,321,322,323,324,325,326,327,328,329,330,331,332,333,334,335,336,337,338,339,340,341,342,343,344,345,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360,361,362,363,364,365,366,367,368,369,370,371,372,373,374,375,376,377,378,379,380,381,382,383,384,385,386,387,388,389,390,391,392,393,394,395,396,397,398,399,400,401,402,403,404,405,406,407,408,409,410,411,412,413,414,415,416,417,418,419,420,421,422,423,424,425,426,427,428,429,430,431,432,433,434,435,436,437,438,439,440,441,442,443,444,445,446,447,448,449,450,451,452,453,454,455,456,457,458,459,460,461,462,463,464,465,466,467,468,469,470,471,472,473,474,475,476,477,478,479,480,481,482,483,484,485,486,487,488,489,490,491,492,493,494,495,496,497,498,499,500,501,502,503,504,505,506,507,508,509,510,511,512,513,514,515,516,517,518,519,520,521,522,523,524,525,526,527,528,529,530,531,532,533,534,535,536,537,538,539,540,541,542,543,544,545,546,547,548,549,550,551,552,553,554,555,556,557,558,559,560,561,562,563,564,565,566,567,568,569,570,571,572,573,574,575,576,577,578,579,580,581,582,583,584,585,586,587,588,589,590,591,592,593,594,595,596,597,598,599,600,601,602,603,604,605,606,607,608,609,610,611,612,613,614,615,616,617,618,619,620,621,622,623,624,625,626,627,628,629,630,631,632,633,634,635,636,637,638,639,640,641,642,643,644,645,646,647,648,649,650,651,652,653,654,655,656,657,658,659,660,661,662,663,664,665,666,667,668,669,670,671,672,673,674,675,676,677,678,679,680,681,682,683,684,685,686,687,688,689,690,691,692,693,694,695,696,697,698,699,700,701,702,703,704,705,706,707,708,709,710,711,712,713,714,715,716,717,718,719,720,721,722,723,724,725,726,727,728,729,730,731,732,733,734,735,736,737,738,739,740,741,742,743,744,745,746,747,748,749,750,751,752,753,754,755,756,757,758,759,760,761,762,763,764,765,766,767,768,769,770,771,772,773,774,775,776,777,778,779,780,781,782,783,784,785,786,787,788,789,790,791,792,793,794,795,796,797,798,799,800,801,802,803,804,805,806,807,808,809,810,811,812,813,814,815,816,817,818,819,820,821,822,823,824,825,826,827,828,829,830,831,832,833,834,835,836,837,838,839,840,841,842,843,844,845,846,847,848,849,850,851,852,853,854,855,856,857,858,859,860,861,862,863,864,865,866,867,868,869,870,871,872,873,874,875,876,877,878,879,880,881,882,883,884,885,886,887,888,889,890,891,892,893,894,895,896,897,898,899,900,901,902,903,904,905,906,907,908,909,910,911,912,913,914,915,916,917,918,919,920,921,922,923,924,925,926,927,928,929,930,931,932,933,934,935,936,937,938,939,940,941,942,943,944,945,946,947,948,949,950,951,952,953,954,955,956,957,958,959,960,961,962,963,964,965,966,967,968,969,970,971,972,973,974,975,976,977,978,979,980,981,982,983,984,985,986,987,988,989,990,991,992,993,994,995,996,997,998,999,1000,1001,1002,1003,1004,1005,1006,1007,1008,1009,1010,1011,1012,1013,1014,1015,1016,1017,1018,1019,1020,1021,1022,1023,1024,1025,1026,1027,1028,1029,1030,1031,1032,1033,1034,1035,1036,1037,1038,1039,1040,1041,1042,1043,1044,1045,1046,1047,1048,1049,1050,1051,1052,1053,1054,1055,1056,1057,1058,1059,1060,1061,1062,1063,1064,1065,1066,1067,1068,1069,1070,1071,1072,1073,1074,1075,1076,1077,1078,1079,1080,1081,1082,1083,1084,1085,1086,1087,1088,1089,1090,1091,1092,1093,1094,1095,1096,1097,1098,1099,1100,1101,1102,1103,1104,1105,1106,1107,1108,1109,1110,1111,1112,1113,1114,1115,1116,1117,1118,1119,1120,1121,1122,1123,1124,1125,1126,1127,1128,1129,1130,1131,1132,1133,1134,1135,1136,1137,1138,1139,1140,1141,1142,1143,1144,1145,1146,1147,1148,1149,1150,1151,1152,1153,1154,1155,1156,1157,1158,1159,1160,1161,1162,1163,1164,1165,1166,1167,1168,1169,1170,1171,1172,1173,1174,1175,1176,1177,1178,1179,1180,1181,1182,1183,1184,1185,1186,1187,1188,1189,1190,1191,1192,1193,1194,1195,1196,1197,1198,1199,1200,1201,1202,1203,1204,1205,1206,1207,1208,1209,1210,1211,1212,1213,1214,1215,1216,1217,1218,1219,1220,1221,1222,1223,1224,1225,1226,1227,1228,1229,1230,1231,1232,1233,1234,1235,1236,1237,1238,1239,1240,1241,1242,1243,1244,1245,1246,1247,1248,1249,1250,1251,1252,1253,1254,1255,1256,1257,1258,1259,1260,1261,1262,1263,1264,1265,1266,1267,1268,1269,1270,1271,1272,1273,1274,1275,1276,1277,1278,1279,1280,1281,1282,1283,1284,1285,1286,1287,1288,1289,1290,1291,1292,1293,1294,1295,1296,1297,1298,1299,1300,1301,1302,1303,1304,1305,1306,1307,1308,1309,1310,1311,1312,1313,1314,1315,1316,1317,1318,1319,1320,1321,1322,1323,1324,1325,1326,1327,1328,1329,1330,1331,1332,1333,1334,1335,1336,1337,1338,1339,1340,1341,1342,1343,1344,1345,1346,1347,1348,1349,1350,1351,1352,1353,1354,1355,1356,1357,1358,1359,1360,1361,1362,1363,1364,1365,1366,1367,1368,1369,1370,1371,1372,1373,1374,1375,1376,1377,1378,1379,1380,1381,1382,1383,1384,1385,1386,1387,1388,1389,1390,1391,1392,1393,1394,1395,1396,1397,1398,1399,1400,1401,1402,1403,1404,1405,1406,1407,1408,1409,1410,1411,1412,1413,1414,1415,1416,1417,1418,1419,1420,1421,1422,1423,1424,1425,1426,1427,1428,1429,1430,1431,1432,1433,1434,1435,1436,1437,1438,1439,1440,1441,1442,1443,1444,1445,1446,1447,1448,1449,1450,1451,1452,1453,1454,1455,1456,1457,1458,1459,1460,1461,1462,1463,1464,1465,1466,1467,1468,1469,1470,1471,1472,1473,1474,1475,1476,1477,1478,1479,1480,1481,1482,1483,1484,1485,1486,1487,1488,1489,1490,1491,1492,1493,1494,1495,1496,1497,1498,1499,1500,1501,1502,1503,1504,1505,1506,1507,1508,1509,1510,1511,1512,1513,1514,1515,1516,1517,1518,1519,1520,1521,1522,1523,1524,1525,1526,1527,1528,1529,1530,1531,1532,1533,1534,1535,1536,1537,1538,1539,1540,1541,1542,1543,1544,1545,1546,1547,1548,1549,1550,1551,1552,1553,1554,1555,1556,1557,1558,1559,1560,1561,1562,1563,1564,1565,1566,1567,1568,1569,1570,1571,1572,1573,1574,1575,1576,1577,1578,1579,1580,1581,1582,1583,1584,1585,1586,1587,1588,1589,1590,1591,1592,1593,1594,1595,1596,1597,1598,1599,1600,1601,1602,1603,1604,1605,1606,1607,1608,1609,1610,1611,1612,1613,1614,1615,1616,1617,1618,1619,1620,1621,1622,1623,1624,1625,1626,1627,1628,1629,1630,1631,1632,1633,1634,1635,1636,1637,1638,1639,1640,1641,1642,1643,1644,1645,1646,1647,1648,1649,1650,1651,1652,1653,1654,1655,1656,1657,1658,1659,1660,1661,1662,1663,1664,1665,1666,1667,1668,1669,1670,1671,1672,1673,1674,1675,1676,1677,1678,1679,1680,1681,1682,1683,1684,1685,1686,1687,1688,1689,1690,1691,1692,1693,1694,1695,1696,1697,1698,1699,1700,1701,1702,1703,1704,1705,1706,1707,1708,1709,1710,1711,1712,1713,1714,1715,1716,1717,1718,1719,1720,1721,1722,1723,1724,1725,1726,1727,1728,1729,1730,1731,1732,1733,1734,1735,1736,1737,1738,1739,1740,1741,1742,1743,1744,1745,1746,1747,1748,1749,1750,1751,1752,1753,1754,1755,1756,1757,1758,1759,1760,1761,1762,1763,1764,1765,1766,1767,1768,1769,1770,1771,1772,1773,1774,1775,1776,1777,1778,1779,1780,1781,1782,1783,1784,1785,1786,1787,1788,1789,1790,1791,1792,1793,1794,1795,1796,1797,1798,1799,1800,1801,1802,1803,1804,1805,1806,1807,1808,1809,1810,1811,1812,1813,1814,1815,1816,1817,1818,1819,1820,1821,1822,1823,1824,1825,1826,1827,1828,1829,1830,1831,1832,1833,1834,1835,1836,1837,1838,1839,1840,1841,1842,1843,1844,1845,1846,1847,1848,1849,1850,1851,1852,1853,1854,1855,1856,1857,1858,1859,1860,1861,1862,1863,1864,1865,1866,1867,1868,1869,1870,1871,1872,1873,1874,1875,1876,1877,1878,1879,1880,1881,1882,1883,1884,1885,1886,1887,1888,1889,1890,1891,1892,1893,1894,1895,1896,1897,1898,1899,1900,1901,1902,1903,1904,1905,1906,1907,1908,1909,1910,1911,1912,1913,1914,1915,1916,1917,1918,1919,1920,1921,1922,1923,1924,1925,1926,1927,1928,1929,1930,1931,1932,1933,1934,1935,1936,1937,1938,1939,1940,1941,1942,1943,1944,1945,1946,1947,1948,1949,1950,1951,1952,1953,1954,1955,1956,1957,1958,1959,1960,1961,1962,1963,1964,1965,1966,1967,1968,1969,1970,1971,1972,1973,1974,1975,1976,1977,1978,1979,1980,1981,1982,1983,1984,1985,1986,1987,1988,1989,1990,1991,1992,1993,1994,1995,1996,1997,1998,1999,2000,2001,2002,2003,2004,2005,2006,2007,2008,2009,2010,2011,2012,2013,2014,2015,2016,2017,2018,2019,2020,2021,2022,2023,2024,2025,2026,2027,2028,2029,2030,2031,2032,2033,2034,2035,2036,2037,2038,2039,2040,2041,2042,2043,2044,2045,2046,2047,2048,2049,2050,2051,2052,2053,2054,2055,2056,2057,2058,2059,2060,2061,2062,2063,2064,2065,2066,2067,2068,2069,2070,2071,2072,2073,2074,2075,2076,2077,2078,2079,2080,2081,2082,2083,2084,2085,2086,2087,2088,2089,2090,2091,2092,2093,2094,2095,2096,2097,2098,2099,2100,2101,2102,2103,2104,2105,2106,2107,2108,2109,2110,2111,2112,2113,2114,2115,2116,2117,2118,2119,2120,2121,2122,2123,2124,2125,2126,2127,2128,2129,2130,2131,2132,2133,2134,2135,2136,2137,2138,2139,2140,2141,2142,2143,2144,2145,2146,2147,2148,2149,2150,2151,2152,2153,2154,2155,2156,2157,2158,2159,2160,2161,2162,2163,2164,2165,2166,2167,2168,2169,2170,2171,2172,2173,2174,2175,2176,2177,2178,2179,2180,2181,2182,2183,2184,2185,2186,2187,2188,2189,2190,2191,2192,2193,2194,2195,2196,2197,2198,2199,2200,2201,2202,2203,2204,2205,2206,2207,2208,2209,2210,2211,2212,2213,2214,2215,2216,2217,2218,2219,2220,2221,2222,2223,2224,2225,2226,2227,2228,2229,2230,2231,2232,2233,2234,2235,2236,2237,2238,2239,2240,2241,2242,2243,2244,2245,2246,2247,2248,2249,2250,2251,2252,2253,2254,2255,2256,2257,2258,2259,2260,2261,2262,2263,2264,2265,2266,2267,2268,2269,2270,2271,2272,2273,2274,2275,2276,2277,2278,2279,2280,2281,2282,2283,2284,2285,2286,2287,2288,2289,2290,2291,2292,2293,2294,2295,2296,2297,2298,2299,2300,2301,2302,2303,2304,2305,2306,2307,2308,2309,2310,2311,2312,2313,2314,2315,2316,2317,2318,2319,2320,2321,2322,2323,2324,2325,2326,2327,2328,2329,2330,2331,2332,2333,2334,2335,2336,2337,2338,2339,2340,2341,2342,2343,2344,2345,2346,2347,2348,2349,2350,2351,2352,2353,2354,2355,2356,2357,2358,2359,2360,2361,2362,2363,2364,2365,2366,2367,2368,2369,2370,2371,2372,2373,2374,2375,2376,2377,2378,2379,2380,2381,2382,2383,2384,2385,2386,2387,2388,2389,2390,2391,2392,2393,2394,2395,2396,2397,2398,2399,2400,2401,2402,2403,2404,2405,2406,2407,2408,2409,2410,2411,2412,2413,2414,2415,2416,2417,2418,2419,2420,2421,2422,2423,2424,2425,2426,2427,2428,2429,2430,2431,2432,2433,2434,2435,2436,2437,2438,2439,2440,2441,2442,2443,2444,2445,2446,2447,2448,2449,2450,2451,2452,2453,2454,2455,2456,2457,2458,2459,2460,2461,2462,2463,2464,2465,2466,2467,2468,2469,2470,2471,2472,2473,2474,2475,2476,2477,2478,2479,2480,2481,2482,2483,2484,2485,2486,2487,2488,2489,2490,2491,2492,2493,2494,2495,2496,2497,2498,2499,2500,2501,2502,2503,2504,2505,2506,2507,2508,2509,2510,2511,2512,2513,2514,2515,2516,2517,2518,2519,2520,2521,2522,2523,2524,2525,2526,2527,2528,2529,2530,2531,2532,2533,2534,2535,2536,2537,2538,2539,2540,2541,2542,2543,2544,2545,2546,2547,2548,2549,2550,2551,2552,2553,2554,2555,2556,2557,2558,2559,2560,2561,2562,2563,2564,2565,2566,2567,2568,2569,2570,2571,2572,2573,2574,2575,2576,2577,2578,2579,2580,2581,2582,2583,2584,2585,2586,2587,2588,2589,2590,2591,2592,2593,2594,2595,2596,2597,2598,2599,2600,2601,2602,2603,2604,2605,2606,2607,2608,2609,2610,2611,2612,2613,2614,2615,2616,2617,2618,2619,2620,2621,2622,2623,2624,2625,2626,2627,2628,2629,2630,2631,2632,2633,2634,2635,2636,2637,2638,2639,2640,2641,2642,2643,2644,2645,2646,2647,2648,2649,2650,2651,2652,2653,2654,2655,2656,2657,2658,2659,2660,2661,2662,2663,2664,2665,2666

DOCKETED ITEMS

263

F. Security, medical, emergency & fire protection plans

7905030462 Forwards and responses to 7905024 meeting minutes re STRIDE fire hazard analysis. Includes proposed design changes to fire protection and requests early meeting to discuss responses
GILLESLAND, J. E. Tennessee Valley Authority 79/05/20 App

G. Adjudication correspondence

7905040876 Request adoption of de minimus theory of Perkin ABLS Certificate of Etc and
DANBER, H. E., WALLACE, L. E., SUTTERMAN, A. H. Tennessee Valley Authority 79/04/08 App

7905104188 Response to ALAB-SDV re radon emissions & de minimus theory from Perkins record Certificate of Etc and
SCHEIDT, J. F. Hearings Division 79/04/11 App

7905100189 Response to 790404 brief of Philadelphia Electric Co, PERKINS & Atlantic City (N) Electric Co re de minimus theory Certificate of Etc and
NEPHEW, C. E. Citizens For Safe Environment 79/04/11 App

7905140322 Notice of consolidation of fire intervenor groups re radon emissions issue Perkins have until 790520 in which to file for summary disposition
DUFF, D. L. Atomic Safety and Licensing Appeal Panel 79/04/25 App

J. Insurance & indemnity information

7905070497 Confirms increased liability limit to \$126,000,000 for policies #1, 25, 43, 79, 80, 100, 111, 180, 146, 181, 161, 146, 170, 173, 174, 178, 180, 182, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 205, 207, 208, 210, 212, 214, 215, & others
OMT, T. C. American Nuclear Insurers 79/05/01 App

7905070502 Confirms increase in liability limit to \$26,000,000 for policies #22, 24, 29, 37, 39, 46, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 75, 77, 79, 80, 86, 87, 88, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

H. Periodic operating reports & related correspondence

7905100189 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/05/23 App

7905100072 Forwards IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 re 790522-08 No noncompliance noted
HARRIS, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 App

--7905100091 IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 re 790522-08 No noncompliance noted. Major areas inspected: concrete foundations of spray pond areas; implemented by Civil Engineering Manual
HARRIS, T. E. Region 2, Atlanta, Office of the Director
HARRIS, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 App

7905100422 Forwards IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 re 790522-08 No noncompliance noted
HARRIS, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/22 App

--7905100431 IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 re 790522-08 No noncompliance noted. Major areas inspected: concrete foundations of spray pond areas; implemented by Civil Engineering Manual
HARRIS, T. E. Region 2, Atlanta, Office of the Director
HARRIS, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/22 App

7905100448 Forwards IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 re 790522-08 No noncompliance noted
HARRIS, C. E. Region 2, Atlanta, Office of the Director 79/04/26 App

--7905100507 IE Insp Repts 50-518/79-06, 50-519/79-06, 50-520/79-06 & 50-521/79-06 re 790522-08 No noncompliance noted. Major areas inspected: concrete foundations of spray pond areas; implemented by Civil Engineering Manual
HARRIS, T. E. Region 2, Atlanta, Office of the Director
HARRIS, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/26 App

7905100568 Forwards IE Bulletin 79-07, "Stress Stress Analysis of Safety-Related Piping"
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/04/14 App

7905100570 Forwards IE Bulletin 79-08, "Review of Operational Errors & By Misalignments Identified During THE Incident"
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/04/14 App

7905100588 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Heat Power Reactors Identified During THE Incident"
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/04/14 App

7905100591 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets"
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/04/14 App

7905100592 Forwards IE Bulletin 79-09, "Failures of SE Type AM-2 Circuit Breaker in Safety-Related Sys. - Licensee action required"
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/04/17 App

7905100597 Forwards IE Bulletin 79-09, "Review of Operational Errors & By Misalignments Identified During THE Incident"
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/04/17 App

7905100598 Forwards IE Bulletin 79-09, "Review of Operational Errors & By Misalignments Identified During THE Incident"
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/04/17 App

I. Periodic operating reports & related correspondence

7905100598 Forwards "Economic Monitoring & Mitigation Repts" Apr 1979
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/05/23 App

--7905100599 "Economic Monitoring & Mitigation Repts" Apr 1979
O'NEILL, J. P. Region 2, Atlanta, Office of the Director 79/05/23 App

J. Reportable occurrences, LERs & related correspondence

7905100478 Forwards final report of reportable condition re BMR & BMR local control panels (BMR & BMR)
GILLESLAND, J. E. Tennessee Valley Authority 79/04/23 App

--7905100482 Reportable condition re 790522-08. Defect identified in BMR panel BMR-2022. Caused by installation of nonqualified type relay. Procedures revised & QA program modified
GILLESLAND, J. E. Tennessee Valley Authority 79/04/23 App

DOCKET 518-521 HARTSVILLE NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7905080448 Discussed still position on leak testing pressure & temp requirements of ACI Spec 318 & 319 for piping to be embedded in concrete. Revision to RMR re embedded piping will be implemented immediately.
GILLESLAND, J. E. Tennessee Valley Authority 79/05/23 App

DOCKETED ITEMS

F Security, medical, emergency & fire protection plans

790300462 Forwards add response to 790206 meeting minutes re BTRIDE
fire hazards analysis includes proposed design changes to
fire protection and suggests early meeting to discuss
responses
GILLENAND, J E Tennessee Valley Authority 79/03/20 9pp

G Adjudication correspondence

7903003974 Requests adoption of de minimus theory of Partine AGC.
Certificate of Gov encl.
BENGDH, H S Tennessee Valley Authority. 79/04/08 10pp

790310480 Response to ALAD-809 re radon emission & de minimus theory
Plan Partine record Certificate of Gov encl
ACEDIG, J F Hearings Division 79/04/11 45pp

790310589 Response to 790404 brief of Philadelphia Electric Co. REBEO &
Atlantic City INU Electric Co re de minimus theory
Certificate of Gov encl.
MDFORD, C R Citizens for Safe Environment 79/04/11 8pp

790310330 Request for consolidation of five intervenor groups re radon
emissions. Issues Partine have until 790625 in which to file
for summary judgment.
DUPLO, R E Atomic Safety and Licensing Appeal Panel 79/04/23
13pp

J Insurance & indemnity information

790300947 Confirms increased liability limit to \$154,000,000 for
policy #F-22, 26, 27, 28, 29, 44, 46, 47, 49, 50, 51, 52, 53, 54, 56, 58,
59, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 75, 77, 78, 79, 80, 84, 85,
86, 90, 91, 92, 93, 94, 95 & 96.
QUATROCHI, J American Nuclear Insurers 79/03/01 1p

790300982 Confirms increase in liability limit to \$20,000,000 for
policy #F-22, 26, 27, 28, 29, 44, 46, 47, 49, 50, 51, 52, 53, 54, 56, 58,
59, 60, 61, 64, 66, 67, 68, 69, 70, 71, 72, 74, 75, 77, 78, 79, 80, 84, 85,
86, 90, 91, 92, 93, 94, 95 & 96.
ROBERTS, D H Mutual Atomic Energy Liability Underwriters 79/03/01
10pp

O Inspection reports, IE Bulletins & correspondence

790300201 Forwards IE Info Mktter 79-36, "Stress Analysis of
Safety-Related Piping"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/03/23 2pp

790300207 Forwards IE Insp Repts 30-318/79-04, 30-319/79-04,
30-325/79-04 & 30-321/79-06 as 790206-2R No noncompliance
noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/03/23 2pp

790300208 IE Insp Repts 30-318/79-04, 30-319/79-04, 30-320/79-04 &
30-321/79-04 as 790206-2R No noncompliance noted. Major areas
inspected, consist activities, IE circulars & QA program as
implemented by Const Engineering Manual.
BURDETTE, T E Region 2, Atlanta, Office of the Director,
79/03/23 4pp

790300422 Forwards IE Insp Repts 30-318/79-07, 30-319/79-07,
30-320/79-07 & 30-321/79-07 as 790207-6R No noncompliance
noted
MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering
Support Branch 79/04/02 2pp

790300432 IE Insp Repts 30-318/79-07, 30-319/79-07, 30-320/79-07 &
30-321/79-07 as 790207-6R No noncompliance noted. Major
areas inspected, consist activities, IE circulars & QA program as
implemented by Const Engineering Manual.
BURNETT, T E Region 2, Atlanta, Office of the Director,
79/04/02 4pp

790300449 Forwards IE Insp Repts 30-318/79-08, 30-319/79-08,
30-320/79-08 & 30-321/79-08 as 790208-032R No noncompliance
noted
MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/05 4pp

790300450 IE Insp Repts 30-318/79-08, 30-319/79-08, 30-320/79-08 &
30-321/79-08 as 790208-032R No noncompliance noted. Major
areas inspected, consist activities, IE circulars & QA program as
implemented by Const Engineering Manual.
BURNETT, T E Region 2, Atlanta, Office of the Director,
79/04/05 4pp

790300206 Forwards IE Bulletin 79-07, "Stress Analysis of
Safety-Related Piping" Licensee action required
O'REILLY, J P Region 2, Atlanta, Office of the Director,
79/04/14 2pp

790300423 Forwards IE Bulletin 79-08, "Review of Operational Errors &
Key Misalignments Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 2pp

790310509 Forwards IE Bulletin 79-08, "Events Relevant to Selling
Power Reactors Identified During TMI Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/14 1p

790300341 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Brackets"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 1p

790300517 Forwards IE Bulletin 79-08, "Failures of BC Type AM-2
Circuit Breaker in Safety-Related Bus" Licensee action
required
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/17 2pp

790300547 Forwards IE Bulletin 79-08, Revision 1, "Review of
Operational Errors & Key Misalignments Identified During TMI
Incident"
O'REILLY, J P Region 2, Atlanta, Office of the Director
79/04/18 2pp

790300620 Submits supplemental responses to IE Bulletin 79-07 Original
response submitted 780123 Provides addl info received from
manufacturer & describes plans in area of electrical
generators
GILLENAND, J E Tennessee Valley Authority 79/04/27 5pp

R Periodic operating reports & related correspondence

790310206 Forwards "Socioeconomic Monitoring & Mitigation Rep"
Apr 1979. Future rep will be prepared semiannually
GILLENAND, J E Tennessee Valley Authority 79/05/09 1p

790310204 Forwards "Socioeconomic Monitoring & Mitigation Rep" Apr 1979
as Tennessee Valley Authority 79/04/20 4pp

S Reportable occurrences, LERs & related correspondence

790310478 Forwards final rept of reportable condition re BWR-6 IPDS
local control panels INCC 00-79-01
GILLENAND, J E Tennessee Valley Authority 79/04/03 1p

790310482 Reportable condition on 790206-2R determined that delay
waited in IPDS panel 102-0020. Caused by installation of
nonqualified type relay. Procedures revised & QA program
modified
Tennessee Valley Authority 79/04/03 2pp

DOCKET BYN-30-322 SHADY NUCLEAR POWER PROJECT, UNIT 1

A Application/construction stage documents & correspondence

790300201 Forwards summary of 790227 meeting of Shady River Indian's
representatives w/ House Committee on Interior & Insular
Affairs.
LEBEN, P H Environmental Projects Branch 2 79/04/10 1p

790300202 Summary of 790227 meeting w/representatives of Indian tribes
in Washington DC re study, funded by Bureau of Indian
Affairs, of potential impact of facility on local hydrology,
socioeconomic conditions & Indian fisheries.
HARMER, G Office of Congressional Affairs 79/03/03 5pp

790300626 Discusses delays in issuance of OF in response to 790218
telegram to President Carter
RITZ, J F Light Water Reactors Branch 1 79/04/14 2pp

790300627 Approves request to withhold from public disclosure 790203
& 79016, lists re magnetoplastic data.
RITZ, J F Light Water Reactors Branch 1 79/04/09 4pp

790300700 Forwards "Division Assessment, QA Plant Assessment" in
response to NRC 780403 request. Recommends new re mgmt
improvements in Agreement in principle mitigation plan. Encl
available in Control Files.
BERLAND, S Agriculture Dept of 79/04/02 2pp

DOCKETED ITEMS

255

7905160347 Forwards "Report of Geological Investigations in 1978-1979," Vols 2 & 3. Discusses deferred & supplemental sections.
MDCJA, J.E. Puget Sound Power & Light Co. 79/05/10 7pp

--7905160355 "Report of Geological Investigations in 1978-1979" Vols 2 & 3
Full covered drawings encl.
Puget Sound Power & Light Co. 79/05/10, 20pp

7905103083 Responds to 790530 request for add geological info Forwards add supportive mat'l to "Report of Geologic Investigations in 1978-1979." Extensive geologic investigations confirm site suitability. Rept encl.
MDCJA, J.E. Puget Sound Power & Light Co. 79/05/25 100pp

B. Adjudicatory correspondence

7905140159 Motion for leave to file interim statement of issues three days out of time on 790512
BUDCH, R.W. Evergreen Legal Services. HEARN, D.S. Hearn, Donald S. 79/05/12. 3pp.

--7905140161 Intervenor Tribes interim statement of issues in response to 790508 order.
BUDCH, R.W. Evergreen Legal Services. HEARN, D.S. Hearn, Donald S. 79/05/12 3pp.

7905230918 Forewarn on Board/Coalition for Safe Power's statement of issues, submitted per 790508 order Follows applicant 790522 revised statement. Discusses various issues. Certificate of Rec encl.
STACHEN, E.G. Coalition for Safe Power 79/05/16 4pp.

7905101013 Forwards request for Board notification re non-safety-grade equipment to mitigate transients
BUDCH, J.F. Hearings Division 79/04/02 3pp

--7905101026 Board notification re assessment re non-safety-grade equipment to mitigate transients
VASSALLO, D.B. Assistant Director for Light Water Reactors 79/05/29 3pp.

--7905101018 Board notification, recent issue on non-safety-grade equipment to mitigate transients More info is required
TECHNICAL, R.L. Assistant Director for Reactor Safety 79/05/16 3pp.

7905290125 Forwards policy statement re NUREG/CR-0400, reactor safety study & survey of uses made of WASH-1400 site encl.
BLANCH, R.L. Branch 1. 79/04/04 1p.

7905140030 Order for agenda of conference scheduled for 790426-28.
SCALE, V.B. Atomic Safety and Licensing Board Panel. 79/04/10 7pp

7905290180 Advises that recommended order of OR Energy Facility Siting Council hearing examiner will be issued in Aug 1979 rather than Aug 1978.
BANDY, R.H. Oregon State of 79/04/17. 1p

I. Financial Information

7905290439 Forwards add financial info, as requested by NRC 790408 ltr. Info includes mat'l re testimony & exhibits in next month. Rept encl.
MDCJA, J.E. Puget Sound Power & Light Co. 79/05/17 350pp

--7905290440 "Annual Financial Rept 1978."
Puget Sound Power & Light Co. 79/05/31. 43pp.

--7905290470 "Annual Financial Rept 1978"
Pacific Power Co. 78/12/31. 35pp

7905103272 Responds to 790405 ltr. Forwards financial info, form REC 10-N, prospectus, testimony, exhibits & "Portland GE Pro Forma Sources of Funds for Bay-Wide Const. Expenditures & Capital Structure." Encl in Central Files.
MDCJA, J.E. Puget Sound Power & Light Co. 79/05/25. 400pp.

T. Hearing transcripts on non-antitrust matters

7905140014 Transcript of 790424 meeting in Seattle, WA, by (1, 778-15, 983, SCALE, V.B.; LINDENBERG, S.; HOPPER, F.P. Atomic Safety and Licensing Board Panel. 79/04/24. 17pp.

DOCKET 871N-50-522 SHAWET NUCLEAR POWER PROJECT, UNIT 2

A. Application/contraction stage documents & correspondence

7905050211 Forwards summary of 790227 meeting of Skagit River Indian's representatives w/ House Committee on Interior & Insular Affairs.
LEEDER, H. Environmental Projects Branch 2 79/04/10 1p

--7905050264 Summary of 790227 meeting w/ representatives of Indian tribes in Washington, DC re study, funded by Bureau of Indian Affairs, of potential impact of facility on local hydrogeologic/economic conditions & Indian fisheries.
HARRISON, C. Office of Congressional Affairs 79/05/05 2pp

7905020804 Discusses delays in issuance of CP in response to 790212 telegram to President Carter.
STOLZ, J.F. Light Water Reactors Branch 1 79/04/16 3pp

7905230887 Approves request to withhold from public disclosure 790523 & 790466 ltr re aeromagnetic data.
STOLZ, J.F. Light Water Reactors Branch 1 79/04/30 4pp

7905050070 Forwards "Environ Assessment, DCA Plant Assessment," in response to NRC 790508 request. Recommends add re mat'l requirements in applicant's mitigation plan Encl available in Central Files.
DESLAND, S. Agriculture Dept of 79/05/02 2pp

7905140347 Forwards "Report of Geological Investigations in 1978-1979," Vols 2 & 3. Discusses deferred & supplemental sections.
MDCJA, J.E. Puget Sound Power & Light Co. 79/05/10 7pp

--7905140355 "Report of Geological Investigations in 1978-1979" Vols 2 & 3
Full covered drawings encl.
Puget Sound Power & Light Co. 79/05/10 20pp

7905103083 Responds to 790530 request for add geological info Forwards add supportive mat'l to "Report of Geologic Investigations in 1978-1979." Extensive geologic investigations confirm site suitability Rept encl.
MDCJA, J.E. Puget Sound Power & Light Co. 79/05/25 100pp

G. Adjudicatory correspondence

7905140159 Motion for leave to file interim statement of issues three days out of time on 790512
BUDCH, R.W. Evergreen Legal Services. HEARN, D.S. Hearn, Donald S. 79/05/12 3pp

--7905140161 Intervenor Tribes interim statement of issues in response to 790508 order.
BUDCH, R.W. Evergreen Legal Services. HEARN, D.S. Hearn, Donald S. 79/05/12. 3pp

7905230918 Forewarn on Board/Coalition for Safe Power's statement of issues, submitted per 790508 order Follows applicant 790522 revised statement. Discusses various issues. Certificate of Rec encl.
STACHEN, E.G. Coalition for Safe Power 79/05/16 4pp

7905290118 Forwards request for Board notification re non-safety-grade equipment to mitigate transients.
BUDCH, J.F. Hearings Division 79/04/02 3pp

--7905051
4611
VAB
79/1

--79050
440
780
3pp

7905250
1000
BLANK

7905140
DEALS

DOCKETED ITEMS

E. Financial Information

7905250459 Forwards addl financial info. as requested by NRC 790405 ltr. Info includes addl re benefits & exhibits in brief recent rate relief actions. BCS production & annual financial reports. NRCDA: J E Puget Sound Power & Light Co 79/05/17 35pp

--7905250463 Annual Financial Report 1970
+ Puget Sound Power & Light Co 79/10/31 40pp

--7905250472 Annual Financial Report 1970
+ Pacific Power Co 79/12/21 30pp

7905310372 Response to 790405 ltr Forwards financial info from SEC 10-K, prospectus, testimony, exhibits & "Portland SE Port Source Sources of Funds for Site Civil Expenditures & Capital Structure" Encl in Central Files. NRCDA: J E Puget Sound Power & Light Co 79/05/25 40pp

F. Hearing transcripts on non-substantive matters

7905340014 Transcript of 790426 meeting in Seattle, WA. Pt II, 79-18, 453. DEAR: V. J. LINDENBERGER, O. HOFER, P. F. Atomic Safety and Licensing Board Panel. 79/04/24 17pp.

DOCKET 80-324 BARTON, UNIT 1

g. Regulatory correspondence

7905140083 Describes NRC notification to AGLAS during past year re nuclear power reactors for info of Board & parties in proceeding. OSAT: J R Branch 3 79/04/12 3pp

--7905140207 Discusses issue of neutron exposure at commercial power reactors re problem exists. Questions date on which concerns were based. EISENHART, D. Division of Operating Reactors. VOLUME: R.H. Assistant Director for Site Analysis. 79/03/05 3pp

--7905140242 Follows up 790306 memo & 790306 & OD meetings re GE's SAR-10880 equipment adequacy evaluation. Describes action plan with parallel program & proposed decision process plan. HATTSON, R. J. Division of Systems Safety. 79/03/16 4pp

--7905140244 Summary of 790305 meeting w/GE re GE's SAR-10880 equipment adequacy evaluation for Mark II & III plants w/supporting documentation. HATTSON, R. J. Division of Systems Safety. 79/03/16 2pp

DOCKET 80-325 BARTON, UNIT 2

h. Regulatory correspondence

7905140280 Describes NRC notification to AGLAS during past year re nuclear power reactors for info of Board & parties in proceeding. OSAT: J R Branch 3 79/04/12 3pp

--7905140287 Discusses issue of neutron exposure at commercial power reactors re problem exists. Questions date on which concerns were based. EISENHART, D. Division of Operating Reactors. VOLUME: R.H. Assistant Director for Site Analysis. 79/03/05 3pp

--7905140282 Follows up 790306 memo & 790306 & OD meetings re GE's SAR-10880 equipment adequacy evaluation. Describes action plan with parallel program & proposed decision process plan. HATTSON, R. J. Division of Systems Safety. 79/03/16 4pp

--7905140289 Summary of 790305 meeting w/GE re GE's SAR-10880 equipment adequacy evaluation for Mark II & III plants w/supporting documentation. HATTSON, R. J. Division of Systems Safety. 79/03/16 2pp

DOCKET 80N-50-526 PALO VERDE NUCLEAR STATION, UNIT 1

A. Application/construction stage documents & correspondence

7905250036 Requests authorization to use encl ABME code cases in plant plans. VAN BRUNT, E.E. Arizona Public Service Co. 79/05/27 3pp.

--7905250092 Ask receipt of 790504 ltr requesting approval of ABME Code 1401 for use in design of hydrogen recombiner for post-LOCA. Info. Approval is granted. BUCHHEIMER, P. Atomic Energy Commission- Directorate of Licensing (PWR-1979) 79/10/22 1p.

--7905250097 Requests authorization to use ABME Code Case 1592 in design of hydrogen recombiners for post-LOCA use. M/let of LWR projects incorporating safety criteria. BUCHHEIMER, P. Atomic Energy Commission- Directorate of Licensing (PWR-1979) 79/10/22 1p.

G. Inspection reports, IE Referrals & correspondence

7905150409 Forwards IE Insp Repts 90-500/70-07 & 90-520/70-07 on 790210-21 No nonconformance noted. VAN BRUNT, E.E. Region 5, San Francisco. Reactor Construction & Engineering Support Branch 79/03/16 2pp.

--7905150420 IE Insp Repts 90-500/70-09 & 90-029/70-07 on 790210-21 No nonconformance noted. Major areas inspected: containment structural concrete, containment post handling area, reactor vessel, final alignment & electrical cable & components. HANSEN, C. C. Region 5, San Francisco. Office of the Director. BUCHHEIMER, P. Region 5, San Francisco. Reactor Construction & Engineering Support Branch 79/03/16 11pp.

7905100292 Forwards IE Info Notice 79-06, "Review Analysis of Safety-Related Piping". ENGELBORN, R.H. Dallas, Office of the Director 79/03/23 1p

7905140074 Forwards IE Info Notice 79-07, "Repters of Radiactive Tests". ENGELBORN, R.H. Region 5, San Francisco. Office of the Director 79/03/24 1p

7905200034 Response to IE Bulletin 79-03 Forwards 790117 ltr. VANBRUNT, E.E. Arizona Public Service Co. 79/04/03 1p

7905100084 Forwards IE Bulletin 79-06A, "Review of Operational Errors & Operator Misalignments Identified During THE Incident". ENGELBORN, R.H. Region 5, San Francisco. Office of the Director 79/04/14 1p

7905140037 Forwards IE Bulletin 79-06B, "Review of Operational Errors & Operator Misalignments Identified During THE Incident". ENGELBORN, R.H. Region 5, San Francisco. Office of the Director 79/04/14 1p

7905140044 Forwards IE Bulletin 79-08, "Events Relevant to Boiling Water Reactor Identified During THE Incident". ENGELBORN, R.H. Region 5, San Francisco. Office of the Director. 79/04/14 1p

7905170098 Forwards IE Bulletin 79-07, "Radiation Stress Analysis of Safety-Related Piping". Licensee action required. ENGELBORN, R.H. Region 5, San Francisco. Office of the Director. 79/04/14 1p

7905200286 Forwards IE Bulletin 79-08, "Failures of GE Type AN-2 Circuit Breaker in Safety-Related Sys.". Licensee action required. ENGELBORN, R.H. Region 5, San Francisco. Office of the Director 79/04/17 1p

7905200285 Forwards IE Bulletin 79-08B, "Nuclear Incident at THE Reactor". ENGELBORN, R.H. Region 5, San Francisco. Office of the Director. 79/04/21 1p.

7905200272 Response to IE Bulletin 79-12 & 79-12A will be submitted by 790512 awaiting specific req from O-6. VANBRUNT, E.E. Arizona Public Service Co. 79/05/25 1p.

H. Reportable occurrences, LWRs & related correspondence

7905150037 Forwards PHD-79-02L. ENGELBORN, R.H. Region 5, San Francisco. Office of the Director 79/04/16 1p

7905150165 Forwards PHD-79-02S. ENGELBORN, R.H. Region 5, San Francisco. Office of the Director. 79/04/11 1p.

7905140121 Forwards PHD-79-02L. ENGELBORN, R.H. Region 5, San Francisco. Office of the Director 79/04/12 1p

DOCKETED ITEMS

257

- 790510132a Forwards PHD-79-47T
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/13 1p
- 790509090 Forwards PHD-79-47U
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p
- 790509125 Forwards PHD-79-47A
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/20 1p
- 790510420 Forwards PHD-79-47AB
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/21 1p
- 790510442 Forwards PHD-79-47AC & AD
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/23 1p
- 790510454 Forwards PHD-79-47AE
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/24 1p
- 790509030 Forwards PHD-79-47AF
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/25 1p
- 790509055 Forwards PHD-79-47AB
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p
- 790509018 Forwards PHD-79-47AH
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/27 1p
- 790507025 Forwards PHD-79-47A2, A3 & A4 per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/20 1p
- 790504035 Forwards PHD-79-47AL per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/05/21 1p
- 790504038 PHD-79-47AL summary of info re nuclear incident as of
790505. Describes plans & modern status
E Office of Inspection & Enforcement 79/05/01 3pp.
- 790511099 Forwards PHD-79-47AM
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/05/07 1p
- DOCKET 87H-30-329 PAUL VERNE NUCLEAR STATION, UNIT 2
A Application/Construction Stage documents & correspondence
79/05/07 1p
- 790502086 Requests authorization to use excl ADME code cases in plant
cases
VAN BEUNT, E. E. Arizona Public Service Co. 79/05/07 3pp
- 790502092 Ask receipt of 741054 ltr requesting approval of ADME Code
1481 for use in design of hydrogen recombiner for post-LOCA
use Approval is granted
SCHNEIDER, P. Atomic Energy Commission, Directorate of Licensing
Ipra-17793, 74/10/22 1p
- 790502097 Requests authorization to use ADME Code Case 1592 in design
of hydrogen recombiner for post-LOCA use w/limit of LWR
projects incorporating such criteria
BTDOL, E. Rockwell International Corp 78/04/14 3pp.
- 0 Inspection reports: IE Bulletin & correspondence
- 790510409 Forwards IE Insp Rpts 30-328/78-09 & 30-329/78-07 on
781218-21. No nonconformance noted.
VAN BEUNT, E. E. Region 3, San Francisco, Reactor Construction &
Engineering Support Branch. 79/05/16 3pp.
- 790510420 IE Insp Rpts 30-328/78-09 & 30-329/78-07 on 781218-21. No
nonconformance noted. Major areas inspected: containment
structural concrete reinforcement post installation app reactor
vessel final alignment & electrical cable & components
HARTER, L. C. Region 3, San Francisco, Office of the Director.
EDWARDS, J. H. Region 3, San Francisco, Reactor
Construction & Engineering Support Branch 79/05/16 11pp.
- 790510020 Forwards IE Info Notice 79-04, "Stress Analysis of
Safety-Related Piping"
ENGLER, R. H. Region 3, San Francisco, Office of the Director 79/05/23
1p
- 790504078 Forwards IE Info Notice 79-07, "Regulation of Reducible Tanks,"
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/05/26 1p
- 790509056 Response to IE Bulletin 79-03 Forwards 781117 ltr
VANBEUNT, E. E. Arizona Public Service Co. 79/04/02 1p
- 790510056 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Misalignments Identified During THE Incident."
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/14 1p
- 790504057 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Misalignments Identified During THE Incident."
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p
- 790504044 Forwards IE Bulletin 79-08, "Events Relevant to Rolling
Motor Power Reactors Identified During THE Incident."
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p
- 790510049 Forwards IE Bulletin 79-07, "Detailed Stress Analysis of
Safety-Related Piping - Licensee action required."
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p
- 790503084 Forwards IE Bulletin 79-09, "Failure of GE Type AM-2
Circuit Breaker in Safety-Related Bay - Licensee action
required."
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/17 1p
- 790506035 Forwards IE Bulletin 79-08D, "Nuclear Incident at
THE Reactor."
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/23 1p
- 790507052 Response to IE Bulletin 78-12 & 78-12A will be submitted by
VANBEUNT, E. E. Arizona Public Service Co. 79/05/23 1p
- 0 Reportable occurrences: LORs & related correspondence
- 790510057 Forwards PHD-79-47L
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/04 1p
- 790510415 Forwards PHD-79-47E
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/11 1p
- 790504012 Forwards PHD-79-47E
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/12 1p
- 790510414 Forwards PHD-79-47E
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/13 1p
- 790502090 Forwards PHD-79-47U
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p
- 790510428 Forwards PHD-79-47AA
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/20 1p
- 790510430 Forwards PHD-79-47AB
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/21 1p
- 790510442 Forwards PHD-79-47AC & AD
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/23 1p
- 790510454 Forwards PHD-79-47AE
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/24 1p
- 790509030 Forwards PHD-79-47AF
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/25 1p
- 790509055 Forwards PHD-79-47AB
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p
- 790509018 Forwards PHD-79-47AH
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/27 1p

DOCKETED ITEMS

7905090303 Forwards PHO-79-67AD
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/04/26 1p

7905090313 Forwards PHO-79-67AH
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/27 1p

7905090305 Forwards PHO-79-67AJ & AK per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p

7905090308 Forwards PHO-79-67AL per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p

7905090309 Forwards PHO-79-67AM
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/03/07 1p

DOCKET BTH-SO-525 PALO VERDE NUCLEAR STATION, UNIT 3
A Application/constructive change documents & correspondence

7905090307 Suggests NRC demand & control ltr w/communications link
that automatically receives data from operating reactors &
shippers of BWR
ROBLAR, E. H. Radiological Health Standards Branch 79/04/17
1p

7905090306 Requests authorization to use encl ABCE code copy in plant
encl
WAM SMITH, E. H. Arizona Public Service Co 79/05/07 2pp

--7905090302 Act receipt of 741004 ltr requesting approval of ABCE Code
1481 for use in design of hydrogen recombiner for post-LOCA
use Approval is granted.
GOWENLOCK, F. Atomic Energy Commission, Directorate of Licensing
(Pre-1975) 74/10/22 1p

--7905090307 Requests authorization to use ABCE Code Case 1392 in design
of hydrogen recombiners for post-LOCA use. Will of LAR
projects incorporating sub. criteria
STOEHL, R. Section International Corp. 79/04/14 2pp

8 Inspection reports, IE Bulletin & correspondence

7905090309 Forwards IE info Notice 79-04, "Stress Analysis of
Safety-Related Piping."
ENGLER, R. H. Region 4, Dallas, Office of the Director. 79/03/20
1p

Forwards IE info Notice 79-07, "Regulations of Redwood Tanks"
Region 3, San Francisco, Office of the Director

IE Bulletin 79-03 Forwards 790517 ltr.
re Public Service Co. 79/04/03. 1p.

lin 79-06A, "Review of Operational Errors &
and During TMI Incident,"
San Francisco, Office of the Director.

lin 79-06B, "Review of Operational Errors &
and During TMI Incident,"
San Francisco, Office of the Director.

lin 79-06, "Events Relevant to Boiling
Liquid During TMI Incident,"
San Francisco, Office of the Director.

lin 79-07, "Seismic Stress Analysis of
certain action required
San Francisco, Office of the Director

lin 79-08, "Features of GE Type AB-2
Related Sys." License action
San Francisco, Office of the Director.

7905090303 Forwards IE Bulletin 79-05, "Nuclear Incident at
TMI-Bug-1."
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/21 1p

7905090307 Response to IE Bulletin 79-12 & 79-12K will be holding by
790513. Awaiting generic rpts from C-E
WAMSMITH, E. H. Arizona Public Service Co 79/05/25 1p

8. Reportable occurrences, LERs & related correspondence

7905090307 Forwards PHO-79-67L
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/03 1p

7905090308 Forwards PHO-79-67E
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/11 1p.

7905090301 Forwards PHO-79-67G
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/12 1p

7905090306 Forwards PHO-79-67T
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/13 1p

7905090305 Forwards PHO-79-67U
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/14 1p

7905090305 Forwards PHO-79-67AA
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/20 1p

7905090302 Forwards PHO-79-67AB
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/21 1p

7905090304 Forwards PHO-79-67AC & AD
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/23 1p.

7905090306 Forwards PHO-79-67AE
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/24 1p.

7905090308 Forwards PHO-79-67AF
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/25 1p

7905090303 Forwards PHO-79-67AG
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p

7905090315 Forwards PHO-79-67AH
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/27 1p

7905090309 Forwards PHO-79-67AJ & AK per NRC 790401 ltr transmitting
IE Bulletin 79-05
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/04/26 1p

7905090305 Forwards PHO-79-67AL per NRC 790401 ltr transmitting IE
Bulletin 79-05
ENGLER, R. H. Region 3, San Francisco, Office of the Director.
79/05/05 1p.

7905090309 Forwards PHO-79-67AM
ENGLER, R. H. Region 3, San Francisco, Office of the Director
79/05/07 1p

DOCKET BTH-SO-525 BEBBAR-021

1. Insurance & indemnity information

7905090302 Confirms increase in liability limit to \$36,000,000 for
policies 79-02, 79-03, 79-04, 79-05, 79-06, 79-07, 79-08, 79-09, 79-10, 79-11, 79-12, 79-13, 79-14, 79-15, 79-16, 79-17, 79-18, 79-19, 79-20, 79-21, 79-22, 79-23, 79-24, 79-25, 79-26, 79-27, 79-28, 79-29, 79-30, 79-31, 79-32, 79-33, 79-34, 79-35, 79-36, 79-37, 79-38, 79-39, 79-40, 79-41, 79-42, 79-43, 79-44, 79-45, 79-46, 79-47, 79-48, 79-49, 79-50, 79-51, 79-52, 79-53, 79-54, 79-55, 79-56, 79-57, 79-58, 79-59, 79-60, 79-61, 79-62, 79-63, 79-64, 79-65, 79-66, 79-67, 79-68, 79-69, 79-70, 79-71, 79-72, 79-73, 79-74, 79-75, 79-76, 79-77, 79-78, 79-79, 79-80, 79-81, 79-82, 79-83, 79-84, 79-85, 79-86, 79-87, 79-88, 79-89, 79-90, 79-91, 79-92, 79-93, 79-94, 79-95, 79-96, 79-97, 79-98, 79-99, 79-100, 79-101, 79-102, 79-103, 79-104, 79-105, 79-106, 79-107, 79-108, 79-109, 79-110, 79-111, 79-112, 79-113, 79-114, 79-115, 79-116, 79-117, 79-118, 79-119, 79-120, 79-121, 79-122, 79-123, 79-124, 79-125, 79-126, 79-127, 79-128, 79-129, 79-130, 79-131, 79-132, 79-133, 79-134, 79-135, 79-136, 79-137, 79-138, 79-139, 79-140, 79-141, 79-142, 79-143, 79-144, 79-145, 79-146, 79-147, 79-148, 79-149, 79-150, 79-151, 79-152, 79-153, 79-154, 79-155, 79-156, 79-157, 79-158, 79-159, 79-160, 79-161, 79-162, 79-163, 79-164, 79-165, 79-166, 79-167, 79-168, 79-169, 79-170, 79-171, 79-172, 79-173, 79-174, 79-175, 79-176, 79-177, 79-178, 79-179, 79-180, 79-181, 79-182, 79-183, 79-184, 79-185, 79-186, 79-187, 79-188, 79-189, 79-190, 79-191, 79-192, 79-193, 79-194, 79-195, 79-196, 79-197, 79-198, 79-199, 79-200, 79-201, 79-202, 79-203, 79-204, 79-205, 79-206, 79-207, 79-208, 79-209, 79-210, 79-211, 79-212, 79-213, 79-214, 79-215, 79-216, 79-217, 79-218, 79-219, 79-220, 79-221, 79-222, 79-223, 79-224, 79-225, 79-226, 79-227, 79-228, 79-229, 79-230, 79-231, 79-232, 79-233, 79-234, 79-235, 79-236, 79-237, 79-238, 79-239, 79-240, 79-241, 79-242, 79-243, 79-244, 79-245, 79-246, 79-247, 79-248, 79-249, 79-250, 79-251, 79-252, 79-253, 79-254, 79-255, 79-256, 79-257, 79-258, 79-259, 79-260, 79-261, 79-262, 79-263, 79-264, 79-265, 79-266, 79-267, 79-268, 79-269, 79-270, 79-271, 79-272, 79-273, 79-274, 79-275, 79-276, 79-277, 79-278, 79-279, 79-280, 79-281, 79-282, 79-283, 79-284, 79-285, 79-286, 79-287, 79-288, 79-289, 79-290, 79-291, 79-292, 79-293, 79-294, 79-295, 79-296, 79-297, 79-298, 79-299, 79-300, 79-301, 79-302, 79-303, 79-304, 79-305, 79-306, 79-307, 79-308, 79-309, 79-310, 79-311, 79-312, 79-313, 79-314, 79-315, 79-316, 79-317, 79-318, 79-319, 79-320, 79-321, 79-322, 79-323, 79-324, 79-325, 79-326, 79-327, 79-328, 79-329, 79-330, 79-331, 79-332, 79-333, 79-334, 79-335, 79-336, 79-337, 79-338, 79-339, 79-340, 79-341, 79-342, 79-343, 79-344, 79-345, 79-346, 79-347, 79-348, 79-349, 79-350, 79-351, 79-352, 79-353, 79-354, 79-355, 79-356, 79-357, 79-358, 79-359, 79-360, 79-361, 79-362, 79-363, 79-364, 79-365, 79-366, 79-367, 79-368, 79-369, 79-370, 79-371, 79-372, 79-373, 79-374, 79-375, 79-376, 79-377, 79-378, 79-379, 79-380, 79-381, 79-382, 79-383, 79-384, 79-385, 79-386, 79-387, 79-388, 79-389, 79-390, 79-391, 79-392, 79-393, 79-394, 79-395, 79-396, 79-397, 79-398, 79-399, 79-400, 79-401, 79-402, 79-403, 79-404, 79-405, 79-406, 79-407, 79-408, 79-409, 79-410, 79-411, 79-412, 79-413, 79-414, 79-415, 79-416, 79-417, 79-418, 79-419, 79-420, 79-421, 79-422, 79-423, 79-424, 79-425, 79-426, 79-427, 79-428, 79-429, 79-430, 79-431, 79-432, 79-433, 79-434, 79-435, 79-436, 79-437, 79-438, 79-439, 79-440, 79-441, 79-442, 79-443, 79-444, 79-445, 79-446, 79-447, 79-448, 79-449, 79-450, 79-451, 79-452, 79-453, 79-454, 79-455, 79-456, 79-457, 79-458, 79-459, 79-460, 79-461, 79-462, 79-463, 79-464, 79-465, 79-466, 79-467, 79-468, 79-469, 79-470, 79-471, 79-472, 79-473, 79-474, 79-475, 79-476, 79-477, 79-478, 79-479, 79-480, 79-481, 79-482, 79-483, 79-484, 79-485, 79-486, 79-487, 79-488, 79-489, 79-490, 79-491, 79-492, 79-493, 79-494, 79-495, 79-496, 79-497, 79-498, 79-499, 79-500, 79-501, 79-502, 79-503, 79-504, 79-505, 79-506, 79-507, 79-508, 79-509, 79-510, 79-511, 79-512, 79-513, 79-514, 79-515, 79-516, 79-517, 79-518, 79-519, 79-520, 79-521, 79-522, 79-523, 79-524, 79-525, 79-526, 79-527, 79-528, 79-529, 79-530, 79-531, 79-532, 79-533, 79-534, 79-535, 79-536, 79-537, 79-538, 79-539, 79-540, 79-541, 79-542, 79-543, 79-544, 79-545, 79-546, 79-547, 79-548, 79-549, 79-550, 79-551, 79-552, 79-553, 79-554, 79-555, 79-556, 79-557, 79-558, 79-559, 79-560, 79-561, 79-562, 79-563, 79-564, 79-565, 79-566, 79-567, 79-568, 79-569, 79-570, 79-571, 79-572, 79-573, 79-574, 79-575, 79-576, 79-577, 79-578, 79-579, 79-580, 79-581, 79-582, 79-583, 79-584, 79-585, 79-586, 79-587, 79-588, 79-589, 79-590, 79-591, 79-592, 79-593, 79-594, 79-595, 79-596, 79-597, 79-598, 79-599, 79-600, 79-601, 79-602, 79-603, 79-604, 79-605, 79-606, 79-607, 79-608, 79-609, 79-610, 79-611, 79-612, 79-613, 79-614, 79-615, 79-616, 79-617, 79-618, 79-619, 79-620, 79-621, 79-622, 79-623, 79-624, 79-625, 79-626, 79-627, 79-628, 79-629, 79-630, 79-631, 79-632, 79-633, 79-634, 79-635, 79-636, 79-637, 79-638, 79-639, 79-640, 79-641, 79-642, 79-643, 79-644, 79-645, 79-646, 79-647, 79-648, 79-649, 79-650, 79-651, 79-652, 79-653, 79-654, 79-655, 79-656, 79-657, 79-658, 79-659, 79-660, 79-661, 79-662, 79-663, 79-664, 79-665, 79-666, 79-667, 79-668, 79-669, 79-670, 79-671, 79-672, 79-673, 79-674, 79-675, 79-676, 79-677, 79-678, 79-679, 79-680, 79-681, 79-682, 79-683, 79-684, 79-685, 79-686, 79-687, 79-688, 79-689, 79-690, 79-691, 79-692, 79-693, 79-694, 79-695, 79-696, 79-697, 79-698, 79-699, 79-700, 79-701, 79-702, 79-703, 79-704, 79-705, 79-706, 79-707, 79-708, 79-709, 79-710, 79-711, 79-712, 79-713, 79-714, 79-715, 79-716, 79-717, 79-718, 79-719, 79-720, 79-721, 79-722, 79-723, 79-724, 79-725, 79-726, 79-727, 79-728, 79-729, 79-730, 79-731, 79-732, 79-733, 79-734, 79-735, 79-736, 79-737, 79-738, 79-739, 79-740, 79-741, 79-742, 79-743, 79-744, 79-745, 79-746, 79-747, 79-748, 79-749, 79-750, 79-751, 79-752, 79-753, 79-754, 79-755, 79-756, 79-757, 79-758, 79-759, 79-760, 79-761, 79-762, 79-763, 79-764, 79-765, 79-766, 79-767, 79-768, 79-769, 79-770, 79-771, 79-772, 79-773, 79-774, 79-775, 79-776, 79-777, 79-778, 79-779, 79-780, 79-781, 79-782, 79-783, 79-784, 79-785, 79-786, 79-787, 79-788, 79-789, 79-790, 79-791, 79-792, 79-793, 79-794, 79-795, 79-796, 79-797, 79-798, 79-799, 79-800, 79-801, 79-802, 79-803, 79-804, 79-805, 79-806, 79-807, 79-808, 79-809, 79-810, 79-811, 79-812, 79-813, 79-814, 79-815, 79-816, 79-817, 79-818, 79-819, 79-820, 79-821, 79-822, 79-823, 79-824, 79-825, 79-826, 79-827, 79-828, 79-829, 79-830, 79-831, 79-832, 79-833, 79-834, 79-835, 79-836, 79-837, 79-838, 79-839, 79-840, 79-841, 79-842, 79-843, 79-844, 79-845, 79-846, 79-847, 79-848, 79-849, 79-850, 79-851, 79-852, 79-853, 79-854, 79-855, 79-856, 79-857, 79-858, 79-859, 79-860, 79-861, 79-862, 79-863, 79-864, 79-865, 79-866, 79-867, 79-868, 79-869, 79-870, 79-871, 79-872, 79-873, 79-874, 79-875, 79-876, 79-877, 79-878, 79-879, 79-880, 79-881, 79-882, 79-883, 79-884, 79-885, 79-886, 79-887, 79-888, 79-889, 79-890, 79-891, 79-892, 79-893, 79-894, 79-895, 79-896, 79-897, 79-898, 79-899, 79-900, 79-901, 79-902, 79-903, 79-904, 79-905, 79-906, 79-907, 79-908, 79-909, 79-910, 79-911, 79-912, 79-913, 79-914, 79-915, 79-916, 79-917, 79-918, 79-919, 79-920, 79-921, 79-922, 79-923, 79-924, 79-925, 79-926, 79-927, 79-928, 79-929, 79-930, 79-931, 79-932, 79-933, 79-934, 79-935, 79-936, 79-937, 79-938, 79-939, 79-940, 79-941, 79-942, 79-943, 79-944, 79-945, 79-946, 79-947, 79-948, 79-949, 79-950, 79-951, 79-952, 79-953, 79-954, 79-955, 79-956, 79-957, 79-958, 79-959, 79-960, 79-961, 79-962, 79-963, 79-964, 79-965, 79-966, 79-967, 79-968, 79-969, 79-970, 79-971, 79-972, 79-973, 79-974, 79-975, 79-976, 79-977, 79-978, 79-979, 79-980, 79-981, 79-982, 79-983, 79-984, 79-985, 79-986, 79-987, 79-988, 79-989, 79-990, 79-991, 79-992, 79-993, 79-994, 79-995, 79-996, 79-997, 79-998, 79-999, 80-000, 80-001, 80-002, 80-003, 80-004, 80-005, 80-006, 80-007, 80-008, 80-009, 80-010, 80-011, 80-012, 80-013, 80-014, 80-015, 80-016, 80-017, 80-018, 80-019, 80-020, 80-021, 80-022, 80-023, 80-024, 80-025, 80-026, 80-027, 80-028, 80-029, 80-030, 80-031, 80-032, 80-033, 80-034, 80-035, 80-036, 80-037, 80-038, 80-039, 80-040, 80-041, 80-042, 80-043, 80-044, 80-045, 80-046, 80-047, 80-048, 80-049, 80-050, 80-051, 80-052, 80-053, 80-054, 80-055, 80-056, 80-057, 80-058, 80-059, 80-060, 80-061, 80-062, 80-063, 80-064, 80-065, 80-066, 80-067, 80-068, 80-069, 80-070, 80-071, 80-072, 80-073, 80-074, 80-075, 80-076, 80-077, 80-078, 80-079, 80-080, 80-081, 80-082, 80-083, 80-084, 80-085, 80-086, 80-087, 80-088, 80-089, 80-090, 80-091, 80-092, 80-093, 80-094, 80-095, 80-096, 80-097, 80-098, 80-099, 80-100, 80-101, 80-102, 80-103, 80-104, 80-105, 80-106, 80-107, 80-108, 80-109, 80-110, 80-111, 80-112,

DOCKETED ITEMS

259

DOCKET 67H-93-372 RDP R47

A. Application/Construction stage documents & correspondence

7905040576 Notices that expiration date for Preliminary Design Approval 2 is extended to 8/10/87 based on review of Amend V to application
BOWD, R. B. Division of Project Management 79/05/03 Dpp

DOCKET 33-337 Clinch River Breeder Reactor

A. Application/Construction stage

7905030033 Forwards affidavit confirming distribution of FRAB Amend 40 to designated local public officials & EPA representatives
COMPLAND, L. Energy Dept. of Clinch River Breeder Reactor Plant
79/04/23 Dpp

DOCKET 33-808 MEMPHIS STATE UNIV RESEARCH REACTOR

J. Insurance & indemnity information

7905140232 Forwards Amend 2 to Indemnity Agreement 8-99, per 100MR140 changes re liability insurance to increase from \$140 million to \$160 million effective 7/9/85. Supporting documentation encl
BALTDWA, J. Antitrust & Indemnity Group 79/05/01 Dpp

O. Inspection reports, IE Submittals & correspondence

7905070135 Forwards IE Bulletin 79-05, 79-05A & 79-06 re nuclear incident at TMI
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director
79/04/12 Dpp

DOCKET 67H-93-346 MARBLE HILL NUCLEAR STATION, UNIT 1

A. Application/Construction stage documents & correspondence

7905070092 Response to comments re application for consent of purchase intake & discharge structures w/79050130 for from Attorney General of WV to Corps of Engineers, Louisville re design & fill application of Public Use Co. of IN
MORTIMER, M. H. Army Dept. of Corps of Engineers 79/01/06 Ypp

7905050206 Notices of licensee's mitigation plan to recover archeological resources disturbed by consent of intake & discharge structures w/IN Dept of Natural Resources its siting plan
BALLARD, R. L. Environmental Projects Branch 2 79/04/22 Dpp

7905020445 Forwards NRES-0301, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of licensee's availability WFO encl
VANDERLIND, B. Assistant Director For Light Water Reactors
79/03/23 Dpp

7905010821 Response to 79040330 re vehicle license w/Improperly Issued License Matter will be reviewed in future Insp
FORDALL, O. Region 2, Chicago, Office of the Director 79/04/17 Dpp

7905010717 Notification of 790503 meeting w/Util in Bethesda, MD to discuss Forecast Panel's estimate for Fuel load data & submitted data for FRAB
VANDERLIND, B. Light Water Reactors Branch 4 79/04/23 Dpp

7905100296 Notification that lack of expected prehistoric resources justified termination of mitigation effort
BALLARD, R. L. Environmental Projects Branch 1 79/04/30 Dpp

7905060415 Discusses NRC intention to delay FRAB review until end of year. Delay is unacceptable, as based on average cost schedule Unit is better than average & Unit is committed for 1982 operation FRAB will be filed in June 1979.
CONRAD, J. A. Public Service Co. of Indiana, Inc 79/05/04 Dpp

G. Administrative correspondence

7905100220 Motion to reopen safety hearings to discuss WASH-1400 & accident "2,4,5-T"
BATTILO, T. H. Battila, T. H. 79/03/22 Dpp

7905030446 Forwards NRC memo discussing problems experienced w/size support base slab design piping design analysis on case-by-case basis being reviewed under RFP Section 3.1.2.
BRUNER, L. Branch 3 79/04/05 Dpp

7905030446 Forwards 790503 memo from Director of OFC of Nuclear Reactor Regulation to the Commissioners discussing fire protection research test results conducted by UL.
BRUNER, L. Branch 3 79/04/05 Dpp

7905140208 Forwards latest motion to reopen safety hearings by T Battila on behalf of Save the Valley - Save Marble Hill
Forwards revisions to draft motions attached to 790402
MURRAY, J. P. Rulemaking & Enforcement Division 79/04/05 Dpp

7905160212 Motion to suspend & revoke CP for proposed facility license of TMI incident
BATTILO, T. H. Battila & Battila 79/04/04 Dpp

7905100438 Response to ALAB-509 re radon emissions & de minimus theory re Parties request Certificate of Nuc encl.
KENTON, D. F. Hearings Division 79/04/11 Dpp

7905140519 Response to 790404 brief of Philadelphia Electric Co. PHE&O & Atlantic City L&S Electric Co. re de minimus theory
Certificate of Nuc encl.
KAPFORD, C. E. Citizens for Safe Environment 79/04/11 Dpp

7905040794 Ack receipt of 790404 petition to institute cost suspension proceedings. Decision under consideration. Forwards 790412
FR notice
KENTON, D. F. Office of Nuclear Reactor Regulation 79/04/12 Dpp

7905040812 FR notice of request to reopen safety hearing
BOWD, R. B. Office of Nuclear Reactor Regulation 79/04/12 Dpp

7905040830 Forwards motion of intervenor to reopen safety hearing. Motion to revoke CP & FR notice.
KENTON, D. F. Office of Nuclear Reactor Regulation 79/04/12 Dpp

7905040872 Motion for ALAB to reopen safety hearings
BATTILO, T. H. Save the Valley - Save Marble Hill 79/04/12 Dpp

7905040904 Motion to reopen safety hearings due to EPA has on herbicide & availability of WASH-1400
BATTILO, T. H. Save the Valley - Save Marble Hill 79/04/12 Dpp

7905140330 Notices of consolidation of five intervenor groups re radon emissions. These Parties have until 790525 in which to file summary disposition.
BUTLER, M. E. Atomic Safety and Licensing Appeal Panel 79/04/28 Dpp

H. General correspondence

7905040725 Discusses ability of Commissioners to reach objective decisions re nuclear power in light of evc in preaminals capacity WASH-1400 suggests add govt funding for researching civilian energy needs.
WATKINS, G. Kentucky State of 79/04/30 Dpp

O. Inspection reports, IE Submittals & correspondence

7905040326 Forwards IE Insp Regs 30-844/79-02 & 30-847/79-02 on 790327-0301 & notice of violation.
FORDALL, O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/03/14 Dpp

7905070090 Notice of violation from Insp on 790327-0301.
Region 3, Chicago, Office of the Director 79/03/12 Dpp

7905070093 IE Insp Noncompliance N Inspection for
BOWEN, B. D. Office of IE

790510028 Safety
NPPLE
Dpp

790504020 NPPLE
Dpp

79050306 Reg RI
NPPLE
Dpp

79050301 Reg RI
NPPLE
Dpp

DOCKETED ITEMS

790504023 Forward 1E Bulletin 79-048, "Review of Operational Errors & Missalignments Identified During TMI Incident." 79/04/14
 KAPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
 1p

790504039 Forward 1E Bulletin 79-05, "Events Relevant to Belling Water Power Reactor, Identified During TMI Incident." 79/04/14
 KAPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
 1p

790507047 Forward 1E Bulletin 79-07, "Dynamic Stress Analysis of Safety-Related Piping - Licensee action required." 79/04/14
 KAPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
 1p

790501041 Forward 1E Info Notice 79-05, "Nonconforming Pipe Support Straps." 79/04/16
 KAPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/16
 1p

790503041 Forward 1E Bulletin 79-04, "Failures of DE Type AN-2 Circuit Breaker in Safety-Related Systems - Licensee action required." 79/04/17
 KAPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/17
 1p

790508050 Forward 1E Bulletin 79-038, "Nuclear Incident at TMI-2." 79/04/21
 KAPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/21
 1p

790504021 Act receipt of 790410 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 53-546/79-02 & 50-547/79-02 79/04/25
 PABELLI, J. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/25
 1p

--790504027 Response to NRC 790314 ltr re violations noted in 1E Insp Repts 53-546/79-02 & 50-547/79-02. Corrective actions space heaters attempted & shutoff initiated. 79/04/10
 COOPER, L. J. Public Service Co. of Indiana, Inc. 79/04/10
 2pp

790504033 Response to 1E Bulletin 79-03 re piping w/dg by Youngstown Welding & Engineering Co. Piping not in use at facility. 79/03/03
 COOPER, L. J. Public Service Co. of Indiana, Inc. 79/03/03
 1p

8 Separable occurrences, LERs & related correspondence

790503027 Forward 1E Bulletin 79/121 ltr re 1E Bulletin 79/013 ltr re public cooler defects & repairs. 79/04/02
 KAPPLER, J. O. Region 3, Chicago, Office of the Director 79/04/02
 1p

790504040 Potential NO on 790409 two great cracks collided & fell, striking confinement liner Vertical angle stiffener. Horizontal reinforcing bars & circular CD ring stiffener were damaged. Evaluation report to follow. 79/05/09
 COOPER, L. J. Public Service Co. of Indiana, Inc. 79/05/09
 1p

790505040 Provides interim report of NO on 790414 possible damage to two post-tensioning templates & surrounding concrete caused by overloading from propane fired burners used to repair tendon. Airt Repair procedures studied. 79/05/14
 COOPER, L. J. Public Service Co. of Indiana, Inc. 79/05/14
 1p

DOCKET WITH-30-047 MARBLE HILL NUCLEAR STATION, UNIT 2

A. Application/construction stage documents & correspondence

790504022 Response to comments re application for coast of pumphouse intake & discharge structure. 79/04/04 ltr from Attorney General of NY to Corps of Engineers, Louisville re dredge & fill application of Marble Hill Co. of Ind. 79/11/06
 METLOCK, H. M. Army, Dept. of Corps of Engineers. 79/11/06
 7pp

--790505028 Inhibition of licensee's mitigation plan to recover archeological resources disturbed by coast of intake & discharge structures. W/IN Dept of Natural Resources ltr discussing plan. 79/04/22
 BALLARD, R. L. Environmental Projects Branch 2. 79/04/22
 2pp

790505043 Forward MARCO-0021, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Pumps" & notice of Licensee & availability. 79/04/22
 VORHALL, D. B. Assistant Director for Light Water Reactors 79/04/22
 3pp

790505021 Response to 790402 ltr re public coolers w/ improperly installed pressure. Matter will be reviewed in future Insp. 79/04/27
 PABELLI, J. O. Region 3, Chicago, Office of the Director 79/04/27
 1p

790505071 Notification of 790502 meeting w/UBI in Bethesda, MD to discuss Certified Personnel Panel's estimate for fuel test costs & submitted data for PWR. 79/04/23
 WOOD, S. A. Light Water Reactors Branch 4. 79/04/23
 4pp

790505076 Notification that lack of expected prehistoric resources justified termination of mitigation efforts. 79/04/20
 BALLARD, R. L. Environmental Projects Branch 1. 79/04/20
 2pp

790505042 Discusses NRC intention to delay PWR review until end of year delay in construction is based on average fuel test schedule. UBI is better than average & unit is committed for 1982 operation. PWR will be filed in June 1979. 79/05/04
 COOPER, L. J. Public Service Co. of Indiana, Inc. 79/05/04
 4pp

9 Adjudicatory correspondence

790503020 Motion to reopen safety hearings to discuss WASH-1400 & homicide 79.4.3-T. 79/03/20
 DATTILO, T. H. Marble Hill 79/03/20
 2pp

790502048 Forward NRC memo discussing problems experienced w/1st support beam plate design. Piping design analysis on existing case basis being reviewed under SSP Section 2.9.2. 79/04/05
 HENRICH, L. Branch 3. 79/04/05
 2pp

790502046 Forward 790402 memo from Director of Of. of Nuclear Reactor Regulation to Commissioner, discussing fire protection research test results conducted by UL. 79/04/05
 HENRICH, L. Branch 3. 79/04/05
 2pp

790504028 Forward latest motion to reopen safety hearings by F. DeBelle on behalf of Save the Valley - Save Marble Hill. Forward revisions to draft motions attached to 790402. 79/04/05
 KAPPLER, J. O. Rulemaking & Enforcement Division 79/04/05
 2pp

--790504022 Motion to suspend & revoke CP for proposed facility because of TMI incident. 79/04/04
 DATTILO, T. H. Marble Hill 79/04/04
 2pp

790504041 Response to ALAB-009 re radon emissions & de minimus threat from Perkins record. Certificate of BNC sent. 79/04/11
 KAPPLER, J. O. Hearings Division 79/04/11
 45pp

790504050 Response to 790404 brief of Philadelphia Electric Co. PEEC & Atlantic City LAMP Electric Co. re de minimus threat. Certificate of BNC sent. 79/04/11
 HENRICH, L. Branch 3. 79/04/11
 2pp

790504071 Act receipt of 790404 petition to inhibit civil suspension proceedings. Decision under consideration. Forward 790402 PR notice. 79/04/12
 DATTILO, T. H. Office of Nuclear Reactor Regulation 79/04/12
 1p

--790504012 PR notice of request to reopen safety hearing. 79/04/12
 DATTILO, T. H. Office of Nuclear Reactor Regulation 79/04/12
 2pp

--790504080 Forward motion of intervenor to reopen safety hearing. 79/04/12
 DATTILO, T. H. Office of Nuclear Reactor Regulation 79/04/12
 2pp

--790504072 Motion for ALAB to reopen safety hearings. 79/04/12
 DATTILO, T. H. Save the Valley - Save Marble Hill 79/04/12
 2pp

--790504064 Motion to reopen safety hearings due to EPA ban on herbicide & toxicity of WASH-1400. 79/04/12
 DATTILO, T. H. Save the Valley - Save Marble Hill 79/04/12
 3pp

790504032 Motion of consolidation of five intervenor groups re radon emissions issue. Parties have until 790525 to which to file for summary disposition. 79/04/25
 KAPPLER, J. O. Atomic Safety and Licensing Appeal Panel 79/04/25
 13pp

H. General correspondence

790504072 Discusses ability of Commissioner to reach objective decisions re nuclear power. In light of avc in promotional capacity w/ABC suggests add gov't funding for researching civilian energy needs. 79/04/26
 HENRICH, L. Branch 3. 79/04/26
 2pp

DOCKETED ITEMS

261

Q Inspection reports, IE Bulletins & correspondence

7902070386 Forwards IE Insp Repts 80-546/79-02 & 80-547/79-02 to
790227-0301 & notice of violation
FIDELLER, J. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/03/16. 2pp

--7905040370 Notice of violation from Insp on 790227-0301.
* Region 3, Chicago, Office of the Director 79/03/13 1p

--7905040373 IE Insp Repts 80-546/79-02 & 80-547/79-02 on 790227-0301
Noncompliance noted failure to have special storage
instruction for safety-related pump & meter
REACTOR, E. S., FIDELLER, J. F., RAPP, R. C. Region 3, Chicago,
Office of the Director 79/03/12 10pp

7903010260 Forwards IE Info Notice 79-06, "Stress Analysis of
Safety-Related Piping"
FIDELLER, J. Region 3, Chicago, Office of the Director 79/03/23
1p

7903040351 Forwards IE Info Notice 79-07, "History of Radiated Yards"
FIDELLER, J. Region 3, Chicago, Office of the Director 79/03/26
1p

7903030049 Forwards IE Bulletin 79-06, "Review of Operational Errors &
Sys Missalignments Identified During TMI Incident"
FIDELLER, J. Region 3, Chicago, Office of the Director 79/04/11
1p

7903010402 Forwards IE Bulletin 79-06A, "Review of Operational Errors &
Sys Missalignments Identified During TMI Incident"
FIDELLER, J. Region 3, Chicago, Office of the Director 79/04/14
1p

7903040423 Forwards IE Bulletin 79-06B, "Review of Operational Errors &
Sys Missalignments Identified During TMI Incident"
FIDELLER, J. Region 3, Chicago, Office of the Director 79/04/14
1p

7903040587 Forwards IE Bulletin 79-06, "Events Relevant to Boiling
Water Reactor Reactors Identified During TMI Incident"
FIDELLER, J. Region 3, Chicago, Office of the Director 79/04/14
1p

7903070467 Forwards IE Bulletin 79-07, "Dynamic Stress Analysis of
Safety-Related Piping" - Licensee action required
FIDELLER, J. Region 3, Chicago, Office of the Director 79/04/14
1p

7903010411 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support
Stems"
FIDELLER, J. Region 3, Chicago, Office of the Director 79/04/16
1p

7903030241 Forwards IE Bulletin 79-09, "Failures of GE Type AA-2
Circuit Breaker in Safety-Related Sys" - Licensee action
required.
FIDELLER, J. Region 3, Chicago, Office of the Director 79/04/17
1p

7903030587 Forwards IE Bulletin 79-08B, "Nuclear Incident at
TMI-2 (Cont.)"
FIDELLER, J. Region 3, Chicago, Office of the Director 79/04/21
1p

7903040691 Ack receipt of 790410 ltr re informing NRC of steps taken to
correct violations noted in IE Insp Repts 80-546/79-02 &
80-547/79-02.
FIDELLER, J. Region 3, Chicago, Reactor Construction & Engineering
Support Branch 79/04/23 1p

--7903040297 Response to NRC 790314 ltr re violations noted in IE Insp
Repts 80-546/79-02 & 80-547/79-02. Corrective actions: space
heaters energized & shafts retained.
COUHLIN, J. Public Service Co. of Indiana, Inc. 79/04/10. 2pp

7903020433 Response to IE Bulletin 79-05 re piping wdg by Youngstown
Rolling & Engineering Co. Piping not in use at Facility.
COUHLIN, J. Public Service Co. of Indiana, Inc. 79/05/03. 1p.

R Reportable occurrences, LRs & related correspondence

7905030529 Forwards R Schoel 79/011 ltr re HE Junction 790315 ltr re
subtle control defects & repairs.
FIDELLER, J. Region 3, Chicago, 79/04/03. 1p.

7905040400 Potential RO on 790407 two control rooms collided & fell,
striking containment liner. Vertical angle stiffener,
horizontal reinforcing bars & circular CR ring stiffener
were damaged. Containment rack to follow.
COUHLIN, J. Public Service Co. of Indiana, Inc. 79/05/01 1p

7903010420 Provides interim rept of RO on 790416 possible damage to two
positioning transmitters & surrounding concrete caused by
overheating from propane fired torches used to repair tendon
dirt. Repair procedures studied.
COUHLIN, J. Public Service Co. of Indiana, Inc. 79/05/16 1p

DOCKET 80-549 PORT CALHOUN STATION, UNIT 2

A Adjudicatory correspondence

7903240909 Forwards info on turbine behavior during postulated generator
take rupture accidents & ECCB performance characteristics
ORRIS, J. H. Branch 1 79/04/10 2pp

--7903241001 Discusses accumulator delivery comparisons for LDF tests
LI-3 & LI-4, & effect on ECCB performance
ORRIS, J. H. Assistant Director for Reactor Safety 79/03/03
2pp

7903010310 Forwards notifications re UL fire protection test. Lewis
Committee Rept, "Transportation of Radioisotopes in Urban
Environments" & neutron dosimetry
ORRIS, J. H. Branch 1 79/04/12 4pp.

7903240801 Submit annual rept on behalf of Util. Lawuit brought
by NE Public Power District against Util. has been settled.
Request further licensing procedures be held in absence
due to parallel suit
VOST, H. H. Lawuit, Lamb, Leiby & Hayes 79/04/20 1p

DOCKET 80-549 GREENE COUNTY NUCLEAR POWER PLANT

A Application/authorization stage documents & correspondence

7903030330 Comments on "Federal-State Authorities & Cooperation in
Nuclear Power Plant Licensing" outlines changes to NY ruling
law & attempts to eliminate duplication of regulatory
procedures between Federal & state agencies
SHULIMSKY, J. New York, State of, 79/04/24 4pp

B Adjudicatory correspondence

7903030339 Forwards interrogatories by NY Dept of Environ Conservation to
NY Dept of Public Bvt.
SHULIMSKY, J. New York, State of 79/03/06. 1p

--7903030247 Interrogatories of NY Dept of Environ Conservation to NY
Dept of Public Bvt.
SHULIMSKY, J. New York, State of, 79/03/09 3pp

7903040433 Forwards Board Notification 79-10 on reactor inspector
certs re RM plants, Certificate of Bvt and
SCDOTO, J. F. Hearings Division, 79/03/25. 14pp

7903030841 NRC meeting for med of 790323 Joint Board hearing extending
scheduled date in proceeding. Power for stay of filing dates
pending Util's rept to be filed on 790330. Certificate of Bvt
and
LORD, B. H.

7903010410

equipment

SCDOTO, J.

79030101

equipment

79030101

equipment

79030101

equipment

79030101

equipment

79030101

equipment

7905040428 Forwarded IE Bulletin 79-048, "Review of Operational Errors and Key Missions Identified During THE Incident."
REPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
1p

7905040509 Forwarded IE Bulletin 79-050, "Events Relevant to Boiling Water Reactors Identified During THE Incident."
REPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
1p

7905050167 Forwarded IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping." Licensee action required.
REPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
1p

7905050411 Forwarded IE Info Notice 79-16, "Nonconforming Pipe Support Struts."
REPLER, J. O. Region 3, Chicago, Office of the Director 79/04/14
1p

7905050541 Forwarded IE Bulletin 79-09, "Failures of SE Type AN-2 Circuit Breaker in Safety-Related Bus." Licensee action required.
REPLER, J. O. Region 3, Chicago, Office of the Director 79/04/17
1p

7905050557 Forwarded IE Bulletin 79-058, "Nuclear Incident at TW-3499."
REPLER, J. O. Region 3, Chicago, Office of the Director 79/04/21
1p

7905140091 Act receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-347/79-02 & 30-347/79-02
FIDELL, J. O. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/28
1p

7905140097 Response to NRC 790334 ltr re violations noted in IE Insp Repts 30-347/79-02 & 30-347/79-02. Corrective actions space heaters assigned & shifts rotated.
COUSHELM, J. Public Service Co. of Indiana, Inc. 79/04/10
1p

7905200433 Response to IE Bulletin 79-02 re piping wfy by Westinghouse Welding & Engineering Co. piping met in use at facility.
COUSHELM, J. Public Service Co. of Indiana, Inc. 79/03/03
1p

B. Reportable occurrences, USRs & related correspondence

7905200529 Forwarded E. Scheid 791121 ltr & NE Jackson 790313 ltr re tubular cooler defects & repairs.
KORSH, R. France Co. 79/04/23
1p

7905240400 Potential RD on 790409, bus coast crane collided & fell, striking containment liner. Vertical angle stiffener, horizontal reinforcing bars & circular CB ring stiffener were damaged. Evaluation req. to follow.
COUSHELM, J. Public Service Co. of Indiana, Inc. 79/05/09
1p

7905310420 Provides interim rep. of RD on 790414 possible damage to two post-tensioning straps & surrounding concrete caused by overloading from propane fired torques used to repair tendon duct repair procedure voided.
COUSHELM, J. Public Service Co. of Indiana, Inc. 79/05/16
1p

BOCKET 8790-50-547 MARBLE HILL NUCLEAR STATION, UNIT 3

a/Construction stage documents & correspondence

In re application for consent of purchase
- M78010 ltr from Attorney
Sims, Louisville re dredge &
ve Co. of Ind.
Cons. of Engineers, 79/11/36
7p.

1 plan to recover
of debris &
Resources ltr
Branch 2 79/09/02
2p

re & Evaluation of Stress
& notice of

glt Water Reactory,

customers w/ improperly
in Volume Insp.
f the Director 79/04/17

7905350171 Notification of 790520 meeting w/ultr in Bethesda-MD to discuss Detailed Forensic Panel's schedule for final load data & submittal data for FBR.
WARR, S. A. Light Water Reactors Branch 4 79/04/23
4p

7905350246 Notification that lack of expected prehistoric resources justify termination of mitigation efforts.
SHULMAN, L. Environmental Projects Branch 1 79/04/20
2p

7905390415 Discusses NRC intention to delay FBR review until end of October delay in USDOE's assessment based on average 100000 lbs. of debris. USDOE is better than average & unit is certified for 1982 operation. FBR will be filed in June 1979.
COUSHELM, J. Public Service Co. of Indiana, Inc. 79/05/04
4p

C. Regulatory correspondence

7905150202 Motion to reopen safety hearings to discuss NASH-1450 & heretofore "2.4.9-T"
DATTILIO, T. N. Dattilio, T. N. 79/05/02
2p

7905350448 Forwarded NRC memo discussing problems experienced w/pipe support base plate design. Piping design analysis on category case basis being reviewed under SRP Section 3.0.2.
RENNER, L. Branch 3 79/04/05
2p

7905200426 Forwarded 790527 memo from Director of Div of Nuclear Reactor Regulation to Commissioners discussing fire protection research test results conducted by IA.
SHULMAN, L. Branch 3 79/04/05
2p

7905140058 Forwarded latest motion to reopen safety hearings by T Dattilio on behalf of Rowe the Valley - Rowe Marble Hill
Forwarded revisions to draft motions attached to 790402
DATTILIO, T. N. Dattilio, T. N. 79/04/05
2p

7905140012 Motion to suspend & revoke CP for proposed facility because of TMI incident.
DATTILIO, T. N. Dattilio, T. N. 79/04/04
2p

7905140018 Response to ALAB-509 re radon emissions & de minimus theory from Partion record. Certificate of Rev. and
DATTILIO, T. N. Dattilio, T. N. 79/04/11
4p

7905140019 Response to 790404 brief of Philadelphia Electric Co. FBR 610 & Atlantic City OGD Electric Co. re de minimus theory.
Certificate of Rev. and
DATTILIO, T. N. Dattilio, T. N. 79/04/11
4p

7905140071 Act receipt of 790406 petition to institute consent suspension proceedings. Decision under consideration. Forwarded 790402
RE notice.
DATTILIO, T. N. Office of Nuclear Reactor Regulation 79/04/12
1p

7905240812 PR notice of request to reopen safety hearing.
MAY, R. B. Office of Nuclear Reactor Regulation 79/04/12
2p

7905240850 Forwarded motion of intervenor to reopen safety hearing, petition to revoke CP & PR notice.
DATTILIO, T. N. Office of Nuclear Reactor Regulation 79/04/12
2p

7905240872 Motion for ARLAB to reopen safety hearings.
DATTILIO, T. N. Rowe the Valley - Rowe Marble Hill 79/04/12
2p

7905240404 Motion to reopen safety hearings due to EPA ban on heretofore & availability of MARBLE-100.
DATTILIO, T. N. Rowe the Valley - Rowe Marble Hill 79/04/12
2p

7905140032 Notification of consideration of five intervenor groups re radon emissions issue. Partion have until 790520, in which to file for summary disposition.
DATTILIO, T. N. Atomic Safety and Licensing Appeal Panel 79/04/20
1p.

H. General correspondence

7905240723 Discusses ability of Commissioners to reach objective decisions re nuclear power, in light of rev in production capacity w/ARC. Suggests add joint funding for researching civilian energy needs.
MAY, R. B. Kentucky, State of, 79/04/20
2p.

DOCKETED ITEMS

261

Q Inspection reports, IE Bulletins & correspondence

7405092086 Forwards IE Insp Repts 80-846/79-02 & 80-847/79-02 on 7/27/80-025 & notice of violation
7405092086 L.S. Region 3, Chicago, Reactor Construction & Engineering Support Branch 7/27/80 13 App

7405092090 Notice of violation from Insp on 7/20/80-0351
Region 3, Chicago, Office of the Director 7/20/80 13 is

7405092093 IE Insp Repts 80-846/79-02 & 80-847/79-02 on 7/20/80-0351
Noncompliance noted failure to have special storage instruction for safety-related pump & motor
7405092093 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092095 Forwards IE Info Notice 79-06, "Stress Analysis of Safety-Related Piping"
7405092095 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092097 Forwards IE Info Notice 79-07, "Reprints of Radiologic Tests"
7405092097 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092099 Forwards IE Bulletin 79-06, "Review of Operational Errors & By Missalignments Identified During TMI Incident"
7405092099 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092102 Forwards IE Bulletin 79-06A, "Review of Operational Errors & By Missalignments Identified During TMI Incident"
7405092102 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092104 Forwards IE Bulletin 79-06B, "Review of Operational Errors & By Missalignments Identified During TMI Incident"
7405092104 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092106 Forwards IE Bulletin 79-06C, "Review of Operational Errors & By Missalignments Identified During TMI Incident"
7405092106 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092108 Forwards IE Bulletin 79-06D, "Events Relevant to Boiling Water Reactor Identified During TMI Incident"
7405092108 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092110 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping" Licensee action required
7405092110 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092112 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets"
7405092112 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092114 Forwards IE Bulletin 79-05, "Failures of SF Type AM-2 Circuit Breaker in Safety-Related Sgs." Licensee action required
7405092114 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092116 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-2"
7405092116 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092118 Act receipt of 790410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-846/79-02 & 80-847/79-02
7405092118 L.S. Region 3, Chicago, Reactor Construction & Engineering Support Branch 7/24/80 13 App

7405092120 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 80-846/79-02 & 80-847/79-02, corrective actions, spare headers equipped & charts related
7405092120 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092122 Responds to IE Bulletin 79-03 re piping wfg by Youngstown Machine & Engineering Co. Piping wfg done at facility
7405092122 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092124 Responds to IE Bulletin 79-03 re piping wfg by Youngstown Machine & Engineering Co. Piping wfg done at facility
7405092124 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092126 Responds to IE Bulletin 79-03 re piping wfg by Youngstown Machine & Engineering Co. Piping wfg done at facility
7405092126 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092128 Responds to IE Bulletin 79-03 re piping wfg by Youngstown Machine & Engineering Co. Piping wfg done at facility
7405092128 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092130 Responds to IE Bulletin 79-03 re piping wfg by Youngstown Machine & Engineering Co. Piping wfg done at facility
7405092130 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092132 Responds to IE Bulletin 79-03 re piping wfg by Youngstown Machine & Engineering Co. Piping wfg done at facility
7405092132 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092134 Responds to IE Bulletin 79-03 re piping wfg by Youngstown Machine & Engineering Co. Piping wfg done at facility
7405092134 L.S. Region 3, Chicago, Office of the Director 7/20/80 13 App

7405092136 Potential RO on 790409 two crank cranes collided & fell, striking containment liner. Vertical angle stiffener, horizontal reinforcing beam & circular CR ring stiffener were damaged. Evaluation ref to follow
7405092136 L.S. Public Service Co. of Indiana, Inc. 7/20/80 13 App

7405092138 Provides interim rep of RO on 790410 possible damage to two post-tensioning tendons & surrounding concrete. Caused by overloading from grout pipe torches used to repair tendon
7405092138 L.S. Public Service Co. of Indiana, Inc. 7/20/80 13 App

DOCKET 80-848 FORT CALHOUN STATION, UNIT 2
Q Adjudicatory correspondence

7405092140 Forwards info on iodine behavior during postulated generator tube rupture accidents & ROCS performance characteristics
7405092140 L.S. Branch 1 7/20/80 13 App

7405092142 Discusses accumulator delivery components for LOFT tests L1-2 & L1-4, & effect on ROCS performance
7405092142 L.S. Branch 1 7/20/80 13 App

7405092144 Forwards notification re UL fire protection test. Lewis Commission Rept, "Transportation of Radioisotopes in Urban Settings" & nuclear destruction
7405092144 L.S. Branch 1 7/20/80 13 App

7405092146 Submits transmittal ref on behalf of util. Lewis brought by NE Public Power Directorate against util. has been notified. Requests further licensing procedures be held in abeyance due to parallel util.
7405092146 L.S. LeBeau, Lamb, Leiby & MacLean 7/20/80 13 App

DOCKET 80-849 GREENE COUNTY NUCLEAR POWER PLANT
Q Adjudicatory correspondence

7405092148 Comments on "Federal-State Authorities & Cooperation in Nuclear Power Plant Licensing" outlines changes to NY siting law & attempts to eliminate duplication of regulatory processes between federal & state agencies
7405092148 L.S. New York, State of 7/20/80 13 App

7405092150 Forwards interagency by NY Dept of Environ Conservation to NY Dept of Public Soc.
7405092150 L.S. New York, State of 7/20/80 13 App

7405092152 Forwards interagency by NY Dept of Environ Conservation to NY Dept of Public Soc.
7405092152 L.S. New York, State of 7/20/80 13 App

7405092154 Forwards Board Notification 79-13 on reactor inspection concerns re RM plants Certificate of Env. qual.
7405092154 L.S. Hearings Division 7/20/80 13 App

7405092156 NRC action for mod of 790320 Joint Board ruling extending scheduled dates in proceeding. Moves for stay of filing dates pending util's ref to be filed re 790320. Certificate of Env. qual.
7405092156 L.S. Branch 2 7/20/80 13 App

7405092158 Forwards request for Board notification re non-safety-grade equipment to be used in tests.
7405092158 L.S. Hearings Division 7/20/80 13 App

7405092160 Board notification re assessment re non-safety-grade equipment to mitigate transients.
7405092160 L.S. Assistant Director for Light Water Reactors 7/20/80 13 App

7405092162 Board notification re assessment re non-safety-grade equipment to mitigate transients. More info is required.
7405092162 L.S. Assistant Director for Reactor Safety 7/20/80 13 App

7405092164 Forwards transmittal memo for document which contains info potentially relevant to issue of sabotage of spent nuclear fuel. NRC want.
7405092164 L.S. Branch 2 7/20/80 13 App

Q Reportable occurrences, LERs & related correspondence

7405092166 Forwards K Schaef 791121 ltr & ME Jensen 790315 ltr re cubicle control defects & repairs.
7405092166 L.S. Trade Co 7/20/80 13 App

7405092168 Forwards K Schaef 791121 ltr & ME Jensen 790315 ltr re cubicle control defects & repairs.
7405092168 L.S. Trade Co 7/20/80 13 App

7405092170 Forwards K Schaef 791121 ltr & ME Jensen 790315 ltr re cubicle control defects & repairs.
7405092170 L.S. Trade Co 7/20/80 13 App

7405092172 Forwards K Schaef 791121 ltr & ME Jensen 790315 ltr re cubicle control defects & repairs.
7405092172 L.S. Trade Co 7/20/80 13 App

DOCKETED ITEMS

7903070141 Forwards draft report on sabotage attacks on 4000 Fuel Transportation system. Report is first one available re high level explosive attack on spent fuel shipping casks WFO and CARTON, T. F. Division of Nuclear Regulation 79/03/22 App.

7903010122 Board notification Nuclear Incident at THE Reactors located on cases involving BBN reactors be provided with Bulletin 79-05 & 79-07 & 20A, B, C, D, E, F, G & H. WILKINS, D. S. Assistant Director for Light Water Reactors 79/04/03 App.

7903200080 Suspends further hearings re suit's application for certificate for authority to construct & operate plant. Grants 790329 Interlocutory appeal of State of NY Dept of Public Use Certificate of One and One Half Acres. State of NY 79/04/05 App.

7903010180 Forwards requested summary of 790401 balloon w/tilt re parallel to construct nuclear facility. HOSKE, J. E. Branch 2 79/04/12 App.

7903040080 Motion by Greene County & towns of Athens & Catehitt in support of AEC & NY Dept of Public Use 790405 motion to dismiss application & terminate proceeding & in opposition to applicant's 790404 alternative request. BOUTZ, A. R. Motion & Answer 79/04/22 App.

7903200067 Forwards draft "Historical & Cultural Context of Proposed Greene County Nuclear Power Plant." Requests certain data not be reproduced due to copyrights. LEWIS, B. H. Branch 3 79/04/20 App.

J Insurance & Indemnity Information

7903070497 Confirms increased liability limit to \$124,000,000 for policies 89-1, 25, 63, 74, 83, 100, 111, 140, 144, 151, 141, 144, 170, 173, 174, 178, 179, 182, 183, 185, 186, 187, 188, 189, 192, 193, 194, 195, 197, 198, 200, 201, 204, 205, 207, 208, 210, 213, 214, 215 & others. SMITH, T. M. American Nuclear Insurance, 79/05/01 App.

7903070282 Confirms increase in liability limit to \$36,000,000 for policies 89-26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, B. M. Mutual Atomic Energy Liability Underwriters 79/03/01 App.

B Reportable occurrences, LERs & related correspondence

7903102003 Board notification Westbrook refueling water storage tank design deficiency. SCHULTZ, J. Hearings Division 79/03/29 App.

DOCKET 87H-30-390 OGDEN-300-ROF INTERFAZE

J Insurance & Indemnity Information

7903070282 Confirms increase in liability limit to \$36,000,000 for policies 89-26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95 & 96. ROBERTS, B. M. Mutual Atomic Energy Liability Underwriters 79/03/01 App.

DOCKET 87H-30-583 PHIPPS BEND NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

7903100090 Discusses 790229 site visit re addl fault found in core cooling water trench. Unit 1 provide description of trench fault, discussion of fault's relationship to regional geology & fault area mapping. WILKINS, D. S. Hearings Division 79/04/17 App.

7903040343 Forwards description of addl fault discovered beneath equipment cooling water pumping station. Fault not considered to be capable of core overheat draining. Unit 1. WILKINS, D. S. Tennessee Valley Authority, 79/04/30 App.

7903080041 Discusses unit position on leak testing, pressure & temp requirements of AEC State 313 & 349 per piping to be embedded in concrete. Revision to 790308 re embedded piping will be implemented immediately. WILKINS, D. S. Tennessee Valley Authority, 79/05/05 App.

7903100070 Describes adjusted route for transporting reactor pressure vessels. Unit 1 finds evidence impact to be within scope of original analysis. WILKINS, D. S. Tennessee Valley Authority, 79/05/07 App.

F Security, medical, emergency & fire protection plans

7903030048 Forwards addl responses to 790304 meeting minutes re STRIDE fire hazards analysis. Includes proposed design changes to fire protection and Requests early meeting to discuss responses. GILLILAND, J. C. Tennessee Valley Authority 79/05/20 App.

G Application correspondence

7903040074 Requests adoption of de minimis theory of Perkins ALE Certificate of One and One Half Acres. WILKINS, D. S. Tennessee Valley Authority 79/04/05 App.

7903100408 Response to ALE-300 re action measures & de minimis theory. Free Perkins record Certificate of One and One Half Acres. GENTON, J. F. Hearings Division 79/04/11 App.

7903100319 Response to 790404 brief of Philadelphia Electric Co./PECO's Atomic City (ACU) Electric Co re de minimis theory. Certificate of One and One Half Acres. WILKINS, D. S. Citizens for Safe Environment, 79/04/11 App.

7903100333 Notification of consolidation of fire intervention groups re radio selection issue. Parties have until 790323 at which to file for summary disposition. DUFF, R. E. Atomic Safety and Licensing Appeal Panel, 79/04/23 App.

G Inspection reports, IE Bulletins & correspondence

7903010041 Forwards IE Info Notice 79-04, "Stress Analysis of Safety-Related Piping." O'BRIEN, J. P. Region 2, Atlanta: Office of the Director 79/03/29 App.

7903030038 Forwards IE Bulletin 79-07, "Stress Analysis of Safety-Related Piping - Licensee action required." O'BRIEN, J. P. Region 2, Atlanta: Office of the Director 79/04/14 App.

7903040033 Forwards IE Bulletin 79-08, "Review of Operational Errors & Key Missions Identified During ENI Incident." O'BRIEN, J. P. Region 2, Atlanta: Office of the Director 79/04/14 App.

7903100268 Forwards IE Bulletin 79-09, "Events Relevant to Boiling Water Reactor Identified During ENI Incident." O'BRIEN, J. P. Region 2, Atlanta: Office of the Director 79/04/14 App.

7903010041 Forwards IE Info Notice 79-10, "Nonconforming Pipe Support Brackets." O'BRIEN, J. P. Region 2, Atlanta: Office of the Director 79/04/18 App.

7903030038 Forwards IE Bulletin 79-09, "Failures of OE Type AW-2 Circuit Breaker in Safety-Related Sys." Licensee action required. O'BRIEN, J. P. Region 2, Atlanta: Office of the Director 79/04/17 App.

7903030038 Forwards IE Bulletin 79-04a, Revision 1, "Review of Operational Errors & Key Missions Identified During ENI Incident." O'BRIEN, J. P. Region 2, Atlanta: Office of the Director, 79/04/18 App.

7903030033 Submits supplemental response to IE Bulletin 77-07, Original response submitted 790120. Provides addl info received from manufacturer & describes plans in area of electrical penetrations. GILLILAND, J. C. Tennessee Valley Authority 79/04/27 App.

B Reportable occurrences, LERs & related correspondence

7903040070 Forwards final report of reportable condition re 31H/4 & 31H/5 local control panels. (NRC 50-79-001). GILLILAND, J. C. Tennessee Valley Authority, 79/04/05 App.

7903100080 Reportable condition re 790304, SE determined that defect existed in 31H/5 panel H2S-7025, caused by installation of nonqualified type relay. Procedures revised & QA program modified. Tennessee Valley Authority 79/04/05 App.

DOCKETED ITEMS

263

DOCKET 87H-00-054 PHIPPS BEND NUCLEAR PLANT, UNIT 2

A Application/Construction stage documents & correspondence

790505092 Discusses 790329 site visit re add fault found in core cooling water branch unit to provide description of branch fault, discussion of fault's relationship to regional geology & fault area mapping
HILLER, L. W. Tennessee Valley Authority 79/04/17 App

790505093 Forwards description of add fault discovered beneath concrete cooling water pumping station. Fault not considered to be capable of one overlying (drawing encl)
HILLER, L. W. Tennessee Valley Authority 79/04/20 App

790505094 Discusses unit position on leak testing, pressure & temp requirements of ACI Steel 208 & 209 for piping to be embedded in concrete. Revision to 790408 re embedded piping will be implemented immediately
HILLER, L. W. Tennessee Valley Authority 79/05/02 App

790505095 Describes adjusted note for transporting reactor pressure vessels. Unit finds adverse impact to be within scope of original analysis
HILLER, L. W. Tennessee Valley Authority 79/05/07 App

F Security, medical, emergency & fire protection plans

790505096 Forwards add response to 790504 meeting minutes re BTRIDE fire hazard analysis. Includes proposed design changes to fire protection. Re Requests marj meeting to discuss responses
HILLER, L. W. Tennessee Valley Authority 79/05/20 App

G Adjudicator correspondence

790505097 Response to ALAB-507 re radon analysis & de minimus theory from Perkins record Certificate of Bv encl
BCHEND, J. F. Hastings Division 79/04/11 App

790505098 Response to 790408 brief of Philadelphia Electric Co. PMS&S & Atlantic City (AC) Electric Co re de minimus theory Certificate of Bv encl
KAMPF, C. R. Citizens for Safe Environment, Inc. 79/04/11 App

790505099 Notices of cancellation of five intervenor groups re radon analysis (see Perkins have until 790503 in which to file for summary disposition)
DUPON, R. E. Atomic Safety and Licensing Appeal Panel 79/04/25 App

H Inspection reports, DE Bulletin & correspondence

790505100 Forwards DE Info Notice 79-26, "Stress Analysis of Safety-Related Piping," Region 2, Atlanta, Office of the Director
O'BRIEN, J. P. 79/03/23 App

790505101 Forwards DE Bulletin 79-07, "Stress Analysis of Safety-Related Piping," Licensee action required
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director, 79/04/14 App

790505102 Forwards DE Bulletin 79-08, "Review of Operational Errors & Re Investigations Identified During TMI Incident,"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director 79/04/14 App

790505103 Forwards DE Bulletin 79-09, "Events Relevant to Boiling Water Reactor Identified During TMI Incident,"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director, 79/04/14 App

790505104 Forwards DE Info Notice 79-10, "Noninterfering Pipe Support Stress,"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director, 79/04/18 App

790505105 Forwards DE Bulletin 79-07, "Failures of QC Type AN-2 Circuit Breaker in Safety-Related Sys," Licensee action required
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director 79/04/17 App

790505106 Forwards DE Bulletin 79-08, "Review of Operational Errors & Re Investigations Identified During TMI Incident,"
O'BRIEN, J. P. Region 2, Atlanta, Office of the Director, 79/04/18 App

790505107 Submits supplemental response to DE Bulletin 79-07, Original response submitted 790329, Provides add info received from manufacturer & describes plans in area of electrical penetrations.
HILLER, L. W. Tennessee Valley Authority 79/04/27 App

B Repeatable occurrences, LED's & related correspondence

790505108 Forwards final rept of repeatable condition re Bv/S HPCB local control panels (OSC DE-79-01)
HILLER, L. W. Tennessee Valley Authority 79/04/05 App

790505109 Repeatable condition on 790505 DE determined that defect existed in HPCB panel H22-P228 caused by installation of nonqualified type relay. Procedures revised & DA program modified
HILLER, L. W. Tennessee Valley Authority 79/04/05 App

DOCKET 87H-00-056 BLACK FOX STATION, UNIT 1

A Application/Construction stage documents & correspondence

790505110 Forwards NUREG-5801, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability of encl
HILLER, L. W. Assistant Director for Light Water Reactors 79/03/23 App

790505111 Notification of 790503-04 geologic site visit w/utill in TMI-02 to observe site excavation & geologic mapping activities
HILLER, L. W. Light Water Reactors Branch 1 79/04/05 App

C NRC Safety Evaluation Report (SER), update & correspondence

790505112 Forwards Suppl 2 re SER
HILLER, L. W. Light Water Reactors Branch 4 79/04/05 App

D Adjudicator correspondence

790505113 Response by utill in opposition to intervenors' 790303 motion to supply record w/Tulsa Metropolitan Area Urban Shog, Draft, Summary Resolutions & Study, prepared by Tulsa Army Corps of Engineers M/Certificate of Bv encl
HILLER, L. W. Tulsa Area Office 79/03/14 App

790505114 Applicant's response to intervenors' 790307 motion to file supplemental brief & to intervenors' supplemental brief (see Brief concerns failure to consider Class 9 accidents in previous review Certificate of Bv encl
HILLER, L. W. Tulsa Area Office 79/03/16 App

790505115 NRC response in opposition to intervenors' 790303 motion to supply record w/Tulsa Metropolitan Area Urban Shog, Draft, Summary Resolutions & Study, prepared by Tulsa Army Corps of Engineers Certificate of Bv encl
HILLER, L. W. Branch 4 79/03/16 App

790505116 NRC response to intervenors' 790304 motion to file supplemental brief re latter's Exceptions 112 & 113 Certificate of Bv encl
HILLER, L. W. Branch 4 79/03/23 App

790505117 Forwards request equipment to mitigate to: SCINTO, J. P. Hear

790505118 Forwards request equipment to mitigate to: SCINTO, J. P. Hear

790505119 Forwards request equipment to mitigate to: SCINTO, J. P. Hear

790505120 Forwards request equipment to mitigate to: SCINTO, J. P. Hear

790505121 Forwards request equipment to mitigate to: SCINTO, J. P. Hear

790505122 Forwards request equipment to mitigate to: SCINTO, J. P. Hear

DOCKETED ITEMS

790320062 Forwards errors sheet correcting errors in findings of fact & conclusions of law submitted 7903026 & 28
DALLS, J. Ishaan, Lincoln & Seale 79/04/09 App

790320069 Intervenor Citizens Action for Safe Energy, L. Burrell & J. Youstain regulations re interconnection of Age of both reactors. In event of accident at one reactor affecting safe operation at other reactor.
DANTE, L. D. Branch 4 79/04/11 App

790320087 Notice of filing of intervenors Citizens for Safe Energy, L. Burrell & J. Youstain proposed findings of fact, conclusions of law & proposed order in form of partial initial decision Certificate of Doc and
FARRIS, J. R. Green, Feldman, Hall & Woodard 79/04/12 App

790320093 Intervenor Citizens Action for Safe Energy, L. Burrell & J. Youstain proposed findings of fact, conclusions of law & proposed order in form of partial initial decision re radiological health & safety matters
FARRIS, J. R. & SODERBERG, J. R. Green, Feldman, Hall & Woodard 79/04/12 App

790320094 Proposed findings of fact & conclusions of law in form of initial decision re radiological health & safety matters
M/S supporting documentation
DAVIS, D. L. & PATRICK, M. D. Branch 4 M/S/SEAD, C. F. Branch 3 79/04/13 App

790320094 Requests Read reply & submit reply to be returned to SE Repts will be made available for NRC review, if needed Certificate of Doc and
EDGAR, G. L. Morgan, Lewis & Boeckle 79/04/13 App

790320095 Requests extension until 790426 to file EDCB portion of proposed findings of fact & conclusions of law Certificate of Doc and
DAVIS, D. L. Branch 4 79/04/16 App

790320099 Proposed findings of fact & conclusions of law in form of initial decision re radiological health & safety matters.
M/S EDCB section Certificate of Doc and
DAVIS, D. L. Branch 4 79/04/16 App

790320099 Requests Read Reply to be maintained in confidence pending ARL ruling re whether reply should be reduced to SE
EDGAR, G. L. Morgan, Lewis & Boeckle 79/04/18 App

790320099 Moves for indefinite stay of proceeding concerning issuance of initial decision pending investigation of TH-6 & hearings re facility financing Certificate of Doc and
SODERBERG, J. R. & CARTWRIGHT, J. E. Oklahoma, State of 79/04/19 App

790320099 Ack receipt of 790419 for Request basis is hypotheticals
NRC personnel have requested ARL for access to Read Reply NRC technical & legal staff will not have access to report until 790420
MORFEE, J. J. Atomic Safety and Licensing Board Panel 79/04/19 App

790320099 Advice that motion has been filed to stay issuance of initial decision.
ROGERS, C. Oklahoma, State of 79/04/19 App

790320099 Errors sheet & table of contents to applicants 790426 reply to proposed findings of fact & conclusions of law filed by NRC & intervenors
Ishaan, Lincoln & Seale 79/04/20 App

790320094 Response by intervenors Citizens Action for Safe Energy, L. Burrell & J. Youstain supporting adoption of motion by State of OK for indefinite stay in issuance of initial decision Certificate of Doc and
FARRIS, J. R. Green, Feldman, Hall & Woodard 79/04/22 App

790320094 Forwards info re schedule & cost analysis. Commercial operation for Unit 1 shall begin on 05/07/01 & for Unit 2 on 05/05/01 Applicants file reply to NRC & intervenors' proposed findings of fact & conclusions of law on 790426
DALLS, J. Ishaan, Lincoln & Seale, 79/04/30 App

790320094 Grants extension until 790509 to file proposed findings of fact re EDCB per NRC 790426 request
MORFEE, J. J. Atomic Safety and Licensing Board Panel 79/05/01 App

790320094 Grants extension until 790501 for until & NRC to file answers to motion by State of OK for indefinite stay of issuance of initial decision
MORFEE, J. J. Atomic Safety and Licensing Board Panel 79/05/01 App

H General correspondence

790320079 Requests info re June 1979 hearing in Phoenix, AZ Greg wants to send delegation to hearing
Nuclear Free State 79/03/08 App

790320083 Bellview SE should publish Read Reply re unacceptable safety issues Opposes nuclear plant cost Supporter solar & wind power research
BELOCK, T. Affiliation Unknown 79/04/16 App

790320097 Urges NRC to release all portions of transcripts of safety hearings, including portions dealing with Read Reply
GARRATT, R. & SODERBERG, J. Affiliation Unknown 79/04/17 App

I Financial information

790320094 Requests add financial info on updated cost estimates in order to complete review of revised financial info.
EDGAR, G. L. Public Service Co of Oklahoma 79/05/07 App

790320097 Annual Financial Rept 1978
Central & Southwestern Services, Inc. 79/05/09 App

790320099 Annual Financial Rept 1978
Public Service Co of Oklahoma 79/05/09 App

790320094 Requests add financial info in response to NRC 790307 request Previous info was solely to assist of cost & schedule study & not in response to motions to intervene
Govt link
EDGAR, G. L. Public Service Co of Oklahoma 79/05/14 App

790320099 Requests to NRC 790301 request for add info until 790420 for included all available financial info
EDGAR, G. L. Public Service Co of Oklahoma 79/05/14 App

J Inspection reports, SE Bulletin & correspondence

790320094 Forwards SE Ins Repts 30-054/79-02 & 30-057/79-02 on 790306-04. No noncompliance noted
EDGAR, G. L. Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/02 App

790320097 IE Ins Repts 30-054/79-02 & 30-057/79-02 on 790306-04. No noncompliance noted Major areas inspected: cost status, development of concrete mix design, training & indoctrination & QA
BURMAN, W. C. & CROSBY, W. L. & HALL, R. E. Region 4, Dallas, Office of the Director 79/05/02 App

DOCKET ITEM 30-037 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

7903200482 Forwards MURDOCK-0501, "Investigation & Evaluation of Stress Corrosion Cracking in Piping of LWR Plants" & notice of issuance & availability W/S and
MORFEE, J. J. Assistant Director for Light Water Reactors 79/05/02 App

790320048 Notification of 790303-04 seismic site visit will be held. OK to observe site excavation & seismic modeling activities.
EDGAR, G. L. Light Water Reactors Branch 1 79/04/06 App

C. NRC Safety Evaluation Report (SER), supply & correspondence

790320068 Forwards Serp 2 to NRC.
MORFEE, J. J. Light Water Reactors Branch 4 79/04/05 App

D. Administrative correspondence

790320094 Response by until in opposition to intervenors' 790301 motion to compel record w/ Tulsa Metropolitan Area, Tulsa Urban Study/Draft Summary Repts/Summary 2 Grade prepared by Tulsa Army Corps of Engineers. W/Certificate of Doc.
MORFEE, J. J. & SODERBERG, J. E. Ishaan, Lincoln & Seale, 79/05/14 App

790320098 Applicants' response to intervenors' 790307 motion to file brief re: brief concerning failure to consider Class 9 accidents in written Review Certificate of Doc and
MORFEE, J. J. & SODERBERG, J. E. Ishaan, Lincoln & Seale, 79/05/16 App

DOCKETED ITEMS

285

- 7905010021 NRC response in opposition to intervenors 790301 action to appeal record of Tulsa Metropolitan Area Urban Study Draft, Summary Report-Stage 2 Study prepared by Tulsa Army Corps of Engineers Certificate of Env. eval.
SARVIS, D Branch 4 79/03/19 App
- 7905010022 NRC response to intervenors 790301 action to file supplemental brief re letter's Exceptions 112 & 113 Certificate of Env. eval.
SARVIS, D Branch 4 79/03/02 App
- 7905010115 Forwarded request for Reed notification re non-safety-grade equipment to mitigate transients
SCIND, J.F. Hearings Division 79/04/02 App
- 7905010150 Reed notification staff assessment re non-safety-grade equipment to mitigate transients
SARVIS, D Branch 4 Assistant Director for Light Water Reactors. 79/03/29 App
- 7905010170 Reed notification recent issue on non-safety-grade equipment to mitigate transients
SARVIS, D Branch 4 Assistant Director for Reactor Safety 79/03/16 App
- 7905010222 Requests extension until 790412 to file proposed findings of fact & conclusions of law Certificate of Env. eval.
FARRIS, J.R. Citizens Action For Safe Energy 79/04/03 App
- 7905010275 Declines to file proposed findings of fact & conclusions of law in limited record Certificate of Env. eval.
THORNTON, D. & ROBERTS, C.E. Oklahoma, State of 79/04/05 App
- 7905100059 Forwarded MURED-0150, Mar 1979, Suppl. 2 to MUR
SARVIS, D Branch 4 79/04/09 App
- 7905020362 Forwarded errata sheet correcting errors in findings of fact & conclusions of law submitted 790328 to 2P
GALL, J. Idaho, Lincoln & Seale 79/04/09 App
- 7905020389 Discusses regulations re interconnection of sig. of both reactors in event of accident at one reactor affecting safe operation at other reactor
SARVIS, D Branch 4 79/04/03 App
- 7905140347 Notice of Filing of Intervenor Citizens For Safe Energy, L. Burrell & J. Youngblood proposed findings of fact, conclusions of law & proposed order in form of partial initial decision Certificate of Env. eval.
FARRIS, J.R. Green, Feldman, Hall & Hordard 79/04/12 App
- 7905140350 Intervenor Citizens Action For Safe Energy, L. Burrell & J. Youngblood proposed findings of fact, conclusions of law & proposed order in form of partial initial decision re radiological health & safety matters
FARRIS, J.R. & ROBERTS, C.E. Green, Feldman, Hall & Hordard. 79/04/12 App
- 7905100236 Proposed findings of fact & conclusions of law in form of initial decision re radiological health & safety matters
W/Supporting documentation.
SARVIS, D Branch 4, PATRICK, D. Branch 4, ROBERTS, C.E. Branch 4 79/04/02 App
- 7905020314 Requests Reed reply & submit reply be returned to GE. Reply will be made available for NRC review if needed Certificate of Env. eval.
EDGAR, R.L. Morgan, Lewis & Bostick 79/04/12 App
- 7905100213 Requests extension until 790405 to file 8028 portion of proposed findings of fact & conclusions of law Certificate of Env. eval.
SARVIS, D Branch 4 79/04/14 App
- 7905100219 Proposed findings of fact & conclusions of law in form of initial decision re radiological health & safety matters
W/8228 section Certificate of Env. eval.
SARVIS, D Branch 4 79/04/16 App
- 7905020329 Requests Reed reply be withheld in confidence pending ABL review on whether report should be returned to GE.
EDGAR, R.L. Morgan, Lewis & Bostick. 79/04/18 App
- 7905100643 Review for indefinite stay of proceeding concerning issuance of initial decision pending investigation of TMS-2 & hearings re facility financing Certificate of Env. eval.
THORNTON, D. & ROBERTS, C.E. & GARNETT, J.E. Oklahoma, State of. 79/04/10 App
- 7905103475 Ack receipt of 790418 ltr Request basis is hypotheticalism
NRC staff will be made available for access to Reed Reply NRC technical & legal staff will not have access to request until 790430
MURPHY, J.R. Atomic Safety and Licensing Board Panel 79/04/17 App
- 7905020379 Advice that motion has been filed to stay issuance of initial decision
SCIND, J.F. Oklahoma, State of. 79/04/17 App
- 7905020379 Errata sheet & table of contents to applicants 790426 reply to proposed findings of fact & conclusions of law filed by NRC (Intervenor)
* Idaho, Lincoln & Seale. 79/04/26 App
- 7905100924 Response by Intervenor Citizens Action For Safe Power, L. Burrell & J. Youngblood supporting adoption of motion by State of OK for indefinite stay in issuance of initial decision Certificate of Env. eval.
FARRIS, J.R. Green, Feldman, Hall & Hordard 79/04/27 App
- 79050203175 Forwarded info re schedule & cost analysis Commercial operation for Unit 1 shall begin on 03/07/01 & for Unit 2 on 03/07/01 Applicants filed reply to NRC & intervenors' proposed findings of fact & conclusions of law on 790426
GALL, J. Idaho, Lincoln & Seale 79/04/30 App
- 7905030360 Grants extension until 790509 to file proposed findings of fact re 8028 per NRC 790328 request.
MURPHY, J.R. Atomic Safety and Licensing Board Panel 79/03/01 App
- 7905030370 Grants extension until 790511 for stay of NRC to file answers to motion by State of OK for indefinite stay of issuance of initial decision
MURPHY, J.R. Atomic Safety and Licensing Board Panel 79/03/01 App
- II Several correspondence
- 7905030377 Requests info re June 1979 hearing in Phoenix, AZ Group wants to send delegation to hearing.
* Nuclear Free State 79/03/25 App
- 7905030352 Believes GE should which Reed Reply re unacceptable safety issues discuss nuclear plant control computer system & wind power research
SCIND, J.F. Affiliation Unknown. 79/04/16 App
- 7905030377 Urges NRC to release all portions of transcripts of safety hearings, including portions dealing w/Reed Reply
GARNETT, J. & GARNETT, J. Affiliation Unknown 79/04/17 App
- III. Financial Information
- 7905030377 Requests add financial info in updated cost estimates in order to complete review of revised financial info
MURPHY, J.R. Public Service Co. of Oklahoma 79/03/07 App
- 7905030357 "Annual Financial Plan 1978"
* Central & Southeast Services Inc. 79/03/07 App
- 7905030357 "Annual Financial Plan 1978"
* Public Service Co. of Oklahoma 79/03/07 App
- 7905030342 Submits add financial info in response to NRC 790307 request Practices info was solely to advise of cost & schedule study & not in response to motions to intervene.
See ltr. eval.
EDGAR, R.L. Public Service Co. of Oklahoma. 79/03/14 App
- 7905040375 Response to NRC 790301 request for add info. Util 790430 ltr included all available financial info
EDGAR, R.L. Public Service Co. of Oklahoma 79/04/14 App
- 6 Inspection reports, DE Bulletin & correspondence
- 7905100804 Forwarded 1E Insp Report 80-286/79-02 & 80-287/79-02 on 790326-09. No correspondence noted.
SCIND, J.F. Region 4, Dallas: Reactor Construction & Engineering Support Branch. 79/03/23 App
- 7905100370 Insp Report 80-286/79-02 & 80-287/79-02 on 790326-09 No non-compliance noted Major areas inspected: cond. station, development of concrete mix design, training & indoctrination
MURPHY, J.R. & GARNETT, J. & HALL, R.E. Region 4, Dallas: Office of the Director. 79/03/23 App

DOCKETED ITEMS

DOCKET 80-86A NUCLEAR FUELS RECOVERY & RECYCLE CENTER

J Insurance & indemnity information

7905030497 Confirms increased liability limit to \$124,000,000 for policies NF-1,25,43,74,82,105,111,140,146,181,181,184,192,175,174,178,179,180,182,182,184,187,188,197,190,193,194,195,197,198,200,201,204,204,207,208,210,212,214,215; & others QUMT800441-J American Nuclear Insurers 79/05/01 3p

7905030582 Confirms increase in liability limit to \$26,000,000 for policies NF-23,24,29,35,39,44,46,47,49,50,81,90,93,94,95,96,97,98,99,101,104,107,109,110,111,112,113,114,115,116,117,118,119,120,121,122,123,124,125,126,127,128,129,130,131,132,133,134,135,136,137,138,139,140,141,142,143,144,145,146,147,148,149,150,151,152,153,154,155,156,157,158,159,160,161,162,163,164,165,166,167,168,169,170,171,172,173,174,175,176,177,178,179,180,181,182,183,184,185,186,187,188,189,190,191,192,193,194,195,196,197,198,199,200,201,202,203,204,205,206,207,208,209,210,211,212,213,214,215,216,217,218,219,220,221,222,223,224,225,226,227,228,229,230,231,232,233,234,235,236,237,238,239,240,241,242,243,244,245,246,247,248,249,250,251,252,253,254,255,256,257,258,259,260,261,262,263,264,265,266,267,268,269,270,271,272,273,274,275,276,277,278,279,280,281,282,283,284,285,286,287,288,289,290,291,292,293,294,295,296,297,298,299,300,301,302,303,304,305,306,307,308,309,310,311,312,313,314,315,316,317,318,319,320,321,322,323,324,325,326,327,328,329,330,331,332,333,334,335,336,337,338,339,340,341,342,343,344,345,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360,361,362,363,364,365,366,367,368,369,370,371,372,373,374,375,376,377,378,379,380,381,382,383,384,385,386,387,388,389,390,391,392,393,394,395,396,397,398,399,400,401,402,403,404,405,406,407,408,409,410,411,412,413,414,415,416,417,418,419,420,421,422,423,424,425,426,427,428,429,430,431,432,433,434,435,436,437,438,439,440,441,442,443,444,445,446,447,448,449,450,451,452,453,454,455,456,457,458,459,460,461,462,463,464,465,466,467,468,469,470,471,472,473,474,475,476,477,478,479,480,481,482,483,484,485,486,487,488,489,490,491,492,493,494,495,496,497,498,499,500,501,502,503,504,505,506,507,508,509,510,511,512,513,514,515,516,517,518,519,520,521,522,523,524,525,526,527,528,529,530,531,532,533,534,535,536,537,538,539,540,541,542,543,544,545,546,547,548,549,550,551,552,553,554,555,556,557,558,559,560,561,562,563,564,565,566,567,568,569,570,571,572,573,574,575,576,577,578,579,580,581,582,583,584,585,586,587,588,589,590,591,592,593,594,595,596,597,598,599,600,601,602,603,604,605,606,607,608,609,610,611,612,613,614,615,616,617,618,619,620,621,622,623,624,625,626,627,628,629,630,631,632,633,634,635,636,637,638,639,640,641,642,643,644,645,646,647,648,649,650,651,652,653,654,655,656,657,658,659,660,661,662,663,664,665,666,667,668,669,670,671,672,673,674,675,676,677,678,679,680,681,682,683,684,685,686,687,688,689,690,691,692,693,694,695,696,697,698,699,700,701,702,703,704,705,706,707,708,709,710,711,712,713,714,715,716,717,718,719,720,721,722,723,724,725,726,727,728,729,730,731,732,733,734,735,736,737,738,739,740,741,742,743,744,745,746,747,748,749,750,751,752,753,754,755,756,757,758,759,760,761,762,763,764,765,766,767,768,769,770,771,772,773,774,775,776,777,778,779,780,781,782,783,784,785,786,787,788,789,790,791,792,793,794,795,796,797,798,799,800,801,802,803,804,805,806,807,808,809,810,811,812,813,814,815,816,817,818,819,820,821,822,823,824,825,826,827,828,829,830,831,832,833,834,835,836,837,838,839,840,841,842,843,844,845,846,847,848,849,850,851,852,853,854,855,856,857,858,859,860,861,862,863,864,865,866,867,868,869,870,871,872,873,874,875,876,877,878,879,880,881,882,883,884,885,886,887,888,889,890,891,892,893,894,895,896,897,898,899,900,901,902,903,904,905,906,907,908,909,910,911,912,913,914,915,916,917,918,919,920,921,922,923,924,925,926,927,928,929,930,931,932,933,934,935,936,937,938,939,940,941,942,943,944,945,946,947,948,949,950,951,952,953,954,955,956,957,958,959,960,961,962,963,964,965,966,967,968,969,970,971,972,973,974,975,976,977,978,979,980,981,982,983,984,985,986,987,988,989,990,991,992,993,994,995,996,997,998,999,1000,1001,1002,1003,1004,1005,1006,1007,1008,1009,1010,1011,1012,1013,1014,1015,1016,1017,1018,1019,1020,1021,1022,1023,1024,1025,1026,1027,1028,1029,1030,1031,1032,1033,1034,1035,1036,1037,1038,1039,1040,1041,1042,1043,1044,1045,1046,1047,1048,1049,1050,1051,1052,1053,1054,1055,1056,1057,1058,1059,1060,1061,1062,1063,1064,1065,1066,1067,1068,1069,1070,1071,1072,1073,1074,1075,1076,1077,1078,1079,1080,1081,1082,1083,1084,1085,1086,1087,1088,1089,1090,1091,1092,1093,1094,1095,1096,1097,1098,1099,1100,1101,1102,1103,1104,1105,1106,1107,1108,1109,1110,1111,1112,1113,1114,1115,1116,1117,1118,1119,1120,1121,1122,1123,1124,1125,1126,1127,1128,1129,1130,1131,1132,1133,1134,1135,1136,1137,1138,1139,1140,1141,1142,1143,1144,1145,1146,1147,1148,1149,1150,1151,1152,1153,1154,1155,1156,1157,1158,1159,1160,1161,1162,1163,1164,1165,1166,1167,1168,1169,1170,1171,1172,1173,1174,1175,1176,1177,1178,1179,1180,1181,1182,1183,1184,1185,1186,1187,1188,1189,1190,1191,1192,1193,1194,1195,1196,1197,1198,1199,1200,1201,1202,1203,1204,1205,1206,1207,1208,1209,1210,1211,1212,1213,1214,1215,1216,1217,1218,1219,1220,1221,1222,1223,1224,1225,1226,1227,1228,1229,1230,1231,1232,1233,1234,1235,1236,1237,1238,1239,1240,1241,1242,1243,1244,1245,1246,1247,1248,1249,1250,1251,1252,1253,1254,1255,1256,1257,1258,1259,1260,1261,1262,1263,1264,1265,1266,1267,1268,1269,1270,1271,1272,1273,1274,1275,1276,1277,1278,1279,1280,1281,1282,1283,1284,1285,1286,1287,1288,1289,1290,1291,1292,1293,1294,1295,1296,1297,1298,1299,1300,1301,1302,1303,1304,1305,1306,1307,1308,1309,1310,1311,1312,1313,1314,1315,1316,1317,1318,1319,1320,1321,1322,1323,1324,1325,1326,1327,1328,1329,1330,1331,1332,1333,1334,1335,1336,1337,1338,1339,1340,1341,1342,1343,1344,1345,1346,1347,1348,1349,1350,1351,1352,1353,1354,1355,1356,1357,1358,1359,1360,1361,1362,1363,1364,1365,1366,1367,1368,1369,1370,1371,1372,1373,1374,1375,1376,1377,1378,1379,1380,1381,1382,1383,1384,1385,1386,1387,1388,1389,1390,1391,1392,1393,1394,1395,1396,1397,1398,1399,1400,1401,1402,1403,1404,1405,1406,1407,1408,1409,1410,1411,1412,1413,1414,1415,1416,1417,1418,1419,1420,1421,1422,1423,1424,1425,1426,1427,1428,1429,1430,1431,1432,1433,1434,1435,1436,1437,1438,1439,1440,1441,1442,1443,1444,1445,1446,1447,1448,1449,1450,1451,1452,1453,1454,1455,1456,1457,1458,1459,1460,1461,1462,1463,1464,1465,1466,1467,1468,1469,1470,1471,1472,1473,1474,1475,1476,1477,1478,1479,1480,1481,1482,1483,1484,1485,1486,1487,1488,1489,1490,1491,1492,1493,1494,1495,1496,1497,1498,1499,1500,1501,1502,1503,1504,1505,1506,1507,1508,1509,1510,1511,1512,1513,1514,1515,1516,1517,1518,1519,1520,1521,1522,1523,1524,1525,1526,1527,1528,1529,1530,1531,1532,1533,1534,1535,1536,1537,1538,1539,1540,1541,1542,1543,1544,1545,1546,1547,1548,1549,1550,1551,1552,1553,1554,1555,1556,1557,1558,1559,1560,1561,1562,1563,1564,1565,1566,1567,1568,1569,1570,1571,1572,1573,1574,1575,1576,1577,1578,1579,1580,1581,1582,1583,1584,1585,1586,1587,1588,1589,1590,1591,1592,1593,1594,1595,1596,1597,1598,1599,1600,1601,1602,1603,1604,1605,1606,1607,1608,1609,1610,1611,1612,1613,1614,1615,1616,1617,1618,1619,1620,1621,1622,1623,1624,1625,1626,1627,1628,1629,1630,1631,1632,1633,1634,1635,1636,1637,1638,1639,1640,1641,1642,1643,1644,1645,1646,1647,1648,1649,1650,1651,1652,1653,1654,1655,1656,1657,1658,1659,1660,1661,1662,1663,1664,1665,1666,1667,1668,1669,1670,1671,1672,1673,1674,1675,1676,1677,1678,1679,1680,1681,1682,1683,1684,1685,1686,1687,1688,1689,1690,1691,1692,1693,1694,1695,1696,1697,1698,1699,1700,1701,1702,1703,1704,1705,1706,1707,1708,1709,1710,1711,1712,1713,1714,1715,1716,1717,1718,1719,1720,1721,1722,1723,1724,1725,1726,1727,1728,1729,1730,1731,1732,1733,1734,1735,1736,1737,1738,1739,1740,1741,1742,1743,1744,1745,1746,1747,1748,1749,1750,1751,1752,1753,1754,1755,1756,1757,1758,1759,1760,1761,1762,1763,1764,1765,1766,1767,1768,1769,1770,1771,1772,1773,1774,1775,1776,1777,1778,1779,1780,1781,1782,1783,1784,1785,1786,1787,1788,1789,1790,1791,1792,1793,1794,1795,1796,1797,1798,1799,1800,1801,1802,1803,1804,1805,1806,1807,1808,1809,1810,1811,1812,1813,1814,1815,1816,1817,1818,1819,1820,1821,1822,1823,1824,1825,1826,1827,1828,1829,1830,1831,1832,1833,1834,1835,1836,1837,1838,1839,1840,1841,1842,1843,1844,1845,1846,1847,1848,1849,1850,1851,1852,1853,1854,1855,1856,1857,1858,1859,1860,1861,1862,1863,1864,1865,1866,1867,1868,1869,1870,1871,1872,1873,1874,1875,1876,1877,1878,1879,1880,1881,1882,1883,1884,1885,1886,1887,1888,1889,1890,1891,1892,1893,1894,1895,1896,1897,1898,1899,1900,1901,1902,1903,1904,1905,1906,1907,1908,1909,1910,1911,1912,1913,1914,1915,1916,1917,1918,1919,1920,1921,1922,1923,1924,1925,1926,1927,1928,1929,1930,1931,1932,1933,1934,1935,1936,1937,1938,1939,1940,1941,1942,1943,1944,1945,1946,1947,1948,1949,1950,1951,1952,1953,1954,1955,1956,1957,1958,1959,1960,1961,1962,1963,1964,1965,1966,1967,1968,1969,1970,1971,1972,1973,1974,1975,1976,1977,1978,1979,1980,1981,1982,1983,1984,1985,1986,1987,1988,1989,1990,1991,1992,1993,1994,1995,1996,1997,1998,1999,2000,2001,2002,2003,2004,2005,2006,2007,2008,2009,2010,2011,2012,2013,2014,2015,2016,2017,2018,2019,2020,2021,2022,2023,2024,2025,2026,2027,2028,2029,2030,2031,2032,2033,2034,2035,2036,2037,2038,2039,2040,2041,2042,2043,2044,2045,2046,2047,2048,2049,2050,2051,2052,2053,2054,2055,2056,2057,2058,2059,2060,2061,2062,2063,2064,2065,2066,2067,2068,2069,2070,2071,2072,2073,2074,2075,2076,2077,2078,2079,2080,2081,2082,2083,2084,2085,2086,2087,2088,2089,2090,2091,2092,2093,2094,2095,2096,2097,2098,2099,2100,2101,2102,2103,2104,2105,2106,2107,2108,2109,2110,2111,2112,2113,2114,2115,2116,2117,2118,2119,2120,2121,2122,2123,2124,2125,2126,2127,2128,2129,2130,2131,2132,2133,2134,2135,2136,2137,2138,2139,2140,2141,2142,2143,2144,2145,2146,2147,2148,2149,2150,2151,2152,2153,2154,2155,2156,2157,2158,2159,2160,2161,2162,2163,2164,2165,2166,2167,2168,2169,2170,2171,2172,2173,2174,2175,2176,2177,2178,2179,2180,2181,2182,2183,2184,2185,2186,2187,2188,2189,2190,2191,2192,2193,2194,2195,2196,2197,2198,2199,2200,2201,2202,2203,2204,2205,2206,2207,2208,2209,2210,2211,2212,2213,2214,2215,2216,2217,2218,2219,2220,2221,2222,2223,2224,2225,2226,2227,2228,2229,2230,2231,2232,2233,2234,2235,2236,2237,2238,2239,2240,2241,2242,2243,2244,2245,2246,2247,2248,2249,2250,2251,2252,2253,2254,2255,2256,2257,2258,2259,2260,2261,2262,2263,2264,2265,2266,2267,2268,2269,2270,2271,2272,2273,2274,2275,2276,2277,2278,2279,2280,2281,2282,2283,2284,2285,2286,2287,2288,2289,2290,2291,2292,2293,2294,2295,2296,2297,2298,2299,2300,2301,2302,2303,2304,2305,2306,2307,2308,2309,2310,2311,2312,2313,2314,2315,2316,2317,2318,2319,2320,2321,2322,2323,2324,2325,2326,2327,2328,2329,2330,2331,2332,2333,2334,2335,2336,2337,2338,2339,2340,2341,2342,2343,2344,2345,2346,2347,2348,2349,2350,2351,2352,2353,2354,2355,2356,2357,2358,2359,2360,2361,2362,2363,2364,2365,2366,2367,2368,2369,2370,2371,2372,2373,2374,2375,2376,2377,2378,2379,2380,2381,2382,2383,2384,2385,2386,2387,2388,2389,2390,2391,2392,2393,2394,2395,2396,2397,2398,2399,2400,2401,2402,2403,2404,2405,2406,2407,2408,2409,2410,2411,2412,2413,2414,2415,2416,2417,2418,2419,2420,2421,2422,2423,2424,2425,2426,2427,2428,2429,2430,2431,2432,2433,2434,2435,2436,2437,2438,2439,2440,2441,2442,2443,2444,2445,2446,2447,2448,2449,2450,2451,2452,2453,2454,2455,2456,2457,2458,2459,2460,2461,2462,2463,2464,2465,2466,2467,2468,2469,2470,2471,2472,2473,2474,2475,2476,2477,2478,2479,2480,2481,2482,2483,2484,2485,2486,2487,2488,2489,2490,2491,2492,2493,2494,2495,2496,2497,2498,2499,2500,2501,2502,2503,2504,2505,2506,2507,2508,2509,2510,2511,2512,2513,2514,2515,2516,2517,2518,2519,2520,2521,2522,2523,2524,2525,2526,2527,2528,2529,2530,2531,2532,2533,2534,2535,2536,2537,2538,2539,2540,2541,2542,2543,2544,2545,2546,2547,2548,2549,2550,2551,2552,2553,2554,2555,2556,2557,2558,2559,2560,2561,2562,2563,2564,2565,2566,2567,2568,2569,2570,2571,2572,2573,2574,2575,2576,2577,2578,2579,2580,2581,2582,2583,2584,2585,2586,2587,2588,2589,2590,2591,2592,2593,2594,2595,2596,2597,2598,2599,2600,2601,2602,2603,2604,2605,2606,2607,2608,2609,2610,2611,2612,2613,2614,2615,2616,2617,2618,2619,2620,2621,2622,2623,2624,2625,2626,2627,2628,2629,2630,2631,2632,2633,2634,2635,2636,2637,2638,2639,2640,2641,2642,2643,2644,2645,2646,2647,2648,2649,2650,2651,2652,2653,2654

DOCKETED ITEMS

267

DOCKET 87H-80-84H NEP NUCLEAR, UNIT 1

A. Adjudicatory correspondence

790504044 Changes insurance date for OES to early May 1979
GUTHRIE, J. H. Branch 3 79/04/12 1p

790504040 Withdraw appearance on behalf of Intervenor Concerned
Citizens of R. effective 790402 Certificate of Rev. encl
COLLINS, C. G. Affiliation Unknown 79/04/13 App.

I. Financial information

7905030200 Notices of denial of request to withhold from public
disclosure: Revision 2 to general & financial info section of
license application Forwards NRC ltr
790503020 Light Water Reactors Branch 3 79/03/12 App

7905030200 Responds to NRC 790309 ltr re public availability of
financial info submitted for license application Submission
of financial info for public disclosure does not contravene
SEC requirements
COOK, J. H. Securities & Exchange Commission 79/12/14 App

DOCKET 87H-80-86H NEP Nuclear, Unit 2

A. Application/construction stage

790504041 Changes insurance date for OES to early May 1979
GUTHRIE, J. H. Branch 3 79/04/12 1p

790504040 Withdraw appearance on behalf of Intervenor Concerned
Citizens of R. effective 790402 Certificate of Rev. encl
COLLINS, C. G. Affiliation Unknown 79/04/13 App

7905030200 Notices of denial of request to withhold from public
disclosure: Revision 2 to general & financial info section of
license application Forwards NRC ltr
790503020 Light Water Reactors Branch 3 79/03/12 App

7905030200 Responds to NRC 790309 ltr re public availability of
financial info submitted for license application Submission
of financial info for public disclosure does not contravene
SEC requirements
COOK, J. H. Securities & Exchange Commission 79/12/14 App

DOCKET 87H-80-87A BARNES NUCLEAR POWER PROJECT

A. Adjudicatory correspondence

790502148 Opposes licensing of proposed Hestingsham nuclear power
plant in Philippines
ATH, P. P. Another Nether For Peace 79/10/21 1p

790503020 Requests denial of nuclear reactor support license to
Philippines Reactor design is unsatisfactory on earthquake
resistance. Fear active volcanism & in view was seen, thus
jeopardizing US soldier nearby
HARLEY, J. Maritime Alliance 79/11/26 1p

DOCKET 87H-80-88A ERIC NUCLEAR PLANT, UNIT 1

A. Application/construction stage documents & correspondence

790518070 Forwards request for addl info to continue review of CP
application
REDAIN, H. Environmental Projects Branch 3 79/04/06 4pp

790504070 Requests addl info re new mgmt organization to be
incorporated into PSAR Amend 21.
BARN, S. L. Light Water Reactors Branch 2 79/04/30 App.

G. Adjudicatory correspondence

790516010 Forwards Board Notification 79-10 on reactor inspector
concerns re BWR plants Certificate of Rev. encl.
SCINTO, J. F. Hearings Division 79/03/29 14pp

790510115 Forwards request for Board notification re non-safety-grade
equipment to mitigate transients.
SCINTO, J. F. Hearings Division 79/04/02 3pp

790510115 Board notification: staff assessment re non-safety-grade
equipment to mitigate transients
VARGAS, D. S. Assistant Director for Light Water Reactors,
79/03/29 App.

790505010 Board notification: recent issue on non-safety-grade
equipment to mitigate transients. More info is required
TERENCE, R. L. Assistant Director for Reactor Safety 79/03/16
3pp

790516012 Board notification: nuclear incident at THE, recommends boards
on cases involving BWR reactors be provided w/IE Bulletin
79-05 & PSAR-07 & BWR, C. S. L. P. O. & H.
VARGAS, D. S. Assistant Director for Light Water Reactors,
79/04/03 2pp

790507025 Forwards memo re problems of pipe support base plate
design.
BARTH, C. A. Branch 3 79/04/05 2pp

790508037 Informs that NRC has recently discovered document possibly
relevant to subgrade of spent fuel info is classified & may
never be published in final form Forwards TP Carter 790122
memo. Info assessment will follow when available.
BARTH, C. A. Branch 3 79/04/05 2pp

790510085 Forwards aspects of PWR accumulator delivery re ECCS
performance characteristics
BARTH, C. A. Branch 3 79/04/05 5pp

H. Repeatable occurrences, LERs & related correspondence

790510020 Board notification: Babcock refueling water storage tank
design deficiency
SCINTO, J. F. Hearings Division 79/03/29 30pp

DOCKET 87H-80-89I ERIC NUCLEAR PLANT, UNIT 2

A. Application/construction stage documents & correspondence

790518070 Forwards request for addl info to continue review of CP
application
REDAIN, H. Environmental Projects Branch 3 79/04/06 17pp

790504070 Requests addl info re new mgmt organization to be
incorporated into PSAR Amend 21.
BARN, S. L. Light Water Reactors Branch 2 79/04/30 App.

790516010 Forwards Board Notification 79-10 on reactor inspector
concerns re BWR plants Certificate of Rev. encl.
SCINTO, J. F. Hearings Division 79/03/29 14pp

790510115 Forwards request for Board notification re non-safety-grade
equipment to mitigate transients
SCINTO, J. F. Hearings Division 79/04/02 3pp

790510115 Board notification: staff assessment re non-safety-grade
equipment to mitigate transients
VARGAS, D. S. Assistant Director for Light Water Reactors,
79/03/29 App.

790505010 Board notification: recent issue on non-safety-grade
equipment to mitigate transients. More info is required
TERENCE, R. L. Assistant Director for Reactor Safety 79/03/16
3pp

790516012 Board notification: nuclear incident at THE, recommends boards
on cases involving BWR reactors be provided w/IE Bulletin
79-05 & PSAR-07 & BWR, C. S. L. P. O. & H.
VARGAS, D. S. Assistant Director for Light Water Reactors,
79/04/03 2pp

790507025 Forwards memo re problems of pipe support base plate
design.
BARTH, C. A. Branch 3 79/04/05 2pp

790508037 Informs that NRC has recently discovered document possibly
relevant to subgrade of spent fuel info is classified & may
never be published in final form Forwards TP Carter 790122
memo. Info assessment will follow when available.
BARTH, C. A. Branch 3 79/04/05 2pp

790510085 Forwards aspects of PWR accumulator delivery re ECCS
performance characteristics.
BARTH, C. A. Branch 3 79/04/05 5pp

I. Repeatable occurrences, LERs & related correspondence

790510020 Board notification: Babcock refueling water storage tank
design deficiency.
SCINTO, J. F. Hearings Division 79/03/29 30pp

DOCKETED ITEMS

269

8. NRC Draft/Final Environmental Statements, supplements and correspondence

--790500049 Addendum 2 to General Financial Info. "Artesia Public Service Co. 7/9/05/23 50pp.

790500008 Forwards SDB for review H/s and
REGAN M.H. Environmental Projects Branch 2. 7/9/04/12 2pp

790500040 Submits on comments on SDB
BARRELL M.L. Agriculture Dept of 7/9/05/03 1p Available at NRC
SIR

790500008 Requests 30-day extension of comment period for SDB
MIRIAM H. California, State of 7/9/05/14 1p

790500044 Comments on SDB discuss soil survey drainage areas and pit
organic matter content & texture of soils
MCCORMACK M.L. Agriculture Dept of 7/9/05/23 1p

790500042 No comments on SDB
DALLARD J.B. Transportation Dept of 7/9/05/24 1p

0. Administrative correspondence

790500027 NRC response to amended contention of L. Bard Opposes
admission of contaminants re transportation of spent fuel
Lester in controversy Certificate of No. 101
BENNETT B. H. Branch 2 7/9/03/21 3pp

7905000178 Palo Verde Nuclear Intervenor's petition to intervene is
defective for unduly delay & lack of standing. Denies
petition sub grants intervenors opportunity to cure defects
by filing amended petition within ten days
LARS E. H. Atomic Safety and Licensing Board Panel 7/9/03/22 7pp

790500002 Amended petition for co-intervention filed in response to
NRC 790306 response to first petition for co-intervention is
granted co-intervenor status will be permitted to file an
amendable contention on transportation of hazardous
materials. Denies that intervenors be limited to 790301 order
GROSS A. C. - EISENBERG C. A. Small & Wilson 7/9/03/28 3pp

790500002 Joint applicants' response to undated third amended
contention of L. Bard States that Bard failed to file an
amendable contention on transportation of hazardous
materials. Denies that intervenors be limited to 790301 order
GROSS A. C. - EISENBERG C. A. Small & Wilson 7/9/03/28 3pp

790500004 Request development of nuclear power in US be stopped for
sake of safety
JOSCHKE P. Affiliation Unknown 7/9/04/03 1p

790500048 Forwards NRC report, "Flagging inquiry into Allegation of
Employee Misconduct by Restricting Investigation to
Detection Reliability of Power Grid Serving St. Louis"
BENNETT B. H. Branch 2 7/9/04/11 1p

790500007 Discusses evaluation of new info re C-E flow blockage
model for SDB in order to determine sys design performance
re requirements of App. 100000 40
DUNN M.L. H. Branch 2. 7/9/04/11 2pp

790500002 Forwards SDB for Facility H/s and
BENNETT B. H. Branch 2. 7/9/04/17 2pp

H. General correspondence

790500002 Confirms agreement to meet w/representatives & E. H. in Anaheim,
Ca. re 790405
DOLAN M.L. H. Anti-Trust Division. 7/9/04/10 1p

I. Financial Information

790500046 Requests add info re ownership, sources of funds & annual
reports to complete financial review. Previous responses add
790311 & 790325 have not been adequate.
FARMER D. Light Water Reactors Branch 2. 7/9/04/23 3pp

790500002 Forwards add financial info. Info withheld (ref 100026, 7901,
JOHNSON M. H. St. Paul Electric Co. 7/9/04/24 3pp

790500040 Forwards "Sources of Funds for St. Paul Electric Expenditures
During Period of Control of Babcock Nuclear Plant."
w/ Application to withhold document & affidavit of N. Rompe.
Preliminary info withheld (ref 100092, 7901,
MARTIN V.P. San Diego Gas & Electric Co. 7/9/05/03 3pp

790500007 Forwards "Addendum 2 to General Financial Info."
and BENTLEY E. Artesia Public Service Co. 7/9/05/23 3pp.

DOCKET 870-80-054 NRC NUCLEAR UNIT 1

A. Application/Construction stage documents & correspondence

790500003 Forwards requested RM Reg 790119 1st to a Minikah re
alternate site analysis w/o mail.
SANDERSON S. T. Branch 1 7/9/03/28 1p

790500044 Forwards proposed schedule for radiological safety review
ROYB R. H. Division of Project Management 7/9/04/12 3pp

790500040 In response to 790327 1st, forwards signed agreements for
technical support in review of facility
2900000 R. C. Division of Site Safety & Environmental Analysis
7/9/04/13 2pp

790500027 Requests add info per completion of PSAR review. Mail
concerns discrepancy in participation of operator license
candidates in simulator training course
COLLINS M. P. Operator Licensing Branch 7/9/04/10 3pp

790500002 Comments on "Federal-State Authorities & Cooperation in
Nuclear Power Plant Licensing," outlines changes to NF citing
law & attempts to delineate duplication of regulatory
processes between Federal & state agencies
BENJAMIN R. New York, State of 7/9/04/24 3pp

790500027 Inform of establishment of schedule for radiological safety
review of application for CP Estimates prospective decision
date to be 8/10/08
EIDEN R. S. Division of Project Management 7/9/04/24 4pp

790500007 Notification of 790308 meeting w/Utah, NY state
representatives & ANL in Mexico, NY to request local
residents' assistance in providing information to regulatory
agencies. Denies that intervenors be limited to 790301 order
BENJAMIN R. Environmental Projects Branch 2. 7/9/04/24 3pp

790500044 Forwards "1978 Hudson River Shortnose Sturgeon Study, Scope
of Work."
RAY M. J. New York State Electric & Gas Corp. 7/9/04/23 23pp.

790500046 Requests add info in order to continue evaluation of PSAR
Specific info requested concerned areas of containment sys.,
effluent treatment sys., radiological assessment, geology &
seismology & operator training.
FARMER D. D. Light Water Reactors Branch 2. 7/9/04/27 13pp.

790500046 Forwards previously omitted page 4 from 790427 1st re
Questions 261, 24 & 381 25.
FARMER D. D. Light Water Reactors Branch 2. 7/9/05/03 3pp.

790500040 Responds to 790427 1st requesting add info info will be
submitted as PSAR amend by mid-July.
KENTON M. A. R. New York State Electric & Gas Corp. 7/9/05/14 1p

B. Utility Preliminary Safety Analysis Report, comments

790500044 Forwards affidavit of att. for Amend 3 to PSAR & CP
application
KINTON M. A. R. New York State Electric & Gas Corp. 7/9/05/14 4pp.

C. Utilizing Environmental Report (ER), amendments & correspondence

790500046 Requests add info re analysis of cooling tower & thermal
discharge. Amend to avoid para containing responses to
mail questions should be submitted by 790515 in order to
continue review.
REGAN M.H. Environmental Projects Branch 2. 7/9/04/23 4pp.

790500047 Requests attention to file preliminary draft of first
chapter of environmental statement.
BENJAMIN R. New York, State of 7/9/04/24 3pp

790500047 Amend 2 to original report.
KINTON M. A. R. New York State Electric & Gas Corp. 7/9/05/24 30pp.

D. Administrative correspondence

790500002 Petitions to intervene in proceeding. Assesses health &
safety will be adversely affected by plant.
MARTIN V.P. Ecology Action of Oswego. 7/9/05/06 3pp.

7905240098 Petition to Intervene, submitted by Columbia County, NY, Town of Gloversville, NY & Concerned Citizens For Safe Energy, Inc. RAFFIN, R. J. 7/9/03/12 3pp

---7905240104 Supporter petition to Intervene submitted by Columbia County, NY, Town of Gloversville, NY & Concerned Citizens For Safe Energy, Inc. Notice of appearance & Certificate of Doc encl. RAFFIN, R. J. 7/9/03/12 10pp

7905250350 Petitions to Intervene in proceeding Assents health & safety will be adversely affected by plant. CLAMORE, L. Safe Energy For New Haven 7/9/03/16 3pp

7905250409 Mid-Hudson Nuclear Opponents' petition to Intervene as full party re alternate site considerations, need for facility. Financial qualifications of Applicants & cost of proposed plant. BROWN, P. D. Mid-Hudson Nuclear Opponents, Inc. 7/9/03/14 3pp

7905250345 Notice of appearance on behalf of util. SCHMITT, R. ; ZERNAN, I. L. Water, Hagitt, Lawrence & Parrell 7/9/03/20 1p

---7905250370 Answer to intervention petitions of various groups including NY State Electric & Gas, Columbia County, Schoharie County, Schoharie & Safe Energy For New Haven, Certificate of Doc encl. SCHMITT, R. ; ZERNAN, I. L. Water, Hagitt, Lawrence & Parrell 7/9/03/20 3pp

7905100178 Response to petitions to Intervene filed in Columbia/Ulster County area during Per 1979 Interventions failed to establish standing. Petitions should be denied. Certificate of Doc encl. BMAHORN, D. T. Branch 3 7/9/04/22 12pp

7905240140 Answer seeking denial of 790319 petition to Intervene filed by Mid-Hudson Nuclear Opponents, Inc. Certificate of Doc encl. SCHMITT, R. ; ZERNAN, I. L. New York State Electric & Gas 7/9/04/03 4pp

7905190304 Response First set of interrogatories to util from NY St Dept of Environ Conservation. BODEL, D. A. New York, State of 7/9/04/04 1p

---7905190371 First set of interrogatories for util from NY St Dept of Environ Conservation. New York, State of 7/9/04/04 3pp

7905190144 Requester copy of 790402 "PAC Answer to Petition to Intervene Filed in Columbia/Ulster County Area" ZERNAN, I. L. Water, Hagitt, Lawrence & Parrell 7/9/04/05 2pp

7905240146 Requester leave to Intervene in proceedings re selection of alternate sites. Prehearing previous denial of intervention status. KEEFING, H. Gardiner, NY. 7/9/04/12 1p

H. General correspondence

7905250347 Notice to all parties & interested persons to send documents for 1st set of questions to 801 West Outer Drive, Oak Ridge, TN. WADKINS, S. Atomic Safety and Licensing Board Panel. 7/9/04/20 1p

7905190115 Forwarded info requested in 790115 ltr re nuclear reactor cost for visit & study. BROWN, M. H. Environmental Projects Branch 2 7/9/04/20 3pp

DOCKET 879-50-897 NEW HAVEN, UNIT 2

A. Application/construction stage documents & correspondence

7905250003 Forwarded requested MS Regd 790115 ltr to A Kinloch re alternate site analysis. H/ re encl. BMAHORN, D. T. Branch 3 7/9/03/20 1p

7905010044 Forwarder proposed schedule for radiological safety review. BROWN, P. D. Division of Project Management, 7/9/04/13 3pp

7905020070 In response to 790327 ltr, forwarder signed agreements for technical support in review of facility. BROWN, P. D. Division of Site Safety & Environmental Analysis 7/9/04/13 3pp

7905070070 Requester add info for completion of PSAR review. Mail examine discrepancy in participation of operator license candidates in simulator training course. COLLINS, P. P. Operator Licensing Branch, 7/9/04/13 3pp

7905030350 Comments on "Federal-State Authorities & Cooperation in Nuclear Power Plant Licensing" outlines changes to NY existing law & attempts to eliminate duplication of regulatory processes between Federal & state agencies. BROWN, M. H. New York, State of. 7/9/04/24 3pp

7905030357 Informer of establishment of schedule for radiological safety review of application for PSAR. Estimates prospective decision date to be 01/20/05. BROWN, P. D. Division of Project Management 7/9/04/24 3pp

7905050107 Notification of 790505 meeting w/Util-NY state representatives & AEL in Hudson NY to account local residents' solicitation of nuclear review. BELL, S. D. Environmental Projects Branch 2 7/9/04/24 3pp

7905010494 Forwarder "1978 Hudson River Shortnose Sturgeon Study-Scope of Work" BAY, N. J. New York State Electric & Gas Corp 7/9/04/25 20pp

7905250064 Requester add info in order to continue evaluation of PSAR. Specific info requested concerns areas of containment system, effluent treatment system, radiological assessment, geology & seismology & operator training. KINLOCH, D. Light Water Reactors Branch 3 7/9/04/27 15pp

7905010464 Forwarder previously omitted page from 790427 ltr re Questions 381-38 & 382-3. KINLOCH, D. Light Water Reactors Branch 3 7/9/05/03 3pp

7905250120 Response to 790427 ltr requesting add info. Info will be submitted as PSAR amend by mid-July. KINLOCH, A. E. New York State Electric & Gas Corp 7/9/05/14 1p

B. Utility Preliminary Safety Analysis Report, amends

7905010343 Forwarder affidavit of doc for Amend 3 in PSAR & GP Application. KINLOCH, A. E. New York State Electric & Gas Corp 7/9/05/16 4pp

C. Utility Environmental Report (ER), amends & correspondence

7905070314 Requester add info re analysis of cooling tower & thermal discharge amend to involve risk containing responses to all questions should be submitted by 790510 in order to continue review. Review. BROWN, M. H. Environmental Projects Branch 2 7/9/04/23 3pp

7905070447 Requester extension to file preliminary draft of first chapters of environ statement. BROWN, M. H. New York, State of 7/9/04/26 3pp

7905030477 Amend 2 to environ report. KINLOCH, A. E. New York State Electric & Gas Corp 7/9/05/24 20pp

D. Advisory correspondence

7905250393 Petitions to Intervene in proceeding Assents health & safety will be adversely affected by plant. MILLER, S. ; DALY, K. Ecology Action of Oswego, 7/9/03/08 3pp

7905240098 Petition to Intervene, submitted by Columbia County, NY, Town of Gloversville, NY & Concerned Citizens For Safe Energy, Inc. Notice of appearance & Certificate of Doc encl. RAFFIN, R. J. 7/9/03/12 3pp

---7905240104 Supporter petition to Intervene submitted by Columbia County, NY, Town of Gloversville, NY & Concerned Citizens For Safe Energy, Inc. Notice of appearance & Certificate of Doc encl. RAFFIN, R. J. 7/9/03/12 10pp

7905250350 Petitions to Intervene in proceeding Assents health & safety will be adversely affected by plant. CLAMORE, L. Safe Energy For New Haven, 7/9/03/16 3pp

7905250409 Mid-Hudson Nuclear Opponents' petition to Intervene as full party re alternate site considerations, need for facility. Financial qualifications of Applicants & cost of proposed plant. BROWN, P. D. Mid-Hudson Nuclear Opponents, Inc. 7/9/03/14 3pp

7905250345 Notice of appearance on behalf of util. SCHMITT, R. ; ZERNAN, I. L. Water, Hagitt, Lawrence & Parrell. 7/9/03/20 1p

DOCKETED ITEMS

7902010293 Forwards affidavit certifying 790202 distribution of kits containing/safe safety tags. Amend 1
HAUGHTON, W. F. Commercial Office Co 79/03/20 2pp

6. Adjudicatory correspondence

7902010294 Notice of hearing re request for early site review & CP
CHILDS, M. J. Office of the Secretary of the Commission 79/05/01
7pp.

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 79-0060 Battelle Columbus Laboratories

7903020854 Forwards "Nuclear Security Personnel Training Plan for
Facility 4" Encl withheld (ref 10CFR2 790)
TOY, H. L. Battelle Memorial Institute, Columbus Laboratories
79/02/20 2pp

7903010591 Forwards IE Info Notice 79-06, "Interconnection of
Contaminated Site w/Hot Air Site Used as Source of Breathing
Air"
NEPFLER, J. D. Region D, Chicago, Office of the Director 79/03/26
1p

7903010592 Forwards 790328 ltr requesting fee for review of security
training & qualification plan. Requests fee be forwarded
within 15 days W/O encl
SEIBER, G. License Fee Management Branch 79/04/24 1p

DOCKET 79-0022 ROCKWELL INTERNATIONAL CORP

7903010593 Forwards IE Info Notice 79-06, "Interconnection of
Contaminated Site w/Hot Air Site Used as Source of Breathing
Air"
ENGELKIND, R. H. Region 2, San Francisco, Office of the Director
79/03/26 1p

DOCKET 79-0027 BABCOCK & WILCOX CO

7903040105 Act receipt of 790322 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 79-0027/79-02
SERRE, M. E. Region 2, Atlanta, Safeguards Branch 79/04/02 1p

--7903040114 Response to NRC 790309 ltr re violations noted in IE Insp
Repts 79-0027/79-02 Corrective actions withheld (ref 10CFR2 790)
BENNO, J. P. Babcock & Wilcox Co 79/03/23 1p

--7903040116 Forwards IE Insp Repts 79-0027/79-02 on 790213-14 Notice of
violations withheld (ref 10CFR2 790)
SERRE, M. E. Region 2, Atlanta, Safeguards Branch 79/03/24
2pp

----- IE Insp Repts 79-0027/79-02 on 790213-14 Noncompliance noted
to include weight measurements of fabrication
specimens in limit of error calculations. Details
(ref 10CFR2 790)
Region 2, Atlanta, Office of the Director
Region 2, Atlanta, Safeguards Branch 79/03/24

Issue of efforts to develop new LBMS model
7903 including add time required to
or validation. Procedural made will
0100
Wilcox Co 79/04/23 1p.

DOCKET 79-0023 TEXAS INSTRUMENTS, INC.

7903020277 Forwards IE Insp Repts 79-0023/79-02 on 790202-22 No
noncompliance noted
MARTIN, H. G. Region 1, Philadelphia, Safeguards Branch 79/03/14
2pp.

--7903020288 IE Insp Repts 79-0023/79-02 on 790202-22 No noncompliance
noted. Major areas inspected: physical inventory verification
& measurement & statistical control of nuclear mat. Details
withheld (ref 10CFR2 790)
ZIMMERMAN, L. C. Region 1, Philadelphia, Office of the
Director JOYNER, J. H. Region 1, Philadelphia, Safeguards
Branch 79/03/14 1p

7902040010 Forwards revision to HFIR project safeguards contingency
plan for final acceptance review. Plan withheld (ref Atomic
Energy Act of 1954 & Energy Reorganization Act of 1974)
ENDERS, F. L., SENI, A. E. Texas Instruments, Inc 79/04/12 2pp

DOCKET 79-0102 AMHERST COLLEGE

7903010422 Discusses IE Insp of Licenses 29-0370-02, 29-0370-03,
29-0370-04 & SM-194 on 790309 No noncompliance noted
Major areas inspected: qualifications of procedures &
representative records & interview of personnel.
MSL, LINDEN, S. O. Region 1, Philadelphia, Office of the Director,
79/03/20 1p

DOCKET 79-0120 BABCOCK & WILCOX CO

7903050565 Forwards revised organization chart for PA operations &
updated position description for nuclear mat control &
accountability personnel, excluding SM-1 custodian &
technical positions, which were not changed
AUSTIN, H. A. Babcock & Wilcox Co., Nuclear Material Div 79/03/26
1pp.

7903050567 Responds to 790306 ltr to LO House Agree to assignment of
SRT as compliance section manager & deletion of regulatory
projects coordinator position. Assignment of Canada as
licensing & nuclear safety specialist is conditional
SOSMA, W. F. Division of Fuel Cycle & Material Safety 79/03/16
2pp

7903040294 Forwards Table A, "Comprehensive Listing of Storage Area
Codes" summarizing current mat balance areas & item control
areas. Table was omitted from 790310 ltr
AUSTIN, H. A. Babcock & Wilcox Co 79/04/04 2pp

7903020378 Act receipt of 790320 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 79-0123/79-02 &
79-0344/79-02
MARTIN, H. G. Region 1, Philadelphia, Safeguards Branch 79/04/06
1p

--7903020387 Responds to NRC 790320 ltr re violations noted in IE Insp
Repts 79-0123/79-02 & 79-0344/79-02 Corrective action
withheld (ref 10CFR2 790)
AUSTIN, H. A. Babcock & Wilcox Co., Nuclear Material Div. 79/03/20
1p

--7903020387 Forwards IE Insp Repts 79-0123/79-02 & 79-0344/79-02 on
790310-1201 Notice of violation withheld (ref 10CFR2 790)
MARTIN, H. G. Region 1, Philadelphia, Safeguards Branch
79/01/26 2pp

--7903020392 IE Insp Repts 79-0123/79-02 & 79-0344/79-02 on 790310-1201.
Noncompliance noted. Failure to maintain code program for
crane scale & failure to secure crane weights and
measurements of element details withheld (ref 10CFR2 790)
KUPFER, W. L., JOYNER, J. H. Region 1, Philadelphia, Safeguards
Branch 79/03/20 1p

7903020348 Responds to 790321 ltr requesting assessment of potential
magnitude of NUP bias due to degree of verification
corrective performance. No add measurements required for
verification. Forwards measurements control plan w/o encl.
AUSTIN, H. A. Babcock & Wilcox Co. 79/04/20 2pp

7903040278 Act receipt of 790415 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 79-0123/79-02 &
79-0344/79-02
MARTIN, H. G. Region 1, Philadelphia, Safeguards Branch 79/04/26
1p

--7903040262 Responds to NRC 790320 ltr re violations noted in IE Insp
Repts 79-0123/79-02 & 79-0344/79-02 Corrective actions
step taken will be scheduled to review NRC customer
responsibilities.
AUSTIN, H. A. Babcock & Wilcox Co. 79/04/16 2pp.

--7903040278 Forwards IE Insp Repts 79-0123/79-02 & 79-0344/79-02 on
790310-1201 Notice of violation withheld (ref 10CFR2 790)
MARTIN, H. G. Region 1, Philadelphia, Safeguards Branch
79/03/20 2pp

--7903040284 IE Insp Repts 79-0123/79-02 & 79-0344/79-02 on 790310-1201
Noncompliance noted. Failure to advise NRC of changes to
licensing areas & failure to adhere to control
procedures for SM-194. Details withheld (ref 10CFR2 790)
KUPFER, W. L., JOYNER, J. H. Region 1, Philadelphia, Office of the Director
JOYNER, J. H. Region 1, Philadelphia, Safeguards Branch
79/03/20 2pp

DOCKETED ITEMS

273

7903020303 Accepts and proposed contingency plan to provide acceptable level of physical protection in event of strikes as discussed & agreed upon during MO Definitive 790403 visit Plan withheld (ref 10CFR2 7903).

7903040100 Physical Security Licensing Branch 79/04/26.

DOCKET 79-0143 NUCLEAR FUEL SERVICES, INC.

7903020304 Responds to NRC 790104 for submitting decommissioning program for U-235 facilities & requesting that Part 2 be withheld (ref 10CFR2 7901) Request denied/considerations are not specific enough.

7903020305 Fuel Process & Feb. Branch 79/03/09. App.

7903020404 Forwards IE Insp Rept 79-0143/79-08 on 790224-0302 No noncompliance noted.

7903020405 Region 2, Atlanta, Safeguards Branch. 79/03/19. App.

7903020407 IE Insp Rept 79-0143/79-08 on 790224-0302 No noncompliance noted. Major areas inspected: records & logs.

7903020408 Region 2, Atlanta, Office of the Director.

7903020409 Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/19. App.

7903020404 Informs that info requested re amend to Certificate of Compliance 4700 will be submitted by 790403.

7903020405 Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/03/23. 1p.

7903020403 Requests Amend RFP-1 to Licensee 89W-124 Details withheld (ref 10CFR2 7901).

7903020404 Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/03/29. App.

7903020303 Forwards project rept on site analysis study Study withheld (ref 10CFR2 7901).

7903020304 Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/04/03. 1p.

7903020304 Requests proposed new Section 7.7 of fundamental nuclear fuel control plan for approval in response to 790112 1p.

7903020305 Details withheld (ref 10CFR2 7901).

7903020306 Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/04/05. App.

7903020407 Act receipt of 790402 for informing NRC of steps taken to correct violations noted in IE Insp Rept 79-0143/79-07.

7903020408 Region 2, Atlanta, Safeguards Branch. 79/04/02. 1p.

7903020403 Responds to NRC 790312 for re violations noted in IE Insp Rept 79-0143/79-07. Corrective actions re safeguards measures withheld (ref 10CFR2 7901).

7903020404 Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/04/04. 1p.

7903020403 Forwards IE Insp Rept 79-0143/79-07 Notice of violation withheld (ref 10CFR2 7901).

7903020404 Region 2, Atlanta, Safeguards Branch. 79/03/12. App.

7903020403 IE Insp Rept 79-0143/79-07 on 790110-0204 Noncompliance noted. Failure to calculate bias associated w/maintenance of process help & stack & loading discharges.

7903020404 Region 2, Atlanta, Office of the Director.

7903020405 Region 2, Atlanta, Safeguards Branch. 79/03/07. 1p.

7903020404 Act receipt of IE Insp Rept 79-0143/79-13 on 790414-13. No noncompliance noted.

7903020405 Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.) 79/04/20. 1p.

7903020403 Forwards IE Insp Rept 79-0143/79-13 on 790414-13. No noncompliance noted.

7903020404 Region 2, Atlanta, Office of the Director. 79/04/23. 1p.

7903020403 IE Insp Rept 79-0143/79-13 on 790414-13. No noncompliance noted. Major areas inspected: shutdown preparations & plant operations.

7903020404 Region 2, Atlanta, Office of the Director. 79/04/19. App.

7903020404 Notifies that Section 7.7 of fundamental nuclear fuel control plan submitted in 790403. IE License 89W-124 is revised condition 5.1 of Amend RFP-1 to Licensee 89W-124 is revised accordingly.

7903020405 Material Control Licensing Branch. 79/04/24. App.

7903020406 Material Control Licensing Branch. 79/04/26. 1p.

7903020303 Responds to 790403 for requesting time extension for submitting low enriched U inventory. Request is granted.

7903020304 Material Control Licensing Branch 79/04/26. 1p.

7903020304 Orders that revised & corrected safeguards contingency plan is acceptable. License Conditions 9 & 10 are being amended.

7903020305 Physical protection requirements and 7903040100 Physical Security Licensing Branch 79/03/02. App.

7903020307 Forwards IE Info Notice 79-08. "Interconnection of Contaminated Air with Air Age Used as Source of Breathing Air."

7903020308 Region 2, Atlanta, Office of the Director.

7903020309 1p.

DOCKET 79-0150 FORDS UNIV

7903020304 IE Insp Rept 79-0150/79-01 & 79-0150/79-02 on 790212-12 Notice of violation withheld (ref 10CFR2 7901).

7903020305 Region 3, Chicago, Safeguards Branch 79/03/26. App.

7903020307 IE Insp Rept 79-0150/79-01 & 79-0150/79-02 on 790212-12 Noncompliance noted. Keys, locks & hardware deficiencies for feed transfer material facility details withheld (ref 10CFR2 7901).

7903020308 CHS/OTSP/89-0. H. HARRIS, T. J. Region 3, Chicago, Office of the Director.

7903020309 MING, J. A. Region 3, Chicago, Safeguards Branch. 79/03/21. 1p.

DOCKET 79-0204 PARKS TOWNSHIP BIVE, BARCOCK & WILCOX CO

7903020304 Forwards revised organization chart for PA operations & updated position description for nuclear fuel control & technician positions, which were not changed.

7903020305 BARCOCK & WILCOX CO. Nuclear Material Div. 79/02/24. 1p.

7903020303 Requests administrative change to License 89W-414, changing limits of U enrichment in fuel. Limitations portion of Tech Spec.

7903020304 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/03/01. App.

7903020307 Responds to 790303 for re License 89W-414, changing limits of U enrichment in fuel. Limitations portion of Tech Spec.

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/02/24. 1p.

7903020307 Responds to 790303 for re License 89W-414, changing limits of U enrichment in fuel. Limitations portion of Tech Spec.

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/02/24. 1p.

7903020307 Responds to 790303 for re License 89W-414, changing limits of U enrichment in fuel. Limitations portion of Tech Spec.

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/02/24. 1p.

7903020307 Act receipt of 790402 for informing NRC of steps taken to correct violations noted in IE Insp Rept 79-0150/79-01 & 79-0150/79-02.

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/04/19. 1p.

7903020307 Responds to NRC 790402 for re violations noted in IE Insp Rept 79-0150/79-01 & 79-0150/79-02. Corrective action withheld (ref 10CFR2 7901).

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/04/20. 1p.

7903020307 Forwards IE Insp Rept 79-0150/79-01 & 79-0150/79-02 on 790110-1204 Noncompliance noted. Failure to maintain tide program for crane scale & failure to ensure crane weights & measurements of element details withheld (ref 10CFR2 7901).

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/03/22. 1p.

7903020307 Forwards revisions to proposed Parks Township site safeguards contingency plan in response to 790224 1p. Plan withheld (ref Atomic Energy Act of 1954 & Energy Reorganization Act of 1974).

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/04/19. 1p.

7903020307 IE Insp Rept 79-0150/79-01 & 79-0150/79-02 on 790110-1204 Noncompliance noted. Failure to maintain tide program for crane scale & failure to ensure crane weights & measurements of element details withheld (ref 10CFR2 7901).

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/03/22. 1p.

7903020307 Forwards revisions to proposed Parks Township site safeguards contingency plan in response to 790224 1p. Plan withheld (ref Atomic Energy Act of 1954 & Energy Reorganization Act of 1974).

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/04/19. 1p.

7903020307 IE Insp Rept 79-0150/79-01 & 79-0150/79-02 on 790110-1204 Noncompliance noted. Failure to maintain tide program for crane scale & failure to ensure crane weights & measurements of element details withheld (ref 10CFR2 7901).

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/03/22. 1p.

7903020307 Forwards revisions to proposed Parks Township site safeguards contingency plan in response to 790224 1p. Plan withheld (ref Atomic Energy Act of 1954 & Energy Reorganization Act of 1974).

7903020308 AUSTIN, H. A. BARCOCK & WILCOX CO. Nuclear Material Div. 79/04/19. 1p.

DOCKETED ITEMS

790020030 Responds to 7900203 ltr Data generated in Pu glovebox line must be treated individually
 PARLOW J G Material Control Licensing Branch 79/04/24 3p

790010092 Responds 790032 ltr requesting \$100 fee for amend to delay Pu physical inventory Request payment within 15 days of receipt of ltr
 MESSER D License Fee Management Branch 79/04/24 3p

790020076 Summary of 790020 meeting w/MSR re revisions to Section II of License 88M-41 re improvement of Pu facility fire protection & ventilation app
 BURKHARDT W Fuel Reprocess & Recycle Branch 79/04/26 3p

790024075 Ack receipt of 790466 ltr informing MEC of steps taken to correct violations noted in IE Insp Rept 79-0325/79-01 & 79-0344/79-02
 MARTIN M G Region I, Philadelphia, Safeguards Branch 79/04/26 3p

79-00240763 Responds to MRC 7900203 ltr re violations noted in IE Insp Repts 79-0325/79-01 & 79-0344/79-02 re corrective actions
 AUSTIN R A Babcock & Wilcox Co 79/04/16 2pp

790026079 Responds SE Insp Rept 79-0325/79-01 & 79-0344/79-02 on 790133-0022 Notice of violation withheld (ref 10CFR 7901)
 MARTIN M G Region I, Philadelphia, Safeguards Branch 79/03/20 3pp

79-00240764 IE Insp Rept 79-0325/79-01 & 79-0344/79-02 on 790133-0022
 Recommendations noted failure to advise MEC of changes to internal control sys & failure to adhere to control procedures for SRM Details withheld (ref 10CFR 7901)
 HUGHES W L Region I, Philadelphia, Office of the Director
 JEWETT M H Region I, Philadelphia, Safeguards Branch 79/03/19 3pp

790030083 Accepts meet proposed contingency plan to provide acceptable level of physical protection in event of strike as discussed & agreed upon during NJ Billipoint 790023 visit Plan withheld (ref 10CFR 7901)
 HODGSON D G Physical Security Licensing Branch 79/04/26 2pp

790016016 Forwards Amend 1 to Indemnity Agreement 0-4 per 10CFR 140 changes re liability insurance increase from \$140 million to \$140 million effective 790031 Supporting documentation add
 BALTISMAN J Antitrust & Indemnity Group 79/06/01 3pp

7900110288 Confirms 790001 before increasing liability limit to \$30 million for MSLU Policies 79-01, 79-04 & 79-05
 ROBERTS G Mutual Atomic Energy Liability Underwriters 79/05/02 1p

790030040 Forwards executed Amend 1 to Indemnity Agreement 0-4
 LOWIS J R Babcock & Wilcox Co Nuclear Material Div 79/05/21 2pp

790030080 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/UC Air Sys Used as Source of Breathing Air"
 ORRICK R H Region I, Philadelphia, Office of the Director 79/03/28 3p

DOCKET 79-0371 UNITED NUCLEAR CORP

790024039 Forwards Naval Products Div training & qualification plan. Plan withheld (ref 10CFR 7901)
 KIRK M F United Nuclear Corp 79/03/13 2pp

790020075 Responds to 790033 request to use salt type seal as drums for burial. Request referred to OIC of OMS Development
 PARLOW J G Material Control Licensing Branch 79/04/09 1p

790024094 Responds to 790410 ltr requesting exemption from License Conditions 3 & 10CFR 7901. SRM Administrative amend fee is required
 MESSER D License Fee Management Branch 79/04/17 1p

790023086 Responds to 790030 ltr re fee for pre-issuing training & qualification plan. Purpose of review & approval of plan is to determine whether licensee meets requirements of regulations. Amend fee of \$5,200 is required.
 HELLER M G License Fee Management Branch 79/03/08 2pp

DOCKET 79-0734 GENERAL ATOMIC CO

790010034 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/UC Air Sys Used as Source of Breathing Air"
 ENGELBACH R H Region I, San Francisco, Office of the Director 79/03/28 3p

790010098 Ack receipt of 790030 ltr in response to 790030 notice of violation. Corrective actions will be reviewed during next physical protection Insp.
 HODGSON D G Region I, San Francisco, Safeguards Branch 79/04/03 1p

DOCKET 79-0734 WILCOX NUCLEAR DIVISION, GENERAL ELECTRIC CO

790020070 Forwards details of proposal to eliminate need for granting of exemption re events SRM holdings at Facility Proposal withheld (ref 10CFR 7901)
 HODGSON R A General Electric Co Nuclear Energy Products Div 79/03/11 2pp

790020080 Forwards security training & qualification plan. Plan withheld (ref 10CFR 7901)
 CUMMINGS W E General Electric Co Nuclear Energy Products Div 79/02/16 2pp

790020020 Forwards IE Info Notice 79-08, "Interconnection of Contaminated Sys w/UC Air Sys Used as Source of Breathing Air"
 ENGELBACH R H Region I, San Francisco, Office of the Director 79/03/28 3p

790020018 Forwards safeguards meeting plan w/comments on revisions suggested in MRC 790023 ltr Plan & comments withheld (ref 10CFR 7901)
 CUMMINGS W E General Electric Co Nuclear Energy Products Div 79/04/03 2pp

790000040 Responds to 790011 ltr Agree w/concept of tailored fundamental nuclear matl control & accounting program for Advanced Fuel Lab. Request for matl to plants plan should include description of process equipment & flows
 PARLOW J G Material Control Licensing Branch 79/04/23 1p

790014016 Forwards Amend 1 to Indemnity Agreement 0-4 per 10CFR 140 changes re liability insurance increase from \$140 million to \$140 million effective 790031 Supporting documentation add
 BALTISMAN J Antitrust & Indemnity Group 79/06/01 3pp

790024030 Determines request for amend to License 88M-960 contains administrative changes requiring \$30 administrative fee.
 MESSER D License Fee Management Branch 79/05/02 1p

790013062 Amend 1 to Indemnity Agreement 0-4.
 BALTISMAN J Antitrust & Indemnity Group, BARNETTER R M General Electric Co 79/05/08 1p

DOCKET 79-0820 United Nuclear Corp

790013042 Forwards Fuel recovery operation training & qualifications plan withheld (ref 10CFR 7901)
 GELBERT L United Nuclear Corp 79/04/15 2pp

790010059 Forwards IE Insp Repts 79-0603/79-06 & 79-2760/79-01 on 790220 No noncompliance noted.
 MARTIN M G Region I, Philadelphia, Safeguards Branch 79/03/07 2pp

790011003 IE Insp Repts 79-0603/79-06 & 79-2760/79-01 on 790220 No noncompliance noted. Major areas inspected: export shipment of SRM.
 MARTIN M G, HODGSON R H Region I, Philadelphia, Office of the Director
 JEWETT M H Region I, Philadelphia, Safeguards Branch 79/03/05 3pp

790020082 notifies that response to 790030 ltr re proposed vault mods is not accepted until further advice from licensee.
 HODGSON D G Physical Security Licensing Branch 79/03/19 1p

790020036 Forwards add info in form of revised pages re const of recovery by 790033. SRM Administrative amend fee is required. Does not involve changes in process/diagram layout or safety & motion controls. Amend drawings.
 TOWERS E E United Nuclear Corp 79/03/26 2pp

790020067 Forwards fee for safeguards Insp conducted on 790022-24. Payment is submitted under protest. Request refund if decision is reversed.
 SCOTT D N United Nuclear Corp 79/04/06 3pp

DOCKETED ITEMS

276

790520792 Requests exception to License Condition 7.3.20 for contractor vehicles to be used to transport excavated soil within protected areas. Each vehicle to be escorted by armed Security Unit. United Nuclear Corp. 7/9/04/09 1p

790520796 Forwarded revised pages of "United Nuclear Corp Recovery Sys. Fundamental Nuclear Fuel Control Plan," in response to 790520 1tr. Plan withheld. Leaf Atomic Energy Act of 1954 & Energy Reorganization Act of 1974. J. Edgar Hoover. 7/9/04/20 2pp

790520798 Modified that reph on safeguard contingency plan changes in withheld. Leaf Atomic Energy Act of 1954. J. Edgar Hoover. 7/9/04/20 1p

DOCKET 79-0824 WABCOCK & WILCOX CO.

790520148 Forwarded Amend 1 to Indemnity Agreement Q-Super JCCP140. Changes re liability insurance increase from \$100 million to \$500 million, effective 7/9/05. Supporting documentation and. BULLMAN, J. Antitrust & Insurance Group. 7/9/05/05 1pp

790520208 Confirms 790501. Notes increasing liability limits to \$50 million for WABCO Policies #3, #4, #5, #6, #7, #8, #9, #10, #11, #12, #13, #14, #15, #16, #17, #18, #19, #20, #21, #22, #23, #24, #25, #26, #27, #28, #29, #30, #31, #32, #33, #34, #35, #36, #37, #38, #39, #40, #41, #42, #43, #44, #45, #46, #47, #48, #49, #50, #51, #52, #53, #54, #55, #56, #57, #58, #59, #60, #61, #62, #63, #64, #65, #66, #67, #68, #69, #70, #71, #72, #73, #74, #75, #76, #77, #78, #79, #80, #81, #82, #83, #84, #85, #86, #87, #88, #89, #90, #91, #92, #93, #94, #95, #96, #97, #98, #99, #100. J. Edgar Hoover. 7/9/05/02 1p

790520446 Modified BSW of overpayment of license amend fee refund will be sent. MEGLO, D. License Fee Management Branch. 7/9/05/02 1p

DOCKET 79-0904 PACIFIC NORTHWEST LAB

790520228 Forwarded IE Info Notice 79-26. "Interconnection of Contaminated Gas w/Bruc Air Gas Used as Source of Breathing Air." Region 2, San Francisco. Office of the Director. 7/9/03/20 1p

DOCKET 79-1007 GENERAL ELECTRIC CO.

790520228 Forwarded IE Info Notice 79-26. "Interconnection of Contaminated Gas w/Bruc Air Gas Used as Source of Breathing Air." Region 2, San Francisco. Office of the Director. 7/9/03/20 1p

790520500 Forwarded Annual Electric Rept 1970. "General Electric Co. Nuclear Energy Products Div. 7/9/03/30 1p

DOCKET 79-1014 MORTIMER & MORTIMER CORP.

790520507 Forwarded "Biannual Effluent Monitoring Rept." Jul-Dec 1978. MORTIMER, J. Westinghouse Electric Corp. 7/9/03/02 1pp

790520514 "Biannual Effluent Monitoring Rept." Jul-Dec 1978. MORTIMER, J. Westinghouse Electric Corp. 7/9/03/02 1p

DOCKET 79-1100 CONSTRUCTION ENGINEERS, INC.

790520207 Forwarded emergency plan for low enriched U oxide fuel fabrication plant in Windsor, CT. In response to 790520 1tr. LICHTENBERGER Construction Engineering, Inc. 7/9/04/05 1p

790520427 Emergency plan for low enriched U oxide fuel fabrication plant in Windsor, CT. M790012 & 780414 1tr. Construction Engineering, Inc. 7/9/04/01 05pp

DOCKET 79-1113 GENERAL ELECTRIC CO.

790520207 Forwarded requested revisions to Wilmington Hg Dept's emergency plan. Changes reflect use of protective equipment & supplies; notification of outside agencies & restoration of plant to safe status. KAPLAN, A. L. General Electric Co. Nuclear Energy Products Div. 7/9/04/04 1pp

790520600 Extends appreciation for guidance re reporting of proposed changes to fundamental nuclear fuel control plan. Agrees w/MSR position re prompt submission of plan. Changes. KAPLAN, A. L. General Electric Co. Nuclear Energy Products Div. 7/9/04/04 1p

790520291 Act receipt of 1tr reporting results of 790520-15 Insp conducted by SA Jones at Fuel Fabrication plant. KAPLAN, A. L. General Electric Co. 7/9/04/09 1p

790520291 Act receipt of IE Insp Rept 79-1113/79-10 on 790520 No preparatory info. KAPLAN, A. L. General Electric Co. Nuclear Energy Products Div. 7/9/04/10 1p

790520291 Forwarded IE Insp Rept 79-1113/79-10 on 790520 No noncompliance noted. BUTTERLAND, J. F. Region 2, Atlanta. Fuel Facility & Materials Safety Branch. 7/9/04/06 2pp

790520161 IE Insp Rept 79-1113/79-10 on 790520 No noncompliance noted. Rept area inspected determination of site boundary concentration due to combined release on 790520. TROOP, D. L. Region 2, Atlanta. Office of the Director. 7/9/04/04 1pp

790520401 Act receipt of results of 790520-30 Insp conducted at Fuel Fabrication plant. KAPLAN, A. L. General Electric Co. Nuclear Energy Products Div. 7/9/04/10 1p

790520208 Forwarded revised version of App D to emergency plan re dose distance plots. KAPLAN, A. L. General Electric Co. Nuclear Energy Products Div. 7/9/04/10 1pp

790520208 Act receipt of 790426 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 79-1113/79-07. BUTTERLAND, J. F. Region 2, Atlanta. Fuel Facility & Materials Safety Branch. 7/9/04/30 1p

790520401 Forwarded re NRC 790529 1tr re violations noted in IE Insp Rept 79-1113/79-07. Corrective actions. New procedure implemented re posting of documents required by NRC. KAPLAN, A. L. General Electric Co. 7/9/04/06 2pp

790520207 Forwarded IE Insp Rept 79-1113/79-07 on 790520-0302 & notice of violation. BUTTERLAND, J. F. Region 2, Atlanta. Fuel Facility & Materials Safety Branch. 7/9/03/29 2pp

790520204 Notice of violation from Insp on 790520-0302. Region 2, Atlanta. Office of the Director. 7/9/03/29 1p

790520401 IE Insp Rept 79-1113/79-07 on 790520-0302 Noncompliance noted. Failure to post responses to notice of violation. KAPLAN, A. L. Region 2, Atlanta. Office of the Director. 7/9/03/29 1pp

790520208 Review 790520 1tr to OAD re record-keeping requirements found in 790520. 15 Records retained for five years unless part of investigation. PARTLOW, J. D. Material Control Licensing Branch. 7/9/03/02 1p

DOCKET 79-1113 WESTINGHOUSE ELECTRIC CORP.

790520424 Forwarded amend fee re safeguard contingency plan review. Submits final report. SIFKIN, R. A. Westinghouse Electric Corp. 7/9/01/30 2pp

790520204 Forwarded Revision A to "Plan for Providing Physical Security at (Security) Site." Revision withheld. Westinghouse Electric Corp. 7/9/02/19 1p

7905201008 Forwarded IE Info Notice 79-26. "Interconnection of Contaminated Gas w/Bruc Air Gas Used as Source of Breathing Air." Region 1, Philadelphia. Office of the Director. 7/9/03/28 1p

7905201002 Act receipt of 790516 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 79-1113/79-01 & 30-1113/79-01. SIFKIN, R. A. Region 1, Philadelphia. Fuel Facility & Materials Safety Branch. 7/9/04/04 1p

7905201007 Response to NRC 790526 1tr re violations noted in IE Insp Rept 79-1113/79-02 & 30-1113/79-01. Corrective actions. More detailed copy of control has been instituted. NORME, J. D. Westinghouse Electric Corp. 7/9/03/14 2pp

DOCKETED ITEMS

--790510102 Forwards IE Insp Repts 79-1843/79-02 & 79-4136/79-01 on 790123-04-01 & 0201 & notice of violator
Region 1, Philadelphia: Fuel Facility & Materials
Safety Branch 79/02/26 App

--790510108 Notice of violator from Insp on 790123-04-01 & 0201
Region 1, Philadelphia: Fuel Facility & Materials
Safety Branch 79/02/26 App

--790510110 IE Insp Repts 79-1843/79-02 & 79-4136/79-01 on 790123-04-01 & 0201 Noncompliance noted Failure to perform site safety analysis
Region 1, Philadelphia: Office of the
Director CROCHEN, H. M. Region 1, Philadelphia: Fuel Facility & Materials Safety Branch 79/02/26 App

790510108 Forwards Amend 1 to Indemnity Agreement G-3, per 10CFR140 changeover liability insurance increases from \$100 million to \$100 million effective 790501 Supporting documentation encl
BILTMAN, J. Antitrust & Indemnity Group. 79/03/01 App

790510208 Confirms 790501 telcon increasing liability limit to \$20 million for MAMU Electric HPP-3, HPP-4 & HPP-5.
790501 G. Mutual Atomic Energy Liability Underwriters 79/03/02 App

DOCKET 79-1181 WESTINGHOUSE ELECTRIC CORP.

790503040 Requests license amend to accommodate contaminated low enriched uranium (LEU) of greater than 10% for period not to exceed Jul 1989. Contaminated scrap will be purified through solvent extraction. Details withheld (ref 10CFR2790)
DUFFAZIA, R. P. Westinghouse Electric Corp. 79/05/13 App

7905030712 Requests forwarded mail HNS-1050-048 to be withheld from public disclosure (ref 10CFR2790)
DUFFAZIA, R. P. Westinghouse Electric Corp. 79/03/28 App

790510208 Clarifies issues discussed in recent telcon re request for License BSM-1107 exemption from regulations, including accumulation of scrap containers
FOSBER, M. Westinghouse Electric Corp. 79/03/28 App

7905020474 Forwards revised Page 3 of 7903020 submitted of proposed solid waste fixation, transportation & burial info in response to 790303 telcon.
NEITZEL, E. K. Westinghouse Electric Corp. 79/03/23 App

--7905030477 Forwards proposed solid waste fixation, transportation & burial info describing operations at Columbia site
NEITZEL, E. K. Westinghouse Electric Corp. 79/03/28 App

7905100419 Confirms 790327 telcon request for extension of next BSM physical inventory from 790408 to 790519 Details various for request
FOSBER, M. Westinghouse Electric Corp. 79/03/27 App

7905040303 Forwards IE Insp Repts 79-1181/79-04 on 790328-08-01 Noncompliance noted.
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/03/27 App.

--7905040304 IE Insp Repts 79-1181/79-04 on 790328-08-01 Noncompliance noted Major areas inspected reports license container identification & documentation & radiation & contamination monitoring.
OLNEY, L. J. GILLERIE, F. P. Region 2, Atlanta, Office of the Director. 79/03/27 App.

7905100519 Forwards IE Insp Repts 79-1181/79-04 on 790328-08-01 Noncompliance noted.
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/03/28 App.

--7905040312 IE Insp Repts 79-1181/79-04 on 790319-01 Noncompliance noted Major areas inspected reports license container identification & documentation & radiation & contamination monitoring.
OLNEY, L. J. GILLERIE, F. P. Region 2, Atlanta, Office of the Director. 79/03/28 App.

7905040319 Forwards IE Insp Repts 79-1181/79-04 on 790319-01 Noncompliance noted.
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/03/28 App.

7905040319 Forwards IE Insp Repts 79-1181/79-04 on 790319-01 Noncompliance noted.
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/03/28 App.

7905040319 Forwards IE Insp Repts 79-1181/79-04 on 790319-01 Noncompliance noted.
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/03/28 App.

7905040317 Forwards application for amend to License BSM-1107 to authorize operations w/SM in expanded Columbia Facility. Requester earlier submitted of 790303 Application withheld (ref 10CFR2790)
DUFFAZIA, R. P. Westinghouse Electric Corp. 79/04/04 App

790502044 Ask receipt of 790403 info informing NRC of a shape taken to correct violations noted in IE Insp Repts 79-1181/79-04
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/04/02 App

--7905020419 Responds to NRC 790328 info re violations noted in IE Insp Repts 79-1181/79-04 Corrective actions withheld (ref 10CFR2790)
DUFFAZIA, R. P. Westinghouse Electric Corp. 79/04/05 App

--7905020419 Forwards IE Insp Repts 79-1181/79-04 on 790328-04 Notice of violation withheld (ref 10CFR2790)
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/03/03 App

790502041 IE Insp Repts 79-1181/79-04 on 790328-04 Noncompliance noted Failure to follow approved plan for sampling U oxide pellets Details withheld (ref 10CFR2790)
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/03/13 App

790503040 Forwards IE Insp Repts 79-1181/79-04 on 790409-12 No noncompliance noted.
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/04/23 App

--7905070202 IE Insp Repts 79-1181/79-04 on 790409-12 No noncompliance noted Major areas inspected onsite records & reports. Details withheld (ref 10CFR2790)
GILLERIE, F. P. Region 2, Atlanta, Safeguards Branch
NEITZEL, E. K. Region 2, Atlanta, Office of the Director. 79/04/18 App

790503040 Forwards 790417 discussion re current LEID model Westinghouse-Columbia model needs to be modified to ensure proper treatment of systematic errors.
PARTLOW, J. O. Material Control Licensing Branch. 79/05/03 App

DOCKET 79-1179 HENRYHART COALCOKE

7905030512 Ask receipt of 790427 info identifying inaccurate amend numbers in NRC 790409 (IE) Forwards corrected pages. First withheld (ref 10CFR2790).
HODGKINS, G. M. Physical Security Licensing Branch. 79/05/07 App

DOCKET 79-1193 CUMMINGS FACILITY, KERR-HOGUE CORP.

7905100517 Forwards IE Insp Repts 79-06, "Interconnection of Contaminated Bay w/Hot Air Bay used as Source of Breathing Air"
NEITZEL, E. K. Region 3, Chicago, Office of the Director. 79/03/28 App.

7905030734 Cancels Amend HPP-2 & issues encl safeguards Amend HPP-3 for License BSM-1174
BARNETT, R. F. Division of Safeguards. 79/04/09 App.

--7905030771 Amend HPP-3 to License BSM-1174 re requirements for control, monitoring & physical security of BSM.
BARNETT, R. F. Division of Safeguards. 79/03/31 App

7905040319 Responds to 790319 info re dismantling & removal of solvent extraction system. Forwards license Amend 3. Comments on deletions & revisions to license, shipments & mail inventories, except where specified in Condition 2.1.
BARNETT, R. F. Division of Safeguards. 79/04/09 App.

--7905040444 Amend 3 to License BSM-1174 regarding measurement of U/Fu & U-235 content of BSM receipt, shipments & mail inventories, except where specified in Condition 2.1.
BARNETT, R. F. Division of Safeguards. 79/03/31 App.

DOCKET 79-1104 UPR & COMMERCE FACILITY, BASCOCK & WILCOX CO

7905100512 Forwards IE Insp Repts 79-1201/79-05 on 790327-03 No noncompliance noted.
KEMMA, M. B. Region 2, Atlanta, Safeguards Branch. 79/04/13 App

DOCKETED ITEMS

277

- 7903100116 IE Insp Rept 70-1201/79-09 on 790327-30 No noncompliance noted. Major areas inspected: licensee action on previously identified items & measurements & statistical control. Details withheld (ref 10CFR2 7901).
JONES, S. W., WILKINS, T. D. Region 3, Atlanta, Office of the Director
BUREAU, COLLIER, F. P. Region 2, Atlanta, Safeguards Branch
79/04/01 Ip
- 7903070243 Act Receipt of 790412 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1201/79-06.
KEMNA, M. B. Region 2, Atlanta, Safeguards Branch. 79/04/20 Ip
- 7903070245 Response to NRC 790326 ltr re violations noted in IE Insp Rept 70-1201/79-06. Corrective actions withheld (ref 10CFR2 7901).
BILM, R. J. Babcock & Wilcox Co. 79/04/12 Ip
- 7903070252 Response IE Insp Rept 70-1201/79-06 on 790326-0301, Notice of violation withheld (ref 10CFR2 7901).
KEMNA, M. B. Region 2, Atlanta, Safeguards Branch. 79/03/26 Sp
- 7903070254 IE Insp Rept 70-1201/79-06 on 790326-0301 Noncompliance noted. Failure to determine measurements bias from 4544 program details withheld (ref 10CFR2 7901).
MULLIN, D. H., ROBERTSON, J. S. C. Region 2, Atlanta, Safeguards Branch. 79/03/22 Ip
- 7903030014 Response IE Insp Rept 70-1201/79-11 on 790419-20 No noncompliance noted.
KEMNA, M. B. Region 2, Atlanta, Safeguards Branch. 79/03/02 Sp
- 7903030020 IE Insp Rept 70-1201/79-11 on 790419-20 No noncompliance noted. Major areas inspected: storage & internal control & following up previous enforcement actions. Details withheld (ref 10CFR2 7901).
TODD, C. A. Region 2, Atlanta, Office of the Director
SILVERSTEIN, F. R. Region 3, Atlanta, Safeguards Branch. 79/03/01 Ip
- 790320184 Processes adding new licensee conditions to Amend RFP-2 to allow for procedures in fundamental nuclear anti-control plant category to list of regulation. Requests response as to acceptability of amendment.
PARTLOW, J. D. Material Control Licensing Branch. 79/03/08 Sp
- 906KEY 70-1287 MIXED OXIDE FERTILIZATION PLANT, EXXON NUCLEAR CO., INC.
- 7903150456 Response IE Insp Rept 70-1287/79-01 on 790312-1A No noncompliance noted.
BROWN, H. C. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/03/16 Sp
- 7903150701 IE Insp Rept 70-1287/79-01 on 790312-1A No noncompliance noted. Major areas inspected: safety committee activities; training; safety critical safety emergency planning & fire & radiation protection.
COOLEY, W. J., DUNHAM, R. P. H. Region 5, San Francisco, Office of the Director
BROWN, H. C. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 79/03/16 Sp
- 7903150828 Response IE Insp Rept 79-06, "Interconnection of Cooled Reactor Sigsbee Air Sys Used as Source of Breathing Air".
BROWN, H. C. Region 5, San Francisco, Office of the Director
BROWN, H. C. Region 5, San Francisco, Office of the Director. 79/03/28, Ip
- 7903150830 Response IE Insp Rept 70-1287/79-02 on 790326-31 Rept withheld (ref 10CFR2 7901).
MCDONALD, R. R. Region 5, San Francisco, Safeguards Branch. 79/04/24 Sp
- 7903180123 Response Amend 1 to Indemnity Agreement 3-Owner 10CFR140 therefore liability insurance from increase from \$145 million to \$145 million effective 790326 Supporting documentation incl.
MULLIN, D. H. Antitrust & Economy Group. 79/03/26, Sp
- DOCKET 70-1328 NRRIS OPERATIONS, GENERAL ELECTRIC CO.
- 7903140058 Response table indicating re status change for fuel stored in bin & Feb 1979.
SAMMON, D. H. General Electric Co. Nuclear Energy Products Div. 79/03/09, Sp.
- 7903200437 Response IE Insp Rept 70-1309/79-02 on 790326-0301-02 & 07. No noncompliance noted.
DAVIS, A. E. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 79/03/28, Sp.
- 7903200442 IE Insp Rept 70-1309/79-02 on 790326-0301-02 & 07. No noncompliance noted. Major areas inspected: emergency planning & fire protection.
MULLIN, D. H., ROBERTSON, J. S. C. Region 3, Chicago, Office of the Director. 79/03/21, Sp.
- 7903200456 Response to NRC 790326 ltr re decommissioning plan for NRRIS Operation.
SAMMON, D. H. General Electric Co. Nuclear Energy Products Div. 79/04/04, Sp.
- 7903200370 Response Amend 7 to License BWR-1245, BWR-1251, re reinstated ROURE, L. C. Fuel Reprocess & Recycle Branch. 79/04/10, Sp.
- 7903200382 Amend 7 to License BWR-1245, terminating License BWR-1251 & incorporating operation space of consolidated SAR Chapter 10.
ROURE, L. C. Fuel Reprocess & Recycle Branch. 79/04/10, Sp.
- 7903180247 Act Receipt of 790404 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1309/79-01.
Details withheld (ref 10CFR2 7901).
HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/04/20 Sp.
- 7903150320 Response to NRC 790316 ltr re violations noted in IE Insp Rept 70-1309/79-01 Corrective Actions withheld (ref 10CFR2 7901).
SAMMON, D. H. General Electric Co. Nuclear Energy Products Div. 79/04/04, Ip.
- 7903150744 Response IE Insp Repts 70-1309/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted.
HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/04/26, Sp.
- 7903150754 IE Insp Repts 70-1309/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted. Major areas inspected: review of BWR records; PWR-21 decay calculations & nuclear mail transaction details withheld (ref 10CFR2 7901).
FINLEY, D. O., PATTERSON, J. F. Region 3, Chicago, Office of the Director
HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/04/26, Ip.
- DOCKET 70-1309 NRRIS OPERATIONS, GENERAL ELECTRIC, GENERAL
- 7903240370 Response Amend 7 to License BWR-1245, BWR-1251 re reinstated ROURE, L. C. Fuel Reprocess & Recycle Branch. 79/04/10, Sp.
- 7903200382 Amend 7 to License BWR-1245, terminating License BWR-1251 & incorporating operation space of consolidated SAR Chapter 10.
ROURE, L. C. Fuel Reprocess & Recycle Branch. 79/04/10, Sp.
- 7903180744 Response IE Insp Repts 70-1309/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted.
HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/04/26, Sp.
- 7903150754 IE Insp Repts 70-1309/79-04 & 70-1309/79-01 on 790410-12 No noncompliance noted. Major areas inspected: review of BWR records; PWR-21 decay calculations & nuclear mail transaction details withheld (ref 10CFR2 7901).
FINLEY, D. O., PATTERSON, J. F. Region 3, Chicago, Office of the Director
HIND, J. A. Region 3, Chicago, Safeguards Branch. 79/04/26, Ip.
- DOCKET 70-1309
- 7903150028
- STURDIS
- 790320002
- NE, NUC
- REACTOR
- 114000
- 000000
- 79/04/26
- DOCKET 7
- 790320002
- NE, NUC
- REACTOR
- 114000
- 000000
- 79/04/26

DOCKETED ITEMS

27

79029070 Second set of interrogatories submitted to applicant
891844A.2. Natural Resources Defense Council 7/9/04/02 Ypp

79029070 Motion for order to dismiss Caroline Ashton as active
participant in proceeding due to failure to provide answers
to applicant's interrogatories of 790316 Certificate of Rec
and 79029070 J M Duke Power Co 7/9/05/02 Ypp

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 Ack receipt of 790303 for informing NRC of steps taken to
correct deviation noted in IE Insp Regs 30-1073/79-01 &
79-0733/79-01
79029070 J M Duke Power Co 7/9/05/02 Ypp

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC
79029070 79029070 HCLVORC HCLVORC HCLVORC HCLVORC

DOCKETED ITEMS

DOCKET 71-0047 CAPITAL INTERNATIONAL, AMER. INC.

7905050799 Forwards request for addl info to complete review of QA program
MCDONALD, C. E. Transportation Branch 79/04/13 2pp

7905180452 Forwards QA requirements for transportation packaging in response to 790428 telcon
BARNES, E. Capital International Airways, Inc. 79/04/27 1p

--7905180499 "QA Requirements for Transportation Packaging (100FR71) As Applicable to Industrial Radiography Licenses"
B. Capital International Airways, Inc. 79/04/27. 4pp

DOCKET 71-0048 INTERMOUNTAIN PIPE & WELDING

7905150114 Proposed QA program does not meet requirements of App E to 100FR71. Forwards sample QA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790502.
MCDONALD, C. E. Transportation Branch 79/04/27. 2pp

DOCKET 71-0050 HESLAND-BOSCH CORP.

7905190318 Forwards QA program approval for radioactive mail package
MCDONALD, C. E. Transportation Branch 79/03/28 1p

--7905190323 QA program approval for radioactive mail package 0950.
Revision G
MCDONALD, C. E. Transportation Branch 79/03/22 1p.

DOCKET 71-0055 H. H. INSPECTION SERVICE

7905200908 Forwards addl info for approval of QA program
BOONER, H. H. H. Inspection Service 79/03/02. 4pp

DOCKET 71-0056 PHILADELPHIA ELECTRIC CO.

7905240104 Informa that Amend 25 to PWRB contains existing QA program, in response to NRC 790521 request.
DELTROFF, D. L. Philadelphia Electric Co. 79/04/10 1p

DOCKET 71-0057 EXCON CO. USA, EXCON CORP.

7905050489 Forwards Radiation Safety Committee organizational chart, in response to NRC 790428 ltr.
WILLIAMS, R. H. Excon Corp. 79/04/28 2pp

DOCKET 71-0063 GAWK AIRLINES, INC.

7905150482 Forwards request for addl info to complete review of QA program. Requests statement that scope of audit program will include annual audit of personnel training/personnel qualifications & factors loading.
MCDONALD, C. E. Transportation Branch 79/04/13 2pp

7905150094 Forwards QA Program for License 28-13991-01.
YOUNG, R. E. Gawk Airlines 79/04/20 1p

--7905150094 QA Program for License 28-13991-01.
B. Gawk Airlines. 79/04/22. 4pp.

DOCKET 71-0065 H. F. & ASSOCIATES, INC.

7905240582 Proposed QA program does not meet requirements of App E to 100FR71. Forwards sample QA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790502.
MCDONALD, C. E. Transportation Branch. 79/04/27. 2pp.

DOCKET 71-0066 CERTIFIED TESTING LABS., INC.

7905190540 Proposed QA program does not meet requirements of App E to 100FR71. Forwards sample QA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790427.
MCDONALD, C. E. Transportation Branch. 79/04/27. 2pp.

DOCKET 71-0068 VIKING ATOMIC ELECTRIC CO.

7905240311 Forwards QA program approval for radioactive mail package
MCDONALD, C. E. Transportation Branch 79/05/04 1p

--7905240318 QA program approval for radioactive mail package 0606.
Revision D
MCDONALD, C. E. Transportation Branch 79/05/04 1p

DOCKET 71-0070 GENERAL MOTORS CORP.

7905240342 Informa that proposed QA program does not meet requirements of App E to 100FR71. Forwards sample QA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790502.
MCDONALD, C. E. Transportation Branch 79/04/20 1p.

--7905240350 "QA Program for Industrial Radiography Licenses"
B. Transportation Branch 79/04/02 2pp

DOCKET 71-0072 BABCOCK & WILCOX CO.

7905110457 Proposed QA program does not meet requirements of App E to 100FR71. Forwards sample QA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790502.
MCDONALD, C. E. Transportation Branch. 79/04/27 2pp

DOCKET 71-0074 NUCLEAR WELDING, INC.

7905110071 Proposed QA program does not meet requirements of App E to 100FR71. Forwards sample QA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790502.
MCDONALD, C. E. Transportation Branch 79/04/27. 2pp

DOCKET 71-0077 HIBETATE TESTING LAB.

7905030285 Forwards QA Program for License 15-11822-01
HEILMAN, J. J. Hibetate Testing Laboratory, Inc. 79/04/05 1p.

--7905030289 QA Program for License 15-11822-01
HEILMAN, J. J. Hibetate Testing Laboratory, Inc. 79/04/05 4pp.

7905240145 Forwards request for addl info to complete review of QA program
MCDONALD, C. E. Transportation Branch 79/04/27 2pp

DOCKET 71-0087 NAVY, DEPT. OF

7905110254 Proposed QA program does not meet requirements of App E to 100FR71. Forwards sample QA program for industrial radiography licenses, dtd 790402, to assist in application revision. Requests revision by 790502.
MCDONALD, C. E. Transportation Branch. 79/04/20 2pp.

DOCKET 71-0088 BABCOCK & WILCOX CO.

7905240147 Forwards request for addl info to complete review of QA program.
MCDONALD, C. E. Transportation Branch. 79/04/13 12pp

DOCKET 71-0089 NAVY, DEPT. OF

7905070447 Forwards request for addl info to complete review of QA program
MCDONALD, C. E. Transportation Branch 79/04/13 2pp.

DOCKET 71-0090 COMBUSTION ENGINEERING CO., INC.

7905250913 Responds to request for addl info re QA program. Will continue to use existing QA program until approval of QA Program CERN-QM is obtained. Supporting documentation incl 1107070305. Combustion Engineering, Inc. 79/04/11. 4pp.

DOCKETED ITEMS

281

DOCKET 71-0099 POSTER SHIELDER ENERGY CORP.

7905070025 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/13 App

DOCKET 71-0103 THEN CITY TESTING & ENG'G LAB

7905070029 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/13 App

DOCKET 71-0104 CHICAGO BRIDGE & IRON CO

7905070026 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/13 App

7905070031 Forwards QA program for License 52-05630-01
MERRILL R R Chicago Bridge & Iron Co 79/04/13 App

--7905060514 QA program for License 52-05630-01
Chicago Bridge & Iron Co 79/04/13 App

DOCKET 71-0109 UNION CARBIDE CORP

7905061009 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/20 12pp.

DOCKET 71-0110 BUXHEVE STEEL CASTINGS

7904230011 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/06 App.

7905240034 Forwards QA program for industrial radiography re handling & shipping of packages
KORBER, J F Bortage International, Inc., Wheel Castings Div.
79/04/27 App

--79052400715 QA program for industrial radiography
Bortage International, Inc. Wheel Castings Div. 79/04/27 App

DOCKET 71-0111 MATERIAL TESTING LAB. OF VIRGINIA, INC.

7905110075 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licenses, dtd 790430, to assist in application revision Request revision by 790502
NACSONAL.D.C.E Transportation Branch 79/04/27 App

DOCKET 71-0116 NAVY DEPT. OF

7905110010 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licenses, dtd 790430, to assist in application revision Request revision by 790502
NACSONAL.D.C.E Transportation Branch 79/04/20 App

DOCKET 71-0119 UNDERHILL-BANK CO.

7905050027 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/13 App

DOCKET 71-0120 DANIEL INTERNATIONAL CORP.

7905110015 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licenses, dtd 790430, to assist in application revision Request revision by 790502
NACSONAL.D.C.E Transportation Branch 79/04/27 App.

DOCKET 71-0121 NEVRON PRODUCTS, INC.

7905240135 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/27 12pp

DOCKET 71-0125 STRATHEM CORP

7905180740 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/13 App

DOCKET 71-0127 NATIONAL ANNEALING BOX CO

7905070028 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/13 App.

7905050104 Forwards inspectional chart requested by NAC 790413 ltr.
FRANTZ-J-R National Annealing Box Co 79/04/14 App

DOCKET 71-0128 AMSCO GIL CO

7905110001 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licenses, dtd 790430, to assist in application revision Request revision by 790502
NACSONAL.D.C.E Transportation Branch 79/04/27 App

DOCKET 71-0130 CHICAGO BRIDGE & IRON CO

7905070037 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/13 App

DOCKET 71-0131 HOLDING INSTITUTE OF ALABAMA

7905110019 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licenses, dtd 790430, to assist in application revision Request revision by 790502
NACSONAL.D.C.E Transportation Branch 79/04/27 App.

DOCKET 71-0137 METALS TESTING CO., INC.

7905180078 Forwards "Shipping Container QA Requirements,"
SELIGLE R. Metals Testing Co., Inc 79/04/16. 1p.

--7905180008 "Shipping Container QA Requirements"
Metals Testing Co., Inc 79/04/16 App.

DOCKET 71-0141 ROCKWELL INTERNATIONAL

7905110004 Proposed QA program does not meet requirements of App E to 10CFR71 Forwards sample QA program for industrial radiography licenses, dtd 790430, to assist in application revision Request revision by 790502
NACSONAL.D.C.E Transportation Branch 79/04/27 App.

DOCKET 71-0142 RANCHERS EXPLORATION & DEV. CO

7905040161 Forwards request for addl info to complete review of QA program
NACSONAL.D.C.E Transportation Branch 79/04/27 App.

DOCKETED ITEMS

DOCKET 71-0151 HESS OIL VIRGIN ISLANDS CORP

790502004 Responds to request for addl info re GA program Discusses organization, document control, handling, storage & shipping; test records & audits
 PHELAM, R. H. Hess Oil Virgin Islands Corp 79/04/16 App

DOCKET 71-0154 GENERAL DYNAMICS

790502016 Inform that been "radiation safety officer" has been replaced w/ "radiation protection officer" for License
 35-11415-01
 ROBERTS, V. M. General Dynamics Corp - Quincy Shipbuilding Div 79/04/16 App

DOCKET 71-0174 INDUSTRIAL FABRICATING CO

790511063 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography license, dtd 790425, to assist in application revision. Requests revision by 790503
 MACDONALD, C. E. Transportation Branch 79/04/27 App

DOCKET 71-0193 X-RAY INDUSTRIES, INC

790504085 Forwards info to clarify GA program for License 21-05472-01, in response to 790413 ltr
 THOMPSON, R. W. X-Ray, Inc 79/04/24 App

DOCKET 71-0161 CURTIS-WRIGHT CORP

790505084 Responds to NRC 790403 ltr re radioactive sealed source shipping procedure. Forwards revised GA program
 JACKSON, C. Curtis-Wright Corp 79/05/01 App

--790505084 Revised GA program
 JACKSON, C. Curtis-Wright Corp. 79/05/01, App.

DOCKET 71-0142 EMBAC SERVICES, INC

790501085 Forwards request for addl info to complete review of GA program
 MACDONALD, C. E. Transportation Branch 79/04/12 App

DOCKET 71-0146 NEW YORK TESTING LABS, INC

790515017 Forwards request for addl info to complete review of GA program
 MACDONALD, C. E. Transportation Branch 79/04/13 App

DOCKET 71-0167 FINLAY TESTING LABORATORIES

790510149 Forwards request for addl info to complete review of GA program
 MACDONALD, C. E. Transportation Branch 79/04/13 App

DOCKET 71-0168 QUALITY ASSURANCE LABS

790515020 Forwards request for addl info to complete review of GA program
 MACDONALD, C. E. Transportation Branch 79/04/13 App

DOCKET 71-0149 FLORIDA POWER & LIGHT CO.

790524034 Forwards GA program approval for radioactive mail packages
 MACDONALD, C. E. Transportation Branch 79/05/04 App

--790524034 GA program approval for radioactive mail packages
 MACDONALD, C. E. Transportation Branch, 79/05/04, App

DOCKET 71-0174 SOUTHERN CALIFORNIA Edison CO.

790524039 Forwards chronology of PSA and re GA program, in response to NRC 790320 request
 BARKIN, K. P. Southern California Edison Co. 79/04/27 App

DOCKET 71-0175 SC SERVICES, INC

790502034 Forwards request for addl info to complete review of GA program
 MACDONALD, C. E. Transportation Branch 79/04/13 App

DOCKET 71-0176 HARRY PRODUCE GROUP

790502039 Forwards request for addl info to complete review of GA program
 MACDONALD, C. E. Transportation Branch 79/04/12 App

DOCKET 71-0180 HARTFORD WEAH OUTLER CO

790502039 Forwards request for addl info to complete review of GA program
 MACDONALD, C. E. Transportation Branch 79/04/12 App

DOCKET 71-0181 CONSOLIDATED X-RAY SERVICE CORP

790511009 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography license, dtd 790420, to assist in application revision. Requests revision by 790503
 MACDONALD, C. E. Transportation Branch 79/04/27 App

DOCKET 71-0188 HAYWARD STEEL CASTING CO

790512017 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography license, dtd 790420, to assist in application revision. Requests revision by 790503
 MACDONALD, C. E. Transportation Branch 79/04/27 App

DOCKET 71-0197 TONG SHIPYARD CORP

790512014 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography license, dtd 790420, to assist in application revision. Requests revision by 790503
 MACDONALD, C. E. Transportation Branch 79/04/27 App

DOCKET 71-0202 PACIFIC GAS & ELECTRIC CO

790529001 Responds to 790513 ltr. Lists references to specific docketed info describing operational GA program
 CRANE, P. A. Pacific Gas & Electric Co 79/04/20 App

DOCKET 71-0203 QUALITY TESTING, INC.

790528004 Forwards GA program for use of approved packages in shipment of sealed sources
 MASTERSON, D. J. Quality Testing, Inc 79/05/01 App

--790528004 GA program for use of approved packages in shipment of sealed sources
 MASTERSON, D. J. Quality Testing, Inc 79/05/01 App

DOCKET 71-0207 CONNECTICUT Yankee Atomic Power Co

790524030 Inform that label revision to operational GA program is described in Revision 2A to GA regd MU-Qa-1, forwarded to NRC on 790424
 COUNSEL, W. G. Connecticut Yankee Atomic Power Co. 79/04/26 App

DOCKET 71-0209 JACKSONVILLE SHIPYARD, INC

790511008 Proposed GA program does not meet requirements of App E to 10CFR71. Forwards sample GA program for industrial radiography license, dtd 790420, to assist in application revision. Requests revision by 790503
 MACDONALD, C. E. Transportation Branch, 79/04/27, App

DOCKETED ITEMS

283

DOCKET 71-0219 INTERENTAIN TESTING CO.

7905020066 Forwards request for addl info to complete review of GA program
NACDNDMLB.C E Transportation Branch 79/04/12 App.

DOCKET 71-0214 GAN REMITALS, INC.

7905100567 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses-dtd 790402, to assist in application revision Requests revision by 790502
NACDNDMLB.C E Transportation Branch 79/04/27 App

DOCKET 71-0215 SPACE SCIENCE SERVICES

7905100568 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses-dtd 790402, to assist in application revision Requests revision by 790502
NACDNDMLB.C E Transportation Branch 79/02/10 App

DOCKET 71-0216 NUCLEAR ENERGY SERVICES, INC.

7905020084 Forwards request for addl info to complete review of GA program
NACDNDMLB.C E Transportation Branch 79/04/12 App

7905040025 Forwards GA Program 99-06-002
GAMBLE.C C Associate code 79/04/27 App

--7905040038 Responds to Dec 1970 application requesting approval of GA program Requests addl info re operating logs & results of insps
NACDNDMLB.C E Transportation Branch 79/04/12 App

--7905040043 GA Program 99-06-002
GAMBLE.C C Associate code 79/11/30 App

DOCKET 71-0217 FULLMAN KELLERS, INC.

7905020027 Forwards request for addl info to complete review of GA program
NACDNDMLB.C E Transportation Branch 79/04/08 App

7905100447 Responds to 790405 ltr requesting addl info re GA program For License 42-16073-01 Lists changes which will be incorporated into program
TURNER.C E Fullman, Inc 79/04/17 App

DOCKET 71-0220 GENERAL SYNTHETIC CORP.

7905020076 Forwards request for addl info to complete review of GA program
NACDNDMLB.C E Transportation Branch 79/04/12 App

DOCKET 71-0222 ST. LOUIS TESTING LAB., INC.

7905020072 Responds to 790405 request for info re GA program sections concerning radioactive metal shipping package design & responsibility for performing critical handling & storage
TURNER.C E St. Louis Testing Lab., Inc 79/04/26 App

DOCKET 71-0223 R. F. BISH, INC.

7905020021 Forwards request for addl info to complete review of GA program
NACDNDMLB.C E Transportation Branch 79/04/12 App.

DOCKET 71-0225 NAVY, DEPT OF

7905020114 Forwards request for addl info to complete review of GA program
NACDNDMLB.C E Transportation Branch 79/04/12 App.

DOCKET 71-0226 NEW YORK STATE UNIV. OF

7905020093 Forwards request for addl info to complete review of GA program
NACDNDMLB.C E Transportation Branch 79/04/12 App

DOCKET 71-0228 3-BAY, INC.

7905020064 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses-dtd 790402, to assist in application revision Requests revision by 790502
NACDNDMLB.C E Transportation Branch 79/04/27 App

DOCKET 71-0230 ARMY, DEPT OF

7905020043 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses-dtd 790402, to assist in application revision Requests revision by 790502
NACDNDMLB.C E Transportation Branch 79/04/27 App

DOCKET 71-0232 AGRICULTURE, DEPT OF

7905020147 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses-dtd 790402, to assist in application revision Requests revision by 790502
NACDNDMLB.C E Transportation Branch 79/04/27 App

DOCKET 71-0233 NAVY, DEPT OF

7905020191 Forwards request for addl info to complete review of GA program
NACDNDMLB.C E Transportation Branch 79/04/12 App

DOCKET 71-0234 UNITED NUCLEAR CORP.

7905040074 Forwards request for addl info to complete review of GA program
NACDNDMLB.C E Transportation Branch 79/04/20 ltrp

DOCKET 71-0235 WESTINGHOUSE ELECTRIC CORP.

7905020094 Responds to 790320 ltr Confirms that package suppliers need not have GA program approved per App E of 10CFR71 User is responsible to ensure that all transportation activities meet specified criteria
NACDNDMLB.C E Transportation Branch 79/04/26 ltr

DOCKET 71-0239 WASHINGTON CO.

7905100317 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses-dtd 790402, to assist in application revision Requests revision by 790502
NACDNDMLB.C E Transportation Branch 79/04/27 App

DOCKET 71-0257 INDUSTRIAL LAMM, INC.

7905100332 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses-dtd 790402, to assist in application revision Requests revision by 790502
NACDNDMLB.C E Transportation Branch 79/04/27 App

DOCKET 71-0242 AMTITECH, INC.

7905100199 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses-dtd 790402, to assist in application revision Requests revision by 790502
NACDNDMLB.C E Transportation Branch 79/04/20 App.

DOCKET 71-0241 NAVY, DEPT OF

7905020233 Proposed GA program does not meet requirements of App E to 10CFR71 Forwards sample GA program for industrial radiography licenses-dtd 790402, to assist in application revision Requests revision by 790502
NACDNDMLB.C E Transportation Branch 79/04/20 App.

DOCKETED ITEMS

DOCKET 71-0266 DUKE POWER CO

7903040241 Comply to applying Revision 4 to GA Nuclear Regs. State-I-A.
To comply w/10CFR71 App E requirements in response to 790402
for
PARMER, R. G. Duke Power Co 79/04/11 1p

7903040609 Forwards GA program approval for radioactive mail package
MACDONALD, C. E. Transportation Branch 79/03/01 1p

7903040404 GA program approval for radioactive mail packages issued to
Duke Power Co
MACDONALD, C. E. Transportation Branch 79/03/01 1p

DOCKET 71-0268 HWY. DEPT OF

7903030239 Proposed GA program does not meet requirements of App E to
10CFR71 Forwards sample GA program for industrial
radioactive license. dtd 790302. Re submit in application
revision Requested revision by 790302
MACDONALD, C. E. Transportation Branch 79/04/20 3pp

DOCKET 71-0273 HWY. DEPT OF

7903030448 Proposed GA program does not meet requirements of App E to
10CFR71 Forwards sample GA program for industrial
radioactive license. dtd 790302. Re submit in application
revision Requested revision by 790302
MACDONALD, C. E. Transportation Branch 79/04/20 3pp

DOCKET 71-0277 ALLIED CHEMICAL CORP

7903070628 Forwards request for addl info to complete review of GA
program
MACDONALD, C. E. Transportation Branch 79/04/11 10pp.

7903040867 Response to 790411 ltr Will discuss GA program during
790302 meeting Will revise program to meet NRC
requirements
MCDONALD, R. Allied Chemical Corp 79/04/27 1p

DOCKET 71-0280 ABCO REFRIGERATORS, INC

7903030284 Forwards GA program for License 4-1720 authorizing shipment
of radiolabeled
COOK, C. L. ABCO Refrigerators, Inc 79/03/12 3pp

7903030478 GA program for License 4-1720 authorizing shipment of
radiolabeled
COOK, C. L. ABCO Refrigerators, Inc 79/03/12 3pp

DOCKET 71-0282 WEN MILLHEAD SYSTEMS, INC.

7903030286 Forwards GA program for License LA-0265-1-01
CARROLL, E. Wen Millhead Systems, Inc 79/03/14 3pp.

DOCKET 71-0286 BPS INSTRUMENTS, INC

7903030334 Forwards GA program for License 12-17342-01
GRACE, J. O. BPS Instruments, Inc 79/03/17 1p.

7903030627 GA program for License 12-17342-01 for compliance w/10CFR71,
App E
GRACE, J. O. BPS Instruments, Inc 79/03/17 3pp

DOCKET 71-0287 CARBON NON-DESTRUCTIVE TESTING

7903030318 Forwards request for addl info to complete review of GA
program
MACDONALD, C. E. Transportation Branch 79/04/13 3pp.

DOCKET 71-0288 NORTH DAKOTA STATE WATER COMMISSION

7903030393 Forwards GA program for License 20-0240-01
BURRIS, P. A. North Dakota, State of 79/03/14 1p.

7903030393 GA program for ND State Water Commission for compliance
w/10CFR71, App E
BURRIS, P. A. North Dakota, State of 79/03/15 3pp

DOCKET 71-0290 UNITED TESTING SERVICES, INC

7903030283 Forwards GA program of United Testing Svc implemented for
LA-271-1-01 per 10CFR71 App E requirements 10/10/1978
Baker
United Testing Services, Inc 79/03/20 4pp

DOCKET 71-0294 OMA ELECTRIC LIGHT & POWER CO

7903030460 Plans to modify GA program in order to implement shipping
activities Re further shipments of Type B radioactive will be
made until approval is received from NRC
LNU, L. Oma Electric Light & Power Co 79/03/16 1p

7903030723 Forwards GA program approval for radioactive mail package
MACDONALD, C. E. Transportation Branch 79/04/10 2pp

DOCKET 71-0297 E. LEWIS COOK & ASSOCIATES

7903030443 Forwards GA program for License 12-0320-1-5
HARRIS, R. W. E. Lewis Cook & Associates 79/03/21 1p

7903030443 GA program for License 12-0320-1-5
HARRIS, R. W. E. Lewis Cook & Associates 79/03/21 4pp

DOCKET 71-0299 QUALITY CONTROL SERVICES, INC

7903040173 Forwards GA program for License 12-1455-01
GACHNE, J. Quality Control Services, Inc 79/03/30 1p

7903040183 GA program for License 12-1455-01
GACHNE, J. Quality Control Services, Inc 79/03/30 2pp

DOCKET 71-0300 INDEPENDENT TESTING LABORATORIES

7903030296 Forwards GA program for License 20-1581-02
BANK, M. E. Independent Testing Laboratories 79/03/26 1p

7903030296 GA program for License 20-1581-02
BANK, M. E. Independent Testing Laboratories 79/03/26 3pp

DOCKET 71-0304 TELETYPE BROWN ENGINEERING CO.

7903030303 Forwards GA program for State of N. License 599
MYERS, H. A. Teletype Brown Engineering Co 79/03/27 1p

7903030303 GA program for State of N. License 599
MYERS, H. A. Teletype Brown Engineering Co 79/03/27 3pp

DOCKET 71-0308 AMERICAN 2-BAY & INSPECTION, INC

7903030341 Forwards GA program for License 21-15475-01
SHAWMUT, T. B. American 2-Bay & Inspection 79/03/30 1p.

7903030341 GA program for License 21-15475-01.
SHAWMUT, T. B. American 2-Bay & Inspection 79/03/31 3pp

DOCKET 71-0307 TREAT PIPE BENDING CO OF PUERTO RICO

7903030348 Forwards GA program for License 20-15620-01
MARRON, R. C. Treat Pipe Bending Co (subs of Bendit Corp).
79/03/20 1p.

7903030348 GA program for License 20-15620-01
MARRON, R. C. Treat Pipe Bending Co (subs of Bendit Corp).
79/03/20 3pp

DOCKET 71-0309 WASHINGTON PUMP CORP. (USA)

7903030763 Forwards GA program for License 20-02210-02
HOLMES, R. L. Washington Pump, Inc (subs of Budehardt-Washington
N. Inc.). 79/03/30 1p

DOCKETED ITEMS

285

7905150705 SA program for License 24-03210-02
HOLMES, E. L. Worthington Pump, Inc. (subs. of
Stokewater-Worthington, Inc.) 79/01/01 7pp

DOCKET 71-0311 LUGWELL, INC.

7905150489 Forwarded SA program for License 35-13565-03
BAILEY, F. G. Lugwell 79/03/30 1p

7905150493 SA program for License 35-13565-01
BAILEY, F. G. Lugwell 79/03/30 4pp

DOCKET 71-0302 METALFORM, INC.

7905150426 Forwarded SA program for License 8-2261
BENNETT, C. Metalform, Inc. 79/03/29 1p

7905150432 SA Program for License 8-2261
BENNETT, C. Metalform, Inc. 79/03/29 43pp

DOCKET 71-0317 HUDSON PRODUCTS CORP.

7905240305 Forwarded SA program for License 8-2370
BENEFIELD, H. E. Hudson Products Corp. 79/04/16 1p

7905240210 SA program for License 8-2370
BENEFIELD, H. E. Hudson Products Corp. 79/04/16 4pp

DOCKET 71-0322 CONTROL COMPONENTS INTERNATIONAL

7905290004 Forwarded SA program for Control Components Intl. implemented
for License 3284-30, State of CA
LAMBERT, R. Babcock & Wilcox Co. 79/04/11 1p

7905290008 SA program implemented for License 3284-30 State of CA
LAMBERT, R. Babcock & Wilcox Co. 79/04/11 3pp

DOCKET 71-4984 MODEL 9A-B, EXXON NUCLEAR CO., INC.

7905240317 Forwarded Revision 4 of Certificate of Compliance 4984 for
shipping package Models 9A-1, 2, 3 & 4
MACDONALD, C. E. Transportation Branch 79/04/26 3pp

7905240323 Certificate of Compliance 4984, Revision 4, for radioactive
material shipping package Models 9A-1, 2, 3 & 4
MACDONALD, C. E. Transportation Branch 79/04/26 3pp

DOCKET 71-5006 MODEL 80-40-020, ATOM-INC.

7905240205 Informs that operations & assets of Protective Packaging, Inc.
were transferred from Nuclear Engineering Co. to Teledyne
Energy Sys. in Jan. 1979. Requests applicable certificates of
compliance be changed to this effect.
MILLER, E. Teledyne, Inc. 79/04/06 1p

DOCKET 71-5450 MODEL HSC-1, -2, -3, WESTINGHOUSE ELECTRIC CORP.

7905240297 Withdrew proprietary portion of application for reviews of
Certificate of Compliance 5450; to include authorization of
BCC-4 type shipping package Halls being reclassified as
nonproprietary.
DIFENDEA, R. F. Westinghouse Electric Corp. 79/04/06 1p.

7905240291 Requests registration as user of Model 5450
DUMAS, C. R. Siquel Light Co. 79/04/10 1p.

DOCKET 71-5790 MODEL, AL-HO, ENERGY, DEPT OF

7905200691 Informs that Albuquerque Operations Div. 790130 ltr
responding to NRC 780101 request for add'l info for Models
AL-HO & AL-HO packages did not fully answer questions.
Requests advisement of further info within 30 days.
MACDONALD, C. E. Transportation Branch 79/03/30 1p

DOCKET 71-5790 MODEL, AL-HO, ENERGY, DEPT OF

7905200691 Informs that Albuquerque Operations Div. 790130 ltr
responding to NRC 780101 request for add'l info for Models
AL-HO & AL-HO packages did not fully answer questions.
Requests advisement of further info within 30 days.
MACDONALD, C. E. Transportation Branch 79/03/30 1p

DOCKET 71-5795 MODEL, HOME, ENERGY, DEPT OF

7905240252 Forwarded 790220 ltr requesting registration as user of ORNL
Foamless shipping container. Since this is DOE-approved
package DOE field etc. should be contacted.
MACDONALD, C. E. Transportation Branch 79/04/13 1p

7905240258 Requests authorization as shipper of ORNL Foamless Shipping
Container under same terms & conditions listed in
Certificate of Compliance 5795
NEEDHAM, W. P. Argonne National Laboratory 79/02/26 1p

DOCKET 71-5805 MODEL ATOM WARE CAGE, ATOM-INC.

7905200447 Requests add'l info to complete review of 790121 application
for amend to Model Vandenburgh packaging. Requests
delineation of changes made to Drawing 6999-2-07, Revision P.
MACDONALD, C. E. Transportation Branch 79/03/10 1p

DOCKET 71-5958 MODEL, DOT-04 TYPE B, MACDONALD & HULSHOF CO.

7905200490 Requests revised Certificate 5958 for 4M packaging
MOTT, H. E. Energy, Dept. of 79/04/20 1p

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO.

7905200527 Forwarded updated version of drawings of GE Model 100
shipping container due to incremental editorial changes
M12 drawings.
CONRADSON, E. E. General Electric Co. 79/04/09 3pp

DOCKET 71-5957 MODEL 2H-1, ENERGY, DEPT OF

7905050580 Notification of registration as user of Model 2H-1 in
response to 790223 request.
MACDONALD, C. E. Transportation Branch 79/04/20 1p

DOCKET 71-6058 MODEL 03-1, NUCLEAR ENGINEERING CO.

7905070047 Notifies that Model 03-1 packaging may not conform to design
approval in Certificate of Compliance 6058, Revision 3. Users
should confirm that packages were properly fabricated before
use.
MACDONALD, C. E. Transportation Branch 79/04/02 3pp

7905070000 Follows up 790312 ltr re review which disclosed that
shipping tank Model 03-1 lifting lugs have been fabricated
out of stainless steel rather than Co-In as specified in
Certificate of Compliance 6058
MORRIS, H. Union Carbide Corp. 79/03/22 1p

7905240409

Energy Sys.
complex
MILLER, H. E.

7905150281

Re: this
is found c
VITTHAL, H.

7905150136

Ref: 780101
Inc. Ship:
of case
BUREAU, R.
79/04/21

7905240219

shipping
MACDONALD

DOCKETED ITEMS

---170302002A Certificate of Compliance 4088, Revision 4, for radioactive mail shipping package Model 82-1
NACDNLALD.C.E Transportation Branch 79/04/27 Dpg

DOCKET 71-6244 MODEL 6144, NUCLEAR ENGINEERING CO

790304006B Informs that operations & assets of Protective Packaging, Inc. were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979. Requests applicable certificates of compliance be changed to this effect.
NALL.M.C. Teledyne, Inc 79/04/06 1p

790307007B Forwards Revision 3 of Certificate of Compliance 6144 for shipping package Model 6144
NACDNLALD.C.E Transportation Branch 79/04/23 Dpg

---790307008B Certificate of Compliance 6144, Revision 3, for radioactive mail shipping package Model 6144.
NACDNLALD.C.E Transportation Branch 79/04/23 Dpg

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

790308008B Notifies that info requested in 790316 ltr will be forwarded by 790320
NALL.M.C. Chem-Nuclear Systems, Inc 79/04/11 1p

790304012B Informs that Certificate of Compliance 6244 for shipping package Model 6244 expires 790830. Renewal must be requested.
NACDNLALD.C.E Transportation Branch 79/04/12 1p

790306004B Responds to 790412 notice of 790320 expiration of Certificate of Compliance 6244. Expresses to submit application for license renewal & amend by 790520
NALL.M.C. Chem-Nuclear Systems, Inc 79/04/20 1p

DOCKET 71-6272 MODEL POLY PANTHER, NUCLEAR ENGINEERING CO

790304002B Informs that operations & assets of Protective Packaging, Inc. were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979. Requests applicable certificates of compliance be changed to this effect.
NALL.M.C. Teledyne, Inc 79/04/06 1p

790307002B Forwards Revision 2 of Certificate of Compliance 6272 for shipping package Model Poly Panther
NACDNLALD.C.E Transportation Branch 79/04/23 Dpg

---790307007B Certificate of Compliance 6272, Revision 2, for radioactive mail shipping package Model Poly Panther
NACDNLALD.C.E Transportation Branch 79/04/23 Dpg

DOCKET 71-6272 MODEL: 40X, P. A. Y. ALLIRED-GENERAL, NUCLEAR SERVICES

790304002B Responds to 790108 ltr requesting review of "U Hazardous Waste Handling Procedures & Container Criteria," 790-001, Revision 4, dated Apr 1977. Unacceptable replacement for Revision 3, general notice deleted.
NACDNLALD.C.E Transportation Branch 79/04/26 1p

DOCKET 71-6344 MODEL: FW-1, GENERAL ATOMIC CO.

790305007B Forwards addl info supporting application for shipping cash design using alternate closure configuration. Derived analyses show impact limiter protects cash closure, ensuring radioactive waste will not be released to enviro.
HUNTER, M.H. General Atomic Co 1-sub. of Gulf Oil Corp 1 79/04/06 8pgs

DOCKET 71-6366 MODEL 6366/001, ENERGYS, DEPT. OF

790308004B Forwards Revision 4 of Certificate of Compliance 6366 for shipping package Model 6366/001.
NACDNLALD.C.E Transportation Branch 79/05/01 1p

---790308004B Certificate of Compliance 6366, Revision 4, for radioactive mail shipping package Model 6366/001.
NACDNLALD.C.E Transportation Branch 79/05/01 Dpg

DOCKET 71-6387 MODEL: 40, RAYTHEON MEMORIAL INSTITUTE

790305007B Forwards 790319 ltr from MED. requesting mode of NRC certificate of compliance to reflect new types & sizes of fuel pins.
FILLIPPOPOV, T.B. Energy, Dept of 79/04/05 8pg

DOCKET 71-6400 MODEL: SUPER TIGER, WESTINGHOUSE ELECTRIC CORP

790305004B Informs that info requested re amend to Certificate of Compliance 6400 will be submitted by 790420.
NACDNL.C.E Nuclear Fuel Services, Inc 1-sub. of Getty Oil Co 1 79/03/23 1p

790305012B Forwards request for exemption from 10CFR71.40(a) re shipping of waste mail in Model Super Tiger shipping container.
DIPALJAN, R.P. Westinghouse Electric Corp 79/04/03 1p

---790305012B "Info for Pu Waste Drum Shipments" re Westinghouse Electric Corp 79/04/03 7pgs

790304008B Informs that operations & assets of Protective Packaging, Inc. were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979. Requests applicable certificates of compliance be changed to this effect.
NALL.M.C. Teledyne, Inc 79/04/06 1p

790304003B Forwards Revision 3 of Certificate of Compliance 6400 for shipping package Model Super Tiger
NACDNLALD.C.E Transportation Branch 79/04/26 8pgs

---790305003B Certificate of Compliance 6400, Revision 3, for radioactive mail shipping package Model Super Tiger
NACDNLALD.C.E Transportation Branch 79/04/26 8pgs

DOCKET 71-6550 MODEL: PACIFIC TIGER, ENERGYS, DEPT. OF

790304012B Responds to 790108 ltr requesting review of "U Hazardous Waste Handling Procedures & Container Criteria," 790-001, Revision 4, dated Apr 1977. Unacceptable replacement for Revision 3, general notice deleted.
NACDNLALD.C.E Transportation Branch 79/04/26 1p

DOCKET 71-6679 MODEL: 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO

790304002B Informs that operations & assets of Protective Packaging, Inc. were transferred from Nuclear Engineering Co to Teledyne Energy Sys in Jan 1979. Requests applicable certificates of compliance be changed to this effect.
NALL.M.C. Teledyne, Inc 79/04/06 1p

790305005B Forwards Revision 2 of Certificate of Compliance 6679 for shipping package Model Half Super Tiger
NACDNLALD.C.E Transportation Branch 79/04/26 8pgs

---790305005B Certificate of Compliance 6679, Revision 2, for radioactive mail shipping package Model Half Super Tiger
NACDNLALD.C.E Transportation Branch 79/04/26 8pgs

DOCKET 71-6697 MODEL: 6650 PEG, GENERAL ELECTRIC CO.

790304007B Forwards Revision 4 of Certificate of Compliance 6697 for shipping package Model GE-6500
NACDNLALD.C.E Transportation Branch 79/04/06 8pgs

---790304007B Certificate of Compliance 6697, Revision 4, for radioactive mail shipping package Model GE-6500.
NACDNLALD.C.E Transportation Branch 79/05/03 8pgs

DOCKET 71-6670 MODEL: NPS-6, NUCLEAR FUEL SERVICES, INC

790305002B Reports deviation of NAC-1 cash from spec in certificate of compliance. Corrective action being taken.
NALL.M.C. J.D. Nuclear Services Corp. 79/04/06 8pgs

DOCKETED ITEMS

287

7905020174 Forwards order to show cause, effective immediately, which prohibits further use of Model NPB-4 package, requiring evaluation of deviations from design approval & requires further order of NRC to return packaging to nrc
DISCHAS-J Office of Nuclear Material Safety & Safeguards
79/04/06 2pp

7905020180 Order to show cause, effective immediately, prohibiting further use of Model NPB-4 package, requiring evaluation of deviations from design approval & requiring further order of NRC to return packaging to nrc
DISCHAS-J Office of Nuclear Material Safety & Safeguards
79/04/06 2pp

7905020468 Response to NRC 790406 ltr with no plans to use NPB-4 packaging to ship nuclear fuel in near future.
BAYNARD-P Florida Power Corp 79/04/16 1p

7905020414 Requests extension until 790515 to respond to 790406 order to show cause re Nuclear Assurance Corp cask Model NPB-4.
MCGARRY-J H Debevoise & Lieberman 79/04/20 1p

DOCKET 71-4744 MODEL POLY TIGER; NUCLEAR ENGINEERING CO

7905020605 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Telepho Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect
MALL-W C Telepho, Inc 79/04/26 1p

7905020609 Forwards Revision 2 of Certificate of Compliance 6764 for shipping package Model Poly Tiger
MCDONALD-C E Transportation Branch 79/04/24 2pp

DOCKET 71-6771 MODEL MN-1; NUCLEAR ENGINEERING CO

7905020408 Informs that operations & assets of Protective Packaging, Inc were transferred from Nuclear Engineering Co to Telepho Energy Sys in Jan 1979 Requests applicable certificates of compliance be changed to this effect
MALL-W C Telepho, Inc 79/04/26 1p

7905020290 Forwards Revision 2 of Certificate of Compliance 6771 for shipping package Model MN-1
MCDONALD-C E Transportation Branch 79/04/24 2pp

7905020299 Certificate of Compliance 6771, Revision 2, for radioactive mail shipping package Model MN-1
MCDONALD-C E Transportation Branch 79/04/24 2pp

DOCKET 71-6009 MODEL FL 10-1; GENERAL ELECTRIC CO

7905020910 Requests amend to Certificate of Compliance 9009, Revision 2 re Model FL 10-1 shipping package Diagram of container arrangement and
SUNSHINEMAN-G E General Electric Co Nuclear Energy Products Div
79/04/16 4pp

7905020041 Forwards Revision 2 of Certificate of Compliance 9009 for shipping package Model FL 10-1
MCDONALD-C E Transportation Branch 79/05/04 2pp

7905020044 Certificate of Compliance 9009, Revision 2, for radioactive mail shipping package Model FL 10-1
MCDONALD-C E Transportation Branch 79/05/04 4pp

DOCKET 71-6010 MODEL MLI-1/2; M. INDUSTRIES, INC.

7905020571 Requests registration of listed parties as users of Model MLI-1/2 re: Users have Revision 1 of certificates of compliance Request Forwarding of future revisions
RDSB-D H Energy Dept of 79/05/01 1p

7905020575 Notification of registration as user of Model MLI-1/2 package MLI-1 in reference to license 790502 request
MCDONALD-C E Transportation Branch 79/05/02 1p

DOCKET 71-6022 MODEL MLI-1/2/4; M. INDUSTRIES, INC.

7905020501 Informs that license will provide requested info re 790413
MILLIAMS-C E M. Industries, Inc Nuclear Div 79/04/28 1p

DOCKET 71-6022 MODEL MLI-1/2/4; TECHNICAL OPERATIONS, INC.

7905020088 Requests revision to Certificate of Compliance 9003, Revision 2 to include correct address for American Airlines
AMERICAN-C H American Airlines, Inc 79/04/04 1p

DOCKET 71-6044 MODEL GE-1485; GENERAL ELECTRIC CO

7905020074 Requests registration as user of Model GE-1485 radioactive mail shipping package
OEDJA-J F Northeast Utilities 79/04/27 1p

DOCKET 71-9079 MODEL NN-55; ENERGY DEPT OF

7905020424 Notification of registration as user of Model NN-55 in response to license 790502 request
MCDONALD-C E Transportation Branch 79/05/04 1p

DOCKET 71-9079 MODEL NN-100 SERIES 2; HITMAN NUCLEAR & DEVELOPMENT

7905020074 Responds to 790518 ltr re driver checklists submitted w/ BAE for various radioactive packages Unless checklists are specifically required by certificate of compliance, users may develop their own procedures
MCDONALD-C E Transportation Branch 79/04/13 1p

DOCKET 71-9080 MODEL NN-100; HITMAN NUCLEAR & DEVELOPMENT CORP

7905020074 Responds to 790518 ltr re driver checklists submitted w/ BAE for various radioactive packages Unless checklists are specifically required by certificate of compliance, users may develop their own procedures
MCDONALD-C E Transportation Branch 79/04/13 1p

DOCKET 71-9080 MODEL NN-100 SERIES 2; HITMAN NUCLEAR & DEVELOPMENT

7905020074 Responds to 790518 ltr re driver checklists submitted w/ BAE for various radioactive packages Unless checklists are specifically required by certificate of compliance, users may develop their own procedures
MCDONALD-C E Transportation Branch 79/04/13 1p

DOCKET 71-9080 MODEL NN-100 3; HITMAN NUCLEAR & DEVELOPMENT CORP.

7905020074 Responds to 790518 ltr re driver checklists submitted w/ BAE for various radioactive packages Unless checklists are specifically required by certificate of compliance, users may develop their own procedures
MCDONALD-C E Transportation Branch 79/04/13 1p

DOCKET 71-9090 MODEL M800; ALLIED CHEMICAL CORP.

7905020128 Responds to 781108 ltr requesting review of "U Handling Procedures & Container Criteria" (NRC-88) Revision 4, 24 Apr 1977. Unacceptable replacement for Revision 3; general notes deleted
MCDONALD-C E Transportation Branch 79/04/24 1p

DOCKET 71-9091 MODEL DC A; GENERAL ELECTRIC CO.

7905020128 Responds to 781108 ltr requesting review of "U Handling Procedures & Container Criteria" (NRC-88) Revision 4, 24 Apr 1977. Unacceptable replacement for Revision 3; general notes deleted
MCDONALD-C E Transportation Branch 79/04/24 1p

DOCKETED ITEMS

DOCKET 71-9070 MODEL 1H-300. HERTHAN NUCLEAR & DEVELOPMENT CORP

7705100079 Responds to 7702312 ltr re driver checklist submitted w/ data for various radioactive packages. Unless checklist are specifically required by certificate of compliance, users may develop their own procedures.
NACDORMLD.C E Transportation Branch 79/04/13 1p

DOCKET 71-9093 MODEL 1H-300. HERTHAN NUCLEAR & DEVELOPMENT CORP

7705100079 Responds to 7702312 ltr re driver checklist submitted w/ data for various radioactive packages. Unless checklist are specifically required by certificate of compliance, users may develop their own procedures.
NACDORMLD.C E Transportation Branch 79/04/13 1p

DOCKET 71-9114 MODEL CHA-808. NUCLEAR PACKAGING, INC

7705040497 Requests info re status of application for certificate of compliance authorizing shipment of nuclear mail in RA-Pac CHA-808 shielded cask.
HARRELL J Nuclear Packaging, Inc 79/04/06 1p

DOCKET 71-9130 MODEL TH-12. TRANSNUCLEAR CORP

7705150788 Withdraws method proposed in 770131 ltr to demonstrate fracture toughness of TH-12 containment vessel steel.
SOLISMAN, R. Transnuclear, Inc 79/04/06 3pp

7705050666 Forwards Revision 5 to RAR of TH-12 packaging in response to 770507 request for addl info.
HARRELL J, Transnuclear, Inc 79/04/30 500pp

DOCKET 71-9132 MODEL T-3. NUCLEAR PACKAGING, INC

7705100786 Notifies that licensee will respond to 770305 request for addl info re T-3 shipping cask by 770605.
BENJAMIN, J D Nuclear Packaging, Inc 79/04/05 1p

DOCKET 71-9104 MODEL H087684-2. ENERGY, DEPT OF

7705080108 Forwards drawings for shipping container Model H086, as requested in 770302 memo.
BLANCHET, R K Rossmore Co 79/03/27 10pp

7705040509 Requests addl info re Model H0 27684-2 package. All-purpose Operations Ctr. 770302 response not sufficient. Requests 30-day notification if info will be provided.
NACDORMLD.C E Transportation Branch 79/04/27 1p

DOCKET 71-9105 MODEL 82W624H. ENERGY, DEPT OF

7705020264 Forwards response to NRC 781225 concerning re SAR for shipment of 82W624H spent core cartridge shipping container.
BENJAMIN, R E Energy, Dept of 79/04/05 10pp

DOCKET 71-9102 MODEL DT-14. ENERGY, DEPT OF

7705020110 in ref to 770302 ltr requests addl info for review of Model DT-14 shipping package.
HACORNALB.C E Transportation Branch 79/04/06 2pp

NONDOCKETED ITEMS

- 7904300020 Inform of review of all category A, S, C & D generic technical activities & procedures according to 10 CFR 43. Requests comments on DFC of Nuclear Regulatory Research Reg. & 43.45 Commission paper by 781012.
- DECONNO, R. C. Division of Site Safety & Environmental Analysis. 78/02/27. 2pp.
- 7904300024 Forwarded Report 7 on status of generic items re LWRs in effort to simplify referencing, numbering sys for generic items has been revised.
- CARROLL, H. W. ACRS - Advisory Committee on Reactor Safeguards. 79/02/21. 2pp.
- 7904300091 Research Info Ltr 48 discusses effectiveness of cable tray sealing mats & barriers in retarding combustion of cable trays subjected to exposure fires & in preventing propagation between cable trays.
- LEDSHAW, R. Division of Reactor Safety Research. 79/02/04. 11pp.
- 7904300093 Response to 790906 memo re NRC/NRC interface on input from different branches. Environ. Projects/Operations, Meteorology/Hydrology & Accident Analysis.
- DECONNO, R. C. Division of Site Safety & Environmental Analysis. 79/02/06. 2pp.
- 7904300171 Response to request for comments on W-111 Tailings Radiation Act of 1978 NRC has regulatory jurisdiction over mill tailings until D-11100 & should conduct specific mill tailings licensing proceedings.
- SCHEFFNER, M. O. Fried, Frank, Harris, Shriver & Kampelman. 79/03/09. 2pp.
- 7904300171 Forwarded report of Review Group for EPA, "Risk Assessment of Radioactive Waste Isolation in Deep Geologic Formations".
- ROBERTS, I. C. Assistant Director for Siting Standards. DOLAN, P. W. Probabilistic Analysis Branch. 79/03/16. 2pp.
- 7904300175 "Risk Assessment of Radioactive Waste Isolation in Deep Geologic Formations" from 781004-08 meeting of Review Group for EPA.
- A. Assistant Director for Siting Standards. 79/12/08. 23pp.
- 7904300179 Response to 781129 memo re status of AD Little vents & EPA planned use in developing radioactive waste site. Steps are in draft stages & will be used as partial support for waste site.
- MARTIN, J. E. Environmental Protection Agency. 79/11/30. 1p.
- 7904300211 Summary of 781111 meeting w/NRC DA Review Team re plans to review DA practices.
- RENNETT, G. L. Research Support Branch. 79/04/12. 2pp.
- 7904300261 Summary of 790406 meeting w/Research Review Group re future course of Project "Health/Science Studies of Sociotechnical Aspects of Nuclear Power Plant Siting."
- PODMARIN, C. Environmental Effects Research Branch. 79/04/06. 2pp.
- 7904300269 Response to 790204 Ltr re perimeter fence requirements. Forwarded portion of "Barrier Technology Handbook" which discusses perimeter fence.
- PHILLIPS, A. Safeguards Standards Branch. 79/03/19. 2pp.
- 7904300270 Response to 790228 Ltr re perimeter fence requirements. Inquiry has been forwarded to NRC headquarters.
- SHAW, J. R. Region 3, Philadelphia. Office of the Director. 79/02/28. 1p.
- 7904300274 Response info re regulations & standards re fence design for nuclear plants.
- SCOTT, S. Seriatly Consolidated, Inc. 79/03/24. 1p.
- 7904300289 Forwarded product presentation info for iron oxide mortar to be used as fail-safe passive heat sink for reactors, if each plant can contain worst possible accident, antineutronics forces will be rendered ineffective.
- MILLER, C. Chabrier Corp. 79/04/12. 2pp.
- 7904300292 Ask receipt of 790605 Ltr concerning reduction of probability of extended reactor outages by using high thermal reactivity concrete. NRC cannot conduct use of product, these conditions would be effort.
- HEINEMANN, S. E. Division of System Safety. 79/06/01. 1p.
- 7904300299 "Assured Above & Below Ground Containment of a Class V Accident in a Nuclear Power Reactor."
- MILLER, C. Chabrier Corp. 79/03/20. 2pp.
- 7904300312 Certificate of disposition of waste under License 20-0308-01. Waste transferred to Tracerlab, Inc.
- WELSH, M. H. Metals & Controls Corp. 79/04/01. 2pp.
- 7904300320 Waste under License 20-0308-2 have been transferred to Kiewit-Whitcomb Co.
- BUFFET, A. Metals & Controls Corp. 42/03/20. 1p.
- 7904300331 Application for amendment of Metal/Byproduct License 20-0308-1 authorizing En-50 to be used in beta gauge.
- WELSH, M. H. Metals & Controls Corp. 24251. 41/04/27. 2pp.
- 7904300332 Certificate of disposition of waste under License 20-0308-03 disposing of En-50 by burial at Nuclear Engineering site in Massachusetts on 77002.
- JOLAN, S. S. Tapes Instruments, Inc. 3101. 77/06/22. 1p.
- 7904300341 Certificate of disposition of waste under License 20-0308-03 by transfer of En-60 to Tracerlab, Inc.
- WELSH, M. H. Metals & Controls Corp. 24251. 72/08/28. 1p.
- 7904300342 Metal/Byproduct License 20-0308-3 for Metals & Controls, Inc. is amended per 430020 application authorizing any byproduct metal, En-60 & En-60 to be used for repair & add of essential reactor components & film cell.
- HEINEMANN, S. E. Atomic Energy Commission (Per 7978). 45/09/16. 2pp.
- 7904300354 Certificate of disposition of waste under License 20-0308-03 by transfer of En-60 to Tracerlab, Inc.
- WELSH, M. H. Metals & Controls Corp. 24251. 72/08/28. 1p.
- 7904300355 Emphasizes importance of need for free & open communications between all organizations/levels in course of managing NRC.
- ROBERTS, I. C. Assistant Director for Siting Standards. 79/03/04. 1p.
- 7904300356 Notification of personnel change in Power Reactor Licensing Div. as of 790518.
- WELSH, M. H. General Atomic Co. (subs. of Gulf Oil Corp.). 79/04/25. 1p.
- 7905010002 Approval of initial FOIA decision to deny request for Section 4 & C of contract between Dow Chemical Co. & Consumers Power Co.
- PREKINS, S. Public Interest Research Group. 79/03/18. 2pp.
- 7905010001 Response to appeal of denial of FOIA request for Section 4 & C of 790401 general agreement contract between Dow Chemical Co. & Consumers Power Co. Requested info remains exempt from public disclosure.
- WELSH, M. H. General Atomic Co. Office of the Executive Director for Operations. 79/04/25. 2pp.
- 7905010473 Forwarded responses to NRC 790227 request for addl info re logical report AT-1000A test 790227.
- SPONSTEIN, M. ATOM. SC 2475. 79/04/24. 2pp.
- 7905010506 Request Executive Branch position re Edlow Intl Co application for license to export special nuclear fuel to Argentina.
- WELSH, M. H. General Atomic Co. Office of the Executive Director for Operations. 79/04/12. 1p.
- 7905010560 In response to request for addl info re GE Core spray distribution program, forward "Protect Prediction for Reactor Steam Test Facility Core Spray Test."
- LEVINE, A. J. General Electric Co. Nuclear Energy Products Div. 79/04/12. 1p.
- 7905010561 "Protect Prediction for Reactor Steam Test Facility Core Spray Test."
- LEVINE, A. J. General Electric Co. Nuclear Energy Products Div. 79/04/12. 2pp.
- 7905010568 FOIA request for info re Govt contracts on low level radioactive waste shipment of contractor, contract number, beginning & completion dates & brief description of packages.
- LOHMEYER, T. NRC Corp. 24251. 79/03/22. 1p.
- 7905010602 Response to FOIA request for info re Govt contracts on low level radioactive waste shipment of contractor, contract number, beginning & completion dates, & brief description of packages.
- LOHMEYER, T. NRC Corp. 24251. 79/03/22. 1p.
- 7905010634 FOIA request for info justifying previous failure to use known to find facilities, preventing release of radioactivity into atmosphere.
- SCOTT, J. H. Affiliation Unknown. 79/03/31. 1p.

7903010437 Response to FOIA request for records re non-use of boric acid in fluid reactor core. Forwarded to Division 79-03A & discussed. Reactor System Incident, M/R encl. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903010440 Response to FOIA request for transcripts of closed NRC meetings re W-101 from 790303-790405. Transcripts for 790303-0405 meetings are available in PDR. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020304 "Heavy-Section Steel Technology Program": quarterly progress report for Oct-Dec 1978. MULTIMEDIA D. Oak Ridge National Laboratory. PIN A-6119. ORNL/NSRDS/TH-2 7/10/24 20p.

7903020302 NUREG/OR-0380 "Detector of Defective PWR Fuel Rods During Power Ramp & Fuel Shuffling Operations". ORNL/NSRDS/TH-2 7/10/24 20p.

7903020307 FOIA request for info re test scores for licensing C Faust & E Frederick as reactor operators & N. Gryn & D. Smith as senior operators. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020308 Forwarded per Public Law 95-601 "Means for Improving State Participation in Licensing & Development of Federal Nuclear Waste Facilities." NUREG-0339. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020303 NUREG-0339 "Means for Improving State Participation in Licensing & Development of Federal Nuclear Waste Facilities." * Office of State Programs. 7/10/24 3p.

7903020302 Response to FOIA request for info re test scores for licensing C Faust & E Frederick as reactor operators & N. Gryn & D. Smith as senior operators. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020305 FOIA request for winning proposal re evaluation of reactor radiation streaming to be provided as requested 7/10/24 2p.

7903020309 Response to FOIA request for winning proposal for RFP 79-030-70-100 Forwarded relevant correspondence considered acceptable for public disclosure. M/R encl. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020300 FOIA request for outline of NRC structural organization, nature of administration's existence, basic health & safeguard role & important areas of past & present. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020306 Response to FOIA request for various info re NRC organization & activities. Forwarded appropriate documents including organization chart, 1978 Annual Report & other NRC insurance. Discussed the types of NRC with M/R encl. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020309 Response to FOIA request for final report on W-101 BL-1 prototype reactor accident resulting in death of three naval personnel at Nati Reactor Testing Station. Idaho Falls: 10. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020304 Response to FOIA request for final report on W-101 BL-1 reactor accident at Nati Reactor Testing Station. Forwarded press announcement & final investigation report. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020301 Forwarded final report on BL-1 accident occurring at Nati Reactor Testing Station re BL-102. Reactor main cavity was sealed without loss of central control rod blades from core beyond specified limits. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020306 License for Nibit & Co. Inc. to export 25,000 pounds of Zircaloy-4 tube shells to Japan. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020302 Proposed Revision 4 to Reg Guide 3.8 "Info Relevant to Licensing of Occupational Radiation Exposure at Nuclear Power Stations Will Be As Low As Reasonably Achievable." * Office of Standards Development. 7/10/24 3p.

7903020301 "Investigation of Post-Critical Heat Flux Transfer for Water-Cooled Reactor Application & Development of Two Phase Flow Instrumentation." progress report Oct-Dec 1978. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020304 "Grease Refill Effects Program." Grease Project 243-10 progress report for 1978. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020302 Agency of ACRS 790302 meeting to discuss FFEP project & ACRS - Advisory Committee on Reactor Safeguards. 7/10/24 3p.

7903020304 Application for extension of time to respond to interviewers' NRC comments as Statistician's Certificate of Efficacy. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020307 Notification of contract execution "Ege Maint Programming." awarded to Shell Business Administration. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020302 Contract for "Ege Maint Programming" awarded to Shell Business Administration. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020302 Request for License 87-0429 to extend expiration from 7/10/24 to 8/10/24. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020307 Request for License 87-0429 to modify intermediate response M/R encl. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020308 Discussed LOCA evaluation model, lethality rule approximation justification is appropriate & effect of high heat transfer re calculated peak clad heat will result in reduction by several hundred degrees. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020304 In response to NRC 790404 meeting w/BBM & 177 fuel assembly plant owners. BBM agreed to describe scope & status of all analytical work requested info should be provided by 7/10/24. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020304 License for Westinghouse to export 92 IR tubes & accessories specially designed or prepared parts & components for use in reactors to Italy. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020305 License for Nibit & Co. Inc. to export 77,000 lb of Zircaloy-4 tube shells to Japan. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020306 License for Nibit & Co. Inc. to export 25,000 pounds of Zircaloy-4 tube shells to Japan. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020306 License for Nibit & Co. Inc. to export 25,000 pounds of Zircaloy-4 tube shells to Japan. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020306 License for Nibit & Co. Inc. to export 25,000 pounds of Zircaloy-4 tube shells to Japan. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020306 License for Nibit & Co. Inc. to export 25,000 pounds of Zircaloy-4 tube shells to Japan. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

7903020309 License for Westinghouse Electric Corp. to export fuel tubes, fuel rod springs, and spacers (top & bottom) to Sweden. 7/10/24 J.M. Division of Rules and Records 7/10/24 3p.

NONDOCKETED ITEMS

283

790340247 Comments on proposed rule 10CFR11 & 20 adequate basis does not exist for calling hearing on occupational dose limiting dose. Studies referred to have all been regulated & proposed exposure limits too low
LIMBIS, L. Edison Electric Institute. 79/04/16 2pp

790340250 Comments on proposed rule 10CFR50 suggest some proposed regulations which permit creation of liability in meeting public health & safety state TME-2 process need for more regulation
JOHNS, H.A. Affiliation Unknown. 79/04/09. 1p

790340261 Comments on proposed rule 10CFR50 urges Commission not adopt proposed rule. Reexamination of any relaxation of requirements re nuclear power safety mechanisms should be completed TME-2 indicates need for more study
JOHNS, H.A. Affiliation Unknown. 79/04/02

790340265 Comments on proposed rule 10CFR20 supports revocation of 10CFR20.204
ANDERSON, W.L. West Virginia. State of. 79/04/13 1p.

790340274 Comments on proposed rule 10CFR30.790328 notice use automatically requires streamlining of licensing procedure
Request to amend App 5 is good as it will protect vessel integrity. Changes change to App 5.
ANDERSON, J.C. Affiliation Unknown. 79/04/16. 1p.

790340283 Comments on proposed rule 10CFR20 encourages proposed changes. Any disposal of radioactive should be licensed
Affiliation Unknown. 79/04/15 1p

790340274 Comments on proposed rule 10CFR20, calendar quarter should be defined as a quarter to avoid use of different date info
resolving periods
STALLION, S.L. Washington Public Power Supply System. 79/04/06 1p

790340305 Comments on proposed rule 10CFR10 & 20 suggests wording be clarified & replacement of word "dose" w/ "occupational dose" wherever it occurs.
STALLION, S.L. Virginia Electric & Power Co. 79/04/06 5pp

790340313 Comments on proposed rules 10CFR11 & 20, some airlines use radioteletype for load of aircraft & equipment ATA
member airlines support proposal. Comments from American Airlines & Air Canada encl.
WIDRIG, E.L. Air Transport Association. 79/04/17 4pp

790340314 Comments on proposed rules re new way of recordkeeping using magnetic tape along w/ transcription of individual interviews w/ NRC employees. believes program may contradict
Student Career's wish to reduce cost costs
COOPER, M.J. Affiliation Unknown. 79/03/04. 1p.

790340342 Ltr of assurance certifying mail mentioned in application for license to export 140.2 mg U containing 320.1 mg U-235
& transfer of this mail is subj to all terms & conditions of 60025 addl agreement for cooperation.
GOFTEL, W. Euratom Supply Agency (Belgium). 79/03/08. 1p.

790340358 Notification of 790425 meeting w/GE in Bethesda, MD to discuss two new test apparatus & model development.
GODDARD, M.H. Analysis Branch. 79/04/20. 1p

790340394 Responses to NRC 790308 Questions re Mount Taylor U Mill Project. Unreviewed drawing
Gulf Oil Corp., Gulf Mineral Resources Co. 79/04/12. 40pp

790340410 Urges issuance of license for GE to export neutron detectors containing U to India to replace failed detectors which might endanger Varadur reactor safety
WILSON, D.S. General Electric Co. 79/04/03. 1p.

790340411 Comments on proposed Reg Guide 3.3. Reg guide should conform to procedural provisions established by CED for NEPA. Portion of proposed rule should contain description of mining activities.
HEISLOPP, L.W. Rocky Mountain Energy Co. 79/04/14 4pp

790340471 Comments on proposed rulemaking 10CFR20-13: certification by American Board of Health Physics is preferable to NRC certification plan.
DULEY, J.W. Affiliation Unknown. 79/04/12. 3pp.

790340481 Comments on proposed rulemaking 10CFR20-13 endorses presentation & notes address of Natl Society of Radiation Protection Technologists.
BARTON, M.P. Affiliation Unknown. 79/04/09 2pp

790340501 Forwards "Probable Max Flood from Canon de Maricao Watershed for Realigning U Tailings Impoundment Drainage Diversion Sys.
Maricao-NM - Miscellaneous appraisals
TOPP, A. New Mexico. State of. 79/03/30 4pp

790340503 "Probable Max Flood from Canon de Maricao Watershed Re-Designing U Tailings Impoundment Drainage Diversion Sys.
Maricao-NM. Rehabilitation Corp.
STOKES, D. S. L.L.B. N. Colorado State Univ. 79/03/30 34pp

790340522 Requests POME supply Northern CA Power Authority witnesses of all persons until done to have been members of "control group" for periods from which documents claimed as privileged have arisen
ADAMSON, J.H. Briggs & McNameis. 2 79/04/04 2pp

790340532 Comments on proposed rulemaking 10CFR20-13 opposes petition & believes public certification program sufficient
KARPER, D.C. Affiliation Unknown. 79/04/10 1p

790340542 Comments on proposed rulemaking 10CFR20-13 Forest certification of health physicist university
SCHAFER, S.H. Iowa-Ilinois Sea & Electric. 79/04/02 2pp

790340547 Comments on proposed rulemaking 10CFR20-6 strongly supports regulation that licensing proceedings should be conducted in timely manner
CASEN, V.J. Power Authority State of New York. 79/04/06 3pp

790340548 Comments on proposed rulemaking 10CFR20-7 opposes petition due to potential for abuse & delays in licensing process
Lohm, Lincoln & Beale. 79/04/05 3pp

790340552 Comments on proposed rulemaking 10CFR20-7 rejects proposal & suggests some rigid rules & requirements to prevent unnecessary information
Affiliation Unknown. 79/04/05 3pp

790340548 Comments on proposed rulemaking 10CFR20-13 opposes petition because objections are currently being achieved under existing regulations. No evidence of need for further regulation
JENSEN, H. Detroit Edison Co. 79/04/08 2pp

790340549 Forwards Initial evaluation of Oiv of Operating Reactors' fire protection needs for NRC
HALL, S.E. Brookhaven National Laboratory. 79/04/30 4pp

790340550 Forwards proprietary rept 500-9085P, Revision A: "Reactor Production Sys"
TALBOT, J.H. Babcock & Wilcox Co. 79/04/12 2pp

790340564 Informs that add info re ATRM mitigating capability of plants which use C-6 AESR will be submitted after 790501
BOWEN, A.E. C-6 Power Systems. LB-79-026 79/05/01 1p

790340565 Forwards Revision 3A to GA program rept MU-5A-1
CONRICK, W.O. Northeast Utilities. 50-2187 79/04/23 1p

790340569 Accepts Revision 3A to GA Typical Rept MU-5A-1
HAGGARD, P. Quality Assurance Branch. 79/03/13 2pp

790340569 Typical rept evaluation of GA program Rept MU-5A-1 Rept results will be compile w/ response of GA to 10CFR50
Quality Assurance Branch. 79/03/09 1p

790340566 MU-5A-1
GA program rept. Revision 3A
Northeast Utilities. 79/03/04. 7pp

790340569 FOIA request for NRC rept & recommendations on petition for rulemaking filed by PDR
DICKSON, N.S. California. State of. 79/03/08 1p

790340569 Response to FOIA request for NRC rept & recommendations on petition for rulemaking filed by PDR. Forwards relevant info.
FELTON, J.H. Division of Rules and Records. 79/03/01 1p

790340569 BOWEN-79-026
Attempts to obtain NRC approval of response to PDR petition for rulemaking
HIMMEL, S.B. Office of Standards Development. 78/12/14 4pp

NONDOCKETED ITEMS

256

- 7905000210 Comments on proposed Reg Guide 1.144 frequency of activity should be established based upon type of activity, experience & other relevant factors. AMEC 148 2 10-1977 provides such guidance. LDB/J. American Society of Mechanical Engineers 79/03/23. Dpp
- 7905000243 Forwards "Operating Procedure Guidelines for Small Breaks - Background info that will be used as training aid for operators." TAYLOR, J.H. Babcock & Wilcox Co. 79/03/05. Spp
- 7905000244 Forwards 790426 documents re BWR transient & accident analysis methods. MATTHEW, R. J. Division of Systems Safety. 79/04/26. Ip
- 7905000270 Forwards background info re BWR operating plant response to transients/unpredicted equipment malfunctions. BSM will submit detailed analyses per schedule to be decided at 790426 meeting w/MRC. RZE, D.H. Babcock & Wilcox Co. 79/04/26. A4pp
- 7905000292 Forwards results of LOFT Test LB-3 in response to MRC 790117 ltr. OMBLEY, G.P. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 79/04/30. Spp
- 7905000405 Forwards hardcopy from 790208 advisor review & subsequent progress review meetings on 2088 safety-related operator action study. Hardcopy includes preliminary results re operator time margin. PARKER, U.S. Research Support Branch. 79/04/10. Spp
- 7905000440 Forwards "Test Results For Solenoid Valve Performance Test." Final report-HSC-2388, per F. Clemons request. SCHAEFER, D. General Electric Co. NRC 110-79. 79/05/01. Ip
- 7905000442 HSC-2388 "Test Results For Solenoid Valve Performance Test." final report. General Electric Co. 79/04/30. Spp
- 7905000494 Lists all MRC contracts & copies of 1978-79 re low level radioactive waste. Commission 79/04/25. Spp
- 7905000510 FISA request for 1978 diary, calendar & telephone log of Commissioner GILKIN. Affiliation Unknown. 79/04/02. Ip
- 7905000512 Response to FISA request for 1978 diary, calendar & telephone log of Commissioner GILKIN. Commissioner does not maintain telephone log or diary. Calendar is being placed in FIO. FELTON, J.H. Division of Rules and Records. 79/05/05. Ip
- 7905000514 Notice of 790315 meeting w/ACRS Subcommittee on Port Of Main Nuclear Power Station; utility & MRC staff at Longmont, CO to review operating experience, reviewing operations & proposed aids for facility. MOYLE, J.C. ACRS - Advisory Committee on Reactor Safeguards. 79/05/26. Spp
- 7905000516 Notice of proposed meetings from 790323-790312 of ACRS subcommittees & working groups. MOYLE, J.C. ACRS - Advisory Committee on Reactor Safeguards. 79/05/26. Spp
- 7905000523 Notice of proposed meetings from 790323-790319 of ACRS subcommittees & working groups meetings from 790323-0319. MOYLE, J.C. ACRS - Advisory Committee on Reactor Safeguards. 79/05/26. Spp
- 7905000525 FISA request for info re cost of proposed nuclear power plants before year 2000, specific locations, siting areas & MRC status of each plant. SCHAEFER, D. Affiliation Unknown. 79/04/14. Spp
- 7905000528 Revised notice of 790405-07 meeting of ACRS & MRC in Washington, DC to discuss basis for shutting down five nuclear plants to resolve piping questions, revision other changes in meeting schedule. MOYLE, J.C. ACRS - Advisory Committee on Reactor Safeguards. 79/05/26. Spp
- 7905000532 Response to FISA request for info re proposed cost of nuclear power plants to be built by year 2000 & info concerning presently operating plants. Forwards site map. FELTON, J.H. Division of Rules and Records. 79/04/27. Ip
- 7905000531 "PA 37 Pipe Systems Study". CLARK, H.L. General Electric Co. NRC-04-75-002. 79/03/09. A4pp
- 7905000532 FISA request for outline of MRC structural organization, nature of administration's assistance, basic basis & safeguards aids & "important" cases. Lists documents available from MRC. COMLEY, R. Affiliation Unknown. 79/03/18. Ip
- 7905000538 Response to FISA request for records re MRC organization health & safeguards aids & "important" cases. Lists documents available from MRC. FELTON, J.H. Division of Rules and Records. 79/04/28. Spp
- 7905000548 HSC-0335 "Cost & Funding of State & Local Govt Radiological Emergency Response Plans & Preparedness in Support of Commercial Nuclear Power Stations". SLOAN, R. Office of State Programs. 79/03/26. S3pp
- 7905000549 Transcript of 790328 public meeting in Washington, DC re continuation of discussion of HSC-79-264. Final report "Registration of Federal Radioactive Waste Activities." by L. B. MCGRAW-79-002 and J. H. MCGRAW, V. J. MCGRAW, R. T. Commission. 79/03/29. S3pp
- 7905000557 HSC-79-0346 Provides followup to MRC requirements re initial briefing on HSC-79-264. Draft report, "Registration of Federal Radioactive Waste Activities." IDENTICAL. Office of Nuclear Reactor Regulation. 79/03/26. Dpp
- 7905000558 Response to request for info re M. Peoples 790221 ltr protesting 10CFR71. App & because the packaging requirements are unjustified. Requirements apply generally to shippers of fissile and fissionable materials. CORNELL, E. K. Office of the Executive Director for Operations. 79/04/02. A4pp
- 7905000561 Minutes & copy of 791207-09 224th ACRS meeting in Washington, DC re MRC safety research program (HSC-0346). ACRS resolution & combination of dynamic loads in nuclear facilities during earthquake. Advisory Committee on Reactor Safeguards 79/12/09. S3pp
- 7905000562 "Application of Internal Pipeline Nondestructive Evaluation Techniques for Detecting Insipient Cracking at Pipe Joints & Pipes in BWR Piping" Progress Report 9. WAGNER, L. B. Gas Research Association, Inc. MRC-04-79-242 79/04/09. S3pp
- 7905000568 Forwards generic letter to all BWR licensees re relief & safety relief valves which are installed in reactor coolant systems for automatic depressurization systems. CLEMONS, F. Plant Systems Branch. 79/04/09. Ip
- 7905000571 Concludes that implementation of requirement for increased surveillance testing is not most effective way of assuring safety relief valve reliability. Requests answers to questions re target rack safety relief valves. GILKIN, R. Assistant Director for Engineering & Projects. 79/04/05. A4pp
- 7905000573 Comments on proposed Reg Guide 2.8. Revision presents DOE case for EIR should be reviewed changes in EIR process. WOLFE, T. New Mexico State of. 79/03/16. Spp
- 7905000582 Notification of ACRS Subcommittee on Waste High 790418-19 meeting w/MRC to discuss reclassification. GILKIN, R. J. Spp
- 7905000594 790418-20 790418 10 GILKIN, R. J. Spp
- 7905000597 Instructions. R. GILKIN
- 7905000599 for NRC attorneys. THOMPSON
- 7905000602 Plans. S. OFI

NONDOCKETED ITEMS

- 7905000234 Preliminary value/impact assessment supporting draft reg guide "Lightning Protection for Nuclear Power Plants" - Proposed Alternate Regulatory Position" and a Office of Standards Development. 79/12/12 1p.
- 7905000241 Comments on proposed Reg Guide 3.8: Revision 4 notes editorial mistakes on certain footnotes. NRCES, R. S. American Nuclear Society. 79/04/12 1p.
- 7905000242 Comments on proposed Reg Guide 3.8: believes NRC should address only radiation safety & not general safety. No need for detailed corporate organization rules in application if general competence is described. YELDERMAN, J. C. US Steel Corp. 79/03/19 2pp.
- 7905000243 Notice of 790329 meeting of ACRS Subcommittee on Palo Verde Nuclear Generating Station, Units 4 & 5, its consultants & NRC staff in Washington, DC to review contract application. HEDLEY, J. C. ACRS - Advisory Committee on Reactor Safeguards. 79/03/08 2pp.
- 7905000247 Notice of date change of meeting of ACRS Subcommittee on Evaluation of LWRs in Washington, DC from 790322-24 to 790322-24.
- 7905000248 ACRS - Advisory Committee on Reactor Safeguards. 79/03/09 1p.
- 7905000249 Forwards Revision 1 to HPL-TDR-1A. "Operational QA Manual," per NRC 790211 Instructions. HEDLEY, J. C. Mississippi Power & Light Co. ACRS/79-26. 79/05/05 1p.
- 7905000251 "Operational QA Manual" - STANLEY, N. L. Mississippi Power & Light Co. 79/05/03 18pp.
- 7905000252 Notice of 790403 meeting of ACRS Subcommittee on Combination of Dynamic Loads, its consultants & NRC in Washington, DC to review technical basis of order to shut down five plants with load-related violating nonconformities. HEDLEY, J. C. ACRS - Advisory Committee on Reactor Safeguards. 79/03/10 2pp.
- 7905000253 Notice of 790323-24 meeting of ACRS Subcommittee on Evaluation of LWRs, its consultants & NRC staff in Washington, DC to review LWRs of 1978-79. HEDLEY, J. C. ACRS - Advisory Committee on Reactor Safeguards. 79/03/01 2pp.
- 7905000254 Forwards review of updated NRC-6491, "Fuel Rod Bowing." Acceptable basis has been provided for calculating critical heat flux on bowed rods. STREBL, J. F. Light Water Reactors Branch 1. 79/04/05 1p.
- 7905000255 Topical report evaluation of NRC-6491, "Fuel Rod Bowing." Reply provides acceptable data base for critical heat flux based on test of bow necessary for contact. Light Water Reactors Branch 1. 79/04/05 1pp.
- 7905000256 Details changes to Tech Specs re use of reflector elements & fuel element pebbles. BARNETT, R. M. Babcock & Wilcox Co. 79/05/02 2pp.
- 7905000257 Summary of 790428 meeting w/Meetinghouse to discuss capabilities of natural circulation for Meetinghouse plants. Forwards responses to questions raised re power operated pressurizer relief valve opening. ANDERSON, T. H. Meetinghouse Electric Corp. NS-TSM-2078. 79/05/01 2pp.
- 7905000264 Due to increased workload from TMI, ATWS data per NRC 790215 request will be submitted 790501.
- 7905000265 ANDERSON, T. H. Meetinghouse Electric Corp. NS-TSM-2077. 79/05/01 1p.
- 7905000269 Notification of contract awarded: "Design of NRC Supply & Maint Modules of Property & Supply Sys." awarded to Small Business Administration & subcontract awarded to Rehab Sys, Inc. HANSEN, T. F. Administrative Contracts Branch, NRC-10-79-378. 832-44-94944. 79/04/03 1p.
- 7905000270 Contract for "Design of NRC Supply & Maint Modules of Property & Supply Sys." awarded to Small Business Administration & subcontract awarded to Rehab Sys, Inc. HANSEN, T. F. Administrative Contracts Branch, NRC-10-79-378. 79/03/19 12pp.
- 7905000401 NRCES/CR-0285 "COMPTON-1/1028 Computer Program for Predicting Containment Pressure Response for LWRs." HARRINGTON, G. W., METCALFE, L. J. EG & G, Inc. FIH A-4009. 79/03/21. 449pp. Available at NTIS.
- 7905000406 NRCES/CR-0723 "Test Plan Large Scale Molten Salt-Water Vapor Explosion Alternative Safety Analysis for Advanced Reactors." HANBY, R. E. Argonne National Laboratory. FIH A-2026. 79/02/28 22pp. Available at NTIS.
- 7905000408 NRCES/CR-0390 "An Evaluation of Fuel Rod Behavior During Test LDR-11." CDDK, T. F., EG & G, Inc. PSI A-4041. 79/03/21 105pp. Available at NTIS.
- 7905000413 Forwards NRC computer security program responses to GAO recommendations & NRC Manual Chapter 213: "NRC Security Program." HANSEN, J. H. Commission. 79/04/12 37pp.
- 7905000414 Comments on proposed Reg Guide 1.2B: Revision 2 language of ACRS MS 2-1777 should be maintained. Requirements for specific procedures eliminate desirable flexibility. SULLIVAN, T. J. Consumers Power Co. 79/04/03 1p.
- 7905000417 NRCES/CR-0734 "An Evaluation of the Effect of Intergranular Stress Corrosion Cracking on Normalized Type 304 Stainless Steel." HANBY, R. E., METCALFE, L. J., POLLEY, R. T. American Univ. FIH B-5603. 79/04/03 522pp. Available at NTIS.
- 7905000422 NRCES/CR-0442 "The Critical Experiments," progress report Oct-Dec 1978. GOSSEL, R. B., D. L., FORD, R. H. Rockwell International Corp. FIH A-1036. 8PP-2888. 79/04/20 29pp.
- 7905000423 NRCES/CR-0434 "Effects of Nuclear Power Plants on Community Growth & Residential Property Values." Final report 790320-790319. GOSSEL, R. B., DUNN, R. H., BAUDERLEND, D. H. Pennsylvania State Univ. FIH A-1173. 79/04/20 55pp. Available at NTIS. 86 GC.
- 7905000430 Comments on proposed rule 10CFR26 re acceptable criteria for SCCS for LWRs, supports relevant research & forwards list of research needs. LECHENBERG, H. Electric Power Research Institute. 79/03/19 18pp.
- 7905000431 Comments on proposed rule re generic rulemaking to improve nuclear power plant licensing. Agrees w/NRC proposed change & forwards suggestions. HEDLEY, J. C. Environmental Protection Agency. 79/03/18 4pp.
- 7905000432 Comments on proposed rule re generic rulemaking to improve nuclear power plant licensing. endorses concept if it does not delay or cause expensive & complicated lawsuits on plants already in licensing process. LUNDA, M. J. Portland General Electric Co. 79/03/09 2pp.
- 7905000433 Comments on proposed rulemaking 10CFR27: proposed change has potential for add costs & delays w/o corresponding benefits to public. Should not be adopted. BARNES, A. Virginia Electric & Power Co. 154. 79/03/20 2pp.
- 7905000434 Forwards corrected motion to reschedule RM Dardas deposition on 790204 Certificate of Suit and. STREBL, E. J., Spiegel & McDiarmid. 79/04/12 1p.
- 7905000507 Corrected motion for rescheduling of RM Dardas deposition served on 790204 Certificate of Suit and. HATT, P. R., STREBL, E. J., Spiegel & McDiarmid. 79/04/12 7pp.
- 7905000593 Transcript of 790417 briefing in Washington, DC on operational safety data-gathering & analysis. 2p 1-99. OLLINGER, V. R., BRACFORD, P. A., KEMMERTON, R. T. Commission. 79/04/19. 105pp.
- 7905000624 Requests briefing on operational safety data-gathering & analysis. Outline & relevant LWR and. CHILDS, S. J. Office of the Secretary of the Commission. 79/02/22 15pp.
- 7905000625 NRCES-79-209 Proposed 11a be prepared from Secretary denying Kramish FOIA Appeal 7904-0111 should state that deleted portions are properly classified. SICHART, L. Office of the General Counsel. 79/03/22 3pp.
- 7905000645 Response to FOIA 78107 request for transcript of 78106 Commission meeting re Control System. Portions of transcript withheld. Appeal possible. FULTON, J. H. Division of Rules and Records. FCIA-78-018. 79/03/05 1p.

NONDOCKETED ITEMS

297

- 7905100047 Commission determination re public disclosure of 781104 transcript of Special testimony Portions of record withheld
CHILDS, J. Office of the Secretary of the Commission 79/02/26, 1p
- 7905100050 Appeals deletions from 781104 Commission meeting transcript supplied in response to NSIA 78-310.
NRA/INRA Trends Publishing, Inc 79/02/07 1p
- 7905100048 Response to 790309 appeal of initial determination re NSIA 78-310 requesting transcript of Commission meeting on 781104 vote in Sunshine Act preclude making deleted portions available
CHILDS, J. Office of the Secretary of the Commission 79/03/09 1p
- 7905100051 "Baseline Support Analysis for Generic C-E Plant (Including Commercial Steam Generator Tube Rupture) Phase 1."
COWELL, H. R., LEVINE, H. B., BIERER, S. Brookhaven National Laboratory. FN-4-3505 84--NBS-28895 79/03/21, 72pp.
- 7905100022 Evidence of circuit breaker failure indicating defects affecting safety of nuclear power plants Bafst monitoring patches driving pump broke at weld & cutter pin securing latching pump shaft broke
CONORS, J. E. Golden Gate Distributor Co 79/03/20 3pp.
- 7905100028 Response to 790316 Mr Lewis report, Would welcome opportunity to meet & discuss issues in future testimony of Mr Benton on 790321 before Congress and.
NEHRKE, J. M. Commission 79/04/22 1p.
- 7905100032 Believes NRC press release of 790119 was major source of confusion since positive findings of Lewis report were not mentioned & release put entire NRC-1400 on same level as executive summary.
HEDRICK, G. Illinois State of 79/03/16, 3pp
- 7905100033 Transcript of 790321 statement before Subcommittee on Energy & Meter Development re computer code readout on seismic design of pipe stress analysis Supporting documentation encl
ROTHMAN, H. M. Office of Nuclear Reactor Regulation 79/03/21, 22pp.
- 7905100036 Forwards notice of denial of petition for rulemaking re amending 10CFR60.501a, 501a for Protection Against Radiation.
Reg guide will be issued to clarify meaning of regulation
HARRIS, M. S. Office of Standards Development 79/04/08 1p
- 7905100043 Forwards relevant press releases & preliminary notifications issued to date in response to 790330 letter re TH1 incident
KAMMERER, C. Office of Congressional Affairs 79/04/10 4pp.
- 7905100044 Act receipt of 790404 ltr re info on nuclear safety & emergency evacuation plans.
KAMMERER, C. Office of Congressional Affairs 79/04/10, 4pp
- 7905100051 Act receipt of 790402 ltr requesting security status report re security at Oconee 1, 2 & 3 in light of TH1 incident
KAMMERER, C. Office of Congressional Affairs 79/04/10, 4pp.
- 7905100053 8802V-78-27D
Forwards, for Commission consideration, application from Edsel Ehl Co for license to export U-235/Uranium to Argentina.
CHILDS, J. Office of the Secretary of the Commission. 79/04/20, 1p.
- 7905100056 Recommendations license re granted to Westinghouse to import U-235 to U from Sweden Requests notification of license.
CHILDS, J. Office of the Secretary of the Commission. 79/04/20, 1p.
- 7905100059 Draft evaluation of Subur Resources proposal will use include radiological assessment section due to insufficient info.
SCAMAND, B. A., Assistant Director for Waste Management (Pn 790301), 79/04/09, 1p.
- 7905100062 Forwards JM Cavanaugh 790403 ltr expressing support for federal central control status for US nuclear plants Requests info necessary for reply.
PETER, R. House of Rep. 79/04/10, 3pp.
- 7905100070 Minutes of ACRR A/E Balance of Plant Subcommittee 790326 meeting in Madison, SC to review Plover Power Bore, re GOFBAR & relationship to BAF Ref Bgr OBAR-203 for preliminary design approval
ACRR - Advisory Committee on Reactor Safeguards. 79/01/26, 14pp.
- 7905100091 Act receipt of 790320 ltr re TH1 incident Complete response will be forwarded as soon as possible Forwards NRC press releases & preliminary notifications re incident.
KAMMERER, C. Office of Congressional Affairs. 79/04/10 3pp.
- 7905100101 Response to 790319 ltr Northern CA Power Authority (NCPA) How can appear that it is time to move ahead w/ previously authorized discovery directed toward individual NCPA member NCPA will not permit will to search member files file
MCARDLE, R. C. Signal & McCardell 79/02/20 3pp
- 7905100102 Act receipt of 790405 ltr re TH1 incident Complete response will be forwarded as soon as possible Forwards NRC press releases & preliminary notifications re incident.
KAMMERER, C. Office of Congressional Affairs 79/04/10 3pp
- 7905100138 Supports ALE 790325 order denying Southern CA Edison Co's 790325 motion to quash subpoena duces tecum. Supporting documentation & Certificate of RV encl
GOLDBERG, J., VOLSEN, S. H. Anti-Truist Division 79/04/18 47pp
- 7905100142 Response by unit to NRC & intervenors' preliminary comments re commitments. Discusses specific suggested changes to commitments Supporting documentation & Certificate of RV encl
GOYLE, N. H., ARMSTRONG, W. H., HATTON, H. J. McCutchen, Doyle, Brown & Emerson 79/04/16 130pp
- 7905100152 Forwards revision to NPI operator instructions per IE Bulletin 79-034
TAYLOR, J. H. Babcock & Wilcox Co. 79/04/17, 3pp.
- 7905100159 Act receipt of 790402 ltr re TH1 incident Complete response will be forwarded as soon as possible Forwards relevant releases & preliminary notifications.
KAMMERER, C. Office of Congressional Affairs. 79/04/09 3pp
- 7905100165 Requests info re design or operational problems generic to BAF facilities & relationship to similar problems experienced at the
FATIS, V. House of Rep. 79/04/02, 3pp
- 7905100168 NUREG/CR-0423
"Full Comparability Tests for LOFT Nuclear Reactor Fuel Centerline Transmutations"
CHANG, I. L., REYNOLDS, C. C., EUSTON, P. M. Hanford Engineering Development Laboratory. TFC-1000. NUREG-TM-70-39 79/03/31, 68pp Available at NTIS. 63.28.
- 7905100174 Act receipt of 790403 ltr re safety of South TX project in light of TH1
KAMMERER, C. Office of Congressional Affairs 79/04/10, 3pp
- 7905100185 Forwards third submittal to App D of NRC-24011-P-A "Generic Relief Fuel Application" Encl withheld
(ref 10CFR2.701).
GIRING, J. F. General Electric Co. Nuclear Energy Products Div. MC 852 79/03/08, 3pp
- 7905100190 NUREG/CR-0726
"Transportation of Radioactive Mail in U.S." 77026-75046
U Illinois, State of. 79/04/30 30pp. Available at NTIS 64.50.
- 7905100194 Forwards second submittal to App D of NRC-24011-P-A "Generic Relief Fuel Application" Encl withheld
(ref 10CFR2.701).
GIRING, J. F. General Electric Co. Nuclear Energy Products Div. MC 852 79/02/28, 4pp.
- 7905100198 In response to 790401 ltr re TH1 incident, forwards press release & preliminary notifications issued to date & NRC requests re Government Bureau's request to close Radio Bore.
KAMMERER, C. Office of Congressional Affairs. 79/04/10, 3pp.
- 7905100213 NUREG/CR-0423
"Radiation Dose Calculations & Hazard Evaluations for Inhaled Radionuclides." Annual progress report July 1977-June 1978.
NEARLUND, J. A. Lovelock Biomet & Environmental Research Institute. LF-65. 79/02/31, 84pp. Available at NRC 67.50.
- 7905100218 Act receipt of 790402 ltr re TH1 incident Complete response will be forwarded as soon as possible. Forwards NRC press releases & preliminary notifications re incident.
KAMMERER, C. Office of Congressional Affairs. 79/04/09, 3pp.
- 7905100239 NUREG/CR-0724
"Status of Research on Radiotoxicity of Low Level Waste Processing."
NRC-1703. J. J. W. TRAN, T. Assoc. Inc. 79/04/30, 13pp. Available at NTIS 67.50.

- 7705100230 Supplement 770617 ltr Licensing action on application for export of components to the Philippines not yet completed
GASCO, L.A. Office of International Programs 77/04/27. 1p
- 7705100340 NUREG/CP-0008
"Proceedings of Conference on High Level Radioactive Solid Waste Forms Dec 19-21/77 at Beaver-05"
CASEY, L.A. Office of Nuclear Material Safety & Safeguards
77/12/19 80pp. Available at NTIS. 821.30
- 7705100345 "Bioscience Experiments in Aquatic Environments" quarterly progress report for Oct-Dec 1978
ANDERSON, D.R.; BEAN, R.M.; DIBSON, G. Battelle Memorial Institute, Pacific Northwest Laboratory PNL-3099-7. PNL-2931. 77/03/31 43pp
- 7705100352 NUREG-0380 V3 R4
"Program Summary Rep." Vol 3-Rev 4
"Office of Management and Program Analysis 77/04/20 103pp
Available at NTIS. 612.50
- 7705100364 On behalf of Marubeni Canada Ltd., requests extension of expiration date of License U-0293 to 800401 to date 50.000
lg U-0293 expired against license
HARRISON, G.M. Edison International Co 77/03/13 7pp
- 7705100369 Comments on proposed draft reg guide "Qualification of QA Program Audit Personnel for Nuclear Power Plants" - ASME code activities would be excluded in ANSI/ASME NRC 5.20 unless otherwise indicated.
TRINER, E.B.G. Arkansas Power & Light Co 819-4 77/03/23 1p
- 7705100377 Summary of 770528-07 meeting w/OA Co in San Diego, CA re QCFPR & NRC program descriptions, licensing overview, R&D programs & inservice insp requirements.
HARRISON, P.M.; HARRISON, J.F. Advanced Reactors Branch. 77/04/17 8pp.
- 7705100378 Weekly info rept for week ending 770420
RENN, T.A. Office of the Executive Director for Operations 77/04/27 27pp
- 7705100387 Requests info re application for license to export to USA
-32 microgram Pu-239 & whether or not it is sub to terms of US-LEA agreement for cooperation
PETERSON, H. Office of International Programs 77/03/01. 1p
- 7705100393 Ltr of assurance in response to NRC 770302 ltr re Reuter-Brosius application for license to export U-235 to Norway. Transfer will be only to all terms & conditions of a 770302 agreement for cooperation.
STENNA, A. Norway. 77/03/30. 2pp
- 7705100430 Summary of 770406 meeting w/Baccarat Municipal Util District & BMA re termination of 770320
Operating Reactors Branch 4. 77/07/13. App
DUTT, D.B.
- 7705100443 Ack receipt of 770330 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept
77050400/77-01.
POZAP, B.V. Region 4, Dallas. Vendor Inspection Branch.
77/04/11 1p.
- 7705100531 Response to NRC 770301 ltr re deviation noted in QA Program Insp Rept 77050400/77-01. Corrective actions charge inspection is being processed to correct design
insufficiencies & review of subcontracts will be conducted
WHEELER, J.M. Babcock & Wilcox Co 77/03/30. 4pp.
- 7705100536 Forwarded QA Program Insp Rept 77050400/77-01 on 770212-16 & notice of deviation.
POZAP, B.V. Region 4, Dallas. Vendor Inspection Branch.
77/03/01. 2pp
- 7705100540 Notice of deviation from Insp on 770212-16
"Region 4, Dallas. Vendor Inspection Branch. 77/02/24. 1p
- 7705100546 QA Program Insp Rept 77050400/77-01 on 770212-16.
Noncompliance noted Section 11 of project internal procedures manual not verified by 770125 as committed.
BRINLEY, S.H.; HALL, C.J. Region 4, Dallas. Vendor Inspection Branch. 77/03/09 4pp
- 7705100549 NRC/77-04
Forwarded for Commission consideration, application from Transnuclear, Inc for license to export U-235 to the Netherlands.
BENSA, J.R. Office of International Programs 77/04/16 1p
- 7705100547 Requests application for license to export U-235 to the Netherlands
Transnuclear, Inc 77-121/01. 77/04/11 1p
- 7705100548 Forwarded Abnormal Occurrence 50-012-79-3 for Rancho Sec 1.
"Baccarat Municipal Utility District 77/03/11. 1p.
- 7705100549 Abnormal Occurrence 50-012-79-3 on 770212. turbine/generator tripped when over-speed trip using broken faulty transmitter
de-energized due to cable drift faulty transmitter replaced
"Baccarat Municipal Utility District 77/03/11 1p
- 7705100549 Inference of review completion of util data re 770320 reactor trip & reactor shutdown transient. Conclude w/Util's intent to return plant to power operation at level below 75% full power. Urge certain recommendations
JAMES, J.T. Babcock & Wilcox Co 77/03/23 2pp
- 7705100549 Confirmed transfer of lead responsibility made verbally
770320 re steam generator level control during auxiliary feedwater operation
JORDAN, L. Division of Reactor Operations Inspections.
16, 801, 77-79-01. 77/01/16 2pp
- 7705100547 License for HMA, Inc to export hollow sealed instrument isolating valves to Canada.
OPLINGER, G.G. Assistant Director for Export/Import & International Safeguards 77/04/27. 1p
- 7705100525 Requests extension of License XRM-909 from 770301 to 770321.
STENNA, A. Westinghouse Electric Corp. 77/03/19. 1p.
- 7705100526 Comments on proposed rulemaking 10CFR20-13 position should be denied. Suggests certification of health physics personnel, although NRC should not have function of certification.
BROOK, P.R. International Brotherhood of Electrical Workers. 77/04/09. 2pp.
- 7705100533 Project on structural integrity of water reactor pressure boundary components, monthly progress rept for Mar 1977.
LOEB, P.J. Naval Dept of, Naval Research Laboratory. 77/04/10 4pp
- 7705100535 Comments on potential effect of loop seals in a pressurizer
wrg line, greater emphasis must be placed on this matter in light of SRS-2
HOWARD, T. Reactor Systems Branch. 77/01/20. 1p.
- 7705100540 Comments on potential effects of loop seals in a pressurizer
wrg line, recommend design for design requirement be studied for all CP reviews to determine if loop seal can be eliminated.
HOWARD, T. Reactor Systems Branch. 77/01/10. 2pp.
- 7705100541 Presents Analysis Branch contribution to task group evaluation of protection of operating BWR plants against feedwater transients, info typically provided is not sufficient
ROBERTSON, J.E. Analysis Branch 77/04/10. 4pp.
- 7705100549 Assigns R Tedesco as group leader of Task Group on Review Review of Feedwater Transient in BWR-Designed Reactors.
CASE, E. Office of Nuclear Reactor Regulation. 77/04/09 1p

NONDOCKETED ITEMS

299

7905110096 Forwards NSAF-7402. "Verification Testing & Analysis of 17:17 Optimized Fuel Assembly." nonproprietary
AMERSON, T.H. Westinghouse Electric Corp. NS-TNA-2074. 79/04/27
IP.

--7905110098 NSAF-7402 (NP)
"Verification Testing & Analysis of 17:17 Optimized Fuel Assembly." nonproprietary
AMERSON, T.H. & GAGNE, P.F. Westinghouse Electric Corp. 79/03/31 79pp

7905110114 Clarifies uncertainties re ODN evaluation and proposed licensing basis evaluation completed re neutron effective yield correlation uncertainty evaluation withheld (ref 7905110098) AFF(davil ent)
GDM, R.W. General Electric Co. NEN 123-79 79/04/30 App

7905110127 Comments on proposed rulemaking 10CFR2-6.2-endorsement petition.
STEVENS, J.R. New England Power Co. 79/04/26 2pp

7905110141 Comments on proposed rulemaking 10CFR2-7.1 it would only serve to complicate already burdensome licensing process
Brenneisen of nuclear plant licensing procedures is needed
SALZBERG, P.A. Affiliation Unknown. 79/03/26, 1p

7905110143 Board notification, 79-79-10, reactor inspector concerns re BSM plant Remanufacture Board is notified Supporting documentation ent.
WAGS, D.L. Assistant Director for Light Water Reactors 79/03/04 3pp

7905110145 Comments on proposed rulemaking 10CFR2-7.2-press rules re information are adequate.
FRECHER, J. Affiliation Unknown. 79/03/26 1p

7905110146 Comments on proposed rulemaking 10CFR2-7.2-press rules re working of "good cause" is vague.
ZIM, J.K. Affiliation Unknown. 79/04/02, 1p.

7905110150 Comments on proposed rulemaking 10CFR2-13.1-world place justified & potentially unsafe requirements on operation emergency planning.
MCGOWAN, K. Airline Public Service Co. 79/04/06 2pp.

7905110154 Forwards charter & member list of Task Group on Generic Review of Feedwater Transients in BSM Designed Reactors
DAVIS, S.K. Systematic Evaluation Programs Branch. 79/04/02 2pp

7905110174 Forwards info on possible nuclear incidents in USSR. Progress briefing by ONS.
GILBERT, V. Commission. 79/04/23, 7pp.

7905110180 Discusses Tech Specs for reactor coolant age heating & condenser rates & pressure/temp limits.
GMA, L.D.V. Division of Operating Reactors. 78/04/17, 2pp.

7905110182 Ask receipt of 790511 memo defining mail sub j to FOIA request Request clarification re personal diaries & tapes.
GILBERT, V. Commission. 79/04/16 1p.

7905110188 Summarizes status of NEM briefing, evacuation plan & talks re Governor Brown re BSM reactor problem
GILBERT, V. Commission. 79/04/03, 1p.

7905110204 Requests view on Reactivity 790510 memo re feedwater transients.
GILBERT, V. Commission. 79/04/12, 1p

--7905110226 Presents Analysis Branch contribution to task group evaluation of generic feedwater transients in BSM reactors
REBUTT, J.R. Analysis Branch. 79/04/10, 7pp

7905110229 Outlines that little benefit would result from reducing all BSM plants to BSM power should event similar to THE OCON.
TODD, R.L. Assistant Director for Plant Systems 79/04/24, 2pp.

7905110233 Tabulates reactor safety research supplemental funding
MULLEN, T.E. Division of Reactor Safety Research. 79/04/24, 2pp.

7905110248 Forwards "C-E Best Estimate Pre-Test Analysis of LOFT Test L3-3."
SCHERER, A.E. C-E Power Systems, LD-79-029. 79/03/09, 1p.

--7905110244 LD-79-029
"Best Estimate Pre-Test Analysis of LOFT Test L3-3."
May 1979
C-E Power Systems 79/03/09 24pp

7905110241 Motion for postponement of 790400 deadline for discovery & 790400 prehearing conference due to THE incident.
SCOTT, B.K. Texas Public Interest Research Group 79/04/05, 2pp

7905110242 Motion for postponement of 790410 prehearing conference
investigation of THE
DARTY, J.F. Affiliation Unknown. 79/04/04, 2pp.

7905110247 Motion by intervenors to reopen record indefinitely & postpone decision on generic safety issue considerations
pending full investigation of THE
PFAFFKORN, H.G. PFAFFKORN, D.C. PFAFFKORN & CO., P.A. 79/04/03, 2pp

7905110249 Discusses & clarifies actions for Emergency Procedure 3-Line of shutdown w/radiological control program.
TERRILL, L. Assistant Director for Plant Systems 79/04/05, 2pp

7905110253 Motion to reopen safety hearings to consider suspension & revocation of CP.
DARTY, J.F. Affiliation Unknown. 79/04/04, 2pp

7905110255 Requests comments re environ qualification & instrumentation re Police course of an accident
MAMMER, D.H. Assistant Director for Plant Systems 79/04/06 2pp

7905110277 Notification of ACRS Subcommittee on Power & Electrical Sys 790230 meeting with consultants & NRC staff in Washington, DC to review interconnection of protection & safety sys w/reactor control sys on REDAN-4 design
MOTIL, J.C. ACRS - Advisory Committee on Reactor Safeguards. 79/03/14 2pp

7905110278 Forwards BA Program Insp Rep 79050104/79-01 on 790205-08. No noncompliance noted.
POTAMOV, L. Region 4, Dallas. Vendor Inspection Branch 79/03/08, 2pp.

--7905110404 BA Program Insp Rep 79050104/79-01 on 790205-08. No noncompliance noted. Major areas inspected: implementation of 10CFR2-6.2-press rules & applicable codes & rules including action on previous findings, rep & tests.
MONTGOMERY, V.H. WHITEHEAD, S.E. Region 4, Dallas. Vendor Inspection Branch. 79/02/28, 2pp.

7905110412 Notification of contract execution: "Development of Improved Techniques for Analyzing Heat Control & Accounting Data." awarded to Science Applications, Inc.
SCIENCE APPLICATIONS, INC. Technical Assistance Contracts Branch. FIN 8-6399-Y. NRC-02-79-028. 79/04/20 1p.

--7905110413 Contract: "Development of Improved Techniques for Analyzing Heat Control & Accounting Data." awarded to Science Applications, Inc.
SCIENCE APPLICATIONS, INC. Technical Assistance Contracts Branch. FIN 8-6399-Y. NRC-02-79-028. 79/04/20 25pp.

7905110414 Board notification, RE reactor inspector concerns re BSM plants.
WAGS, D.L. Assistant Director for Light Water Reactors 79/04/03, 1p.

--7905110430
790226 #
HOBBS, E.V.
79/03/21

--7905110431
HOBBS, E.V.
79/03/21

7905110439
in Richland
HOBBS, E.V.
Reactor R.

7905110440
of Project
Eliavert
Saviro

NONDOCKETED ITEMS

301

790140297 Clarified application of Leibnitz rule in integration of conservation of mass equations in BAFK code
STROUD, E. F. General Electric Co., Nuclear Energy Products Div
N94378-79. 79/03/20. App.

790140313 Forwards draft NUREG-0583, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
Requests comments by 790509. W/A encl.
RYAN, R. O. Office of State Programs. 79/04/10. 1p

790140320 Forwards NUREG-0583, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
Requests comments by 790509. W/A encl.
RYAN, R. O. Office of State Programs. 79/04/10. 1p

790140325 Forwards draft NUREG-0583, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
Requests comments by 790509. Final report will be issued shortly after 790509. W/A encl.
RYAN, R. O. Office of State Programs. 79/04/10. 1p

790140329 Forwards draft NUREG-0583, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
Requests comments by 790509. W/A encl.
RYAN, R. O. Office of State Programs. 79/04/10. 1p

790140333 Forwards draft NUREG-0583, "Beyond Defense-in-Depth Cost & Funding... In Support of Commercial Nuclear Power Stations."
Requests comments by 790509. W/A encl.
RYAN, R. O. Office of State Programs. 79/04/10. 1p

790140314 Comments on SF Res to EO Case memo summarizing meeting re natural circulation considerations. Drafts Res to 171029
transmittal resulted in subcooling of 60 F or more. Numerous implications made by Nicholson East.
TAYLOR, J. H. Dabco & Hilco Corp. 79/05/04. 1p.

790140326 Forwards new application for export license w/ requested corrections.
MARTINEZ, F. Spain. 79/04/09. 1p.

790140329 Corrected application by Spanish designers for license to export 31 kg U-235 to Switzerland to Spain
Spain. 79/02/28. 1p.

790140392 Forwards proprietary report NUREG-21892-P, "Submerged Structures Model, Main Vent Air Discharge Evaluation Report." Affidavit and report available in Central File.
BRODIE, J. General Electric Co., Nuclear Energy Products Div.
N94121-79. 79/04/20. App.

790140426 Submittal requested info re 2-loop test apparatus & evaluation model reactor calculations, vaporization correlation data, & response to NRC question re vaporization in 2-loop test apparatus. W/A encl.
BRODIE, J. General Electric Co. N94022-79. 79/01/30. App

790140428 Discuss NRC concern re heat transfer coefficient of 4-inch BAFK code & GE clarification.
BRODIE, J. General Electric Co. N94021-79. 79/01/29. App

790140444 Forwards slides presented at 790113 meeting w/MRC re BOCB evaluation model. Submittal contains proprietary info
Inf. 102762, 7901.
BRODIE, J. H. Westinghouse Electric Corp. N94028-79. 79/04/10. 1p.

790140809 Forwards re furnishing info & list of burial sites in response to PUSA request for info re all nuclear plants, either completed under contract or all nuclear waste burial sites. W/A encl.
FELTON, J. H. Division of Rules and Records. 79/05/10. 1p.

790140811 PUSA request for map & current geographical listing of all nuclear plants either completed or under contract or all nuclear waste burial sites.
Comments & Affiliation Unknown. 79/09/01. 1p.

790140821 Comments on draft map guide & value/impact statement re "Nuclear Analysis & Design of Concrete Radiation Shielding." Specific criteria for design of concrete radiation shielding structures should be provided.
GARDNER, F. E. Energy Dept. 79/04/02. 1p.

790140825 Responses to PUSA request for info re drawings & spec of model Theatrum, MC-2000 teletherapy unit. Forwards various documents, drawings & list of drawings withheld as proprietary. Documents & drawings not encl.
FELTON, J. H. Division of Rules and Records. 79/05/07. App.

790140827 PUSA request for internal files of facilities.
BLDOW, J. H. Mississippi Sentinel. 79/04/10. 1p.

790140834 Forwards PUSA request for access to documents in regional office.
APPEL, J. B. Region 3, Chicago. Office of the Director. 79/04/20. 1p

790140836 Response to PUSA request for records not in NRC PDR re facilities.
FELTON, J. H. Division of Rules and Records. 79/03/08. 1p

790140872 NUREG-0583
"The Steamline Heat Transfer Separation-Effects Program Data Evaluation Report, 1977 Test Series II."
MELNICK, C. B. N94010-79. 79/03/08. 1p. Oak Ridge National Laboratory. FIN 4-0128. OMA, NUREG-0583. 79/04/20. 199p. Available at NTIS

790140873 NUREG-0584
"Handbook of Average & Initializations."
Office of Administration. 79/02/21. 121pp

790140875 NUREG-0583
"The Steamline Heat Transfer Separation-Effects Program Data Evaluation Report, 1977 Test Series II."
MELNICK, C. B. N94010-79. 79/03/08. 1p. Oak Ridge National Laboratory. FIN 4-0128. OMA, NUREG-0583. 79/04/20. 199p. Available at NTIS

790140876 NUREG-0584
"Computer Program R-FIX/ROFI Mod of Computer Program R-FIX for Application in Fluid Flow Simulation in LDMT Sys.
MELNICK, C. B. N94010-79. 79/03/08. 1p. Oak Ridge National Laboratory. FIN 4-0128. OMA, NUREG-0584. 79/04/20. 199p. Available at NTIS

790140880 Transcript of 790404 open meeting for NRC briefing on five subcommittee panels. (atomic design) Pg 1-57.
HENDRICK, J. H. OILIBRARY, V. N94003-79. 79/04/26. 199p

790140881 Add receipt of 790310 w/ statement on "Probabilistic Risk Assessment & Its Application in Reactor Safety & Licensing."
Forwards NRC policy statement re Louis Res & Submissions to NRC & facilities before USAR subcommittee.
HENDRICK, J. H. Commission. 79/04/20. 1p

790140882 Forwards copy of "Probabilistic Risk Assessment & Its Application in Reactor Safety & Licensing" submitted to Committee on Interior & Insular Affairs.
RICHARDS, C. L. American Atomic Co. (subs. of Gulf Oil Corp.) 79/03/10. App

790140889 Testimony of PA Redford before Subcommittee on Energy & Environment of House Committee on Interior & Insular Affairs.
BRODIE, J. H. Commission. 79/02/26. App

790140890 Testimony of J. H. Hendrick before Subcommittee on Energy & Environment of House Committee on Interior & Insular Affairs.
HENDRICK, J. H. Commission. 79/02/26. App.

790140894 NUREG-0545. VI. NO
"Title List of Documents Made Publicly Available for Mar 1979."
Office of Administration. 79/03/01. 101pp. Available at NTIS. 82.00.

790140897 License for Transnuclear, Inc. to export 413 kg U-235 & 0.0235 kg U-233 to West Germany.
OPININGER, G. S. Assistant Director for Export/Import & International Safeguards. 79/04/27. App

790140898 License for Nukon, Inc. to export hollow sealed valves, valve manifolds, sealed pipe valves, metal instrument (valves) valves & manifolds to Canada.
OPININGER, G. S. Assistant Director for Export/Import & International Safeguards. 79/04/27. 1p

790140899 License for Transnuclear, Inc. to export 405 kg U-235 & 0.0235 kg U-233 to West Germany.
OPININGER, G. S. Assistant Director for Export/Import & International Safeguards. 79/04/27. App.

790140900 License for Nukon Nuclear Co. Inc. to export 1940 A to G-235 to Belgium.
OPININGER, G. S. Assistant Director for Export/Import & International Safeguards. 79/04/27. App.

790140903 License for Nukon, Inc. to export hollow sealed globe valves, needs & globe valves to Canada.
OPININGER, G. S. Assistant Director for Export/Import & International Safeguards. 79/04/27. 1p.

NONDOCKETED ITEMS

- 7905190039 License for Hoke, Inc. to export bellows sealed instrument isolating valves, sealed valves & valve manifolds to Canada.
OPL/INR/08.0 0 Assistant Director for Export/Import & International Safeguards 79/04/27 1p
- 7905190037 License for Hoke, Inc. to export bellows sealed instrument isolating valves & spares, valve manifolds & sealed instrument valves to Canada.
OPL/INR/08.0 0 Assistant Director for Export/Import & International Safeguards 79/04/27 1p
- 7905190039 License for Hoke, Inc. to export bellows sealed instrument isolating valves to Canada.
OPL/INR/08.0 0 Assistant Director for Export/Import & International Safeguards 79/04/27 1p
- 7905190040 License amendment for GE to export 2.45 kw Pu & 40 kw natural U to France.
OPL/INR/08.0 0 Assistant Director for Export/Import & International Safeguards 79/04/26 1p
- 7905190047 Ltr of acceptance certifying fuel elements mentioned in General Atomics 790222 application will be subject to conditions of 402222 add'l agreement for cooperation with IAEA. European Communities. Commission of. 79/03/27 1p
- 7905190046 Notice of 790319-20 ACRS Subcommittee on ECRG meeting, write consultants & NRC in Los Angeles, CA to discuss status of physical data inputs, current licensing actions & asymptotic blindfolded forces.
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. 79/02/26 2pp
- 7905190043 Response to 790312 ltr requesting NRC extend comment period for NRC/ECR-0499, "Preliminary Statement on General Policy for Licensing to Improve Nuclear Plant Licensing".
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. 79/03/16 2pp
- 7905190046 Comments on NRC/ECR-0499, "Preliminary Statement on General Policy for Licensing to Improve Nuclear Plant Licensing".
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. 79/03/16 2pp
- 7905190049 Executive Branch position re Mitsubishi Travel Div of America, Inc. application for license to export reactor components to Japan. Japan, Dept. of, Bureau of Ocean & Internal, Environ & Scientific Affairs. 79/04/20 1p
- 7905190049 "Water Reactor Safety Research, Heat Transfer Highlights" Jan 1979.
LOTTER, P.A. Argonne National Laboratory. DOE 40-650-79 79/11/30. 4pp
- 7905190101 Notification of contract execution, Had & to "A/E Consulting Div., Contractor, Burns & Roe, Inc."
OTM/TA. Research Contracts Branch. FIN 5-4230 NRC-04-77-077, 79/03/21. 1p
- 7905190109 Red line cost view extension through 800331 to "A/E Consulting Div."
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. FIN 5-4230. NRC-04-77-077 79/03/21 2pp
- 7905190108 Application by Hoke, Inc. for license to export motorized & isolating valves & spares parts to Korea.
LINDMEYER, P. Hoke, Inc. 79/04/16. 1p
- 7905190104 Application by Hoke, Inc. for license to export bellows sealed instrument isolating valves & valve manifolds to Korea.
Hoke, Inc. 79/04/19. 1p
- 7905190122 Executive Branch position re Mitsubishi Intl Corp application for license to export 342 kg U-235 to Japan.
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. 79/04/16. 1p
- 7905190140 Monthly ltr report for Feb 1979 re technical project status of "General Measurements & Modeling for Fast Reactor Safety".
GUSEK, A.A. Battelle Memorial Institute, Columbus Laboratories. 79/03/28. 3pp
- 7905190134 Summary of 790330 meeting w/GE re Target React safety relief valves & review of progress toward reducing number of SRB blowdowns.
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. 79/04/12. 14pp
- 7905190150 Forward petition to intervene & request for hearing on behalf of CTR for Development Policy & two other intervenors re application for export license U.S. and U.S.
ASHER, T.E. Asher, T.E. PC 88800 1471. 79/04/23. 1p
- 7905190150 License for Mitsubishi Travel Div of America, Inc. to export miscellaneous reactor parts to Japan.
OPL/INR/08.0 0 Assistant Director for Export/Import & International Safeguards 79/04/13. 1p
- 7905190161 Application by Sigma Chemical Co for license to export compound containing sodium & 4 kg dioxolane liquid over 2-year period to Australia.
Sigma Chemical Co. (subs. of Sigma Aldrich Corp.). 79/04/11. 1p
- 7905190162 License for Mitsubishi Travel Div of America, Inc. to export miscellaneous reactor parts & prepared parts for use in reactors to Japan.
OPL/INR/08.0 0 Assistant Director for Export/Import & International Safeguards 79/04/13. 1p
- 7905190179 Request approval of proposal to expand scope of DOR gearless issue 5-23, "Degraded Grid Voltage," to accommodate causes of degraded voltage identified by Arkansas Nuclear One abnormal occurrence.
VOLLMEYER, R. Assistant Director for Systems & Projects. 79/04/03 2pp
- 7905190183 Executive Branch position re Edlow Intl Co application for license to export 800,000 CI of tritium to Switzerland.
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. 79/04/12. 2pp
- 7905190186 Executive Branch position re Westinghouse application for license to export fuel rod tubes, springs & end plugs to Sweden. License should be granted.
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. 79/04/12. 2pp
- 7905190188 Response to 790337 ltr, Block OA program description does not meet NRC/ECR-0200. It will not be introduced to NRC topical report program. NRC/ECR topical report program description.
HARRIS, W. P. & Consulting Engineering Co. 79/03/28 2pp
- 7905190191 Executive Branch position re Mitsubishi Travel Div of America, Inc. application for license to export 11,000 polystyrene tubes to Japan. License should be granted.
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. 79/04/19. 2pp
- 7905190195 Application by Transnuclear, Inc. to amend export license to include add'l quantity of 0.2 g of U-235.
HARRIS, W. P. Transnuclear, Inc. 79/04/19. 1p
- 7905190196 Application by Edlow Intl Co to amend export license to show ABEA ATRM as only intermediate consignee.
HARRIS, W. P. Edlow International Co. 79/04/19. 1p
- 7905190199 Response to 8007-79-08 "Timing of Certain Requirements of U.S. Tailings Radiation Control Act of 1978." Details position re Federal-state authority to license mills regarding requirements of AEC Act Section 204.
KING, S. New Mexico State of. 79/02/07. 2pp
- 7905190203 Application by GE to amend license to export mail to Japan. Reactor components of first shipment to 790201.
MILBURN, S.D. General Electric Co./Nuclear Energy Products Div. 800-79006. 79/04/12. 1p
- 7905190208 Application by General Atomic Co. to amend license to export fuel elements containing U to Japan. Request extension of expiration date to 800701.
NRC/ECR-1.0 ACRS - Advisory Committee on Reactor Safeguards. 79/04/13. 1p
- 7905190213 NRC/ECR-0985
"Assessment of Intergranular Fracture Within Unwelded US Fuel Rods to Film Melting Operation."
CHANDRASEKHAR, A. W. WAGLE, T. R. ES & S. Inc. FIN A-4046. TREC-1330. 79/03/21. 9pp. Available at NRC.
- 7905190219 NRC/ECR-0913
"Reactor Safety Research Program," quarterly progress report Jul-Sep 1979.
KUTS, R. J., KATZ, M. J., FORDAN, G. Brookhaven National Laboratory. DOE-79-1-32-0015 (NRC-0985-0913). 79/01/20 21pp. Available at NRC.

NONDOCKETED ITEMS

303

790510227 Comments on proposed rules 100FR19 & 20 address proposed limit for emitting manufacturing of minor 15 years of age or under who are exposed to radiation above natural background levels
LAMPAR, J V. Bunker Hill Community College 79/03/15 2pp

790510238 Request to separate NRC into two entities one covering power reactors, U mining, nuclear weapons, and nuclear fuel processors & other dealing with radioactive waste
PEPPER, M P. Non-Destructive Testing Management Association 79/04/12 2pp

790510241 Response to 790218 ltr re application for license to export sensitive ore to India. Application was forwarded to Executive Branch on 790201 for review
BIRK, J R. Assistant Director For Export/Import & International Safeguards 79/04/13 1p

790510254 Application by Borg-Warner Corp. Nuclear Valve Div for license to export globe & check valves, carbon steel & stainless steel to Belgium
ANDERSON, B. Borg-Warner Corp 79/04/14 1p

790510327 Ack receipt of 790321 ltr providing views on NRC interpretation & implementation of U Hill facilities
Redaction Control Act of 1970
GILFILLAN, H. Office of the Executive Legal Director 79/03/07 1p

790510332 Weekly info rept for week ending 790427.
RENN, T A. Office of the Executive Director For Operations 79/04/01 5pp

790510346 NRC review of application need not be completed by 790331 due to probable change of ownership & act for NW Mineral Corp. Kanto project. Forwards Resources Corp 790331 ltr to CD Dept of Health
HARRIS, A J. Colorado: State of 79/03/16 4pp

790510349 Comments on NUREG-0226 "Summary of Operating Experience of Reactor Fueling Machine Generators - Considers this one of the best types of sub
RUBINSTEIN, S. Wisconsin Electric Power Co. 79/05/10 2pp

790510348 Review for protective order to prevent deposition of NRC Records Certificate of the NRC
WATKINS, J. OGDEN, H. H. Hutchinson, Doyle, Brown & Karsner, FRIEDMAN, H. H. Pacific Gas & Electric Co. 79/03/31 1pp

790510367 Request that GE rept NRC-21944-P "Quarter Scale Pressure Suppression Test Small Test Program Plant Unique Tests" be included in doclet.
FLANET, J M. Milwaukee Public Power District. 79/03/28 1p

790510394 Comments on proposed rule 100FR19 & 20 adequacy of present occupational dose limiting rule is essential.
STRELOW, R. Commonwealth Edison Co. 79/04/19 1p

--790510490 Comments on proposed rule 100FR19 & 20: preferable to address dose accumulation & occupational exposure at dose averaging hearings. Current proposal has not been thoroughly evaluated & potential consequences ignored.
STRELOW, R. Commonwealth Edison Co. 79/03/19 3pp

790510524 FOIA request for info re all records of LERs & NRC insps re NRC Industries, Inc Nuclear Div plant in Wilmington, DE
RIVKIN, T. News-Journal Co. NJ, Delaware 79/03/19 1p

790510528 Response to FOIA request for info re all records of LERs & NRC insps re NRC Industries, Inc Nuclear Div plant in Wilmington, DE re LERs for NRC Industries, Inc. Forwards four facility licenses & insps records. NRC encl.
FELTON, J M. Division of Files and Records. 79/03/10 1p

790510573 Certified mail mentioned in GA Co license application re export Pressur Chamber to Italy will be subj to all terms & conditions of amended 600728 add agreement for cooperation.
BIRK, J R. European Communities. Commission of. 79/03/26 1p

790510581 Forwards GA Program Insps Rept 99900360/79-01 on 790226-99. No noncompliance notes.
POYARD, V. U. Region 4, Dallas. Office of the Director 79/03/26 2pp

--790510585 GA Program Insps Rept 99900360/79-01 on 790226-99. No noncompliance noted. Major areas inspected: implementation of 100FR19, App B & other applicable regulations.
NELL, M. D., JOHNSON, J. H., WHITEHEAD, S. E. Region 4, Dallas. Vendor Inspection Branch. 79/03/29 1pp

790510592 Inform that PR notice of denial of petition for rulemaking has been modified to indicate that five rather than four people have submitted comments on petition for rulemaking
790510592 Revised page of notice sent
BARNES, R F. Transportation & Product Standards Branch 79/04/09 2pp

--790510598 Comments on PRN 20-9 re allowable radiation levels for radiographer safety & radioactive transport suggests 50 is better level than 100 (at 8 cm) but 73 may be suitable compromise
MUTCH, M C., JACOB, C. Atomic Energy Control Board, Canada 79/07/18 1p

--790510602 Comments on PRN 20-9 & PRN 24-1 present limits are presently providing necessary protection. Recommendations for revision to be made as compliance would be too difficult to develop & enforce
BOSCHMEL, K R. Westinghouse Electric Corp. WAB-LSL-275 79/07/18 1p

--790510607 Comments on PRN 20-9 & PRN 24-1 new regulations not needed to overcome impracticability & inconsistency of 79016 in determining radiation intensities at surface changes will be too restrictive
MORSE, D K. Niagara Mohawk Power Corp. 79/07/18 1p

--790510605 Comments on PRN 20-9 change restrictive operations on nuclear power plants & does not follow ALARA philosophy. Present rule is adequate
WELLS, S E. Florida Power & Light Co. L-77-028 79/07/25 2pp

--790510611 Comments on PRN 20-9 confirm opposition expressed in 790718 telegram. Finds first proposal reasonable, but second & third proposals are unacceptable
WELLS, S E., WHITE, M C. Atomic Energy Control Board, Canada 79/08/03 3pp

--790510619 Comments on PRN 20-9 change does not improve quality of work, nor does it provide better control of external dose. Major proposed adds would be more impracticable than existing regulations
BARNETT, L L. Rochester Gas & Electric Corp. 79/08/18 1p

790510644 Comments on proposed rules 100FR19 & 20: adequate retention of quarterly dose limit & approval of proposed dose per CY
BARNETT, A L. Affiliation Unknown 79/03/28 2pp

790510642 Comments on proposed Reg Guide 0.23 acceptable contamination limits are too restrictive
STRAUB, P J. Michael Weiss Hosp & Medical Center 79/03/21 1p

790510702 Response to 790508 ltr commenting on proposed deletion of dose averaging formula. SIB-101 Forwards draft rept of Interagency Task Force on Ionizing Radiation Wre encl.
ALEXANDER, R E. Occupational Health Standards Branch 79/03/15 1p

--790510704 Requests citations re epidemiological data & associated recommendations for nonoccupational lower dose
7905080, J L. Affiliation Unknown 79/03/25 1p

790510705 Forwards application add request from GE to change date of first scheduled shipment from 791225 to 790801 Wre encl.
OPLINGER, S B. Assistant Director for Export/Import & International Safeguards 79/04/25 1p

790510710 Oral argument
ALEX 791025 order will
OPLINGER, S B. Atomic Co 2pp

790510715 Denies CI
790502 as date for
HILLER, M E. 2pp

790510727 values in doc their OADR10

7905107 users address profile EVANET

NONDOCKETED ITEMS

7901150703 Notification of 790519 meeting w/ALB & NY State in
Babcock, NY to provide NRC review team opportunity to
visit alternate site in order to discharge NPPA obligation
BELL, S. E. Environmental Projects Branch 2 79/04/27 App

7901150734 Comments on proposed Reg Guide 10 B "thin window" survey
mat not necessary to detect low radiation. Detectivity
equipment for area wipe tests too low
CORRMAN, H. C. Laboratory Medical Center Dr. Illinois 79/04/03. Ip.

7901150738 Comments on proposed rulemaking 100782 734 recommends denial
of petition as destructive of present balance between
civilian interests & administrative needs. Proceedings could be
indiscriminately postponed & continued
THOMAS, R. G. F. Shaw Pittman, Potts & Frawley 79/04/10 App

7901150741 Comments on proposed Reg Guide 1. B. Revision 2 believes
staffing requirements for technical competence are much too low
HILLIS, C. A. Philippines. 79/04/02 Ip

7901150752 Comments on proposed Reg Guide 3 B approve provisions
requesting info on ore body location & openings of related
mines because mill operator should only be responsible.
MALPUE, J. R. American Mining Company 79/03/14 App

7901150777 "Study of Plutonium Solids Last Notes from OHSIP
Committee" quarterly progress report Oct-Dec 1978
BOSCHMANN, L. C. MATH, H. J. HANNAH, J. Battelle Memorial Institute,
Pacific Northwest Laboratory PNL-3292. PNL-3292-9. 79/03/01.
42pp Available at NTIS.

7901150784 Requests quantity of net to be raised to 75 lbs of TAP4 &
extension of application date to 79/03/31 for license to export
Uranium to Australia.
COLTON, C. Cerro, Inc 79/04/07 App

7901150785 Comments on proposed rulemaking 20-13 amend may be
appropriate for nuclear power plants but should not cover
airline employees
ANDERSON, C. R. American Airlines, Inc 79/04/12. Ip.

7901150787 License for GE to export four HA 200 local power range
reactors to India.
OPLINGER, D. S. Assistant Director for Export/Import & International
Safety 79/04/03 Ip

7901150792 Forward SA Program Engr Book 79050077/79-01 on 790226-026
No correspondence noted.
POTTS, G. B. Region 4, Dallas, Vendor Inspection Branch.
79/03/15 App.

7901150797 SA Program Engr Book 79050077/79-01 on 790226-026
No correspondence noted. Major areas inspected: implementation of
10CFR50 app 8 criteria, applicable codes & standards & actions on
previous loop flooding
ROSENBERG, W. W. HANCOCK, D. M. Region 4, Dallas, Vendor
Inspection Branch. 79/03/14 App.

7901150823 Supplemental answer by mail to first set of interrogatories.
Affidavit & Certificate of Due oath.
DOYLE, M. L. MULLIN, T. J. McCubben, Oglet, Deak & Swenson
LLC, H. L. Pacific Gas & Electric Co. 79/04/16 App.

7901150834 License for Air Products & Chemicals, Inc to export 100 g
of uranium to United Kingdom.
OPLINGER, D. S. Assistant Director for Export/Import & International
Safety 79/04/27. App.

7901150857 Executive Branch position re Edw Ind Co application for
license to export 240 g U-235 to United Kingdom re
restriction into fuel assemblies for reload in Italy.
License should be granted LTR of assurance encl.
MORSE, L. V. State, Dept. of Bureau of Ocean & Internal, Environ.
& Scientific Affairs. 79/04/24. App.

7901150868 Responds to 790323 request. Provides comments &
recommendations re proposed revision of Reg Guide 1.08.
Statements conflict re length of time that equipment must
function safely
WOLFE, R. Assistant Director for Systems & Projects. 79/04/09
App

7901150881 License for Teledyne Mah Chem Albany to export 15,000 lb
of Uranium to Canada.
OPLINGER, D. S. Assistant Director for Export/Import & International
Safety 79/04/27. Ip.

7901150883 License for Bigen Chemical Co to export 2 lb heavy water
to Belgium.
OPLINGER, D. S. Assistant Director for Export/Import & International
Safety 79/04/27. App.

7901150885 License for Transnuclear, Inc to export 340 kg U-235 to
Belgium.
OPLINGER, D. S. Assistant Director for Export/Import & International
Safety 79/04/27. App

7901160105 Comments on 790306 request for transmission of info to ALB
re reactor inspector's concerns about B&B plants
B&B, H. M. Office of the Executive Legal Director. 79/03/29 App

7901160109 Forward procedures for notifying ALB, ASL&B & NRC of new
info
B&B, H. M. Office of the Executive Legal Director 79/07/12
App

7901160209 Executive Branch position re Eberline Instrument Corp
application for license to export SI & microprobe Pu-239 to
Israel.
MORSE, L. V. State, Dept. of Bureau of Ocean & Internal, Environ.
& Scientific Affairs 79/04/24 App

7901160204 Executive Branch position re Cordis Corp application for
license to export 40 g U-235 to Saudi Arabia & Jordan.
MORSE, L. V. State, Dept. of Bureau of Ocean & Internal, Environ.
& Scientific Affairs. 79/04/20 App

7901160205 Transcript of 790426 meeting of Subcommittee on License
Examination Repts in Washington DC Pg 1-242
ROSLER, D. W. ELLERINGTON, R. R. J. J. AGS - Advisory Committee on
Nuclear Safety. 79/04/26. 244pp.

7901160275 Responds to 790307 request for addl info re "Evaluation of
Transient Behavior & Small RCS Breaks in 177 Fuel Assembly
Plant." Forwards ref mail & addl info re App 2.
TAYLOR, H. H. Babcock & Wilcox Co. 79/05/10. App.

7901160279 Responds to NRC request for addl info re small break
analysis in "Evaluation of Transient Behavior & Small
RCS Breaks in 177 Fuel Assembly Plant." Forwards requested
analysis.
TAYLOR, H. H. Babcock & Wilcox Co. 79/05/12. 44pp.

7901160289 Responds to NRC request for info on B&B 790307 reft re
"Evaluation of Transient Behavior & Small RCS Breaks in 177
Fuel Assembly Plant." Discusses pump status, operating limits
& position on pump integrity
TAYLOR, H. H. Babcock & Wilcox Co. 79/05/10 App.

7901160293 Submits schedule for completion of generic licensing topical
rept in response to NRC 790426 request.
CHASMAN, M. S. Sargent, Inc (subs. of Fermat International, Inc.)
79/03/11. Ip.

7901160441 Comments on NUREG-0221, "Investigation & Evaluation of
Stress Corrosion Cracking in Piping at LWR Plants." more
detailed recommendations for inspection loop being prepared.
Requests addl info
GRUBBS, R. L. General Electric Co. Nuclear Energy Products Div.
NEH-130-79. 79/03/04. App

7901160277 Forward "Upward Fire Propagation in Vertical Cable Tray
Fire Propagation Over Central Thermally Thin Cables" &
"Fire Resistance of Cable Penetration Seals/Theory for
Radially Isothermal Cables."
FEIT, R. Division of Reactor Safety Research 79/04/12. App

7901160279 TR-93
"Upward Fire Propagation in Vertical Cable Tray/Fire
Propagation Over Central Thermally Thin Cables."
HARTER, L. M. Johns Hopkins Univ. 79/03/12. 10pp

7901160280 TR-93
"Fire Resistance of Cable Penetration Seals/Theory for
Radially Isothermal Cables."
HARTER, L. M. Johns Hopkins Univ. 79/03/09. App.

7901160286 Application by H&B, Inc for license to export bellows-sealed
instrument isolating valves to Canada.
LINSNER, T. P. H&B, Inc. 79/04/04. App.

7901160283 Application by H&B, Inc for license to export bellows-sealed
instrument isolating valves to Canada.
LINSNER, T. P. H&B, Inc. 79/04/04. App.

7901160285 Application by H&B, Inc for license to export bellows-sealed
slide pattern, exercising valves to Canada.
LINSNER, T. P. H&B, Inc. 79/04/04. App.

7901160287 Application by H&B, Inc for license to export bellows-sealed
valves, three valve manifolds & bellows-sealed instrument
isolating valves to Canada.
LINSNER, T. P. H&B, Inc. 79/04/04. App.

NONDOCKETED ITEMS

305

7905170073 Application by H&M, Inc. for license to export ball-valve valves, three valve manifolds, globe valves & instrument isolating valves to Canada.
LINDNER, T.P. H&M, Inc. 79/04/03 App.

7905170059 License contract codes/previous employee codes for previous installation equipment.
a Office of Inspection & Enforcement. 79/03/12. 1pp

7905170063 Response to 790513 for FORWARDS requested add info re electrical equipment qualifications.
ANDERSON, T.M. Westinghouse Electric Corp. MS-TNA-0029. 79/05/04 3pp

7905170064 Discussion response of TDA to radiation under specified conditions in response to NRC Request.
KOSKOFF, C.H. Commerce Dept. of National Bureau of Standards 79/04/20 1p

7905170065 Forwarded add requested info re small break ECCB Analysis.
ANDERSON, T.M. Westinghouse Electric Corp. MS-TNA-0029. 79/05/10 5pp.

7905170161 Forwarded "Evaluation of Transient Behavior & Small RCS Breaks in 177 Fuel Assembly Plant." Vol 1 & 12 App.
TAYLOR, J.H. Babcock & Wilcox Co. 79/05/07 2pp

--7905170164 "Evaluation of Transient Behavior & Small RCS Breaks in 177 Fuel Assembly Plant." Vol 1 & 12 App.
a Babcock & Wilcox Co. 79/05/07. 50pp

7905170200 Discussion organizational changes in 30 days which will be implemented during next revision to RMR 04 plan 80000.
KELLY, H.B. House & Hubler Engineering Corp. 79/05/09 2pp

7905170094 Comments on NRC 329 Draft of May 1979; not accepted because of confusing language.
HARRISON, D.H. Office of the Executive Director for Operations 79/06/17 1p

7905170136 Forwarded "Mark-B2 Demonstration Assembly Licensing Rep." for Reactors & nonreactors versions Affidavit for withholding wact (ref 100572.790)
TAYLOR, J.H. Babcock & Wilcox Co. 79/05/03. 7pp

--7905170130 NAD-1000
"Mark-B2 Demonstration Assembly Licensing Rep."
nonreactor version
a Babcock & Wilcox Co. 79/04/03. 11pp.

7905170164 Response to 790504 for FORWARDS add info re reactor core response to excessive secondary steam release demands.
Questions will be answered by 790501.
ANDERSON, T.M. Westinghouse Electric Corp. MS-TNA-0029. 79/05/07 22pp.

7905170152 Forwarded "Mark I Containment Program Safety/Relief Valve Analysis." General For Use (Draft) Release Charge
Text 7.1.1.1. (draft) For Use (draft) (ref 100572.790)
GOSWAMI, J. General Electric Co. Nuclear Energy Products Div. MS-TNA-0029. 79/05/07. 14pp.

7905170164 FBR Amend 35 Incorporating changes to Section 13.3.
a Hanford Engineering Development Laboratory. HEDL-TS-75002-3 79/04/30. 60pp.

7905170184 Response FBR Amend 36: revision of Chapter 17 "FFTF Tech Specs." Does not constitute DOE technical approval for final design.
BARNES, L. Hanford Engineering Development Laboratory 02085 79/05/14 1p.

--7905170187 Revision of chapter 17 "FFTF Tech Specs." submitted as Amend 36 to FBR.
a Hanford Engineering Development Laboratory. HEDL-TS-75002-3 79/05/31. 07pp.

7905170232 Summary of "Decay Heat Removal During Small Break LOCA for BWR 2CR Fuel Assembly."
MICKELSON, C. Babcock & Wilcox Co. 79/01/31. 3pp

7905170023 Forwarded BN-TOP-4 Revision 1, "Subcomponent Pressure & Temp Transient Analysis."
JACO, J.C. Becthal Power Corp. (subs. of Becthal Corp. 1). 79/05/10. 1pp.

--7905170024 BN-TOP-4
"Subcomponent Pressure & Temp Transient Analysis."
a Becthal Power Corp. (subs. of Becthal Corp. 1) 77/10/25. 00pp.

7905170034 Comments re proposed rule 10CFR19 & 20 reports w/ proposed regulation. License Requirements that NRC Form-4 be submitted for license application.
a Office of International Programs 79/05/12 3pp

7905170043 Research Note Ltr 49 in vitro dissolution of U product results from four U mills.
LAVINE, B. Office of Nuclear Regulatory Research. LF-59. 79/04/04 3pp

7905170081 RCR-79-024
Analysis of NRC review of proposed issuance of license to Union Nuclear Co. Inc. to import 40,000g U-235 from Russia.
Recommendation license be issued.
MORAN, R. Office of International Programs 79/04/12 3pp

--7905170080 License for Union Nuclear Co. Inc. to import 40,000 g enriched to max of 3.3 in U-235 isotopic as U hexafluoride.
DILINGER, D.C. Assistant Director for Export/Import & International Safeguards 79/05/23 2pp

7905170056 Provides further response to 30 (and 790505) ltr requesting documents re NRC-79-007 & 30 SAR pipe cracking problems occurring since 1975 Forwarded xillographs of available documents.
FELTON, J.H. Division of Rules and Records. 79/04/10 3pp

7905170077 Transcript of 790502 briefing on steam generator denting & replacement held in Washington, DC Pg 1-69.
HARRISON, D.H. & DILINGER, D.C. 790507-R T. Commission 79/05/02 70pp

7905170089 Forwarded nonregulatory & proprietary versions of Amend 3-2P & 3P re CDMP-103 "Evaluation of Uncertainty in Nuclear Form Factor Measured by Self-Powered Fast Neutron Detector Sp." revised Chapter 4: error power calculation error.
a Consultant Engineering, Inc. 79/04/20 50pp

--7905170080 CDMP-103 3-2P
Nonregulatory version of Amend 3-2P re CDMP-103
"Evaluation of Uncertainty in Nuclear Form Factor Measured by Self-Powered Fast Neutron Detector Sp." revised Chapter 4: error power calculation error.
a Consultant Engineering, Inc. 79/04/20 50pp

7905170234 Forwarded Bupel 1 to Section 6 of "Evaluation of Transient Behavior & Small RCS Breaks in 177 Fuel Assembly Plant." and 790507
TAYLOR, J.H. Babcock & Wilcox Co. 79/05/12 1p

--7905170236 "Evaluation of Transient Behavior & Small RCS Breaks in 177 Fuel Assembly Plant." Vol 1: Section 6 & Bupel 1
a Babcock & Wilcox Co. 79/05/12 41pp

7905170208 Discussion Lighthill rule simplification & high heat transfer in LSCA model. Provides verified results demonstrating that current LSCA evaluation model is conservative in calculation of peak clad temp.
WISSEMEIER, A. General Electric Co. MS-TNA-0029. 79/05/02 11pp.

7905170240 Forwarded Bupel 1 to App 2: "Steam Generator Tube Thermal Stress Evaluation."
TAYLOR, J.H. Babcock & Wilcox Co. 79/05/10 1p

--7905170240 "Steam Generator Tube Thermal Stress Evaluation." Bupel 1 to App 2
a Babcock & Wilcox Co. 79/05/10 05pp

7905170242 Response to 16 Bulletin 79-044 re TMI Incident. Forwarded add wact to clarify position on Item 7 re operating procedures & Licensing Instructions.
ANDERSON, T.M. Westinghouse Electric Corp. MS-TNA-0027. 79/05/17 10pp.

7905170248 Requests Executive Branch position re Sigma Chemical Co application for license to export heavy water to Argentina.
DILINGER, D.C. Assistant Director for Export/Import & International Safeguards 79/04/03 1p.

7905170249 Requests Executive Branch position re Edline Intl Co application for license to export source wact to Brazil.
DILINGER, D.C. Assistant Director for Export/Import & International Safeguards 79/05/22 1p

7905170248 Forwarded distribution list for kinetic test interia data.
PICKER, L.H. Paul Behavior Branch 79/04/17 2pp.

NONDOCKETED ITEMS

- 790520048 Summary of 790501 meeting w/HC in Bethesda, MD re natural circulation in C-E operating reactors
* Reactor Systems Branch 79/05/01. 2pp
- 790520060 Details info re renewal of Licenses 579-579 Application to be filed 30 Sept before expiration date of existing license
LAWRENCE, S. L. Atomic Energy Commission (FPA 1975) 44/07/06. 1p
- 790520078 Rubels addl recommendations re mg procedure controls
Progeny relation measures conducted to assure sufficient radiation control. Emphasis results of survey conducted re radioactivity in controlled & uncontrolled areas
CARROLL, M. H. Fallowell Medical Mfg. Co., Inc. Fallowell-Testaver
Siv. 44/12/17. 2pp.
- 790520087 Requests extension from 441222 to 442222 of submission deadline for procedures of controlling spread of contamination.
CARROLL, M. H. Fallowell Medical Mfg. Co., Inc. Fallowell-Testaver
Siv. 44/11/04. 1p
- 790520088 Ack receipt of 490104 for notifying of license expiration
Permits application for renewal of Licenses 579-579
CARROLL, M. H. Fallowell Medical Mfg. Co., Inc. Fallowell-Testaver
Siv. 596. 56/08/07. 1p
- 790520097 Notifies what License 579-579 expires 480251.
MCGOWAN, J. E. Atomic Energy Commission (FPA 1975) 48/01/24. 1p
- 790520104 FOIA request for info re Thorcon, licensing, manufacturers & licenses.
FELDMAN, J. M. Feldman & Feldman. 79/04/26. 1p
- 790520174 Application by GE for license to export 296, 326 kg low enriched U oxide powder-enriched to max of 3.65 U-235 to Japan.
WILSON, D. B. General Electric Co. Atomic Energy Products Div
79/03. 79/04/23. 4pp.
- 790520188 Agenda for ACRS 790416-17 meeting w/HC & nuclear industry representatives in Washington DC to discuss 12 Bulletin 79-036, "Nuclear Incident at TH-1" & other related items.
* ACRS - Advisory Committee on Reactor Safeguards. 79/04/11. 3pp
- 790520201 Executive Branch position re Mitsubishi Travel Inc application for license to export 300,000,000 & parts for test reactors to Japan. License should be issued.
MCGOWAN, J. E. State, Dept. of Bureau of Oceanic & International Environ. & Scientific Affairs. 79/04/16. 3pp.
- 790520207a FOIA request for related documents on WASH-1400 & BECV-79-127, as identified in HQ Denon 790211 memo to LV
BENTLEY, Massachusetts, State of 79/04/10. 1p
- 790520400 Response to FOIA request for related documents on WASH-1400 & BECV-79-127. Forwarded 14 requested documents others not yet reviewed by HQ.
FELDMAN, J. M. Division of Rules and Records. 79/05/11. 2pp.
- Recomm review of draft liquid pathway generic study
1 to subject re WASH-1400. Contamination risks should be re-evaluated per recommended revisions.
Office of Nuclear Regulatory Research. 76/05/09. 1p
- 1/4s draft responses for SA Energy Resources
Development Commission in response to 760729
SCL
Probabilistic Analysis Branch 76/06/23. 12pp.
- Info on EPA draft publication concerning technical
protection methods to be used as basis for
laws for nuclear accident/transport in of little
value hypothetical conditions evaluated.
Office of Nuclear Regulatory Research. 76/10/07. 2pp
- Issue technical errors noted in Judge JE McMillen
proline Environ. Survey. Involves error in
interpretation of Levine's testimony & error in
the last paragraph by plants is significant.
Probabilistic Analysis Branch. 79/05/17. 4pp.
- Info on draft NUREG-0396, "Modified Planning Basis for
P. Phase & Local Area Radiological Emergency
in Support of LWRs;" use of 10-mils & 70-mils
radiol is excessive
Office of Nuclear Regulatory Research. 78/05/22. 2pp
- 790520442 Comments on sections of RBA draft environ statement re
disposal of Charleston Naval Auxiliary Landing Field
"hazards" should be referred to as "risks"
DARR, A. R. Probabilistic Analysis Branch 78/06/04. 2pp
- 790520460 Discusses review of ATWS suppl. NUREG-0461. ATWS is not
overcoming safety problem in plant design. ATWS risk
estimates cannot be substantially improved
BMA, A. R. Probabilistic Analysis Branch. 79/09/21. 2pp.
- 790520463 Forward comments on "Investigation of Probability of
Hypothetical Catastrophic Accidents in Oyster Creek Nuclear
Power Plant." by W. Davis upper bound estimate of protection
age failure probability is not justified
LWV, R. E. Office of Nuclear Regulatory Research 76/11/09. 10pp
- 790520468 BECV-79-024
Requests approval of NRC response to PIR0.4 application for
rulemaking to amend 10CFR100 re population density criteria
around nuclear reactor sites
NIMBLE, R. E. Office of Standards Development 79/12/04. 22pp
- 790520473 Comments on BECV-79-024, PIR0 petition for rulemaking on
population density around reactor sites. Proposed response by
NRC is deficient.
POCROSS, R. E. Office of Policy Evaluations. HOLLEY, J. L. Office
of the General Counsel 79/01/04. 11pp.
- 790520475 Informs that NRC will seek recommendation of Biting
Policy Test Force before taking action on BECV-79-024.
CHALK, E. J. Office of the Secretary of the Commission. 79/01/04.
1p.
- 790520484 Requests progress briefing by Biting Policy Test Force re
work status, problems & principal issues receiving test
force attention. Comments on role of certain concepts in
policy for site evaluation.
CHALK, E. J. Office of the Secretary of the Commission. 79/01/05.
1p
- 790520494 Comments on BECV-79-024, PIR0 petition for rulemaking on
population density around reactor sites. NRC should not
respond to petition until further info is received. Agree
w/request for test force briefing.
MAGNUS, J. F. Commission 79/01/09. 1p
- 790520497 Comments on BECV-79-024, PIR0 petition for rulemaking on
population density around reactor sites. Commissioner Ahearne
believes test force should be informed of specific questions
re petition or proposed response.
CHALK, E. J. Office of the Secretary of the Commission. 79/01/11.
1p.
- 790520713 Comments on BECV-79-024, PIR0 petition for rulemaking on
population density around reactor sites. ST. Hannan's proposed
response to petition is acceptable
SHAFER, H. A. Office of the Executive Legal Director. 79/05/11.
2p.
- 790520800 Proposed Reg Guide 1.3, "Assumptions Used for Evaluating
Light Water Power Reactor Siting Distances for Purposes of
10CFR100."
* Office of Standards Development 78/12/31. 13pp.
- 790520801 Proposed Reg Guide 1.4 "Assumptions Used for Evaluating
Potential Radiological Consequences to Public from Design
Basis Accidents in LWRs for Purposes of 10CFR100 & 51."
Proposed revision to 10CFR100 incl.
* Office of Standards Development. 78/12/31. 41pp.
- 790520904 Requests Executive Branch position re Note, Inc application
for license to export components to Argentina.
OPLIN, S. O. Assistant Director for Export/Import & International
Safeguards 79/04/26. 1p
- 790520902 Requests Executive Branch position re Transnuclear, Inc
application for license to export SSM to Denmark.
OGBRIEN, L. V. Office of the Executive Director for Operations.
79/04/26. 1p.
- 790520987 BECV-79-072
Informs Commissioners of receipt of withdrawal of 790408
license application by Beaminco, Inc to export 400 to
India.
OGBRIEN, L. V. Assistant Director for Export/Import & International
Safeguards. 79/04/17. 1p

--7903230603 Response to 790312 1st re application for license to export materials to India. Application forwarded 790323 to Executive Branch for review. License to be completed when application was completed in Dec 1979.
SHEA, J. M. Office of International Programs. 79/04/13. 1p

7903230641 Comments on proposed rulemaking 10CFR72 relating rules are adequate for protection of rights of parties and necessary to give finality to proceedings.
PORTER, M. L. Duke Power Co. 79/04/13. 2pp

7903230693 86CV-79-271
Provides background info re proposed issuance of license for GEIWA Intl Co. re import of 400000 U Free Japan Remittance License be granted
SHEA, J. M. Office of International Programs. 79/04/16. 3pp.

7903230699 Executive Branch position re Byron Jackson Power Pw application for license to export components & parts to Burkariand. License should be granted
ADDONALD, L. V. State, Dept. of Bureau of Ocean & Internal Environ. & Scientific Affairs. 79/04/24. 2pp.

7903230667 Requests license to import fuel assemblies being returned to US from Japan for reprocessing, on behalf of British Nuclear Fuels Ltd (Unigrip 1987 license and)
EILSON, J. Edison International Co. 79/02/07. 3pp.

7903230672 Agenda of 790300-10 287th ACRS meeting in Washington DC to discuss various ACRS repts re status of LMS genetic items & dynamic loads as design basis for nuclear facilities
W. ACRS - Advisory Committee on Reactor Safeguards. 79/03/28. 5pp

7903230673 Executive Branch position re Byron Jackson Power Pw application for license to export parts for use in reactor coolant pump to Italy. License should be granted
ADDONALD, L. V. State, Dept. of Bureau of Ocean & Internal Environ. & Scientific Affairs. 79/04/24. 2pp.

7903230677 Comments on proposed Reg Guide 1.23 guide is too specific & leaves no leeway for health physics to set health criteria of action guide aimed at procedures & not protection.
SHEA, J. M. Office of International Programs. 79/04/17. 3pp.

7903230691 Forwarded SA Program Item Sept 7903031079-01 on 790324-0002 & notice of violation
FOTARD, D. W. Region 4, Dallas. Vendor Inspection Branch. 79/03/15. 3pp.

--7903230687 Notice of deviation from loss on 790324-0002
Region 4, Dallas. Vendor Inspection Branch. 79/03/14. 1p

--7903230693 SA Program Item Sept 7903031079-01 on 790324-0002.
Noncompliance noted: released stress repts not reviewed by committed corrective action completion date
CONTELL, J. J. SHEA, J. M. Region 4, Dallas. Vendor Inspection Branch. 79/03/14. 1pp.

7903230697 Executive Branch position re SE application for license to export components & parts to Japan. License should be granted.
ADDONALD, L. V. State, Dept. of Bureau of Ocean & Internal Environ. & Scientific Affairs. 79/04/24. 2pp.

7903230606 Notification of current status of NRC-Fin re emergency response for transportation accidents involving radioactive materials
Great repts of NRC/DOE study of transportation hazards released for public comments which NRC must consider
MILBURN, R. J. Office of Standards Development. 79/04/17. 1p.

--7903230611 Forwarded NRC-Fin & AD public comments received for consideration in conjunction with rulemaking proceedings.
NRC and
SHEA, J. M. Assistant Director for Materials Safety Branch. 79/04/17. 1p.

7903230621 Amend 4 to License 1899-1410 for Transnuclear, Inc. attending expiration date from 790630 to 800430.
ADDONALD, L. V. Assistant Director for Export/Import & International Safeguards. 79/04/13. 1p.

7903230634 Provides NRC position re Exner Nuclear Co. Inc. Sept 1970 application to export 35,400 U to U. Belgian License should be granted based on Executive Branch position & use statement.
ADDONALD, L. V. Office of International Programs. 79/04/27. 1p.

7903230630 Notification of contract execution: "Two Phase Flow Aspects of Reactor Safety," awarded to Bernhardt College.
ADDONALD, L. V. Technical Assistance Contracts Branch. FIN 8-5328. NRC-03-79-102. 79/04/24. 1p.

--7903230647 Contract "Two Phase Flow Aspects of Reactor Safety," awarded to Bernhardt College.
ADDONALD, L. V. Division of Contracts. FIN 8-5328. NRC-03-79-102. 79/04/24. 1pp.

7903230648 Executive Branch position re SW Shattuck Chemical Co application for license to export 10 2 is depleted U-235
MILBURN, R. J. State, Dept. of Bureau of Ocean & Internal Environ. & Scientific Affairs. 79/04/25. 2pp.

7903230682 Notification of contract execution: "Assessment of Nuclear Environment" Impact on Environments - Contractor Univ of SA.
MILBURN, R. J. Research Contracts Branch. FIN 8-5479. NRC-04-79-222. 79/04/26. 1p.

--7903230646 NRC continuing funding & work on Test 2 to "Assessment of Nuclear Industrial Impact on Environments"
MILBURN, R. J. Research Contracts Branch. FIN 8-5479. NRC-04-79-222. 79/04/19. 1p.

7903230676 Notification of change in 790322 222 & 790301 139 to read "Variation of 'Uranium'"
MILBURN, R. J. General Electric Co. 79/03/20. 1p.

7903230677 Notification of contract execution: "Improvement of Laser Techniques for Analyzing Atmospheric Dispersion of Nuclear Power Plant Effluents" - Contractor Stanford Research
MILBURN, R. J. Research Contracts Branch. FIN 8-5479. NRC-04-79-222. 79/04/19. 1p.

--7903230678 NRC changing period of performance to 790430 at no cost to "Improvement of Laser Techniques for Analyzing Atmospheric Dispersion of Nuclear Power Plant Effluents"
MILBURN, R. J. Research Contracts Branch. FIN 8-5479. NRC-04-79-222. 79/04/23. 2pp.

7903230706 Executive Branch position re Bellow Intl Corp application for license to export 3,190 kg U-235 to Sweden. License should be granted for U. State, Dept. of Bureau of Ocean & Internal Environ. & Scientific Affairs. 79/03/01. 2pp.

7903230716 SHEA's NRC conclusions re Transnuclear, Inc. application for license to export 35,400 kg U to West Germany. License should be issued
MILBURN, R. J. Office of International Programs. 79/04/27. 1p.

7903230717 Notification of contract execution: "NRC Model Control Room Infiltration Program." - Contractor Dept of Commerce
MILBURN, R. J. Technical Assistance Contracts Branch. FIN 8-5328. NRC-03-79-102. 79/04/20. 1p.

--7903230720 NRC decreasing funding by \$40 47 to "NRC Model Control Room Infiltration Program"
ADDONALD, L. V. Division of Contracts. FIN 8-5328. NRC-04-79-222. 79/04/20. 1pp.

7903230721 Research Data for 1979: development of U product samples from four U mills. Forwarded JMS/DOE-0414 1/2 and
MILBURN, R. J. Office of Nuclear Regulatory Research. 79/04/04. 2pp.

7903230741 Forwarded USR petition requesting that NRC order immediate revocation of operating plants to determine whether
MILBURN, R. J. Sheela, Herman & Holman. 79/03/28. 2pp.

--7903230740 USR emergency petition for revocation of capacity of operating US nuclear power plants to withstand earthquakes
MILBURN, R. J. Sheela, Herman & Holman. 79/03/28. 1pp.

7903230741 Comments on proposed Reg Guide 1.14: flexibility provided by AMI 185.2, 13-17T is extremely beneficial in solving operation while still ensuring that grade of progress are achieved.
MILBURN, R. J. Customer Power Co. 79/03/20. 2pp.

7903230745 Agenda for 790307-09 224th ACRS meeting in Washington DC to discuss ACRS annual repts to Congress on NRC safety research program.
W. ACRS - Advisory Committee on Reactor Safeguards. 79/03/21. 3pp.

7903230773 Comments on proposed Reg Guide 1.23: "Functional Spec for Safety-related Valve Assembly in Nuclear Power Plants"
MILBURN, R. J. State, Dept. of Bureau of Ocean & Internal Environ. & Scientific Affairs. 79/04/12. 1p.

NONDOCKETED ITEMS

790520781 Confirms understandings re 781013 application for
license to export 110,530 lb Zinc-oxide-A tube shells to
West Germany. License action will be withheld pending
retransfer assurances from Iranian govt.
OPLINER, G O Assistant Director for Export/Import & International
Sanctions 79/04/13 Is

7905230787 Agenda of 790104-00 225th ACRR meeting in Washington, DC to discuss ATNR & reg guides
* ACRR - Advisory Committee on Reactor Safeguards. 79/12/23 Gpp

7905230700 "Sociometry & Electransport Models to Implement ALARA." quarterly progress rept; Oct-Dec 1978
MILLER, D O . KOCHER, D C Oak Ridge National Laboratory FTR
B-5150 ORNL/TM-80-12 75/12/22 4pp

7905230001 Reaffirms that O Helt is Plant Site Branch representative to follow safety aspects of qualification testing evaluation.
NTHLQ.V. Division of Operating Reactors 79/04/04 is

790523084 Requests plant shutdowns be scheduled to avoid blackouts.
Firm's production is directly dependent upon availability
of electric cooling systems
MAY, K H Affiliation Unknown 79/04/26 1p

7409230320 GEEH-79-142A
 Notice of NRC review of proposed Westinghouse license
 to import low enriched U from Sweden. Recommends license be
 issued
 BRDA, J.R. Office of International Programs, 79/04/02, 30p

INFORMS OF COMPLETION OF IRO REVIEW OF PROPOSED ASAND TO
Korean license to import partially completed fuel assemblies
from West Germany ASAND should be issued.
DREA-J.R. Office of International Programs 77/04/92. Sg

--PROCECORN2B Amend 1 to Korean Nuclear Co. Inc license to export increased quantity of U-235 to West Germany
OPLINSEN, G G Assistant Director for Export/Import & International Safeguards 29/01/02 Sp.

--705202024 License for Essen Nuclear Co. Inc to export 2.357 kg U-235
to West Germany
OPLINER.D.C Assistant Director for Export/Import &
International Safeguards 77/05/23 Rpp.

--PYO2303646: Amed 1 to Exxon Nuclear Co, Inc license to import increased amount of U from West Germany.
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 78/12/04 lpp.

7405220849 Forwards request for addl info re H090-21000, "Mark I
Long-Term Program Load Definition Rept"
#1080849JT,D C Division of Operating Systems, 79/05/03, See

7908260001 RECY-79-1008
Provides NBC relief of proposed Sequence of license to
Hirohichi Intl Corp to export source ash to Canada.
Requests Commissioner comments by 790330.
DRA,R. Office of International Programs. 79/03/30. 3pp

--7900845000 Forwards application for license to export source mail to
Eldorado Nuclear Ltd, Canada.
THOU, K Mitsubishi International Corp (subs. of Mitsubishi
Corp 3, NYC/NA-000, 78/09/34 Ig.

--900524000 Application For Mitsubishi Int'l Corp to export 338,311 kg U
enriched in 433,036 kg U-235 to Canada.
TSUTSUKI, K. Mitsubishi International Corp. (subs. of Mitsubishi
Corp.) HQA-5602-01. 7/03/14 2pg.

7906240021 HRC position re Transnuclear, Inc. application for license
 need to export low enriched U to Switzerland. License should
 be granted
 MOORE, R. M. Office of International Programs. 79/04/09. Is

7903240033 Forwards application for export license for minor nuclear
waste. List of references required. W/s encl.
CPL 28065, G. G. Assistant Director for Export/Import & International
 Safeguards 79/04/26, 1p.

PRC9945029 JAWED/CR-0040 VI HQ
"Civilian Contractor & Vendor Insp Status Rept." quarterly
rept.
* Office of Inspection & Enforcement, 78/04/30, 308pp. Available
at NTIS, \$12.50.

7703240028 HANDB-0040 V2 W1
 Licensee/Contractor & Vendor Reg. Status Rept. quarterly
 Post
 * Office of Inspection & Enforcement 79/02/01 100pg Available
 4x HT10 \$12.50

7903240001 NJR2-0040 V2 NK
"Licensee, Contractor & Vendor Insp Status Rpt." quarterly
rpt
* Office of Inspection & Enforcement 7/5/12/05. 237pp Available
as HTIS. 822 80

7908240039 NUREG-0040 V1 A2
"Licensee, Contractor & Vendor Insps Status Rpt," quarterly
Rpt
* Office of Inspection & Enforcement 78/03/35. 227pp. Available
as NTIS 87 50

7902240047 NUREG-0040 V1 A2
"Licensee, Contractor & Vendor Insp System Rept." quarterly
rept
* Office of Inspection & Enforcement. 77/12/30 204pp. Available
at NTIS \$7.50

7903240050 Requests Executive Branch position re Berg-Mannor Corp
application for license to export globe & chuck valves to
Belgium
DPL:INOR.d @ Assistant Director for Export/Import & International
Relationships 79/04/24 1p

7908260001 NUREG-0040-77/2
 "Licenses, Contractor & Vendor Insp System Rept." quarterly
 rept.
 * Office of Inspection & Enforcement. 77/Ga/30. 149pp. Availabl
 as NTIS. \$7.50

* Office of Inspection & Enforcement, 77/03/21 179pp. Available as HTF AIR 50.

* Office of Inspection & Enforcement, 740G/30 158pp. Available as NTIS. \$6.75.

7405240087 RECV-79-126A
Forwards background info re proposed issuance of license to
Elex Nuclear Co., Inc. to import low enriched U.License should
be granted.
SAC, J.R. Office of International Programs 79/04/02 Doc

4. Office of Inspection & Enforcement 74/03/35. 67pp. Available at NTIS \$4.95.

7901240063 NUREG-0640-03
"Licenses, Contractor & Vendor Inexp Status Rept." quarterly
rept
* Office of Inspection & Enforcement. 75/09/30. 144pp. Availabl
as DTIC \$4.00

T903540066 Confirms 790420 telcon informing that C/O of General Counsel will serve Executive Secretary of DOD & HK Shaper, NRC Executive Legal Director, re Meetinghouse application to export IBM Meetinghouse has been served.
ASHE, T R Asher, T. R. PC. 79/04/20. 1a.

7905240070 Agenda of 790405-07 1225th ACPS meeting w/NRC & DOE in Washington, DC to discuss various ACPS topics re generic items & selected reactions
* ACPS - Advisory Committee on Reactor Safeguards. 79/02/28 000

7902240002 Notification of 790501 meeting w/Exxon Nuclear Co to discuss
Exxon rod low assembl.
HARRON, J M. Operating Research Branch 3. 79/04/10. Geo

7905240503 Comments on 790116 ACNR meeting in Washington, DC: specs of SA code applications should be provided as fully & clearly as possible
MLT Y. Wt. T. Y. 79/05/16. See.

7903240107 Notification of contract execution, Mod 4 to "Antitrust Consultants." Contractor Charles River Associates
LEBO, C. B. Technical Assistance Contracts Branch FIN 8-3445 79/04/24. 1p

7903240111 Mod 4 decreasing amount obligated by 83,902.92 to "Antitrust Consultants"
O'DONNELL, S. J. Division of Contracts. FIN 8-3445 79/04/23 1p.

7903240112 "Acoustic Detection/Flow Relationships for Inservice Monitoring of Nuclear Pressure Vessels." Mar 1979 progress report re flow growth in ANS200 pressure vessel test.
HUTTING, P. L., SOHMER, E. S., KURTZ, R. J. Battelle Memorial Institute, Pacific Northwest Laboratory. FIN 3-2685. 79/04/17 11p.

7903240116 Application by Isotope Products Labs for license to export 100 Ci Cs-134 contained in ceramic disc to Canada
ARMSTRONG, K. Isotope Products Laboratories. HVO 4823 79/04/23 2pp

7903240118 Notification of contract execution "Computer Package for Bayesian Analysis of Attribute Data of Failures Prior to Distribution." awarded to RG State Univ
HARVEY, H. Research Contracts Branch. FIN 8-3455. NRC-04-79-182. 79/04/24. 1p

7903240122 Contract "Computer Package for Bayesian Analysis of Attribute Data of Failures Prior to Distribution." awarded to RG State Univ.
MORTON, K. V. Research Contracts Branch. PERRY, R. H. Kansas State Univ. FIN 8-3705. NRC-04-79-182. 79/04/17 4pp.

7903240119 Forwarded application for license to export movable isotope detector to Belgium
KEDNAR, R. P. Westinghouse Electric Corp. ICR-8056 79/04/19. 1p

7903240123 Application by Westinghouse for license to export one movable isotope detector containing 0.0041 g U-235 to Belgium
KEDNAR, R. P. Westinghouse Electric Corp. 79/04/20 1p.

7903240125 Requeste expiration date of license ICR-1452 be extended from 790500 to 030405.
HATFIELD, V. Transnuclear, Inc. 79/04/26. 1p.

7903240130 Summary of 790418 meeting w/SM in Bethesda, MD re natural circulation in BWR reactors
KOSSE, D. F. Division of Project Management 79/04/24 14pp

7903240147 OECD-79-240
Notifies NRC of receipt of British Embassy application for license to export source material to United Kingdom.
BIRN, J. R. Office of International Programs. 79/04/26 1p.

7903240155 Weekly info rept for week ending 790406.
SCOTT, T. A. Office of the Executive Director for Operations 79/04/11 56pp.

7903240158 Weekly info rept for week ending 790330.
SCOTT, T. A. Office of the Executive Director for Operations. 79/04/05. 21pp

7903240164 Forwarded RE Williams 790330 ltr re groundwater contamination at Galters site, Shullsburg 790218 memo re tailings (equipment) & SA Harko weapons.
KORONATH, E. J. M. 79/04/11. 1p.

7903240170 Suggests method for monitoring groundwater contamination at Galters site. Notes wells which should be used. Suggests location of another which should be drilled. Mentions substantial dam design.
WILLIAMS, R. E. Idaho Univ. of 79/03/28. 14pp

7903240173 OECD-79-249
Informs of receipt of license application from GE to export low enriched U oxide grade to Japan.
BIRN, J. R. Office of International Programs. 79/04/06. 1p

7903240202 Requeste comments re Nishinomiya American Corp. permit to export license application changing address of intermediate consignee.
KORONATH, E. J. Office of the Executive Director for Operations. 79/04/05. 1p.

7903240208 Transcription of 790310 1st 22th ACMR meeting in Washington, DC. Pg 1-1000.
CARPENA, K. H., PLEKSTET, R. S., BERNER, K. ACRR - Advisory Committee on Reactor Safeguards 79/03/10. 94pp

7903240204 Notification of 790306 presentation by Harry Diamond Lab to Qualification Testing Evaluation Research Review Group to discuss fluid development re nuclear plants
FETTER, Division of Reactor Safety Research 79/03/02 2pp

7903240201 OECD-79-238
Notifies NRC of receipt of Transnuclear, Inc. application for license to export highly enriched U to Sweden
BIRN, J. R. Office of International Programs. 79/04/12 1p

7903240202 Inform that Commissioners have reviewed License ICR-79004 of Exxon Nuclear Co. Inc. & accepted OECD-79-235 recommendation to award license to increase quantity of low enriched U to be imported from West Germany
CHILK, S. J. Office of the Secretary of the Commission 79/04/20 1p

7903240206 Research Info Ltr 48 Forwards NUREG-0362, "Tactical Overview of Nuclear Misconduct"
LEVINE, B. Office of Nuclear Regulatory Research 79/04/02 4pp

7903240206 NUREG-0362
Re "Tactical Overview of the Nuclear Misconduct"
HENDON, J., BRADLEY, L. W. Purdue Univ. NRC/LR-0-R Texas. Univ. of 77/11/20 104pp Available at NTIS 84 30

7903240200 "Fire Protection in Operating Nuclear Power Stations."
2nd Progress Report Unit 2 SSB review
MULLER, E. Brookhaven National Laboratory. FIN 8-3107 79/03/21 1pp

7903240202 Application by Wols-Inc for license to export nuclear components to South Korea
LINDNER, T. P. Wols, Inc. 1123 79/04/16. 3pp

7903240207 Requeste add info to complete review of 8978-1-0, "SA Program Description."
MAGUIRE, P. Quality Assurance Branch. NRC-1-0. 79/04/20 14pp

7903240204 "Environ Statements Project/Cost/Benefit Analysis Group." progress rept for Feb 1979
SCOTT, R. C. Oak Ridge National Laboratory. FIN 8-0411 79/03/22 3pp

7903240203 "BWR Shutdown/Emergency Core Cooling Program" monthly rept for Mar 1979.
BURNETT, S. A. General Electric Co. Nuclear Energy Products Div. NRC-04-79-215. 79/04/05 1pp

7903240206 Notifies that Commission has reviewed & accepted Transnuclear, Inc. license to export 4.33 kg U enriched to 90.25 U-235 to Canada (OECD-79-197).
CHILK, S. J. Office of the Secretary of the Commission 79/03/07 1p.

7903240207 Summary of 790425 meeting w/WH in TN re visit to facilities to acquire info for further development of fast breeds by Saville Labs.
HARRIS, G. J. Light Water Reactors Branch 1. 79/05/04 2pp.

7903240206 Informes that Commissioners have reviewed & accepted Transnuclear, Inc. license to export 3,900 kg U enriched to 90.25 U-235 from France (OECD-79-204).
CHILK, S. J. Office of the Secretary of the Commission. 79/03/07 1p

7903240207 NRC-79-2085
Informs Commission of receipt of GE 790412 application for license to export low enriched U to Japan
BIRN, J. R. Office of International Programs. 79/04/24. 1p

7903240207 Forwarded Status Resources 790418 rept to NRC 790303 request for info re tabulation of data & annotations re airborne emissions for Bakers W. site.
TOPP, A. A. New Mexico State of. 79/04/20 27pp.

7903240209 "LMR Thermal Hydraulic Development Program." monthly progress review & comment.
JONES, D. C. Brookhaven National Laboratory. FDE A-3045. 79/03/31 3pp.

7903240208 Forwarded NUREG-0211, Vol 1-2, "Draft OER on U Milling."
SCARABIA, R. A. Uranium Recovery Licensing Branch. 79/04/18. 1p

7903240406 NUREG-0211 Vol 1
"Draft OER on U Milling." Vol 1, summary & text
Office of Nuclear Material Safety & Safeguards 79/04/20. 34pp.

- 7903240403 MUREO-0811 U2
"Draft SEIB on U Milling." Vol 2, App
Office of Nuclear Material Safety & Safeguards 79/04/20
33pp.
- 7903240404 Forward state agencies' comments on MUREO-0499, "Preliminary Statement on General Policy for Licensing to Improve Nuclear Power Plant Licensing." Arizona, State of 79/02/12 8pp
- 7903240404 "Physical Protection of Nuclear Facilities." progress report for Feb 1979
CHPMAN, L. D. Sandia Laboratories FIN A-1060 79/03/16 4pp
- 7903240409 Notification of contract execution, Mod 3 to "Investigation of Use of Cyclic-Torsional Screw Plate Test to Determine Use of Liquidation Potential of Cobalt-60 in the Reactor Unit of IL
HAGUE, H. Research Contracts Branch. FIN D-0284 NRC-04-77-171 79/04/24 1p
- 7903240409 Mod 3, adding funds for second year of U-2 contract, to "Investigation of Use of Cyclic-Torsional Screw Plate Test to Determine Use of Liquidation Potential of Cobalt-60 in the Reactor Unit of IL
HAGUE, H. Research Contracts Branch. FIN D-0284 NRC-04-77-171. 79/04/24. 4pp
- 7903240410 Forward state agencies' comments on MUREO-0499, Suppl. 1, "Preliminary Statement on General Policy for Licensing to Improve Nuclear Power Plant Licensing." Arizona, State of 79/02/09 3pp
- 7903240415 "Thermal Hydraulic LMFBR Safety Experiments." monthly highlights for Mar 1979
JOHNS, D. C. Brookhaven National Laboratory FIN A-3024 79/03/21. 4pp
- 7903240417 Offers on comments on MUREO-0499, Suppl. 1, "Preliminary Statement on General Policy for Licensing to Improve Nuclear Power Plant Licensing." Michigan, State of 79/01/26. 1p.
- 7903240424 Offers on comments on MUREO-0499, "Preliminary Statement on General Policy for Licensing to Improve Nuclear Power Plant Licensing." Utah, State of 79/01/02 1p.
- 7903240427 "Short Ranged Oak Code Development & Validation." project highlights for Mar 1979.
HOFMAN, A. S. Brookhaven National Laboratory FIN A-3025-B 79/03/21 7pp.
- 7903240431 Executive Branch position re Canva Precision Engineering & Mfg Corp application for license to export 20,000 diamond incoated springs to India. License should be granted.
HOFMAN, A. S. State, Dept. of: Bureau of Oceanic & Internatl. Environ. & Scientific Affairs. 79/04/30. 4pp.
- 7903240433 Comments on proposed rule outlines biographical statements expiring nuclear plant sitting experience
HOFMAN, A. S. Ohio, State of 79/03/02 3pp.
- 7903240435 Teltell discussion of extension of interim fuel cycle rule through 790325. Under NRC request for meeting re "Statement of Consideration for U Fuel Cycle Rule" (RM 00-33) subsequently scheduled for 790302
GOLDS, E. J. Office of the Secretary of the Commission. 79/03/01. 1p.
- 7903240438 Offers on comments on MUREO-0499, "Preliminary Statement on General Policy for Licensing to Improve Nuclear Power Plant Licensing." Arizona, State of 79/03/06. 4pp.
- 7903240439 Notification of contract execution, Mod 3 to "Institutional Radiative Shielding." Contractor: Univ. of NY
HAGUE, H. Research Contracts Branch. FIN D-0590 NRC-04-78-344. 79/04/24. 1p.
- 7903240447 Mod 3, extending period of performance until 790430 to "Institutional Radiative Shielding." Contractor: Univ. of NY
HAGUE, H. Research Contracts Branch. FIN D-0590 NRC-04-78-344. 79/04/24. 1p.
- 7903240448 Requests 790324 FIN notice (Vol 430242). Pg 26379-21336 sent to parties listed.
LEWIS, M. Affiliation Unknown. 79/02/16. 3pp.
- 7903240450 Summary of 790423 meeting w/EC re natural circulation capabilities
THOMAS, A. C. Reactor Systems Branch. 79/03/02 4pp.
- 7903240454 Forward "Bapt on Analysis Methods for RCB Natural Circulation." TAYLOR, J. H. Babcock & Wilcox Co 79/03/18 1p
- 7903240459 "Best on Analysis Methods for RCB Natural Circulation." Babcock & Wilcox Co 79/03/18 3pp
- 7903240459 Notice of availability of MUREO-0811, "Draft SEIB on U Milling." EGARAND, R. A. Uranium Recovery Licensing Branch 79/04/16. 4pp
- 7903240459 "Advanced Reactor Safety Analysis Technical Assistance, Reactor Projects." monthly highlights for Mar 1979
BARR, R. A. Brookhaven National Laboratory. FIN A-3000 79/04/10 3pp.
- 7903240460 "Safeguards Analysis for Byproduct Heat & Small Quantities of ENR." monthly progress report for Mar 1979
CHAMBER, R. C., HARRISON, R. A., RAYMOND, M. L. Oak Ridge National Laboratory FIN D-0428 ORNL/MS-34. 79/04/09 5pp
- 7903240462 Forward list of documents on file in support of Gulf Taylor U mill license application
HAGUE, H. J. New Mexico, State of 79/04/28 4pp
- 7903240470 "First Quarter FTR Progress Report on Refill Effects Program." CHAMBER, R. C., ROTH, P. H., GARY, C. H. Crease, Inc. NRC-04-75-162 CREASE IN-292. 79/04/30 2pp
- 7903240470 "Physical Protection of Nuclear Plant in Transit Project." monthly report for Mar 1979
CHAMBER, L. D. Sandia Laboratories FIN A-1173 79/04/17 4pp.
- 7903240505 "Bapt on Foreign Travel of TB Haves to Karlsruhe, Germany & Saarbrücken, France." KREBS, T. B. Oak Ridge National Laboratory. FIN D-0121 ORNL/FTR-356. 79/04/19 37pp
- 7903240507 Application by Westinghouse for license to export reactor internal reactor control drive mechanisms components for reactor fuel chipping & discharging machines to Belgium & France
HOFMAN, A. S. Westinghouse Electric Corp. 108-8374 79/04/20 2pp
- 7903240509 "European Assessments of Fuel Cycle Facilities." monthly progress report for Mar 1979.
CHAMBER, R. C. Oak Ridge National Laboratory. FIN D-0479. ORNL/FTR-356 79/03/08. 4pp.
- 7903240517 Application by Westinghouse to amend license to export equipment, parts & components for nuclear reactors to Belgium & France
HOFMAN, A. S. Westinghouse Electric Corp. 108-8080. 79/04/24. 1p.
- 7903240507 "Evaluation of Socket Files of Terminated License." monthly progress report for Mar 1979.
CHAMBER, R. C. Oak Ridge National Laboratory. FIN A-0662-7. ORNL/MS-33. 79/03/31. 4pp.
- 7903240600 Notification of contract execution, Mod 3 to "Radiocell Extension & Land Form Mod in Surface Pathways." Contractor.
HAGUE, H. Research Contracts Branch. FIN D-0608 NRC-04-77-165 79/04/23. 1p.
- 7903240604 Mod 4, extending period of performance to 790331 at no cost to "Radiocell Extension & Land Form Mod in Surface Pathways." Contractor.
HAGUE, H. Research Contracts Branch. FIN D-0608 NRC-04-77-167 79/04/20. 2pp.
- 7903240676 Requests denial of UCB 77104 petition for emergency & remedial action & UCB 780500 petition for reconsideration of NRC 780108 memo & order.
EDWARDS, B. Yankee Atomic Electric Co. 79/05/16. 10pp.
- 7903240707 Notification of contract execution, Mod 3 to "Antitrust Hearings." Contractor: Charles River Associates, LLC, 2 B. Technical Assistance Contracts Branch. AT/49-241-0063 79/04/24. 1p.
- 7903240808 Mod 3, decreasing amount obligated for "Antitrust Hearings." Contractor: Charles River Associates, LLC, 2 B. Technical Assistance Contracts Branch. AT/49-241-0063. 79/04/30. 1p.

7903240020 Accepts recommendation for Dept of Army to export 250 kg depleted U to United Kingdom Requests notification of issuance & delivery of license to Dept of Army by 790307 CHEN, E. J. Office of the Secretary of the Commission. 79/03/01 Ip

7903240030 Requests Executive Branch position re TS Nuclear Use application for license to export 500 kg to Peru. OPLIN, G. O. Assistant Director for Export/Import & International Safeguards. 79/04/03 Ip

7903240043 Confirms 790425 action approving agreement between NRC & PRC for extension of time to file action to compel discovery to NRC first set of supplemental interrogatories. BARNES, J. L. Anti-Invest Division. 79/04/02 Ip.

7903240053 Executive Branch position re Byron Jackson Pump Dip application for license to export two rotating elements & two mechanical seal cartridges & accessories to Japan. License should be granted. ROSEN, D. L. V. State, Dept of. 79/03/02 Spp

7903240063 Executive Branch position re Spax Industries, Inc application for license to export 2 DMS-3 U-235, contained in 3 g U for use in mass spectrophotometric analysis to Japan. License should be granted. Japanese lit of assurance encl. ROSEN, D. L. V. State, Dept of. 79/03/02 Spp

7903240084 NUREG/CR-0795 "COMINT-1: Three-Dimensional Transient Single-Phase Component Computer Program for Thermal Hydraulic Analysis" Synthesizes exact computing NUREG/CR-0412 to NUREG/CR-0795. BIA, M. T., DONAHUE, H. M., SCHWITZ, R. C. Argonne National Laboratory. FIN A-2045 79/09/00 120pp

7903240085 Executive Branch position re GE application for license to export 25 kg U-235 contained in 11.958 kg U enriched to max of 2.1% to Japan. License should be granted. Japanese lit of assurance encl. ROSEN, D. L. V. State, Dept of. 79/03/02 Spp

7903240097 Executive Branch position re GE application for license to export over 10-yr period, specially designed or prepared reactor parts & components to Russia. License should be granted. ROSEN, D. L. V. State, Dept of. 79/03/02 Spp

7903240098 NUREG/CR-0486 "Survey of Postirradiation Heat Treatment as Means to Mitigate Radiation Embrittlement of Reactor Vessel Steels." HANCOCK, J. K. Navy, Dept of. Naval Research Laboratory. NRC-NEB-77-103. NRC Rept 6897. 79/02/14 Spp. Available as NTIS.

7903240077 Advises that addl eval to CDM-100-P re method for determining overall uncertainty in 308 operating margin is acceptable. Forwards revised evaluation. BIER, R. L. Light Water Reactors Branch 2. 79/04/05. 7pp.

7903240079 Notices of NRC position change re application of ANSI AS. 2.12, referenced in Reg Guide 1.123. Discusses current position & requests acceptance or alternative proposal within 30 days. HOWARD, M. P. Quality Assurance Branch. 79/05/02. Ip.

7903240090 Requests addl info to complete review of NRC-21821 & NRC-21821-23. BIRF Feasibility Study/Report. Final rept & BOP-1 respectively. STUBBINS, S. G. Division of Operating Reactors. 79/03/08 Spp.

7903240091 Forwards license application summary & refuels review submitted by Cotter Corp to OS Dept of Health, W & Encl. ROSEN, D. L. V. McCreath, E. J. 79/04/11. Ip.

7903240097 Lists licensees who received RE Bulletin 79-025. "Nuclear Incident at TRI-Suppl." Bulletin encl. PAPPAS, N. Region 3. Chicago. Office of the Director. 79/04/23 Spp.

7903250003 80CFR-79-183A Discusses NRC review of proposed issuance of export license to Mitsubishi Int'l Corp. SMCA, J. R. Office of International Programs. 79/04/02. App

7903250037 Application by Mitsubishi Int'l Corp for license to export 543 kg U-235, contained in 10.341 kg U, to Japan. TROTT, R. Mitsubishi International Corp. Tokyo of Mitsubishi Corp., 3300-1286, 78/05/25. Spp.

7903250041 Forwards application for license to export enriched U hexafluoride to Japan to be used for fabrication of fuel assemblies. MATAMORI, N. Mitsubishi International Corp. (subs of Mitsubishi Corp.). HMA-0478-08 79/04/29 Spp

7903250048 Forwards 790314 and use statement. MATAMORI, N. Mitsubishi International Corp. (subs of Mitsubishi Corp.). KMM-1286 79/03/19. Spp.

7903250054 Executive Branch position re Mitsubishi Int'l Corp application for license to export 543 kg U-235 to Japan. Japanese lit of assurance encl. ROSEN, D. L. V. State, Dept of. Bureau of Oceanic & International Environment & Scientific Affairs. KMM-1286 79/03/23 Spp.

7903250059 License for Mitsubishi Int'l Corp to export 543 kg U-235, contained in 10.341 kg U, to Japan. OPLIN, G. O. Assistant Director for Export/Import & International Safeguards. 79/04/02 Spp

7903250058 Response to 790325 lit re 10CFR20.308 & Meigs Retreat Farm. NRC is licensee by State of NC, not by NRC. Proposal to amend 10CFR20.304 presently under consideration. Would allow burial of radioactive soil w/NRC approval. KMM, R. G. Office of State Programs. 79/04/17. Ip

7903250055 Requests addl info & clarifications to complete evaluation of generic licensing. Typical rept 030-1. Requests schedule for responses as rept review schedule can be drawn up. SAEH, R. L. Light Water Reactors Branch 2. 79/04/23 Spp.

7903250053 Advises that Commissioners have approved proposed license by Transatomic, Inc to export 19.8 kg U enriched to 4.5% U-235 to Netherlands. Requests description of security measures. CHEN, E. J. Office of the Secretary of the Commission. 79/04/11. Ip

7903250049 Comments on proposed rule 10CFR20-20-Forwards talk presented at AEP 79/04/04 conference re regulation of radiation. Proposal would be very costly to implement. LEE, S. Commonwealth Edison Co. 79/04/06. Spp.

7903250056 Summary of ACSS Subcommittee on Procedures & Administration 790307 meeting in Washington, DC re work assignments of ACSS fellows & possible fellow appointments. Encl withheld (ref 10CFR2.792) & ACSS - Advisory Committee on Reactor Safeguards. 79/02/07 Spp

7903250052 Notification of 790301 meeting w/CC in Bethesda, MD to discuss plant transient responses & Nicholson rept. THASANI, C. Reactor Systems Branch. 79/04/26. Ip

7903250054 Summarizes ACSS 0038 Subcommittee 790319-20 meeting in Los Angeles. CA re old problem program. ZUBANE, Z. Franklin Institute Research Laboratory. 79/03/30 Spp.

7903250011 Evaluates Reactor 790304 mid-year review re upper head injection RELAP model development, statistical LOCA study, two-phase gas-steam explosion phenomena & molten core interactions. CATTON, J. California Univ. of Los Angeles. 79/03/22. App

7903250012 Notification of 790308 meeting w/CC in Bethesda, MD to discuss two loop test apparatus & model development. ROSEN, D. L. V. Analysis Branch. 79/04/26. Ip.

7903250014 Notification of contract execution. Ref 2 to "Review of Proposed Pile Foundations for Bell's Nuclear Generating Station." Contractor: HF Davison. PELLHAM, J. Purchasing Division. NRC-03-78-166. NRC-03-78-166 79/03/07. Ip

7903250012 New 3-standing period of performance to 790426 re "Review of Proposed Pile Foundations for Bell's Nuclear Generating Station." HARRITT, S. J. Division of Contracts. NRC-03-78-166. NRC-03-78-166. 79/04/11. Ip.

7903250018 Lit of assurance confirming final authorization for license to receive & process nuclear matl identified in application. Transfer will be sub to all conditions of 640008 agreement for cooperation between Switzerland & US. MULLER, R. E. Switzerland. ASI-513 000-NR/. 79/03/24. Ip.

- 7903250108 Reviewers LEAs letter operator training is needed. Discusses several incidents indicating operator problems & requests corrective follow-up repts covering noted LEAs.
CAITON, L. California, Univ. of. Los Angeles 79/04/17 3pp.
- 7903250109 Summary of 790303 meeting w/Black & Veatch Consulting Engineers in Kansas City, MO re hospital rext BVTM-10.
"On Progress Description"
EFRAIM, J. Quality Assurance Branch 79/04/27 2pp
- 7903250110 Requests comments on NUREG-2646 re operating experience of emergency mobile diesel generators at LWRs.
WASSERLIE, J. B. Assistant Director for Light Water Reactors 79/04/18 3pp.
- 7903250113 Comments on ACRS ECCO Subcommittee 790307-20 meeting re code work on transient two-phase flow. LST L2-2 test. SWR code upgrade test program. CRENS summer program & test problem program.
LACROIX, R. B. Battelle Memorial Institute, Pacific Northwest Laboratory 79/03/28 2pp
- 7903250119 Comments on Mark 5 owners group 790213 meeting re vent clearing & pool walk phase of suppression pool level definition study.
CAITON, L. California, Univ. of. Los Angeles 79/03/08 2pp.
- 7903250140 "Rept on Foreign Travel of 80 Eads Manager for Advanced Instrumentation for Reflood Studies Program"
GARD, S. D. Oak Ridge National Laboratory ORNL/PTR-381 79/04/20 5p
- 7903250144 Inform that IIR of assurance has been sent re Eberline Instrument Corp license to export 0.22 microgram Pu-239 to Austria.
"Austria" 79/04/13 1p
- 7903250147 Ack receipt of invitation to speak to Univ of VA Student Legal Forum. Request to give five minutes at UVA class.
HENDRICK, J. H. Commission 79/03/26 1p
- 7903250149 Extends invitation to speak at Student Legal Forum at Univ of VA School of Law.
HENDRICK, J. H. Virginia, Univ. of 79/04/12 1p
- 7903250159 Summary of 790308-10 22th ACRS meeting in Washington, DC re review of request for SL for Lower Nuclear Power Station Unit 1, International for resolution of ATRG re review of status of generic items relating to LWRs.
CARROLL, M. W. ACRS - Advisory Committee on Reactor Safeguards. 79/03/28 3pp.
- 7903250160 Ask 790301 IIR requesting joint hearing re license applications/concure w/suggestion. Both organizations have already developed procedures to be proposed to any joint hearing.
HENDRICK, J. H. Commission 79/04/24 1p.
- 7903250169 Progress joint hearing for consideration of issues over which NRC & NY State Public Use Commission have concurrent jurisdiction.
ZIELINSKI, G. A. New York, State of. 79/03/21 2pp.
- 7903250207 Notifies that NRC has not completed licensing action on application to export low enriched fuel to Japan. Favorable Executive Branch view received on 790307. Formal letters under review.
WHEA, J. R. Office of International Programs. 79/05/03 1p.
- 7903250214 "Crack Arrest Technology" monthly progress rept for Mar 1979.
BODENFELD, A. B. Battelle Memorial Institute, Columbus Laboratories 79-04-70-093-26. 79/04/11 3pp.
- 7903250224 Transcript corrections of 790219 hearing.
LINDER, H. Natural Resources Defense Council. 79/03/27 1p
- 7903250231 Notification of 790424 meeting w/EPRs & WEI re SE Bulletin 79-51.
JONES, E. L. Division of Reactor Operations Inspections. 79/04/19 2pp.
- 7903250232 License for Edlow Intl Co to import 110 kg U as irradiated RTN fuel elements.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 2pp
- 7903250233 License for Consolidated Controls Corp to export twenty 4.61 L21 resistance loss detectors to U.S.A.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards. 79/05/09 1pp
- 7903250237 License for Edlow Intl Co to export 36.198 kg U-235 contained in 41.750 kg U hexafluoride to Sweden.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards. 79/05/09 2pp
- 7903250244 EECU-79-208
Permits application Free Aerojet Ordnance Co to export source repts to Canada.
WHEA, J. R. Office of International Programs 79/04/16 1p
- 7903250270 Application for amend & renewal of license to export 100,000 kg U to Canada.
WHEA, J. R. Aerojet Ordnance Co 79/04/06 2pp.
- 7903250280 Application by Reactor-Stokes, Inc. for license to export Reactor-Stokes Model RS-C1-1210-125 compressed air blower to France.
GRAEF, J. D. Reactor-Stokes, Inc. U-0129 79/04/27 1p
- 7903250282 License for Hols, Inc. to export needle valves, ball-valve sealed instrument isolating valves, ball-valve sealed manually & pneumatically operated valves, bleed & drain valves & three valve manifolds to South Korea.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p
- 7903250276 License for Hols, Inc. to export ball-valve sealed instrument isolating valves to Korea.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p.
- 7903250289 License for Hols, Inc. to export ball-valve sealed manually & pneumatically operated valves, bleed & drain valves & three valve manifolds to Korea.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p.
- 7903250287 Amend 2 to License PU-3934, increasing quantity of repts to 125,000 kg U contained in 126,000 kg depleted U, for export to Canada.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p
- 7903250291 Amend 2 to License EPRM-0023, deleting Transnuclear as other party to export & substituting Nishinomiya Co., Ltd. for transport purposes only.
WHEA, J. R. Assistant Director for Export/Import & International Safeguards. 79/05/09 1p
- 7903250293 License for Hols, Inc. to export ball-valve sealed instrument isolating valves & three valve manifolds to South Korea.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards 79/05/09 1p.
- 7903250299 Notification of contract awarded: "Reactor Vessel Irradiation Damage," awarded to Naval Research Lab.
GLAZDOL, A. F. Technical Assistance Contracts Branch FIN 8-6804. 22-14-04-00-2. 79/04/02 1p.
- 7903250309 Update contract for "Reactor Vessel Irradiation Damage."
Extends period of performance & increases cost estimate.
DOUGHERTY, P. D. J. Technical Assistance Contracts Branch. FIN 8-6809. 22-14-04-00-29-143. 79/04/02 2pp.
- 7903250300 License for Hols, Inc. to export ball-valve sealed instrument isolating valves & three valve manifolds to South Korea.
OPLINGER, G. O. Assistant Director for Export/Import & International Safeguards. 79/05/09 1p.
- 7903250306 Application by Telega Products Lab for license to export 0.01 micrograms Cf-252 methionine source sealed in stainless steel capsule to Australia.
ALLAN, R. Telega Products Laboratories. 79/05/01 1p.
- 7903250312 Notice of shipment of 1 g Th-232, 0.6 g U-238 & 0.09 g Pu-237 to Russia between Jan & Oct 1979. Requests procedural instructions.
CHETTER, M. A. V. National Aeronautics & Space Admin. LR-235-3. 79/04/13 1p.
- 7903250321 Comments on W. R. 344, U.S. R. 2 & U.S. 1009 per request. Forwards comments on 0 2 which is similar to H. R. 2. Requests duplicative budget review and supports objectives of bill to eliminate overlapping federal programs.
HENDRICK, J. H. Commission. 79/03/16 2pp.
- 7903250326 Response to request for review of R. 2 bill passed by Senate on 7/6/01. Opports legislation to eliminate waste & duplication in federal govt. Questions effectiveness of 1981 bill. Requests for studies re to statutory limitations.
OTTENRE, C. Office of the General Counsel. 79/02/19 2pp.

- 7905250329 Forwards H.R. 544 to require authorization of new budget authority for gov't programs at least every five years & to establish criteria for zero-based budgeting. Requests: review & comments
BROOKS, J. House of Rep., Government Operations 79/01/29, 3pp
- 7905250336 Forwards H.R. 1039 to require authorization of new budget authority & review for gov't programs at least every five years. Requests: review & comments.
BROOKS, J. House of Rep., Government Operations 79/02/07, 32pp
- 7905250337 Forwards H.R. 919 requiring new budget authority & program review at least every ten years
BROOKS, J. House of Rep., Government Operations 79/03/24 36pp.
- 7905250338 Research Info Ltr 30 earthquake intensity scale, USGS should promulgate new intensity scale based on analysis described in ltr.
COMMISSIONER, Office of Nuclear Reactor Regulation HENDEGUE, B. Office of Standards Development 79/04/23 4pp.
- 7905250339 Authorizes issuance of licenses to follow Intl Co. for export of 61,750 kg U-enriched to 3,335 U-235 to Sweden
HODGINS, W. Office of International Programs 79/05/09 3p
- 7905250347 Application by Unipac Intl for license to export 960 kg depleted U to Korea
YOUNG, J. M. Unipac International 79/03/29 4pp.
- 7905250348 Advice that Commission has approved proposed license by Edson Intl Co. to import enriched U from Japan (USCIV-79-071). Requests notification of issuance & delivery of license to Edson by 790511
COLLINS, J. Office of the Secretary of the Commission 79/05/08 1p.
- 7905250349 Application by MELCO USA, INC. for license to export radiation detector to Japan
HARATANI, T. Melco U.S.A., Inc. 79/05/02, 4pp.
- 7905250354 Summary of NRC 790503 discussion in Washington, DC re D-3 reformulating.
CHILDS, R. J. Office of the Secretary of the Commission 79/05/04 1p
- 7905250358 Summary of 790425-30 meeting w/ABC in Argonne, IL re preparation of final OESB on handling & storage of spent LWR fuel.
ROBERTS, J. P. Fuel Reprocess & Recycle Branch 79/05/02 3p.
- 7905250361 Requests Executive Branch position re Washington application for license to export miscellaneous parts & components to Netherlands
OPININGER, G. S. Assistant Director for Export/Import & International Safeguards 79/05/09, 1p.
- 7905250376 Comments on proposed rule 100R19-02: rule does not allow flexibility provided by 50F-581 does averaging formula
HODGINS, W. Radiation Services, Inc. 79/03/14, 1p.
- 7905250379 Inform that conference w/consent will be held on 790518-17 re brief & responses filed by parties & objections to utility's fourth set of interrogatories & motions for protective order.
MILLER, M. E. Atomic Safety and Licensing Board Panel 79/04/17, 1p
- 7905250442 Executive Branch position re Hiroshima-Iwata American Corp application for license to export 6 AMB to U-235 to Japan
LORAN, J. State: Dept. of Energy & International Affairs 79/04/03, 2pp.
- 7905250444 Forwards comments received as of 790330 re NUREG-0396, "Planning Basis for Development of State & Local Civil Radiological Emergency Response Plans in Support of Light Water Nuclear Power Plants."
COLLINS, R. E. Assistant Director for Emergency Preparedness 79/04/05, 1p
- 7905250447 Notice of availability of NUREG-0396, rep of NRC/EPA Task Force on Emergency Planning.
RYAN, R. G. Office of State Programs 79/12/16 1p
- 7905250489 PC98-79137
Comments on NUREG-0396: emergency zone should be planned for small area around reactor. Once tested & perfected, zone could be expanded to appropriate size.
CLARK, P. Citizens for a Better Environment 79/03/29, 7pp.
- 7905250438 Comments on NUREG-0396. Lack of NRC functions against inadequate plans shows fundamental flaw. Reliance on NUREG-1420 is misplaced
ROSMAN, A. C. National Resources Defense Council 79/01/19, 3pp.
- 7905250440 Comments on NUREG-0396. Objects to absence of regulatory impact assessment & questions reliability of info used to support planning basis elements. Posing parameters on emergency planning time in planning process.
REED, C. Commonwealth Edison Co 79/03/26, 3pp
- 7905250442 Comments on NUREG-0396. emergency planning zones unnecessary & inappropriate. Regt is overly conservative & unrealistic. Implementation of Regt Plans will be very costly & lead to possible public misinformation.
MILNER, C. F. Georgia Power Co 79/03/26, 3pp
- 7905250444 Comments on NUREG-0396. 50-mile radius emergency plan is absurd. Regt not responsive to stable program directors' needs. Utility may be required to finance state emergency plans. Utility for realistic planning
PARKER, W. D. Duke Power Co 79/03/27, 2pp.
- 7905250447 Comments on NUREG-0396. planning for Class 9 actions is not justified. Questions validity of info supporting Regt. Implementation of emergency planning zones will be very costly.
ROSENBERG, D. L. Washington Public Power Supply System 79/03/28 3pp.
- 7905250449 Comments on NUREG-0396. planning for Class 9 accident is illogical. Regt lacks perspective on public risks & implementation costs & feasibility are exaggerated. Requests value impact assessment & withdrawal of Regt.
HARD, J. E. Atomic Industrial Forum 79/03/30, 3pp.
- 7905250450 Comments on NUREG-0396. Regt is premature & based on inadequate info. Issuing Regt could complicate licensing process. Planning for Class 9 events should be reconsidered.
WANDENBURG, G. Yankee Atomic Electric Co 79/03/28, 3pp
- 7905250474 Comments on NUREG-0396. potential exists for confusion re licensees' emergency planning obligations. Requests model clarification prior to NRC adoption of Regt.
DEIN, H. F. General Electric Nuclear Div. Aesir & Tall 79/03/30 7pp.
- 7905250478 Comments on NUREG-0396. Adoption of Regt could be very costly. Requests NRC provide adequate support in planning & implementation. Requests withdrawal & reconsideration of Regt.
BULL, W. M. T. J. Consumers Power Co 79/03/23, 2pp.
- 7905250491 Comments on NUREG-0396. present plans are adequate. Questions validity of emergency planning zones. Implementation would be very costly.
MAREN, G. V. Citrus County, FL 79/03/19, 4pp.
- 7905250493 Comments on NUREG-0396. suggests Regt be advisory only. Expanded emergency planning zones are excessive & burdensome. Five & twenty-mile radii zones are more reasonable.
TOLLE, J. Grundy County, IL 79/03/23 2pp.
- 7905250494 Comments on NUREG-0396. Regt could be helpful if used early in planning process. Use of Regt would lead to interjurisdictional planning & substantial costs.
HODGINS, A. T. Connecticut: State of 79/03/09, 1p.
- 7905250495 Comments on NUREG-0396. local govts offer more meaningful planning participation than other govts. Indiana Township, IN would like to participate in emergency planning discussions, but lacks funds. Inquires whether NRC can provide funds.
GRAY, R. CRAFTON, Indiana Township, IN 79/01/13, 1p.
- 7905250496 Comments on NUREG-0396. current emergency plans are adequate. Requesting standardizing approach. Requests Regt be withdrawn.
HODGINS, R. N. Kansas County, MO 79/03/06, 3pp.
- 7905250497 Comments on NUREG-0396. planning for Class 9 event is unnecessary. Questions validity of sustainability data.
HALL, R. S. Florida: State of 79/03/23, 3pp.

NONDOCKETED ITEMS

- 770220496 Forwards comments on NUREG-0396 planning based on Class V accident is not realistic. Emergency plan criteria should be consistent with licensing criteria. Ten & fifteen-mile radii should be eliminated.
LEHLE, L. Affiliation Unknown. 7/7/82/22 2pp
- 770220497 Civil Defense Sec has no comments on NUREG-0396.
BRYAN, H. Highland County, NC. 7/7/82/08 1p
- 770220500 Comments on NUREG-0396. Few county govt have expertise to prepare emergency plans. More guidance needed.
FARMER, D. R. Allen County, NC. 7/7/81/13 1p
- 770220502 Comments on NUREG-0396. local govt do not have expertise to understand or implement reqd. Rept provides no objective means to measure emergency.
WISSE, E. H. Gaston County, NC. 7/7/82/28 1p
- 770220503 Act receipt of NUREG-0396. Requests add info for preparing comments. Requests info on WASH-1400 reevaluation & its impact on NUREG-0396. Consideration schedule.
HARRIS, E. D. Affiliation Unknown. 7/7/81/29 1p
- 770220504 Comments on NUREG-0396. comprehensive emergency response plan already exists for CT. Rept does not address real health & safety needs of public. Suggest future inclusion of medical, meteorological & transportation aspects. In Repts.
HARRIS, J. P. Connecticut, State of. 7/7/81/08 2pp
- 770220505 Comments on NUREG-0396. cost effectiveness is not adequately treated in Rept. Comments from 7702203 Charlotteville Delap. Progress re. Louisiana County investigation of fallout facilities near North Anna plant.
MOSLEY, C. Virginia, Univ. of. 7/7/82/22 2pp
- 770220506 Comments on NUREG-0396. questionable reliance of Rept on WASH-1400. Rept should provide detailed description of worst case LCA. Should evaluation of event probability & suggest public evaluation drive.
JENSEN, H. M. California State Univ. of Sacramento. 7/7/82/24 2pp
- 770220507 Forwards summary of 770220 public hearing. No one present supported extension of plant 30-50 mile emergency planning zones to 10-50 mile radii proposed in NUREG-0396. County Commissioners oppose rule extension.
GIBBS, J. Citrus County, FL. 7/7/82/28 1p
- 770220508 Comments on NUREG-0396. request overview of SC Bureau of Radiological & Environ. Control. County is outside plans. Request pathway for accidents discovered. add cost for emergency planning.
KIND, R. B. Anderson County, NC. 7/7/81/12 1p
- 770220509 Comments on NUREG-0396. Rept is vague re level of planning required for emergency planning. Some more consideration should be given to Class 3-8 accidents.
HOGUE, T. C. South Carolina, State of. 7/7/81/15 1p
- 770220511 Comments on NUREG-0396. establishment of emergency planning zones at various distances from all facilities is inappropriate. Suggest zones be established as required for each facility.
WYTHE, J. Ltr commenting on draft NUREG-0396.
HARRIS, J. P. Pennsylvania, State of. 7/7/82/14 5pp
- 770220512 Comments on NUREG-0396. guidance useful, but expects considerable costs in implementing 50-mile emergency planning zones. Plant siting & emergency planning should be inseparable.
BROOKS, L. M. Arkansas, State of. 7/7/81/28 3pp
- 770220513 Comments on proposed amendments to 10CFR20. App. E proposal is unnecessary. Revisions rational for improving interior regulations. Amendments would be very costly. Requests defeat of proposal.
COMBELL, W. D. Northeast Utilities. 7/7/82/10 3pp
- 770220514 Comments on NUREG-0396. most local civil defense directors do not have expertise to understand Rept.
BLANK, J. Oconee County, NC. 7/7/81/15 1p
- 770220515 Comments on NUREG-0396. questions reft reliance on WASH-1400 & validity of emergency planning zones radii. Rept needs more work to be costly to implement.
JOHNSON, L. Virginia, State of. 7/7/82/21 2pp
- 770220516 States no comments should be made on NUREG-0396 until after Region 1 & State civil defense preparedness agencies conduct briefings & conferences w/ local representatives.
PRICE, W. H. Florence County, NC. 7/7/81/15 1p
- 770220517 Comments on NUREG-0396. criticism reft methodology for calculations of accident probabilities. Offers alternative. Funding not available for implementation of Rept.
PARKER, M. Oregon, State of. 7/7/82/08 2pp
- 770220521 Comments on NUREG-0396. expedited emergency planning zones not necessary & costly to implement. Suggests inclusion of guidance for local adjustments to zone radii.
BARNARD, M. H. Humboldt County, CA. 7/7/81/14 2pp
- 770220523 Comments on NUREG-0396. Rept implementation would be very costly. Overstates feasibility & legal basis. Rept lacks historical perspective & technical basis in using Class V accident as planning basis.
COMBELL, W. D. Northeast Utilities. 7/7/81/13 4pp
- 770220528 Comments on NUREG-0396. unilateral adoption of Rept methodology by NRC will probably not have desired results. Rept is good for bld consensus in absence of significant data to WASH-1400.
JONES, R. T. Office of State Programs. 7/7/82/25 4pp
- 770220542 Comments on NUREG-0396. revision is cosmetic in nature & provides comments will apply. Forwards 770220 comments on draft of same Rept.
HARRIS, J. P. Gilbert Associates, Inc. 7/7/82/23 1p
- 770220543 Forwards comments on Draft 2 of NUREG-0396. planning for Class V accidents is unnecessary. Suggests NRC use of WASH-1400. Questions appropriateness of dose calculation methodology. Rept will increase public confusion.
HARRIS, J. P. Gilbert Associates, Inc. 7/7/81/26 4pp
- 770220551 Forwards requested info: demographic statistics on reactor effects, an adequacy of census population distribution & meteorological transport used in reactor safety study & COLLINS, H. E. Assistant Director for Emergency Preparedness. 7/7/82/12 1p
- 770220572 Requests demographic info for use in preparing comments on NUREG-0396.
JONES, H. C. Virginia, Univ. of. 7/7/81/24 1p
- 770220580 Comments on NUREG-0396. requests info re relationship of Rept to existing safety analyses & administrative emergency plans. Suggests Rept be used guide for regulation.
HARRIS, H. E. Bechtel Power Corp. (subs. of Bechtel Corp.). 7/7/81/14 1p
- 770220584 Act receipt of 770114 ltr re NUREG-0396. Rept not intended as regulation. No relationship exists to past analyses performed on plant siting. Forwards NUREG-0396 & NUREG-770114. SAs and COLLINS, H. E. Assistant Director for Emergency Preparedness. 7/7/81/14 1p
- 770220587 Act receipt of 770223 ltr commenting on NUREG-0396. Clarifies concept of 30-mile emergency planning zone. Rept implementation should not present substantial costs. Objects to suggestion that planning be based on historical events.
HARRIS, H. E. Assistant Director for Emergency Preparedness. 7/7/82/26 2pp
- 770220590 Comments on NUREG-0396. would be very costly to implement. NRC should Rept the test. St. Louis County Commission voted to object to 50-mile concept at 770220 meeting.
HARRIS, H. E. St. Louis County, MO. 7/7/82/23 2pp
- 770220446 No comments on NUREG-0449. Dopl 1. "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing."
WALLACE, A. T. Iowa, State of. 7/7/81/19 1p
- 770220451 No comments on NUREG-0449. Dopl 1. "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing."
HARRARD, H. Delaware, State of. 7/7/82/06 1p
- 770220493 Requests info re NUREG-0449. "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing."
JOHNSON, J. H. Pennsylvania, State of. 7/7/82/01 1p
- 770220494 Comments on proposed rule 10CFR19-20. questions justification of expense of changing regulations which is currently acceptable. Suggests continuation of present regulations to protect populace from radiation.
SMITH, A. Your Heat Transfer Corp. 7/7/82/27 2pp

NONDOCKETED ITEMS

315

7902200497 Comments on NUREC-0499, "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing," new licensing for nuclear plants in public state utility are not requesting new plants
LEWIS, R. J. Affiliation Unknown. 79/01/31. 1p.

7902200463 No comments on proposed rule "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing" -
HILL, R. M. Nevada. State of. 79/02/26. 1p.

7902200460 Comments on proposed rule "Preliminary Statement on General Policy for Rulemaking to Improve Nuclear Power Plant Licensing" proposed project does not adversely affect state plans
DEGATEA, P. V. Kansas. State of. 79/02/12. 7pp.

7902200470 Comments on NUREC-0499, Reg. 1.7 nuclear plant licensing improvements as simple as possible.
VORNOSELO, J. Arizona. State of. 79/02/05. 11pp.

7902200483 Reg. Guide 3.11.1, "Operational Insp & Surveillance of Embankment Retention Sgs for W Hill Tailings."
C. Office of Standards Development. 79/04/20. 8pp.

7902200407 Comments on proposed Reg. Guide 7.9, various technical error. Fuel rods cannot contain anything within cladding. Guide should not be distributed.
LEWIS, R. J. Affiliation Unknown. 79/04/13. 1p.

7902200502 Forwards comments on NUREC-0394 emergency planning should be done by licensee prior to GL planning issues are adequate
CLACK, E. J. Georgia. State of. 79/02/21. 3pp.

7902200531 Comments on proposed Reg. Guide 1.2M, Revision 2, recommends clarification of term "safety-related." & believes Section C to be too restrictive.
VIOLETTE, J. B. Bechtel Power Corp. (subs of Bechtel Corp.). JAW-74-70. 79/03/20. 2pp.

7902200529 Forwards NRC determination statement re public withholding of transcript of 790220 discussion of personnel matter
CINUL, M. J. Office of the Secretary of the Commission. 79/05/08. 2pp.

7902200563 Forwards 790226 ltr & w/ statement from Radio-Chemical
LEWIS, R. J. Radio Chemical Co., Inc. 79/04/18. 3pp.

7902200508 Transcript of 790202 Affirmation Session 79-05 in
Washington, DC. 79-05.
HICKS, J. E. J. OILINREY, V. MEMPHIS, R. F. Commission. 79/05/02. 4pp.

7902200518 Response to 790407 ltr to JH Hendrix requesting info re operator license requirements Forwards Reg. Guide 1.134.
"Medical Evaluation of Nuclear Power Plant Personnel Requiring GL."
GUTH, R. G. Assistant Director for Light Water Reactors. 79/04/19. 1p.

--7902200518 Reg. Guide 1.134, Revision 1, "Medical Evaluation of Nuclear Power Plant Personnel Requiring Operator License."
C. Office of Standards Development. 79/05/31. 2pp.

--7902200524 Requests info on nuclear power plant personnel regulations on alcohol before & during duty
C. United Christian Action, Inc. 79/04/09. 1p.

7902200503 Comments on proposed rule 10CFR19 & 20, approve elimination of accumulated dose averaging formula.
HARDE, W. H. West Virginia. State of. 79/04/06. 1p.

7902200503 Comments on proposed rule 10CFR19 & 20, failure of individual to disclose exposure rules could endanger firm.
RECONRACK, J. B. Affiliation Unknown. 79/04/04. 1p.

7902200547 Comments on proposed rule 10CFR19 & 20, favors making S reactor dose limit for whole body exposure limit for calendar quarter should be abolished. Regulations should reflect most conservative aerial limits.
GALLAGHER, P. E. California. Univ. of. Santa Barbara. 79/04/04. 2pp.

7902200547 Lists northern CA electric capacity margins in event of shutdown of plant margins are insufficient to prevent customer load curtailment should added forced outage occur.
7902200529 Integrates to public utility commission.
BETMAN, R. P. Sacramento Municipal Utility District. 79/04/26. 2pp.

7902200505 Ack receipt of 790227 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept
7902200579-01
Region 4, Dallas. Vendor Inspection Branch. 79/04/23. 1p.

--7902200501 Response to NRC 790228 ltr re deviation noted in QA Program Insp Rept 7902200579-01
Corrective actions audit report
content will be added to checklist for internal audit prior to next scheduled internal audit
BARNES, J. General Electric Co. Nuclear Energy Products Div. 79/03/27. 2pp.

--7902200507 Forwards QA Program Insp Rept 7902200579-01 on 790205-09 & notice of deviation.
7902200579-01
Region 4, Dallas. Vendor Inspection Branch. 79/02/28. 2pp.

--7902200504 Notice of deviation from Insp on 790203-09.
C. Region 4, Dallas. Vendor Inspection Branch. 79/02/26. 2pp.

--7902200513 QA Program Insp Rept 7902200579-01 on 790203-09
Noncompliance action audit summary report did not mention audit team meetings did not identify checklist used & did not list personnel contacted during audit
DORR, L. J. & BROWN, E. L. WOLCIC, J. Region 4, Dallas. Vendor Inspection Branch. 79/03/26. 2pp.

7902200501 Forwards specific info re proposed and uses of tritium gas for export license submitted on 790213 M/s and
DILLARD, G. S. Assistant Director for Export/Import & International Safeguards. 79/04/06. 1p.

7902200507 Forwards Gulf Nuclear Inc. comment on proposed rule 10CFR19 & 20.
FEL, R. House of Rep. 79/04/18. 1p.

--7902200513 Comments on proposed rule 10CFR19 & 20, propose rule because on latitude allowed & wording indicates overcautions are deliberate
FELDER, E. J. Affiliation Unknown. 79/04/18. 2pp.

7902200518 Comments on proposed Reg. Guide 1.144.1.125 Revision 1 & 2
Revision 2 & 1.0 Revision 1.
SILVERMAN, J. E. Tennessee Valley Authority. 79/04/03. 8pp.

7902200518 Forwards export license application for Transnuclear, Inc. by expert G. B. to Canada.
WATSON, V. Transnuclear, Inc. 79/04/20. 1p.

--7902200512 Application by Transnuclear, Inc. for license to export 15 COB by U.S. Form U-225 submitted to export G. B. to Canada.
WATSON, V. Transnuclear, Inc. 79/04/20. 2pp.

7902200514 Comments on proposed Reg. Guide 1.144 suggests deletion of paragraph 3.04 guidance is provided in Reg. Guide 1.33.
SMITH, W. J. Connecticut Edison Co. of New York. 79/03/28. 3pp.

7902200517 License for Electric Instrument Corp. to export G. B. to Australia.
DILLARD, G. S. Assistant Director for Export/Import & International Safeguards. 79/04/23. 2pp.

7902200528 License for Edison Intl. Co. to export 600,000 G. B. to Switzerland.
DILLARD, G. S. Assistant Director for Export/Import & International Safeguards. 79/04/23. 1p.

7902200513 Defers RM Jordan's deposition served on 790228 until after 790318-17 prehearing conference.
HILLER, R. E. Atomic Safety and Licensing Board Panel. 79/04/03. 2p.

7902200513 License for Milwaukee Travel Bus to export miscellaneous specially designed or prepared parts & components for use in nuclear reactors to Japan.
DILLARD, G. S. Assistant Director for Export/Import & International Safeguards. 79/04/23. 1p.

7902200513 Applies for license to export reactor internals, reactor control drive mechanism, components for reactor fuel charging & discharging machines to Spain.
RENNAN, R. P. Westinghouse Electric Corp. 79/04/12. 2pp.

7902200518 Applies for license to increase enrichment in U-235 from 3.4 to 3.80 w/o ass.
DALLMAN, C. G. Westinghouse Electric Corp. 79/04/17. 1p.

NONDOCKETED ITEMS

7903290107 Application by Hiteville Travel Svc of America, Inc for license to export 20 pieces of motor having for EID SHM
Road to Japan
YAMAHA, Inc Hiteville Travel Service of America, Inc. 79/04/13. 2pp.

7903290141 Application by Eilow Int Co for license to export 2
amplifiers of SRM 4.333 Pw-242 to Sweden
HARRIS, D. Eilow International Co. 79/04/19. 2pp.

7903290148 Application by Air Products & Chemicals, Inc for license to
export 1,886 liters of acetone to England
HOWARD, D. Air Products & Chemicals, Inc. 79/04/17. 1p.

7903290181 Requests participation in rebuilding re radioactive exposure of workers
LEWIS, H. Environmental Coalition on Nuclear Power. 79/03/22. 1p.

7903290187 Requests that J. Johnson & C. Hapgood be granted
participation in rebuilding re radioactive exposure of
workers.
LEWIS, H. Environmental Coalition on Nuclear Power. 79/03/22. 1p.

7903290188 Advice of correction to Eilow Co application for license to
export source mail to Brazil mail is natural U & element
weight should read 711X
DILLINGER, D. Assistant Director for Export/Import & International
Nephegards. 79/04/25. 1p.

7903290190 Minute application by Nichol-Steel American Corp to amend
license by changing intermediate consignee
TRAVIS, S. Nichol-Steel American Corp. 79/04/20. 1p.

7903290231 Notification of contract execution, Red 10 to "Geologic &
Seismologic Review & Approval of Nuclear Facilities.
Miscellaneous Investigations & Technical Support."
Contractor: GE Dept of Technical
GLADIS, A. P. Technical Assistance Contracts Branch.
MNC-02-78-113. 79/04/24. 1p.

7903290242 Red 88, extending period of performance to 790320 who change
in such to "Geologic & Seismologic Review & Approval of
Nuclear Facilities, Miscellaneous Investigations & Technical
Support."
DOWNEY, D. J. Division of Contracts. MNC-02-78-113. 79/04/24.
1p.

7903290248 Application by Aerjet Ordnance Co to amend & renew license
to export 180,000 sq y of to Canada
BENNETT, H. Aerjet Ordnance Co. 79/04/04. 2pp.

7903290249 Forwarded NRC-21944-P-1/4 Scale Pressure Suppression Pool
Small Test Program/Plant Unload Test, "Unit 1-4 Affidavit
for withholding encl. Regs withheld (ref LCPH 7901.
RENNAL, J. General Electric Co., Nuclear Energy Products Div.
NRC-113-79. 79/04/24. 2pp.

7903290262 Transcript of 790308 meeting in Washington, DC P-1-200.
GILBERT, P. & G. GILBERT, P. AGS - Advisory Committee on
Nuclear Safeguards. 79/05/08. 20pp.

7903290348 Transcript of 790316 meeting in Bethesda, MD. P-1-2430-2640.
WILLIAMS, K. LUTON, C. WILSON, R. Atomic Safety and Licensing Board
Panel. 79/05/16. 20pp.

7903290361 Comments on proposed Reg Guide 1.8, paragraph C.1 to
enhance paragraph C.2 provides detailed description of
Nuclear Safety & Security statement is unsatisfactory
DERBY, M. B. Affiliation Unknown. 79/03/20. 2p.

7903290426 Suggests subsurface explorations in bedrock & soils to
find area stratigraphic & structural conditions prior to
conducting a new & affiliation detailed.
* Affiliation Unknown. 49/05/07. 2pp.

7903290421 Notification of contract execution, Red 2 to "Antitrust
Hearings Concerning Dues." Contractor: GE Dept of
Technical Assistance Contracts Branch. PIN B-1119.
AT149-241-0240. 79/04/20. 1p.

7903290436 Red 2, deobligating \$12,995.27 & closing out contract
"Antitrust Hearings Concerning Dues."
DOWNEY, D. J. Division of Contracts. PIN B-1119.
AT149-241-0240. 79/04/20. 1p.

7903290439 Forwarded memo of agreement between EPA Region II & NY State
Siting Board on Electric Generation Siting & Review, Regs
disables Siting Board authority to issue permits for major
steam electric generating stations.
GLADIS, J. H. New York State. 79/03/22. 2pp.

7903290445 Response to request for comments on Sunset bills, H.R. 2 &
H.R. 33 suggests plan to promote port efficiency by
eliminating overlapping Federal programs.
HODGINS, J. H. Committee. 79/03/16. 2pp.

7903290478 Forwarded H.R. 2 which would require budget authority & review
of port programs every 10 years, & H.R. 33 to improve
Congressional oversight of Federal programs Requests
response by 790329
SOLIM, E. House of Rep. Committee on Rules. 79/03/25. 105pp.

7903290491 "Dynamic Photoelastic Study of Crack Arrest." Monthly
progress report for Mar 1979
GALT, J. H. Maryland Univ. of NW-04-74-172. 79/04/09. 2pp.

7903290498 "Methods in Chemistry for Nuclear Regulation." Quarterly
progress report for Oct-Dec 1978
BERNARD, S. R. CRISTY, R. Ford, R. S. Oak Ridge National Laboratory
PIN B-0410-0. OML/NRCSD-22. 79/01/04. 4pp.

7903290523 Response proposed amend to regulations which would eliminate
accumulated dose averaging formula mentioned in encl
article: "Radiation Test Force Dept Force Hazards Regs Re
Greater than Previously Specified."
ELLIOT, J. G. Tennessee Valley Authority. 79/04/23. 2pp.

7903290529 Requests info re creating of NRC feedwater nozzle neckup &
development of improved ultrasonic testing procedures. Info
will be used to resolve generic feedwater nozzle inspection
issue
SHIELDS, R. P. Synthetic Evaluation Programs Branch. 79/04/16.
1p.

7903290573 Application by Air Products & Chemicals, Inc for license to
export 4.5 g of acetone to England.
DOWNEY, D. J. Air Products & Chemicals, Inc. 79/04/24. 2pp.

7903290579 Application by Westinghouse for license to export
mechanical inspection chambers to France.
DOWNEY, D. J. Westinghouse Electric Corp. 79/04/20. 1pp.

7903290589 Application by Air Products & Chemicals, Inc for license to
export 7.5 g of acetone to United Kingdom
ELLIOT, J. G. Air Products & Chemicals, Inc. 79/03/08. 1p.

7903290597 Notification of time change of 790501 meeting w/C-E in
Bethesda, MD to discuss plant transient responses &
Nichegards report
THOMAS, A. C. Reactor Systems Branch. 79/04/27. 1p.

7903290673 Progress report 18 for Mar 1979 on NRC-02-79-180 discussing
irradiation calculations & finances
PLATT, P. Michigan Univ. of NRC-02-79-180. 79/03/20. 10pp.

7903290678 NUREG/CR-0482
"Quarterly Progress Report on Fission Product Behavior in LWR
Area 0-1 to Sec IVB"
MILNER, R. A. P. Oak Ridge National Laboratory. PIN B-0127.
OPL/NRCSD/79-1. 79/04/20. 20pp. Available at NTIS.

7903290682 Response to 790426 1st to ME Danish requesting that 2-reg
technician training at Pacific County NJ Community College
be investigated.
DOWNEY, D. J. Assistant Director for Program Development. 79/05/11.
1p.

7903290686 Requests intervention in 2-reg technician training at
Pacific County NJ Community College, Forwarded 790426 &
790417 1st from NJ
PICKETT, J. F. Affiliation Unknown. 79/04/24. 2pp.

7903290684 Comments on proposed Reg Guide "Guide for Preparation of
Nuclear Safety & Security Statement" severely harmful
to small companies & too detailed. Notes that new rules not
in referenced documents.
GLENN, H. R. RISA Corp. 79/04/11. 2pp.

7903290692 Notification of contract execution: "SBA to Develop
Regulatory Framework for Nuclear Waste Mgt." awarded to
Nuclear Sciences Corp.
LEWIS, C. B. Technical Assistance Contracts Branch.
MNC-02-77-201-43. 79/04/24. 1p.

7903290694 Contract: "SBA to Develop Regulatory Framework for Nuclear
Waste Mgt." awarded to Nuclear Sciences Corp.
DOWNEY, D. J. Division of Contracts. MNC-02-77-201-43.
79/04/24. 1p.

NONDOCKETED ITEMS

317

7903000178 Notification of contract execution. "Contract of Nuclear & Fossil Fueled Power Plants," awarded to US Dept of Labor. OLAWALA, A. F. Technical Assistance Contracts Branch. FIN B-4540. NRC-03-79-129. 79/04/20. 1p.

7903000186 Contract. "Contract of Nuclear & Fossil Fueled Power Plants" awarded to Dept of Labor. OLAWALA, A. F. Technical Assistance Contracts Branch. FIN B-4540. NRC-03-79-129. 79/04/20. 4pp.

7903000187 Reactor Operator Training Programs Utilizing Nuclear Power Plants. COLLINS, P. F. Operator Licensing Branch. NO 16(4) VI 9. 79/05/23. 36pp.

7903000194 Notification of contract execution. Mod 2 to "Review of Proposed Pile Foundations for Bellingham Nuclear Generating Station." Contractor RT Division. PERLUM, J. Division of Contracts. NRC-03-79-166. 79/04/24. 1p.

7903000200 Mod 2, adding miscellaneous expenses to contract to "Review of Proposed Pile Foundations for Bellingham Nuclear Generating Station." COLLINS, D. J. Division of Contracts. NRC-03-79-166. 79/04/24. 1p.

7903000208 Notification of contract execution. Mod 2 to "Application of ILLAC IV TRS for Determining Helium Environment at Nuclear Power Plant." COLLINS, D. J. Technical Assistance Contracts Branch. FIN B-4540. NRC-03-79-162. 79/04/24. 1p.

7903000207 Mod 2, designating \$49,941.00, to "Application of ILLAC IV TRS for Determining Helium Environment at Nuclear Power Plant." COLLINS, D. J. Division of Contracts. FIN B-4540. NRC-03-79-162. 79/04/24. 2pp.

7903000207 Notification of contract execution. "BDA to Develop Regulatory Framework for Nuclear Waste Mgt." awarded to PUGCO, Inc. LEBOW, C. B. Technical Assistance Contracts Branch. NRC-03-79-261-04. 79/04/24. 1p.

7903000260 Contract. "BDA to Develop Regulatory Framework for Nuclear Waste Mgt." awarded to PUGCO, Inc. DOUMERTY, D. J. Division of Contracts. NRC-03-79-261-04. 79/04/24. 1p.

7903000269 Notification of contract execution. "Economic Consulting W/L Connection w/PL Power & Light Co's Application for License to Construct & Operate Unit 2 Nuclear Power Plant," awarded to J. Hoffman. OLAWALA, A. F. Technical Assistance Contracts Branch. FIN B-4503-9. NRC-03-79-147. 79/04/24. 1p.

7903000280 Contract. "Economic Consulting W/L Connection w/PL Power & Light Co's Application for License to Construct & Operate Unit 2 Nuclear Power Plant," awarded to J. Hoffman. DOUMERTY, D. J. Division of Contracts. FIN B-4503-9. NRC-03-79-147. 79/04/24. 4pp.

7903000278 "Licensing & Certification of Personnel at Nuclear Power Plants." Office of Nuclear Reactor Regulation. 79/05/22. 12pp.

7903000282 "NRC Examination Results Update, 1978-1978." App. A, 1978-74. Commission. 74/12/31. 14pp.

7903000288 Reactor Operator Training Programs Utilizing Nuclear Power Plant Simulators. COLLINS, P. F. Atomic Energy Commission. Structures of Licensing (AEC-1978). 74/12/31. 26pp.

7903000289 "License Examination Results Update, 1978-1978." MOULMAN, J. J. Operator Licensing Branch. 78/12/31. 27pp.

7903000290 Notification of contract execution. Mod 1 to "Electric Engineering Contract Assistance for South TE Antitrust Proceedings." Contractor RT Division. OLAWALA, A. F. Technical Assistance Contracts Branch. NRC-03-79-129. 79/04/24. 1p.

7903000297 Mod 1, extending period of performance to 790430 & changing principal engineer to "Electric Engineering Contract Assistance for South TE Antitrust Proceedings." DOUMERTY, D. J. Division of Contracts. NRC-03-79-129. 79/04/24. 2pp.

7903000298 NUREG-0860 "Safety Risk Assessment of Fossil Reactors in PWRs Designed by BWR." Office of Nuclear Reactor Regulation. 79/05/25. 280pp. Available at NTIS.

7903000302 Notification of contract execution. Mod 2 to "Safequards for High Level Waste Repositories." Contractor Science Applications. NRC-03-79-129. 79/04/24. 1p.

7903000308 Mod 2, changing key personnel to "Safequards for High Level Waste Repositories." DOUMERTY, D. J. Division of Contracts. FIN B-4576-9. NRC-03-79-035. 79/04/24. 1p.

7903000317 Response to DO Eisenhower 781020 for Buelala Info re safety analysis. Response in order to broaden scope of NRC approval of NRC-04011-P-A. "Nuclear Reactor Fuel Application." W/0 encl. NRC-03-79-129. 79/04/24. 1p.

7903000381 Forward application for export license. HANLEY, R. General Atomic Co. (subs of Gulf Oil Corp.). 3EL-1690. 79/04/24. 1p.

7903000386 Application by General Atomic Co. for license to export multi-stage pistonless linear power channels, wide range gas power electronic flow controller & variable trip module to Egypt. HANLEY, R. General Atomic Co. (subs of Gulf Oil Corp.). 79/04/24. 1p.

7903000392 Forward application for export license. HANLEY, R. General Atomic Co. 79/04/24. 1p.

7903000397 Application by HANLEY Research Corp. for license to export C-20 & P-20 enriched in P-235 sealed neutron source manufactured to Turkey. HANLEY, R. HANLEY Research Corp. 79/04/25. 1p.

7903000402 Forward minutes of Risk Assessment Review Group 780927-01 meeting. AUSTIN, J. H. Office of Policy Evaluations. 79/02/27. 1p.

7903000406 Summary of 780927-01 Risk Assessment Review Group meeting in Washington DC. FR 30316-attendance list & list of available documents. Office of Policy Evaluations. 79/02/27. 2pp.

7903000408 Response to 780904 FR notice requesting comments re agenda for meeting of Risk Assessment Review Group. Subsequent evaluation issues should be resolved. GARNETT, E. G. Affiliation Unknown. 78/08/13. 1p.

7903000409 Buelala preliminary info re natural circulation cooling at TDC-2. LAFLEUR, J. D. Office of International Programs. 79/04/28. 2pp.

7903000409 Buelala preliminary info which is subj to confirmation of regulatory action re BWR plants. LAFLEUR, J. D. Office of International Programs. 79/04/27. 2pp.

7903000463 Forward 3E Bulletin 79-008 re procedures & training for establishing & maintaining natural circulation & reactor vessel integrity at BWR plants. W/0 encl. LAFLEUR, J. D. Office of International Programs. 79/04/23. 1p.

7903000468 Forward responses to NRC questions re heat transfer & flow distribution aspects of revised flow blockage model. Requests approval of model for future licensing applications. GARNETT, E. G. C-E Power Systems. LD-78-000. 79/04/23. 14pp.

7903000469 Forward 3E Bulletin 79-004 79-004, 79-004 & 79-004 addressing aspects of TMI incident which apply to Westinghouse & C-E reactors. W/0 encl. LAFLEUR, J. D. Office of International Programs. 79/04/18. 1p.

7903000470 Buelala preliminary info on TMI incident. Further actions should be considered for all LWRs above pressure level. Indication problem may be generic in nature. LAFLEUR, J. D. Office of International Programs. 79/04/11. 2pp.

7903000474 Comments on training, examination & licensing program for plant operators. Program has serious flaws & needs prompt attention. NRC-03-79-129. 79/04/20. 7pp.

NONDOCKETED ITEMS

- 7903003275 Requests to FOIA 790403 & 0406 requests for transcripts of closed NRC meetings re TMI incident Describes process involved in obtaining info List of closed Commission meetings re TMI incident sent
PILTON, J. H. Division of Rules and Records. 79/09/03 App.
- 7903003083 FOIA request for transcripts of NRC meetings, public statements & internal memo re TMI incident.
ETHESZ, S. L. Massachusetts Institute of Technology 79/04/19 1p
- 7903003085 FOIA request for tapes of NRC meetings re TMI incident
ETHESZ, S. L. Massachusetts Institute of Technology 79/04/20 1p
- 7903003087 Requests to FOIA 790408 request & forwards WHM-1400 & WHM-1400, Levine rept & NRC 790318 policy statement
PILTON, J. H. Division of Rules and Records. 79/03/10 1p
- 7903003094 FOIA request for Rosenstien report WHM-1400
MAY, H. Affiliation Unknown 79/04/20 1p
- 7903003400 Forwards charter of Task Group on Generic Review of Power Reactors in BWR Designed Reactors.
GARR, E. D. Office of Nuclear Reactor Regulation. 79/04/02 App.
- 7903003414 Notification of contract execution, WHM 3 to "Modeling Bye for Piping Nuclear Power Plants," Contractor, US Naval Facilities Engineering Command.
MORSE, S. B. Technical Assistance Contracts Branch. PIN 8-8304 AT(49-24)-0122. 79/04/24. 1p.
- 7903003423 Ref 5 decreasing funds by \$10,000, 40 to "Hearing Bye for Piping Nuclear Power Plants"
DOUGHERTY, D. J. Division of Contracts. PIN 8-8304 AT(49-24)-0122 79/04/24 1p
- 7903003449 Comments on WHM-0501, insufficient justification for reclassifying recirculation-pump piping to nonconforming sub-remedial category
UTLEY, E. K. Carolina Power & Light Co. 00-79-0208 79/05/21 1p
- 7903003460 Forwards signed executive personnel delegation performance agreement in response to 790403 memo.
HENDRIE, J. H. Commission. 79/04/20. App.
- 7903003464 Extends gratitude for 790419 ltr re recommendations for improving regulatory process
HENDRIE, J. H. Commission 79/05/01 1p
- 7903003467 Forwards copy of ltr to President Carter & 790417 ltr to New York Times re recommendations for improving regulatory process
GUTHRIE, M. E. Meteorological Evaluation Services, Inc. 79/04/19 App.
- 7903003481 Responds to 790403 & 790504 request for meeting transcripts Explain status of classified & unclassified portions of transcripts, some of which will be made available following classification review
CHILDS, R. J. Office of the Secretary of the Commission. 79/05/14. 1p
- 7903003487 Requests disclosure of transcripts of listed NRC meetings re expert of nuclear reactors & mails Citan applicability portions of Sunshine Act
JACOBSON, T. J. Project for Open Government. 79/04/23. App.
- 1/26 NRC expert licensing authority ever situation which declined or prepared for nuclear facility to be licensed generic retransfer assurances
adding partners
79/05/21. App
- requirements for licensing expert of 2r in concerns of consultant that
79/04/02 1p
- Comments on freedom of info.
1/26 comment on first amendment to that comment
info rise to
- 7903003501 Requests explanation of meaning of statement made re negotiation to first amendment that 790301 press conference on PSEI/NEI/J. W. American Newspaper Publishers Association 79/04/17 1p
- 7903003532 Forwards "Evaluation of Effects of Corrosion Particles on Control Rod Drive Operation" Rept will assist in evaluation of SE proposal to delete control rod drive return line
MORSE, S. B. General Electric Co. Nuclear Energy Products Div. WHM-14-79 79/05/20 1p
- 7903003536 "Evaluation of Effects of Corrosion Particles on Control Rod Drive Operation"
General Electric Co. Nuclear Energy Products Div. 79/05/22 App
- 7903003538 Forwards rept. "Technical Description of Ring Vortex Heel, Mar 1978"
MORSE, S. B. General Electric Co. Nuclear Energy Products Div. WHM-14-79 79/05/22 1p
- 7903003540 "Technical Description of Ring Vortex Heel, Mar 1978"
MORSE, S. B. General Electric Co. Nuclear Energy Products Div. General Electric Co. 79/05/22 App
- 7903003542 Discusses meeting of Senate Bill 6, 562, NRC authorization for FY80, which excluded three of four NRC proposals Requests meeting to discuss how best to proceed
HENDRIE, J. H. Commission. 79/05/02 App
- 7903003543 Apologizes for use of term "blind man" in derogatory manner & describes it as "slip of tongue"
HENDRIE, J. H. Commission. 79/04/20 1p
- 7903003547 Protests ref to "blind man stumbling around making decisions" & requests more care to taken w/comments in future.
GUTHRIE, M. E. Affiliation Unknown. 79/04/10. 1p.
- 7903003548 Forwards summary of info which led to order to shut down five nuclear plants on 790318, Reviews NRC actions taken to expedite return to operation
HENDRIE, J. H. Commission. 79/05/02. App.
- 7903003572 Forwards prompt examination of independent evaluation which concludes that piping supports comply w/NRC stds. Critical energy evaluation exists in NRC. Urges immediate return of plant to full operation
MORSE, S. B. Maine, State of. 79/03/03 1p
- 7903003577 Extends gratitude for 790416 ltr & offer of assistance Requests to be informed of new developments re Energy Ctr concept. Will forward reasons to other Commissioners
HENDRIE, J. H. Commission 79/05/01. 1p.
- 7903003587 Offers personal adv to nuclear industry re areas of equipment design & design philosophy main: operational control & organization Suggests US adopt Energy Generation Ctr programs
STODOLKA, R. L. Affiliation Unknown. 79/04/16 App.
- 7903003596 Responds to President 790410 memo regarding 2x reduction in agency energy use, Supports reduction effort, NRC supplies information re: 2x goal has not met.
HENDRIE, J. H. Commission. 79/04/27. 1p
- 7903003606 Requests conservation efforts to decrease consumption by 2x & details specific actions to achieve goals. White House memo to 2x goal has not met.
HENDRIE, J. H. Commission. 79/04/27 App
- 7903003613 Ask receipt of 790321 ltr re fire protection, NRC will certify comments in the response to group 790302 petition.
CHILDS, R. J. Office of the Secretary of the Commission 79/05/03 1p.
- 7903003619 Asserts relative risk of serious reactor accidents from electrical cable fires is higher than from earthquakes. Cites NRC concerns re problem. Requests action be taken
POMER, S. P. Union of Concerned Scientists. 79/03/21. App
- 7903003632 Summary rept of 790319 meeting of ad-hoc working group in Washington, DC re fire protection
H. AOSB - Advisory Committee on Reactor Safeguards. 79/01/19 App.

NONDOCKETED ITEMS

319

790300040 Weekly Info rept for week ending 790403
 MEMO, T.A. Office of the Executive Director for Operations
 79/04/10 30pg

790300052 Explains misunderstanding arising from lack of details in
 790316 weekly info rept re PIP0078680 code error. Response to
 790322 ltr. Related FR notice encl.
 HENRIE, J.H. Commission 79/03/11 3pg

--790300067 Discusses differing impressions created by NRC testimony &
 790316 weekly info rept re PIP0078680 code error re
 "conservative" calculational technique.
 USAL, J.H. House of Rep. 79/03/02 3pg

790300072 Responds to 790219 ltr re proposed interim report of reactor
 components to Philippines under license XCOM-0013 Case under
 review. Repts on petition to consolidate application w/
 30-120 to be issued before final decision.
 HENDRIE, J.H. Commission 79/03/02 1pg

--790300077 Advises final Executive Branch recommendation on reactor
 export license application for Philippines plant is pending.
 Urges issuance of XCOM-0013 to avoid reactor coast damage.
 FICKERLING, T.H. State, Dept. of, Bureau of Ocean & Internatl.
 Environ. & Scientific Affairs. 79/02/19 3pg

790300078 Discusses support needed to implement Reg Guide 1.97:
 "Instrumentation of LWR Plants to Assess Plant Conditions
 During & Following Accident"
 LAING, G. Plant Systems Branch. 79/04/10 3pg

790300079 Concludes w/RD 1.140, Revision 1, "Design-Testing & Maint
 Criteria for Normal Ventilation Exhaust Dry Air Filtration &
 Adsorption Units of Light-Water Cooled Nuclear Power
 Plants"
 EMBOLD, H.H. ACNS - Advisory Committee on Reactor Safeguards.
 79/04/10 1pg

790300077 Certifies that 3041 g U-235 will be sub to all terms &
 conditions of 950720 dual agreement for cooperation & that
 EREN M.V. of Belgium is authorized consignee
 GOFEL, H. European Communities, Commission of. 79/03/07 1pg

790310019 "Nissan Generator Tube Integrity Program" progress rept for
 Mar 1977.
 CLARA, R.A. Battelle Memorial Institute, Pacific Northwest
 Laboratory. PIN 9-2097 79/04/11 3pg

790310047 Responds to 790404 ltr. Forwards list of documents placed in
 PDR M/O encl.
 FELDM, J.H. Division of Rules and Records 79/03/22 1pg

790310048 Forwards application by TX Nuclear Div for license to export
 1.76 mg Pu-238 to Holland
 HENRIE, J.H. Reactor Engineering Co. 79/04/25 1pg

--790310074 Application by TX Nuclear Div for license to export 1.76 mg
 Pu-238 to Holland
 HENRIE, J.H. Reactor Engineering Co. 79/04/25 1pg

790310081 Forwards magnetic tape of time histories used to generate
 cumulative damage function curves for NRCB applications
 presented in NRCB 245107. Index of contents, info re
 formatting & example printouts of time histories encl.
 SIBSON, J. General Electric Co., Nuclear Energy Products Div
 WPA-255-79 79/03/29 7pg


790310089 Requests proprietary computer program PDRB & NRCB-245077,
 "PIRB User Manual" did her 1979. Is withheld
 (ref 10078 7903 Affidavit encl)
 SIBSON, J. General Electric Co., Nuclear Energy Products Div
 WPA-255-79 79/03/22 3pg

790310093 Clarifies commitment contained in M Taylor 790428 ltr re
 schedule for developing auxiliary Feedwater control sys
 Independent of integrated control sys
 TAYLOR, J.H. Babcock & Wilcox Co. 79/03/22 3pg

790310097 Forwards Regg 3 to Vol 1, Section 4 of "Evaluation of
 Transient Behavior of Small RSB Breaks in 177 Fuel Assembly
 Plant" 44 790324.
 TAYLOR, J.H. Babcock & Wilcox Co. 79/03/24 1pg

--790310098 Regg 3 to Vol 1, Section 4 of "Evaluation of Transient
 Behavior of Small RSB Breaks in 177 Fuel Assembly Plant"
 Babcock & Wilcox Co. 79/03/24 3pg

790310095 Forwards affidavit supporting request for proprietary
 classification of 304-480, "Pressure Red Lg
 Effluence Test" 44 790301.
 TAYLOR, J.H. Babcock & Wilcox Co. 79/03/19 3pg



PERSONAL AUTHOR INDEX

ACCESSION NUMBER	DOCSET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCSET NUMBER	REPORT NUMBER
AMDE, H. H.	7705040268		AMDE, T. B.	7705040408		
AMDE, H. H.	7705040268		AMDELL, D. L.	7705110380	50-362	
AMDETT, J.	7705050034		AMDELL, D. L.	7705110384	50-362	
AMDETT, J.	7705050040	50-322	AMDELL, D. L.	7705110408	50-362	
AMDETT, J.	7705050547		AMDELL, D. L.	7705110428	50-362	
AMERMAN, K.	7704210177		AMERMAN, K.	7705110517	50-364	
AMERMAN, K.	7705110507	50-360	AMERMAN, K.	7705110524	50-366	
AMERMAN, K.	7705110540	50-360	AMERMAN, K.	7705110530	50-366	
AMERMAN, K.	7705050520		AMERMAN, K.	7705110534	50-366	
AMERMAN, M. E.	7705110541	50-320	AMERMAN, K.	7705110538	50-366	
AMERMAN, M. E.	7705050522		AMERMAN, K.	7705110540	50-366	
AMERMAN, M. E.	7705050527	7705040427	AMERMAN, K.	7705110542	50-366	
AMERMAN, M. E.	7705110544		AMERMAN, K.	7705110544	50-366	
AMERMAN, M. E.	7705110546		AMERMAN, K.	7705110546	50-366	
AMERMAN, M. E.	7705110548		AMERMAN, K.	7705110548	50-366	
AMERMAN, M. E.	7705110550		AMERMAN, K.	7705110550	50-366	
AMERMAN, M. E.	7705110552		AMERMAN, K.	7705110552	50-366	
AMERMAN, M. E.	7705110554		AMERMAN, K.	7705110554	50-366	
AMERMAN, M. E.	7705110556		AMERMAN, K.	7705110556	50-366	
AMERMAN, M. E.	7705110558		AMERMAN, K.	7705110558	50-366	
AMERMAN, M. E.	7705110560		AMERMAN, K.	7705110560	50-366	
AMERMAN, M. E.	7705110562		AMERMAN, K.	7705110562	50-366	
AMERMAN, M. E.	7705110564		AMERMAN, K.	7705110564	50-366	
AMERMAN, M. E.	7705110566		AMERMAN, K.	7705110566	50-366	
AMERMAN, M. E.	7705110568		AMERMAN, K.	7705110568	50-366	
AMERMAN, M. E.	7705110570		AMERMAN, K.	7705110570	50-366	
AMERMAN, M. E.	7705110572		AMERMAN, K.	7705110572	50-366	
AMERMAN, M. E.	7705110574		AMERMAN, K.	7705110574	50-366	
AMERMAN, M. E.	7705110576		AMERMAN, K.	7705110576	50-366	
AMERMAN, M. E.	7705110578		AMERMAN, K.	7705110578	50-366	
AMERMAN, M. E.	7705110580		AMERMAN, K.	7705110580	50-366	
AMERMAN, M. E.	7705110582		AMERMAN, K.	7705110582	50-366	
AMERMAN, M. E.	7705110584		AMERMAN, K.	7705110584	50-366	
AMERMAN, M. E.	7705110586		AMERMAN, K.	7705110586	50-366	
AMERMAN, M. E.	7705110588		AMERMAN, K.	7705110588	50-366	
AMERMAN, M. E.	7705110590		AMERMAN, K.	7705110590	50-366	
AMERMAN, M. E.	7705110592		AMERMAN, K.	7705110592	50-366	
AMERMAN, M. E.	7705110594		AMERMAN, K.	7705110594	50-366	
AMERMAN, M. E.	7705110596		AMERMAN, K.	7705110596	50-366	
AMERMAN, M. E.	7705110598		AMERMAN, K.	7705110598	50-366	
AMERMAN, M. E.	7705110600		AMERMAN, K.	7705110600	50-366	
AMERMAN, M. E.	7705110602		AMERMAN, K.	7705110602	50-366	
AMERMAN, M. E.	7705110604		AMERMAN, K.	7705110604	50-366	
AMERMAN, M. E.	7705110606		AMERMAN, K.	7705110606	50-366	
AMERMAN, M. E.	7705110608		AMERMAN, K.	7705110608	50-366	
AMERMAN, M. E.	7705110610		AMERMAN, K.	7705110610	50-366	
AMERMAN, M. E.	7705110612		AMERMAN, K.	7705110612	50-366	
AMERMAN, M. E.	7705110614		AMERMAN, K.	7705110614	50-366	
AMERMAN, M. E.	7705110616		AMERMAN, K.	7705110616	50-366	
AMERMAN, M. E.	7705110618		AMERMAN, K.	7705110618	50-366	
AMERMAN, M. E.	7705110620		AMERMAN, K.	7705110620	50-366	
AMERMAN, M. E.	7705110622		AMERMAN, K.	7705110622	50-366	
AMERMAN, M. E.	7705110624					

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
BARTON, C. A.	7903200324	50-338		BERNARD, R.	7903180220	50-320	
BARTON, C. A.	7903200073	50-339		BERNARD, R. H.	7903200411	50-320	
BARTON, C. A.	7903200093	50-340		BERMAN, W. L.	7903200167	50-320	
BARTON, C. A.	7903200147	50-348		BESID, U.	7903170292	40-1142	
BARTON, C. A.	7903007016	50-400		BESSETTE, D. E.	7903140011	50-306	
BARTON, C. A.	7903007025	50-400		BETH, R.	7903200437	50-311	
BARTON, C. A.	7903008041	50-350		BETTON, W. B. B.	7903200750	50-311	
BARTON, C. A.	7903009039	50-441		BETTON, P. A.	7903100149	50-384	
BARTON, C. A.	7903009377	50-441		BIVENS, R.	7903100349	50-384	
BARTON, C. A.	7903009147	50-491		BLOOM, J. H.	7903140049	50-320	
BARTON, C. A.	7903156485	50-580		BLOOM, L.	7903140179	50-450	
BARTON, C. A.	7903202413	50-580		BLOOM, L.	7903100030	50-320	
BARTON, C. A.	7903245638	50-198		BLOOM, L.	7903000296	50-320	
BARTON, C. A.	7903247003	50-100		BLOOM, L.	7903140143	50-320	
BARTON, C. A.	7903247038	50-491		BLOOM, L.	7903140144	50-320	
BARTON, C. A.	7903260193	50-491		BLOOM, L.	7903140188	50-320	
BARTON, C. A.	7903260079	50-491		BLOOM, L.	7903000255	50-320	
BARTON, C. A.	7903300152	50-480		BLOOM, L.	7903003329	50-343	
BARTON, C. A.	7903300399	50-488		BLOOM, L.	7903000312	50-485	
BARTON, C. A.	7903110014	50-339		BLOOM, L. A. F.	7903110054	50-339	
BARTON, C. A.	7903240384	50-339		BLOOM, L. A. F.	7903050189	50-334	
BARTON, C. A.	7903300140	50-255		BLOOM, L. A. F.	7903000322	50-339	
BARTON, C. A.	7903110021	50-448		BLOOM, L. A. F.	7903200371	50-018	
BARTON, H. C.	7903140424	50-387		BLOOM, L. A. F.	7903200365	50-453	
BAKIN, R. P.	7903140314	50-386		BLOOM, L. A. F.	7903200374	50-453	
BAKIN, R. P.	7903240373	50-258		BLOOM, L. A. F.	7903000138	50-320	
BAKIN, R. P.	7903210160	50-341		BLOOM, L. A. F.	7903200105	50-437	
BAKIN, R. P.	7903200048	50-341		BLOOM, L. A. F.	7903150789	50-399	
BAKIN, R. P.	7903140031	50-326		BLOOM, L. A. F.	7903150032	50-392	
BATES, A.	7903140034	50-326		BLOOM, L. A. F.	7903000437	50-349	
BATES, J. H.	7903000011	50-121		BLOOM, L. A. F.	7903150324	50-399	
BATES, J. H.	7903160129	50-320		BLOOM, L. A. F.	7903110087	50-339	
BATES, J. H.	7903160302	50-322		BLOOM, L. A. F.	7903200034	50-339	
BATES, J. H.	7903210107	50-320		BLOOM, L. A. F.	7903000099	50-135	
BATES, J. H.	7903000200	50-320		BLOOM, L. A. F.	7903200480	50-135	
BATES, J. H.	7903000492	50-277		BLOOM, L. A. F.	7903200278	50-135	
BATES, J. H.	7903000438	50-277		BLOOM, L. A. F.	7903150487	50-135	
BATES, J. H.	7903000482	50-284		BLOOM, L. A. F.	7903200095	50-135	
BATES, J. H.	7903000484	50-284		BLOOM, L. A. F.	7903000448	50-135	
BATES, J. H.	7903000339	50-280		BLOOM, L. A. F.	7903200514	50-135	
BATES, J. H.	7903100703	50-350		BLOOM, L. A. F.	7903200514	50-135	
BATES, J. H.	7903100799	50-350		BLOOM, L. A. F.	7903200514	50-135	
BATES, J. H.	7903240027	50-350		BLOOM, L. A. F.	7903200514	50-135	
BATES, J. H.	7903240027	50-350		BLOOM, L. A. F.	7903200514	50-135	
BATES, J. H.	7903240027	50-350		BLOOM, L. A. F.	7903200514	50-135	
BATES, J. H.	7903240027	50-350		BLOOM, L. A. F.	7903200514	50-135</	

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

326

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ORRICK, J. H.	7005010007	30-29		ORRICK, J. H.	7005010010	30-30	
ORRICK, J. H.	7005010010	30-30		ORRICK, J. H.	7005010011	30-31	
ORRICK, J. H.	7005010012	30-32		ORRICK, J. H.	7005010013	30-33	
ORRICK, J. H.	7005010014	30-34		ORRICK, J. H.	7005010015	30-35	
ORRICK, J. H.	7005010016	30-36		ORRICK, J. H.	7005010017	30-37	
ORRICK, J. H.	7005010018	30-38		ORRICK, J. H.	7005010019	30-39	
ORRICK, J. H.	7005010020	30-40		ORRICK, J. H.	7005010021	30-41	
ORRICK, J. H.	7005010022	30-42		ORRICK, J. H.	7005010023	30-43	
ORRICK, J. H.	7005010024	30-44		ORRICK, J. H.	7005010025	30-45	
ORRICK, J. H.	7005010026	30-46		ORRICK, J. H.	7005010027	30-47	
ORRICK, J. H.	7005010028	30-48		ORRICK, J. H.	7005010029	30-49	
ORRICK, J. H.	7005010030	30-50		ORRICK, J. H.	7005010031	30-51	
ORRICK, J. H.	7005010032	30-52		ORRICK, J. H.	7005010033	30-53	
ORRICK, J. H.	7005010034	30-54		ORRICK, J. H.	7005010035	30-55	
ORRICK, J. H.	7005010036	30-56		ORRICK, J. H.	7005010037	30-57	
ORRICK, J. H.	7005010038	30-58		ORRICK, J. H.	7005010039	30-59	
ORRICK, J. H.	7005010040	30-60		ORRICK, J. H.	7005010041	30-61	
ORRICK, J. H.	7005010042	30-62		ORRICK, J. H.	7005010043	30-63	
ORRICK, J. H.	7005010044	30-64		ORRICK, J. H.	7005010045	30-65	
ORRICK, J. H.	7005010046	30-66		ORRICK, J. H.	7005010047	30-67	
ORRICK, J. H.	7005010048	30-68		ORRICK, J. H.	7005010049	30-69	
ORRICK, J. H.	7005010050	30-70		ORRICK, J. H.	7005010051	30-71	
ORRICK, J. H.	7005010052	30-72		ORRICK, J. H.	7005010053	30-73	
ORRICK, J. H.	7005010054	30-74		ORRICK, J. H.	7005010055	30-75	
ORRICK, J. H.	7005010056	30-76		ORRICK, J. H.	7005010057	30-77	
ORRICK, J. H.	7005010058	30-78		ORRICK, J. H.	7005010059	30-79	
ORRICK, J. H.	7005010060	30-80		ORRICK, J. H.	7005010061	30-81	
ORRICK, J. H.	7005010062	30-82		ORRICK, J. H.	7005010063	30-83	
ORRICK, J. H.	7005010064	30-84		ORRICK, J. H.	7005010065	30-85	
ORRICK, J. H.	7005010066	30-86		ORRICK, J. H.	7005010067	30-87	
ORRICK, J. H.	7005010068	30-88		ORRICK, J. H.	7005010069	30-89	
ORRICK, J. H.	7005010070	30-90		ORRICK, J. H.	7005010071	30-91	
ORRICK, J. H.	7005010072	30-92		ORRICK, J. H.	7005010073	30-93	
ORRICK, J. H.	7005010074	30-94		ORRICK, J. H.	7005010075	30-95	
ORRICK, J. H.	7005010076	30-96		ORRICK, J. H.	7005010077	30-97	
ORRICK, J. H.	7005010078	30-98		ORRICK, J. H.	7005010079	30-99	
ORRICK, J. H.	7005010080	30-100		ORRICK, J. H.	7005010081	30-101	
ORRICK, J. H.	7005010082	30-102		ORRICK, J. H.	7005010083	30-103	
ORRICK, J. H.	7005010084	30-104		ORRICK, J. H.	7005010085	30-105	
ORRICK, J. H.	7005010086	30-106		ORRICK, J. H.	7005010087	30-107	
ORRICK, J. H.	7005010088	30-108		ORRICK, J. H.	7005010089	30-109	
ORRICK, J. H.	7005010090	30-110		ORRICK, J. H.	7005010091	30-111	
ORRICK, J. H.	7005010092	30-112		ORRICK, J. H.	7005010093	30-113	
ORRICK, J. H.	7005010094	30-114		ORRICK, J. H.	7005010095	30-115	
ORRICK, J. H.	7005010096	30-116		ORRICK, J. H.	7005010097	30-117	
ORRICK, J. H.	7005010098	30-118		ORRICK, J. H.	7005010099	30-119	

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
HENDERSON, J. H.	7700000024	50-320		HENDERSON, J. H.	7700210030	50-320	
HENDERSON, J. H.	7700110017	50-320		HENDERSON, J. C.	7700200437	50-289	
HENDERSON, J. H.	7700110020	50-320		HILL, R. H.	7700210019	50-320	
HENDERSON, J. H.	7700110044	50-320		HILLMAN, H. M.	7700110024	50-267	
HENDERSON, J. H.	7700200432	50-320		HILLMAN, H. M.	7700110023	50-267	
HENDERSON, J. H.	7700200792	50-320		HILLMAN, H. M.	7700110024	50-267	
HENDERSON, J. H.	7700200044	50-320		HINDLE, S. W.	7700200110	50-323	
HENDERSON, J. H.	7700310001	50-320		HINDLE, J. A.	7700110047	50-182	
HENDERSON, J. H.	7700311017	50-320		HINDLE, J. A.	7700110048	50-110	
HENDERSON, J. H.	7700310002	50-320		HINDLE, J. A.	7700110077	50-293	
HENDERSON, J. H.	7700314020	50-320		HINDLE, J. A.	7700110078	50-293	
HENDERSON, J. H.	7700300640	50-320		HINDLE, J. A.	7700110079	50-293	
HENDERSON, J. H.	7700300005	50-320		HINDLE, J. A.	7700200035	50-110	
HENDERSON, J. H.	7700310008	50-320		HINDLE, J. A.	7700200036	50-464	
HENDERSON, J. H.	7700310009	50-320		HINDLE, J. A.	7700200037	50-464	
HENDERSON, J. H.	7700310010	50-320		HINDLE, J. A.	7700200038	50-464	
HENDERSON, J. H.	7700310011	50-320		HINDLE, J. A.	7700200039	50-464	
HENDERSON, J. H.	7700310012	50-320		HINDLE, J. A.	7700200040	50-464	
HENDERSON, J. H.	7700310013	50-320		HINDLE, J. A.	7700200041	50-464	
HENDERSON, J. H.	7700310014	50-320		HINDLE, J. A.	7700200042	50-464	
HENDERSON, J. H.	7700310015	50-320		HINDLE, J. A.	7700200043	50-464	
HENDERSON, J. H.	7700310016	50-320		HINDLE, J. A.	7700200044	50-464	
HENDERSON, J. H.	7700310017	50-320		HINDLE, J. A.	7700200045	50-464	
HENDERSON, J. H.	7700310018	50-320		HINDLE, J. A.	7700200046	50-464	
HENDERSON, J. H.	7700310019	50-320		HINDLE, J. A.	7700200047	50-464	
HENDERSON, J. H.	7700310020	50-320		HINDLE, J. A.	7700200048	50-464	
HENDERSON, J. H.	7700310021	50-320		HINDLE, J. A.	7700200049	50-464	
HENDERSON, J. H.	7700310022	50-320		HINDLE, J. A.	7700200050	50-464	
HENDERSON, J. H.	7700310023	50-320		HINDLE, J. A.	7700200051	50-464	
HENDERSON, J. H.	7700310024	50-320		HINDLE, J. A.	7700200052	50-464	
HENDERSON, J. H.	7700310025	50-320		HINDLE, J. A.	7700200053	50-464	
HENDERSON, J. H.	7700310026	50-320		HINDLE, J. A.	7700200054	50-464	
HENDERSON, J. H.	7700310027	50-320		HINDLE, J. A.	7700200055	50-464	
HENDERSON, J. H.	7700310028	50-320		HINDLE, J. A.	7700200056	50-464	
HENDERSON, J. H.	7700310029	50-320		HINDLE, J. A.	7700200057	50-464	
HENDERSON, J. H.	7700310030	50-320		HINDLE, J. A.	7700200058	50-464	
HENDERSON, J. H.	7700310031	50-320		HINDLE, J. A.	7700200059	50-464	
HENDERSON, J. H.	7700310032	50-320		HINDLE, J. A.	7700200060	50-464	
HENDERSON, J. H.	7700310033	50-320		HINDLE, J. A.	7700200061	50-464	
HENDERSON, J. H.	7700310034	50-320		HINDLE, J. A.	7700200062	50-464	
HENDERSON, J. H.	7700310035	50-320		HINDLE, J. A.	7700200063	50-464	
HENDERSON, J. H.	7700310036	50-320		HINDLE, J. A.	7700200064	50-464	
HENDERSON, J. H.	7700310037	50-320		HINDLE, J. A.	7700200065	50-464	
HENDERSON, J. H.	7700310038	50-320		HINDLE, J. A.	7700200066	50-464	
HENDERSON, J. H.	7700310039	50-320		HINDLE, J. A.	7700200067	50-464	
HENDERSON, J. H.	7700310040	50-320		HINDLE, J. A.</			

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	DATE NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DATE NUMBER	REPORT NUMBER
BOZDAR, B	7905100200	50-300	334-HF-79-07	BRUCKER, R	7905070000	50-300	
BRADLEY, J. L.	7905060471	50-329		BRUCKER, W. C.	7905070519	50-320	
BRADLEY, L. E.	7905060426	50-320		BRUCKER, W. C.	7905070502	50-320	
BRADLEY, P. R.	7905060448	50-320		BRUCKER, W. C.	7905070503	50-320	
BRADLEY, H. J.	7905060560	50-320		BRUCKER, N. L.	7905100134	50-301	
BRADLEY, H. J.	7905060544	50-320		BRUCKER, N. L.	7905060102	50-320	
BRADLEY, H. J.	7905060548	50-320		BRUCKER, N. L.	7905060103	50-320	
BRADLEY, H. J.	7905060546	50-320		BRUCKER, N. L.	7905060107	50-320	
BRADLEY, H. J.	7905060543	50-320		BRUCKER, N. L.	7905060104	50-320	
BRADLEY, H. J.	7905060547	50-320		BRUCKER, N. L.	7905060105	50-320	
BRADLEY, H. J.	7905060548	50-200		BRUCKER, N. L.	7905060106	50-320	
BRADLEY, H. J.	7905060550	50-320		BRUCKER, N. L.	7905060107	50-320	
BRADLEY, H. J.	7905060549	50-320		BRUCKER, N. L.	7905060108	50-320	
BRADLEY, H. J.	7905060551	50-320		BRUCKER, N. L.	7905060109	50-320	
BRADLEY, H. J.	7905060552	50-320		BRUCKER, N. L.	7905060110	50-320	
BRADLEY, H. J.	7905060553	50-320		BRUCKER, N. L.	7905060111	50-320	
BRADLEY, H. J.	7905060554	50-320		BRUCKER, N. L.	7905060112	50-320	
BRADLEY, H. J.	7905060555	50-320		BRUCKER, N. L.	7905060113	50-320	
BRADLEY, H. J.	7905060556	50-320		BRUCKER, N. L.	7905060114	50-320	
BRADLEY, H. J.	7905060557	50-320		BRUCKER, N. L.	7905060115	50-320	
BRADLEY, H. J.	7905060558	50-320		BRUCKER, N. L.	7905060116	50-320	
BRADLEY, H. J.	7905060559	50-320		BRUCKER, N. L.	7905060117	50-320	
BRADLEY, H. J.	7905060560	50-320		BRUCKER, N. L.	7905060118	50-320	
BRADLEY, H. J.	7905060561	50-320		BRUCKER, N. L.	7905060119	50-320	
BRADLEY, H. J.	7905060562	50-320		BRUCKER, N. L.	7905060120	50-320	
BRADLEY, H. J.	7905060563	50-320		BRUCKER, N. L.	7905060121	50-320	
BRADLEY, H. J.	7905060564	50-320		BRUCKER, N. L.	7905060122	50-320	
BRADLEY, H. J.	7905060565	50-320		BRUCKER, N. L.	7905060123	50-320	
BRADLEY, H. J.	7905060566	50-320		BRUCKER, N. L.	7905060124	50-320	
BRADLEY, H. J.	7905060567	50-320		BRUCKER, N. L.	7905060125	50-320	
BRADLEY, H. J.	7905060568	50-320		BRUCKER, N. L.	7905060126	50-320	
BRADLEY, H. J.	7905060569	50-320		BRUCKER, N. L.	7905060127	50-320	
BRADLEY, H. J.	7905060570	50-320		BRUCKER, N. L.	7905060128	50-320	
BRADLEY, H. J.	7905060571	50-320		BRUCKER, N. L.	7905060129	50-320	
BRADLEY, H. J.	7905060572	50-320		BRUCKER, N. L.	7905060130	50-320	
BRADLEY, H. J.	7905060573	50-320		BRUCKER, N. L.	7905060131	50-320	
BRADLEY, H. J.	7905060574	50-320		BRUCKER, N. L.	7905060132	50-320	
BRADLEY, H. J.	7905060575	50-320		BRUCKER, N. L.	7905060133	50-320	
BRADLEY, H. J.	7905060576	50-320		BRUCKER, N. L.	7905060134	50-320	
BRADLEY, H. J.	7905060577	50-320		BRUCKER, N. L.	7905060135	50-320	
BRADLEY, H. J.	7905060578	50-320		BRUCKER, N. L.	7905060136	50-320	
BRADLEY, H. J.	7905060579	50-320		BRUCKER, N. L.	7905060137	50-320	
BRADLEY, H. J.	7905060580	50-320		BRUCKER, N. L.	7905060138	50-320	
BRADLEY, H. J.	7905060581	50-320		BRUCKER, N. L.	7905060139	50-320	
BRADLEY, H. J.	7905060582	50-320		BRUCKER, N. L.	7905060140	50-320	
BRADLEY, H. J.	7905060583	50-320		BRUCKER, N. L.	7905060141	50-320	
BRADLEY, H. J.	7905060584	50-320		BRUCKER, N. L.	7905060142	50-320	
BRADLEY, H. J.	7905060585	50-320		BRUCKER, N. L.	7905060143	50-320	
BRADLEY, H. J.	7905060586	50-320		BRUCKER, N. L.	7905060144	50-320	
BRADLEY, H. J.	7905060587	50-320		BRUCKER, N. L.	7905060145	50-320	
BRADLEY, H. J.	7905060588	50-320		BRUCKER, N. L.	7905060146	50-320	
BRADLEY, H. J.	7905060589	50-320		BRUCKER, N. L.	7905060147	50-320	
BRADLEY, H. J.	7905060590	50-320		BRUCKER, N. L.	7905060148	50-320	
BRADLEY, H. J.	7905060591	50-320		BRUCKER, N. L.	7905060149	50-320	
BRADLEY, H. J.	7905060592	50-320		BRUCKER, N. L.	7905060150	50-320	
BRADLEY, H. J.	7905060593	50-320		BRUCKER, N. L.	7905060151	50-320	
BRADLEY, H. J.	7905060594	50-320		BRUCKER, N. L.	7905060152	50-320	
BRADLEY, H. J.	7905060595	50-320		BRUCKER, N. L.	7905060153	50-320	
BRADLEY, H. J.	7905060596	50-320		BRUCKER, N. L.	7905060154	50-320	
BRADLEY, H. J.	7905060597	50-320		BRUCKER, N. L.	7905060155	50-320	
BRADLEY, H. J.	7905060598	50-320		BRUCKER, N. L.	7905060156	50-320	
BRADLEY, H. J.	7905060599	50-320		BRUCKER, N. L.	7905060157	50-320	
BRADLEY, H. J.	7905060600	50-320		BRUCKER, N. L.	7905060158	50-320	
BRADLEY, H. J.	7905060601	50-320		BRUCKER, N. L.	7905060159	50-320	
BRADLEY, H. J.	7905060602	50-320		BRUCKER, N. L.	7905060160	50-320	
BRADLEY, H. J.	7905060603	50-320		BRUCKER, N. L.	7905060161	50-320	
BRADLEY, H. J.	7905060604	50-320		BRUCKER, N. L.	7905060162	50-320	
BRADLEY, H. J.	7905060605	50-320		BRUCKER, N. L.	7905060163	50-320	
BRADLEY, H. J.	7905060606	50-320		BRUCKER, N. L.	7905060164	50-320	
BRADLEY, H. J.	7905060607	50-320		BRUCKER, N. L.	7905060165	50-320	
BRADLEY, H. J.	7905060608	50-320		BRUCKER, N. L.	7905060166	50-320	
BRADLEY, H. J.	7905060609	50-320		BRUCKER, N. L.	7905060167	50-320	
BRADLEY, H. J.	7905060610	50-320		BRUCKER, N. L.	7905060168	50-320	
BRADLEY, H. J.	7905060611	50-320		BRUCKER, N. L.	7905060169	50-320	
BRADLEY, H. J.	7905060612	50-320		BRUCKER, N. L.	7905060170	50-320	
BRADLEY, H. J.	7905060613	50-320		BRUCKER, N. L.	7905060171	50-320	
BRADLEY, H. J.	7905060614	50-320		BRUCKER, N. L.	7905060172	50-320	
BRADLEY, H. J.	7905060615	50-320		BRUCKER, N. L.	7905060173	50-320	
BRADLEY, H. J.	7905060616	50-320		BRUCKER, N. L.	7905060174	50-320	
BRADLEY, H. J.	7905060617	50-320		BRUCKER, N. L.	7905060175	50-320	
BRADLEY, H. J.	7905060618	50-320		BRUCKER, N. L.	7905060176	50-320	
BRADLEY, H. J.	7905060619	50-320		BRUCKER, N. L.	7905060177	50-320	
BRADLEY, H. J.	7905060620	50-320		BRUCKER, N. L.	7905060178	50-320	
BRADLEY, H. J.	7905060621	50-320		BRUCKER, N. L.	7905060179	50-320	
BRADLEY, H. J.	7905060622	50-320		BRUCKER, N. L.	7905060180	50-320	
BRADLEY, H. J.	7905060623	50-320		BRUCKER, N. L.	7905060181	50-320	
BRADLEY, H. J.	7905060624	50-320		BRUCKER, N. L.	7905060182	50-320	
BRADLEY, H. J.	7905060625	50-320		BRUCKER, N. L.	7905060183	50-320	
BRADLEY, H. J.	7905060626	50-320		BRUCKER, N. L.	7905060184	50-320	
BRADLEY, H. J.	7905060627	50-320		BRUCKER, N. L.	7905060185	50-320	
BRADLEY, H. J.	7905060628	50-320		BRUCKER, N. L.	7905060186	50-320	
BRADLEY, H. J.	7905060629	50-320		BRUCKER, N. L.	7905060187	50-320	
BRADLEY, H. J.	7905060630	50-320		BRUCKER, N. L.	7905060188	50-320	
BRADLEY, H. J.	7905060631	50-320		BRUCKER, N. L.	7905060189	50-320	
BRADLEY, H. J.	7905060632	50-320		BRUCKER, N. L.	7905060190	50-320	
BRADLEY, H. J.	7905060633	50-320		BRUCKER, N. L.	7905060191	50-320	
BRADLEY, H. J.	7905060634	50-320		BRUCKER, N. L.	7905060192	50-320	
BRADLEY, H. J.	7905060635	50-320		BRUCKER, N. L.	7905060193	50-320	
BRADLEY, H. J.	7905060636	50-320		BRUCKER, N. L.	7905060194	50-320	
BRADLEY, H. J.	7905060637	50-320		BRUCKER, N. L.	7905060195	50-320	
BRADLEY, H. J.	7905060638	50-320		BRUCKER, N. L.	7905060196	50-320	
BRADLEY, H. J.	7905060639	50-320		BRUCKER, N. L.	7905060197	50-320	
BRADLEY, H. J.	7905060640	50-320		BRUCKER, N. L.	7905060198	50-320	
BRADLEY, H. J.	7905060641	50-320		BRUCKER, N. L.	7905060199	50-320	
BRADLEY, H. J.	7905060642	50-320		BRUCKER, N. L.	7905060200	50-320	
BRADLEY, H. J.	7905060643	50-320		BRUCKER, N. L.	7905060201	50-320	
BRADLEY, H. J.	7905060644	50-320		BRUCKER, N. L.	7905060202	50-320	
BRADLEY, H. J.	7905060645	50-320		BRUCKER, N. L.	7905060203	50-320	
BRADLEY, H. J.	7905060646	50-320		BRUCKER, N. L.	7905060204	50-320	
BRADLEY, H. J.	7905060647	50-320		BRUCKER, N. L.	7905060205	50-320	
BRADLEY, H. J.	7905060648	50-320		BRUCKER, N. L.	7905060206	50-320	
BRADLEY, H. J.	7905060649	50-320		BRUCKER, N. L.	7905060207	50-320	
BRADLEY, H. J.	7905060650	50-320		BRUCKER, N. L.	7905060208	50-320	
BRADLEY, H. J.	7905060651	50-320		BRUCKER, N. L.	7905060209	50-320	
BRADLEY, H. J.	7905060652	50-320		BRUCKER, N. L.	7905060210	50-320	
BRADLEY, H. J.	7905060653	50-320		BRUCKER, N. L.	7905060211	50-320	
BRADLEY, H. J.	7905060654	50-320		BRUCKER, N. L.	7905060212	50-320	
BRADLEY, H. J.	7905060655	50-320		BRUCKER, N. L.	7905060213	50-320	
BRADLEY, H. J.	7905060656	50-320		BRUCKER, N. L.	7905060214	50-320	
BRADLEY, H. J.	7905060657	50-320		BRUCKER, N. L.	7905060215	50-320	
BRADLEY, H. J.	7905060658	50-320		BRUCKER, N. L.	7905060216	50-320	
BRADLEY, H. J.	7905060659	50-320		BRUCKER, N. L.	7905060217	50-320	
BRADLEY, H. J.	7905060660	50-320		BRUCKER, N. L.	7905060218	50-320	
BRADLEY, H. J.	7905060661	50-320		BRUCKER, N. L.	7905060219	50-320	
BRADLEY, H. J.	7905060662	50-320		BRUCKER, N. L.	7905060220	50-320	
BRADLEY, H. J.	7905060663	50-320		BRUCKER, N. L.	7905060221	50-320	
BRADLEY, H. J.	7905060664	50-320		BRUCKER, N. L.	7905060222	50-320	
BRADLEY, H. J.	7905060665	50-320		BRUCKER, N. L.	7905060223	50-320	
BRADLEY, H. J.	7905060666	50-320		BRUCKER, N. L.	7905060224	50-320	
BRADLEY, H. J.	7905060667	50-320		BRUCKER, N. L.	7905060225	50-320	
BRADLEY, H. J.	7905060668	50-320		BRUCKER, N. L.	7905060226	50-320	
BRADLEY, H. J.	7905060669	50-320		BRUCKER, N. L.	7905060227	50-320	
BRADLEY, H. J.	7905060670	50-320		BRUCKER, N. L.	7905060228	50-320	
BRADLEY, H. J.	7905060671	50-320		BRUCKER, N. L.	7905060229	50-320	
BRADLEY, H. J.	7905060672	50-320		BRUCKER, N. L.	7905060230	50-320	
BRADLEY, H. J.	7905060673	50-320		BRUCKER, N. L.	7905060231	50-320	
BRADLEY, H. J.	7905060674	50-320		BRUCKER, N. L.	7905060232	50-320	
BRADLEY, H. J.	7905060675	50-320		BRUCKER, N. L.	7905060233	50-320	
BRADLEY, H. J.	7905060676	50-320		BRUCKER, N. L.	7905060234	50-320	
BRADLEY, H. J.	7905060677	50-320		BRUCKER, N. L.	7905060235	50-3	

PERSONAL AUTHOR INDEX

353

[illegible]

PERSONAL AUTHOR INDEX

[illegible]

PERSONAL AUTHOR INDEX

355

AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	DOCKET NUMBER	REPORT NUMBER
ZIEHARD, D. L.	790300029	50-258		ZIEHARD, D. L.	790303032	32-258	
ZIEHARD, D. L.	790304027	50-155		ZIEHARD, D. L.	790300729	50-245	
ZIEHARD, D. L.	790304046	50-309		ZIEHARD, D. L.	790300957	50-245	
ZIEHARD, D. L.	790305021	50-204		ZIEHARD, D. L.	790303032	32-245	
ZIEHARD, D. L.	790305031	50-244		ZIEHARD, D. L.	790303031	32-245	
ZIEHARD, D. L.	790305042	50-29		ZIEHARD, D. L.	790318049	50-193	
ZIEHARD, D. L.	790305043	50-244		ZIMMERMAN, R. P.	790305044	50-245	
ZIEHARD, D. L.	790305047	50-244		ZITT, R. L.	790303049	50-258	
ZIEHARD, D. L.	790305049	50-244		ZITTEL, H. E.	790304874		790304874
ZIEHARD, D. L.	7903100174	50-409		KEANE, J.	790305041		
ZIEHARD, D. L.	790320099	50-409		KUPLET, E.	790311025	50-303	
ZIEHARD, D. L.	7903060150	50-425		KUHLER, P. E.	790310701	70-1257	
ZIEHARD, D. L.	7903050192	50-409		LEITZ, J.	790310555		
ZIEHARD, D. L.	790329074	50-425					



CORPORATE SOURCE INDEX

[illegible]

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOC- ID	AUTHOR AFFILIATION	ACCESSION NUMBER	DOC- ID
	7903080440	80-304		79030110023	80-404
	7903080448	80-304		7903102061	80-404
	7903080458	80-304		7903103046	80-404
	7903080459	80-304		7903040332	80-404
	7903080461	80-304		7903040432	80-404
	7903103031	80-304		7903040434	80-404
	7903103032	80-304		7903040436	80-404
	7903103033	80-304		7903040438	80-404
	7903103034	80-304		7903103035	80-404
	7903103035	80-304		7903103036	80-404
	7903103036	80-304		7903103037	80-404
	7903103037	80-304		7903103038	80-404
	7903103038	80-304		7903103039	80-404
	7903103039	80-304		7903103040	80-404
	7903103040	80-304		7903103041	80-404
	7903103041	80-304		7903103042	80-404
	7903103042	80-304		7903103043	80-404
	7903103043	80-304		7903103044	80-404
	7903103044	80-304		7903103045	80-404
	7903103045	80-304		7903103046	80-404
	7903103046	80-304		7903103047	80-404
	7903103047	80-304		7903103048	80-404
	7903103048	80-304		7903103049	80-404
	7903103049	80-304		7903103050	80-404
	7903103050	80-304		7903103051	80-404
	7903103051	80-304		7903103052	80-404
	7903103052	80-304		7903103053	80-404
	7903103053	80-304		7903103054	80-404
	7903103054	80-304		7903103055	80-404
	7903103055	80-304		7903103056	80-404
	7903103056	80-304		7903103057	80-404
	7903103057	80-304		7903103058	80-404
	7903103058	80-304		7903103059	80-404
	7903103059	80-304		7903103060	80-404
	7903103060	80-304		7903103061	80-404
	7903103061	80-304		7903103062	80-404
	7903103062	80-304		7903103063	80-404
	7903103063	80-304		7903103064	80-404
	7903103064	80-304		7903103065	80-404
	7903103065	80-304		7903103066	80-404
	7903103066	80-304		7903103067	80-404
	7903103067	80-304		7903103068	80-404
	7903103068	80-304		7903103069	80-404
	7903103069	80-304		7903103070	80-404
	7903103070	80-304		7903103071	80-404
	7903103071	80-304		7903103072	80-404
	7903103072	80-304		7903103073	80-404
	7903103073	80-304		7903103074	80-404
	7903103074	80-304		7903103075	80-404
	7903103075	80-304		7903103076	80-404
	7903103076	80-304		7903103077	80-404
	7903103077	80-304		7903103078	80-404
	7903103078	80-304		7903103079	80-404
	7903103079	80-304		7903103080	80-404
	7903103080	80-304		7903103081	80-404
	7903103081	80-304		7903103082	80-404
	7903103082	80-304		7903103083	80-404
	7903103083	80-304		7903103084	80-404
	7903103084	80-304		7903103085	80-404
	7903103085	80-304		7903103086	80-404
	7903103086	80-304		7903103087	80-404
	7903103087	80-304		79	

[illegible]

[illegible]

CORPORATE SOURCE INDEX

374

AUTHOR AFFILIATION	ACCESSION NUMBER	SOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	SOCKET NUMBER
Genie Laboratories	7905240346			7905140032	50-026
	7905230708			7905240553	
	7905140149			7905240404	
	7905110249	50-020		7905110247	50-023
	7905050061	50-020			

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCRETION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCRETION NUMBER	DOCKET NUMBER
	790329032A	50-392		790318056A	
	7903070223	50-350		790307027A	
	7903070230	50-350		790307028A	
	7903070231	50-350		7903070287	
	7903070234	50-350		7903110217	
	7903070235	50-350		7903110219	
	7903140163	50-350		7903070270	
	7903140164	50-350		7903070272	
	7903140168	50-350		7903070273	
	7903070218	50-350		7903070274	
	7903070220	50-350		7903070275	
	7903070250	50-350		7903070276	
	7903070251	50-350		7903070277	
	7903070252	50-350		7903070278	
	7903070253	50-350		7903070279	
	7903070254	50-350		7903070280	
	7903070255	50-350		7903070281	
	7903070256	50-350		7903070282	
	7903070257	50-350		7903070283	
	7903070258	50-350		7903070284	
	7903070259	50-350		7903070285	
	7903070260	50-350		7903070286	
	7903070261	50-350		7903070287	
	7903070262	50-350		7903070288	
	7903070263	50-350		7903070289	
	7903070264	50-350		7903070290	
	7903070265	50-350		7903070291	
	7903070266	50-350		7903070292	
	7903070267	50-350		7903070293	
	7903070268	50-350		7903070294	
	7903070269	50-350		7903070295	
	7903070270	50-350		7903070296	
	7903070271	50-350		7903070297	
	7903070272	50-350		7903070298	
	7903070273	50-350		7903070299	
	7903070274	50-350		7903070300	
	7903070275	50-350		7903070301	
	7903070276	50-350		7903070302	
	7903070277	50-350		7903070303	
	7903070278	50-350		7903070304	
	7903070279	50-350		7903070305	
	7903070280	50-350		7903070306	
	7903070281	50-350		7903070307	
	7903070282	50-350		7903070308	
	7903070283	50-350		7903070309	
	7903070284	50-350		7903070310	
	7903070285	50-350		7903070311	
	7903070286	50-350		7903070312	
	7903070287	50-350		7903070313	
	7903070288	50-350		7903070314	
	7903070289	50-350		7903070315	
	7903070290	50-350		7903070316	
	7903070291	50-350		7903070317	
	7903070292	50-350		7903070318	
	7903070293	50-350		7903070319	
	7903070294	50-350		7903070320	
	7903070295	50-350		7903070321	
	7903070296	50-350		7903070322	
	7903070297	50-350		7903070323	
	7903070298	50-350		7903070324	
	7903070299	50-350		7903070325	
	7903070300	50-350		7903070326	
	7903070301	50-350		7903070327	
	7903070302	50-350		7903070328	
	7903070303	50-350		7903070329	
	7903070304	50-350		7903070330	
	7903070305	50-350		7903070331	
	7903070306	50-350		7903070332	

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX[illegible]

ORGANIZATIONAL SOURCE INDEX

[illegible]

331

[illegible]

ORGANIZATIONAL SOURCE INDEX

[illegible]

[illegible]

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SOCIETY NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	SOCIETY NUMBER
	7908040428	50-344	Region 3, Chicago, Reactor Operations Nuclear Support Branch	7905100079	50-344
	7908040507	50-346		7905100974	50-344
	7905130137	50-346		7905060086	50-355
	7905010411	50-346		7905050027	50-373
	7908050024	50-346		7905040729	50-358
	7908060557	50-346		7905080149	50-351
	7905030267	50-346		7905090178	50-409
	7905040038	50-346		7905130134	50-361
	7905050176	50-346		7905100143	50-356
	7905050422	50-346		7905040161	50-394
	7908030053	50-346		7905100159	50-354
	7908050064	50-346		7905030002	50-318
	7905140427	50-346		7905110152	50-315
	7905040993	50-346		7905070030	50-373
	7905070174	50-346		7905110034	50-493
	7905030248	50-346		7905040719	50-388
	7905040509	50-346		7905080086	50-393
	7905050048	50-348		7905040523	50-353
	7908040080	50-483		7905040147	50-353
	7908050056	50-483		7908080173	50-409
	7908050116	50-483		7905040165	50-351
	7905040428	50-483		7905100184	50-351
	7908040461	50-483		7908020044	50-351
	7905040915	50-483		7905110100	50-344
	7908010405	50-483		7905100254	50-344
	7908030269	50-483		7905110077	50-344
	7908080112	50-483		7905110092	50-344
	7905010870	50-446		7905110089	50-346
	7905040660	50-446		7905030113	50-346
	7908010181	50-446	Region 3, Chicago, Safeguards Branch	7905110047	50-346
	7908020477	50-446		7905100777	50-346
	7905050056	50-446		7905100754	50-350
	7905010613	50-446		7905100488	50-354
	7908040431	50-446		7905110241	50-352
	7908040438	50-346		7905100754	50-350
	7905040898	50-346		7905100277	50-350
	7908030053	50-346		7905100748	50-350
	7908060515	50-346		7905020326	50-350
	7905010672	50-352	Region 4, Dallas, Office of the Director	7905010371	50-313
	7908040049	50-352		7905010395	50-313
	7908030184	50-352		7905010051	40-708A
	7905050069	50-352		7905010075	50-445
	7905100119	50-352		7905010236	50-462
	7908040474	50-352		7905010368	50-462
	7908040442	50-352		7905010211	50-462
	7905040A30	50-352		7905010370	50-445
	7908030288	50-352		7905010379	50-445
	7908080105	50-352		7905010383	50-445
	7905010101	50-445		7905050241	50-445
	7908090182	70-1379		7905050250	50-445
	7905110234	50-445		7905100544	50-382
	7908050057	50-480		7905100550	50-382
	7905100994	50-480		7905100644	50-382
	7905030179	50-480		7905100644	50-382
	7908040740	50-461		7905020348	50-382
	7905100303	50-390		7905020128	50-382
	7905130119	50-341		7905020481	50-382
	7905100434	50-351		7905100581	50-313
	7905050094	50-359		7905100579	50-313
	7905130338	50-359		7905010448	50-313
	7908030054	50-370		7905020441	50-313
	7905040740	50-456		7905020277	50-313
	7905040711	50-370		7905020419	50-313
	7905010059	50-346		7905020434	50-313
	7908070009	50-358		7905140152	50-313
	7905070499	50-358		7905130445	50-313
	7905140107	50-358		7905140586	50-348
	7908070030	50-359		7905040488	50-313
	7905050000	50-359		7905040456	50-313
	7905040349	50-359		7905070043	50-313
	7905040728	50-359		7905010929	50-313
	7905070054	50-358		7905090096	50-313
	7905050056	50-341		7905050045	50-313
	7905126410	50-341		7905010508	50-313
	7905080024	50-341		7905010501	50-313
	7905080004	50-341		7905080034	50-313
	7905040347	50-445		7905080048	50-349
	7905070048	50-445		7905010367	50-313
	7905090038	50-344		7905010083	50-349
	7905140091	50-344		7905010217	50-349
	7905020461	50-350		7905010488	50-349
	7905030044	50-353		7905030131	50-349
				7905040489	50-349
	7905010160	50-346		7905040510	50-349
	7905050440	70-1379		7905070095	50-349
	7905050420	50-331		7905050443	50-349
	7905050426	50-331		7905050098	50-349
	7905050425	40-2392		7905030020	50-349
	7905050437	50-349		7905010208	50-349
	7905010807	50-315		7905010487	50-349
	7905040440	50-315		7905030108	50-349
	7905050041	50-315		7905040402	50-349
	7905020412	50-315		7905040413	50-349
	7905010109	50-315		7905070088	50-349
	7905040126	50-382		7905010441	50-349
	7905010405	50-382		7905040099	50-349
	7905010142	50-346		7905050071	50-349
	7905010635	70-1379		7905010200	50-349
	7905010071	40-2561		7905010489	50-349
Region 3, Chicago, Fuel Facility & Materials Safety Branch					

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX[illegible]

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

389

[illegible]

390

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7905070069	71-4344		7908130093	
	7905070070	71-4479		7908200025	90-021
	7905070071	71-4244		7908240001	90-434
	7905070072	71-08		7908240039	90-280
	7905070073	71-4771		7908260137	
	7905070074	71-489		7908260027	
	7905070075	71-109		7908260137	
	7905070076	71-286		7908260137	90-546
	7905070077	71-4094		7908260137	90-272
	7905070078	71-068		7908260137	90-447
	7905070079	71-0038		7908260137	90-263
	7905070080	71-0109		7908260137	90-363
	7905070081	71-4379		7908260137	90-489
	7905070082	71-0679		7908260137	90-110
	7905070083	71-4039		7908260137	90-029
	7905070084	71-4771		7908260137	90-434
	7905070085	71-4771		7908260137	90-031
	7905070086	71-77		7908260137	90-456
	7905070087	90-030		7908260137	90-443
	7905070088			7908260137	90-000
	7905070089	40-6659		7908260137	90-022
	7905070090	40-6659		7908260137	90-022
	7905070091	40-6659		7908260137	90-022
	7905070092	40-6659		7908260137	90-022
	7905070093	40-6659		7908260137	90-022
	7905070094	40-6659		7908260137	90-022
	7905070095	40-6659		7908260137	90-022
	7905070096	40-6659		7908260137	90-022
	7905070097	40-6659		7908260137	90-022
	7905070098	40-6659		7908260137	90-022
	7905070099	40-6659		7908260137	90-022
	7905070100	40-6659		7908260137	90-022
	7905070101	40-6659		7908260137	90-022
	7905070102	40-6659		7908260137	90-022
	7905070103	40-6659		7908260137	90-022
	7905070104	40-6659		7908260137	90-022
	7905070105	40-6659		7908260137	90-022
	7905070106	40-6659		7908260137	90-022
	7905070107	40-6659		7908260137	90-022
	7905070108	40-6659		7908260137	90-022
	7905070109	40-6659		7908260137	90-022
	7905070110	40-6659		7908260137	90-022
	7905070111	40-6659		7908260137	90-022
	7905070112	40-6659		7908260137	90-022
	7905070113	40-6659		7908260137	90-022
	7905070114	40-6659		7908260137	90-022
	7905070115	40-6659		7908260137	90-022
	7905070116	40-6659		7908260137	90-022
	7905070117	40-6659		7908260137	90-022
	7905070118	40-6659		7908260137	90-022
	7905070119	40-6659		7908260137	90-022
	7905070120	40-6659		7908260137	90-022
	7905070121	40-6659		7908260137	90-022
	7905070122	40-6659		7908260137	90-022
	7905070123	40-6659		7908260137	90-022
	7905070124	40-6659		7908260137	90-022
	7905070125	40-6659		7908260137	90-022
	7905070126	40-6659		7908260137	90-022
	7905070127	40-6659		7908260137	90-022
	7905070128	40-6659		7908260137	90-022
	7905070129	40-6659			

391

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCID NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCID NUMBER
	7703160117	50-185		7703160290	50-183
	7703160360	50-5		7703160367	50-344
	7703160381	50-182		7703160399	50-338
	7703160393	50-286		7703160399	50-267
	7703160394	50-223		7703160399	50-273
	7703160393	50-267		7703160399	50-266
	7703160394	50-404		7703160399	50-341
	7703160393	50-266		7703160399	50-266
	7703160393	50-113		7703160399	50-341
	7703160393	50-484		7703160399	50-341
	7703160393	50-326		7703160399	50-312
	7703160393	50-142		7703160399	50-346
	7703160393	50-427		7703160399	50-289
	7703160393	50-303		7703160399	50-312
	7703160393	50-131		7703160399	50-312
	7703160393	50-148		7703160399	50-312
	7703160393	50-148		7703160399	50-312
	7703160393	50-2		7703160399	50-312
	7703160393	50-103		7703160399	50-312
	7703160393	50-184		7703160399	50-312
	7703160393	50-5		7703160399	50-312
	7703160393	50-282		7703160399	50-312
	7703160393	50-112		7703160399	50-312
	7703160393	50-143		7703160399	50-312
	7703160393	50-112		7703160399	50-312
	7703160393	50-42		7703160399	50-312
	7703160393	50-75		7703160399	50-312
	7703160393	50-139		7703160399	50-312
	7703160393	50-154		7703160399	50-312
	7703160393	50-184		7703160399	50-312
	7703160393	50-184		7703160399	50-312
	7703160393	50-27		7703160399	50-312
	7703160393	50-139		7703160399	50-312
	7703160393	50-131		7703160399	50-312
	7703160393	50-32		7703160399	50-312
	7703160393	50-364		7703160399	50-312
	7703160393	50-624		7703160399	50-312
	7703160393	50-13		7703160399	50-312
	7703160393	50-264		7703160399	50-312
	7703160393	50-1257		7703160399	50-312
	7703160393	50-37		7703160399	50-312
	7703160393	50-754		7703160399	50-312
	7703160393	50-18		7703160399	50-312
	7703160393	50-304		7703160399	50-312
	7703160393	50-187		7703160399	50-312
	7703160393	50-94		7703160399	50-312
	7703160393	50-84		7703160399	50-312
	7703160393	50-1143		7703160399	50-312
	7703160393	50-87		7703160399	50-312
	7703160393	50-251		7703160399	50-312
	7703160393	50-251		7703160399	50-312
	7703160393	50-27		7703160399	50-312
	7703160393	50-274		7703160399	50-312
	7703160393	50-33		7703160399	50-312
	7703160393	50-184		7703160399	50-312
	7703160393	50-340		7703160399	50-312
	7703160393	50-313		7703160399	50-312
	7703160393	50-293		7703160399	50-312
	7703160393	50-10		7703160399	50-312
	7703160393	50-10		7703160399	50-312
	7703160393	50-285		7703160399	50-312

U.S. NUCLEAR REGULATORY COMMISSION
ORGANIZATIONAL SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCSET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCSET NUMBER
Cost Benefit Analysis Branch Division of Operating Reactors	7905100092	50-183	Reactor Safeguards Licensing Branch Assistant Director For Systems & Projects	7905240346	50-299
	7905100098	50-183		7905140323	50-298
	7905230170	50-326			
	7905050412	50-320			
	7905100024	50-320		7908150193	50-320
	7905070014	50-329		7908150179	50-320
	7905200849			7908150608	
	7905240970			79081405112	50-320
	7905200128	50-326		7908110120	50-323
	7905200129	50-326		7908110123	50-323
7905200120	50-326	7908110179	50-323		
7905100150	50-329	7908240283	50-320		
7908070017	50-329	7908040180	50-219		
7908140327	50-324	7908040471	50-320		
7908150119		7908070118	50-320		
7908200123	50-330	7908240352	50-256		
7908190194	50-330	7908240421	50-10		
7908230061	50-330	7908240731	50-255		
7908250065	50-330				
7908150114	50-313	Operating Reactors Branch 1	7908250674	50-286	
7908230061	50-330		7908070031	50-286	
7908250073	50-330		7908040309	50-261	
7908110020	50-312		7908070114	25-250	
7908110180	50-312		7908200119	50-250	
7908250061	50-330		7908250409	50-248	
7908250069	50-330		7908140503	50-344	
7908250069	50-330		7908240903	50-328	
7908150174	50-313		7908240911	50-225	
7908210058	50-320		7908200666	50-244	
7908250582	50-276		7908090576	50-244	
7908090171			7908250183	50-243	
Assistant Director For Engineers & Projects	7908080239	50-271	7908250190	50-293	
	7908110223	50-320	7908240378	50-303	
	7908230252	50-312	7908200113	50-341	
	7908110117	50-312	7908070130	50-261	
	7908110123	50-320			
	7908230256	50-330	7908070080	50-340	
	7908240275	50-320	7908100084	50-348	
	7908230258	50-320	7908180042	50-266	
	7908230256	50-320	7908100446	50-266	
	7908070184	50-251	7908140232	50-262	
7908090181	50-244	7908240333	50-262		
7908200199	50-251	7908290054	50-305		
7908090201	50-251	7908180044	50-308		
7908110022	50-298	7908200432	50-270		
7908110023	50-298	7908250034	50-249		
7908200141	50-237	7908090679	50-246		
7908090070	50-312	7908250263	50-249		
7908050647	50-10	7908250207	50-241		
7908150108	50-324	7908070121	50-261		
7908090103	50-344	7908070109	50-256		
7908150049	50-331	7908240208	50-252		
7908240194	50-331	7908140511	50-244		
7908110001	50-298	7908200540	50-244		
7908080244	50-223	7908100439	50-244		
7908110023		7908240875	50-255		
7908240152		7908240270	50-321		
7908250480	50-265	7908290680	50-320		
7908150028	50-328	7908290680	50-320		
7908250358	50-249	7908290680	50-320		
7908230321	50-249	7908290680	50-320		
7908070337	50-30	7908290680	50-320		
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50-304				
7908070337	50				

U.S. NUCLEAR REGULATORY COMMISSION ORGANIZATIONAL SOURCE INDEX

394

AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER	AUTHOR AFFILIATION	ACCESSION NUMBER	DOCKET NUMBER
	7908110393	50-320		7908110203	50-320
	7908250497	50-320		7908110209	50-320
	7908110349	50-320		7908110201	50-320
	7908110316	50-320		7908110202	50-320
Auxiliary Systems Branch	7908110323	50-320		7908200450	50-320
Containment Systems Branch	7908200214	50-320		7908160432	50-320
	7908200228	50-320		7908110207	50-320
Electric Instrumentation and Control Systems Branch	7908110331	50-320		7908090237	50-320
	7904500123	50-320		7908110204	50-320
Assistant Director for Reactor Safety	7908200448	50-320		7908200428	50-320
	7908010198	50-320		7908200441	50-320
	7908200449	50-320		7908200413	50-320
	7908200212	50-320		7908200314	50-320
	7908241001	50-344		7908090236	50-320
	7908080041	50-491		7908200714	50-320
	7908250037	50-320		7908220443	50-320
Analysis Branch	7908110341	50-320		7908200741	50-320
	7908110204	50-320		7908160131	50-320
	7908110061	50-320		7908200253	50-320
	7908110068	50-320		7908110229	50-320
	7908110074	50-320		7908160203	50-320
	7908200064	50-320		7908110464	50-320
	7908200113	50-320		7908200442	50-320
	7908110061	50-320		7908110201	50-320
	7908110204	50-320		7908200432	50-320
	7908110034	50-320		7908200227	50-320
Core Performance Branch	7908200097	50-320		7908110218	50-320
Reactor Systems Branch	7908250210	50-295		7908110319	50-320
	7908110040	50-320		7908110048	50-320
	7908200098	50-320		7908110038	50-320
	7908250474	50-295		7908110039	50-320
	7908250087	50-320		7908110034	50-320
	7908250102	50-320		7908110289	50-320
	7908110098	50-320		7908110288	50-320
				7908110209	50-320
				7908160032	50-320
OFFICE OF STANDARDS DEVELOPMENT			Probabilistic Analysis Branch		
Office of Standards Development	7908200460	50-320		7908200419	50-320
	7908200282	50-320		7908160171	50-320
	7908200384	50-320		7908200443	50-320
	7908200305	50-320		7908160044	50-320
	7908200408	50-320		7908200449	50-320
	7908200311	50-320		7908110315	50-320
	7908200462	50-320		7908110312	50-320
	7908200312	50-320		7908110319	50-320
	7908200328	50-320		7908160143	50-320
	7908200483	50-320		7908160149	50-320
	7908200480	50-320		7908200414	50-320
	7908200485	50-320	Environmental Effects Research Branch	7908110375	50-320
	7908200486	50-320		7908110372	50-320
	7908200487	50-320	System Performance Branch	7908110320	50-320
	7908200488	50-320	Division of Reactor Safety Research	7908110317	50-320
	7908200489	50-320		7908110315	50-320
	7908200490	50-320		7908110312	50-320
	7908200491	50-320		7908110319	50-320
	7908200492	50-320		7908110320	50-320
	7908200493	50-320		7908110320	50-320
	7908200494	50-320		7908110320	50-320
	7908200495	50-320		7908110320	50-320
	7908200496	50-320		7908110320	50-320
	7908200497	50-320		7908110320	50-320
	7908200498	50-320		7908110320	50-320
	7908200499	50-320		7908110320	50-320
	7908200500	50-320		7908110320	50-320
	7908200501	50-320		7908110320	50-320
	7908200502	50-320		7908110320	50-320
	7908200503	50-320		7908110320	50-320
	7908200504	50-320		7908110320	50-320
	7908200505	50-320		7908110320	50-320
	7908200506	50-320		7908110320	50-320
	7908200507	50-320		7908110320	50-320
	7908200508	50-320		7908110320	50-320
	7908200509	50-320		7908110320	50-320
	7908200510	50-320		7908110320	50-320
	7908200511	50-320		7908110320	50-320
	7908200512	50-320		7908110320	50-320
	7908200513	50-320		7908110320	50-320
	7908200514	50-320		7908110320	50-320
	7908200515	50-320		7908110320	50-320
	7908200516	50-320		7908110320	50-320
	7908200517	50-320		7908110320	50-320
	7908200518	50-320		7908110320	50-320
	7908200519	50-320		7908110320	50-320
	7908200520	50-320		7908110320	50-320
	7908200521	50-320		7908110320	50-320
	7908200522	50-320		7908110320	50-320
	7908200523	50-320		7908110320	50-320
	7908200524	50-320		7908110320	50-320
	7908200525	50-320		7908110320	50-320
	7908200526	50-320		7908110320	50-320
	7908200527	50-320		7908110320	50-320
	7908200528	50-320		7908110320	50-320
	7908200529	50-320		7908110320	50-320
	7908200530	50-320		7908110320	50-320
	7908200531	50-320		7908110320	50-320
	7908200532	50-320		7908110320	50-320
	7908200533	50-320		7908110320	50-320
	7908200534	50-320		7908110320	50-320
	7908200535	50-320		7908110320	50-320
	7908200536	50-320		7908110320	50-320
	7908200537	50-320		7908110320	50-320
	7908200538	50-320		7908110320	50-320
	7908200539	50-320		7908110320	50-320
	7908200540	50-320		7908110320	50-320
	7908200541	50-320		7908110320	50-320
	7908200542	50-320		7908110320	50-320
	7908200543	50-320		7908110320	50-320
	7908200544	50-320		7908110320	50-320
	7908200545	50-320		7908110320	50-320
	7908200546	50-320		7908110320	50-320
	7908200547	50-320		7908110320	50-320
	7908200548	50-320		7908110320	50-320
	7908200549	50-320		7908110320	50-320
	7908200550	50-320		7908110320	50-320
	7908200551	50-320		7908110320	50-320
	7908200552	50-320		7908110320	50-320
	7908200553	50-320		7908110320	50-320
	7908200554	50-320		7908110320	50-320
	7908200555	50-320		7908110320	50-320
	7908200556	50-320		7908110320	50-320
	7908200557	50-320		7908110320	50-320
	7908200558	50-320		7908110320	50-320
	7908200559	50-320		7908110320	50-320
	7908200560	50-320		7908110320	50-320
	7908200561	50-320		7908110320	50-320
	7908200562	50-320		7908110320	50-320
	7908200563	50-320		7908110320	50-320
	7908200564	50-320		7908110320	50-320
	7908200565	50-320		7908110320	50-320
	7908200566	50-320		7908110320	50-320
	7908200567	50-320		7908110320	50-320
	7908200568	50-320		7908110320	50-320
	7908200569	50-320		7908110320	50-320
	7908200570	50-320		7908110320	50-320
	7908200571	50-320		7908110320	50-320
	7908200572	50-320		7908110320	50-320
	7908200573	50-320		7908110320	50-320
	7908200574	50-320		7908110320	50-320
	7908200575	50-320		7908110320	50-320
	7908200576	50-320		7908110320	50-320
	7908200577	50-320		7908110320	50-320
	7908200578	50-320		7908110320	50-320
	7908200579	50-320		7908110320	50-320
	7908200580	50-320		7908110320	50-320
	7908200581	50-320		7908110320	50-320
	7908200582	50-320		7908110320	50-320
	7908200583	50-320		7908110320	50-320
	7908200584	50-320		7908110320	50-320
	7908200585	50-320		7908110320	50-320
	7908200586	50-320		7908110320	50-320
	7908200587	50-320		7908110320	50-320
	7908200588	50-320		7908110320	50-320
	7908200589	50-320		7908110320	50-320
	7908200590	50-320		7908110320	50-320
	7908200591	50-320		7908110320	50-320
	7908200592	50-320		7908110320	50-320
	7908200593	50-320		7908110320	50-320
	7908200594	50-320		7908110320	50-320
	7908200595	50-320		7908110320	50-320
	7908200596	50-320		7908110320	50-320
	7908200597	50-320		7908110320	50-320
	7908200598	50-320		7908110320	50-320
	7908200599	50-320		7908110320	50-320
	7908200600	50-320		7908110320	50-320
	7908200601	50-320		7908110320	50-320
	7908200602	50-320		7908110320	50-320
	7908200603	50-320		7908110320	50-320
	7908200604	50-320		7908110320	50-320
	7908200605	50-320		7908110320	50-320
	7908200606	50-320		7908110320	50-320
	7908200607	50-320		7908110320	50-320
	7908200608	50-320		7908110320	50-320
	7908200609	50-320		7908110320	50-320
	7908200610	50-320		7908110320	50-320
	7908200611	50-320		7908110320	50-320
	7908200612	50-320		7908110320	50-320
	7908200613	50-320		7908110320	50-320
	7908200614	50-320		7908110320	50-320
	7908200615	50-320		7908110320	50-320
	7908200616	50-320		7908110320	50-320
	7908200617	50-320		7908110320	50-320
	7908200618	50-320		7908110320	50-320
	7908200619	50-320		7908110320	50-320
	7908200620	50-320		7908110320	50-320
	7908200621	50-320		790811	

REPORT NUMBER INDEX

[illegible]



APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. Application/Construction Stage Documents and Correspondence

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Correspondence and documents relating to unresolved design and construction issues.
2. Meeting announcements and summaries of meeting discussions on issues of item 1.
3. Correspondence regarding Preliminary and Final Safety Analysis Reports.
4. NRC questions, requests for additional information, and applicant responses.
5. Applicant's Quality Assurance Manual.
6. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
7. Federal Register notices that do not apply to other categories.
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Scheduling of license application submission or review.
10. Reports of site visits.
11. Backup technical documents (i.e., topical reports) submitted in support of the application.
12. Early site review information.
13. Construction Permit, amendments and correspondence relating to construction permit.
14. Environmental review information.
15. Construction permit.

B. Utility Preliminary Safety Analysis Report (PSAR) and Amendments

This category is strictly limited to the items listed below. All related to Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by
2. Amendments and changes to the PSAR.
3. Transmittal letters.
4. Letters acknowledging receipt.
5. Hazards Summary Report submitted by utility (now desl.

6. Safety Analysis Report submitted by utility (now designated PSAR).
7. Certificates of Service of PSAR.

C. Utility Environmental Report (ER), Amendments and Correspondence

1. Environmental Report (ER) submitted by the utility.
2. Amendments and supplements to the ER.
3. Transmittal letters.
4. Information on scheduling of submittal or review of ER.
5. NRC questions, requests for additional information, and applicant responses.
6. Federal Register notice citing availability of items 1 and 2.
7. Correspondence relating to the review of ER.
8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), Supplements and Correspondence

1. Draft and Final Environmental (Impact) Statements (DES and FES).
2. Supplements to DES and FES.
3. Correspondence relating to the DES or FES.
4. Comments from other federal, state, and local government agencies.
5. Transmittal letters.
6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
7. Backup technical documents submitted in connection with above.
8. Notices of availability of above.
9. Draft of detailed statement.

NRC Safety Evaluation Report (SER), Supplements and Correspondence

1. Safety Evaluation Report (SER).

2. SER.

4. Notices advising of the availability of 1 and 2.
5. Information on scheduling of SER submittals and review.
6. Requests for additional information for use in preparing SER; responses to such requests.
7. Meeting announcements or reports of meetings where the primary subject of discussion is the safety review or safety evaluation.
8. Transmittal letters.
9. Comments from other agencies relative to safety review.
10. NRC-AEC Hazard Analysis Reports (now designated SER).

F. Security, Medical, Emergency, and Fire-Protection Plans

All plans in this category are submitted separately. Information submitted for the PSAR or FSAR is excluded.

1. Correspondence relating to plans.
2. Supplements, changes, and revisions to plans.
3. Fire Hazard Protection Plan and Surveys.

G. Adjudicatory Correspondence

This category contains all documents on hearings, Atomic Safety and Licensing Board (ASLB) review, and opposition except word-for-word transcripts of ASLB hearings (Category T) and anti-trust hearings (Category N).

1. ASLB hearing and review documents.
2. Correspondence to and from intervenors.
3. Correspondence to and from persons writing in opposition to the facility. Those writing for information or in support of the facility are in category H.
4. Board orders and decisions.
5. Requests to make appearances at hearings.
6. Transmittal of supporting documents (i.e., SER, PES) to the board.
7. Federal Register notices regarding hearings.
8. Requests for a hearing.
9. Petitions from participants (including petition for request for extension)
10. Corrections to transcripts.
11. Professional qualifications, if presented at a hearing.

12. Memorandums and orders authorizing issuance of license, changes, and other issuances by the Atomic Safety and Licensing Board.
13. Hearing index.

H. General correspondence

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Qualification statements of new employees.
2. Change of address notifications.
3. Changes in organization.
4. Changes in service lists, "Certificate of Service" documents (without a document attached).
5. NRC requests to applicant for additional copies of documents.
6. Correspondence from the public in support of or requesting information about the facility.
7. Letters of "concern" (NOT "opposition") and response thereto.
8. Correspondence on strictly administrative matters.
9. Correspondence regarding the local Public Document Room.
10. Memoranda to Public Document Room regarding withholding a document (unaccompanied by that document).
11. Press releases from applicant.
12. Any other material that fits the criteria given above.
13. Professional qualifications (resumes).
14. Congressional correspondence and constituent letters.

Information

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. Insurance and Indemnity Information

1. All correspondence and documentation regarding indemnity and insurance.
2. Endorsements to insurance policies.
3. NELPIA - Nuclear Energy Liability Property Insurance information.

K. Utility Final Safety Analysis Report (FSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR).
2. Amendments and changes to the FSAR.
3. Transmittal letters.
4. Letters acknowledging receipt of items.
5. Hazards Final Summary Report (now designated FSAR).
6. Certificates of Service of FSAR.

L. Limited Work Authorization and Related Correspondence

This category is limited to items issued before the construction permit is granted.

1. Limited Work Authorizations.
2. Environmental exemptions.
3. Correspondence relating to 1 and 2.
4. All information concerning site preparation prior to the issuance of a construction permit.

M. Antitrust Correspondence

1. All material concerning antitrust except hearing transcripts (category N)
2. All material marked with an A immediately following the docket number. The A signifies antitrust proceedings.

N. Antitrust Hearing Transcripts

This category contains only word-for-word transcripts of hearings in antitrust cases they will be marked with an A following the docket number. Related in category M.

O. Advisory Committee on Reactor Safeguards (ACRS) Reports and Correspondence

1. Correspondence and letter reports relating to ACRS reviews
2. Correspondence from ACRS
3. Announcements of ACRS meetings

4. Transmittal letters to ACRS
5. ACRS reports.

P. Operating License Stage Documents and Correspondence

This file assumes the position of the application file for general technical items dated on or after the issuance of the operating license. It includes:

1. Operating license, amendments, proposed amendments, and changes.
2. Technical specifications and changes.
3. Announcements of issuance of 1 and 2.
4. Transmittal letters.
5. All general technical correspondence relating to technical specifications or operating license.
6. License conditions.
7. Operator licenses or administrative information bearing on the licensing of operators.
8. Meeting announcements or summaries of discussions where the main subject is technical specifications, operating license, or any technical issue arising after the issuance of the operating license.
9. Correspondence regarding codes (ASME), regulations, laws, or changes in policy that may affect plant operation or bear on the operating license.
10. Information on the Standard Review Plan (SRP).
11. Results of surveys or tests conducted in accordance with the technical specifications (NOT periodic reports, which fall in category R).
12. Requests for issuance of operating license.
13. Requests for copies of items 1 and 2 and responses.
14. Correspondence on generic technical issues.
15. Owner's group meeting announcements and reports.
16. Orders for modification of license.
17. Requests for extension date of license or license modification.
18. Quality assurance information.

Environmental matters (technical).

are cooling system.

waste information.

Q. Inspection Reports, IE Bulletins and Correspondence

1. Inspection reports.
2. Bulletins and Circulars of NRC Office of Inspection and Enforcement (IE).
3. Responses by applicant to IE correspondence.
4. Applicant's determination of proprietary nature of inspection reports.
5. Letters concerning areas of noncompliance.
6. Any correspondence relating to inspection and enforcement that does not specifically relate to incidents as defined in category S.
7. In-service inspections.
8. Regulatory Operations (RO) Bulletins.

R. Periodic Operating Reports and Related Correspondence

This category includes periodic reports of a routine nature.

1. Monthly, semiannual, or annual reports (other than financial).
2. Periodic environmental monitoring, effluent testing, or similar reports.
3. Gray Book Information.
4. Correspondence or other documents relating to the above listed items.

S. Reportable Occurrences, LERs and Related Correspondence

This category contains all materials relating to abnormal, unusual, reportable, nonroutine, or 10 CFR 50.55e occurrences. This includes:

1. All 24-hour, 10-day, 30-day, interim, final, and followup reports on these events.
2. Other related documents.

NOTE: Also called licensee event reports, incident reports, etc.

T. Hearing Transcripts on Non-Antitrust Matters

This category contains only word-for-word transcripts in non-antitrust matters. Related correspondence is in category G.



NRC FORM 335 (7-77)		U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		1. REPORT NUMBER (Assigned by DDC) NUREG-0540 Vol. 1 No. 5	
4. TITLE AND SUBTITLE (Add Volume No., if appropriate) Title List of Documents Made Publicly Available				2. (Leave blank)	
7. AUTHOR(S)				3. RECIPIENT'S ACCESSION NO.	
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Technical Information and Document Control U.S. Nuclear Regulatory Commission Washington, D. C. 20555				5. DATE REPORT COMPLETED MONTH June YEAR 1979	
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Technical Information and Document Control U.S. Nuclear Regulatory Commission Washington, D. C. 20555				DATE REPORT ISSUED MONTH June YEAR 1979	
13. TYPE OF REPORT Monthly				6. (Leave blank)	
16. SUPPLEMENTARY NOTES				8. (Leave blank)	
10. ABSTRACT (200 words or less) This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The docketed information includes information formerly issued through U.S. DOE's Technical Information Center under the title Power Reactor Docket Information (PRDI). This document replaces PRDI, which will no longer be prepared. It is indexed by a Personal Author Index, Corporate Source Index and Report Number Index.				10. PROJECT/TASK/WORK UNIT NO.	
17. KEY WORDS AND DOCUMENT ANALYSIS				11. CONTRACT NO.	
17a. IDENTIFIERS/OPEN-ENDED TERMS				13. PERIOD COVERED (Indicate dates) May 1 to May 31, 1979	
18. AVAILABILITY STATEMENT Unlimited				14. (Leave blank)	
19. SECURITY CLASS (This report)				16. DESCRIPTORS	
20. SECURITY CLASS (This paper)				17b. IDENTIFIERS/OPEN-ENDED TERMS	
21. NO. OF PAGES				22. PRICE	